

This is a digital copy of a book that was preserved for generations on library shelves before it was carefully scanned by Google as part of a project to make the world's books discoverable online.

It has survived long enough for the copyright to expire and the book to enter the public domain. A public domain book is one that was never subject to copyright or whose legal copyright term has expired. Whether a book is in the public domain may vary country to country. Public domain books are our gateways to the past, representing a wealth of history, culture and knowledge that's often difficult to discover.

Marks, notations and other marginalia present in the original volume will appear in this file - a reminder of this book's long journey from the publisher to a library and finally to you.

#### Usage guidelines

Google is proud to partner with libraries to digitize public domain materials and make them widely accessible. Public domain books belong to the public and we are merely their custodians. Nevertheless, this work is expensive, so in order to keep providing this resource, we have taken steps to prevent abuse by commercial parties, including placing technical restrictions on automated querying.

We also ask that you:

- + *Make non-commercial use of the files* We designed Google Book Search for use by individuals, and we request that you use these files for personal, non-commercial purposes.
- + Refrain from automated querying Do not send automated queries of any sort to Google's system: If you are conducting research on machine translation, optical character recognition or other areas where access to a large amount of text is helpful, please contact us. We encourage the use of public domain materials for these purposes and may be able to help.
- + *Maintain attribution* The Google "watermark" you see on each file is essential for informing people about this project and helping them find additional materials through Google Book Search. Please do not remove it.
- + *Keep it legal* Whatever your use, remember that you are responsible for ensuring that what you are doing is legal. Do not assume that just because we believe a book is in the public domain for users in the United States, that the work is also in the public domain for users in other countries. Whether a book is still in copyright varies from country to country, and we can't offer guidance on whether any specific use of any specific book is allowed. Please do not assume that a book's appearance in Google Book Search means it can be used in any manner anywhere in the world. Copyright infringement liability can be quite severe.

#### **About Google Book Search**

Google's mission is to organize the world's information and to make it universally accessible and useful. Google Book Search helps readers discover the world's books while helping authors and publishers reach new audiences. You can search through the full text of this book on the web at http://books.google.com/

EWBIGGING'S

MANDBOOK FOR

Gas Engineers


and Managers.

University of Wisconsin

Class LRN

M42






#### THE

# GAS MANAGER'S HANDBOOK.

SIXTH (AND CENTENARY) EDITION.

15/





WILLIAM MURDOCH

# HANDBOOK

FOR

# GAS ENGINEERS

AND

# MANAGERS.

BY

# THOMAS NEWBIGGING,

Member of the Institution of Civil Engineers.

SIXTH (AND CENTENARY) EDITION, ILLUSTRATED.

### Nondon :

WALTER KING,
OFFICE OF THE "JOURNAL OF GAS LIGHTING," &c.,
11, BOLT COURT, FLEET STREET, E.C.
1898.



48985 29 My'99

LRN .N42

# PREFACE

TO THE

SIXTH (AND CENTENARY) EDITION.

The constant advances that are being made in the Gas Industry have necessitated the addition of much new matter to the present Edition of the Handbook. To make room for this, without increasing the bulk of the volume, I have left out most of the coal testing results that were given in previous Editions. Some of these had become obsolete.

Much of the text has been re-written, and its arrangement and classification simplified and otherwise improved.


I have adhered, wherever possible, to my original plan of dividing the text into short paragraphs, with the object of assisting the memory and allowing of easy reference.

T. N.

5, Norfolk Street,

Manchester,

August, 1898.



# PRINCIPAL CONTENTS.

# [For Alphabetical Index, see end.]

					PAGE
Introduction			•	•	1-10
Coal					10-29
Chief Kinds of Coal					11
Analyses of Coals and Cannels					16-17
Storage of Coal				•	18
Spontaneous Ignition of Coal					19
Gases Occluded in Coal					20
Testing of Coal for its Producing Qualit	ies				21
Gas Production					30
Retort House					30
Inclined or Sloping Retorts					33
Retort Stack					35
Retorts					38
Retort Settings					40
Regenerative System of Heating Retorts	l				44
Flues and Draught					49
Analysis of Furnace Gases					51
Retort Bench Mountings					54
Hydrocarbon and other Gases and Vapour	rs				61
Retort House Tools and Appliances .					70
Machine Charging and Drawing					71
Condensation					72
Naphthalene			•	•	73
Condensers	•				76
Exhausters					85-88

.

# ILLUSTRATIONS.

FIG.			PAGE
1	Coal Testing Apparatus		. 23
2	Specific Gravity Balance		. 25
3	Ground Floor Retort House, single, and	Coal	l
	Store		. 30
4	Ground Floor Retort House, double, and	Coa	l
	Ou		. 31
5	Stage Floor Retort House and Coal Stores		. 32
6-7	Retort House for Inclined Retorts .		. 33-34
8	Bench of Retorts		. 36
9	Fraser's Ribbed Iron Retort, section .		. 38
10-11-12-13	Retorts, Round, D-shaped and Oval .		. 39
14	Brick Retort and Tiles, section		. 39
15-16	Generator Furnace		. 44-45
17	Regenerative Furnace		. 46
18	Tar Furnace		. 53
19-20-21	Buckstaves, sections and elevations .		. 55
22	Coke Slaking arrangement		. <b>5</b> 5
23	Furnace Ash Pan		. 55
18	Furnace Frame and Door		. 53
24-25-26-2	Retort Mouthpiece, Lid and Fittings .		. 57
28-29	Bridge and Dip Pipes		. 59
30-31-32	Hydraulic Main, various sections		. 60
33	"Livesey" Hydraulic Main, section .	•	. 60
34	Bridge Pipe with Wing Valve	•	. 65
35	Charging Scoop		. 70
36	Discharging Rake		. 70
37	Auger	•	. 70
38	Ash Pan Rake	_	. 70

PIG.		PAGE
122	Hutchinson's Service Cleanser	244
123	Service Pipes and Fittings	249
124-125	Street Lamp Posts	252
126	Sugg's Street Lamp and Burners	254
127-128	Bray's ditto ditto	254
129	Siemens's ditto ditto	254
130	Borradaile's Regulator	255
131	Hutchinson's Lamp Service Cleaner	255
132-133	Wet Meter	259
134-135	Dry ditto	259
136	Warner and Cowan Measuring Wheel	260
137	Sanders and Donovan Meter	261
138	Greenall and Heaton's "Positive" Meter	262
139	Parkinson's Motive Power Meter	263
140	Apparatus for Testing Meters	265
141	Cowan's Ventilating Globe Light	283
142	Strode's Ventilating Sun Light	284
143	Sulphuretted Hydrogen Test	293
144	Sulphur Test	294
145-145a	Sheard's Apparatus for Estimating Carbonic	
	Acid, Ammonia, and Sulphuretted Hydrogen	291
146	Harcourt's Colour Test	297
147	Referees' Sulphuretted Hydrogen Test	302
148	Referees' Sulphur Test	306
149	Sugg's "London" Argand, No. 1	310
150	Referees' Street Lamp Pressure Gauge	313
150a	Referees' 1-12th cubic foot measure	315
151	Letheby-Bunsen Photometer	<b>3</b> 18
152	Harcourt's Aerorthometer	322
153	The Carcel Lamp	324
154	Methven's Standard	325
155	Ditto Carburettor	325
156	Harcourt's 1-Candle Pentane Standard Lamp.	326

710.	711 1 10 G N 70 4 4 4 1	PAGE
157	Dibden's 10-Candle Pentane Argand	328
158	Harcourt's 10-Candle Pentane Lamp	331
159	Lowe's Jet Photometer	332
160	Scale for ditto	333
161	Sugg's Illuminating Power Meter	334
162	Thorp and Tasker's Jet Photometer	335
163	Letheby's Specific Gravity Apparatus	337
164	Wright's Specific Gravity Balloon	. 341
165	Lux's Specific Gravity Balance	342
166-234	Devices for Illuminations	325-367
166-179	Brunswick Stars—Beehive and Scroll—Prince	
	of Wales' Feathers—Elephant and Castle—	
	Compass and Square—Rosette, Shield and	
	Cross-Shield and Bars-Crown, Coronet-	
	Eight and Twelve Pointed Stars	352
180-181	The All-seeing Eye—Three Legs of Man	353
182-193	Rosette and Circle—Star—Bird and Shield—	
	Star-Maltese Cross-Bible, Sceptre and	
	Sword of State—Globe and Cross—Crown	
	AureoleMaltese Cross with Queen's	
	Head—Cross Keys—Anchor	354
194-195	Head of Britannia and Legend-Britannia	
	Rules the Waves	355
196-202	Maltese Cross—Crescent with Rays—Windmill	
	and Legend—Hour Glass—Mitre—Lion	
	Rampant—Masonic Emblem	356
203-204	Medal with Legend—Rising Sun	357
	· ·	301
205-211	Harp—Rose, Shamrock and Thistle—Light-	
·	house and Legend—Crescent—Star and	
	Circle—Anchor and Cable—Anchor, Heart	
	and Cross	<b>35</b> 8
212-213	Honey Rea-Resket of Fruit with Legend	250

FIG.		PAGE
214-219	Star—Star of India—Hand and Heart—	PAGE
	Finger Post and Globe-Star and Circle-	
	Crown, Circle and V.R	360
220-221	Spider's Web-Horse Shoe with Legend	361
222-224	Union Jack-Comet with Legend-The All-	
	Seeing Eye	362
225-226	Star of the Bath—Star of the Garter	363
227-229	Lion and Unicorn—John Bull—True Lovers'	
	Knot	364
230-231	Star of St. Patrick—Star of the Thistle	365
232-233	Justice—Angel and Trumpet with Legend .	366
234	Illuminated Arch and Columns	367
235	Coke Breaking Hammer	371
236-237-2	38 Apparatus for the manufacture of Sulphate of	
	Ammonia and the Recovery of Sulphur .	376
239	Stephenson's Apparatus for Testing Spent Oxide	387

### ERRATA.

Page 229, line 2 from bottom-

for 
$$\left(\sqrt{\frac{h \ d}{s \ l}} = \frac{12}{\cdot 4 \times 1250}\right) = \cdot 024$$
, read  $\sqrt{\frac{h \ d}{s \ l}} = \sqrt{\frac{12}{\cdot 4 \times 1250}} = \sqrt{\cdot 024}$ 

Page 824, line 14 from top, for 6:692 inches read :6692 inches.

- " 407. " 20 from top, for CaO2, MNO2 read CaO2, MnO2.
- ,, 451, bottom line, read  $\sqrt{(8 \times \text{weight to be raised})}$ .
- ,, 456, line 10 from top, Load of unhewn timber = 40 cubic feet.

", 468, ", 8 from bottom, for 
$$\sqrt[3]{\frac{20 \times 12}{80}} = 2$$
, read  $\sqrt[3]{\frac{20 \times 12}{30}} = 2$ .

# **NEWBIGGING'S HANDBOOK**

FOR

# GAS ENGINEERS AND MANAGERS.

## COAL GAS.

#### INTRODUCTION.

THE art of coal gas manufacture is just about a century old.

Between 1792 and 1798, William Murdoch, its inventor, was engaged, first at Redruth in Cornwall, then at Old Cumnock in Ayrshire, and finally at Birmingham, in experimenting with different coals, and in devising apparatus for their distillation.

In 1797-8 lighting by coal gas became an accomplished fact, for Murdoch, by means of his experimental plant, first lit up his dwelling-house at Old Cumnock with the new illuminant, and, on his removal to Birmingham in the latter year, having erected an apparatus on a considerable scale, he lighted a portion of the premises of Boulton, Watt, & Co., Soho.

The circumstance that coal would yield an illuminating gas was known long before that time. Natural gas, as it was found to issue from the bowels of the earth in particular districts where coal deposits existed, had been the subject of frequent observation, and its lighting power proved by actual trial; but no practical application was made of the knowledge till Murdoch bent his mind to the study of the subject.

A century is a long time in the history of an industry—longer than one exactly realizes at a first glance. The lapse of so many years since the discovery and application of gas-lighting confers something of the venerableness of age to the art. This is more obvious when cognisance is taken of the initiation of other arts, and the advances which

have been made in them, and not less so in the progress of the sciences, within that period of time.

Take railways for example. As compared with these, gas-lighting is old, for it had a start in life of thirty years before them. Nay, even the steam engine: that is no older than the art of gas-lighting, and much of its initiation and perfecting was due to the same fertile brain, for Murdoch was Watt's right-hand man at Soho, and invented the D slide-valve, the "sun and planet" motion, and the oscillating steam cylinder. As for the telegraph, the telephone, and electric lighting, these are but of yesterday—the younger sisters of the useful arts. Even the science of chemistry was only emerging from its swaddling clothes when gas-lighting was invented.

Although Murdoch had thus realized his dream of employing the gas produced from coal as a lighting medium, there was still much to be done to render the new illuminant acceptable. The impurities in the crude gas were found to be many and objectionable, and means and appliances for their elimination had to be devised. Suitable pipes for the conveyance of the gas to the point of combustion were also required. Murdoch devoted much time and effort in these directions, "washing the gas with water, and employing other means to purify it," and using tinned-copper and iron tubes for its distribution.

Other ingenious minds were early at work in the promising field thus opened out to the labourer. Lebon in France; Winsor at Frankfort, and later in London, where he projected "The National Light and Heat Company," which was afterwards incorporated by Royal Charter as "The Chartered Gaslight and Coke Company." Samuel Clegg, who had been a pupil or apprentice at the Soho Works, Birmingham; Dr. Henry, of Manchester; Northern, of Leeds; Pemberton, of Birmingham; John Malam; Samuel Crosley and T. S. Peckston, of London; Reuben Phillips, of Exeter; and Melville, of Newport, Rhode Island, U.S.A.

Chief amongst these pioneers was Samuel Clegg, who possessed a rare mechanical skill, combined with much shrewd common-sense. In 1805 he began to apply himself to the invention and construction of gas apparatus, and introduced the new method of illumination into many large establishments in different parts of the country. Clegg invented the hydraulic main, and the lime purifier as a separate vessel, though Mr. (afterwards Dr.) William Henry, of Manchester, the distinguished chemist, was the first to suggest the use of lime as a

purifying medium. Clegg also invented the wet gas meter, and evinced infinite resource in improving the apparatus of the gas factory in every department.

In these respects he was ably seconded by John Malam, who now stepped in and perfected the meter in such a way as to render it one of the most ingenious measuring appliances of this or any past age. The arrangement of four purifiers, which, with the centre valve, holds the field to this day, was also the product of Malam's ingenuity.

The new art of gas-lighting was fortunate in many of these its early exponents.

The "Chartered" vessel, launched by Winsor and others associated with him, floundered about for a while in a troubled, and, at times, a boisterous sea, due, no doubt, to the inexperience, but largely also to the incompetence, of some of those in charge; till, at length, the skilful pilotage of Samuel Clegg, who eventually assumed the command, brought her into smooth waters.

It is not surprising that mistakes were made at first, and that immediate success failed to attend the early efforts of the promoters of gas enterprise. The art was a new one; nothing akin to it was there to serve as a model or afford direction and guidance. All the appliances of manufacture, purification, storage, and distribution had not only to be made but invented. The prejudices of the public, too, had to be overcome.

Winsor, with the best intentions, scarcely helped to remove those prejudices. His enthusiastic advocacy, with something of foresight, had in it much of unwisdom. He projected the wildest schemes of gas enterprise ere yet the public—even the immediate public who listened to his harangues and read his pamphlets—had had time or opportunity to grasp the importance of the subject.

Gradually, however, confidence was established. Distrust gave way to admiration; for, under the daily improving management, the new artificial light was shown to be not only cheaper and safer, but vastly superior in lighting power, cleanliness, and handiness, to anything previously in use.

Other companies were soon established in the Metropolis. One by one (like stars coming out at dusk) the larger towns of the kingdom had each its gas company, lighting the public streets and thoroughfares, and supplying its growing number of private consumers.

Thus the new art grew from precarious childhood into youth and sturdy manhood.

It is not too strong an assertion to make, that gas-lighting, during the century of its existence, has proved one of the greatest boons enjoyed by civilized humanity, and no industry that can be named has had a steadier or more abundant success.

This success has been due to two main causes: The inherent utility and value of the invention, and the skill, probity, and business capacity of most of those who, in the earlier years, took a leading part in its furtherance.

The progress which has been made during the century in the machinery of gas manufacture is very striking. This has not been a mere advance in the capacity of the various appliances due to the growing demand for gas-lighting on the part of consumers, but is a positive revolution in constructive detail.

In the first days of the invention the retorts used were of iron, and were placed in the vertical position in the furnace. This was the mode of erection which would be naturally adopted at first, inasmuch as it would lend itself to convenience in depositing the charge.

But it was very soon found that the difficulty of withdrawing the residual coke was such that an alteration in the position was an absolute necessity. Accordingly, no long time elapsed before the retorts began to be laid, first at an inclination, and then horizontally; and instead of only one retort, two, three, and eventually five, were set together and heated, at first by two furnaces, but later by one furnace only.

This was a manifest improvement, and it held its ground for many years. At the present time, in all considerable gas-works, settings of six, seven, eight, nine, and even ten and eleven retorts are in vogue.

Gradually it was found that a high temperature was necessary for economical distillation, inasmuch as with the lower ranges of temperature it was seen that, instead of the evolution of gas, the products were largely in the liquid form.

The retorts themselves were originally of cast-iron, and continued so to be till well into the middle of the century. As the advantages of the higher temperatures of distillation began to be recognized, these were gradually replaced, though not without a struggle, by retorts made of moulded fire-clay, or built up of segmental bricks and tiles.

Instead of direct firing, the regenerative method of heating the retorts, whereby the solid coke is converted into gaseous fuel (CO), is rapidly becoming generally applied, and with marked advantage from every point of view.

The ironwork mountings of the retort bench have undergone considerable modification and improvement during the century. Self-sealing lids, the invention of Mr. Robert Morton, for the retort mouthpieces, have been introduced. The ascension, bridge, and dip pipes have been modified and enlarged; and the hydraulic main is now made of mild steel, and of an improved pattern. Subsidiary or foul mains have been added, by which the gas and denser liquid products are conveyed separately away.

The problem of the application of machinery in gas manufacture, and the consequent saving of manual labour, is advancing towards perfection. This was the dream of the early gas engineers, some of whom attempted it without success. With an ingenuity and persistency deserving of all praise, Mr. John West has devised machinery for stoking, and has, year by year, improved both his hand and power charging and drawing machines. Mr. William Foulis has also been a pioneer in the same direction, and his machinery for that purpose finds wide acceptance.

Inclined or sloping retorts, set at an angle of 30 to 83 degrees, are the latest development in the carbonizing department of a gas-works. Settings of this kind, employed by M. Coze, of Rheims, attracted much attention about eight years ago, and have been adopted at a number of gas-works in this country and abroad. The method and appliances for charging the sloping retorts were imperfect and unsatisfactory at the beginning. Charging appliances of a new type have been introduced, making the system thoroughly practicable. Without doubt, a great future awaits the system, as it simplifies the operations and mitigates the labour in the retort house, besides increasing the productive capacity of the available floor area. The idea of employing retorts set in the inclined position was not new, but an impetus was given to the system by its adoption at Rheims.

Whether it will ever be possible to introduce a method of continuous carbonization, the fresh coal being supplied to the retort and the coke discharged automatically, and without cessation in the working, it is difficult to say. Clegg tried it and failed. Other attempts to that end have been made, but hitherto without marked success, unless the

"Yeadon" system may be considered as a step towards a solution of the problem. This has some good points in its favour, but it has yet to be perfected. It certainly is an ingenious attempt to compass that which earlier inventors failed to accomplish.

Machinery and appliances for the conveyance of coal and coke, and the lime and oxide used in purification, from one point to another, are being widely and successfully applied, and are fast becoming an important labour-saving agency.

The process of washing the gas has been advocated and condemned by various authorities at different periods. Washing was common enough in the early days, but by reason of a supposed deteriorating effect on the illuminating power, it was discredited for a time, and scrubbing by an intercepting material presenting a large area of wetted surface to the gas was preferred.

The view has eventually prevailed that washing as well as scrubbing is indispensable, and the result is that various apparatus to accomplish this object have been introduced with excellent effect.

It is now universally admitted that washing and scrubbing, both with clean water and ammoniacal liquor, are absolutely necessary in order to remove the lighter tars, and arrest the ammonia impurity, as well as to eliminate a proportion of the sulphuretted hydrogen and carbonic acid from the crude gas. It may be safely asserted that the gas of to-day as supplied to consumers is absolutely free from the objectionable ammonia, with the further advantage that this is secured for sale at the gas-works.

The same can be said as regards sulphuretted hydrogen and carbonic acid. In all well-managed gas-works these impurities are unknown in the distributed gas. The use of lime secures their removal with ease and certainty.

Lime was the only medium employed for arresting sulphuretted hydrogen in the earlier days of gas-lighting, till Mr. F. C. Hills introduced the use of hydrated peroxide of iron for that purpose; and although this has no affinity for carbonic acid, the latter impurity is taken out by passing the gas through lime either in the first instance, or in the last stage of purification.

The advantage of using the oxide of iron is its economy, as it can be revivified by exposure to the air after it has become foul, and can be used over and over again, till its bulk has been about doubled by the presence of free sulphur. It also secures another important

desideratum—the reducing of the mountains of foul or spent lime that would otherwise accumulate in the gas yard, and for which there is no great demand on the part of agriculturists. True, a process of spent lime revivification has been invented by Mr. George Hislop; but although this is efficacious in action, it has not been widely adopted.

With the advent of Mr. George Livesey as Engineer-in-Chief of the South Metropolitan Gas Company, a new era in gasholder construction may be said to have begun. It is interesting to note the progress made in his several remarkable structures. The first of Mr. Livesey's notable holders, erected at the Old Kent Road Station, consists of two lifts. It is 180 feet in diameter, and the two lifts rise to a height of 90 feet when fully inflated, the capacity being 2 million cubic feet. His next holder at the same station has a diameter of 214 feet. is in three lifts, and stands when full at a height of 160 feet, having a capacity of 51 million cubic feet. The third one, erected at East Greenwich, is in four lifts, 250 feet in diameter, and rises to a height of 180 feet, its capacity being 81 million cubic feet. The latest and largest gasholder in the world is also erected at East Greenwich. This is a veritable monster in size, being 800 feet in diameter, having no fewer than six lifts, and rising when inflated to a height of 180 feet: its capacity being 12 million cubic feet.

But it is not their size only which makes these enormous vessels remarkable; their structural features are equally noteworthy. Instead of the usual guide framing consisting of columns or standards of large bulk and weight, Mr. Livesey in his later structures introduced a guide framing consisting of comparatively light members, the standards being braced together by diagonals, and horizontal struts.

Although the two holders last referred to are of four and six lifts respectively, the guide framing is not carried up to the full height reached by the inflated vessels. In the first, the inner or top lift rises beyond the framing; and in the second, the two innermost lifts ascend above the summit of the framing, their stability under wind pressure being sufficiently assured on cupping by the limited guide framing applied.

Whether the last mentioned vessel at East Greenwich will ever suffer eclipse by a larger one remains to be seen; but certainly it is safe to assert that it never entered into the dreams of the most advanced gas engineers of the first half of the century that holders of

anything like the enormous proportions named would be called into existence.

There is neither the scope nor the necessity in the provinces for holders of the size of the last named, but Mr. Charles Hunt, at the Windsor Street Station of the Birmingham Corporation Gas-Works, has recently erected two with a capacity of 6½ million cubic feet each. These are in three lifts, rising to a total height of 150 feet, the diameter of the outer lift being 286 feet in each instance.

A remarkable innovation in gasholder guiding, by which the upper framing is dispensed with altogether, is due to the inventive genius of Mr. William Gadd, of Manchester. Mr. Gadd solved the problem in a variety of ways. First, by means of torsional and tensional gearing fixed round the tank, and attached to the holder or floating vessel at its base; but more especially by the introduction of spiral guide rails fixed to the sides of the tank or attached to the sides of the holder in a diagonal direction. The simplicity of this latter device is so self-evident that it is matter for surprise it had never been previously applied or thought of. The first holder of this class was erected at Northwich, in Cheshire, by Clayton, Son, & Co., Ltd., of Leeds, having been designed from the inventor's patent specification by the present writer.

As frequently happens in other cases, there were other minds simultaneously engaged in the solution of the problem of guiding holders without upper framing. Mr. E. L. Pease, of Stockton-on-Tees, invented a system of guiding by means of wire rope gearing, which has been largely adopted; and Mr. J. W. Terrace, of Brechin, also devised a means of guiding by shafting, screws, and wheels. Mr. Gadd's, however, was the patent first in the field.

In the distribution department the improvements have been in the direction of efficiency rather than novelty. An exception to this statement must be made in regard to the jointing of main pipes. The open joint, filled either with lead or some kind of cement caulking, was general down to the introduction of the turned and bored joint by Mr. Alfred King, of Liverpool, about the year 1826. This was without question a step in advance, and although there are engineers who still prefer the open joint, the preference arises more from prejudice than experience and knowledge. The turned and bored joint, with a recess in front for filling with cement or lead, is the most perfect joint possible for mains.

There can be no doubt, also, that much of the success of the coal gas industry is due to the adoption of enlarged mains and service pipes, as compared with the restricted sizes in use from twenty-five to thirty years ago; admitting, as they do, of a reduction in the pressure, with a consequent reduction of loss by leakage, and an increased illuminating value.

In street lighting a marked advance has been witnessed. Perhaps this is due to some extent to the threatened competition of the electric light. Years ago Mr. William Sugg introduced his large argands for street lighting. These undoubtedly gave a magnificent light, but the difficulties attending the regulation of the flame at varying pressures proved an impassable obstacle to their success, and they were finally abandoned.

These were succeeded by the triform arrangement of large flatflames, introduced almost simultaneously by Mr. Sugg and Mr. George Bray. For the illumination of streets, squares, and other wide open spaces they are admirably adapted.

The Welsbach system of incandescent gas lamps, introduced in the year 1887, has created a veritable revolution in domestic lighting, and it bids fair to revolutionize the lighting of streets also. The success of the invention has been as great as it is deserved; not only is the gas economized by its use, but the illuminating value of the light is increased to the extent of 800 to 400 per cent.

The use of gas for cooking and heating, for the production of motive power, and for workshop purposes, has made vast strides of recent years. Fires, stoves, and ranges of all sizes and of excellent design, are produced by a number of first-class makers. The Otto gas engine, as made by Crossley Brothers, has settled beyond question the economy and value of gas for motive power. Other makers of similar engines of great excellence are numerous. In the application of gas to industrial uses generally, the ingenuity of Mr. Thomas Fletcher has found an outlet. In all these directions the field may be pronounced limitless.

The invention and introduction of the prepayment meter has encouraged the use of gas by the poorer class of consumers, and here also it is difficult to conceive of a limit to gas enterprise.

In no department of the gas industry has there been so remarkable a development as in that of dealing with the residual products. There is absolutely no waste in a well-managed gas-works. Everything is utilized, even to the dross yielded by the furnaces. This much can

hardly be asserted of any other industry in existence, and this fact should be borne in mind by those who are sometimes inclined to decry the administrators of gas undertakings.

The tangible result of it all is, that gas property has attained to a reputation for value and stability, scarcely exceeded by any other means of investment outside the Funds, and, competition notwithstanding, there is ground for confidence that it will continue to maintain its deserved popularity.

#### COAL.

The geological position of coal in the earth's crust is shown in the annexed tabular view of the trias, permian, and carboniferous series in England and Wales, by Professor Hull:—

New red sandstone or trias	Keuper { Red marl. { Lower Keuper sandstone. { Upper mottled sandstone. } Conglomerate beds. { Lower mottled sandstone. }
Permian rocks Permian rocks Vorkshire, &c Red sandstones	stone of St. Bees, &c. or magnesian limestones and marls of counties. stone of Lancashire, Cumberland, and c. (on the same horizon with) d, marls conglomerates, and breccia, counties and Salop.
Upper carboniferous	Upper coal-measures, with lime- stone, and thin coal seams. Middle coal-measures, with thick coal seams.
Carboniferous rocks.  Lower carboniferous	Lower coal-measures, or Gannister series, with thin coal seams and lower carboniferous fossils.  Millstone grit, with thin coal seams. Upper limestone shale, or Yoredale rocks. Carboniferous limestone with shales, sandstones, and coal in the Northern counties and Scotland. Lower limestone shale.

Old red sandstone and Devonian rocks.

The area of the coal measures in the United Kingdom is as follows:—

	Area of C	oal Measures.	Entire Area	Proportion of	
	Square Miles.	Acres.	Acres.	Square Miles.	Coal to the whole.
In England	6,089	8,864,960	81,770,615	49,648	1-8th
In Scotland & Islands, ) exclusive of Lakes	1,720	1,100,000	18,944,000	29,600	1-18th
In North Wales In South Wales	210 950	134,400 } 608,000	4,752,000	7,425	1-6th
In Ireland	2,940	1,881,600	20,399,608	31,874	1-11th
In Islands	••	••	1,119,159	1,748	_
Total	11,859	7,588,960	76,985,882	120,290	

Exclusive of wood-coal and lignite formations, and some small undefined areas.

The chief kinds of coal in the United Kingdom are-

Cannel or Parrot Coal.—This is the richest gas-producing coal, and is easily distinguished by its hard, smooth texture. The best varieties are found in different parts of Scotland, in Wales, and at Wigan and Newcastle or their neighbourhood. The latter two yield coke of fair quality; that from the other is less valuable, and much of it is useless as fuel.

Bituminous Coal.—For gas producing purposes the coal most suitable is the bituminous class, which includes caking, splint, cherry, and other coals containing bitumen. It is found widely distributed throughout the kingdom, in Yorkshire, Lancashire, Cumberland, Northumberland, Durham, Derbyshire, Staffordshire, Gloucestershire, Somersetshire, portions of Scotland and Wales. It yields coke generally of excellent quality.

Anthracite or Glance Coal.—This is chiefly Welsh, containing a large proportion of fixed carbon (over 90 per cent.) and but little volatile matter. It glows rather than flames in burning, and is almost smokeless. It is excellent for steam raising purposes and domestic

use where a good draught is available, but is quite useless for the production of illuminating gas.

Lignite or Brown Coal.—This is found at Bovey Tracey, in Devonshire, in a small field near Lancaster, and near to Lough Neagh, in Ireland. It yields but little gas, and that of a low illuminating power and very unpleasant odour. In distillation it gives off a large quantity of water charged with acetic acid, and the residual coke is valueless as fuel. It is, therefore, of no great interest to the gas maker.

The tables annexed show the specific gravity of coals, the chief substances of which they are composed, and their yield of coke per cent.:—

#### NEWCASTLE COALS.

Name of Coal.	Spe- cific Gra- vity.	Car- bon.	Hy- dro- gen.	Nitro- gen.	Sul- phur.	Oxy- gen.	Asb.	Coke.
Willington Tanfield Bowden Close Haswell Wallsend Newoastle Hartley Hedley's Hartley Batee's West Hartley West Hartley Main Original Hartley Average of eighteen samples from different mines	1·26 1·28 1·29 1·31 1·25 1·26 1·25	86·81 85·58 84·92 83·47 81·81 80·26 80·61 81·85 81·18	4.53 6.68 5.50 5.28 5.26 5.29 5.56	1.05 1.26 0.96 1.42 1.28 1.16 1.52 1.69 0.72	0.88 1.82 0.65 0.06 1.69 1.78 1.85 1.18 1.44	5·22 4·89 6·66 8·17 2·58 2·40 6·51 7·58 8·03	1.08 2.14 2.28 0.20 7.14 9.12 4.25 2.51 8.07	72·19 66·13 69·69 62·70 64·61 72·31 59·20 58·22 60·67

#### LANCASHIRE COALS.

## DERBYSHIRE COALS (Fiddes).

Name of Coal.	Spe- cific Gra- vity.	Car- bon.	Hy- dro- gen.	Nitro- gen.	Sul- phur.	Oxy- gen.	Ash.	Coke.
Rarl Fitzwilliam's Elsecar. Holyland and Co.'s Elsecar Butterley Co.'s Langley Staveley Average of seven samples from different mines	1·296 1·317 1·264 1·270 1·292	81·98 80·05 77·97 79·85 79·68	4·98 5·58 4·84	1·27 1·24 0·80 1·28 1·41	0·91 1·06 1·14 0·72 1·01	8·58 8·99 9·86 10·96	2·46 3·78 4·65 2·40 2·65	61·60 62·50 54·90 57·86 59·82

#### GLOUCESTERSHIRE COALS.

Coleford H	igh ]	Delf	(Fo	rest		70.010	7.000	1.550				
		of 1	Des	. (ac	1.319	78.810					3.020	63.97
**	,,		•	• •		76 - 502					6.700	62.60
**	"	•	•								9.210	59.76
	,,					74.464			2.667		10.235	60.86
Trenchard	•		•			80 · 709			1.271			63.88
New Bowso	n, C	inde	rfor	rd.		76 . 860			1.940			58 • 24
		,,										59 • 22
Parkfield .	•				1.874		5.618				8.230	60.97
Hanham .											11 · 480	58.86
Warmley .			•		1.804	82.410	4.870	0.770	0.870	5.230	5.850	71.15

## SCOTCH COALS.

Boghead	1.218 63.980 8.858 0.962 0.320 4.702 21.222 31.70 1.200 76.090 5.220 1.410 1.530 5.060 10.700 58.45
Grangemouth	1·290   79·850   5·280   1·850   1·420   8·580   3·520   56·60   1·250   80·080   6·500   1·550   1·880   8·050   2·440   54·94

## WELSH COALS (Fiddes).

Aberaman, Merthyr	1 800 90		L·210 1·180 0	
Aberdare Co., Merthyr	1 310 88		1.660 0.910 1	
Anthracite (Jones & Co.) .	1.875 91	·440  3·460  (	0.210 0.790 2	·580  1·520   92·9
Coleshill	1.290 78		l·470 2·840 8	
Llantwit	1.278 77		0.560 2.865 12	
			0.420 2.037 10	
Nantgarw Llantwit			0.700 8.450 7	
Rhos Llantwit			0.700 1.648 12	·875 2·332 63·3
,, ,,			0.840 2.312 18	
	1 • 302   73 •	410 5 507 0	0.850 2.414 14	276 4.048 65.
Holly Bush	1.269 80	134 5.045 0	0.518 2.279 8	522 3.502 74.
Tyr Filkens	1.368 82			794 8 903 64 8
Lianhilleth	1.274 87	640 6 085 1	1.120 1.636 2	209 1.310 70.8
Aber Rhondda	1.320 80	675 5.082 0	) 910 8 875 2	768 6 895 70 8
Pontypridd	1.311 79	820 5 470 0	0.700 3.950 3	750 6.310 65.8
Wallsend	1.317 78	270 5.380 0	0.770 1.860 8	900 4.820 65.0
Energlyn	1.312 88	120 5.840 0	0.980 1.870 5	890 2.300 71.8
Rock Vawr	1.290 77	1980   4 1 <b>890  </b> 0	0.570 0.960 8	·550 7·550 69·5

The specific gravity both of cannel and bituminous coals averages about 1.270, distilled water at 62° Fahr. being 1.000.

The proportion of ash in the better class of bituminous coals averages 2.5, and in the residual coke 3.75 per cent. In cannel, the proportion of ash is much greater.

The colour of the ash varies, according to the nature of its constituents, from white, through all the gradations of grey, cream colour, fawn colour, yellow, pink, red, to deep red and brown.

The following is an analysis of the ash of a good Newcastle

						Per cent.
Silica	•		•		•	59.56
Alumina	•	•	•	•		$12 \cdot 19$
Peroxide	of iron	•	·			15.96
$_{ m Lime}$		•				9.99
Magnesia	•					1.18
Potash	•		•	•		1.17
						100.00

The proportion of sulphur in fourteen samples of cannel averaged 1.21, and in forty-two samples of bituminous coal 1.812 per cent.

In the same samples the volatile matter and coke were as follows:-

			•	Volatile Matte Per cent.	er.	Residual Coke. Per cent.
Cannel		•		44.71	• •	55.29
Bitumino	ous co	al.		84.72	• •	65.28

Every-day experience shows that variations occur in the quality of the coal obtained from the same seam and in the same locality. The identical seam of coal also varies in quality in different districts.

Coal got from those parts of the bed where the seam is thickest is more likely to possess uniformity of structure than that got near to the circumference of the basin.

Mr. E. W. Binney's observations led him to the conclusion that seams of coal are materially affected by the nature of the super-imposed strata. If this is of an open character, such as sandstone, the gaseous matter can readily escape. On the other hand, if the roof is of almost air-tight black shale or blue blind, the gas is retained.

Further, it is not unreasonable to infer that the vegetable matter of

which coal is composed would be deposited irregularly. For example, during the ages of primeval vegetable growth, a larger proportion of leaves would be deposited in some places than in others where the deposits of bark and cellular tissue would be in excess. These conditions would naturally tend to produce variations in quality.

In seams of cannel there is more uniformity of quality than in those of ordinary coal, due to the circumstance, as is supposed, of their having been formed from vegetable matter long macerated in water, thus insuring a more intimate admixture of the vegetable substances.

It is well known that variations in the gas-producing qualities of coal are caused by the material having been stacked for a length of time on the pit bank.

It is important that the coal which is to undergo distillation should be clean and dry.

When coal in a wet or moist condition is placed in the retorts, the results are unsatisfactory in several respects.

In the first place, the temperature of the retorts is reduced, and, as a consequence, extra fuel is consumed in restoring the temperature, and in drying the coal by evaporating the moisture and driving it off as steam before the coal is in a fit condition to undergo destructive distillation.

Again, a portion of the moisture or steam is decomposed in contact with the sulphide of iron produced by decomposition from the bisulphide of iron or iron pyrites contained in the coal. The oxygen combines with the iron, forming the oxide of that metal, and the hydrogen with the sulphur, producing sulphuretted hydrogen. Bisulphide of carbon and other sulphur compounds are also formed in considerable volume.

In this way the whole of the sulphur present in the coal is caused to pass off into the gas, and has to be subsequently removed in the process of purification, thus increasing the cost of manufacture.

On the other hand, when the coal is distilled in a dry condition, rather more than one-half of the sulphur present is left behind in the residuary coke.

Sulphur exists in cannel in the free state, and in bituminous coals chiefly in combination with iron, as pyrites or bisulphide of iron, FeS<sub>2</sub>, and this in the retort is converted into sulphide or protosulpheret of iron, FeS.

1

SOME RECENT ANALYSES OF COALS AND CANNELS.

By T. and W. Neweldschie.

GAS COALS.

Name of Coal.	Situation.	Specific Gravity of Coal.	Yield of Purified Gas per Ton in Oubio	Illum. Power of the Gas in Standard Candles	Value of I Cubic Foot of Gas in Grains of Sperm	Value of Gas per Ton of Coal in 1bs. of Sperm.	Sulphur in Coal per Cent.	Coke in lbs. por Ton.	Ash in Ooke Per Cent.
Haigh's Black Bed  Ditto Beeston Nuts Ditto do. Top Seam. Hoyland Silkstone Ditto New Silkstone Ditto Silkstone Cobbles Middleton Main. Beeston Coal Beeston Coal Bersham Main. Ditto Quaker Five Foot Top. Ditto Quaker Gresham Main Ditto Quaker Five Foot Top. Ditto Annel Five Foot Top. Ditto Mixed Four Foot Bodger Mine Ramden's Ditto Di	Bruntoliffe, near Lieda. Barnsley Ditto Ditto Downbull Wood, Batley Ditto North Wales Ditto	1.914 1.924 1.924 1.927 1.926 1.928 1.929 1.926 1.939 1.939 1.939 1.939 1.939 1.939 1.939 1.939 1.939 1.939 1.939 1.939 1.939	11, 360 11, 360 11, 360 11, 360 11, 360 11, 360 12, 000 12, 000 10, 400 10, 40	18.38 19.38 19.38 19.38 19.38 19.39 19.30	440-64 440-76 440-64 440-64 440-64 455-58 510-72 51	714-46 738-93 73	1.56 9.68 1.10	1,409 1,386 1,186 1,186 1,186 1,186 1,386 1,386 1,386 1,386 1,348	8 48 8 66 8 66 6 66 8 66 8 66 8 66 8 66

# CANNELS.

Name of Cannel.	Situation.	Specific Gravity of Cannel.	Yield of Purified Gas per Ton in Cubic	Illum. Power of the Gas in Standard Candles.	Value of 1 Cubic Foot of Gas in Grains of Sperm.	Value of Gas per Ton of Cannel in 1bs. of Sperm.	Bulphur in Coal per Cent.	Coke in 1bs. Per Ton.	Ash in Coke per Cent.
Haigh's Beeston Top Seam.  Low Laithee Scothill Wood Company. Ditto Discount Johnnies Dressed Johnnies Chickenley Heath. Orawahaw and Warburton. Ditto Orito do. Pateswood Bottom Ditto Outley Pontybodkin Silverhill Beraham Bradford Estate Blaydon Main Wastleigh Ramsden's Middle. Dirto do. Bredewringe Middle. Dirto do. Bredewringe Middle. Dirto do. Bredewringe Bottom Sydney Shale Turner's New Abram	Bruntoliffe, near Leeds Ossett Batley Ditto Ditto Devabury Ditto Stanton North Wals Great Lev. r Borth Mals Kentucky, U.S.A. Ditto Ditto Ditto North Wals Great Lev. r Ditto D	1.831 1.270 1.270 1.285 1.288 1.286 1.290 1.101 1.201 1.102 1.103 1.103 1.1193	11, 400 11, 500 11, 50	\$	595-68 594-24 662-45 662-45 662-69 649-98 649-98 647-98 660-00 600-00 600-00 600-00 600-00 600-00 600-00 60	970-10 1078-88 1066-16 11165-16 11165-16 11165-16 11165-16 1177-38 1177-38 1177-38 1189-66 11011-87 11	11:19 12:19 12:19 12:19 12:19 13:19	1,406 1,250 1,250 1,250 1,261 1,261 1,260	18-25 9-25

The Storage of Coal.—In gas making it is economical to use the coal as fresh as possible from the pit; but to be prepared for emergencies, the covered storage room for coal and cannel should be of capacity sufficient to contain from six to eight weeks' stock of the material, reckoned on the basis of the heaviest day's consumption in winter.

An exception to this rule may be made in the case of gas-works situated in the immediate vicinity of the coal fields from which the supply is derived. Under such circumstances, provision for two or three weeks' stock is ample.

In storing coal 48 cubic feet of space per ton is required.

All kinds of coal suffer deterioration by exposure to the weather, both as regards their heating, coking, and gas-yielding qualities.

When coal is so exposed, being stored in the open air without any protecting covering, it is not only liable to be wetted by rain on its outer surface, but it also absorbs and retains moisture within its structural interstices.

The effect of this excess of moisture is to cause disintegration, reducing the size of the lumps, and converting them to a considerable extent into dust and coom.

The exposure of the coal in the winter season in this climate is, of course, the most objectionable as regards disintegration. In hot climates the intense heat of the sun produces the disintegration.

The ill-effects of this absorption of moisture do not end there. Oxidation of the particles of the coal also ensues; and as this is only another name for eremacausis or slow-burning, the material is not only reduced in weight, but its gas-producing power, both as to quantity and quality, and its coking qualities, are greatly impaired.

An absolute loss of weight, due to the evaporation or slow combustion of the more volatile constituents, is also experienced. This is particularly the case with bituminous or caking coal; cannel suffers next in degree; and anthracite the least. Varrentrapp found in one instance that coal which had been exposed for some years to the weather had diminished in weight to the extent of 88.03 per cent.

Wet or damp coal not only yields less gas, but gas of an inferior quality. The sulphur impurities given off from it are more, thus augmenting the cost of purification; whilst some of the sulphur

compounds—notably bisulphide of carbon—are not removable except by a greatly increased area of purification beyond what is to be found in most gas-works.

Spontaneous Ignition of Coal.—Coal containing a large proportion of iron pyrites (bisulphide of iron), commonly called "brasses," when stored in a compact mass in a wet or humid state, is liable to spontaneous ignition. This is not an unusual occurrence in the experience of the gas manager. The indications that combustion has begun are a sensible rise in the temperature of the coal store, a sickly odour, and a choking or smothering sensation in drawing breath.

There is this liability to spontaneous ignition in almost all bituminous coals of a friable nature. It is due to more than a single cause. It may arise from the condensation of oxygen within the pores of the carbonaceous particles, just as oily cotton waste will fire spontaneously in the same way by the rapid absorption of oxygen. According to Professor Abel and Dr. Percy, water or moisture does not accelerate, but rather retards, spontaneous ignition under these circumstances.

The danger of firing is greatest with those coals which contain a large proportion of iron pyrites in the shape of nodules, or "brasses," as they are called, and which are stored in a deep mass in the wet condition. These "brasses" become oxidized by the atmospheric oxygen dissolved in the water with which the coal is saturated; and the heat thus generated raises the temperature of the coal to ignition point.

Notwithstanding a conflict of opinion on the subject, we believe that the best remedy for this is ventilation.

Various expedients are resorted to for effecting this object, amongst which may be mentioned the insertion in the mass of coal of perforated iron pipes with the ends exposed; coarse wickerwork baskets, without bottoms, are used with good results; and ventilating shafts of brick, or venetianed shafts of wood, both horizontal and vertical, have proved efficient. Unless the ventilation is thorough, however, the admission of air will do more harm than good, as a sluggish current will not reduce the temperature, but rather tend to develop and increase it.

A thermometer let down through the pipes or shafts will indicate any rise of temperature, and iron rods thrust into the mass of čoal, when withdrawn and touched by the hand, will answer the like purpose.

When the pyrites are present to a serious extent, the coal should be hand-picked, either at the colliery or when discharging at the gasworks. It is only sheer necessity, however, that will justify the employment of coal of this character for gas-making purposes.

The Gases Occluded in Coal.—Besides the liability to spontaneous combustion or ignition, there is another strong reason why coal should not be stored in the open air, nor, indeed, under cover, for a longer time than is absolutely necessary.

In all bituminous coals a constant chemical change is in progress, by which gas is being liberated. This gas, though frequently several times the volume of the coal, is condensed within the solid substance, being occluded or enclosed therein, until by diffusion it escapes into the air, and to such extent the coal is depreciated for gas making.

In warm weather and in hot climates this deterioration proceeds more rapidly than in low temperatures.

Dr. Lyon Playfair and others in this country, and Dr. E. von Meyer in Germany, have investigated the subject; and the subjoined table by the latter shows the quantity and composition of the gas so occluded, obtained from freshly raised samples of coal submitted to him for analysis.

The plan adopted was to place 100 grammes of the coal in hot de-aërated water, which was then boiled as long as any gas continued to be given off, and the gas collected was analyzed by Bunsen's methods.

	Samples of Coal Submitted.												
No.	1. Low Main Seam		•										
	2. Maudlin Seam	ditto	ditto.										
	8. Main Coal Seam				_								
	4. Five-fourth Sear	n, ditto	ditto.				80						
	5. Ditto	Wingate Grange Col	liery, Du	ırhe	m		74						
	6. Low Main Seam	ı, ditto	ditto.				108						
	7. Harvey Seam,	ditto	ditto.			•	148						
	8. Ditto	Co	llieı	y	25								

4	ANALYSI	<b>S</b> .		
Percentage	Composition	OF	THE	GAS.

	oal bov		CO <sub>2</sub>	CH Marsh Gas.	o	N	Cubic Centimètres of Gas from 100 Grammes of Coal.
No. 1			5.55	6.52	2.28	85 • 65	25 · 2
2		.	8.54	26.54	2.95	61.97	80.7
8		. 1	20.86	1	4.83	74.81	27.4
4		.	16.21	Trace.	5.65	77.84	24.4
5		.	0.34	85.80	Trace.	13.86	91.2
6		.	1.15	84.04	0.19	14.62	288.0
6		. 1	0.28	89.61	0.55	9.61	211.2
8		.	5.31	50.01	0.63	44.05	84.0

1 cubic centimètre = 061028 cubic inch.

1 gramme=0.0022 lb. avoirdupois, 100=0.22 lb.

The Testing of Coal for its Producing Qualities.—It is almost impossible to judge from the appearance of a coal whether its gas and coke-yielding qualities are good, bad, or indifferent. So far as outward indications go, nothing is so deceptive to the inexperienced in such matters; and even to those who have had large practice in coaltesting, it is very difficult to forecast with any certainty the result of a trial of any particular sample.

The most favourable signs are when the coal exhibits traces of carbonate of lime and charcoal deposits on the surfaces exposed by fracture, and the appearance of a brownish coloured streak on being scored with a hard, blunt point. This latter is an invariable sign of richness.

Some of the poorest coals and cannels have a fatty, unctuous appearance, suggestive of richness in gaseous properties; again, the most valuable cannels and shales, yielding gas in extraordinary abundance, have a dull earthy cast, which might readily be taken as indicating poverty of composition and yield. The rich Boghead (Scotland), Sydney (New South Wales), Cloverport (Kentucky) cannels or shales, and the New Abram cannel, Wigan, are striking examples of this latter kind. On the other hand, this does not hold good of the Brazilian shales or "Turba." These have a dull, clayey appearance, and are very indifferent both in the yield and in the illuminating

power of their gas. The importance of being able to test samples of coal or cannel, before entering into a contract for the material in bulk, is therefore obvious.

A test may be made either on a working scale, or in the experimental apparatus in the gas manager's laboratory. In the former case several tons of the material have to be used, and the trial of a single sample is a formidable and tedious process, extending over many days, until the old gas in the apparatus and holder has been replaced by the new. It is obviously impossible to test a variety of samples in this manner within a reasonable period. Besides, such a method of testing is not always satisfactory. The manager has to take a good deal for granted; he is largely dependent on subordinates for the attention and care that ought to be exercised, because his constant personal supervision throughout the time occupied by the test is out of the question.

The experimental test is to be preferred for many reasons. The small apparatus is more under the command of the operator. Full justice is done to the material. The best results it is possible to obtain are secured. Time is economized in making the tests, because a number of samples can be tried in the course of, say, ten to fourteen days.

It may be urged against the experimental, or laboratory test, that, in practical working, equal results are unattainable. If this be the fact, it only proves that either the practical working is at fault to the extent of the difference in result, or that the bulk of the material is not equal to the sample tested.

Assuming, however, that the sample is a fair average of the whole, whatever the deficiencies of practical working may be, the coal at least should not be depreciated below its intrinsic value through defective heats and other faulty methods of carbonization; and although the actual every-day working of the material may afterwards fall short of the results obtained in the trial apparatus, these latter are a standard at which to aim. As a general rule, the difference between the results of actual use and the experimental results, with efficient plant and careful supervision, will not exceed seven to ten per cent. in favour of the experimental test.

To argue that the quality of a coal should be judged and determined solely by the results yielded in actual working, is just about as reasonable as to say that the illuminating power of gas should be decided

by the methods of consumption through possibly defective fittings, and some of the burners largely in use by consumers. Whether coal or gas, the means best calculated to develop its intrinsic qualities should be adopted.

Care should be taken to obtain a fair sample of the coal to be operated upon. For that purpose a full section of the seam should be obtained. It should then be broken up into small pieces and thoroughly intermixed, and from this, three several charges should be taken without selection.

The charge employed in the laboratory trial is the 1000th part of a ton-viz., 2.24, say 21, lbs.

The following are the details of the testing apparatus (Fig. 1).




Fig. 1.

RETORT.—Cast iron; D-shaped; 5 in. wide, 41 in. high, inside; 2 ft. 8 in. long, outside; 1 in. metal.

Ascension Pipe.—2 in. wrought tube.

Connections.—1; in. wrought tube.

CONDENSER.—12 vertical 11 in. wrought tubes, 8 ft. 6 in. long each.

WASHER.-1 ft. long, 6 in. wide, 6 in. deep.

Purifier.—1 ft. 2 in. square, 12 in. deep, with 2 trays of lime.

GASHOLDER.—Capacity, 12 cubic feet, with graduated scale attached.

The retort should be got up to, and maintained throughout the charge at, a bright red heat. If from any cause the temperature is

A table, by Dr. Henry, exhibits the qualities of gas at different periods of distillation:—

From Half a Ton of Wigan Cannel.

	of Imp	easures ure Gas itain		Measure Purified G consist o	100 Measures of Purified Gas		
Time from Beginning of Distillation.	Sulphu- retted Hydro- gen.	Other Com- pounds of Nitrogen and Hy- drogen.		Other Inferior Gases.	Nitrogen.	Consume Oxygen.	Give Carbonio Acid.
an hour.	8	5½	16 18	64 77±	20	180 210	94 112
3 hours.	24	31 31	15	80	42	200	108
	24	2 <u>1</u> 2 <u>1</u> 2 <u>1</u>	18	72	15	176	94
5 ,, 7 ., 9 .,	2	21		76	15	170	83
9 ,,	1	24	9 8 6	77	15	150	73
10 ,,	••	2		74	20	120	54
12 ,,	1	1 1	4	76	20	82	36
From Ha	ilf a To	n of C	ommoi	n Wiga	an Gas	: Coal.	
1 hour.	1 8	3	10	90	١	164	91
3 hours.	2 3	3 2 2	9	91		168	93
<u>5</u> "	8	2	6	94		132	70
7 ,,	1	8	5	80	15	120	64
9 ,,	1	21	2	89	9	112	60
11 ,,	1 1	1	••	85	15	90	48

The rate of production of gas from 2 cwt. of Wigan coal in an experimental retort was found to be as follows:—

							Cu	bic Feet.
1	hour							275
1	,,						•	245
11	hours							200
2	,,							140
24	"							80
8	,,							40
31	"							20
4	,,							15
			T	otal				1015

The annexed table, by Miller, exhibits the quantity and specific gravity of the gas obtained from two bushels of coal during each of five hours' heating in an ordinary retort; and shows the importance of restricting the time during which the coal is subjected to

the action of heat in the manufacture of gas. The rich hydrocarbons diminished, and carbonic oxide and hydrogen increased in quantity as the experiment progressed.

•		С	lubio Fe	ët.	Specific Gravity
In the first hour .			345		•677
In the second hour			203		•419
In the third hour			118		•400
In the fourth hour			54		·322
In the fifth hour.			20		

With cannel the carbonization takes place in considerably less time than with ordinary coal.

For roughly estimating the weight of coal or cannel required to produce a given quantity of gas:

RULE.—Strike off the last four figures from the quantity of gas produced, and the figures remaining will represent the coal or cannel in tons.

Thus:  $20 \mid 0,000$  cubic feet of gas = 20 tons coal.

This will be evident when it is remembered that a ton of coal or cannel produces about 10,000 cubic feet of gas. Should the production rise to 11,000, or fall to 9000 per ton, one-tenth must be deducted from, or added to, the coal, as the case may be.

The average weight of coal per cubic yard is:-

Anthracite,	per	oubic	yard,	solid				2160
Bituminous	-,,	**	,,	,,				2025
Cannel	"	"	,,	,,				2160
Coal, stored	in t	he us	ual w	ay, per	· cubi	c yard		1400
Coke, per co	abie	yard						670
Breeze ,,	,,	"				•		950

The average percentage yield, by weight, of good bituminous coal, is as follows:—

				P	er cent.
Gas			•		18
Coke and breeze .				•	68
Tar					5
Ammoniacal liquor					9
_					
					100

In order to find the value of gas in grains of sperm per cubic foot from the given illuminating power:—

RULE.—Multiply 120 (the grains allowed per hour for the consumption of the standard sperm candle) by the illuminating power,

and divide by 5 (consumption of gas in cubic feet per hour by the standard burner). The answer will be the value of the gas in grains of sperm per cubic foot.

EXAMPLE.—What is the value of gas in grains of sperm per cubic foot, the illuminating power of which is 19.46 candles?

$$\frac{19.46 \times 120}{5} = 467 \text{ grains of sperm, value.}$$

To find the value of any coal per ton in pounds of sperm, the yield of gas and illuminating power being known:—

RULE 1.—Multiply the cubic feet produced per ton by the value of the gas in grains of sperm per cubic foot (ascertained by the previous rule), and divide by 7000 (the number of grains in 1 lb. avoirdupois). The answer will be the value of the coal in lbs. of sperm per ton.

Example.—What is the value of a certain coal in lbs. of sperm per ton, whose yield of gas is 10,540 cubic feet, and illuminating power 19.68 standard sperm candles?

$$\frac{19.68 \times 120}{5} = 471.12$$
, value of the gas in grains of sperm per cubic ft.

Then 
$$\frac{10,540 \times 471 \cdot 12}{7000} = 709.87$$
 lbs. of sperm per ton, value. Or by

RULE 2.—Divide the yield per ton by 5 (cubic feet of gas consumed per hour by standard burner); multiply by the ascertained illuminating power and by 120 (consumption of standard sperm candle per hour in grains); lastly, divide by 7000 (number of grains in 1 lb. avoirdupois). The answer will be the value of the coal in lbs. of sperm per ton.

EXAMPLE.—What is the value of a certain coal in lbs. of sperm per ton, whose yield of gas is 10,540 cubic feet, and illuminating power 19.68 standard sperm candles? Then

$$\frac{10,540}{5} = \frac{2108 \times 19.68 \times 120}{7000} = 709.87 \text{ lbs. of sperm per ton, value.}$$

To ascertain the relative value of different coals and cannels, attach

approximate or actual market prices to the sperm pounds as ascertained above, and to the several residual products, cast up the various items, and compare them by the ordinary rule of proportion.

Example.—The two coals to be compared are—

No. 1, yielding—													£	8.	đ.
10,600 c. ft. of	gas	per	ton,	17	i c	and	<b>es</b>	VA	lue	=	: 68	36 lbs.	_		
sperm .												at ls.	81	16	0
13½ owt. Coke												at 5d.	0	5	71
10 gals. Tar.												at 11d.	0	1	01
22 gals. Ammor	aiaca	l Li	quor				•	•				at 1d.	0	1	10
													£82	4	6
No. 2, yielding-													_		_
9,700 c. ft. of	gas	per	ton.	16	<b>a</b> c	and		***	ılnı		<b>-</b> K	57 lbs	£	8.	. <b>d</b> .
							100	٧.	m	-	- 0	Of IDE.			
sperm		_			-								27	17	0
sperm 14 cwt. Coke .		٠.	• •								•	at 1s.		17 5	-
		•		:			•	•	:		•	at 1s. at 5d.	0	5	-
14 cwt. Coke .	: :	· ·				 	•	:	•	•	:	at 1s. at 5d. at 1½d.	0	5	10

Assuming that No. 1 is 12s. 6d. per ton, the relative value of No. 2 will be found as follows:—

As £82 4s. 6d. : £28 5s. 5\frac{1}{4}d. . 12s. 6d. : 10s. 11\frac{1}{4}d. value per ton of No. 2.

Farmer's rule to find the relation between quantity of gas per ton and illuminating power, may be quoted here, but it must not be assumed as absolutely correct. It is only approximately so, and that only within a limited range. If a given coal yields a known volume of gas of a known illuminating value, to ascertain how much gas it will yield of another value:—

RULE.—Multiply yield of gas by the illuminating power, divide by the required power, and the quotient is the quantity.

Example.—A coal yields 9600 cubic feet per ton of 16-candle gas; how much will it yield of 14 and 17 candle gas respectively?

$$9600 \times 16 = 158,600$$
. Then  $\frac{158,600}{14} = 10,971$  c. ft. and  $\frac{158,600}{17} = 9035$  c. ft.

The above presupposes that the period of distillation is extended or abridged, as the case may be.

## GAS PRODUCTION.


The carbonization or destructive distillation of the coal for the production of gas is accomplished in the retort-house.

This, the first process in gas making, is also the most important. Any want of economy here (and the word "economy" implies efficient apparatus, proper conditions of working, and good management generally), cannot be compensated for in any of the subsequent processes or stages to which the gas has to be subjected, or through which it has to pass before it reaches the consumer.

In the earliest days of gas manufacture, the retorts, which were of cast-iron, were placed or arranged both in the vertical, the inclined, and the horizontal position.

The vertical retort was the first. This was objectionable by reason of the coal consolidating in a mass, preventing the free exit of the gas, and making it a matter of difficulty to remove the resultant coke.

The other two were an important advance on the vertical form, and were so considered by gas engineers, inasmuch as both the charging and discharging were accomplished with greater ease, and, what is indispensable to prevent loss of illuminating power, an open space was




left between the coal and the upper surface of the retort for the issue of the gas.

Retort House.—The retort house may be adapted for either a

single (Fig. 8) or double stack of retorts (Fig. 4), and may be of the ground-floor or stage-floor type of erection according to circumstances.

The ground-floor house (Figs. 8 and 4) is the most usual form. In this, the structures and appliances are all above ground, and the process of gas making is conducted on the one floor on which the retort stack and its appurtenances are erected.




F16. 4.

Now that generator furnaces for the production of gaseous fuel for heating the retorts under the regenerative system are coming largely into use owing to their proved efficiency, provision is made for them in houses of this class, by carrying the foundation of the retort stack to a depth of at least 9 ft. 6 in. below the ground-floor line, and forming an underground passage about 7 ft. or 8 ft. wide all round the stack if it is a double one, or in front, if single. (See Figs. 8 and 4.)

In all cases of ground-floor houses when the site admits of this arrangement, it should be adopted, and this, too, even in comparatively small works. A house with a provision of this kind may be described as a semi-stage-floor house (Figs. 8 and 4).

The stage-floor house proper (Fig. 5) has not only a ground-floor,

but a stage-floor at an elevation of 10 ft. or 12 ft. above the other. From this latter the retorts are charged and drawn, the hot coke being discharged through suitable openings in the stage-floor on to shoots,



and thence to the floor underneath, where it is slaked, and whence it is wheeled or otherwise conveyed away into the coke yard.

A house of this kind costs considerably more than a ground-floor, or semi-ground-floor, house; but, in large works especially, it can be operated with more economy, and the advantages it offers for the removal of the coke, the application of the regenerative system, and in other ways, are very great.


Suitable openings are left in the walls of the retort-house at a height slightly above the stack, for the admission of air and light. The ventilation should be good, and, with that object in view, the louvre should extend from one end of the roof to the other, and be of ample capacity. Ventilating tubes or towers are sometimes used alone or in addition to the louvre ventilator. These are efficient and present a good appearance.

The clear space in front of a retort stack should not be less than 18 feet. When it is intended to employ machinery for charging and drawing the retorts, 22 feet is required.

For convenience in hand-charging and drawing, a slight inclination—say 6 in. to 9 in. in the whole width—towards the stack, should be given to the floor. This allows the waste water from the slaked coke to run into the ash-pans, and is also handier for the stokers in charging.


About 8 feet of the width of the floor, immediately in front of the stack, may be laid with cast-iron plates, or paved with fire-bricks set on edge; the remainder of the floor flagged with 4-inch flags. Blue Staffordshire bricks or tiles, 4 inches thick, make an excellent paving for a retort-house floor; and, when these are used, the fire-bricks in front may be dispensed with.

In a house intended for inclined retorts (Figs. 6 and 7), the con-



ditions of size differ from the others. Here the height is greater, and the width varies according to the length of the retorts, whether 12 ft., 15 ft., 18 ft., or 20 ft., and as to whether it is required to contain a

single stack, or two stacks of settings face to face (Fig. 6), or back to back (Fig. 7). We prefer Fig. 6, as admitting of better ventilation on the higher operating floor. On this floor, with back-to-back retorts, the heat is often unbearable.



The following may be taken as convenient dimensions of retorthouses of the different types:—

House for a single stack of horizontal retorts—Width, inside, 80 feet. Height from charging floor to springing of roof, 20 feet.

House for a double stack of horizontal retorts—Width, inside, 60 feet. Height from charging-floor to springing of roof, 28 feet. Height from basement floor to springing of roof, 88 feet.

House for two stacks of 18 feet inclined retorts, set face to face—Width, inside, 84 feet. Height from discharging mouthpiece floor to springing of roof, 38 feet. Height from basement floor to springing of roof, 48 feet. Width of floor space between the two stacks, 30 feet. Width of stack, 15 feet; space at back, 12 feet.

When designing a House for inclined retorts, recently, the writer made an opening six feet wide, running the length of the house, in the coke discharging floor, to admit of the effectual ventilation of the basement. This can be done in inclined retort houses where the room required in front of the benches is less than in a house with horizontal retorts. A protecting hand-rail extends on both sides of the opening.

Where elevating and conveying machinery are used, the walls in each case require to be about 82 feet high from charging floor.

Wrought-iron or steel, trussed, or arched roof, with ventilator, and slated, or covered with corrugated-iron sheets.

Corrugated-iron sheeting, being lighter than slates or tiles, admits of the principals and purlins being placed wider apart, so reducing their number. The first cost of a roof of this description is less; it is less affected by wind; but its durability is inferior to a slated roof. The sheets should not be thinner than No. 20 gauge.

Retort Stack.—This necessarily varies in size and general construction according to the number of retorts, their dimensions and arrangement in the setting.

In the smaller works a single stack suffices—i.e., a series of ovens or benches about  $10\frac{1}{2}$  feet in depth, containing settings of three, five, six, or seven retorts in an oven; the retorts being 9 feet long each.

In the larger works the stack is double, and contains settings of six, seven, eight, or nine retorts, 20 feet long; either "throughs," or made single by being blocked in the centre. In some large works as many as ten and eleven retorts are set in one bed, with an elevated travelling stage in front from which the higher retorts are charged and drawn.

The following details will be found adequate for the erection of a stack with benches of seven large retorts of any shape, and either single or throughs, set as shown in Fig. 8.

The ovens are 8 ft. 6 in. wide, 8 feet high from floor-line, and 20 feet through, inside measure.

Height to top of bench, 10 ft. 3 in.


Excavation for bench, 8 feet deep. For generator furnaces, 9 ft. 6 in. deep.

Place therein bed of hydraulic lime or Portland cement concrete, 14 inches thick.

Upon this build the brick footings of the division walls of ovens, of good hard common bricks, set in lime mortar.

When these are built, fill up between with a further layer of concrete, 18 inches thick.

Division walls of ovens above footings, 18 inches thick, built of best fire-clay bricks, set in fine, well-tempered fire-clay.



Frg. 8.

Floor of ovens paved two courses on edge with fire-bricks set in fire-clay.

Arched roof of ovens, 14 inches thick, formed of three rings of firebricks moulded to the proper radius set in fire-clay.

Two flue-holes in crown of arch, 12 inches square, communicating with main flue on stack. Damper tiles to be provided for these, 27 inches long, 16 inches wide, 3 inches thick. When the main flue is underneath the stack, the flue-holes in crown of arch are not required.

End or buttress walls of stack, 8 ft. 4½ in. thick, of common bricks, built in with the fire-brick work of stack, and faced with fire-bricks laid in good lime mortar.

The whole of top of stack haunched up five courses above the top of the arches, so as to make the total height of 10 ft. 3 in. from floorline, of good common bricks faced with fire-bricks, laid solid, with close joints, in good lime mortar. Finish with cornice or coping.

Following the example of M. Coze, of Rheims, settings of seven or eight retorts placed at an angle of about 32 degrees have been adopted

by various engineers in this country. These admit of the charge of coal and the discharge of the coke being accomplished with great facility, and with an absence, or at least a minimum, of skilled labour; advantage being taken of the natural slope or angle of repose of the coal, and the law of gravitation, to effect the purpose desired. (Figs. 6 and 7.)

The retorts employed are of the D-shape, tapering usually from  $21 \times 16$  inches diameter at top, to  $28 \times 16$  inches at bottom, and in length from 12 to 20 feet, with a mouthpiece at each end, the gas being taken off from the lower mouthpiece.

The larger pieces of coal are reduced in size by being put through a breaker working in a pit in the coal store. The material is then elevated by mechanical means and discharged into a hopper or hoppers, whence it descends by way of movable charging shoots into the retorts.

In the original Coze system, the mouthpieces are a prolongation of the retorts, and are bent upwards, all reaching the same level. The fall of coal, therefore, from the tipping trucks takes place from one uniform level, which is 8 ft. 4 in. higher than the bottom tier of retorts, 6 ft. higher than the middle tier, and 8 ft. 9 in. higher than the top tier.

It is evident that if a drop of 8 ft. 9 in. is right for the higher tier of retorts, one of 6 ft. and 8 ft. 4 in. cannot be right for the middle and bottom tiers, the retorts all being inclined at the same angle. As a matter of fact, irregular charging is the result.

To overcome these objections, baffling plates are now applied in the shoots to break the force of the stream of coal, and other expedients have been adopted, which have mitigated the drawbacks named.

Mr. Shoubridge, in his charging apparatus, has successfully met the difficulties. In this, the coal contained in the travelling hopper or box is brought down to three different levels, to suit the heights of the three tiers of retorts. The shoots, also three in number, are ranged to meet the same conditions. In addition to these he has an adjustable door at the charger mouth, by which the area of the opening can be varied to suit the conditions of size and dryness or dampness in the coal.

The initial and regulated impulse, due to gravity, which the coal receives in its descent from the hopper and through the charging

shoots, causes it to spread and extend in a uniform layer along the floor of the retort from top to bottom.

The regenerative system of heating is invariably employed for these settings.

The advantages of the inclined or sloping retorts are so manifest and great that their universal adoption is only a question of time.

Retorts.—The materials of which retorts for the distillation or carbonization of coal are made, are fire-clay, either moulded in one piece, or built up in sections, and cast-iron.

In the early days of gas-lighting, and for many years later, castiron retorts only were used. The fact of the iron retorts not being capable of standing a heat sufficiently high for the distillation of coal in the most economical manner, and their liability to rapid oxidation and even fusion in the furnace, operated to cause the adoption of clay in the manufacture of retorts.

Cast-iron retorts are now only employed in the very smallest works, where the gas making is intermittent; here they are useful, as they bear letting down frequently without suffering damage. As carbonizers they are not economical, because the heat which they will stand is not high enough to produce the best results in the yield of gas from the coal. The round, 15 inches diameter, and D-shaped,  $15 \times 18$  inches, are the handiest, and 7 ft. 6 in. is a convenient length. They are usually made  $1\frac{2}{3}$  inch thick, with an ordinary flange, to which the mouthpiece is attached. Their weight is 16 to 18 cwt.




F16. 9.

Fraser's ribbed retort (Fig. 9) is an improvement on the ordinary form.

Clay retorts, in the face of much prejudice and opposition at first, gradually advanced in popularity as their merits became known, until at the present time their use is almost universal. Single clay retorts are burnt

better and more uniformly when the ends are left open in the kiln; the backs are easily jointed in setting, care being taken to butt them close up against the wall. The clay retorts employed are either round (Fig. 10), oval (Fig. 11), or D-shaped (Figs. 12 and 18) in cross-section, their usual diameter being respectively 16 inches or  $21 \times 15$  inches. The round, by reason of its shape, is the strongest and most durable; but it is not equal to the others as a carbonizer.

Clay retorts are usually made 8 inches thick; the flange or swelled portion to which the mouthpiece is bolted being 4 inches thick, and 8 inches broad, the neck tapering to the thickness of the body.



The following are useful and convenient sizes of clay retorts:—
Round . . 16 in. diam.


Oval . . 21 × 15 in. ,, D-shaped, 21 × 15 in. ,,

The weight of a clay retort of the above sizes is from 14 to 16 cwt.

For very small works the following sizes are more suitable:—Round . . 14 in. diam.

Oval.  $.18 \times 14$  in. ,, D-shaped,  $.18 \times 14$  in. ,,

Inside measure, and 9 feet long outside.



Retorts made of fire-bricks and tiles or blocks rebated or grooved together and jointed with fire-clay are extensively in use (Fig. 14). In the matter of durability they possess a clear advantage over the moulded clay retort, their life being three or four times that of the other; and though their first cost is more, this

is compensated for by the saving in wear and tear.

Large retorts of this class, 80 to 50 inches wide, which at one time were common enough, are objectionable for many reasons. A large area is exposed to the cold air every time the charge is drawn, and the time occupied in drawing them is necessarily considerable. Again, there is a tendency to allow carbon to accumulate in such retorts, because in the ample space the inconvenience of the presence of a thick body of carbon is not felt by the men in drawing and charging. If the required temperature, however, is kept up under these circumstances, it must be at an excessive expenditure of fuel and labour. The greater depth of the coal, and the constant inequality of carbonization

between the inner and outer portions of the charge, is also a serious drawback to their use.

Retort Settings.—The first and indispensable requisite for good retort setting is to ensure a solid foundation. Nothing will atone for the want of this. It should also be dry, otherwise heat will be abstracted from the furnace.

The joints of the brickwork should be made with fire-clay mortar; they should be as close and fine as it is possible to make them. Each brick should be dipped in water, placed in position, and then gently but firmly bedded home.

The retorts in a setting should be supported by transverse walls resting on a solid foundation, so that they may satisfactorily bear the strain of working during the time they are expected to last. It is an error to suppose that the brickwork causes a diminution in the heat. Take the case of two benches of retorts set, the one with as much brickwork as is required for proper support without obstructing the draught or unnecessarily covering the retort surfaces; and the other having the least possible quantity of brickwork, supporting (say, for example) the retorts only at their extremities. In getting these benches in action for the first time there can be no doubt the latter would be the first to attain the desired temperature; but although the former would require a little longer time, and the expenditure of more fuel at first, the superior regularity of its action over the other in distilling the gas from the coal will scarcely be questioned.

No doubt the thinner the retorts themselves, compatible with strength, the better, so that the heat may the more readily pass to their interior. But the circumstances attending the retort as the vessel containing the material for distillation are not to be confounded with those appertaining to the adjacent brickwork. This need not be more than is reasonable, but it is better to err on the side of excess than too little.

When the retorts are "through" they are usually in three pieces, jointed together, and have a mouthpiece at each end. The advantages gained in using this kind of retort are important. The accumulation of carbon is less, owing to the absence of backs. The current of air which is drawn through their interior every time they are charged tends to loosen any carbon deposit that takes place. More heating surface for carbonization is obtained without additional expense, and

that in the hottest part of the oven. They are also drawn with greater facility. The scoop (Fig. 85, p. 69) is generally used in charging these retorts. As they have to be drawn and charged at both ends simultaneously, they cannot, where the scoop is used, be conveniently worked where the stokers are fewer than six in number.

Dimensions for a setting of three large sized clay retorts, 8 ft. 6 in. long:—

Width of oven, 5 ft. 2 in.; height, 6 ft. 8 in.; depth, 8 ft. 7 in.

Width of furnace at grate bars, 9 in.

Width of furnace at springing of arch, 16 in.

Length of furnace, 80 in.

Height from floor-level to underneath the flanges of the two bottom retorts, 2 ft. 8 in.

Number of grate bars, two; 30 in. long each, made of 2 in. square bar-iron.

Dimensions for a setting of five large sized clay retorts, 9 ft. 4 in. long:—

Width of oven, 8 ft.; height, 7 ft. 6 in.; depth, 9 ft. 5 in.

Width of furnace at grate bars, 10 in.

Width of furnace at springing of arch underneath the middle retort, 18 in.

Length of furnace, 80 in.

Height from floor-line to underneath the flanges of the bottom retorts, 2 ft. 8 in.

Number of grate bars, two; 80 in. long each, made of 2 in. square bar-iron.

Dimensions for a setting of seven large sized clay retorts, 9 ft. 4 in. long:—

Width of oven, 8 ft. 6 in.; height, 8 ft.; depth, 9 ft. 5 in.

Width of furnace at grate bars, 12 in.

Width of furnace at springing of arch, 20 in.

Length of furnace, 86 in.

Height from floor-line to underneath flanges of two bottom retorts, 16 in.

Number of grate bars, three; 86 in. long each, made of 2 in. square bar-iron.

A setting should never, when it can be avoided, be put into action immediately on completion, as the application of strong heat to the damp clay is liable to crack and open the joints and cause "short circuiting," besides destroying the brickwork. The setting ought to be allowed to stand at least fourteen days, in order that it may be gradually dried and hardened. A slow fire should then be lighted in the furnace and kept going for another fourteen days to complete the drying process, the damper to main flue being entirely closed, but the feeding door and the sight and hand holes kept fully open.

On putting the bench or oven into action, the heat should be applied gently at first, the damper being gradually opened a little more each day until the proper temperature is attained. When the retorts have reached a dull red heat, a light charge of coal thrown into them assists the development of the required temperature, and tends to preserve them in good condition. By careful attention to these points, the cracking of clay retorts on first "gaiting" may be entirely avoided.

A cutting heat from the furnace can be prevented, or greatly modified, by having ample nostrils in the furnace arch. There should, therefore, be no undue contraction of the nostrils. It is here where the evil in some settings exists, obstructing the passage, producing cutting draughts, and hastening the destruction of the brickwork. With ample space for the exit of the hot gases or flame from the furnace or combustion chamber into the oven and through the flues, the best results, both as regards heating and economy of fuel, are obtained.

To prevent radiation, the front wall of the oven should be a brick and a half, or 14 inches, thick; the division walls between the ovens two bricks, or 18 inches, thick; the back wall, where the retorts are not "throughs," 14 inches thick.

The duration of clay retorts greatly depends on the setting. When the retorts are properly supported, and suitably protected at points from the cutting heat of the furnace, they will last for two or three years; otherwise, and this is nearer their average life, they will be burnt out in fifteen to eighteen months.

A setting will break down not only from wear and tear and high heats, but owing to the contractility of the materials composing it. The lesson to be drawn from this is that only such materials as are thoroughly shrunk by hard firing should be used. In moderate sized works, where coke firing is employed, each single horizontal retort should be of capacity sufficient to hold a charge of from 2½ to 8 cwt. of coal; and with five or six hours' charges the yield per mouthpiece with good bituminous coal should be at the rate of 5500 to 6500 cubic feet per diem of twenty-four hours.

Where heating by regenerative furnaces is adopted, the charges may be heavier or more frequent; and the twenty-four hours' yield per mouthpiece will range from 7000 to 9000 cubic feet, according to the quality of coal used. Even this yield is exceeded by the inclined retorts when their length is 18 or 20 feet and they are heated and worked under the best conditions.

Now, eighteen months' continuous production at the rate of, say, only 6000 cubic feet per mouthpiece per day, is equal to a total production of about 82 million cubic feet of gas.

The carbonizing temperature of clay retorts ranges from 2010° Fahr. (orange) and upwards.

The following table by Pouillet gives the colours corresponding to various high temperatures:—

								Fahr.
Faint red .								977°
Dull red .								1290°
Brilliant red								1470°
Cherry red								1650°
Bright cherry re	be							1830°
Orange .								2010°
Bright orange								2190°
White heat								2370°
Bright white he	at							2550°
Dazzling white								2780°
Melting point o	f oa	st-iro	n					
White						199	20° to	<b>2010</b> °
Grey .						20	10° to	2190°

The effect of an excessively low heat in the retorts is to diminish the gaseous products, the chief result of the distillation being the production of tar.

In setting iron retorts a space of about 8 inches should be left in the rear, to allow for the expansion of the metal and prevent their being forced out beyond the front wall, with the possible breakage of the ascension-pipes. Fire-clay tiles are invariably used to protect iron retorts from the direct action of the furnace heat. Oxidation proceeds rapidly on their uncovered surface, and the scale should be frequently removed, otherwise the proper temperature will not be maintained. For facility in doing this, sight holes should be left in convenient positions in the front wall of the bench. They should always be scurfed before being let down, otherwise the unequal contraction of the incrusted carbon and the metal of the retort in cooling will cause fracture in the latter. The duration of an iron retort is equal to the production of about 700,000 to 800,000 cubic feet of gas. The best temperature for them is that ranging from 1650° Fahr. (cherry red) to 1880° Fahr. (bright cherry red). Any temperature beyond this is apt to burn or soften, and so cause distortion of the retort.

The Regenerative System of Heating Retorts.—The use of gaseous fuel for heating retorts has made rapid progress of recent




Fig. 15.

years. From a scientific point of view generator (Figs. 15, 16) and regenerative furnaces (Fig. 17) have everything to recommend them. The saving in fuel by their adoption is considerable, even on the best results obtained by direct coke firing, but they offer other marked advantages. "Clinkering" at the base of the retorts is avoided, and consequently wear and tear of settings is reduced: the heats are higher and steadier, and being more easily regulated they save manual labour: the coal is carbonized more rapidly, and thus charges of shorter duration can

be employed, increasing the production of gas per mouthpiece and economizing space in the retort house.

In the generator furnace, the solid fuel is converted into carbonic oxide gas, CO, and if the regenerative system is not superadded, the gas produced is mixed with the entering air whilst the latter is at the ordinary, or at but a slightly higher temperature, unassisted

by the waste heat from the flue. In some instances where the air is heated, the heat is derived from the active heat within the furnace, and so to this extent (as compared with the regenerative method) detracts from the temperature therein.

In the regenerative system invented by Siemens, the hot furnace gases, after they have done their work in the oven, and which, under ordinary circumstances, are allowed to escape up the chimney, are utilized in heating the air required for combustion.

There is quite a variety of generators in actual use, and though they vary in the details of their construction, and in their position either within the arch of the retort bench or outside of it, the principle of action in each is identical.




Fig. 16.

Mr. Webber gives the following concise description of the generator: "There is much difference in the details of generator furnaces as at present constructed by various engineers; but their main features are always alike, and are remarkably simple. The usual form of the generator itself is that of a kiln, generally sunk underground or beneath the level of the charging floor of the retort house; the capacity of the kiln, of course, varying with the amount of work it is intended to

perform; but it is usually about one and a half diameters in height. The form of cross-section of the generator may be either rectangular or round, the former being easier of construction, although, according to Grahn, the latter gives better results. The generator is fed through




Fig. 17.

a hole in the top, covered with an air-tight cap. The gas is usually taken off by an opening near the top. The lower part of the generator, in which the initial combustion commences, is subject to the greatest wear, especially from the formation of clinker. The air is admitted

either by a grate at the bottom of the generator, as in an ordinary furnace, or by openings in the brickwork, which may be either at the sides or in the bottom—which in that case is tapered down to the size of the opening—or by a combination of the two, as designed by Liegel, who puts a fire grate underneath the opening in the bottom of the generator. . . . . The generator should be lined with at least 9 inches of the best fire-bricks, between which and the surrounding walls of common brickwork, about 18 inches thick, a space of about 6 inches is left to be filled with a comparatively non-conducting material, such as asbestos, or even powdered fire-bricks, in order to diminish the loss of heat by radiation.

"The gas channel, by which the products of combustion leave the generator, varies, according to circumstances, from a short connecting chamber to one of considerable length; but the former, or some similar plan, is obviously preferable when it is convenient to adopt it. In all cases the passage, when of any length, must be provided with a damper.

"In most cases a generator is about 3 feet to 8 feet 6 inches square, which is sufficient for heating two large settings of retorts. For one setting half this area will suffice. The body of incandescent coke is usually about 8 feet deep, although it might be reduced to half that depth without vitiating the gas produced; still it is best to keep a considerable margin, in order to avoid risk of interruption in working, which might otherwise be caused by irregularity in charging the generator, which operation would, with the sizes of apparatus above specified, be necessary at four or five hours' intervals.

"The generator may be situated anywhere in the neighbourhood of the retort bench. The furnace gases are admitted to the interior of the retort stack, guarded as much as possible from loss of their acquired heat while in transit, and there mingle with the proper quantity of previously heated air, the mixture being attended with instant combustion." \*

On the principle of regeneration, as applied to the heating of retorts, it may be pointed out that dry air, though diathermanous to radiant heat, takes up heat with extreme rapidity when brought in contact with a hot surface. It is not necessary, therefore, that the hot flue passage through which the secondary air is caused to travel in

<sup>\* &</sup>quot;King's Treatise on Coal Gas," Vol. III., p. 879.

order to be heated before coming in contact with the combustible gases from the generator, should be long-extended and tortuous in its course.

The advantages of the so-called regenerative arrangements as applied to retort furnaces, are due not only, or chiefly (though this is important), to the heating of the secondary air, which is readily accomplished, but largely to the circumstance that the heat of the waste gases, as the latter traverse the passages constructed alongside the furnace, is at a potential higher than that to which the brickwork in the base of the setting, and in the sides of the generator in the absence of the waste gas flues, could possibly attain. The effect of this is to insulate, as it were, the heat of the furnace, minimizing outward radiation and conduction.

Heat, like water and electricity, tends to establish an equilibrium; and the lower the temperature of a body in contact with another at a higher temperature, the greater the abstraction of heat from the latter by the former.

From this it will be evident that the function fulfilled by the heat of the waste gases cannot properly be considered as "regenerative," in the strict sense of that word. Their temperature is necessarily lower than that of the furnace and the inside of the oven. Heat cannot travel from a lower to a higher potential any more than water under normal conditions can travel uphill, and therefore it is not possible for the lower temperature to "regenerate" the higher. The chief function of the heat of the waste gases is by insulation, as already explained, to conserve, in the ratio of their own temperature, the heat generated by combustion in the furnace. If it were possible to enclose the heated ovens of a retort stack on all sides with an envelope of heat, it is obvious that the heat of the ovens would be conserved, a higher and steadier temperature maintained, and that economy of fuel would result.

At the risk of some repetition, it may be pointed out that the secrets of success in generator furnace-building and retort-setting, are:—

- (1) To make sure that the system adopted is a good one.
- (2) To ensure a sound, unyielding and dry foundation.
- (3) To use only the best materials and workmanship.
- (4) To have the joints of the brickwork throughout as thin and close as possible.

And in the working of these:---

- (1) To get up the heat very slowly and gently at the outset, drying the brickwork gradually and thoroughly at a low temperature.
- (2) To charge the generator with hot coke as drawn from the retorts.
- (8) To carefully regulate the primary air supply, and keep the ash pans full of water.
- (4) To insist on the generators being kept full of coke. If this is not done, CO<sub>2</sub> instead of CO will be produced in them, the concentrated heat melting down the brickwork, instead of doing good service in the ampler area of the retort oven. The generators should be filled up every time the retorts are drawn.

If a gas manager has complaint to make of the regenerative system and settings and their results, then, one, or other, or all of the above points have been neglected.

Flues and Draught.—For a double stack containing eight or ten overs or benches on each side, the main flue should also be double, and the internal dimensions of each division not less than 86 inches in depth by 15 inches in width. For even a less number of ovens, the size of the flue should not vary greatly from the above.

An insufficient draught, whilst it invariably results in diminished heats, causes a waste of fuel, from the consequent incomplete combustion in the furnace, and the usual hard firing that accompanies it. The flame which is occasionally seen at the top of a retort-house chimney is significant of this defect. The flame is produced by the unconsumed carbonic oxide uniting with its due proportion of oxygen on coming in contact with the atmosphere, and, by combustion, being converted into carbonic acid. When the proper quantity of air is supplied to the combustion chamber, the carbonic oxide produced is there converted into carbonic acid, and the heat thus generated is utilized for the distillation of the coal contained in the retorts.

An excessive draught through the ovens is to be avoided, as well as an obstructed one. If too much air is drawn in, its effect is to reduce the heat, as well as to cause the consumption of an excess of fuel. Hence the importance of being able to control the draught by means of a damper placed at the entrance of the cross flue into the main flue of the bench.

According to the experiments of Dulong,

1 lb. of hydrogen, burning to water, yields 62,585 units of heat.

1 ,, ,, carbon, ,, to carbonic acid, ,, 12,906 ,,

1 ,, ,, carbonic oxide, ,, to carbonic acid, ,, 2,495 ,,

1 ,, ,, carbonic oxide, ,, to carbonic acid, ,, 4,478 ,,

Note.—The English standard unit of heat is the quantity of heat necessary to raise the temperature of a pound avoirdupois of water 1° Fahr. The French calorie is the quantity of heat required to raise 1 kilo. (2.2 lbs. avoirdupois) of water 1° Centigrade.

As a rule, when firing with coke, cleaning off the fire bars once in 12 hours is sufficient. Too frequent cleaning entails a waste of coke, besides reducing the heat of the oven.

Instead of the tall chimney-stalk at the end of the retort house, it is the custom to erect chimneys or shafts of less altitude immediately over the bench, or between the benches, rising a few feet above the roof, and serving for four or more double ovens on each side. These are found to produce a sufficient draught, they are more uniform and regular in their action, and their cost is necessarily less. But as they deliver the products of combustion into the atmosphere at a low level, their use should be restricted to neighbourhoods where the nuisance is unobjectionable.

When the room can be spared, it is best to erect the chimney between, and apart from, the retort benches; so that when the latter need to be taken down and rebuilt, the chimney, being a more permanent structure, remains undisturbed.

Sometimes each bench is supplied with a small shaft for its own use. In some American gas-works the main flue and chimney are dispensed with altogether, the opening in the crown of the bench being found sufficient, it is said, to afford the requisite draught. Even assuming the draught; under such conditions, to be ample for ensuring perfect heating and carbonization, which may be doubted, the objections to allowing the hot fumes to escape into the retort house underneath the roof, are sufficiently obvious to cause the practice to be condemned.

The following is a useful rule for determining the size of the vertical opening in retort-house chimneys about 70 feet in height: Allow 1½ square inches of area for each lineal foot of retort, or, say, 15 inches per mouthpiece. Example.—Required the internal sectional area of a chimney-stalk serving ten double benches of eight retorts, or

sixteen mouthpieces each, five benches on each side of chimney; retorts 20 feet through, total, 160 mouthpieces: Then—

$$160 \times 15 = 2400 \over 144 = 16.66$$
 square feet area.

Analysis of Furnace Gases.—For ascertaining the composition of the spent furnace gases from retort settings, Bunte's gas burette is well adapted. A wrought-iron tube is employed for collecting the sample. This is made to project into the centre of the flue, and is continued for some distance outside, so as to cool the gas. The better to obtain an average sample, it is well to aspirate a much larger quantity of gas than is required, and take off the sample simultaneously by a branch tube.

The constituents it is chiefly necessary to determine are carbonic acid and oxygen. The former is absorbed by caustic potash, the latter by pyrogallate of potash. For details of the manipulation, Hempel's or Winkler's works on gas analysis should be consulted.

Should it be also required to determine the amount of carbonic oxide, and especially for the analysis of combustible producer gas, Orsat-Muencke's apparatus is more suitable. The latter operation is, however, seldom carried out, as the composition of the spent gas, or products of combustion, affords a good indication of the efficiency or otherwise of the furnace and setting.

Under good conditions the spent gas should not contain less than 15 or 16 per cent of carbonic acid, nor more than 1, or, at most, 2 per cent. of oxygen.

Carbon Deposit.—In the distillation of coal a deposit of carbon takes place within the retorts, which, if allowed to go on accumulating, eventually seriously contracts their internal area, and causes a diminution in the heats.

This deposit is due principally to the pressure produced by the resistance offered to the passage of the gas through the different apparatus.

Its removal by scurfing with chisel bars in the ordinary way is always more or less attended with damage to the retorts; the more so as they require to stand off for 6 or 12 hours, to loosen the carbon by the admission of air, before applying the bar.

Different methods of scurfing have been tried with varying success; the best probably being that by which a current of air and steam is

made to impinge upon the carbonaceous deposit; but, after all, the best plan of obviating the difficulty is to prevent the deposit as much as possible, by minimizing the dip, by employing an exhauster to reduce the back pressure; and by frequently scurfing the surface of the retorts with a rounded steel scraper.

In the slaking or quenching of hot coke, water is a necessity. It is true that if the coke is drawn from the retorts into iron barrows, and a close cover placed over it, the confined gases, in the absence of atmospheric oxygen, will gradually arrest combustion in the mass; and this method of dealing with the coke is sometimes adopted with a view to abating the nuisance of the escape of steam charged with sulphurous vapours from the retort house, and to preserve the coke for sale in a dry and bright condition. Where the production of coke is great, however, as in the case of large works, this is an inconvenient, if not impossible, method of dealing with the material.

The quantity of water absorbed by the coke when it is slaked in the ordinary way is comparatively small, not exceeding, on the average, 15 per cent. of the weight of coke in the first instance, and the bulk of this evaporates when the coke is deposited outside the retort house in the open air, about 8 per cent. of moisture being permanently retained.

In moderate sized works, skilfully conducted, about 3½ cwt. of coke, or 25 per cent. of the production (say, 18 cwt.) of coke per ton from Newcastle and other high-class bituminous coals, is used as fuel to carbonize one ton of coal.

In large works, under the most favourable conditions, and with the ablest management, the consumption of coke for heating the ovens may be reduced as low as 15 to 20 per cent. of the production.


In small works, one-third the production of coke is nearer the average consumption.

Radiation from the benches is reduced, and fuel economized to an extent greater than might be supposed, by temporarily bricking up the furnace doors and the mouths of all retorts in beds not in use, in proximity to others in action.

Where tar is unmarketable, or but of low value, and there is a ready sale for coke, the former should be employed in heating the retorts.

Its application is exceedingly simple. When applied to an ordinary furnace, the ash pan is first filled up with breeze; the door

is then removed and the door space bricked up, leaving two holes, one above the other, about 4 by 8 inches. The tar is supplied through the top hole, the bottom hole being for the admission of air, and to allow of the fire being stirred when required. A piece of 2-in. angle-iron, or a grooved fire-clay slab, or other convenient channel, is inserted into the furnace through the top hole, and down this the tar is made to flow in a stream about 8-16ths of an inch thick. (Fig. 18.)



The tar can be taken direct from the hydraulic main, or back main, in the bottom of which a 1-in. wrought-iron ferrule, having a stop-cock attached, is screwed. A  $\frac{1}{4}$ -in. reducing coupling is then put on, and this size of pipe brought down to the side of the oven, where the tar is supplied to the trough through a nozzle of the proper dimensions; or a jet of steam directed through the nozzle may be used to spray the tar into the furnace.

As the hydraulic and back mains will not supply all the tar necessary, a pipe should also be brought from a tank or cistern erected in some convenient place outside the retort house. If this tank is placed inside the retort house, the dust arising from the coal mixes with the tar and hinders its flow. Into this tank a supply of tar should be pumped from the tar well as required.

The objection to the use of tar as fuel, as above applied, is that the intense heat which is generated at the point of combustion

soon destroys the arch or tiles underneath the middle retort, breaking the latter down.

As this retort, in the ordinary setting of fives and sevens, is the one usually first burnt out, it is advisable to restrict the use of tar to those benches that have been at work for a length of time, and in which the middle retort is either much burnt or already destroyed.

Numerous other expedients for firing by means of tar have been put forward, but the above has the merit of efficiency with cheapness and extreme simplicity. In the event of a deficiency in the supply of tar, this furnace is readily reconverted for coke firing.


About 50 gallons of tar used as fuel will carbonize 2½ tons of New-castle coal, or a mixture of Wigan coal and cannel, in 24 hours.

At this rate about 6 gallons of tar are equal to a sack (8 bushels) of coke.

The Dinsmore System.—This system (so called after its inventor) of enriching gas by the conversion of a portion of the hydrocarbons present in the tar into permanent gas of a high illuminating power, has been adopted at Widnes under the supervision of Mr. Isaac Carr, who has introduced various modifications in the method of its application, by which results of an important character have been obtained. The chief obstacle to the success of all previous attempts in a similar direction was the blocking of the ascension-pipes and hydraulic and foul mains with pitch. This difficulty has now been overcome. With one-third of the carbonizing plant at work on the tar system, about 10,000 cubic feet of gas per ton, of an illuminating power equal to 19 standard candles, are obtained from an inferior class of coal.

Retort Bench Mountings.—The brickwork of the retort stack is braced together with buckstaves and tie rods, applied both longitudinally and transversely, to enable it to resist the expanding action of the heat. The buckstaves are preferably made of wrought-iron or steel, either rolled H (Fig. 19), or rail section (Fig. 20); or formed of two flat bars 6 in. wide and at least 1½ in. thick, with cast-iron distance pieces between, through which the two flat bars are riveted together with ½-in. rivets. (Fig. 21.)

The boss A, with hole therein, is intended to receive the wroughtiron pipe, 1-in. diameter, leading from the 3-in. water main on the top of the retort stack. To the end of this pipe a brass swivel is attached, and from this again a piece of 1-in. steam tubing, 11 inches long, projects, having a brass swivel cock at its end; a tube of  $\frac{3}{4}$  of an inch



diameter is screwed thereto, and terminates in a 4-in. brass rose jet, through which water is discharged for slaking the coke as it is drawn from the retorts. (Fig. 22.)

The tie rods are of 2-in. round or square iron, threaded 6 in. at each end, and furnished with strong hexagon nuts and washers.

A 2-in. steel plate, extending the width of the stack, and 2 ft. deep, placed in a recess at the end or buttress wall opposite the springing of the arches, and underneath the buckstaves, helps materially to bind the brickwork together, and prevents undue expansion.

The ash pan, where coke firing is employed, may be of wrought plate-iron 5-16 in., or of cast-iron 7-16 in. thick. The usual dimensions are: Length 5 ft., width 12 in., depth 10 in., outside. (Fig. 28.) The pan should always be kept charged with water. The water, heated by the glowing coke, gives off steam in considerable volume, and this, rising underneath and between the furnace bars, contributes to the durability of these by keeping them comparatively cool. In its passage through the hot coke the steam is decomposed into its constituent gases, the hydrogen adding to the furnace fuel, and the oxygen promoting combustion. A tidy fire about, with the ash pan charged with water and reflecting the bright fire between the bars, is one of the indications of good stoking.

The grate bars are two or three in number and 80 in. to 86 in. long, made of 2-in. wrought bar-iron, and supported on two bearing bars 8 in. square in section, 24 in. long, their ends built into the brickwork.

The furnace frame and door (Fig. 18) are of cast-iron, the latter with pocket to receive a tile or fire-brick lining. Cast-iron cleaning-out and sight-hole boxes with plugs are built into the front wall of the setting.

The retort mouthpiece, of cast-iron, is round, D-shaped, or oval, to suit the retort, and 15 in. deep from front to back, with plugs for fastening to the retort with seven \( \frac{7}{2} \)-in. bolts. It has a socket to receive the ascension-pipe end, and is furnished with lugs, cross bar, and screw for securing the luted lid, which is of plate iron or steel \( \frac{1}{2} \) in. thick, with lug on each side, and dished.

The following are the details of a mouthpiece for an oval retort 21 in. by 15 in., and will serve as a model for any other size and shape, allowance being made for varying dimensions. (See Figs. 24 to 27.)

Depth from front to back, over all, 15 in.

Thickness of metal in front portion, § in.

Ditto in lip, 1 in., and planed level.

Ditto in flange, 1 in.

Width of flange in front, 84 in.

Ditto at back, 4 in.

Number of bolt holes, eight; diameter, 1 in.

Ear-box on each side, with slot 2 in. by § in.

Socket, to receive end of ascension-pipe, 5 in. in height, and 61 in. diameter inside; centre 5 in. from front.

Bolts, for securing mouthpiece to retort, eight; diameter, ‡ in.; screwed and nutted at both ends.


Lugs of wrought-iron, 14 in. long, 2 in. broad, and § in. thick; one with jaws and pin for hinging cross-bar, the other cranked and notched as in Fig. 27. Slit at opposite end, 2 in. long, § in. wide; wedged to ear-box.

Cross-bar of wrought-iron, 25 in. long, 2 in. broad at each end, and  $\frac{1}{2}$  in. thick. Middle part  $2\frac{1}{2}$  in. broad, swelled out to 2 in. thick, with 1 in. screwed hole through centre.

Screw, 10 in. long, with square thread 7 in. of its length.

Cross handle, 14 in. long, 3 in. round-iron.

Lid, 1 in. thick, plate-iron, dished, with lug on each side.



# Cements for Jointing Mouthpieces,-

To clay retorts-

Three-fourths by weight of fire-clay. One-fourth by weight of iron borings.

When ready to connect, mix with ammoniacal water. Use no sulphur. 'Or,—

20 lbs. gypsum (sulphate of lime) made into a pulp with water.

10 lbs. iron borings saturated with a strong solution of sal ammoniac.

Mix well together till of a consistency fit for use.

In fixing the mouthpieces to clay retorts, the flange or face of the retort should be notched all over with a sharp-pointed hammer, or a slight channel cut all round (this is best done by the retort maker in course of manufacture), for the cement to bed into when the bolts are screwed up.

For iron retorts-

2 lbs. fine clean iron borings.

1 oz. sal ammoniac.

1 oz. flowers of sulphur.

Mix together and keep dry. When required for use, add water to bring the mixture to a proper consistency.

Besides being fastened with bolts, mouthpieces should always be supported by cross-bars pressing against the flanges, the ends being secured to the buckstaves.

Luting for Retort Lids.—Ordinary lime, or spent lime from the purifiers mixed with fire-clay or common clay, and worked up into mortar.

The following makes a tough persistent luting:-

1 part lime.

2 parts moulding sand.

Ground up together, with water, in a mortar mill.

Self-sealing retort lids are extensively used. This lid is not removed from the mouthpiece in charging the retort, but swivels round with the hinged cross bar, to which it is secured. It is made in any form to suit the shape of the retort, with upturned semi-circular edge, faced true. This pressing against the flat edge of the mouthpiece, which is also faced, makes a gas-tight joint without the intervention of luting.

The ascension or stand pipes may be of cast or wrought-iron, and should not be less than 5 in. diameter. Pipes of 6 in. diameter are commonly adopted.


The best caulking material for ascension-pipes at their junction with the mouthpiece socket, is ordinary ground fire-clay, or slaked lime, made of the consistency of putty. These, when pressed down into the space between the spigot and socket, make a perfectly tight

and durable joint, and are easily removed when the retorts need renewing. On the other hand, when the joints are caulked with iron cement, the labour in cutting it out and the risk of splitting the socket are considerable.

Ascension-pipes occasionally become choked to a greater or less degree with thick tar, pitch, and other carbonaceous matter. When this occurs, it is well to let as many as can be spared at once stand off for a shift (provided the retorts are in condition to admit of this), drawing the charge and removing the bonnet or plug from the top of the bridge-pipe. The heated air making its way through the smallest aperture will thoroughly clear them of the obstruction.

Drawing off the thick tar from the hydraulic main, and allowing free exit of the gas from the latter, and keeping the pipes cool, are the best preventives of choking. This latter may be accomplished to a great extent by making the front walls of the ovens 1½ bricks thick, so preventing undue radiation from the bench, and having the mouthpieces of the retorts so constructed as to allow of the pipes standing 6 or 8 inches away from the front wall of the oven.

The bridge and dip pipes are of cast-iron and 5 in. is the usual diameter. The bridge-pipes are made in various useful forms



(Figs. 28 and 29). The chief consideration in the design should be to secure easy access to their interior for clearing purposes in case of

The quantity of water thus yielded varies with different coals, but the average yield may be set down at 16 gals. per ton. It has previously been explained (see page 15) that a portion of the steam from wet coal is decomposed in the hot retorts, being resolved into its constituent gases. It will be seen, therefore, assuming the correctness of this hypothesis, that two opposite processes are being carried on simultaneously in the retorts—the analytical and the synthetical—and this apparently inconsistent action may be explained by the original character of the substance acted upon—the steam in the one instance, and the gases, oxygen and hydrogen, in the other—and their proximity to, and period of contact with, the hot surface traversed by them.

The strong affinity which exists between this water and the ammonia impurity in the crude gas, causes the absorption of much of the latter by the former, producing what is, roughly speaking, a solution of ammonia. This again, by reason of its affinity for sulphuretted hydrogen and carbonic acid, absorbs a proportion of the gases named, reducing the amount of these impurities in the gas, and thus is produced the complex liquid designated "ammoniacal liquor."

The hydrocarbons contribute largely to the illuminating power of the gas, and it is therefore desirable to retain them in the permanently gaseous form. Some of them, especially such as are of the greatest density, are reduced to the liquid state by the mere mechanical reduction of their temperature; whilst others of equal specific gravity, and many of those of lower density, undergo a change from the gaseous to the liquid condition, by reason of the solvent or absorbent action of the liquid contents of the hydraulic main, through which, by reason of the dip, they have to pass; or with which, in the absence of the dip, they come intimately in contact. The former may be classed as hydrocarbon vapours, the latter as gaseous hydrocarbons. It is thus evident that the process of condensation begins at the hydraulic main, the results there produced materially affecting the quality of the gas.

Those hydrocarbons that are changed to the liquid form by this slight diminution of temperature, it is probably impossible to retain in the gas under any circumstances whatsoever. With the more volatile, though still heavy, hydrocarbons, the case is different; the power of retaining them in the permanently gaseous form is within the bounds of possibility, and these are, therefore, of the greatest interest to the gas manufacturer.

A further class of hydrocarbons are not liquefied at all under ordinary conditions, and there should never be any difficulty experienced in keeping them in the gaseous state.

The retention in the gas of the second class of hydrocarbons—viz., those which, though of high specific gravity, it is practicable to retain in the gaseous state, and how this is most likely to be accomplished, greatly concerns the gas-maker. It has been assumed that the mere reduction of temperature between the retort-mouth and the hydraulic main will not affect their gaseous condition. Under what other circumstances, then, are they condensed in the hydraulic main, and in the subsequent mains leading to the condenser? The answer is clear, and is what has been already indicated—viz., by the affinity which exists between them and the already liquefied hydrocarbons present in the mains.

The cooling of the gas gradually is a provision the wisdom of which is unquestionable, and the plan of causing it to make the circuit of the retort house in pipes is probably the best method of accomplishing that object; but the deposited tar in the hydraulic main and in the foul main at the point, as near as can be ascertained, when its temperature has fallen to about 110° or 100° Fahr.—the temperature at which its absorbent powers come into most active operation—should be drained away direct to the tar-well by its own separate conductor.

The chief advantages believed to accrue from lengthened contact of the gas with the tar are, first, the absorption by the latter of naphthalene that would otherwise be carried forward to be deposited, by reason of the decrease in temperature and other causes, in the mains on the works, and even in the street mains, service pipes, and the internal fittings on the premises of consumers; and, secondly, the absorption also of a considerable portion of the obnoxious sulphur and other compounds.

These advantages will not be forfeited by the direct removal of the bulk of the tar, because sufficient light tar will be left in the circuitous gas main to absorb any excess of naphthalene vapour present, and even to assimilate a portion of the sulphur and other impurities. Besides this, as the general effect will be to leave a larger proportion of the gaseous hydrocarbons in the gas, these, by virtue of the power which they possess in common with the liquid hydrocarbons, of assimilating—and, in this special case, of suspending—other hydro-

carbons, will necessarily assist in retaining in the permanent form a portion of the naphthalene that would, in presence of the greater bulk of tar, have been liquefied and deposited. By a similar train of reasoning, the fact of the inferior quality of the tar produced from the richer cannels, as compared with that from coal, may be explained.

In dealing with this subject, it has been assumed by some that no absorbent action is likely to result so long as the tar with which the gas is in contact is at a temperature of about 100° Fahr., and above: and that, therefore, the dip in the hydraulic main causes no diminution in the amount of hydrocarbon gases present. It has even been assumed that the tar in the main gives off a proportion of hydrocarbon vapour. and in this way increases the illuminating power of the gas. On reflection, however, it will be plain that this argument is altogether untenable, for it is scarcely possible to conceive that hydrocarbons which have already been liquefied at a high temperature, can again, at a lower .temperature, assume the gaseous or vaporous form. There can be no doubt that the heavy tars have an absorbent action, less or more, at all temperatures, being greatest at the lowest; and this being so, the passage of the gas through such tars by reason of the dip in the hydraulic main, must have a prejudicial effect upon the illuminating constituents of the gas. On the other hand, where means are employed for removing the heavy tars from the main as rapidly as possible after they are deposited, the disadvantages of the dip into the lighter liquors contained therein are reduced almost to nil. This is especially true where the arrangements are such that, by careful adjustment, and an adequate area at the water level, the dip is limited to about three-fourths of an inch.

It is desirable that the ends of the dip-pipes in the hydraulic main should be sealed with the ammoniacal liquor in preference to the tar, the latter not only robbing the gas to some extent of its richest illuminating substances, but offering greater resistance to its passage. Various expedients to accomplish this end have been devised and are in use in well-regulated gas-works.

Livesey and Tanner's Differential Tar and Liquor Overflow and Tar Screen is a useful provision for separating the tar and liquor by means of a perforated screen, preventing the oscillation of the liquor in the main and allowing of a minimum of seal. The arrangement for adjusting the difference of seal required for drawing off the tar and liquor separately according to their specific gravities, is also very ingenious and useful.




Fig. 84.

The hydraulic main, and consequently the dip or seal, can be dispensed with altogether by employing a bridge-pipe with a wing valve in the centre of the bridge (Fig. 84). This is shut by means of a rod depending from the end of the lever, during the operation of drawing and charging, and opened again when the retort lid is closed.

It is well known that the gas as it ascends to the hydraulic main, after being in contact with the intensely heated surface of the retorts in which it is generated from the coal, is of

a comparatively low temperature. The reason of this is not apparent at a cursory glance.

At first sight it would appear as though the action upon the gas in a retort would be similar to the effect upon air by the ovens of blast furnaces, where a million cubic feet are heated in the space of an hour to 683° Fahr., the melting point of lead. So far from this being the case, the permanent gas at its highest temperature does not probably exceed 185° Fahr., though generated in a heat usually reaching 2200°. The reason of the difference in the effect produced in the two instances given, is explained by the fact of the rapid absorption of heat by the volatile constituents of the coal in assuming the gaseous form; this heat becoming latent in the gas, as in the case of the formation of steam in an open boiler.

The following is a record of experiments made by the writer to determine the temperature of the gas as it issues from the retort:—

## Experiment No. 1.

This experiment was conducted entirely under the usual conditions of working.

Clay retort, 20 feet through, one in a setting of seven. Heat, bright cherry red. Hole drilled in both ascension-pipes 3 feet above the mouthpiece. Retort charged with 4 cwt. of cannel.

Temperature indicated on insertion of thermometer through the hole on one side of bench, 198° Fahr.

Temperature indicated on insertion of thermometer through the hole on the other side, 510° Fahr.

The temperatures indicated were clearly not those of the gas. In attaining the higher temperature, especially, the mercury rose by starts at the rate of 3° to 5° at once, evidently caused by hot particles of solid carbon, or other solid or semi-fluid substances, coming suddenly in contact with the bulb of the thermometer.

The remarkable difference in the temperature of the two sides is accounted for in this way. On the side in which 198° was indicated the dip-pipe was probably sealed to a greater depth in the hydraulic main, and consequently the flow of gas was neither as abundant nor as rapid on that side as on the other. This was evidenced by the thermometer on withdrawal being found less thickly coated with tar than in the other case. The gas was in a more quiescent state, and therefore there was not the same rush of hot solid particles against the bulb to raise the temperature abnormally.

It may be noted incidentally here, that indications of temperature thus obtained would prove whether the ascension-pipes at the two ends of a through retort were each taking their due share of the gas being produced.

Experiment No. 2.

The conditions were the same as in the previous instance; but instead of inserting the thermometer directly through the hole in the ascension-pipe, the end of a piece of india-rubber tube, 12 inches long,  $\frac{3}{4}$ -inch bore, was pressed against the orifice, and the gas allowed to flow in a stream through the tube. The object of employing the tube was to obviate, if possible, the contact of the semi-solid or semi-fluid substances previously referred to.

The result was: Temperature indicated on one side 250°, ditto on the other side 824°.

The rise of the mercury was still somewhat irregular, and the instrument, so much as was inserted, was again thickly coated with tar.

Experiment No. 3.

One end of the through retort was now bricked up, being made perfectly gas-tight, the gas passing away by one only of the

ascension-pipes; in point of fact, the retort was made single instead of through.

In a short double-flanged piece of the ascension-pipes, within 8 inches of the top of the mouthpiece, were inserted six layers of iron wire netting, cut into discs, accurately fitting the bore of the pipe. Three of these discs had meshes one-eighth, and the other three three-sixteenths of an inch gauge; and the discs were kept three-fourths of an inch apart by sheet-iron rings, inserted edgeways into the pipe.

The charge, 2 cwt. of cannel, thrown into the retort, happened to be taken from a heap that had been exposed to the rain, and there was considerable moisture present.

The hole through which the thermometer was inserted, as in the previous experiments, was 8 feet above the mouthpiece.

The	following	were the	temperature	s indicated :-
THE	TOTTO MITTIE	MOTO ITTO	<b>ADMINISTRACT</b>	THUICANCU .—

Time. Minute		T	emp. Fahr. Degrees.	Time. Minutes.		T	emp. Fahr. Degrees.
10	•	•	200	55 .	•	•	177
15	•		198	<b>60</b> .	•	•	174
20	•	•	195	65 .		•	172
25	•		192	90 .		•	160
80	•		190	105 .			158
. 85			<b>188</b>	.120 .		• .	150
40	•	•	184	180 .	• .		150
45		•	182	140 .	•		148
50	•	•	179	150 .	•	•	142

Through all the higher temperatures, down to 172°, steam was condensed into drops upon a piece of paper held in the stream of gas issuing from the hole. Tar, though not entirely absent, was nearly so, the instrument on each withdrawal being but slightly coated. The temperature, with but few exceptions, rose with great regularity from that of the atmosphere of the retort house (74°) to the rates observed, showing that the semi-solid particles, which were evidently the cause of the high temperatures previously indicated, had been nearly all arrested by the wire netting.

The higher temperatures, I am of opinion, were due to the presence of steam in the gas in varying proportions, and this latter would be caused by the moisture in the coal.

### Experiment No. 4.

The retort was again charged, this time with 2 cwt. of cannel in a drier state. All the other conditions were as in the previous trial. The following were the results obtained:—

Time Minut			T	emp. Fabr. Degrees.	Time Hour	-		T	emp. Fahr. Degrees.
2		•	•	158	12		•	•	129
7		•	•	174	2	•	•	•	123
12		•		177	2 <del>1</del>	٠.	•	•	122
17				172	$2\frac{1}{2}$				119
22	•	•		171	22			•	118
27		•		169	8	•			116
82		•	•	168	81	•	•		113
75				141	81		•		110
90		•	•	184	_				

During the first half-hour of the charge, the presence of steam, mixed with the issuing gas, was indicated as before, but less abundantly, though still, doubtless, affecting the results obtained. When the temperature of the gas within 3 feet of the mouthpiece was at 174°, it stood at 182° in the bridge-pipe, 14 feet higher up.

Temperature of the Gas in the Bridge-Pipe, 14 feet from the Retort Mouthpiece.

Experin	ıer	ıt.			2-c	wt. Ch	rges.		T	emp. of the Gas.
No. 1	l				retort	charge	d l hour	•	•	135° Fahr.
,, 9	3			•	,,	,,	8 bours			116° "
,, 8	3		•		,,	,,	41 hours			119° ,,

It may be suggested that the effect of passing the gas through the wire netting would be to lower the temperature of the gas, just as the wire gauze on a Davy lamp reduces the temperature of the flame impinging against it. The conditions of the two cases, however, are entirely different. The meshes were sufficiently large to admit of an easy passage for the gas, and the metal would be immediately covered with a thick coating of tar, virtually producing insulation. In addition to that, the temperature within 6 inches of the front of the bench was 208°; and the metal of the ascension-pipe, as well as the inserted wire netting, would, as a rule, be above the temperature of the gas.

The results of these researches will be found to confirm, in a remarkable manner, the deductions of earlier investigators.\*

\* Mr. J. T. Sheard differs from the conclusions attempted to be drawn from the experiments recounted above, and his opinion carries weight with the writer.

In a communication, he says:-

Coal must be raised to 600° F. before any volatile matters whatever are given off, and so-called permanent gases are not formed until a temperature of about 1100° F. is attained. Without being able to dogmatize, it is safe to assume that heavy hydrocarbons-volatile at the temperature of the retort, but liquid, or even solid, at atmospheric temperatures—are first formed; which, with more heat, are gradually broken up into lighter compounds of less complex composition, permanent simple gases being the ultimate products. With the first class of substances the action is similar in effect to the melting of ice into water, and its conversion into steam when sufficient heat is applied. A great portion of the total heat supplied becomes latent in the steam; but the steam is evolved at the boiling temperature, 212° F. at least; that is, it has itself acquired the temperature at which it was formed. So the hydrocarbon vapours formed at 600° F. or 1000° F., must, at the instant of liberation, be themselves of the temperature at which they were evolved from the coal or semi-liquid intermediate product from which they were formed.

Your contention, I take it, however, is that the permanent gases are in a different category because of their greater latent heat, and the fact that they are naturally gaseous at a much lower temperature than that at which they are formed in the retort. It seems impossible to put the matter directly to the test, but I cannot conceive how a particle of gas, formed, say, within a mass of hydrocarbon vapour, can be liberated at a temperature much lower than that of the atmosphere in which it is In default of proving the point in a direct manner, I have tested it indirectly by inquiring whether, assuming the gas to be liberated at the higher temperature, the known laws of cooling are sufficient to account for the great loss of heat

which you observed immediately after the gas had left the hot retort.

The temperature of the gas in the ascension-pipe, 3 feet from the mouthpiece, was found to be 174° F., while in the bridge-pipe, 14 feet higher up, it was 182° F.

I assume that the retort was yielding gas at the rate of 6,000 onbic feet per day, or say 9 lbs. of gas and 9 lbs. of tar and liquor = 18 lbs. total weight of gases and vapours evolved per hour. I take the specific heat of the gas at 2°, and of tar and liquor vapours at 0°6, or a mean of 1°6. Assuming the temperature of the gas as it leaves the retort to be 1000° F.,† while at 8 feet above the mouthpiece it was found to be only 1748 E. then the best distincted between these points in one follows: 174° F., then the heat dissipated between those points in one hour is as follows:—
18 lbs.  $\times$  1.6 sp. heat  $\times$  (1000° – 174°) = 23,790 units.

The temperature of the air surrounding the pipe I take at 208° F. Probably it would be much lower, as that was the temperature found within 6 inches of the front of the setting. Therefore the difference to be dissipated is—

Mean temperature of gas to be cooled,  $\frac{1000+174}{2} = 587^{\circ} - 208^{\circ} = 879^{\circ}$  F.

By Webber's formula (Journal of Gas Lighting, Vol. 32, p. 14), the heat lost by radiation and contact is-

 $[.7583 \times 379 \times 6.5] + \left[ \left( .421 + \frac{.307}{5} \right) + 379 + 2 \right] = 2250$ 

units of heat per square foot of exposed surface per hour. Total heat actually lost as above, 23,790 units. Calculated surface required  $=\frac{29790}{2250}=101$  square feet. In


the mouthpiece  $21'' \times 15'' \times 15''$  there is, say,  $6\frac{1}{2}$  square feet. In 3 ft. of 6-in, pipe there is  $4\frac{1}{2}$  square feet. Total, 11 square feet, or more than sufficient cooling

surface to produce the observed result.

Calculating in a similar manner for the difference between the temperature at 3 feet from monthpiece 174,° and that in the bridge-pipe 132° F., I find there is similar accord between theory and practice, calculation and observation, which appears to give further ground for accepting the assumption started with as a correct one.

<sup>†</sup> The temperature within the mass of coal, 3 feet from the mouthpiece and one hour after charging, has been found to be about 1150° F.

Retort House Tools and Appliances.—For charging retorts by hand, the shovel or the scoop is used.



Shovels with riveted handles are not good in or about a retort house. The heat soon causes the wood to dry in, and the rivets give way and become jagged, lacerating the hands of the men who use them. Socketed handles are the best.

A good handy-sized shovel for charging retorts of the ordinary size is one 16 inches long by 11 inches wide. Firing shovels (for coke) are best made an inch wider. Both should be well turned up at the sides.

The scoop (Fig. 35) is a semi-circular trough of sheet-iron or steel, the length of half the through retort, and of capacity to contain about  $1\frac{1}{2}$  or  $1\frac{3}{4}$  cwt. of coal. It is inserted twice into the retort at each end. Six men are required to charge a through retort with the scoop—i.e., three at each mouthpiece. The method of using it is as follows:—On its being filled with coal one man takes hold of the handle at the end, raises it slightly, the "horse" (as it is called) is placed underneath by a second man, and a third grasps the opposite side. The three then raise the scoop and insert its end into the retort mouth, whereupon the "horse" is released, and the man having hold of the handle pushes the scoop with its charge right into the retort, turns it round, and withdraws it, leaving the charge inside. This operation is repeated a second time; the scoop on the first insertion being turned to the left, and on the second to the right.

Other retort house tools consist of the discharging rake (Fig. 86); auger (Fig. 87); ash-pan rake (Fig. 88); and shovel (Fig. 89); fire tongs (Fig. 40); and pricker (Fig. 41); and coal and coke barrows.

Machine Charging and Drawing.—The difficult problem of applying machinery to the charging and drawing of retorts is one which has occupied the minds of gas engineers from the very introduction of gas-lighting, and its solution has been attempted with varying success. Out of about twenty different contrivances that have been invented for the purpose, not more than three or four remain in use at the present time, and these only to a limited extent. It has been solved most successfully by Mr. William Foulis and Mr. John West respectively, in their well-known ingenious labour-saving machines now extensively used for that purpose.

Clegg attempted to perfect an arrangement by which a continuous supply and discharge was effected; and though he did not succeed in producing an economical and satisfactory apparatus, it is greatly to be desired that other efforts in the same direction may be crowned with success.

#### CONDENSATION.

The cooling or condensing of the crude gas is an indispensable preliminary to its purification. Although the heavier tars are deposited in the hydraulic and foul mains within the retort house, there are lighter tars which continue suspended in the gas in the form of vapour, and are carried forward until a reduction in the temperature causes their deposition.

Although it is commonly said that "thorough condensation is half the purification," the degree of condensation to which coal gas should be subjected after leaving the retorts, and before entering the purifiers, has never been determined with that scientific accuracy which the importance of the subject demands.

With respect to one point there cannot be two opinions—viz., the necessity of guarding against a lower temperature in the gas than 50° Fahr. If condensation is carried beyond this, the lighter hydrocarbons are in danger of being deposited, and the gas impoverished.

The bad effects of excessive refrigeration are shown in the following table, which exhibits the loss of illuminating property in coal gas on exposure to the temperature of freezing point, 32° Fahr.:—

Name of Gas.		ons condensed from of Gas on Exposure t of 82° Fahr.	o <b>s</b>			
Boghead cannel	•	•		$4 \cdot 42$	cubic feet.	
Ince Hall ditto	•		•	•87	,,	
Methyl ditto .		•		•88	"	

From which it appears that the richest gas suffers the greatest deterioration on being subjected to cold.

Experience has sufficiently proved that rapid or sudden, as well as excessive, condensation is an evil to be avoided; and that to prevent the deposition of naphthalene in the pipes, and preserve some of the richer illuminants, the gas should be allowed to travel in contact with the lighter tark until the latter are reduced in temperature to about 100° Fahr. before separation takes place.

With this object in view, the pipe leading from the hydraulic main may be carried with a gradual inclination round the interior of the retort house or other convenient building, and from thence to the condenser; provision, or course, being made to allow the thicker tar to run off at a point near to the hydraulic main. By this arrangement

the gas is slowly reduced in temperature, and some of its most valuable light-giving hydrocarbons, which would otherwise be condensed, are retained within it in the permanent state.

Naphthalene.—In dealing with the subject of condensation, that of the formation or deposition of naphthalene may be appropriately discussed. This hydrocarbon when deposited in the solid state in the apparatus and mains of a gas-works, and in the distributing pipes in the streets, is exceedingly troublesome; sometimes entirely blocking the passage of the gas, and entailing much labour and expense in its removal.

It is generally believed that the presence of naphthalene in gas is due, principally, to the high heats necessarily used in the carbonization of the coal, owing to the partial distillation of a portion of the tar. In the early days of gas-lighting, when iron retorts were used exclusively, and the heats were comparatively low, naphthalene as now found in the mains in the solid state was almost unknown. It was not until clay retorts came to be employed, and the heat of carbonization was increased, that naphthalene made its appearance.

It is well known by its flaky crystalline structure, and its peculiar ethereal odour. It is not soluble in water, but easily so in naphtha; hence its removal is effected by steaming with naphtha vapour, or by pouring that liquid into the obstructed mains and apparatus.

Naphthalene is deposited most freely from gas produced from bituminous coal. Some kinds of coal yield it in greater abundance than others. By using a proportion of cannel along with the coal, the gas, being enriched, is enabled to retain some or the whole of the naphthalene in suspension within it in the gaseous condition. The richer the gas, the more capable it is (under ordinary conditions) of retaining the constituents which contribute to its enrichment and vice versā.

In the year 1877 M. Brémond published an account of a series of valuable researches made by him on the question of the formation of naphthalene and its deposition, in which he showed that (to use his own words) "naphthalene is produced wherever there is condensation of the aqueous vapours contained in the gas; that its deposition is preceded by the phenomenon of the condensation of the water; and that gas absolutely deprived, as far as possible, of aqueous vapour does not deposit naphthalene under the ordinary conditions of temperature and pressure."

It is clear, therefore, that the subject of condensation is one of the utmost importance, if naphthalene, or an excess of it, is to be got rid

of. But however perfect the ordinary condensing apparatus may be, it is almost impossible to deprive gas of its aqueous vapour by this means. M. Brémond therefore adopted other means of drying the gas; and for this purpose he employed an ordinary lime purifier, but instead of filling it with slaked or hydrated lime, he charged it with unslaked lime in lumps. By passing the gas through this unslaked lime he completely desiccated the gas, with the interesting result that the aqueous vapour, and consequently the excess of naphthalene also, was arrested. The gas thus deprived of its moisture was found to have increased in illuminating power to a considerable extent.

This remarkable result of drying the gas had previously been observed by the first London Gas Referees. They found that the gas made at Beckton actually gained in illuminating power in traversing the long length of mains from Beckton to London; and they remark as follows: "In considering the satisfactory result of the novel and somewhat perilous enterprise, the Referees are inclined to account for it [the increase in the illuminating power] mainly by the slow and gradual withdrawal of aqueous vapour from the gas in its long journey. This condensation is very different in character from the sudden withdrawal of aqueous vapour produced by the application of great cold. for it takes place very gradually, so that the water is deposited without any appreciable portion of the hydrocarbons being condensed along with it. In order to ascertain the effect of withdrawing the aqueous vapour from gas, we made several experiments by passing the gas through porous chloride of calcium; the results showing that dry gas has a superiority in illuminating power over ordinary gas to the extent of from 6 to 8 per cent.

The experiments of M. Brémond are recounted to show the philosophy underlying the facts, rather than for the purpose of recommending his remedy, which would be cumbrous in practice.

Various other remedies adopted have proved more or less successful. Mr. Botley accomplishes the retention of naphthalene by carburetting the gas after the holders with petroleum oil in the form of mist, produced mechanically. Another method, which has proved efficient, is to vaporise carburine by means of steam, mixing it in the proportion of about twelve gallons of the oil per million cubic feet of gas passing into the holders. These processes are on the lines indicated in the foregoing arguments dealing with the condensable and other hydrocarbons.

The remedy for the objectionable deposit of naphthalene is thus in the gas maker's own hands to a great extent.

The make of gas, as indicated by the station-meter, is materially affected by the temperature at which it is registered.

At the temperature of 60° Fahr., with the barometer at 30 inches, gas is at its standard volume; and as all aëriform bodies expand 70 1.7 of their bulk at 32° Fahr. for every additional degree of temperature, or about 1 per cent. for 5°, it follows that a quantity of gas, say 10,000 cubic feet registered at 60°, would at 70° become 10,208.5, and at 80° 10.407.

The quantity of heat which will raise a cubic foot of water one degree, will raise 2,850 cubic feet of gas or atmospheric air to the same extent.

Temp. Fahr. Degrees.	Expansion.	Temp. Fahr. Degrees.	Expansion.	Temp. Fahr. Degrees.	Expansion.	Temp. Fahr. Degrees.	Expansion.
32 38 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48	1000 1002 · 085 1004 · 070 1006 · 105 1008 · 140 1010 · 175 1012 · 210 1014 · 245 1016 · 280 1018 · 915 1020 · 350 1022 · 885 1024 · 420 1026 · 455 1028 · 456 1028 · 456 1028 · 456	52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68	1040 · 700 1042 · 785 1044 · 770 1048 · 805 1048 · 840 1050 · 875 1052 · 910 1054 · 945 1056 · 980 1059 · 015 1061 · 050 1068 · 085 1065 · 190 1067 · 155 1069 · 190 · 1071 · 225 1071 · 226	72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88	1081 · 400 1083 · 485 1085 · 470 1087 · 505 1089 · 540 1091 · 575 1098 · 610 1095 · 645 1097 · 680 1099 · 715 1101 · 780 1108 · 785 1105 · 820 1107 · 855 1103 · 890 1111 · 925	92 98 94 95 96 97 98 99 100 110 120 130 140 150 160 170 180	1122·100 1124·185 1126·170 1128·205 1180·240 1183·275 1184·810 1186·845 1138·880 1158·780 1179·080 1199·480 1219·780 1240·180 1280·880 1301·180
49 50 51	1082 580 1084 595 1086 680 1088 665	69 70 71	1075 · 295 1077 · 830 1079 · 865	89 90 91	1115 · 995 1118 · 080 1120 · 065	190 200 212	1821 · 530 1341 · 880 1866 · 300

TABLE.—Expansion of Air and Permanent Gases by Heat.

In instituting a comparison between the production per ton of material at different works, and in testing the productive value of different coals, it is, therefore, necessary to take into account the temperature of the gas at the time of measurement. In ascertaining the specific gravity of gas, and in conducting photometrical observations, the same care should be taken to note the temperature at the time and place of making the experiment.

TABLE.—Giving the Mean Temperature (Fahr.) of every Tenth Day in the Year in the Central District of England. (Box.)

Month.	lst.	11th.	21st.	Month.	1st.	lith.	21st.
January February	Deg. 36·5 37·2 40·1 43·6 50·0 56·4	Deg. 35·6 37·5 41·0 45·0 51·3 57·5	Deg. 87·1 38·5 41·9 47·0 53·8 59·8	July	Deg. 61·2 62·5 58·8 53·5 46·4 41·7	Deg. 61·5 61·7 57·4 51·4 44·0 40·2	Deg. 62·0 60·6 55·5 49·0 42·0 88·4

Condensers.—The Atmospherical Horizontal Condenser (Fig. 42) is one of the earliest forms of the apparatus. Its efficiency has not




Fig. 42.

been generally recognized, owing to the want of a correct appreciation of the conditions on which the condensation of coal gas ought to be conducted, and this has led to its being generally discarded in favour of the vertical form.

The earlier method of construction was to fix it against the outside of the wall of the retort house or other convenient building; the several pipes rising with a slight inclination one above the other to allow of the flow of the condensed products, their ends being connected by  $\square$ -shaped bends.

Graham's condenser (Fig. 48) is an improvement on this. It consists of a series of pipes arranged in pairs side by side, and supported on framework, the end of each length being joined to that of the next. From the inlet at the top, through the entire run of the condenser to the outlet at the bottom, there is a gradual inclination, so that it is simply a flat screw or spiral, such as might be represented




Fig. 43.


by winding a length of soft wire round a piece of board, in which case the two ends of the wire would answer to the inlet and outlet of the condenser. Blank flanges are bolted on the end of each length for convenience in cleansing.


In this arrangement there is a recognition of the fact that length rather than height is the desideratum in an atmospherical condenser. In the ordinary vertical form of the apparatus, the cooling effect of the air on the surface of the upper parts of the pipes is almost nil. This will be obvious when it is considered that the air contiguous to the lower part of the condenser, being assimilated to the temperature of the latter, expands, and so, becoming lighter than the surrounding air, ascends in contact with the pipes, extracting less heat in proportion as it rises.

In addition to the other advantages, the ammoniacal liquor on leaving the horizontal condenser is of a strength equal to 5° Twaddel—a result which it is impossible to obtain from the ordinary vertical form.

The ordinary atmospherical condenser (Fig. 44) consists of a series of pipes, usually 18 feet long, put together in two lengths, and placed upright, through which the gas passes up and down alternately. These enter a rectangular cistern at bottom, in which the condensed vapours are deposited, and from whence they flow to the tar well. At the

top is another cistern, containing water to seal the movable hoods covering each pair of pipes, and for further refrigeration, should such





be required, in warm or sunny weather, small streams being made to trickle down the exterior surface of the pipes.

The annular condenser is considered to be an improvement on the foregoing. In Kirkham's condenser, as improved by Wright (Fig. 45), the pipes are placed in the vertical position, and are of large diameter, each one enclosing a smaller pipe; the two forming an annular space through which the gas is made to flow. Other pipes, placed diagonally, connect the top and bottom of the condensing columns alternate-By this arrangement the gas passes through the annular space always in the downward direction, whilst the current of air moves upward through the interior ventilating pipe. cold weather movable covers are placed over the latter, or butterfly valves are fixed at the foot, for closing, to regulate the air draught, which might otherwise reduce the tempera-

ture of the gas below the desired standard. A small pipe is connected to the bottom of each column to carry away the deposited tar and water into a main laid alongside the condenser, and leading into the tar well.

Instead of the diagonal pipe, extending from the top to the bottom of each column alternately, Mr. Warner has inserted a mid-feather or partition, within the annular chamber. This reaches to within a short distance of the top and bottom, the space at the lower end being

sealed by the deposited fluids, and a short connecting piece joins the several columns at the base. By this modification, a free passage is obtained from end to end for the condensed fluids, and the separate tar main is dispensed with.

Cleland's slow-speed condenser consists of a series of vertical pipes, connected together at the top by a tubular cornice or cap, which serves as the common inlet to the whole series. The stream of gas being thus divided equally amongst the several columns, travels through them in a downward direction and at a comparatively slow speed.

In the lower part of each column, to about a fifth part of its length, is inserted a "bottle brush" of wood or other material, with a dripledge above it to divert the descending liquor on to the centre of the brush, which has the effect of converting the apparatus, to that extent, into a scrubber.

The general result is superior efficiency in condensing, and the yield of a high strength of liquor.

An excellent apparatus (atmospherical) is that known as the battery condenser (Fig. 46). This is an oblong vessel, 12 to 24 inches wide,




Fig. 46.

12 to 18 feet in height, and of length suitable to the requirements of the works. It is divided by internal plates or mid-feathers, placed at distances, equal to the width, apart, extending to within a few inches of the top and bottom of the chest alternately; and the gas passes from the inlet, up and down each division, till it arrives at the outlet. To augment its condensing power, small tubes, 2 inches in diameter, through which the air has free circulation, are passed through from side to side of the vessel, and there securely jointed. These trans-

verse tubes serve the double purpose of cooling the gas, and, by breaking it up and retarding its progress, inducing a natural settlement of the heavy condensable vapours.

It may be taken as a general rule that about 10 superficial feet of atmospherical condensing surface for each 1000 cubic feet maximum gas production per day of 24 hours, should be provided. This is assumed to include the length of foul main extending from the hydraulic main. Moreover, the condenser should be protected from the direct action of the sun's rays, or otherwise water should be made to trickle down the outer surface of the pipes during sunshine.

Mr. Livesey, in some of his condensing arrangements, adopts the plan of placing the condensing pipes in a tank divided into channels, through which a stream of water is made to flow, and which can be regulated according to the make of gas. The water enters the tank at the point where the condensed gas makes its exit, and, flowing in the opposite direction to the gas in the pipes, is gradually raised in temperature by the latter till it reaches its outlet, where the crude gas enters. By this means a more uniform condensation is obtained than is possible in the atmosphere.

In this connection the following table by Peclet, showing the relative effects of water and air as cooling agents, is interesting and useful:—

	of Tempe				Quantity of Heat lost by a Square Unit of Exterior Pipe Surface.						
i over ti				n Radia in Air.	ting	V	When plunged in Water.				
For an	excess o	of 10°				8			88		
,,	"	<b>20</b> °				18			266		
"	**	80°				29			5,858		
19	"	<b>40°</b>	•	•		40 ·		•	8,944		
**	"	<b>5</b> 0°	•	•	•	53		•	13,437		

Water is thus shown to be the superior cooling agent, requiring the exposure of much less radiating surface than air; but, for the reasons already adduced, the temperature of the water must be regulated in order to avoid any sudden condensation.

An apparatus that is being rather widely adopted is the combined atmospherical and water condenser. This is made in different forms, the principle of each being the same. It is constructed either of ordinary pipes having small tubes passing through their interior, or of cylindrical or square chambers filled with such tubes, and placed either horizontally or vertically, the latter by preference. Through the tubes a stream of water is made to flow in the opposite direction to

that of the gas which surrounds them, so that by the time the water reaches the inlet of the condenser, it has, by absorbing the heat of the gas, attained a comparatively high temperature, and thus any sudden cooling of the gas at the entrance is avoided. The ease with which the cooling power of the apparatus can be varied and controlled, by increasing or diminishing the flow of the water, is a strong recommendation in its favour.

The underground condenser is so-called because the pipes are placed in the ground out of reach of the fluctuations of temperature in the atmosphere, with a view to obtaining uniformity of action in the process of condensation. By this system, however, a much longer length of piping is required than by any other, owing to the small amount of radiation from the surface of the buried pipes.

There is an advantage in this process of gradual condensation; but it is advisable, wherever in use, to supplement it by finally passing the gas through one of the other forms of condensers having less than the usual area.

In some works condensation is effected by means of dry scrubbers—cast-iron vessels of large diameter—charged with coke, drain tiles, or other material, breaking up the gas into minute streams, which, being thus cooled, deposits its tar and water.

A natural settlement of the condensable matter also takes place, irrespective of the action of the contained material, owing to the velocity of the flow of the gas being reduced on entering the larger area.

The rapid fouling of these vessels, however, necessitating frequent changing of the filling material to prevent undue back pressure and maintain their efficiency, renders their use objectionable.

Precipitating chambers of large size are also employed, without any filling material, in which the gas sleeps, as it were, and deposits its condensable particles. A vessel of this kind is useful in other respects, because the large volume of gas serves as a cushion to counteract pulsatory action between the exhauster and the retorts.


The principle of Pelouze and Audouin's condenser is different to that of any of the other apparatus described. In construction it consists of an outer cylindrical cast-iron chamber, with the usual inlet for gas, and outlets for gas and liquids, and contains a cylinder of perforated sheet-iron constituting the condenser. The sides of the condensing chamber are two thin sheets of iron with a concentric space between. The inner sheet is perforated with holes 1-20th of an

inch in diameter, and the outer with slots of large size; the outer sheet being so arranged as to offer a blank surface opposite the small holes in the inner sheet. The gas and condensable vapours pass through the small perforations, the vapours being as it were wire-drawn, and striking against the opposite solid surface are deposited thereon, and flow down into the receptacle below, and thence to the tar well.

The gas passes on through the slots in the outer cylinder to the outlet pipe.

The condensing cylinder is so balanced as to rise and fall in an annular space containing tar or liquor which acts as a seal. As the make of gas increases or decreases, the cylinder rises or falls, and consequently a larger or less number of openings are uncovered for the passage of the gas. The result is a more complete separation of the tar from the gas than is attainable by any other form of condenser.

It has been attempted, though with doubtful success, to condense and carburet the gas at one and the same time. The Aitken and Young analyzer, and the St. John and Rockwell apparatus, were each designed by their inventors to enrich the gas by carburation. The tar and gas were both conveyed direct from the hydraulic main to the apparatus; their temperature at the inlet being maintained as high as possible. Means were even adopted of raising the temperature, if required, in order that the heavier hydrocarbons present in the crude gas and tar might be permanently suspended, and so become fixed illuminants in the gas, notwithstanding the subsequent reduction of





F1G. 48.

temperature in the ordinary course of purification. Great hopes of the process were at one time entertained, but it failed to meet the expectations of the inventors.

Drory's Main Thermometer.—The illustrations, Figs. 47 and 48, show the improved arrangement invented by Mr. Drory, for ascertaining

the temperature of the gas passing through the condenser and other apparatus, and the mains. It consists of an outer shell fitted with a conical hollow plug having an aperture corresponding to that in the outer shell. The tester which fits into the plug contains a thermometer, which on being turned opposite to the apertures is in immediate contact with the gas, and on withdrawal the temperature is ascertained. For attaching the tester, a hole suitable for a 1-inch wrought-iron pipe is drilled and tapped in the pipe or side of the apparatus, and the instrument is screwed therein.

To convert Degrees of Fahrenheit into those of Centigrade and Réaumur, and conversely.

'To convert Fahr, into Cent.

Rule 1st.—Subtract 32, and divide the remainder by 1.8, thus:

Fahr. 
$$\frac{167 - 82}{1.8} = 75$$
 Cent.

or by-

RULE 2nd.—Subtract 82, multiply the remainder by 5, and divide the product by 9, thus:—

Fahr. 
$$\frac{(167 - 82) \times 5}{9} = 75$$
 Cent.

To convert Cent. into Fahr.

RULE 1st.—Multiply by 1.8, and add 82, thus:—
or by—
Cent.  $75 \times 1.8 + 82 = 167$  Fahr.

RULE 2nd.—Multiply by 9, divide by 5, and add 32, thus:— Cent.  $\frac{75 \times 9}{5} + 82 = 167$  Fahr.

To convert Fahr, into Réau.

RULE 1st.—Subtract 82, and divide by 2.25, thus:—

Fahr. 
$$\frac{118 - 82}{2 \cdot 25} = 86$$
 Réau.

or by-

Rule 2nd.—Subtract 82, multiply by 4, and divide by 9, thus:—
Fahr.  $(118 - 32) \times 4 = 86$  Réau.

'To convert Réau. into Fahr.

RULE 1st.—Multiply by 2.25, and add 32, thus:—or by—Réau.  $36 \times 2.25 + 32 = 118$  Fahr.

RULE 2nd.—Multiply by 9, divide by 4, and add 32, thus:—

Réau. 86 × 9

Réau.  $\frac{86 \times 9}{4} + 82 = 118$  Fahr.

In connection with the subject of Condensation, the following Table, comparing the English and French Thermometers, will be found useful:—

Fahr.	Réau.	Cent.	Fahr.	Réau.	Cent.	Fahr.	Réau.	Cent.	Fahr.	Réau.	Cent.
212	80.0	100.0	160	56.8	71.1	108	83 · 7	42.2	56	10.6	13.8
211	79.5	99.4	159	56 · 4	70.5	107	88.8	41.6	65	10.2	12.7
210	79.1	99.8	158	56.0	70.0	106	82.8	41.1	54	9.7	12.2
209	78.6	98.8	157	55.5	69.4	105	82.4	40.5	58	9.8	11.6
208	78.2	97.7	156	55.1	68.8	104	82.0	40.0	52	8.8	11.1
207	77.7	97.2	155	54.6	68·8 67·7	108	81.5	89.4	51	8.4	10.5
206	77.8	96.6	154	54.2	67.2	102 101	81·1 80·6	38·8 88·8	50 49	8·0 7·5	10·0 9·4
205	76.8	96.1	153	58·7 58·8	66.6	100	80.5	87.7	48	7.1	8.8
204	76.4	95.5	152 151	52.8	66.1	99	29.7	87.2	47	6.6	8.8
208 202	76.0	95·0 94·4	150	52.4	65.5	98	29.8	36.6	46	6.2	7.7
202	75·5 75·1	93.8	149	52.0	65.0	97	28.8	86.1	45	5.7	7.2
201	74.6	98.8	148	51.5	64.4	96	28.4	85.5	44	5.3	6.6
199	74.2	92.7	147	51.1	68.8	95	28.0	85.0	43	4.8	6.1
198	78.7	92.2	146	50.6	63.8	94	27.5	84.4	42	4.4	5.5
197	78.8	91.6	145	50.2	62.7	98	27 1	88.88	41	4.0	5.0
196	72.8	91.1	144	49.7	62.2	92	26.6	88.8	40	8.5	4.4
195	72.4	90.5	143	49.8	61.6	91	26.2	32.7	89	3.1	8.8
194	72.0	90.0	142	48.8	61.1	90	25.7	32.2	88	2.6	8.8
198	71.5	89 · 4	141	48.4	60.2	89	25.8	81.6	87	2.2	2.7
192	71.1	88.8	140	48.0	60.0	88	24.8	81.1	36	1.7	2.2
191	70.6	88.8	139	47.5	59:4	87	24.4	80.2	85	1.8	1.6
190	70.2	87.7	138	47.1	58.8	86	24.0	90.0	84	0.8	1.1
189	69.7	87.2	137	46.6	58.8	85	23.5	29:4	88	0.4	0.2
188	69.8	86.6	136	46.2	57·7 57·2	84 83	28·1 22·6	28.8	82 81	- 0·0 - 0·4	- 0·5
187	68.8	86.1	185	45·7 45·8	56.6	82	22.0	27.7	80	- 0.8	-1.1
186	68.4	85.5	134 188	44.8	56.1	81	21.7	27.2	29	- 1·8	- 1·6
185	68.0	85·0 84·4	182	44.4	55.5	80	21.8	26.6	28	- i·7	$-\hat{2}\cdot\hat{2}$
184	67.5	88.8	181	44.0	55.0	79	20.8	26.4	27	$-\mathbf{z}\cdot\dot{\mathbf{z}}$	$-2.\overline{7}$
183 182	66.6	88.8	130	43.5	54.4	78	20.4	25.5	26	- 2.6	<b>— 8.3</b>
181	66.2	82.7	129	48.1	58.8	77	20.0	25.0	25	- 3.1	-3.8 $-4.4$
180	65.7	82.2	128	42.6	58.3	76	19.5	24.4	24	- 3.5	- 4.4
179	65.8	81.6	127	42.2	52.7	75	19.1	23.8	28	- 4·0	<b>— 5</b> ·0
178	64.8	81.1	126	41.7	52.2	74	18.6	23.3	22	- 4·4	<b>—</b> 5·5
177	64.4	80.5	125	41.8	51.6	78	18.2	22.7	21	<b>— 4·8</b>	<b> 6·1</b>
176	64.0	80.0	124	40.8	51.1	72	17.7	22.2	20	- 5.8	<b>- 6.6</b>
175	63.5	79 · 4	128	40.4	50.5	71	17.8	21.6	19	- 5.7	<b>—</b> 7·2
174	63.1	78 8	122	40.0	50.0	70	16.8	21.1	18	- 6.2	<b>-</b> 7·7
178	62.6	78.8	121	39.5	49.4	69	16:4	20.5	17	-6.6 - 7.1	- 8·3
172	62.2	77.7	120	89.1	48.8	68	16.0	20.0	16	-7.5	- 8·8 - 9·4
171	61.7	77.2	119	38.6	48·3 47·7	67 66	15·5 15·1	19·4 18·8	15 14	- 8·0	-10.0
170	61.8	76.6	118	38·2 37·7	47.2	65	14.6	18.8	13	- 8·4	-10·5
169	60.8	76.1	117 116	87.3	46.6		14.2	17.7	12	- 8·8	-11.1
168	60.4	75.5	115	86.8	46.1	63	13.7	17.2	ii	- 9.8	-11.6
167	60.0	75·0 74·4	114	86.4	45.5	62	13.3	16.6	iô		-12.2
166	59.5	73.8	113	86.0	45.0	61	12.8	16.1		-10.2	19.7
165	58.6	73.8	112	85.5	44.4	60	12.4	15.5	. 8	-10.6	-13.3
164	58.2	72.7	iii	85.1	48.8		12.0	15.0	7	<del></del> 11·1	<b>—13·8</b>
163	57.7	72.2	110	34.6	48.3	58	11.5	14.4		-11.5	-14.4
162	57.8	71.6	109	34.2	42.7	57	11.1	13.8	5	-12.0	-15.0
161	1	1	•	·			·		·	'	

### THE EXHAUSTER.

The exhauster is best placed to follow the condenser. The raison d'stre of this apparatus, which is really nothing more nor less than a pump, is to relieve the retorts of the pressure caused by the obstruction offered to the gas in its passage through the washers, scrubbers, purifiers, and station meter into the holders.

Exhausters are now made of almost any size, down to the smallest, and there are but few gas-works, however small, where they cannot be applied with advantage. The invariable result of the use of the exhauster is to increase the production per ton, to improve the quality of the gas (provided air is not drawn in), and to lengthen the duration of the retorts, by preventing, in a great measure, the deposition of carbon, the removal of which with the ordinary chisel bars is so destructive and unsatisfactory.

Mechanical exhausters are of two kinds, the rotatory and the reciprocating. Both descriptions have their advocates, and much may be said in favour of each.

Beale's exhauster was the first one constructed on the rotatory principle. Its early form is shown in Fig. 49. Its parts consist of a




F1g. 49.

cylinder, inside which a drum revolves, and is provided with pistons or slides which have a radial motion. The drum is smaller in diameter than the inside of the cylinder, and the centre lines or axes of both are parallel and horizontal; but the drum is placed eccentrically in the cylinder, so as to be in contact with it at the bottom without resting on it. The inlet and outlet passages are on the two opposite sides of the cylinder, and as the slides are guided by segments in

the end plates, so that their outer ends are always in contact with the inside of the cylinder, the gas enters one side, is carried round over the drum to the other side, and is forced out at the outlet. This form of exhauster is the one now most generally adopted, and whilst the original type is retained, important modifications and improvements have been effected in its construction and action by various makers of recent years—notably by Gwynne and Co., Bryan Donkin and Co., W. H. Allen and Co., and G. Waller and Co.

The illustrations (Fig. 50) show sections of a Beale's exhauster as made by Gwynne and Co. under their patents, and containing several improvements on the machine as first invented, by which the



areas of wearing surfaces have been augmented so as to greatly increase the durability of the machine. These include the double slides, large segments, steel pins fastened in the segments and extending through the whole length of the slides, and the outside bearings for the axle.

In Fig. 51 is shown a section of Waller's three-blade exhauster, which the inventors consider to be an improvement on the two-bladed




form of the apparatus. The delivery is divided into three parts instead of two, thus giving a steadier gauge. The exhauster can be run in either direction, using either branch pipe as the inlet or outlet, but the direction for running is always from the inlet. The blades turn on a centre spindle and are radial with the cylinder, which is a true circle. The same makers have produced a four-blade exhauster.

Anderson's exhauster, which may be taken as the type of the reciprocating form of the apparatus, is shown in Fig. 52. This works in the vertical position, but others, like Dempster's, have the engine and pumps placed horizontally.

The rotatory exhauster may be driven either by a strap from a line shaft actuated by a steam or gas engine, or by an engine coupled direct. The reciprocating exhauster is always driven directly by the engine.

By employing two of these latter exhausters, and working them from one engine, the slides of the exhausters being placed at right angles to each other, a perfectly steady vacuum and pressure are maintained.



The essential features of a good exhauster are that it should be simple, and work with a minimum of friction and power, that it should give the steadiest possible flow of gas, and that the parts should be perfectly gas-tight. The commonest fault is want of tightness, and when it is remembered that, under a pressure equal to a 14-inch column of water, about 9000 cubic feet of gas will pass per hour through an opening of only one square inch in area, the absolute necessity of the best workmanship only being used in exhausters will be evident.

Crude creosote oil is the best lubricant for the cylinder and slides of an exhauster when the surfaces become "pitched" with tar.

The steam-jet exhauster (Fig. 58), invented by Mr. Cleland, and improved by Körting Brothers, is another form of exhausting apparatus. This operates by projecting a jet of steam, at about 45 lbs. pressure, through an arrangement of pipes or nozzles, without the intervention of any other mechanical appliances—the steam being afterwards extracted by condensation. The capacity of the exhauster is regulated by the adjustable screw and spindle at the end; and by a movable inner sleeve, opening or closing the port holes by means of the screw and nut at the side.

When an exhauster is employed, it is necessary to supplement its use by a gas governor, acting either on a throttle valve within the steam feed-pipe, in this case increasing or diminishing the speed of the engine, or on a valve within a bye-pass connected to the inlet and outlet mains leading to and from the exhauster, the opening of which, when the exhaust is too active, allows a portion of the gas to return through the exhauster, and thus prevents the formation of a partial vacuum in the retorts.

Steam Engines and Boilers.—These should be provided of ample size, allowing




Fig. 58.

a margin over and above the actual power needed. An engine and boiler barely fit to do the work required of them are a nuisance.

The engine, besides turning the exhauster, may be used in pumping water and tar; and the boiler, in addition to supplying steam for the engine, is useful for steaming the mains and apparatus on the works.

Duplicate boilers of the required size should be provided, to allow for periodical cleaning and examination.

For firing the boiler, breeze may be used, mixed with a portion of coke or coal. Or if, instead of the chimney draught, a forced draught be employed, breeze and much of the furnace refuse will serve as fuel.

One pound weight of coal of average quality requires 150 cubic feet of air for its perfect combustion. In actual practice, however, about double this quantity of air passes through the furnaces of steam boilers.

Wherever practicable and convenient, the boiler may be set in such a position as to allow of its being heated with the waste heat from the retort-stack.

In small works, if a steam boiler cannot be employed for want of space, or should a boiler be considered objectionable on other grounds, the exhauster can be driven by a gas engine.

The boiler most suitable for a gas-works of moderate size is the Cornish type, with flat ends, and single internal tube containing the furnace. For large works, the Lancashire or double-flued boiler is best adapted.

The nominal horse power of a boiler is found by multiplying the sum of the diameters of the outer shell and internal flue by the length, and dividing the product by 6.

Example.—Required the power of a Cornish boiler, whose diameter is 4 ft. 6 in., diameter of tube 2 ft. 6 in., and length 12 ft.

$$\frac{(4' 6'' + 2' 6'') \times 12'}{6} = 14 \text{-horse power.}$$

Again-

Required the power of a Cornish boiler whose diameter is 6 ft., diameter of tube 8 ft., and length 20 ft.

$$\frac{(6' + 8') \times 20'}{6} = 80$$
-horse power.

Again -

Required the power of a Lancashire boiler whose diameter is 7 ft., diameter of tubes 2 ft. 9 in., and length 24 ft.

$$\frac{(7'\ 0'' + 2'\ 9'' + 2'\ 9'') \times 24'}{6} = 50$$
-horse power.

In high-pressure or non-condensing engines, with-

Steam at 25 lbs. per square inch, 18.6 circular inches on piston = 1-horse power.

Do. 80 lbs. do. 11.8 do. = do.

The diameter of the piston in inches, squared = circular inches.

The following table gives the diameter of cylinders for highpressure (non-condensing) steam engines, from 3 to 16 horse power, with steam at 25 lbs. and 80 lbs. per square inch respectively, and the length of stroke for the different sizes:—

		of Cylinder ches.	Length		Diameter in I	Length		
Nominal Horse Power.	Steam per S	Square Inch.	Stroke.	Nominal Horse Power.	Steam per f	Square Inch.	Stroke.	
	25 lbs.	80 lbs.	Inches.		25 lbs.	80 lbs.	Inches.	
8 81	6 <u>1</u> 6 <u>1</u>	6 6 <u>1</u>	12 12	8 84	10½ 10¾	9 <u>1</u> 9 <u>7</u>	20 20	
4 41 5 51 6	7 <u>1</u> 72 81	62 71 71 71 71 81	14 14 16	9 10 11	111 112 121	10± 10± 11±	22 22 24	
5½ 6 6½	8 <u>1</u> 9 91	71 81 81	16 18 18	12 18 14	123 181 183	11g 12g 12g	24 26 26	
7 71	9 <u>1</u> 101	9 9 <u>1</u>	18 20	15 16	141 15	13 18 <u>1</u>	28 30	

Cement for stopping leaks in boilers.

Powdered fire-clay . . . . . 6 parts.

Fine iron filings . . . . . 1 part.

Made into a paste with boiled linseed oil.

Cement for metallic joints.

Equal weights of red and white lead, mixed with boiled linseed oil to the consistency of putty.

#### THE WASHER.

The washer was one of the very earliest appliances used in the purification of coal gas, and naturally so, owing to the cooling and condensing property of water, and its power of absorbing ammonia and of arresting the tar. Its construction, however, was often faulty at first, and the limits of its functions misunderstood; so that the misuse, or overuse, of the apparatus, resulting in reduced illuminating power to the gas exposed to its action, caused it to fall for a time into disrepute.

The principle of its action is that of causing the gas to pass in finely-divided streams through a body of water contained in a vessel, so that a portion of the ammonia and other gaseous impurities, and the whole of the floating particles of tar which have escaped condensation, may be removed before the gas enters the scrubbers. However

ample the usual condensing appliances may be, some portion of the lightest tar vapours escape their action. These are arrested in the washer, or tar-extractor as it is sometimes called.

This apparatus should always be used in conjunction with the scrubber, and the gas passed through it in the first instance. It is generally employed as a separate and distinct apparatus, but sometimes it is placed at the bottom of the tower scrubber of which it constitutes a part.

When the washer is exposed to outside atmospheric influence, it is necessary in winter to employ means to prevent the water from falling below a temperature of 50° Fahr.; otherwise the gas, especially a rich gas, passing through it, will suffer deterioration.

All washers give an amount of back pressure, varying from 1 to 4 inches, according to the depth of water traversed. There are numerous designs of the apparatus, but the principal ones are here described.

The persistent advocacy of Mr. George Anderson has done much to restore the washer to favour, and his form of the apparatus is still one of the best.

It consists of a cast-iron outer vessel, containing a number of trays, having on their under side a series of serrated bars extending from side to side; these dip into the water or liquor, and the gas, in passing through the serrations is divided into minute globules. The pressure given can be regulated by raising or lowering the overflow with which the apparatus is provided. A four-way valve is used for shut-off and bye-pass. Weak ammoniacal liquor from the condenser is run in at the top, and drips from tray to tray till it reaches the bottom. The washer is made either single or double as required.

In Cathels' washer the usual oblong or square vessel is divided into sections, as many as may be desired, each elevated higher than the others in the form of steps. The gas enters at the bottom, passes in divided streams through a number of curtain serrations extending the full length of the vessel, and so on through the rest, and out at the top of the higher compartment. When the liquor in the lowest section is of the strength required, it is run off, and the contents of the several sections transferred one step lower, the last or uppermost being charged with fresh water. This apparatus is also arranged in the vertical position to occupy less ground space.

Livesey's washer is a compact and efficient apparatus, occupying less room for the work done than any other. In a rectangular castiron box of any size (depending on the make of gas) is a series of rectangular tubes of wrought-iron, to which wrought-iron perforated plates are fastened, turned down at the sides till they dip into the liquor. The perforations are 1-20th of an inch diameter, and 1-5th of an inch apart.


The gas passes down between the tubes and through the side perforations into spaces filled with liquor, and, bubbling upwards, is again broken up by finding its way through the horizontal perforations into the open space above, and so along to the outlet of the apparatus. Means are provided for securing an active circulation of the liquor, which is constantly flowing through it from the adjacent scrubber, and away by an overflow to the well.

#### THE TOWER SCRUBBER.

The Tower Scrubber (Fig. 54) is a cast-iron vessel, either rectangular or cylindrical (the latter shape being preferred), erected on end, through

which the gas is made to pass in an upward direction after issuing from the washer.

Its primary use is to purify the gas from ammonia by the aid of water: advantage being taken of the well-known great affinity of ammonia for that liquid. Water. at mean temperature and pressure (60° Fahr., barometer 80"), dissolves 783 times its volume of ammoniacal gas-that is, undiluted ammoniacal gas. When the latter is mixed with other gases, as in the case of coal gas, the power of water to arrest it is not nearly so great. It also arrests a considerable proportion of the sulphuretted hydrogen and carbonic acid.






Fig. 54.

bats, roof or draining tiles, furze, or layers of thin boards set on edge, about 5 to 7 inches in width, 3ths of an inch thick, and from ½ to ½ of an inch apart; the material being kept constantly moistened by a stream of water trickling from a suitable distributing apparatus fixed in the crown.

When the coke or other material is placed in layers, it is supported on grids fixed at convenient distances apart; and opposite each space a manhole, secured by a movable lid or cover, is provided, so as to afford access to the interior, either for examination or renewal of the contained material.

The Livesey scrubber is fitted with boards  $\frac{1}{2}$  of an inch thick, 11 inches wide, placed on edge, and kept apart by strips or blocks of wood  $\frac{3}{2}$  of an inch square; thus making one board to 1 inch. The tiers are separated by 2-in. square cross sleepers.

The first cost of filling with boards is greater than when coke or other material is employed, but it possesses the marked advantage of not fouling up, and will rarely or never need renewing. The gas cannot form narrow channels in its passage through the vessel, but is constantly being broken up and brought in contact with the water




Fig. 55.

that drips from all sides. Mr. Green uses canvas screens depending from transverse rods as filling medium. Open scrubbers are also used without any of the materials above mentioned. In such cases the column of gas in its upward progress is met by a descending shower of spray from a Gurney jet (Fig. 55).

The most efficient tower scrubber is the cylindrical, standing in height about five to seven times its diameter. Owing to the difficulty of securing an equal distribution of the water or liquor, the diameter should not exceed 10 feet in the largest works. As a general rule 8 feet diameter is preferable; for, to obtain the full benefit to be derived from this apparatus, there should be immediate contact of the gas with the water or liquor in a state of minute subdivision. Height is an important factor in a tower scrubber. Experience has proved that the best filling is thin rough-sawn boards, placed in alternate layers on edge one over the other, or canvas screens, as before described. When coke is used as the scrubbing material, it may be placed in six or eight layers, with a space of about 6 inches between each. Whatever material is used in filling the scrubber, it is important that all parts of its surface should be wetted as equally as possible. The proper action of the scrubber depends on this.


The necessity of a good water distributing apparatus is therefore obvious. Not only should this be of good construction in the first instance, but it should always be maintained in efficient working order. The gas enters at the bottom of the vessel, and the water or liquor at the top. The gas in travelling upwards is completely broken up, fresh surfaces being constantly presented to the descending drip, and to the wetted sides of the filling material, against which it is rubbed or scrubbed all the way up, until it emerges by the outlet at the top. A trapped overflow at the bottom conveys the liquor either to the washer or to the tar well.

The gas, before entering the scrubbers, should have the whole of the tar eliminated from it; and to ensure this, a washer or tar extractor may be employed, either as a separate apparatus, or placed in the bottom of the tower.

The weak ammoniacal liquor from the hydraulic main and condenser may be employed for distribution through the tower. The object of using this is to arrest a proportion of the carbonic acid and sulphuretted hydrogen, as well as the other sulphur compounds, for which ammonia has a strong affinity, thus relieving the lime and oxide purifiers, and saving labour and purifying materials. The weak liquor is also by this means brought up to the requisite commercial strength.

One method frequently adopted of applying the water or liquor is by a pipe passing through the crown or side of the vessel, from which pipe smaller tubes, pierced with holes, radiate towards the circumference. This may be either fixed or revolving; the latter being the most efficient. In the Mann scrubber, the uppermost part of the tower containing the distributor is made about two of three inches wider than the rest, in order that the sides of the vessel may be wetted as well as the contained material. In this wider portion, and underneath the distributing tubes, there is a revolving layer of birchwood twigs lessening in depth towards the circumference, and the water falling upon this is equally distributed throughout. This arrangement requires the use of a small engine and gearing to produce the slow rotary motion.

To obviate the necessity for an engine, a Barker's mill or other similar appliance is sometimes used for producing the required motion;



With the introduction and perfecting of the rotatory washer-scrubber has come a gradual modification of the views formerly held in regard to the superiority of the tower form. It is now generally admitted that the rotatory apparatus is of much excellence, being more under control, and more certain in its action, than the other. It by no means follows.


however, that the tower scrubber should be discarded. The best provision to make for scrubbing purposes is to apply one tower and one rotatory apparatus for each stream of gas. That is to say: Assuming a works where the gas is sent in one continuous stream through the different appliances of purification, then one tower and one rotatory scrubber will suffice. Thus—

Fig. 56.



When the make is sent through the apparatus in several streams—

as should be the case in large works—the like provision is made for each stream. Thus—



The question as to the capacity of the washer-scrubbers will be decided by the quantity of gas they are intended to pass; whether half, one, or two million cubic feet, and so on, per day of 24 hours.

Adopting this arrangement, the tower scrubber would be supplied exclusively with weak ammoniacal liquor, and the washer-scrubber with clean water. The tower scrubber, even in the largest works, should not exceed ten feet in diameter, for the reasons previously stated; the supply of liquor, which should be plentiful, being moderated or increased according to the season of the year and the quantity of gas being passed.

In works where there are no washer-scrubbers, but towers only, the latter are most economical and effective when they are used in pairs (Fig. 54), the gas being passed through first one and then the other. In such case, weak ammoniacal liquor should be pumped liberally through the first, and fresh water, in the proportion of two to three gallons per 1000 cubic feet of gas passing, through the second scrubber. When more than one pair of tower scrubbers is employed, as is the case in considerable sized works, the gas should be distributed in equal proportion through the several pairs simultaneously—not through each in succession.

Tower scrubbers, when used alone, and not in conjunction with the washer-scrubber, should have an aggregate cubical volume of at least 9 feet for each 1000 cubic feet of gas made per day of 24 hours, taking the maximum production as the basis of the calculation. For example, take a works producing in the depth of winter 600,000 cubic feet of gas per day of 24 hours:—

Then.

 $600 \times 9 = 5400$  feet, cubical volume required.

This would be supplied by

Two scrubbers, each 8 ft. diameter, and 56 ft. high. Or again, take a works producing 1,000,000 cubic feet per day:—Then.

 $1000 \times 9 = 9000$  feet, cubical volume required.

This would be supplied by


Two scrubbers, each 10 ft. diameter, and 58 ft. high.


Where the washer-scrubber is also employed, one tower in each of the above instances is sufficient.

# THE WASHER-SCRUBBER.

The washer-scrubber has come largely into use in recent years, and deservedly so, as it removes the last vestige of free ammonia from the gas, as well as a proportion of the other impurities. It is placed horisontally, is rectangular or round in section, and consists of a cast-iron tank or vessel in divisions, containing water or liquor, in which a series of perforated discs or volutes of sheet-iron, or chambers containing wood balls or bundles, or other filling medium, exposing a large surface, are made to revolve on a central shaft, at a slow speed. These, as they rise from the liquid, are completely wetted on all sides. and the crude gas passing through or amongst them, coming in contact with the wet surfaces, is deprived of its ammonia and a portion of the other objectionable compounds. The clean or fresh water entering at one end, and flowing through the different divisions, is met by the gas which enters at the opposite end, and gradually increases in strength till it issues from the last compartment as 10 or 12 ounce (5° or 6° Twaddel) ammoniacal liquor. Kirkham, Hulett, and Chandler's "Standard" Washer-Scrubber (Fig. 59) and Laycock and Clapham's "Eclipse" Washer-Scrubber (Fig. 60) are of this type.

This apparatus has largely supplanted the tower scrubber, by reason of its being more manageable, as well as more certain in its action as an ammonia extractor. It is a mistake, however, to dispense altogether with the tower. The two should be used in conjunction, as described on page 95, the gas being drenched in the tower with weak ammoniacal, liquor, and afterwards treated with clean water in the rotatory vessel. This is the perfection of gas scrubbing.





Anderson's combined washer and scrubber consists of a rectangular cast-iron vessel, standing on end, and in height about five times its The vessel is divided into compartments, each of which contains a drum caused to revolve by suitable gearing. ference of each drum is fitted with a brush of whalebone or other These fit exactly into the space allotted for them, and, in revolving, dip into the liquid which partially fills the several divisions. The scrubber stands on an Anderson washer (see page 91). stream of pure water, at the rate of 10 to 12 gallons per ton of coal carbonized, is kept flowing into the top compartment through a funnel and sealing tube, and gradually descends by way of the gas-pipes connecting the chamber till it enters the washer, from which there is an overflow pipe to the well. The gas enters the washer at the bottom, and is first relieved of the tar remaining after condensation; thence it passes through the revolving brushes, meeting different strengths of liquor in each division, till it reaches the upper one containing pure water, and away by the outlet. By this means the whole of the ammonia and a large proportion of the other impurities are removed.

In addition to the apparatus described above, the "purifying machine" made by C. & W. Walker is a powerful washer and scrubber combined.

Ford's scrubber-washer and Cockey's washer are compact apparatus, producing excellent results, and these do not require motive power to work them.

Dr. Frankland gives the following useful table showing the number of volumes of various gases which 100 volumes of water at 60°. Fahr., and 30 inches barometric pressure, can absorb:

Ammonia 7	8,000 volumes.
Sulphurous acid	3,900 ,,
Sulphuretted hydrogen .	258 ,,
Carbonic acid	100 ,,
Olefiant gas	12.5 ,,
Illuminating hydrocarbons \ \ No.	ot determined, but probably more soluble than olefiant gas.
Oxygen	3.7 volumes.
Oxygen	•
	3.7 volumes.
Carbonic oxide	8·7 volumes. 1·56 ,,
Carbonic oxide Nitrogen	8·7 volumes. 1·56 ,, 1·56 ,,

When water has been saturated with one gas, and is exposed to the influence of a second, it usually allows a portion of the first to escape, whilst it absorbs an equivalent quantity of the second. In this way a small portion of a not easily soluble gas can expel a large volume of an easily soluble one.

## BYE-PASS MAINS AND VALVES.

In connection with the foregoing apparatus, viz., the condenser, exhauster, washer, tower-scrubber, and washer-scrubber, bye-pass mains closed with valves or water-traps should be provided, in order to allow of any of them being put out of action for cleaning or repairs. The exhauster bye-pass is closed with a flap valve, so that, in case of sudden stoppage of the machinery, the valve opens by the pressure of the gas being thrown against it, and allows the gas to flow unchecked.

# TAR AND LIQUOR WELLS AND TANK.

The tar and ammoniacal liquor underground wells may be built either of bricks laid in cement and carefully puddled at the bottom and sides, or of cement concrete rendered over the whole inside surface, or formed of cast or wrought iron or steel plates, bolted together, and having either planed or caulked or riveted joints. The iron vessel is preferable when the construction of a good foundation is likely to be a matter of great expense.

The well or wells should be of capacity sufficient to contain six weeks' make of material, reckoning from the maximum daily production. Less than six weeks' storage space will serve when the liquor is manufactured into sulphate of ammonia on the premises.

Another well of smaller dimensions, the size depending on the magnitude of the works, ought to be provided, to serve as a lute or seal, into which the drip-pipes from the different apparatus should dip. From this, at a depth of about 15 or 18 inches below the surface of the ground, an overflow-pipe or channel conveys the condensed products into the larger reservoir.

In some works the tar-pipe is taken direct from the hydraulic main into the large well, and there sealed by being made to dip into a vertical pipe secured to the bottom of the tank. This is objectionable, as, in case of stoppage, it is difficult of access. Again, there is always the liability of an escape of gas from that portion of the pipe within

the well; further, where flushing of the hydraulic main is practised, the rushing liquor carries with it a quantity of gas which is liberated within the well. It is also important that the tar should be cooled somewhat before entering the larger receptacle, because hydrocarbon vapour is given off from it at a temperature of about 90° Fahr. and above. In each of these cases the gas or vapour, mixing with the contained air within the well, would explode with disastrous consequences on contact with a light. Accidents which have occurred have been due to one or other of these causes.

In all cases the wells should be covered over to exclude surface and rain water, and prevent the possible loss of ammonia by evaporation.

In addition to the underground well, an elevated cast-iron cistern is indispensable in a well-appointed gas-works. Into this the




Fig. 61.—VERTICAL SECTION.

FIG. 62.—PLAN.

tar and liquor are pumped from the underground well, and suitable draw-off pipes, furnished with stopcocks or valves, serve to discharge the material into the barrels, trucks, or barges of the purchasing contractor.

The cistern may be divided in two by means of a partition plate reaching to within about 6 inches of the top, over which the ammoniacal liquor will flow, separating itself from the tar by reason of its lower specific gravity.

A tar and liquor separator, for placing in the ground in any convenient position near to the underground well, is shown in sectional elevation and plan in Figs. 61 and 62. It consists of a cast-iron vessel, about 4 feet square and 4½ feet deep, for a considerable sized gas-works. The division plate extends from the top of the vessel to within 4 inches of the bottom; the diaphragm, over which the tar-

escapes into its separate well, being placed 1½ inches lower than the other diaphragm for the ammoniacal liquor.

TABLE.

Contents of Circular Tanks or Wells in Gallons for each Foot in Depth.

Diameter. Ft. In.		Gallons for each Foot in Depth.	Diameter. Ft. In.		Gallons for each Foot in Depth.	Diameter. Ft. In.		Gallons for each Foot in Depth.	
9	0	897 • 6	16	6	1336.4	24	0	2827 • 4	
9	8	420.0	16	ğ	1377 • 2	24	š	2886.7	
9	6	448.0	17	ŏ	1418.6	24	6	2948-5	
ğ	ğ	466.6	17	š	1460.7	24	9	8006.9	
10	Ŏ	490.9	17	6	1508.8	25	Ŏ	8068 • 0	
10	Ř	515.7	17	ğ	1546.6	25	8	3129.6	
10	6	541.2	18	ŏ.	1590 · 4	25	ĕ	8191.9	
10	9	567 . 3	18	8	1684 9	25	9	3254 · 8	
īĭ	Ŏ	594.0	18	6	1680.0	26	Õ	8318.3	
11	Š.	621.8	18	9	1725.7	26	Š	3382.4	
11	6	649 2	19	ŏ	1772-1	26	6	8447 • 2	
īī	9	677.7	19	š	1819.0	26	9	8512.5	
12	Ŏ	706.9	19	6	1866 • 6	27	Õ	8578 • 5	
12	Ř	786.6	19	ğ	1914.7	27	8	3645 · 1	
12	6	767.0	20	ŏ	1963 · 5	27	6	8712.2	
12	ğ	798.0	20	8	2012.9	27	9	3780.0	
13	Ŏ	829.6	20	ĕ	2062.9	28	Ŏ	8848 • 5	
18	8	861.8	20	ğ	2118.5	28	8	8917.5	
18	6	894.6	21	Ŏ	2164.8	28	6	3987 • 1	
18	ğ	928 · 1	21	š	2216.6	28	9	4057 • 4	
14	Ŏ	962.1	21	Ř	2269 · 1	29	Ō	4128.3	
14	Ř	996.8	21	ğ	2322 · 1	29	8	4199 · 7	
14	ĕ	1032 · 1	22	ŏ	2875.8	29	6	4271 · 8	
14	ğ	1068.0	22	8	2480 · 1	29	ğ	4344.6	
15 -	Ŏ	1104.5	22	6	2485.0	80	Ŏ	4417.9	
15	8	1141.6	22	ğ	2540.6	80	8	4491.8	
15	6	1179.8	23	ŏ	2596.7	80	6	4566.4	
15	9	1217.7	28	š	2658.5	80	ğ	4641.5	
16	ö.	1256.6	23	6	2710.8	81	Ŏ	4717.8	
16	8	1296.2	28	9	2768 · 8	81	8	4798 · 7	

#### PURIFICATION.

Impurities in Crude Coal Gas.—The chief impurities present in coal gas, in its crude or raw and unpurified state, at the time it leaves the retorts, are tar vapour, ammonia, carbonic acid, sulphuretted hydrogen, and other sulphur compounds, notably bisulphide of carbon.

The first-named impurity, tar vapour, begins to condense and is partially removed in the hydraulic main and pipes leading to the

condensing apparatus, where, if this is of sufficient capacity, and otherwise adapted to the performance of the work required of it, it is nearly all removed. What remains is taken out by the washer or tar extractor.

The ammoniacal gas, of which there is about 1 per cent. by volume, also begins to separate from the crude coal gas in the hydraulic and foul mains, combining with the moisture distilled from the coal. In the condenser and washer a further portion is removed, and in the tower scrubbers and washer-scrubbers, if these are as efficient as they ought to be, or can easily be rendered, the whole of the remaining ammonia (amounting to about 15 per cent.) is extracted.

The hydraulic and foul mains, condensers, washers and scrubbers are also efficacious in removing a portion of the carbonic acid (existing in the gas to the extent of about 2.5 to 8 per cent.), sulphide of hydrogen or sulphuretted hydrogen (from 1 to 2 per cent. of which is contained in the gas), and bisulphide of carbon; but the bulk of these three latter impurities still exists in the gas after leaving the scrubbers, and is carried forward to the purifiers.

These are charged either with hydrate of lime or hydrated peroxide of iron, or a combination of both substances, arranged in separate layers or tiers within the several vessels.

Purification by Lime.—The lime has a perfect and strong affinity for carbonic acid and sulphuretted hydrogen, and accordingly it entirely removes these compounds from the gas, without leaving the slightest trace of their presence. The lime, however, in its state of oxide of calcium, has no affinity for the bisulphide of carbon, so that the greater proportion of this impurity (all, except such part as is removed by the foul lime when in the state of sulphide of calcium), is carried forward into the holders.

Cream or milk of lime was used in purifying in the early days of gas manufacture, and though this was thoroughly efficient, and is probably the most economical method of employing the lime, it has been generally discarded on account of the obnoxious character of the refuse material, "blue billy," as it was called, and the difficulty of getting rid of it. Lime in the hydrated state is now generally adopted.

The lime should be prepared by being slaked with clean water a day or two before it is required for use. If placed in the purifiers

before this necessary interval has elapsed, it is liable to cake or become more compact than it otherwise would. On the other hand, hydrate of lime absorbs carbonic acid from the atmosphere, and its purifying power is nullified in proportion to the extent of such absorption. It should not, therefore, be prepared for any great length of time before it is needed.

It is a mistake to place the prepared lime in the purifiers in a comparatively dry and almost powdery state. Lime used in this condition is less effective than when thoroughly moistened. It is also a wasteful method of using the lime, as a large proportion of the material will be found unspent and almost untouched by the impurities, when the vessel requires to be changed. The finely-divided lime is also more liable to cake than the other, and thus increase the back pressure. When the production of gas is great, as in the depth of winter, these disadvantages are strongly felt.

The lime should be well watered. A hose pipe or india-rubber tube, terminating in a copper spreader or rose, is useful for this purpose. It should then be passed through, by being thrown against, a screen made either of parallel steel rods \(\frac{3}{6}\)-inch thick and 1 inch apart, or of strong wire having 1-inch square meshes. This not only removes the stones or flints which are less or more present, but it gives a granular character to the prepared material, in which condition it best performs its work in the purifiers.

Mr. Hislop has patented a process of calcination in suitable kilns, by which the spent lime is converted into quick lime to an almost unlimited extent, and at considerably less cost than new lime. A nuisance is thus got rid of, and further economy in purification effected.

Notes on Lime.—Limestone is the carbonate of lime found in its natural state, from which the oxide or calcium (quick or caustic lime) is produced by the expulsion of the carbonic acid by means of heat in the limekiln.

Quick or Caustic Lime (oxide of calcium) is lime in the solid state, before absorbing, or being slaked with, water.

Hydrate of Lime is lime in a moist state. It is a chemical compound of lime and water in the proportion of one part of water to three parts of lime.

Milk of Lime, or Cream of Lime, is a mixture or solution of hydrate of lime and water.

Quick lime nearly doubles in bulk on being slaked.

From 90 to 140 lbs. of quick lime, reduced to a hydrate, are required in the purification of the gas produced from 1 ton of cannel, and from 55 to 80 lbs. of that produced from 1 ton of coal.

1 bushel of quick lime weighs about 70 lbs.

1 cubic foot of ,, ,, 54 ,, 1 ,, vard of ,, ,, 1460 ,,

1 ton of ... is equal to about 32 bushels.

The value of limestone as a purifying agent is in inverse proportion to the amount of earthy or foreign matter it contains; that which leaves the smallest proportion of insoluble sediment on being dissolved in diluted acid is the best.

Purification by Oxide of Iron.—Oxide of iron possesses the property of combining with sulphuretted hydrogen, but it has no affinity for carbonic acid and bisulphide of carbon; hence when this oxide is used exclusively, the two latter named impurities are still present in the gas as supplied from the holders. This remark, however, needs some qualification. As oxide of iron, pure and simple, it has no affinity for bisulphide of carbon and other sulpho-carbon compounds, but, from the observations made at the several metropolitan gas-works, Mr. R. H. Patterson (one of the Referees) deduced the interesting fact that the sulphur which is present in a state of minute division in the oxide of iron, after the latter has been in use for some time and frequently revivified, possesses the power of arresting a portion of the bisulphide of carbon.

The hydrated peroxide of iron may be either the natural oxide, bog iron ore as it is called, found largely deposited in some of the bogs in Ireland and elsewhere; or the artificial oxide, obtained as a waste product from various processes of the manufacturing chemist.

Oxide of iron possesses this advantage over lime: After it has been in the purifier, and has taken up its quantum of sulphuretted hydrogen, it can be revivified on exposure to the air. Accordingly, when this material is used, a floor has to be provided on which it can be spread out, and turned over for revivification. At the Manchester Gas-Works, a horse and plough are employed for turning over the foul oxide.

When taken out of the purifier it is sulphide of iron, of a dense black; and after exposure it changes to its original reddish brown colour,

oxygen having been taken up, and sulphur deposited in the free state in the mass. When the sulphur is found in it to the extent of about 40 to 60 per cent. by weight (the proportion depending on the quality of the oxide), the material is sold to the manufacturing chemist, and replaced by fresh oxide.

In using fresh oxide of iron, it is necessary to exercise certain precautions. The foul material, on its exposure to the air for the first two or three times, absorbs oxygen so rapidly as often to generate very intense heat, the whole mass frequently becoming red hot. Should this occur in the purifiers, the danger is considerable, and the wood grids may be completely destroyed. Whenever, therefore, a purifier containing such new oxide has been put out of action, it should be emptied without delay. The danger of ignition may be overcome by mixing the new oxide with a proportion of the spent.

Foul oxide should not be spread out immediately on being removed from the purifiers. If it is allowed to remain in the heap for a space of 12 to 24 hours, and then distributed over the floor, the revivification is more complete, whilst the liability to ignition is reduced.

Average Composition of the Richer Descriptions of Native Bog Ore for Purifying Purposes, dried at 212° Fahr. (King's Treatise):—

As generally used, the material contains 30 to 40 per cent. of water.

Purification by Lime, Sulphide of Calcium (Foul or Spent Lime) and Oxide of Iron, combined.—Lime alone, or the lime and oxide of iron, when properly applied, are capable of freeing the gas entirely of the whole three impurities, carbonic acid, sulphuretted hydrogen, and bisulphide of carbon. This brings us to the method of purifying expounded by the Referees in their Report to the Board of Trade on Sulphur Purification at the Beckton Gas-Works, January 81st, 1872; and also by Dr. Odling, somewhat more in detail, in his lecture on Sulphide of Carbon, delivered at the Annual Meeting of the British Association of Gas Managers, held in London, in June, 1872.

To accomplish this perfect purification in accordance with the suggestions made by Dr. Odling, three sets of purifiers are required; the gas passing through the first set into the second, and on to the third, from which it makes its exit through the station-meter into the holders. The modus operandi is as follows:—

Let it be assumed that three sets of purifiers, consisting of four vessels each, are employed. Nine of these are constantly in action, three being at rest (one from each set), for the purpose of changing or revivifying the purifying material.

The first and second sets are charged with lime, the third set with oxide of iron.

Say the whole nine are newly charged. On the gas from the scrubbers entering the first set, the lime is acted on by the carbonic acid and sulphuretted hydrogen simultaneously, leaving the bisulphide of carbon at the beginning of the process to pass unabsorbed. After they have worked for some time the sulphuretted hydrogen in the first set is gradually expelled by the incoming carbonic acid, for which the lime has a stronger affinity. The second set is now being fouled with sulphuretted hydrogen, the lime being wholly or in part changed in character, having become sulphide of calcium, in which state it has an affinity for, and consequently arrests, the bisulphide of carbon; whilst the unabsorbed sulphuretted hydrogen passes on to be taken up by the oxide of iron with which the final set of purifiers is charged. By the application of the proper tests at the several sets of purifiers, the time for changing the material is ascertained.

The question of supplying gas entirely free from sulphur in any form is a formidable one for gas companies; not so much because of the cost (though that is considerable) of erecting the additional sets of purifiers, as from the difficulty of providing the necessary ground space for their erection. In new works about to be constructed the thing is easily arranged; but in the majority of works already established it would not be easy to carry the system into effect.

As regards the question of cost, a careful estimate shows that to adopt the extended method of purifying as enunciated, would entail an outlay of additional capital equivalent to close upon 2d. per 1000 cubic feet of gas sold.

The property of absorbing or arresting bisulphide or disulphide of carbon possessed by the sulphide of calcium, was known by chemists

and some observant managers of gas-works for a period considerably anterior to the date of the publication of either the able report of the Referees, or of the valuable lecture of Dr. Odling, and the principle of purification, therein recommended, acted on to some extent. Dr. Letheby, in a paper communicated to the British Association of Gas Managers in 1870, speaking of the mode of purification pursued at the Great Central Works, and, after referring to the scrubbers. goes on to say, that "the gas is then passed through a series of dry lime purifiers, which present a very large surface for absorption: and the lime is purposely left in the purifiers after it has become foul, and until a good deal of the sulphuretted hydrogen first absorbed is displaced by carbonic acid. In this manner the natural affinity of sulphide of calcium for bisulphide of carbon is permitted to act, and much sulphur, in this objectionable form, is retained. Leaving the lime purifiers, the gas, which is still charged with more or less of sulphuretted hydrogen, is passed through oxide of iron. The chemical effect of these operations is very intelligible, for sulphide of ammonium (in the scrubbers, &c.) and sulphide of calcium are both endowed with the power of combining with bisulphide of carbon, and therefore of absorbing and fixing this objectionable impurity. It is manifestly then of the greatest importance that coal gas should be kept in contact with these substances as long as possible during the process of purification. . . In the case of sulphide of calcium, it should be permitted to act for some time after the lime has become foul, for it is in this condition that it is most effective, and a lime purifier should not be changed until the sulphuretted hydrogen of the foul lime is largely displaced by the carbonic acid of the raw gas. If it be necessary to use oxide of iron on account of the difficulty of disposing of foul lime, it should be used after the lime."

It remained, however, for Mr. R. H. Patterson to show, which he did conclusively, that this complete purification can only be successfully attained by first extracting the carbonic acid, as, until that is entirely removed from the crude gas, it is impossible to obtain the sulphide of calcium in sufficient quantity or condition to arrest the bisulphide of carbon.

The Use of Air in Purification.—By drawing in a measured quantity, say 1½ to 3 per cent., of air at the inlet to the condenser, revivification of the oxide of iron in situ can be effected to a large extent.

The purifiers are thus made to continue in use for a greater length of time without changing, whilst it is remarkable that the oxide by this process can be charged with as much as 75 per cent. of free sulphur.

Purifiers with a proportionately large area in comparison with the make of gas are required to obtain the full advantage of this process.

In adopting the air process, two layers of oxide are preferable to one deep layer. Owing to the heat generated by chemical action, as well as to the deposition of the sulphur, a considerable increase or expansion in the bulk of the material takes place in the purifiers, and it is necessary, therefore, to allow ample room for the oxide to expand. A space of several inches should be allowed between the two layers, and the surface of the upper layer should be at least three inches below the edge of the water lute.

To counteract the effect of the nitrogen passing into the gas (the oxygen having entered into combination with the purifying material), and reducing the illuminating power, Mr. J. G. Hawkins has devised an apparatus for carburetting the air. This consists of a closed castiron box, oblong in shape, which is constantly supplied with tar from the hydraulic main or condenser, the tar being heated by means of steam pipes at the bottom of the box, to a temperature of 176° Fahr. (the boiling point of benzole). Air is forced by means of a steam pump through the box over the surface of the tar, being made to pursue a tortuous course by means of a series of baffle plates, and is then permitted to join the stream of gas at the condensers; so that any subsequent condensation of hydrocarbon vapour is returned to the tar well.

The Use of Pure Oxygen in Purification.—The chief objection to the use of air for revivifying the oxide of iron in situ is the importation of a considerable volume of the inert gas nitrogen into the gas, reducing the luminiferous value of the latter, unless counteracted by the carburetting process above described.

It is obvious that if pure oxygen is employed instead of atmospheric air, the objection stated will be overcome. The cost of producing oxygen, however, rendered its use prohibitory for this purpose until the advent of Brin's process for the production of pure oxygen from atmospheric air on a commercial scale and at a cheap rate.

In a valuable paper read before the Gas Institute in 1888, Mr. Valon gave an interesting description of a series of careful experiments

carried out by him to test the value of the system of adding pure oxygen to the gas in the process of purification by oxide of iron or lime.

The oxygen was admitted at the exhauster outlet by a pipe connected to a wet meter to register the quantity passing, and to a small holder in which the oxygen was contained.

The quantity of oxygen passed into the oxide was '1 per cent. by volume for every 100 grains of sulphuretted hydrogen per 100 cubic feet of gas.

There was found to be an increase in luminosity of about 5 per cent., whilst the purification was conducted with less than the usual quantity of purifying material and purifying space.

Using lime only in the purifiers, the results were still more satisfactory. It was found that the sulphur was deposited in the solid form, the lime being perfectly carbonated.

The sulphur compounds were kept down to an average of 6 to 8 grains per 100 cubic feet; and the illuminating power of the gas was raised by 1.25 per cent.

In order to obtain the pure oxygen by Brin's process, air is first deprived of its carbonic acid and moisture by being drawn by a pump through chambers containing lime and caustic soda, and the same pump forces it, under a pressure of about one atmosphere, through barium oxide, contained in steel retorts 8 inches in diameter, heated in brick furnaces to a dull red heat by producer gas. At this temperature the barium oxide absorbs a large proportion of the oxygen contained in the air, and is converted into barium peroxide: the nitrogen, and any unabsorbed oxygen, escaping through a reliefvalve at the other end of the retorts. When the barium oxide is sufficiently peroxidized, the temperature of the retorts is raised to bright red, and the pumps, by the changing of the valves, are converted into vacuum pumps; thereupon the absorbed oxygen, under the influence of the higher temperature and reduced pressure, is given off again, and discharged by the pumps into the gasholder. The retorts containing the restored barium oxide are allowed to cool to their previous dull red temperature, when the barium oxide is again ready to abstract a fresh supply of oxygen from the air. With due care, and under proper conditions, there seems to be practically no limit to the number of operations which may be effected by the one charge of barium oxide.

Such was the method of working at the time when Mr. Valon read the paper referred to. The practical process, however, as since perfected by him, and the one in use wherever Brin's method of obtaining oxygen is relied on, is to maintain the retorts containing the barium at one temperature, say about 1250° to 1800°. When the air is being pumped into the retorts it is kept under a pressure, governed by a safety valve, of about 15 lbs. to the square inch; and when the pumps are reversed the pressure is converted into a vacuum of 15 lbs. This alternate pressure and vacuum is governed by an automatic arrangement attached to the eccentric of the engine driving the air pump, so as, in point of time, to pump in for two minutes under pressure, and to pump out for three minutes under vacuum; each complete operation thus taking about five minutes.

The reason for keeping the retorts at one temperature is to overcome the difficulties attending the raising and lowering by alternately using a vacuum and a pressure, as, in practice, nothing that could be devised would withstand the movement caused by alternately raising and lowering the temperature two or three hundred degrees. No doubt, as Mr. Valon says, the latter is the ideal way, which, in practice, cannot be carried out. The only drawback to adopting the new and practical method of working is that, while as much oxygen can be got out in the same given time, the purity cannot be maintained at as high a standard. By alternately heating and cooling it is possible to get 95 per cent. of purity; with the pumps about 88 per cent.

The cost of the oxygen obtained, including interest on capital for plant, wear and tear, and all manufacturing expenses, is given by Brin's Company at 5s. per 1000 cubic feet.

Other Methods of Purification.—Continuous purification, like continuous carbonization, is a dream of both chemists and gas engineers which has not yet been realized. Various attempts have been made to accomplish it, but hitherto without success. The processes suggested and tried are full of interest, and it is worth while referring to them.

Mr. R. H. Patterson patented a process of purifying by washing or scrubbing the gas in solutions of caustic scda and sulphide of sodium, extracting the carbonic acid and sulphur impurities, and so dispensing altogether with the ordinary lime and oxide of iron purifiers. The soda solutions, when saturated with the impurities, possess the important quality of being easily and perpetually revivified or

restored to their original state on the gas-works, whilst the whole of the sulphur is secured for sale. The plan, however, has not been tried on an adequately large scale.

Attempts have been made by Mr. Laming, Mr. Livesey, Mr. F. C. Hills, and others, to purify the gas in closed vessels by employing the ammonia found in the gas for arresting the other impurities. Unfortunately, the loss of ammonia at each time of desulphurating the liquor, owing to its extreme volatility, prevented success in this direction under the conditions adopted.

Claus's Process.—This process of continuous purification in closed vessels, though not hitherto practically successful, is of such importance and promise as to merit a detailed description.

The crude ammoniacal liquor, consisting of sulphide of ammonium and carbonate of ammonia, is passed through a series of towers, wherein it is exposed to the action of carbonic acid (obtained as described below), whereby the sulphide of ammonium is decomposed, sulphuretted hydrogen being liberated, and carbonate of ammonia remaining alone.

The sulphuretted hydrogen passes through and out of the towers in the opposite direction to that in which the crude liquor travels, and is disposed of in the manner described hereafter, whilst the carbonate of ammonia solution passes forward into other towers in which it is heated to a temperature of 180° to 200° Fahr.


At this temperature the carbonate of ammonia, of a strength equa to 10 or 15 cunce liquor, loses two-thirds or three-fourths of its carbonic acid, and a corresponding quantity of caustic ammonia remains in the liquor passing from these towers.

As only a portion of the carbonic acid evolved in the heating vessel or towers is required for the above-mentioned decomposition of sulphide of ammonium, the surplus is allowed to escape in a regulated quantity, and may be used for other purposes forming part of the process.

The sulphuretted hydrogen, after leaving the towers, is conveyed to a closed furnace charged with oxide of iron, where a low incandescent heat is generated and maintained by the admission of a regulated supply of air.

The oxide of iron, once heated, continues to absorb the sulphuretted hydrogen, which, owing to the continual admission of air, is evolved in the form of sulphur, in finely-divided particles, which is carried off

and caught in chambers, so that the oxide does not require revivification, and the same quantity, kept hot by continual working, goes on indefinitely decomposing the sulphuretted hydrogen sent through it.



The purified ammoniacal liquor is then passed down distilling towers, into which steam is admitted, driving off the ammonia gas at the top, which is passed through cooling chambers in which any carbonate of ammonia carried with it deposits in crystals.

Thence, as much of the ammonia gas as is required for the purposes of purification, passes with the coal gas into a chamber, where they are allowed sufficient time to mix.

The gas is then passed through scrubbing towers, where all the impurities are washed out in the liquor, which may be obtained of 40 to 50 oz. strength if required.

Any surplus ammonia, being perfectly pure, can be used for making any of the salts of ammonia desired.

The liquor flowing from the bottom of the distilling towers contains sulphocyanide of ammonium, and may be used over and over again in the scrubbers instead of water, until the sulphocyanide accumulates to such a strength as to make it marketably valuable for chemical manufacture.

Purifying House.—The house to contain the purifiers should be lofty and well-ventilated, not only for the comfort of the workmen employed therein, but to lessen or entirely remove the risk of explosion from any leakage of gas that might occur. The house should also be arranged with a view to future extension.

It is a convenient plan to build the house with a ground and upper floor, and to place the purifying vessels on the latter with the connections and centre or other valves underneath and fully exposed and accessible. The ground floor can thus be used for revivifying the oxide of iron, if that material is employed, or for other purposes. (Figs. 68 to 68.)


The vessels are discharged through an opening in the bottom of each, closed by a gas-tight lid, and the fresh material is raised by means of an endless chain ladder, or other suitable elevating apparatus, to the floor above. (Figs. 66 to 68.)

Purifiers.—The purifying vessels are almost invariably made of cast-iron, with sheet-iron covers secured with suitable fastenings to prevent their being lifted by the inflowing gas pressing on their under surface.

Malam's arrangement of four in the set, with connections and a centre-valve (Fig. 69), by which three of the vessels are kept in action, and one out of use for renewal of the purifying material, is still generally adopted, and is the simplest and most convenient. In some works a second set of two purifiers is used in addition to the series of four, and these are connected together, and to the others, with single or four-way valves. (Fig. 69.) Under this arrangement the set of

four is charged with exide to arrest the sulphuretted hydrogen, and the set of two with lime to take up the carbonic acid, the gas passing through them in the order shown.

In determining the size of purifiers, where either dry lime or oxide of iron is intended to be used, it is of the utmost importance to



provide a liberal superficial area, and to make ample allowance for increased gas-make.

One of the greatest sources of discomfort to a gas manager is having his purifiers so cramped and confined in their area as to be incapable of doing the work required in an efficient manner.

The ordinary and best form of purifier is the square or oblong; this shape is the cheapest, affords the largest area for the space occupied

and is also the most convenient as regards the placing of the trays or grids.






Fig. 67.



The usual depth of purifiers is 5 feet; in some large gas-works they are 6 feet deep.

Purifiers, say, 20 feet square and upwards, should have two or more tie rods of round wrought-iron stretching across them from side to side, at the upper part of the lute, to support the sides under the strain to which they are often subjected by the expansion of the contained oxide of iron, especially where the air process, previously described (page 110), is in operation. These ties should be removable,



having an eyelet hole at both ends, fitting into a forked piece, also furnished with eyelet holes, bolted to the vertical flanges, and secured by an easy fitting bolt or pin.

The capacity or purifying power of the vessels is determined more by

their superficial area than their cubical volume. There is, however, a mutual relation between the two, as, when the depth is increased and fully utilized, the surface area has to be proportionately augmented, on account of the resistance offered by the deeper material to the flow of the gas. It is more strictly correct, then, to say that the superficial area, in proportion to the depth of the purifying material, is the gauge of the capacity or purifying power of the vessels; and the maximum hourly or daily gas-make of which the works are capable should form the basis of any calculation to determine their size.

One of the chief conditions for securing satisfactory purification is the use of vessels of large area. If economy and efficiency are to be considered, time is an important element, and must not be disregarded. The mere passing of the gas through the purifying media is not sufficient in itself to insure good results; time, or what is the same thing in this case, lengthened contact is required, for chemical affinity to operate.

Rule for the Size of Purifiers.—Where there is intended to be four purifiers, three always in action, the maximum daily (24 hours) make of gas, expressed in thousands, multiplied by the constant 6, will give the superficial area in feet of each purifier.

Example.—Required the superficial area of each of the four purifiers in a works equal to the production of 500,000 cubic feet of gas per diem of 24 hours.

 $500 \times 6 = 800$  feet superficial area of each purifier.

 $\sqrt{800} = 17.8$  (say, 18) feet side of square of purifier.

For very small works where there is no exhauster, the constant 8 may be employed with advantage.

Water Lutes.—The evils of contracted area in purifiers are aggravated by having a shallow seal to the lids or covers and the hydraulic centre-valve—if such be used.

In small works the lute should never be less than 12 inches deep by  $4\frac{1}{2}$  inches wide; and in medium sized and large works, from 18 to 80 inches in depth by 6 to 8 inches in width.


Ample depth of water lute is especially important where the back pressure is increased by the use of telescopic holders.

Layers of Purifying Material.—In purifiers charged with hydrate of lime, there may be two or four tiers of sieves. The lime spread upon their surface may be from 4 to 8 inches in depth.

When oxide of iron is used, the layers may be two in number, and the material 15 to 20 inches deep on each.

It is a mistake to adopt the plan of placing either the lime or oxide in a single deep layer. The gas is apt to form passages through the deep material; whereas when there are two or more layers of less depth, it recovers itself and changes its course through each.

Sieves, Trays, or Grids.—Round wrought-iron rods, § of an inch thick, bound together with a framing of angle or flat-iron, make an excellent tray, especially where lime is used: they are less suitable for



oxide of iron, which destroys them by corrosion, though when made of the strength named, they last for many years. They possess a great advantage over most other trays in the smaller space which they occupy in the purifier, and the larger purifying area obtained by their use. Perforated cast-iron and wood trays are suitable for either lime or oxide. The latter are usually made with strips of wood (yellow pine. pitch pine, or red deal, the prices being as 3, 2, 1) of any convenient length; the strips are 17 inches broad. an inch thick, and slightly tapered, the outer pieces of frame being of harder timber (hickory, beech, oak, or ash), and 11 inches thick; the whole bound together with \$-inch bolts and nuts, having the heads, washers. and nuts countersunk in the side frames, and the holes plugged with wood or cement. The strips are kept 1 an inch to 5 of an inch apart by pieces of wood of that thickness, and 17 inches square, put between them at the places where the bolts are inserted (Fig. 70).

Apparatus for Raising the Lids or Covers.—For raising the lids or covers of the purifiers, various contrivances are employed; the most common being a double purchase crab, travelling on rails laid on

either wooden beams or iron lattice girders, having their ends inserted in the walls of the building; or in the absence of walls, supported on pillars. Another arrangement consists of a traveller extending across the purifying house from wall to wall, traversing the length of the house on rails fixed on each side to a beam or girder supported by projecting corbels. On this again there is a lifting crab also on rails, and the gearing of both crab and traveller is actuated by chains from the floor of the house.

The lifting machine, sometimes called a "Goliath" (Figs. 71 and 72), first constructed by Messrs. Cockey and Sons, is a useful and com-




Fig. 71,





Fig. 72.

pact contrivance for the same purpose. This consists of two standards, one on each side of the purifier, connected across the top by two girders a few inches apart. The standards, having grooved or flanged wheels, or rollers attached, traverse the purifying house from one end to the other on rails laid on the floor, The covers are raised by means of two long vertical screws, with an eyelet-hole at the end of each, in which the hooks on the lid are inserted, and moved by a winch and

cog-wheels put in motion by means of a handle at one of the sides. When the apparatus is not in use, it can be wheeled out of the way, leaving the space above the purifiers to the tie-rods or beams of the roof entirely unobstructed. A somewhat similar traveller, in which hydraulic power is applied instead of the wheel gearing and screws, is sometimes employed for accomplishing the same object.

The most compact and efficient lifting arrangement for lids of large size is that of the direct acting hydraulic ram, the head of which is



attached to the centre of the lid, and on the application of water pressure to the ram by means of a hand or steam pump, the lid is raised to the required height. (Fig. 73.)

Centre and other Change Valves.—The dry centre-valve, with surface faced to fit gas-tight, is now extensively adopted, and, as a rule, is preferred to the old hydraulic centre-valve. The chief advantages it possesses over the latter are the greater ease and facility in changing from one purifier to another, one man being able to accomplish this with a few turns of a handle, thus minimizing to the utmost extent the passage of unpurified gas during that operation. It occupies less space, is entirely beneath the purifying-house floor, and presents a dead resistance to pressure admitting of greater steadiness




Fig. 74.




Fig. 75.

in the flow of the gas where an exhauster is at work. But it has its drawbacks. In the larger sizes especially it is liable to lose its tightness on the slightest disturbance of the foundation either by subsidence, or the action of frost, and even by the weight and pressure of the connecting pipes. The Weck valve (Figs. 74 and 75), which consists (for a set of four purifiers) of eight valves within a frame or box. is both handy and efficient, and for large connecting pipes is preferable to the foregoing.

Four-way valves are adopted by some managers in preference to the centre-valve, their chief recommendation being that by their use the connections are simplified. The advantages which they possess over the ordinary single valve are more apparent. When the latter are

employed twelve are needed for a set of four purifiers, and six for a set of two; whereas, with the four-way valves, only one-third that number is required.

Size of Connections.—With respect to the size of the connectingpipes, the rule is to make their internal diameter, in inches, equal, as nearly as possible, to the square root, in feet, of the area of the purifiers.

Thus, purifiers 10 feet square, giving an area of 100 square feet, have connecting-pipes 10 inches in diameter; and purifiers 16 feet by 12 feet, having an area of 192 square feet, have their connecting-pipes 14 inches in diameter. With the larger proportionate sizes of purifiers now being employed over those formerly erected, a deduction of  $\frac{1}{6}$  may safely be made from the result obtained by the above rule. Thus (see rule on p. 119), a works capable of producing 500,000 cubic feet of gas per day requires four purifiers, having each an area of 800 square feet  $[500 \times 6 = 800]$ , the square root being 17.8; deducting  $\frac{1}{6}$ ,

or 2.2, we have 15.1, or, say 15 inches, the diameter of the connecting-pipes.

### CLASSIFICATION

- Of the best known Limestones of this Country, in the Order of their Purity, and which Order also expresses their Value for the purpose of Purifying Coal Gas. (Hughes.)
- 1. The white chalk limestone of Merstham, Dorking, Charlton, Erith, and other parts of the chalk range surrounding the metropolis.
  - 2. The grey chalk limestone, from the lower beds of chalk.
  - 8. The blue beds of the upper and middle Oolites.
  - 4. The lower white and grey limestones of the Oolites.
- 5. The most calcareous and crystalline beds of the carboniferous or mountain limestone, colours grey and bluish.
  - 6. The magnesian limestone of Yorkshire and Derbyshire.
  - 7. The white lias limestone.
  - 8. The blue lias limestone.
- 9. The Silurian limestone of Wenlock, Dudley, &c., and the coralline limestones of Plymouth and the neighbourhood.

TABLE

Showing the Composition of Different Limestones and their Specific Gravity. (Government Commission.)

Quality of Limestone and Locality:	Carbon- ate of Lime.	Carbon- ate of Magnesia.	Silica (Flint.)	Alumina	Water and Loss.	Specific Gravity (Dry.)
Ancaster, Lincolnshire Bath Box, Wiltshire	98·59 94·52	2.90	·.	.80	2.71	2.182
Portland, Dorsetshire	95·16 92·17	1·20 4·10	1 20	1·20 ·50 ·90	1.78 1.94 2.83	1·839 2·145 2·045
6 6 (Barnack, Northamptonshire 5 5 (Chilmark, Wiltshire 1 2 (Ham Hill, Somersetshire .	98·40 79·00 79·80	8·80 3·70 5·20	10·40 4·70	1.80 2.00 8.80	1.50 4.20 2.50	2·090 2·481 2·260

A trace of bitumen was observed in each of the above.

Bolsover, Derbyshire . Huddlestone, Yorkshire Roche Abbey do. Park Nook do.	51·10 54·19 57·50 55·70	40·20 41·37 39·40 41·60	3·60 2·58 ·80	1·80 ·80 ·70 ·40	3·30 1·61 1·60 2·30	2·816 2·147 2·184 2·188
---	----------------------------------	----------------------------------	---------------------	---------------------------	------------------------------	----------------------------------

Other Analyses.

Quality of Limestone and Locality.	Carbon- ate of Lime.	Carbon- ate of Magnesia.	Silica (Flint.)	Iron Alumina (Clay.)	Water and Loss.	Analyst.	
Denton, near York Eldon Aycliffe Portishead, near Bristol Four Miles N.W. of Bristol	68·0 52·0 45·9 58·5 58·0	80·0 45·2 44·6 87·5 88·0	1.5	2·25 1·1 1·57 0·8 1·1	0·25 1·7 2·8 8·2 1·4	Holme Davy do. Gilby do.	

Quality of Limestone and Locality.	Car- bonic Acid.	Lime.	Alu- mina.	Silica.	Bi- tumen.	Water and Loss.	Iron and Clay.	Mag- nesia.
Magnesian, of which York Minster is built	47.00	83 • 24	••	••		••	0.40	19.86
Carboniferous, Whiteford, Flint-	40 • 10	49·65	8.80	0.60	0.60	0.25	••	••

Lime Burning.—This subject is not of absorbing interest to the gas manager in this country, because there is always an abundant supply of lime to be had for the ordering without any need for concern as to how it is produced. But to such as undertake the management of gas-works in some places abroad, it is desirable that they should make themselves familiar with a process which they may have topractice as a matter of necessity or for the sake of economy.


Limestone or carbonate of lime, in some form or other, exists in almost every part of the globe, from the fat or rich qualities down to the lias or hydraulic kinds. These latter are not suitable for gas purification, as they contain an excess of earthy or clayey matter in their composition.

The substance existing in the limestone which gives it its peculiar character of hardness and durability, inasmuch that it resists denuding atmospheric influences almost as effectually as granite and more so than most classes of sandstone—is carbonic acid gas. The chemical formula for limestone is CaCO<sub>3</sub>. The object of burning or calcining the limestone, as is well known, is to expel the water, which is

mechanically held in it, and the carbonic acid, CO. The quicklime or oxide of calcium being left, its formula is therefore CaO. The equation representing the effects of the process of calcination is CaCO. -CaO+CO<sub>2</sub>. Curiously enough, the water which is present in ordinary limestone when it is first broken in pieces, and not dried by exposure to the air, assists the calcination of the material by promoting the escape of the carbonic acid.

The crudest method of burning lime, and that practised by halfcivilized peoples, is to range the materials on the ground in alternate layers with coal, wood, turf, or other fuel, surrounding them with clay or clods of earth to retain the heat; a firehole being left in the bottom, and an opening made in the apex of the heap to allow of the escape of the gas. Fire being applied to the fuel, it is allowed to burn itself out, and the process is complete. This, as might be supposed, is the least economical plan to adopt; the quantity of fuel required bearing an undue proportion to the bulk of lime produced.


Lime kilns are constructed in various forms; but whatever form they take, they are resolvable into two classes—viz., tunnel kilns and flare kilns; the former having the coal or other fuel and limestone arranged within them in alternate layers, and the latter being fired without allowing the fuel to come in contact with the lime. Either of these may be perpetual or draw kilns—that is to say, they may be kept constantly at work by removing the calcined lime from the drawhole at the bottom, and adding fresh material at the top; or the fuel may be fired, and the charge allowed to burn itself out, and become cool



Frg. 76.

before discharging the lime.

A small form of tunnel kiln is shown in Figs. 76 and 77. The lining is of firebrick. 9 inches thick throughout: but this does not always extend to the top, and in some examples the lining is en-



SECTION.

Fig. 77.


tirely of gritstone a foot thick. Between the lining and the outer masonry, a cavity 2 inches wide is left—being filled in with ground stone, ashes, or other yielding material — to admit of the expansion of the lining by the heat without rending the structure.

In charging the kiln, a layer of brushwood or other easily-igniting fuel, is placed at the bottom to assist the kindling of the coal at the beginning. Then comes a layer of coal about 4 or 6 inches thick. After that a layer of limestone 12 to 16 inches deep, in pieces ranging in weight from 2 lbs. to 20 lbs.; the largest being placed in the centre, and so on. The stratification of the materials in alternate layers is continued till the kiln is completely filled, when the fire is lighted, and the burning or calcining process is begun. In the perpetual or draw kilns, where the operation is carried on continuously, so long as the kiln lasts, the burned lime is raked out through the draw-hole at the bottom. The mass gradually subsides, filling up the void; and fresh fuel and limestone are added at the top.


The flare kiln, shown in Figs. 78 and 79, is the more cleanly of the two, the firing substance being kept apart from the lime; but it is not as efficient and certain in its action as the tunnel kiln where the material is placed in alternate layers.

In course of burning, the stone is heated to redness; and when the whole of the carbonic acid has been expelled, the redness disappears, and the quicklime, or oxide of calcium, is left in rich white floury lumps.

The proportion of coal used varies according to the obdurate nature of the limestone. In some instances one measure of coal serves for four of the stone; but in others it takes about one ton of coal to burn two



ELEVATION. Fig. 78.



SECTION.

Fig. 79.

tons of the stone. On the average, three bushels of lime are produced for each bushel of coal consumed. In the case of other fuels: a similar weight of gas-works coke, mixed with one-fourth small coal, is needed, and of wood and turf one cubic foot of limestone requires 1½ cubic feet of these in the burning.

The product known as "lime ashes," is the breeze of the kiln, and consists of small and dusty lime mixed with the ashes of the fuel.

In countries possessing a scanty supply of limestone, calcareous spar and oyster and other shells found on the sea coast are calcined into quicklime, which is produced as a fine flour.

It only remains to be said that the quicklime on its removal from the kiln is stored in sheds under protection from the weather. On its being slacked with water, it evolves much heat, crumbling or falling, and becomes hydrate of lime; its formula being CaH<sub>2</sub>O<sub>2</sub>, in which condition it is ready for the purifiers.

# THE STATION METER AND OTHER INDICATING AND RECORDING APPARATUS.


The most important of the recording appliances in a gas-works is the station meter. The house containing this should be conveniently situated on the works, and made sufficiently large to contain, if possible, in addition to the meters, the station governors, exhaust and pressure registers, a range of pressure gauges, and a jet photometer. When thus arranged they are all within the purview, and immediately under the control, of the workman in charge. The meter house is susceptible of ornamentation, and should have a little bestowed upon it, besides being kept scrupulously clean and well ventilated.

Station Meter.—The quantity of gas manufactured as it passes into the holders after its purification has been completed, is measured and recorded by the station meter.

This is invariably of the "wet" description: that is to say, the measuring wheel is caused to revolve by the elastic force of the gas pressing upon the surface of a body of water, with which the vessel is charged up to a certain line.

In construction it differs slightly from the wet meters used by consumers, but its principle of action is identical with these.

Pressure Gauges.—The ordinary pressure gauge (Figs. 82 and 83) has its tubes, which are of glass, charged with water to the zero line on the ivory or boxwood scale between. This is graduated into inches and tenths. It is made of any length as required, and the scale may be figured either in inches or tenths of an inch, as shown.



On the gauge being attached to the main or service pipe, either directly or by means of a short connecting tube, the difference between the two water levels represents the gas pressure in terms of a column of water.

A series of these gauges, to indicate the pressure existing between the different apparatus of the gas-works, should be fixed in some position convenient for frequent inspection.


King's gauge (Fig. 85) is constructed on the same principle as the above, but it indicates slighter variations of pressure; the finger having a long sweep for small differences of water level, and the dial being graduated into finer divisions.

The differential gauge (Fig. 84) is commonly attached to the inlet and outlet pipes respectively, of station meters; the indications of the instrument being the difference in pressure between the two, showing the pressure absorbed in actuating the meter.

Coloured water for pressure gauges is made by infusing a little pounded cochineal in hot water. It is then filtered, and a few drops of nitric or hydrochloric acid added, to prevent the bright scarlet colour from fading.

The glass tubes of pressure gauges, when foul, may be cleansed with a weak solution of sulphuric acid in water.

Pressure and Exhaust Registers.—The principle of action of these instruments (Fig. 86), invented by Crosley, is the same as that of the foregoing, but they are made to record as well as indicate the pressure or exhaust, as the case may be.



This is accomplished by means of a float in water, to which a vertical spindle is attached, having a lead pencil at the upper end, pressing upon a cylindrical graduated roll of paper upon a drum, which is caused to revolve by clockwork once in the 24 hours. The paper roll is renewed daily.

The exhaust register is connected to the mains on the works at a point between the hydraulic main and the exhauster, and the record shows, whether, in the absence of the manager, the exhauster has been kept working with regularity.

The pressure register is attached to the street main beyond the governor, and records the various pressures maintained therein during the day and night.


The difference between the exhaust and pressure registers is simply one of detail in construction: the zero line in the former being placed midway on the scale, and the spindle lengthened to correspond, whilst the area of the float is also increased. In the latter the zero line is at the bottom.

Wright's pressure register (Fig. 87) is a combination of the King's gauge, with a time-piece having a circular plate and paper disc instead of a dial. The 24 hours are printed on the disc, and a pencil at the end of a rod actuated by the float, pressing upon this, records the varying pressures.

Mr. W. H. Cowan has invented a neat and compact instrument which records the pressures by photography upon sensitized sheets on the revolving cylinder, instead of by the markings of the usual lead pencil.

#### THE GASHOLDER TANK.

The tank is that portion of the storage reservoir for gas which contains the water in which the floating vessel or holder rises and descends. (Figs. 88, 89, 90.)



It may be constructed either wholly or partially under the ground level, or (as in the case of iron tanks) entirely above ground (Fig. 89).

The first thing to be done, in determining the site of a tank. is to sink a well or shaft in the vicinity, or to make a number of borings on or near to the site, in order to ascertain the character of the strata in which the excavation for the proposed tank has to be made. If the ground in the immediate neighbourhood is clear of other tanks or buildings, it is not a matter of serious concern to find that a bed of sand, full of water, has to be encountered. To overcome a difficulty of that kind in such circumstances, is chiefly a question of pumping power. Piling also might be resorted to, and the free use of concrete, in case there is a possibility of the water being removed by pumping from underneath the tank at any future time. But, on the other hand, if there are adjacent structures which it is unwise to run the risk of damaging, then it is well to be chary about pumping the water from the underlying sand and gravel. In such event, it is almost a matter of certainty that the removal of the water, accompanied also by the removal of a large proportion of the sand along with it, would cause subsidence of the ground in the vicinity, with consequent, and possibly irreparable, damage to the structures upon it. The safer and more prudent thing to do in such a case is either to abandon the site for another; or, if that cannot well be done, to construct the tank either wholly or partially above-ground, and of cast or wrought-iron plates.

Assuming that the site for a gasholder tank has been finally settled; that it has been decided the tank shall be constructed of masonry (which term includes stone, brick and concrete, or a combination of these); that it has been ascertained by boring that water is present in objectionable abundance in the substrata to be pierced—the first thing to be done is to sink a well or sump. 8 to 4 feet in diameter. at a convenient distance from the circumference of the proposed excavation. This should be lined with open unmortared brickwork (technically called "steining"), to allow of the free percolation of the water into the sump or well through the joints of the lining. Into this, when the sinker has reached the water-bearing strata, he conveys the suction-pipe of the pump, puts the latter in operation, and clears out the inflowing water to enable him to proceed with his work. This well is carried down to a depth of 8 to 5 feet (depending on the volume of water present), below the bottom of the intended excavation, and is then paved with bricks set in cement. If the strata are of uniformly open character—consisting, say, of a mixture of gravel and sand—one sump will be sufficient to clear the ground of water; otherwise, if it is not uniform, but barred by intervening clayey deposits (not an unusual thing), and even by solid-bedded sand—for this sometimes is almost as impervious as clay—it may be necessary to drain the water to the sump, or even to put down two or more sumps outside the ground operated on. Duplicate pumps should be provided where the inflow of water is very great. With these arrangements completed, the work of excavating and building can be proceeded with unhindered by the presence of any undue amount of water.

In the course of practice, the excavation for a tank of which the writer was engineer was chiefly through hard sand-stone rock, the lavers of which had been tilted up into almost the vertical position. This was fissured and cracked in all directions; and through the crannies, water bubbled up in numberless springs. Although one side of the adjacent ground was at a lower level than the tank bottom, it was impossible, by any reasonable expedient, to draw off the water from the outside. Possibly, by sinking a shaft to a considerable depth, it might have been accomplished. But considering the nature of the strata, that would have been costly; so other means were resorted to to overcome the difficulty. It is not an easy thing-in many cases it may be pronounced to be impossible—to choke out water from a tank from the inside. In puddling the bottom of the tank in question, and covering the puddle with a bed or layer of concrete, the springs were by no means closed; and though they were reduced in number, the flow of water was still quite as plentiful as before. Assuming that the pressure in these springs was sufficiently great to have overcome the pressure of the head of water in the tank when the latter was full, there would have been no objection to leaving them to flow unhindered. But that was a risk which it was not prudent to run. The head of water in the tank would probably have more than counterbalanced the pressure of the springs; and where water can enter, it can as easily make its exit. The plan which in this case was adopted for making the tank water-tight, was to train or drain the different streams of inflowing water to one point by cutting a trench round the side of the bottom where the springs occurred, and laying therein strong 3-inch drain pipes, which in turn were carefully protected by a covering of strong concrete. The springs usually occur at, or near to, the base of the mound or dumpling left in the tank bottom; so that it is easy to gather them together by a drain and convey the water all to one convenient point. There was now only one stream of inflowing water to deal with; and at this point was placed a 8-inch cast-iron stand-pipe, 3 feet in length, closed by a valve at its upper end, and the flanged foot secured by four Lewis bolts let into a base-stone 18 inches square and 9 inches thick, through the centre of which a hole was drilled. This stone was let into the floor slightly below the level of the concrete surface; and a cavity was left underneath it. From this stand-pipe, the inflowing water was pumped to relieve the pressure on the bottom till the cement in which the stone was bedded had set hard. It should be mentioned that, in the side of the stand-pipe. at distances of 9 inches apart, there were three 3-inch holes drilled. These were left open, to allow the water to issue from them without rising to the top. As the filling of the tank proceeded, these holes were each carefully plugged as the water rose above them; then the valve on the upper end of the stand-pipe being closed, the filling with water was completed—the tank proving to be perfectly water-tight.

Another method sometimes adopted, instead of using a stand-pipe as described, is to carry the drain right through the tank wall at its base, thus making an outside exit for the water. The stand-pipe, however, is preferable as being more self-contained and certain in its action. It sometimes happens that, without previous indication of its presence, the pressure of surrounding water will, in the course of construction, blow a hole or holes in the tank bottom. If so, the best thing is to let it blow; let it have free vent until all is completed and the tank ready for water, then apply the stand-pipe as described.

In another instance, the line of circumference of a tank came close up to the side of a retaining wall bounding a considerable stream. In this case, the excavation having to be carried close up to the wall, the latter was laid bare for about 30 feet of its length; and as the cutting had to be taken about 6 feet below the level of the water in the stream, the rush of water through the interstices of the wall would have been fatal to the operations. Accordingly, to shut out the water, a wall of wooden sheet-piling was constructed—a cofferdam, in fact—60 feet in length; and the wooden piles forming one side of it were shod with iron, and driven (most of them) 12 feet into the bed of the stream. They were then bound together at their upper ends by a horizontal beam bolted thereto, and anchored at distances 10 feet apart with long bolts passing through the retaining wall. The space between the piling and the stone wall was two feet in width, and was hand-dredged to a depth

of ten feet below the water level. This space was carefully filled in to above the stream level with stiff clay puddle, well rammed down. The work was eminently successful; and it was found an easy matter to cope with any water from the stream that reached the excavation, either from beneath or from beyond the two ends of the cofferdam.

The presence of water in an excavation is not always objectionable, unless it be excessive in volume. For example, in excavating through stiff clay, it renders the work of the labourer much easier than if the ground is dry and hard. Those who have had experience in shifting boulder clay, will readily endorse this view. Strata of this character are often so hard and parched and intractable as to require blasting to facilitate removal.

Avoid puddling a tank-bottom in wet weather, especially if the bottom is in the form of a mound or cone. Uniformity of consistence in the puddle is of more importance here than against the outside of the walls, for the obvious reason that the bottom has to bear the pressure of the water when the tank is filled. If one portion is well consolidated and firm and another soft and yielding, the concrete covering is liable to crack and split open, owing to the unequal sustenance. It is almost impossible to preserve this necessary uniformity with water coursing down the slope of the mound; the puddle becoming sodden and sloppy. The fact that equal sustenance is of such importance, also proves the necessity of having the clay covering on the bottom of one uniform thickness all over. Even the deeper excavation made to receive the horizontal portions of the inlet and outlet pipes should have a solid concrete filling, allowing for just a like thickness of puddle above them as over the other parts of the apron and cone.

It is not a wise thing to test the tightness of a tank with water immediately on completion. Better wait till the holder is finished, in order to give the puddle and cement time to set before subjecting them to the heavy pressure of water. We have known several instances of the splitting of tanks due to this premature filling with water. Further, before filling a tank with water for the first time, the puddle and backing behind the wall should be carefully watered—by means of a hose-pipe, if possible—for several days before the filling is begun, and also during its progress. This promotes consolidation of the backing.

In excavated tanks, wherever the substratum is favourable, it is economical to leave a circular or conical mound in the centre. This is called the "dumpling" or "cone" (Fig. 88).

Tanks are occasionally formed by making a circular cutting in the ground, and erecting therein an iron or brick annular channel to contain the water, the intervening central space being also covered with water, but of a less depth, depending on the extent to which the subsoil has been removed. This central space requires to be covered with a layer of concrete, and the surface rendered with Portland cement. These are called annular tanks. See Fig. 90.

Excavation for Tank.—The width of the excavation for a tank depends on the nature of the substrata encountered, whether clay, shale, gravel, sand, &c., unless a complete system of close-shoring by means of timber all round is adopted. The best method is to sink a trench 12 feet wide all round the circumference, and close-timber both sides of the excavation. Where the ground is yielding and soft, or saturated with water, the vertical shoring-timbers may be 7 inches wide and 8 inches thick; the waling pieces double, and 8 feet apart, 11 inches by 8 inches, and the struts 9 inches by 6 inches, in cross section. This will afford substantial support.

Natural Slope or Angle of Repose of Earths with Horizontal Line. (Fig. 91.) Sand, dry average  $97^{\circ}$  or 1.88 to 1Sand, damp . 21° ., 2.68 ., 1 Shingle and gravel. 40° ,, 1·2 ,, 1 Clay, drained. 45° ,, 1.0 16° ,, 8·8 Clay, wet Earth, compact 48° ,, 0.9 ,, 1 Frg. 91. Peat or vegetable earth 28° ., 1.89 ., 1


Weight of various Earths and Rocks.

Per Cubic Yard,						Per Cubic Yard.				
Sand, dry .	:	about	2480	lbs.	Marl		. al	bout	2900	lbs.
Sand, damp		,,	<b>3200</b>	,,	Shale			,,	4870	,,
Shingle and gr	avel	٠,,	2850	,,	Chalk	•		,,	4000	,,
Clay		,,	8240	,,	Sandstone		•	,,	4250	,,
Mud		,,	2700	,,	Slate	•	•	,,	4860	,,

Materials of which Tanks are Constructed.—Tanks are constructed of stone (either built up, or excavated from the solid rock) brick, concrete, cast or wrought iron, or a combination of iron with the other materials.

The kind of material employed is regulated, as a rule, by the character of the district where the gas-works are situated, and the nature of the ground whereon the erection is to be. If the neighbourhood abounds in stone, the probability is that that will be the cheapest, and will consequently be adopted in the construction of the tank. But even in districts where stone is plentiful, if this is of a hard nature, the expense of dressing is such as to make the tank more costly than if built of bricks, though the latter may have to be brought from a distance. In places distant from a supply of building material, and to which the latter has to be brought by conveyance, brick will generally be chosen as the most suitable.

On the other hand, where the ground is of such a character as would entail an extraordinary outlay in securing a good foundation, or where it is unsafe for a brick or stone structure; or, again, where the sinking of a tank is almost impossible, owing to the presence of a large body of inflowing water through the strata, as by the sea-side, or contiguous



to some rivers, the best class of tank to be adopted is one made either of cast or wrought iron, or steel plates bolted or riveted together, the cast-iron plate joints being either planed or made water-tight with rust cement. It is only under such circumstances that iron tanks are adopted, as their cost is greater than either brick or stone, and the erection of a tank above ground is disadvantageous in several respects.

It may happen that the ground is of such a nature as to render the construction even of an iron tank upon it unsafe; or there may be a slope or embankment in dangerous proximity. In such cases recourse may be had to piling to give it solidity and prevent movement.

In the construction of a tank the use of a trammel to insure accuracy in the circle is indispensable. In Fig. 92 is shown a convenient form of this apparatus.


When the tank is of large diameter, say 140 feet and above, the movable arm of the trammel is necessarily long and heavy, and in such case the centre post may be a steel lattice girder stayed with wire guy ropes. The apparatus should remain in position and use until the tank coping is fixed. In addition to the trammel, wood templates 16 feet long, made to the proper curve on their outer edge, should be provided and frequently applied to the surface of the wall as it rises.

Masonry tanks, being porous, are generally built with a backing of clay puddle behind the walls and in the bottom; but the puddle can be dispensed with by lining the tank with a coat of neat Portland cement about 1 inch in thickness. Mortar composed of cement and clean sharpsand in equal proportions by measure, makes a water-tight lining, provided it is carefully polished to a smooth face with a steel trowel.

A lining of 4½-inch brickwork, with a space between the tank wall and the lining, 1 inch wide, filled with neat cement or asphalte, is also occasionally adopted.

The walls of a tank so treated, being impervious to water, require to be made somewhat stronger, and the backing more carefully consolidated, than where puddle is employed, because there is no fluid pressure outside to balance the fluid pressure within the tank.

The weakest part of a masonry tank, as usually constructed, is that where the inlet and outlet pipes pass through the wall at the bottom. The instances of failure here are so numerous as to justify



the plan, sometimes adopted, of placing the pipes in a recess built in the tank wall. The objection to this recess is that it breaks the circle of the wall, and consequently weakens its power of resistance to outside pressure; but continuity of the circle can be secured by strutting the opening with cast-iron struts as in Fig. 98.

Or the pipes can be made square in section, and built in with the wall, as in Fig. 94.

When a brick or stone tank built in blue lias lime mortar is of large dimensions, the walls may be strengthened at intervals of 2 or 8 feet apart, by rings 2 or 8 feet in width, of the brick or stone laid in Portland cement mortar.

Hoop-iron, or flat wrought-iron rings, built at intervals into the masonry or concrete, are occasionally used for giving strength to the walls of a tank. When the diameter is great, and particularly in tanks where no puddle is employed, flat bar-iron hoops, braced or tightened by screws or cotters, are also sometimes placed round the outside.

When from any cause it is found impracticable or undesirable to construct a masonry tank, whether of stone, brick, or concrete, with its coping on a level with the adjacent ground, circumstances may require that the raised portion of the wall should be strengthened, in addition to the support given by the earth backing, either by flat wrought-iron or steel rings built into it, or by outside wrought-iron or steel hoops. One such ring or hoop will suffice for every 4 feet in height of the tank wall above the natural ground level. The strength of the iron will, of course, be determined by the dimensions of the tank; but it may be stated, by way of guidance, that for a tank of 102 feet in diameter, the iron should be 5 inches wide and  $\frac{3}{4}$  of an inch thick. The flat ring is made continuous throughout the circle by riveting, and the hoop by screw-bolts or cotters.

The bricks used in building a tank should be thoroughly well wetted before being laid, to cause the mortar to adhere.

In time of severe frost all brick and stone work should cease.

To prevent injury in time of rain, and especially in winter, when a sudden frost might supervene, the top of the new walling should be covered with weather boards.

#### Concrete.

By measure.										
6 parts.										
2 parts.										
1 part.										
Portland cement concrete (for tank walls)—										
7 parts.										
2 parts.										
1 part.										

Mr. J. Douglas gives the following useful instructions for mixing or preparing the concrete :- "A platform, about 20 feet square, of deals, should be laid on the ground to ensure the clean mixing of the materials. The measure for the material is simply a square box without top or bottom, and should contain, as a convenient quantity, about It should be twice as many inches deep as the proporhalf a vard. tions of cement and ballast. For instance, if the cement is 1 in 8, it should be 16 inches deep. Inside, at 2 inches from the top, nail a lath all the way round; and after placing the measure at one end of the platform, fill the box with shingle or ballast to the level of the lath, and complete with cement, striking the cement level with a straight-edge. The box measure can then be lifted up and removed. when the cement will fall down over and among the aggregate, and the whole mass should be twice turned over dry. Water can then be added through a rose, and the whole turned twice over again. As little water should be added as possible, but enough to thoroughly moisten the whole mass. The concrete is then fit for use. In dry weather it is necessary to keep the work damp, as, if there is not sufficient water to enable the cement to set—about 111 per cent.—the concrete will be useless. It is also important to thoroughly wet the previous work on which the fresh concrete is to be laid."

Concrete is best placed in position from barrows wheeled close up; it should then be well and solidly rammed down. To tip it from a height (as was formerly the practice) is objectionable, as tending to disintegrate the ingredients of which it is composed.

The Kind of Mortar Employed.—In the construction of brick or stone tanks, hydraulic mortar or cement mortar, either one or the other, or both, is invariably used. The following is their composition:—

# Hydraulic Mortar.

	4 4 ·/ w/ ·	WILL DO 2	TO VICE	•		
	·					By measure.
Best blue lias lime	•	•	•		•	1 part.
Clean sharp river s	$\mathbf{and}$	•	•	•	•	2 parts.
1		or,				
Best blue lias lime		•	•	•	•	1 part.
Burnt clay .	•	•	•	•	•	2½ parts.
		or,				
Best blue lias lime	•	•		•	•	1-part.
Puzzolana .	•	•	•	•		1 part.
Clean sharp sand	•	•	•	•	•	6 parts.

#### Cement Mortar.

Cement, Portland . . . . . . 1 part. Clean, sharp sand . . . . . . 8 parts.

The lime should be fresh burnt, and not more than sufficient of the mortar for a day's work prepared at once. The cement mortar should only be made as it is being used.

The characteristics of good Portland cement are thus succinctly stated by Mr. Faija:—"In colour it should be of a dull, bluish grey; and should have a clear, sharp, almost floury feel in the hand; it should weigh from 112 lbs. to 118 lbs. per striked bushel (87 to 92 lbs. per cubic foot), and when moulded into a briquette, or small testing-block, and soaked in water for seven days, should be capable of resisting a tensile strain of from 800 to 400 lbs. per square inch. The cement should, during the process of setting, show neither expansion nor contraction."

Puddle.—For puddle, clay mixed with one-third sand, silt, or soil free from vegetable fibre, is preferable to pure clay, being firmer in texture, and less liable to crack when dry. It should be prepared outside of the trench, put in in thin layers as the wall of the tank is built, kept moistened, trodden well in with the feet, and backed up with earth carefully pounded. A cubic yard of puddle weighs about two tons.

Iron Tanks.—In east-iron tanks the flanges of the bottom plates should always be *inside*; whilst those for the sides may be *outside*, and the plates should break joint with each other throughout.

Iron piers, or piers of brick, stone, or concrete, are erected at equal distances apart round the outside of iron tanks, for the purpose of supporting the gasholder columns or standards. If the tank is of small dimensions, the standards may be bolted to strong brackets secured to the upper tier of side plates.

Leakages of water from *iron tanks* may often be greatly reduced or altogether stopped by emptying a bushel or two of horse dung into the water contiguous to the escape. A handful of fine iron filings sprinkled lightly over the dung will be found of advantage. By this simple expedient, very heavy escapes have frequently been reduced to a mere drip within the space of a few minutes.

Dry Wells, and Inlet and Outlet Pipes.—The dry or stand pipe well is not necessarily the invariable accompaniment of a gasholder tank. Some engineers prefer to dispense with it altogether.

Many of the largest tanks are made without dry wells, the inlet and outlet pipes being of such ample diameter as to admit of their examination and repair, if need be, from the inside.

The advantage supposed to be gained by providing a dry well is the facility which it affords of access to the inlet and outlet pipes, both vertical and horizontal, in case of fracture, without disturbing the puddle or other backing of the tank wall.

In small tanks it is not unusual to form a recess in the tank wall in which the inlet and outlet pipes are placed, and are thus accessible when the tank is emptied of water. (Fig. 98.)

The inlet and outlet pipes, especially when of wrought-iron or steel, should be securely anchored or bolted down to the stone or concrete base on which they rest within the tank. If this is not done, the water, by reason of its floatation power, is liable to raise them slightly, and so disturb and cause a leakage through or past the puddle or concrete in which the horizontal portions of the pipes are embedded.

Thickness of Tank Walls.—The walls of masonry tanks (brick, stone, and concrete) are never required to resist, unsupported, the pressure of the water acting upon their sides; but are generally built under the surface level of the ground within the space of an excavation made for that purpose, and having a backing of earth carefully rammed all round them. If the upper portion of the tank is allowed to rise above the natural ground level, a supporting embankment is raised behind the projecting portion. The earth backing offers a resistance to the pressure of the water within the tank, greater than the combined weight of the wall and the cohesive nature of its component ingredients; and consequently in designing a tank wall this fact is allowed for, and a deduction made from the calculated unsupported thickness of the masonry.

In the well-known Mémoire by M. Arson, a translation of which, by Dr. Pole, is given in "King's Treatise" (Vol. II., p. 181 et seq.), the author investigates this subject with his usual ability. After some preliminary observations on the nature of the ground, and the choice and placing of material, he proceeds to a consideration of the forces and resistance in a gasholder tank of masonry, and deduces the formulæ as follows:—

As to the Pressure of the Water.

(1) S D 
$$\frac{H^s}{6}$$
 = the total force of the water.

Then as to the threefold resistance to this force.

(1) C 
$$D^1 \frac{H^2}{2}$$
 = the resistance of the earth backing.

(2) 
$$\frac{P E^{2} D^{1} H}{2}$$
 = the resistance of the weight of the masonry.

(8) K H<sup>2</sup> E = the resistance due to cohesion.

Adding the combined resistance from the three sources together, we have—

$$C D^{1} \frac{H^{2}}{2} + \frac{P E^{2} D^{1} H}{2} + K H^{3} E.$$

And to produce stability of the tank these must be greater than the effect of the pressure of the water—

$$SD\frac{H^8}{8}$$

where D = Internal diameter of the tank in feet.

E = Thickness of the wall (average) in feet.

D1 = External diameter of the tank in feet.

H = Height of wall in feet.

S = Weight of a cubic foot of water.

.C = Resistance of the earth backing in lbs. per sq. foot.

P = Weight of a cubic foot of the masonry.

K = Cohesive force per sq. foot.

Applying these formulæ to a tank actually constructed, let us see how they work out. Take the tank described on p. 154:—

D = Internal diameter of tank, 122 feet.

E = Average thickness of wall, 21 feet.

D1= External diameter, 127 feet.

H = Height (or depth), 24 feet.

S = Weight of a cubic foot of water, 62.5 lbs.

C = Resistance of the earth backing per sq. foot, clay and earth, say average, 1200 lbs.

P = Weight of a cubic foot of the masonry, 112 lbs.

 K = Cohesive force per sq. foot, bricks in 1 Portland cement to 8 sand, mortar, 81,680 lbs. Then-

(1) 
$$8 D \frac{H^{3}}{6} = 62.5 \times 122 \frac{24^{3}}{6} = 17,568,000 = total force of the water in lbs.$$

(1) C 
$$D^1 \frac{H^3}{2} = 1200 \times 127 \frac{24^3}{2} = 43,891,200 = \begin{array}{c} \text{in lbs.} \\ \text{resistance of earth backing.} \end{array}$$

(2) 
$$\frac{P E^{3} D^{1} H}{2} = \frac{112 \times 2 \cdot 5^{3} \times 127 \times 24}{2} = 1,066,800 = \text{resistance of weight of masonry.}$$

(3) K H<sup>3</sup> E =  $81,680 \times 24^3 \times 2.5 = 45,619,200 = \text{resistance due}$  to cohesion.

90,577,200 = total resistance in lbs.

or more than five times the pressure of the water, which is an ample margin for safety.

It has already been pointed out that the walls of brick tanks, which are porous in some degree, having a backing of clay puddle behind and over the tank bottom, are placed in equilibrium by the water on both sides, and therefore do not require to be of as great a thickness as those with an internal lining of cement impermeable to water. In the latter case special care should be taken to see that the earth backing is thoroughly consolidated behind the wall, so that the pressure of the water against the tank may be transmitted thereto direct, without danger of rupture to the masonry.

When it is required to ascertain the thickness of any portion of a tank wall to resist the force of the water pressing against it, the formula as under is applicable:—

$$\frac{PD}{K-P} = \text{thickness in inches.}$$

Where P = the pressure of the water in lbs. per square inch.

D = the radius of the tank in inches.

K = the safe cohesive force in lbs. per square inch.

Example.—A brick and puddle tank set in Portland cement mortar is 122 feet in internal diameter and 24 feet deep to the surface of the rest stones. Required the thickness of wall immediately above footings.

The pressure of the water on each square inch will therefore be-

$$\frac{62.5 \times 24}{144}$$
 = 10 lbs. pressure of water per square inch.

The safe cohesive strength of the brickwork in Portland cement mortar (1 cement, 8 sand) may be taken at  $220 \div 2 = 110$ .

Then: 
$$\frac{PD}{K-P} = \frac{10 \times 782}{110-10} = \frac{7820}{100} = 74$$
 inches, nearly, or 6 ft. 2 in.

the required thickness of the wall. It will be seen, however, that in this calculation no account has been taken either of the resistance offered by the weight of the masonry, or of the support given by the earth backing; so that the result obtained is the thickness of the wall to resist the pressure of the water without any backing. And as this latter may be taken as fully equal to the other, the thickness obtained by the calculation may be reduced by one-half-i.s., to 8 ft. 1 in.—which will be the required thickness of the wall above the The required thickness at any other depth may be found in like manner. The pressure of the water, which varies in proportion to the depth, may be represented by a right-angled triangle ABC.

and, therefore, the thickness at the top would work out to nothing. It must not be overlooked, however, that the tank sides act as a retaining wall to the earth both during construction and at any time afterwards, when the water is withdrawn; and consequently the thickness should be graduated from the ascertained thickness at the base to about 21 or 8 bricks width at the coping.

The thickness of 81 feet at the base of the wall is too thin by more than one-half for an ordinary retaining wall of that height (24 feet); but it must be remembered that this apparent weakness is counterbalanced by the circular form of the structure, possessing as it does all the qualities of the arch, and being built up, both wall and backing, gradually throughout the complete circle from base to coping.

The conditions, as regards backing, of cast, wrought-iron, and steel tanks are different. These being generally erected above ground, the resistance offered to the bursting force of the contained water is entirely due to the cohesive strength of the metal.

The same formula, however, is applicable here, as will be seen from the next example of a cast-iron tank, where the safe cohesive strength of the iron is taken at 4000 lbs. per sectional square inch, its ultimate tenacity being 16,000.

Example.—A cast-iron tank is 80 feet in internal diameter and 18 feet deep. Required the thickness of the lower ring of plates. These are generally 8 to 4 feet in depth, but the water pressure on the lowest foot may be taken.

Here 
$$\frac{62.5 \times 18}{144}$$
 = 7.8 lbs. pressure of water per square inch.

Then-

$$\frac{PD}{K-P} = \frac{7.8 \times 480}{4000-7.8} = \frac{8744}{8992 \cdot 2} = .987$$
, or say 1 inch,

the required thickness; and so in like manner the required thickness of the several higher rings may be ascertained. This thickness may be slightly reduced by making allowance for the assistance given to the lower ring of plates by their attachment to the plates forming the bottom of the tank, and especially if iron hoops are employed round the outer circumference to give rigidity to the structure.

The safe cohesive strength of wrought-iron plates may be taken at 10,000 lbs. per sectional square inch.

Wrought-iron and steel tanks do not require to be strengthened by hoops.

# Examples of Construction.

The following are examples of gasholder tanks constructed under moderately favourable circumstances. It will be found advisable in practice, in some instances, to increase the strength of the walls and footings. A bed of concrete should be laid round the circle, and the brick footings built upon it. This is especially necessary where the ground is of an unsatisfactory character.

# BRICK TANKS.

Diameter, 21 ft. 6 in. Depth, 10 ft.

Footings, 8 single courses; width respectively, 8, 2½, and 2 bricks.

Wall, 1½ bricks thick for half the height, diminishing by an offset on the outside to 1 brick for the remainder.

Coping of wall, bricks set on edge, in cement.

Piers to support gasholder columns, 4 in number, brought up from foundation, and built in with the wall, each capped with a stone 2 ft. square, 8 in. thick, having 8 holes drilled in each for the holding-down bolts.

Rest or landing stones, 8 in number, 15 in. square, 6 in. thick, laid on footings built at bottom, bound in with the wall-footings.

Puddled with clay, mixed with one-third fine sand, or soil free from vegetable fibre, 2 ft. thick at bottom; and at the sides, tapering from 2 ft. at the base to one foot at the top.

Bottom, flagged with 8 in. flags.

Bricks, best hard-burnt stocks.

Mortar, lias lime one-third, sharp river sand two-thirds.

Diameter, 88 ft. 6 in. Depth, 12 ft.

Footings, 2 double courses, width 8 and 2½ bricks.

Wall, 2 bricks thick for 8 ft. high, and 1½ bricks for the remaining 4 ft., set off on outside.

Coping of wall, bricks on edge, laid in cement.

Piers, 4, bound in with wall, and brought up from foundation, each capped with a stone 2 ft. square, 9 in. thick, with 8 bolt-holes.

Rest stones, 8; each 16 in. square, 6 in. thick, let into face of wall 2 in.; laid on footings.

Puddled with clay puddle, composed of two-thirds clay and one-third fine sand, trodden well together, 2 ft. thick at bottom and sides, tapering to 1 ft. 6 in. at top.

Bottom, flagged with yard flags, 8in. thick.

Bricks, best hard-burnt stocks.

Mortar, composed of best lias lime, mixed with two-thirds sharp sand.

Diameter, 89 ft. Depth, 14 ft.

Footings, 2 double courses,  $8\frac{1}{2}$  bricks wide at base, diminishing by offsets to bottom of wall.

Wall, 2½ bricks at bottom to height of 6 ft.; next 4 ft., 2 bricks; remaining 8 ft. 6 in. to underneath coping, 1½ bricks thick.

Coping stones, 6 in. thick, laid in cement, and cramped together on the outside.

Piers, 5, brought up from foundation, each capped with a stone 2 ft. 6 in. square, 9 in. thick, with 4 bolt-holes.

Rest stones, 10, let 8 in. into face of wall, 18 in. square, 6 in. thick on footings.

Puddled with clay, mixed with one-third sand, 2 ft. thick at bottom and at the sides, tapering to 1 ft. 6 in. at top.

Bottom, brick paved.

Bricks, best hard-burnt stocks.

Mortar, lias lime, mixed with two-thirds sharp river sand.

Diameter, 51 ft. 6 in. Depth, 16 ft.

Footings, 2 double courses, 81 and 8 bricks wide.

Wall, thickness at base to height of 7 ft., 2½ bricks; next 5 ft., 2 bricks; and remaining 4 ft., 1½ bricks.

Coping, bricks on edge, set in cement.

Piers, 5, carried up from foundation, each pier capped with a stone 8 ft. square, 9 in. thick, having 4 holes for holding-down bolts.

Rest stones, 10, 18 in. square, 6 in. thick, laid on footings, and let 8 in. into face of wall.

Puddled with clay, mixed with one-third sand, 2 ft. thick at bottom and sides, diminishing to 1 ft. 6 in. at top.

Bottom flagged with yard flags 8 in. thick, bedded on the puddle. Bricks, best hard-burnt stocks.

Mortar, lias lime, mixed with two-thirds sharp river sand.

Diameter, 62 ft. Depth, 14 ft.

Footings, 4 courses; width respectively 4½, 4, 8½, and 8 bricks.

Wall, thickness at base to height of 5 ft.,  $2\frac{1}{2}$  bricks; next 5 ft. 2 bricks; remaining 8 ft. to underneath coping,  $1\frac{1}{4}$  bricks.

Coping stones, 1 ft. thick, dressed to the proper radius, and laid in cement.

Piers, 6, brought up from foundation, bound in with tank wall, each capped with a stone 8 ft. square, 10 in. thick, with 4 bolt-holes.

Rest stones, 12, 18 in. square, 8 in. thick, laid on footings.

Mound or cone left in bottom of tank, 8 feet less in diameter than the latter, flagged round the base, other part pitched with random stones.

Puddled with clay two-thirds, intimately mixed with one-third sand; 2 ft. thick at bottom; the sides, 2 ft. at base to 1 ft. 6 in. at top.

Bricks, best hard-burnt stocks.

Mortar, lias lime, mixed with two-thirds sand.

Diameter, 62 ft. Depth, 20 ft.

Footings, 5 courses, first course, double, 5 bricks in width; others single; 4½, 4, and 8½ bricks wide respectively.

Wall thickness at base to height of 9 ft., 8 bricks; next 6 ft., 2½ bricks; remaining 5 ft. to underneath coping, 2 bricks.

Coping stones, 1 ft. thick, dressed to the proper radius, and laid in cement.

Piers, 8, brought up from foundation, bound in with tank wall, each capped with a stone 8 ft. square, 12 in. thick, with 4 bolt-holes.

Rest stones, 16, 2 ft. 6 in. long, 12 in. wide, 10 in. thick.

Mound or cone left in bottom of tank, 11 ft. less in diameter than the latter, covered with concrete 6 in. thick.

Puddled with clay; 18 in. thick at bottom; the sides, 2 ft. at base to 1 ft. 6 in. at top.

Bricks, best hard-burnt seconds.

Mortar, 1 Portland cement to 2 of sharp sand.

Diameter, 88 ft. 6 in. Depth, 20 ft.

Footings, 4 courses; first course, double, 5 bricks in width; others single; 4½, 4, and 8½ bricks wide respectively.

Wall, from base to height of 7 ft., 8 bricks; next 7 ft., 2½ bricks; and remaining 6 ft., 2 bricks thick.

Coping, bricks set on edge, and laid in cement.

Piers, 9, brought up from foundation, each capped with a stone 4 ft. square, 10 in. thick, with 4 holes for holding-down bolts of columns.

Rest stones, 18, 24 in. square, 10 in. thick, laid on footings, and let 8 in. into sides of tank.

Puddled with clay, 2 ft. thick at bottom; the sides, 2 ft. at base, tapering to 1 ft. 6 in. at top.

Centre pillar, to support crown of gasholder when down, 8 ft. 6 in. diam., built of brick, coated with cement.

Bottom, flagged with Yorkshire flags, 4 in. thick.

Bricks, best hard-burnt stocks.

Mortar, lias lime, mixed with two-thirds sharp river sand.

Diameter, 102 ft. Depth, 24 ft.

Footings, 6 bricks wide at base, diminishing by offsets to the bottom of wall.

Wall, thickness at base to 7 ft. in height, 4 bricks; next 7 ft., 8½ bricks; next 5 ft., 8 bricks; and remaining 4 ft. to coping, 2½ bricks thick.

Coping of stone, 1 ft. thick.

Piers, 12, carried up and built in with wall from foundation. Each capped with a stone 4 ft. square, 15 in. thick, with 4 bolt-holes.

Rest stones, 24, 2 ft. 6 in. square, 12 in. thick, let 4 in. into bottom of wall, and resting on footings.

Stones, 72 in number, 18 in. long, 12 in. by 12 in., built into tank wall, against which the channel guides are fastened.

Puddled with clay, 2 ft. thick at bottom; the sides, 2 ft. 6 in. at base, tapering to 1 ft. 6 in. at top.

Bottom, concreted over the puddle to the depth of 10 in.

Centre pillar, 4 ft. square.

Bricks, best hard-burnt stocks.

Mortar, lias lime, mixed with two-thirds sharp river sand.

Diameter, 102 ft. 6 in. Depth, 80 ft.

Footings, 1 double and 4 single courses, respectively 6,  $5\frac{1}{2}$ , 5,  $4\frac{1}{2}$ , and 4 bricks wide.

Wall, 8 bricks wide for 10 ft. high; next 10 ft., 2½ bricks; and remaining 9 ft. to coping, 2 bricks.

Coping of stone, 12 in. thick, not less than 4 ft. long each stone, Strengthening rings, of brickwork, laid in cement, 5—

1st ring, 2 ft. 6 in. from bottom, 7 bricks deep.

2nd do. 8, 6, , , 6 do. 8rd do. 14, 0, , , 6 do. 4th do. 19, 6, , , 5 do. 5th do. 24, 0, , 4 do.

Piers, 12, brought up from foundation along with and bound into the wall, each capped with a stone 4 ft. 6 in. square, 15 in. thick, with 4 bolt-holes.

Rest stones, 24, 27 in. square, 12 in. thick, on footings, and let 4 in. into tank wall.

Puddled with clay 2 ft. thick throughout.

Centre pillar, of brick, 4 ft. square, cemented over.

Bottom concreted to the depth of 12 in. over the puddle.

Bricks, best hard-burnt stocks.

Mortar, lias lime, mixed with two-thirds sharp river sand.

Diameter, 122 ft. Depth, 24 ft.

Concrete under footings of wall and rest stones, 12 in. thick and 10 ft. wide.

Footings, 8 bricks wide at base, diminishing by 8 offsets to the bottom of the wall.

Wall, thickness at base to 8 ft. 9 in. in height, 4 bricks; next 7 ft., 8½ bricks; next 4 ft. 6 in., 8 bricks; and remaining 8 ft. to coping, 2½ bricks thick. Batter of wall 1 in 100.

Coping of stone, 9 in. thick, by 24 in. wide, and not less than 8 ft. 4 in. long.

Piers, 14, each 7 bricks square carried up and built in with walf from foundation, and capped with a stone 5 ft. 4 in. square, 18 in. thick, and with 4 holding-down bolts to each.

Rest stones, 28, 8 ft. 6 in. by 2 ft. by 12 in. thick, let into wall 41 in., and resting on footings.

Guide rail stones, 56 in number, built into tank wall, 28 of which are 2 ft. by 1 ft. 6 in. by 1 ft. 6 in., the remaining 28 being 2 ft. 6 in. by 1 ft. 6 in. by 1 ft.

Brick ring or apron extending 6 ft. from inside of tank wall at the bottom to form a floor, 8 courses of bricks thick laid flat.

Centre pillar of brickwork, 4 ft. diam., cemented over.

Mortar, Portland cement, 1 part; sand, 8 parts.

Bricks, picked common.

Puddle behind wall of tank 24 in. thick at bottom, tapering to 18 in. at top. On cone in tank bottom 18 in. thick.

Concrete over surface of puddled cone, 6 in. thick.

Diameter, 145 ft. Depth, 55 ft.

Top of tank, 4 ft. above ground level.

Footings, 4 double courses, respectively 5 ft., 4 ft. 8 in., 4 ft. 4½ in., and 4 ft. wide.

Wall, to height of 10 ft. above footings, 8 ft. 7 in., or 4½ bricks thick; next 10 ft., 4 bricks; next 10 ft. 8½ bricks; next 15 ft., 8 bricks; next 5 ft., 2½ bricks; remaining 4 ft., exclusive of coping, 2 bricks thick.

Strengthening rings, or courses, 6 courses in every 5 ft. of height; also the 8 finishing courses, and the corresponding courses in piers, set in cement. The brickwork at no part carried higher than 5 courses of bricks, until the circle up to that level is completed, puddled, and backed up.

Coping of stone, 12 in. thick, bedded in cement.

Piers, 16, 4 ft. 8 in. wide, each capped with a stone 5 ft. square, 18 in. thick, for supporting columns; 4 holes in each for holding down bolts; the said holding down bolts, with castiron plate, built into each pier, 10 ft. below level of coping.

Rest stones, 82, let 4½ in. into face of wall, and resting on piers of brickwork forming part of the general footings.

Blocks of stone, 18 in. by 12 in. by 12 in., inserted in wall opposite each pier, for securing guides.

Cone in centre of tank, 6 ft. less in diameter at the base than the interior of tank; lower part, to height of 20 ft., paved with 4 courses of brickwork; upper part, of clay only.

Puddle, not less than 18 in. in thickness, and kept constantly well moistened; the earth being firmly pounded in behind.

Bricks, best hard-burnt stocks.

Mortar, composed of 1 part fresh burnt lias lime, to 8 parts of clean, sharp river sand; not more than sufficient for one day's work made at one time.

Cement, fresh burnt, with equal proportions of sand, mixed as it is being used.

Dry, or stand pipe well, 15 ft. diameter, 68 ft. deep, paved with 8 courses of brickwork on edge, set in cement.

Diameter, 154 ft. Depth, 40 ft. 6 in.

Foundation of concrete, 12 in. thick, 18 ft. wide under piers, and 11 ft. wide under walling.

Wall, starts from concrete foundation without footings, 5 bricks thick for a height of 16 ft. 10 in.; next 4½ bricks for 6 ft. 5 in. deep; next 4 bricks for 6 ft. 5 in.; next 8½ bricks for 6 ft. 5 in., and 8 bricks the remaining height.

Coping of stone, 12 in. by 2 ft. 3 in., in lengths not less than 4 ft. 6 in.

Piers, 16 in number, 6 ft. square from bottom to top, capped with hard Yorkshire stones, 6 ft. square and 2 ft. thick, with 4 bolt-holes in each.

Rest stones, 82, 4 ft. 10 in. by 2 ft., by 1 ft., built 4½ in. in tank wall.

Guide rail stones, 144 in number, 112 of which are 2 ft. by 1 ft. 9 in. by 1 ft., and the remaining 82 being 2 ft. by 1 ft. 9 in. by 1 ft. 6 in.

Puddled with clay 24 in. thick over surface of mound in bottom, and behind tank wall.

Brick apron, 2 ft. thick and 6 ft. wide, round bottom of tank wall inside, upon which the rest stones are set.

Centre pillar of brick, 6 ft. square at bottom and 6 ft. 8 in. square at top, capped by a stone 12 in. thick.

Mortar, Portland cement, 1 part; sand, 8 parts.

Bond, English; alternate courses of headers and stretchers throughout.

Dry well, 10 ft. in diameter, 48 ft. 6 in. deep.

Diameter, 182 ft. Depth, 40 ft.

Footings, 8 ft. deep below tank bottom, in 8 equal set-offs; placed on elm sleepers, 9 in. by 4 in.

Wall, thickness at base to 15 ft. in height, 4½ bricks; next 15 ft., 4 bricks; next 5 ft., 8 bricks, and remaining 4 ft., 2½ bricks thick.

Coping, Bramley Fall stone, 12 in. thick, and 24 in. wide.

Piers, 28, 6 ft. thick from inside tank to outside pier, and 8 ft. 9 in. wide side to side, capped with granite blocks, 5 ft. 8 in. square and 2 ft. thick, with 4 bolt-holes in each.

Rest stones, 28, built in wall 12 in., are each 4 ft. by 2 ft. 6 in. by 12 in thick.

Guide rail stones, 112 in number, 18 in. by 12 in. by 12 in.

Puddled with clay on cone in bottom of tank, under footings, and behind tank wall a uniform thickness of 24 in.

Cone at bottom covered over the clay with 9 in. of concrete, and paved with a layer of bricks on edge, set in cement.

Centre pillar of brickwork, 7 ft. 6 in. square, capped with granite block, 2 ft. thick, the whole on a foundation of concrete.

Bricks, best hard-burnt stocks.

Mortar, blue lias lime and sharp sand.

Brick ring or apron, 8 ft. thick, extending 6 ft. 6 in. from inside of tank wall at the bottom, to form a floor.

Diameter, 200 ft. Depth, 86 ft.

Footings, laid on elm boards 1½ in. thick, placed on the puddle, are 9 bricks wide at base, diminishing by 2½ in. offsets to bottom of wall.

Wall, thickness at base to 12 ft. in height, 5 bricks; next 6 ft., 4½ bricks; next 5 ft., 4 bricks; next 5 ft., 8½ bricks; next 5 ft.,

8 bricks, and the remaining portion, 2½ bricks; being finished at top, to form a coping, with Staffordshire blue bricks set on edge in cement.

Piers, 22 in number, 5 ft. 6 in. from inside tank to outside the pier, and 7 ft. wide from side to side, surmounted by Bramley Fall column stones, 6 ft. by 5 ft. 6 in. by 1 ft. 4 in. thick, with 4 holes in each.

Piers, intermediate, 22 in number, 5 brick lengths square, brought up from bottom, and capped with stones, 2 ft. square, and 1 ft. 6 in. thick.

Rest stones, 44, 4 ft. 6 in. by 8 ft. by 1 ft. 8 in. thick, set into wall 41 in. and bedded on concrete.

Guide rail stones, 44, 2 ft. square by 1 ft. 6 in.

Puddled with clay, over cone in centre, and under footings 2ft. 6 in. thick, behind tank wall 2 ft. thick at bottom, tapering to 1 ft. 6 in. at top.

Concrete apron, 2 ft. thick, extending 9 ft. from tank wall all round.

Cone, covered with 6 in. of concrete over the clay puddle.

Bricks, well burnt Oldbury brown bricks.

Mortar, blue lias lime, 1 part; sand, 21 parts.

Bond, English, alternate courses of headers and stretchers throughout.

Hoop-iron bond, every sixth course in height, 1½ in. by 1-16th in. is inserted as follows:—In the five bricks thick part, 5 rows are laid in the thickness of the wall at equal distances apart; in the 4½ and 4 bricks thick part, 4 rows; 8½ and 8 bricks part, 8 rows; and 2 rows for the remaining height.

Shallow dry well, 12 ft. diameter, 20 ft. deep.

Diameter, 208 ft. 6 in. Depth, 38 ft.

Footings, bottom course, 7 bricks wide, 4 bricks deep, and 4 single courses, respectively 6, 5\frac{1}{2}, 5, and 4\frac{1}{2} bricks wide.

Wall, thickness for a height of 20 ft., 4 bricks; next 9 ft., 8½ bricks; next 8 ft., 8 bricks.

Coping stone, 24 in. wide, 12 in. thick.

Strengthening rings of brickwork laid in cement, 5, divided equally throughout the depth of tank wall, 10 bricks each in depth.

Piers, 18, on foundations brought up from bottom of tank footings and bound in with wall, each capped with a stone 6 ft. square, 18 in. thick, 4 holes for bolts, the latter with plate built into pier, 10 ft. below the top of coping.

Rest stones, 86, 4 ft. square, 12 in. thick, on footings brought up from bottom of wall footings.

Puddled with clay, mixed with one-third sharp sand, and not less than 2 ft. thick in any part.

Bottom concreted over the puddle to the depth of 12 in.

Bricks, best hard-burnt stocks.

Mortar, 1 part lias lime to 2 parts sharp river sand.

Diameter, 218 ft. Depth, 44 ft. 6 in.

Foundation of concrete 2 ft. thick, 9 ft. 5 in. wide, including apron.

Wall, thickness at base to 20 ft. in height, 5 bricks; next 5 ft., 4½ bricks; next 5 ft., 4 bricks; next 5 ft., 8½ bricks; next 5 ft., 8 bricks, and the remaining portion 2½ bricks; 7 circular bands of brickwork, 6 courses deep each, and extending through the full thickness of the wall, are built in equidistantly in the height of the wall set in Portland cement mortar, the intervening portions of the wall being set in hydraulic lime mortar all in English bond.

Coping of Yorkshire stone, 2 ft. 5 in. by 6 in., in 5 ft. lengths, projecting 1 inch over wall.

Piers, 24, each 7 ft. from inside tank wall to outside of pier, and 5 ft. 6 in. wide, side to side, capped with Bramley Fall stones, 7 ft. by 5 ft. 6 in. by 2 ft., having 7 bolt-holes in each.

Piers, intermediate, 24, each 3 ft. 10 in. square, capped with stones 4 ft. by 4ft. by 6 in.

Rest blocks of concrete, 48, each 4 ft. 6 in. long by 2ft. wide, and standing 6 in. above the concrete apron.

-Guide rail stones, 288, each 18 in. by 12 in. by 12 in., projecting 1 in. from face of tank wall.

Puddled with clay, not less than 18 in. at any part.

Truncated surface of cone paved with stones.

Mortar, blue lias hydraulic lime, 1 part; sand, 8 parts.

·Cement mortar, Portland cement, 1 part; sand, 8 parts.

-Concrete, Portland cement, 1 part; river ballast, 7 parts.

Shallow dry well, 12 ft. diameter, 26 feet deep. .

#### COMPOSITE TANK.

Diameter, 152 ft. Depth, 81 ft.

Footings, 8 ft. 6½ in. wide at bottom, including apron, 2 ft. 6 in. thick.

Wall, brick faced, 9 in. thick, in English bond; backing of concrete; thickness at base, including the backing, to 18 ft. 9 in. high, 3 ft. 4½ in.; next 8 ft. 6 in., 3 feet thick; and the next 8 ft. 6 in., 2 ft. 8 in., to the underside of coping.

Coping of stone, 1 ft. 10 in. by 12 in., in 8 ft. lengths.

Piers, 16, are 8 ft. from inside tank wall to outside pier, and 4 ft. 6 in. wide, from side to side, formed of 9 in. brickwork on three sides, and filled in with concrete, the whole being capped with a stone 8 ft. by 4 ft. by 1 ft.

Rest stones, 2 to each pier, or a total of 32, each 4 ft. by 1 ft. 6 in. by 9 in.

Guide rail stones, 48, each 2 ft. by 1 ft. by 9 in.

Puddled with clay, 2 ft. thick throughout.

Cone, concreted over the clay puddle to a depth of 12 in. and rendered.

Centre pillar, solid brickwork, 6 ft. 6 in. in diameter at top, the sides having a batter of 1 in 40; built on a foundation of concrete 10 ft. square and 8 ft. deep. Stone cap, 6 ft. diameter by 1 ft. thick, on which is placed a double layer of 4 in. oak planking.

Hoop-iron bond, tarred and sanded,  $1\frac{1}{2}$  in. wide, 1-12th in. thick, is placed every  $4\frac{1}{2}$  ft. in height, in the proportion of 1 strip to every  $4\frac{1}{2}$  in. in thickness of the wall.

Mortar, Portland cement, 1 part; sand, 8 parts.

Concrete, Portland cement, 1 part; sand, 8 parts; coarse screened stones, 11 in. diameter, 4 parts.

Dry well, 11 ft. diameter, 40 feet deep to floor.

#### CONCRETE TANK.

Diameter, 82 ft. Depth, 28 ft.

Wall, 8 ft. 8 in. thick at bottom, tapering on the outside to 2 ft. 4 in. at the top, built entirely of concrete, and rendered on inside with neat Portland cement \( \frac{3}{4} \) in. thick.

Piers, 10, each 4 ft. by 8 ft. 8 in. of concrete.

Rest blocks of concrete 2½ ft. long, 18 in. wide, 6 in. thick.

Backing composed of sand.

Cone, concreted over surface, 18 in. thick, and rendered with neat cement 2 in. thick.

Centre pillar, 4 ft. square, 8 ft. high.

Concrete, Portland cement, 1 part; sand, gravel, old retorts, and clinkers, 5 parts.

Diameter, 184 ft. Depth, 47 ft.

Wall, 5 ft. thick at bottom, tapering on the outside to 2 ft. 8 in. at the top, built entirely of concrete, and rendered on inside with neat Portland cement \( \frac{3}{4} \) in. thick.

Piers, 20, each 8 feet thick, of concrete entirely.

Rest blocks of concrete, 6 ft. long.

Puddle, none.

Cone, concreted over surface, 12 in. thick, and rendered with nest cement \( \frac{3}{4} \) in. thick.

Centre pillar, hollow, external diameter 14 ft., internal ditto, 10 ft.

Concrete, Portland cement, 1 part; gravel, sand, ballast, burnt clay, old retorts, and clinkers, 7 parts.

Dry well, 10 ft. diameter, 58 ft. deep, built of concrete 2 ft. thick, and rendered outside with neat cement.

#### STONE TANK.

Diameter, 89 ft. Depth, 20 ft.

Footings, 2 courses. First course composed of stones at least 8 ft. 6 in. square and 9 in. thick; second course, 8 ft. square, 9 in. thick, breaking joint at least 1 ft. on the vertical joint.

Wall, to underneath coping, built of stones not less than 16 in. on the inner face, dressed to the proper radius; no stone having less than 10 in. of a square joint, nor less than 18 in. on the bed, and 5 in. thick. Walling carried out in horizontal courses throughout the circumference of the tank, and backed up with good strong random. Two throughs to every superficial yard. Thickness of wall at base, random included, 2 ft. 8 in., gradually diminishing to 1 ft. 8 in. at top.

Coping of stones, 1 ft. 11 in. broad, 8 in. thick, and not less than 8 ft. 6 in. long, dressed to the proper radius, and laid in cement.

Piers, 9, bound in and built up along with the tank wall; a through of entire size every vertical yard, and capped with a solid cover 3 ft. 6 in. square, 15 in. thick, having 4 holes for foundation bolts of columns.

Rest or bearing stones, 18, throughs 2 ft. wide and 1 ft. thick built in along with wall footings, and projecting 1 ft. 9 in. into the tank.

Mound or Cone in bottom of tank, covered with puddle to the depth of 24 in., its base flagged with a course of yard flags 4 in. thick, the remainder pitched with dry rubble.

Pillar in centre of tank, capped with a solid stone 4 ft. square, 15 in. thick.

Mortar, lias lime, one-third; sharp clean sand, two-thirds.

### CAST-IRON TANKS.

Diameter, 88 ft. Depth, 15 ft.

Plates, not more than 4 ft. in length or width. All, except top course or tier, strengthened with diagonal ribs. Lowest tier, \(\frac{1}{4}\) in. thick; top tier, \(\frac{1}{4}\) in. thick; intermediate and bottom plates, \(\frac{1}{4}\) in. thick. Small brackets or snugs, projecting 4 in., cast 1\(\frac{1}{4}\) in. below centre of side plates, to support the strengthening hoops.

Flanges, 8 in. wide, with brackets between the bolt-holes.

Bolt-holes, square, § in. and ½ in., and 6 in. apart, centres.

Bolts of bottom plates and two lower tiers of sides, § in.; all the others, § in. square under head.

Hoops of flat wrought-iron, 8 in. by § in., bound round each tier of side plates with jaws and screws.

Joints planed.

Diameter, 61 ft. Depth, 17 ft.

Plates, bottom, 1 in. thick, except outside row, 1½ in. thick. Sides, first tier, 1½ in.; second, 1 in.; third, ½ in.; and fourth, ½ in. thick. Depth, 4 ft. 3 in.; width, 4 ft. 9 in. Say, 40 plates in each tier. Snugs, projecting 4 in., cast on each plate, 2 in. below centre, to support the binding hoops.

Flanges, 3 in. wide, not less than 3 in. thick; brackets 1 in. thick between the bolt-holes.

Bolt-holes, square, 3 in.; 7 in. apart, centre to centre.

Bolts, 3 in., square under head.

Hoops of flat-iron, 8½ in. by ½ in., with suitable jaws and tightening screws bound round each tier of side plates.

Joints, planed.

Diameter, 82 ft. Depth, 20 ft.

Plates, bottom 1½ in., except centre plate, 1½ in. Sides, first tier, 1½ in.; second tier, 1½ in.; third tier, 1 in.; fourth tier, ¼ in. 60 plates to each tier. Bearing brackets cast on each plate to support strengthening hoops.

Flanges, 4½ in. wide, 1½ in. thick; brackets ½ in. between boltholes.

Bolt-holes, square, 11 in., 57 in., centre to centre.

Bolts, 1 in., square under head.

Hoops, wrought-iron, 5 in. by \( \frac{2}{4} \) in., \( \frac{4}{5} \) in., and \( \frac{1}{4} \) in.

Joints, planed and caulked with iron cement.

Diameter, 101 ft. Depth, 22 ft. 8 in.

Plates, bottom, outside row, 1½ in., and remainder 1 in., except centre plate, 1½ in. Sides, first and second tiers, 1½ in.; third tier, 1½ in.; fourth and fifth tiers, 1 in. thick. Width, 4 ft. 2½ in. (say 75 plates in each tier); depth, 4 ft. 6½ in. Bearing bracket, projecting 5 in., cast on each plate, 2½ in. below centre, to support the strengthening hoops.

Flanges, 3½ in. wide, equal to plates in strength; brackets, ½ in. between the bolt-holes.

Bolt-holes, square, 1 in.; 7 in., centre to centre.

Bolts, 1 in., square under head.

Hoops, flat-iron, 5 in. by 1½ in., with jaws and screws, bound round each tier of side plates.

Joints, planed.

### · WROUGHT-IRON TANK.

Diameter, 51 ft. 4 in. Depth, 14 ft.

Plates, \( \frac{3}{3} \) in. thick, both sides and bottom, with the exception of the outer row in the latter, and those to which the guide rails are fixed up the sides, which are \( \frac{1}{3} \) in. thick.

Curbs, of angle-iron, extending round the entire circumference of the tank outside; top curb, 4 in. by 4 in. by  $\frac{1}{3}$  in.; two intermediate curbs or rings the same size, and bottom curb  $4\frac{1}{3}$  in. by  $4\frac{1}{3}$  in. by  $\frac{1}{3}$  in., all butt-jointed, and with lapping pieces not less than 18 in. long, riveted to the side plates of the tank with  $\frac{1}{3}$  in. rivets 6 in. apart.

Vertical stays, 12 in number, serving as guides for the holder, 14 ft. long, formed of two 8 in. by  $2\frac{1}{2}$  in. by  $\frac{3}{2}$  in. angle-irons placed thus: JL and riveted to the  $\frac{1}{2}$  in. plates up the sides before mentioned with rivets 6 in. apart.

Lap of plates, not less than 1½ in., riveted hot with § in. rivets, 1¼ in. centres.

Masonry standards or iron brackets to support columns.

#### STEEL TANKS.

Diameter, 62 ft. Depth, 18ft. 3 in.

Plates, mild steel, bottom or floor plates,  $\frac{7}{18}$  in. thick. Sides, four rings, bottom ring,  $\frac{7}{16}$  in., second ring,  $\frac{8}{8}$  in., and two top rows,  $\frac{5}{16}$  in. except standard plates, which are  $\frac{8}{8}$  in.

Curbs, bottom curb securing sides and bottom, of angle-steel 4 in.  $\times$  4 in.  $\times$   $\frac{1}{2}$  in. Top curb,  $8\frac{1}{2}$  in.  $\times$   $8\frac{1}{2}$  in.  $\times$   $\frac{7}{15}$  in. angle-steel.

Guides, 16 in number, 6 in.  $\times$  8 in.  $\times$  8 in.  $\times$  8 in.  $\times$  8 in. channel-steel. Brackets of flat and angle-steel to support standards.

Lap of plates, 21 in., 5 in. rivets, 2 in. centres.

Diameter, 102 ft. Depth, 20 ft. 8 in.

Plates, mild steel, bottom or floor plates, outer row,  $\frac{7}{18}$  in. thick. Inner rows,  $\frac{3}{8}$  in. thick. Sides, five rings, bottom ring,  $\frac{1}{8}$  in. thick; next two rings,  $\frac{1}{8}$  in.; top rings,  $\frac{3}{8}$  in. thick.

Curbs, bottom curb securing sides and bottom, of angle-steel, 4 in. × 4 in. ×  $\frac{5}{8}$  in. Top curb  $8\frac{1}{2}$  in. ×  $8\frac{1}{2}$  in. ×  $\frac{5}{8}$  in. angle-steel. Top of tank finished with a  $\frac{1}{2}$  in. steel plate riveted to standards and top curb, and curved to radius of tank.

Guide bars, 24 in number, 6 in.  $\times$  8 in.  $\times$  3 in.  $\times$   $\frac{3}{5}$  in. channel-steel.

Brackets of flat and angle-steel to support standards.

Lap of plates, 2½ in., ½ in. rivets, 2 in. pitch. Vertical joints to overlap 4½ inches, and to be double riveted.

### ANNULAR OR RING TANKS.

Cast-Iron.

Diameter, 75 ft. Depth, 19 ft.

Plates, bottom or ring plates, 8 ft. 6 in. wide, 1 in. thick. Inner circles, 1 tier of plates only, 4 ft. deep, 1 in. thick; strengthened with 2 horizontal ribs 2 in. deep by \(\frac{3}{4}\) in. thick on side next centre of tank, and on other side with 2 vertical brackets, 9 in. at bottom, diminishing to nothing at top, \(\frac{3}{4}\) in. thick, with foot, 9 in. by 6 in. by \(\frac{3}{4}\) in., on bottom of each bracket, Outer circle, 4 tiers, 4 ft. 9 in. deep, and 1 in., \(\frac{7}{4}\) in., \(\frac{3}{4}\) in., and \(\frac{4}{5}\) in. thick respectively. 55 plates in the circumference. Snug, projecting \(4\frac{3}{4}\) in., 2 in. below centre, to support binding hoops. Flanges, \(8\frac{3}{4}\) in. wide, equal to plates in strength, with brackets between the bolt-holes.

Bolt-holes square, 7 in., 6 in. centre to centre.

Bolts, 7 in. square under head.

Hoops, flat-iron, 4 in. by 1 in., with suitable jaws and screws, bound round each tier of outside plates.

Joints, 1 in. thick, caulked with iron cement.

Diameter, 108 ft. Depth, 22 ft.

Plates, bottom or ring, 5 ft. wide, 1 in. thick. Inner circle, 1 tier of plates only 4 ft. deep, 1 in. thick; strengthened with 2 horizontal ribs, 2 in. deep by \( \frac{3}{4} \) in. thick on side next centre of tank, and on other side with 2 vertical brackets, 9 in. at bottom, diminishing to nothing at top, \( \frac{3}{4} \) in. thick, with foot on bottom of each, 9 in. by 6 in. by \( \frac{3}{4} \) in. Outer circle, 5 tiers, 4 ft. 5 in. deep, and 1\( \frac{1}{4} \) in., 1 in., \( \frac{3}{6} \) in., \( \frac{3}{4} \) in., and \( \frac{3}{4} \) in. thick respectively. 66 plates in the circumference. A snug or bearing bracket cast on each of the outside plates, 2\( \frac{1}{3} \) in. below centre, and projecting 4 in. for supporting the binding hoops.

Flanges, 3 in. wide, 1 in. thick, with brackets between the bolt-holes.

Bolt-holes, 3 in. square, 6 in. apart, centre to centre.

Bolts, 4 in., square under head.

Hoops, flat-iron,  $4\frac{1}{2}$  in. by  $\frac{3}{4}$  in. for bottom tier,  $4\frac{1}{2}$  in. by  $\frac{5}{8}$  in. for the others, with jaws and tightening screws.

Joints, ½ in. thick, caulked with iron cement.

Diameter, 110 ft. Depth, 24 ft. 2 in.

Plates, bottom or ring, 3 ft. 10 in. wide,  $\frac{3}{4}$  in. thick. Inner circle 1 tier of plates only, 4 ft. deep,  $\frac{3}{4}$  in. thick; strengthened with 2 horizontal ribs,  $2\frac{1}{4}$  in. broad by  $\frac{3}{4}$  in. thick on side next centre of tank, and on the other side with 2 vertical brackets, 9 in. at bottom, diminishing to nothing at top,  $\frac{3}{4}$  in. thick, with foot on bottom of each, 9 in. by 6 in. by  $\frac{3}{4}$  in. Outer circle, 5 tiers, 4 ft. 10 in. deep, and  $1\frac{1}{4}$  in., 1 in.,  $\frac{7}{8}$  in.,  $\frac{3}{4}$  in., and  $\frac{3}{4}$  in. thick respectively, 66 plates in the circumference. A bearing bracket cast on each of the outside plates,  $2\frac{1}{4}$  in. below centre, and projecting 4 in., for supporting the binding hoops.

Flanges, 3 in. wide, and same strength as the respective plates; brackets between the bolt-holes.

Bolt-holes, 7 in. square, 6 in. apart, centres.

Bolts, 7 in., square under head.

Hoops, flat-iron, 5 in. by \( \frac{1}{4} \) in. for the bottom tier, and  $4\frac{1}{4}$  in. by \( \frac{1}{6} \) in. for the others, with suitable jaws and tightening screws. Joints, \( \frac{1}{4} \) in. thick, caulked with iron cement.

# Wrought-Iron.

Diameter, 127 ft. Depth, 20 ft. 8 in.

Annular space, 8 ft. 9 in. wide.

Plates, bottom or ring plates \( \frac{1}{2} \) inch thick; sides five rows deep; first and second row of plates from bottom \( \frac{1}{2} \) in. thick; third and fourth rows, 7-16ths in. thick, and the fifth or top row \( \frac{3}{2} \) in. thick; lap of plates, 3 in.; the top of the inner row of plates being 8 in. lower than the outer row; angle-iron curbs in bottom, 4 in. by 4 in., by \( \frac{5}{2} \) in. thick; the \( \frac{1}{2} \) in. and 7-16ths in. plates riveted with \( \frac{7}{6} \) in. rivets, \( 2\frac{1}{2} \) inches apart, and the \( \frac{3}{6} \) in. plates by \( \frac{3}{2} \) in. rivets, \( 2\frac{1}{2} \) in. apart.

Curbs, top outer curb of angle-iron 5 in. by 5 in. by  $\frac{1}{2}$  in.; top inner curb of angle-iron 8 in. by 8 in. by  $\frac{1}{2}$  in.; both riveted with  $\frac{3}{2}$  in. rivets, 6 in. apart.


Standards, 18, box form, 15 in. by 9 in.. of  $\frac{3}{8}$  in. plates on three sides, 8 in. by 8 in. by  $\frac{1}{2}$  in. angle-iron to secure the same to side sheets, and extending round the bottom of the standard at its lower end, and 5 in. by 5 in. by  $\frac{1}{8}$  in. angle-iron round the top to form a base for the columns, all riveted at 6 in. apart with  $\frac{3}{2}$  in. rivets. Two of these standards form the inlet and outlet

pipes, for which purpose they are continued under the annular space and up the inside of the inner ring of side sheets, and riveted with  $\frac{3}{4}$  in. rivets as before, but only 2 in. apart.

### THE GASHOLDER.

THE HOLDER or floating vessel (Fig. 95) is the storage reservoir for the gas, and it serves the all-important purpose of equalizing the distribution of the gas under pressure, and ensures an unbroken continuity of supply so long as any gas remains in it. In form it is invariably cylindrical like a beaker, inverted, and works freely up and down in the tank. To keep it in the true vertical position carriages are fixed on the top and bottom of the vessel, and these carry rollers which work in or against guide-rails attached to the tank sides and to the columns or standards.

The holder may be either single (Fig. 95) or telescopic (Fig. 96) in



two or more lifts. When it is made in the telescopic form, its capacity is nearly double or treble or quadruple (as the case may be) the capacity of the single-lift holder for equal dimensions of tank. Ground space and capital are thus economized by its adoption.

Telescopic holders require great care in construction and working—first, to ensure accuracy in the "cupping" of the water-lute or seal (composed of cup and grip), and, second, to prevent the water in the lute from freezing, which endangers the action of the vessel, or causes distortion, and imperils the lighting of the district.

Holders, whether single or telescopic, are counterbalanced or not, as is found desirable or necessary. Counterbalance weights are not

required where an exhauster on the one hand, and a governor on the other, are employed, as is the case in all but the very smallest works. In the latter, when the diameter and depth of the holder nearly approximate, it will generally be found of advantage to reduce the pressure by counterbalancing.

The crown or roof of a holder may be either trussed (Fig. 95), or untrussed (Fig. 96). In the latter case the top curb, being without radiating struts, requires to be made sufficiently strong to resist the pressure of the gas exerted on the underside of the roof which tends to distort the curb. A framework of wood or iron is required to be erected within the tank to support the untrussed roof when the holder is empty of gas, and resting on the landing stones.

The usual rise given to the roof or crown of a holder is 5 per cent. or one-twentieth of the diameter.

The trussing of a holder is in principle precisely similar to that of the roof of a building. It consists of a crown Plate with king post or centre pillar, having the main T rafters radiating therefrom to the top curb, usually angle-steel of strong section, these being braced with main and secondary tie rods and struts; secondary rafters extending from the curb to about two-thirds of the radius, and all braced together with angle or flat-steel purlins; the whole when complete somewhat resembling a spider's web. Opposite each column and intermediately, are vertical stays reaching from the top to the bottom curb and secured thereto.


The top and bottom curbs of a holder are its most important members, and should be carefully designed, both as regards th strength and form, to resist the strains to which they are subjected.

The lower guide framing of a holder consists of a series of channelirons secured by Lewis bolts to the sides of the tank, one in a vertical line with each column or standard, and one intermediately, in which the rollers, held by carriages attached to the bottom curb, revolve. In the case of telescope holders, each outer lift also carries channel guides attached to the curbs, top and bottom, to receive the rollers of the corresponding inner lifts.

The upper guide framing may either be composed of cast-iron columns, or wrought-iron or steel standards, with back and front members braced together by lattice bars, and having a channel or teeiron guide in front, within or upon which the guide rollers revolve. Tangential rollers are also sometimes applied to vessels of large size.

The roller carriages are attached to the top curb and roof plates (which are made thicker at these points), and, in the case of telescopic holders, to the top of the grip.

The cast-iron columns or wrought-iron or steel standards, are braced together by a series of wrought-iron or steel girders at the upper end (Fig. 95), and also intermediately in the case of telescopic holders





(Fig. 96). Diagonal wind ties of round wrought-iron are also employed to give rigidity to the framing when the columns or standards are of considerable height. (Fig. 96.)

Gasholders with the upper Guide-Framing either partially or wholly dispensed with.—Mr. G. Livesey first introduced at Botherhithe the method of carrying the upper lift of a three-lift holder beyond the guide framing, the only additions made in this case being the replacing of the channel guides with H-iron to furnish paths for the

combined radial and tangential rollers on the grips of the middle and outer lifts. He has further extended this principle at East Greenwich, where the two upper lifts of the large holders rise above the guideframing.

The invention of Mr. W. Gadd introduces a new principle of guiding; the elevated framing being entirely dispensed with, and the vessel guided from the bottom curb. The channel or rail guides, which may either be attached to the tank sides (Fig. 97), or to the outside of the holder (Fig. 98), are placed at an angle like the thread of a screw, instead of in the vertical plane. The rollers upon the bottom curb, or upon the tank coping as the case may be, are ranged either radially or tangentially with the sides of the vessel; and as they work in the channels or rails provided for them, the floating vessel rises and descends in the tank with a helical or screw-like motion.






Mr. E. Lloyd Pease in his ingenious arrangement of wire ropes and pulleys also dispenses with the upper guide framing. The following diagrams (Figs. 99 and 100) shew the principle of the arrangement when adapted to a single lift holder.

As will be seen, three ropes at least are required. These are made of galvanized steelwire, varying in size from half an inch upwards, according to the size of holder. Each rope is fastened, as shewn, to brackets A and E on the tank and passes over the pulleys B C D carried on the holder. The pulleys are grooved so that the rope cannot slip out of

place, and small springs are used to keep the ropes at an even tension. The ropes act independently of each other, so that in case of a failure only one rope is affected.

Mr. G. Livesey's Hydraulic Seal (Fig. 101), for attaching to the underside of the roof of a gasholder over the inlet and outlet pipes,



is an ingenious device for allowing access to the pipes without having to discharge the gas contained in the crown.

Precautions to be observed in the Working of Gasholders.— Telescopic holders are liable in winter to be thrown out of order by the freezing of the water in the cup between the lifts. When the lower lift is down, the upper lift in its progress downward rolls the ice and snow in the lute into lumps, often, if not removed, throwing the vessel out of plumb, and even fracturing the columns. Great care should therefore be taken to keep the water-lute clear; and where steam can be readily applied, it is of the utmost service in accomplishing this object in time of frost. Appliances of various kinds have been devised for preventing the freezing of the water in gasholder tanks and cups, by admitting steam or hot water at intervals round the circumference of the vessel.

Another important precaution is to keep the top or crown of the holder, whether single or telescope, clear of snow, especially when the latter is drifting. Nothing will sooner break down a holder and its guide framing than allowing a mass of snow to collect and lie on one side of the roof.

The oscillation of a telescope holder during strong winds is greater when uncupped than when the lifts are joined. Its liability to damage

from wind is also greater when uncupped, even although less surface is presented to the wind's action.

The sheeting of a holder, being thin and the portion most liable to wear out by oxidation, should be coated outside at least once a year with good oxide of iron or other suitable paint. All rust should be removed before laying on the paint, and for this purpose the sheets should be scrubbed with a brush made of short steel wires. For removing tar a steel scraper may be employed. If coating with tar be preferred to paint, the following recipe will be found useful:

1 gallon of tar.

1 lb. of slaked lime.

1 lb. of pitch.

1 lb. of tallow.

† pint of coal naphtha.

Dissolve the pitch and mix the lime in the tar by heating them in a boiler, being careful not to boil them; ladle out the hot liquid into a bucket, and then add the tallow and the naphtha. Stir the mixture occasionally, and with a brush paint it on the holder before it grows cold.

It happens not unfrequently that the roof of a gasholder becomes pitted with small pin-holes from which there is a considerable and constant escape of gas. This may arise from the inferiority of the iron in the first instance; or from allowing the sheets to become oxidized before fixing; or it may be due to neglect to paint the vessel when in use. In districts where there are numerous chemical works, the impurities in the atmosphere affect the sheets in this manner. The leaks may be stopped by coating the roof with hot tar, and riddling dry sand or cement over it through a sieve, at the same time rubbing the mixture well in with a stiff brush.

# TABLE OF THE WEIGHTS OF GASHOLDERS

In pounds for every One-Tenth of an Inch Maximum Pressure, and from 20 to 200 Feet in Diameter.

Diameter of Gas- holder in Feet.	Weight in lbs. for each One-tenth of an Inch Pressure.	Diameter of Gas- holder in Fest.	Weight in lbs. for each One-tenth of an Inch Pressure.	Diameter of Gas- holder in Feet.	Weight in lbs. for each One-tenth of an Inch Pressure.	Diameter of Gas- holder in Feet.	Weight in lbs. for each One-tenth of an Inch Pressure.
20 21 22 28 24 25 26 27 28 29 90 81 32 88 84 85 86 87 88 49 41 42 43	164 181 198 217 236 256 277 298 821 344 368 893 419 446 473 500 591 622 655 688 722 757 792 828	53 54 55 56 57 58 59 60 61 69 63 64 65 66 67 70 71 72 78 74 75 76	1149 1198 1238 1238 1329 1376 1424 1473 1522 1578 1624 1676 1729 1782 1837 1892 1948 2005 2052 2121 2180 2263 2426 2469	96 87 88 89 90 91 92 98 94 95 96 97 98 99 100 101 102 103 104 105 106 107 108 109 110	3026 3097 8168 8241 8314 8388 8463 8538 8615 8692 8770 8849 8929 4010 4091 4178 4256 4340 4495 4610 4597 4684 4772 4684 4773 4681 2960 5041	119 120 121 122 128 124 125 126 127 128 129 130 181 182 184 185 186 187 188 189 140 141 142 148 144	5798 5891 5990 6089 6189 6290 6392 6495 6598 6708 6908 6914 7021 7128 7287 7346 7456 7567 7678 7791 7904 8018 8138 8249 8366 8488
46 47 48 49 50 51 52	866 904 943 982 1023 1064 1106	79 80 81 82 83 84 85	2558 2618 2684 2751 2818 2887 2956	112 118 114 115 116 117 118	5182 5224 5317 5410 5505 5680 5696	145 146 147 148 149 150 200	8601 8720 8840 8961 9088 9205 16,864

To ascertain the Weight of a Gasholder by the above Table, the Diameter and Maximum Pressure being known.

RULE.—Multiply the number of lbs. standing opposite to the diameter by the pressure in tenths of an inch.

Example.—What is the weight of a gasholder 78 feet in diameter, giving a maximum pressure of 82/10ths?

 $2489 \times 82 = 79,648$  lbs., weight of gasholder.

-

To ascertain, by the preceding Table, the Pressure which a Gasholder will give, the Diameter and Weight being known.

RULE.—Divide the weight in lbs. of the gasholder by the weight given opposite to the diameter.

EXAMPLE.—What pressure will a gasholder give whose weight is 82,075 lbs., and diameter 56 feet?

 $82,075 \div 1288 = 25/10$ ths, maximum pressure of gasholder.

The figures given in the foregoing table are based on the weight of a cubic foot of water—viz., 62.5 lbs.; a column of water 1/10th of an inch high, with an area of 1 square foot, being 52083 lbs., or the 120th part.

Thus, if the area of the holder in feet (obtained by squaring the diameter and multiplying by '7854) be multiplied by 62.5, the weight of a cubic foot of water in lbs., and divided by 120, the number of 10ths of an inch in a foot, the product will be the weight of the holder in lbs. for each 1/10th of an inch maximum pressure.

Or thus: The area of a circle is to the square of its diameter as  $\cdot 7854$  is to 1; hence the weight of a gasholder in lbs., to give 1/10th of an inch pressure, is to the square of its diameter in feet as  $\cdot 52088 \times \cdot 7854$  is to unity; or, which is the same thing, as  $\cdot 4091$  is to unity. So to ascertain the weight of a holder, say, 100 feet diameter, giving a maximum pressure of 85/10ths—

 $100^{\circ} \times 85 \times \cdot 4091 = 148,185$  lbs., weight of gasholder.

TABLE

Giving the CAPACITY OF GASHOLDERS in Cubic Feet for every Foot in Depth, and from 20 to 150 Feet in Diameter, advancing Half a Foot at a Time.

	u I unco.							,	
Dia- meter of Holder in Ft.	Capacity in Cub. Ft. for every Foot in Depth of Holder.	Dia- meter of Holder in Ft.	Capacity in Cubic Ft. for every Foot in Depth of Holder.	Dis- meter of Holder in Ft.	Capacity in Cub. Ft. for every Foot in Depth of Holder.	Dia- meter of Holder in Ft	Capacity in Cub. It. for every Foot in Depth of Holder.	Dia- meter of Holder in Ft.	Capacity in Cub. Ft. for every Foot in. Depth of Holder.
40 40 41 4 42 42 42 42 42 42 42 42 42 42 42 42 4		62½ 63 63 64 64 64 65 65 65 66 66 67 70 71 71 72 72½ 73 75 76 76 77 78 79 80 80 81 81	8067 · 96 8117 · 25 8166 · 92 8267 · 46 8818 · 81 8369 · 56 8421 · 20 8478 · 47 8681 · 68 8685 · 29 8798 · 67 8496 · 68 8908 · 68 8908 · 68 8908 · 68 8908 · 68 4901 · 51 4128 · 25 4185 · 39 4242 · 92 4800 · 85 4859 · 16 4417 · 87 4476 · 97 4596 · 68 4717 · 80 4717 · 80 4718 · 87 4839 · 88 4901 · 68 4963 · 92 5026 · 56 5069 · 58 5153 · 00 5216 · 92	841 85 85 86 86 87 87 88 88 89 90 90 91 91 91 92 93 94 94 95 95 96 96 97 97 98 98 99 90 100 101 102 102 103 103 103	5607 · 95 5674 · 51 5741 · 47 5506 · 81 5876 · 55 5944 · 09 6013 · 21 6082 · 13 6161 · 44 6221 · 15 6291 · 25 6361 · 74 6432 · 62 6503 · 89 6575 · 56 6647 · 62 8720 · 07 6792 · 92 6866 · 16 6989 · 79 7018 · 81 7088 · 23 7168 · 04 7238 · 24 7813 · 84 7813 · 84 7697 · 70 7775 · 65 7854 · 60 77475 · 60 7892 · 78 8011 · 86 8091 · 88 8091 · 88 8171 · 80 8251 · 60 8332 · 30 8413 · 40	114 1141 115 1151 116 1161 117 1171 118 1181	8908·20 8992·04 9076·27 9180·90 9245·92 9881·38 9417·14 9508·34 9588·98 9676·91 9764·28 9852·05 9940·21 10028·77 10117·71 101296·79 10388·91 10477·48 10669·84 10669·84 10751·84 10843·42 10935·90 11028·78 11122·04 11215·70 11309·76 11409·04 11594·28 11688·38 11122·04 11594·28 11188·90 11882·81 11979·11 12076·31 12178·89 112271·87	128½ 129 129½ 180 180½ 181½ 181½ 182 182½ 188 188½ 186½ 187 187 187 187 140½ 141½ 142 142½ 143½ 144½ 144½ 144½ 144½ 144½ 144½ 144	Holder.  12968 · 72 18968 · 84 13171 · 35 18278 · 26 18375 · 55 18478 · 24 18581 · 83 18684 · 80 18788 · 67 18992 · 94 18997 · 59 14102 · 64 14208 · 08 14318 · 91 14420 · 14 14526 · 75 14741 · 17 14848 · 96 14957 · 15 15065 · 73 15174 · 71 15838 · 80 15284 · 08 15398 · 84 15508 · 99 15614 · 53 15725 · 47 15838 · 80 16948 · 52 16060 · 64 16173 · 15 16286 · 06 16399 · 34 16513 · 03 16627 · 11 16741 · 58 16856 · 45 16971 · 70 17087 · 35
59½ 60 60½ 61 61½ 62	2780·51 2827·44 2874·76 2922·47 2970·57 3019·07	82 821 83 831 84	5281 · 02 5845 · 62 5410 · 62 5476 · 00 5541 · 78	104 104 105 105 106	8494.88 8576.76 8659.08 8741.69 8824.75	126 126 127 127 127 128	12469·01 12568·16 12667·71 12767·65 12867·99	148 1481 149 1491 150	17203 · 40 17319 · 83 17436 · 66 17553 · 88 17671 · 50

Gasholder Capacity.—The holder or holders should be of capacity sufficient to contain at least the 24 hours' maximum production of gas. An excess in capacity, though not absolutely necessary, is found advantageous in point of convenience and economy, where the rate of consumption is liable to fluctuations by the non-lighting of the public lamps during the hours of moonlight; and where, as in manufacturing towns and districts, the large manufactories, generally the heaviest gas consumers, being closed on Saturday nights and Sundays, the production for these two days (unless Sunday labour is partially avoided) is greatly in excess of the consumption.

There can be no doubt, also, that abundant gasholder capacity tends to convenience, and, what is of greater importance, to economy, in gas manufacture, especially when, as is now frequently the case, a setting of eight and nine through retorts, heated by one furnace, embraces as many as 16 or 18 mouthpieces. Unless the storage capacity is very ample, it is a matter of difficulty either to start or to let down so many mouthpieces at once.

# DIMENSIONS OF THE PRINCIPAL MATERIALS IN GASHOLDERS IN ACTUAL WORKING.

Single Gasholder.

Diameter, 80 ft. Depth, 15 ft.

Roof sheets, No. 17 B. wire gauge.
Side sheets, No. 18 B. wire gauge.
Inlet and outlet pipes, 6 in. diam.

# Single Gasholder.

Diameter, 35 ft. Depth 12 ft.

Roof sheets, No. 15 B. wire gauge.

Side sheets, No. 16 B. wire gauge.

Crown plate, 8 ft. 6 in. diam., # thick.

4 main and 4 secondary bars, of 3 in. T-iron.

Top and bottom curbs, of 3 in. angle-iron.

4 columns, 18 ft. 6 in. long; diam. at base, 6 in.; at top,  $5\frac{1}{2}$  in.

4 holding-down bolts to each column, 4 ft. long, 1 in. round iron.

Inlet and outlet pipes, 8 in. diam.

# Single Gasholder.

Diameter, 40 ft. Depth, 15 ft.

Crown plate, 3 ft. 5 in. diam., § in. thick.

Roof sheets, No. 14 B. wire gauge.

Side sheets, top and bottom tiers, No. 14 B. wire gauge; all the rest, No. 15 B. wire gauge.

Rivets for sheets, 1 in. diam., 1 in. apart, centre to centre.

Rivets for top curb, \( \frac{1}{2} \) in. diam., 1\( \frac{1}{2} \) in. apart, centre to centre.

Rivets for bottom curb, ½ in. diam., 6 in. apart, centre to centre.

Centre-pipe of cast-iron, 6 ft. long, 4 in. diam.

Truss cup, cast-iron, 2 ft. 6 in. diam.

12 main bars, T-iron,  $2\frac{1}{2} \times 2\frac{1}{2} \times \frac{3}{8}$  in.

4 vertical stays, T-iron,  $8 \times 2\frac{1}{2} \times \frac{3}{8}$  in.

Top curb, angle-iron,  $8 \times 8 \times \frac{3}{8}$  in.

Bottom curb, angle-iron,  $8 \times 8 \times \frac{3}{8}$  in.

- 4 columns, 17 ft. long; diam. at base, 9 in.; diam. at top, 7 in.
- 8 holding-down bolts to each column, 7 ft. long each, 11 in. diam.

Girders of T-iron,  $3 \times 4 \times \frac{1}{2}$  in., trussed.

Balance-weights, 40 cwt.;  $\frac{1}{2}$  in. chains.

Inlet and outlet pipes, 8 in. diam.

# Single Gasholder.

Diameter, 44 ft. 6 in. Depth, 20 ft.

Rise of crown, 1 ft. 9 in.

Crown plate, 3 ft. 6 in. diam., § in. thick.

Roof sheets, inner and outer circles, No. 12 B. wire gauge; all the rest, No. 14.

Side sheets, top and bottom tiers, No. 12 B. wire gauge; the rest, No. 17.

Rivets for Nos. 12 and 14 sheets, 5-16ths in. diam.; for No. 16 sheets, 1 in. diam.

- 5 main and 5 secondary bearing bars, of T-iron, 8 × 3 × 3 in.
- 5 columns, 22 ft. long, 7 in. diam. at base, 53 in. diam. at top; metal 11-16ths thick.
- 4 holding-down bolts, 16 ft. long, 11 in. square-iron.

Inlet and outlet pipes, 8 in. diam.

## Single Gasholder.

Diameter, 50 ft. Depth 16 ft.

Rise of crown, 2 ft. 6 in.

Crown plate, 8 ft. diam., 1 in. thick.

Roof sheets, inner and outer circles, No. 12 B. wire gauge; all the others, No. 14.

Side sheets, top and bottom tiers, No. 14 B. wire gauge; the others, No. 16.

Rivets, 1 in. diam., 1 in. apart, centres.

Rivets for joining sheets to angle-iron, § in. diam., 1½ in. apart, centres.

Rivets for bottom curb, ½ in. diam., 9 in. apart, centres.

10 main and 10 secondary rafters, of T-iron,  $8 \times 3 \times \frac{3}{2}$  in.

Top curb, of angle-iron,  $3 \times 3 \times \frac{3}{8}$  in.

Bottom curb, two rings of angle-iron,  $3 \times 3 \times \frac{3}{5}$  in., 6 in. apart, with flat bar of iron, 6 in. wide and  $\frac{1}{2}$  in. thick, between them.

Centre strut, cast-iron pipe, 9 ft. long, 6 in. external diam.,  $\frac{3}{4}$  in. thick; bearing flanges, 18 in. diam.,  $1\frac{1}{4}$  in. thick; outer rim of cup strengthened by a ring of 8 C and crown-iron,  $2 \times 1$  in., shrunk on hot.

10 vertical ribs, T-iron,  $3\times3\times\frac{3}{5}$  in., secured to top and bottom curbs and to side sheets.

5 columns, 18 ft. long; diam. at base, 7 in.; diam. at top, 5 in.; metal, 3 in. thick.

Suspension chains, 1 in. short link, tested to 5 tons.

Inlet and outlet pipes, 10 in. diam.

# Single Gasholder.

Diameter, 50 ft. Depth, 20 ft.

Rise of crown, 12 in.

Roof sheets, No. 14 B. wire gauge.

Side sheets, No. 15 B. wire gauge.

Rivets, 1 in. apart, centres.

Top and bottom curbs, 3 in. angle-iron.

8 vertical bars.

8 columns, 26 ft. long, cast in two lengths each; 12 in. diam. at base, 6 in. diam. at top.

Inlet pipe and outlet pipes, 10 in. diam.

# Single Gasholder.

Diameter, 60 ft. Depth, 17 ft.

Rise of crown, 8 ft.

Crown plate, 4 ft. diam., 1 in. thick.

Roof sheets, inner and outer circles, No. 18 B. wire gauge; the rest, No. 14.

Side sheets, top and bottom tiers, No 14 B. wire gauge; the rest No 15.

Top curb,  $4 \times 4 \times 7$ -16th. in angle-iron.

Bottom curb, two bars of  $3 \times 3 \times \frac{3}{8}$  in. angle-iron, placed back to back, and bar of flat-iron riveted to the bottom with  $\frac{n}{8}$  in. rivets.

16 vertical bars,  $2\frac{1}{2} \times 2\frac{1}{2} \times \frac{3}{2}$  in. T-iron, riveted to top and bottom curbs and to side sheets.

8 columns, 18 ft. long; diam. at base, 6\frac{2}{3} in.; at top, 5\frac{1}{2} in.; metal, \frac{3}{4} in. thick.

Inlet and outlet pipes, 12 in. diam.

# Single Gasholder.

Diameter, 60 ft. Depth, 18 ft.

Roof sheets, inner and outer circles, No. 13 B. wire gauge; the others, No. 14.

Side sheets, top and bottom tiers, No. 14 B. wire gauge; the others, No. 15.

Top curb,  $4 \times 4 \times \frac{1}{3}$  in. angle-iron.

Bottom curb, formed of two bars of angle-iron,  $4 \times 4 \times \frac{1}{2}$  in., riveted back to back with  $\frac{1}{2}$  in. rivets 12 in. apart, centres.

14 vertical bars,  $4 \times 3 \times \frac{1}{2}$  in. T-iron.

7 columns, 19 ft. 6 in. long each.

Inlet and outlet pipes, 12 in. diam.

# Single Gasholder.

Diameter, 81 ft. 8 in. Depth, 20 ft. 6 in.

Rise of crown, 3 ft.

Crown plate, 4 ft. diam., 1 in. thick.

Roof sheets, inner and outer circles, No. 10; all the rest, No. 14 B. wire gauge.

Side sheets, top and bottom tiers, No. 14; all the rest, No. 16 B. wire gauge.

Rivets, 1 in. diam., 1 in. apart, centres.

16 main rafters,  $5 \times 8 \times \frac{1}{4}$  in. T-iron.

16 secondary rafters,  $4 \times \frac{1}{4}$  in. flat-iron, placed on edge.

Centre strut, cast-iron pipe, 9 ft. long, 7 in. external diam., 1 in. thick; flanges, 18 in. diam.,  $1\frac{1}{2}$  in. thick; cup strengthened by a hoop  $2 \times 1$  in. S C iron, shrunk on hot.

Tension rods, long Queen bolts, short Queen bolts, long suspenders, short suspenders, 16 in number each, of 1½ in., 1½ in., 1½ in., 1 in., and ¼ in. round-iron respectively.

Top curb, of angle-iron,  $4 \times 4 \times \frac{1}{2}$  in.

Bottom curb, of angle-iron,  $4 \times 4 \times \frac{1}{2}$  in., with bar of flat-iron,  $6 \times \frac{1}{2}$  in. between, and riveted with  $\frac{2}{3}$  in. rivets, 12 in. apart.

12 vertical bars,  $4 \times 8 \times \frac{1}{2}$  in. T-iron.

Inlet and outlet pipes, 14 in. diam.

# Single Gasholder.

Diameter, 87 ft. Depth, 20 ft.

Rise of crown, 4 ft.

2 crown plates, 4 ft. diam., 1 in. thick.

Roof sheets, inner and outer circles, No. 12; the rest, No. 14 B. wire gauge, except 9 sheets upon which the sliding carriages are fixed, No. 7 B. wire gauge.

Side sheets, top and bottom tiers, No. 12; all the remainder, No. 14 B. wire gauge.

Rivets, 5-16ths in diam., 1 in. apart, centres.

Centre-pipe of wrought-iron, 12 ft. long, 12 in. diam.

Truss cup, wrought-iron, 8 ft. diam., 2 in. thick.

18 main bars, T-iron,  $4 \times 8 \times \frac{1}{2}$  in.

18 secondary bars, T-iron,  $8 \times 3 \times \frac{1}{4}$  in.

9 rings or purlins of bracket bars, the middle purlin of angle-iron  $8\frac{1}{2} \times 8\frac{1}{2} \times \frac{1}{2}$  in., the remainder of flat-iron  $2 \times \frac{1}{2}$  in., secured to main and secondary bars with  $\frac{4}{3}$  in. bolts.

18 principal tension rods, 11 in. diam.

86 diagonal tension rods, 7 in. diam.

86 truss bars; 18 of 11 in. diam., 18 of 11 in. diam.

Top curb, 2 rings of angle-iron,  $8\frac{1}{2} \times 8\frac{1}{2} \times \frac{3}{8}$  in.

Bottom curb, 2 rings of angle-iron,  $3\frac{1}{2} \times 3\frac{1}{4} \times \frac{3}{4}$  in.

18 vertical truss bars, T-iron,  $8\frac{1}{4} \times 8\frac{1}{4} \times \frac{1}{4}$  in.

9 columns, 22 ft. long each, 14 in. diam. at base, 11 in. at top. 4 holding-down bolts, 8 ft. long, 14 in. diam.

Inlet and outlet pipes, 16 in. diam.

Single Gasholder.

Diameter, 100 ft. Depth, 20 ft.

Rise of crown, 5 ft.

2 crown plates, 5 ft. diam., § in. thick.

Roof sheets, inner and outer circles, No. 10; the remainder, No. 12 B. wire gauge, except carriage sheets, 1 in. thick.

Side sheets, top and bottom tiers, No. 9; the remainder, No. 12 B. wire gauge.

Rivets, 5-16ths in. diam., 1 in. apart, centres.

Centre-pipe of wrought-iron, 14 ft. long, 24 in. diam., 5-16ths in. thick.

18 main and 18 secondary bars,

Top curb, 2 rings of angle-iron,  $4 \times 4 \times 7$ -16ths in.

Bottom curb, 2 rings of angle-iron,  $4 \times 4 \times 7$ -16ths in., and a flat bar of wrought-iron,  $6 \times \frac{3}{8}$  in.

18 vertical bars, T-iron,  $4 \times 4 \times \frac{3}{5}$  in.

9 columns, 24 ft. long, 24 in. diam. at base, 18 in. diam. at top, 11 to 1 in. metals.

4 holding-down bolts, 8 feet long, 1½ in. diam.

Inlet and outlet pipes, 18 in. diam.

Single Gasholder.

Diameter, 110 ft. Depth, 26 ft.

Rise of crown, 5 ft. 6 in.

Crown plates, 4 ft. diam.; § in. thick.

Roof sheets, row next centre and outer row next curb,  $\frac{1}{4}$  in. thick; second row from centre,  $\frac{1}{8}$  in. thick; and second row next curb, 8-16ths in. thick; the remainder, No. 12 B. wire gauge.

Side sheets, top and bottom rows, ½ in. thick; next row to each, 8-16ths in. thick; the remainder, No. 12 B. wire gauge.

Rivets, ½ in. and 3-16ths in. plates, § in. rivets, 2 in. centres; the ½ in. and No. 12 B. wire gauge sheets 5-16ths in. rivets, 1½ in. centres; ¼ in. plates and curb § in. rivets, 2 in. centres.

Top curb of 2 angle-irons  $5 \times 4 \times \frac{1}{2}$  in.

Bottom curb of 2 angle-irons  $4 \times 4 \times \frac{1}{2}$  in.

Vertical stays, 14, of 2 angle-irons  $8 \times 8 \times \frac{1}{2}$  in., and a piece of timber 12 in.  $\times$  4 in. bolted between.

Centre pipe of 1 in. plate, 2 ft. diam.

Main rafters, 28, of T-iron  $5 \times 3 \times \frac{1}{2}$  in.

Purlins, of T-iron  $8 \times 4 \times \frac{1}{2}$  in., and remainder of angle-iron  $8 \times 8 \times \frac{3}{2}$  in.

Struts, 8, on main rafters 11 and 11 in. diam.

Tie rod, principal 15 in. dlam., second 1½ in. diam., and third 1 in. diam.

Columns, 14, of east-iron 1 ft. 6 in. in diam. at bottom, 1 ft. 2 in. at top; metal  $\frac{7}{8}$  in. at bottom, diminishing to  $\frac{5}{8}$  in. thick at top.

Holding-down bolts, 4, 11 in. diam., 20 ft. long.

Lattice girders, 14, 1 ft. 6 in. deep, of two frames of angle-iron,  $8 \times 8 \times \frac{1}{2}$  in., and braces  $2\frac{1}{2} \times \frac{1}{4}$  inch riveted between, top and bottom of girder covered with a plate 10 in. wide by  $\frac{2}{3}$  in. thick.

Inlet and outlet pipes, 20 in. diam.

# Single Gasholder.

Diameter, 142 ft. Depth, 55 ft.

Roof, without trussing or framework.

Roof sheets, first, or outside circle, 8 ft. long, § in. thick; rivets § in. diam., 2½ in. apart, centres. Second circle, 8 ft. long, ½ in. thick; rivets, 9-16ths in diam., 2½ in. apart, centres; centre sheets, forming a circle, 80 ft. diam., ½ inch thick, butted and riveted to each other by lapping pieces, 3½ in. wide; rivets 9-16ths in. diam.; remainder of roof sheets, 5 ft. long, 8-16ths in. (No. 7 B. wire gauge) thick; rivets, § in. diam., 1½ in. apart, centres.

Side sheets, top and bottom tiers,  $\frac{1}{4}$  in. thick; rivets,  $\frac{1}{2}$  in. diam.,  $1\frac{1}{2}$  in. apart, centres. Intervening side sheets, No. 10 B. wire gauge; rivets,  $\frac{3}{8}$  in. diam.,  $1\frac{1}{4}$  in. apart, centres.

Top curb, a circular chamber or girder, in section nearly rectangular, outer depth, 18 in.; inner depth, 19 $\frac{1}{4}$  in.; width, 2 ft. 6 in.; constructed of  $4 \times 4 \times \frac{1}{4}$  in. angle-iron.

Bottom curb, formed of two circles of  $\frac{3}{5}$  in. boiler plates, 12 in. wide, each riveted to a circle of angle-iron,  $4 \times 4 \times \frac{1}{2}$  in.

82 vertical stays, three sides of a rectangular figure, 12 in. wide, 10 in. deep; formed of 4 angle-irons  $8 \times 8 \times \frac{3}{8}$  in. and  $\frac{1}{4}$  in. boiler-plate.

16 columns, diam. at base, 3 ft.; at top, 2 ft. 3 in.; metal,  $\frac{7}{8}$  in. to  $\frac{3}{8}$  in. thick.

4 holding-down bolts, 10 ft. long, 2½ in. round-iron.

Inlet and outlet pipes, 80 in. diam.

Two-lift Telescopic Gasholder.

Diameter of outer lift, 44½ ft. Depth, 16 ft. Diameter of inner lift, 43 ft. Depth, 16 ft.

Rise of crown, 1 ft. 9 in.

Crown plate, 8 ft. 6 in. diam., § in. thick.

Roof sheets, inner and outer circles, No. 12; all the rest, No. 14 B. wire gauge.

Side sheets in both lifts, top and bottom tiers, No. 12; all the rest No. 16 B. wire gauge.

Rivets for Nos. 12 and 14 sheets, 5-16ths in. diam.; for No. 16 sheets, ‡ in. diam.

Cup, inner lift, formed by 2 rings of  $2\frac{1}{2} \times 2\frac{1}{2} \times 5$ -16ths in. angle-iron, connected together with No. 8 plates, with side of No. 10 plate, and a ring  $1\frac{1}{4} \times \frac{1}{2}$  in. half-round iron, riveted round.

Grip, outer lift, the counterpart of the cup inverted.

Main-bearing bars, T-iron,  $8 \times 8 \times \frac{1}{4}$  in.

Secondary bearing bars, T-iron,  $8 \times 8 \times 8$  in.

6 vertical bars, inner lift, T-iron,  $2\frac{1}{2} \times 2\frac{1}{2} \times \frac{3}{2}$  in.

6 vertical bars, outer lift, T-iron,  $2\frac{1}{2} \times 1\frac{1}{2} \times \frac{3}{2}$  in.

Bottom curb, angle-iron, double,  $8 \times 3 \times \frac{3}{8}$  in.

6 columns, 12 in. diam. at base, 10 in. at top; metal, 1 in. to \frac{3}{2} in. thick.

Inlet and outlet pipes, 10 in. diam.

Two-lift Telescopic Gasholder.

Diameter, outer lift, 87 ft. Depth, 20 ft.

Diameter, inner lift, 85 ft. Depth, 201 ft.

Rise of crown, 4 ft.

2 crown plates, 4 ft. diam., ½ in. thick.

Roof sheets, inner and outer circles, No. 12; the rest, No. 14 B. wire gauge, except 9 sheets upon which the carriages are fixed, No. 7 B. wire gauge.

Side sheets, top and bottom tiers, both lifts, No. 12; all the rest, No. 14 B. wire gauge.

Rivets, 5-16ths in. diam., 1 in. apart, centres.

Hydraulic cup and dip, 7 in. wide, 16 in. deep.

Centre-pipe of wrought-iron, 12 ft. long, 12 in. diam.

Truss cup, wrought-iron, 3 ft. diam., 3 in. thick.

18 main bars, T-iron,  $4 \times 3 \times \frac{1}{2}$  in.

18 secondary bars, T-iron,  $3 \times 3 \times \frac{1}{2}$  in.

9 rings or purlins of bracket bars, the middle purlin of angle-iron,  $8\frac{1}{2} \times 3\frac{1}{2} \times \frac{1}{2}$  in., the remainder of flat-iron,  $2 \times \frac{1}{2}$  in., secured to main and secondary bars with  $\frac{5}{8}$  in. bolts.

18 principal tension rods, 11 in., diam.

86 diagonal tension rods, 7 in. diam.

36 truss bars; 18 of 1½ in. diam., 18 of 1½ in. diam.

Bottom curb, 2 rings of angle-iron,  $3\frac{1}{2} \times 3\frac{1}{2} \times \frac{3}{2}$  in.

18 vertical truss bars, T-iron,  $8\frac{1}{2} \times 8\frac{1}{2} \times \frac{1}{2}$  in.

9 columns, 41 ft. long, 80 in. diam. at base, 20 in. at top, 1½ to ½ in. metal, cast in 4 lengths.

4 holding-down bolts, 8 ft. long, 11 in. diam.

Inlet and outlet pipes, 18 in. diam.

# Two-lift Telescopic Gasholder.

Diameter, outer lift, 100 ft. Depth, 22 ft.

Diameter, inner lift, 98 ft. Depth, 22 ft.

Roof sheets, No. 11 B. wire gauge.

Side sheets, top tier, to be No. 11; all the others No. 12 B. wire gauge.

Rivets, 1 in. diam., 1 in. apart, centres.

Hydraulic joint, 8 in. wide, 15 in. deep, No. 10 B. wire gauge; top edge of cup and bottom each of dip bound by half-round iron 2 × 1 in. thick.

Bottom curb, angle-iron,  $4 \times 1$  in. at the root, and ring of bariron  $4 \times 1$  in.

12 columns, 24 in. diam. at base, 16 in. at top; metal  $1\frac{1}{8}$  to 1 in. thick.

4 holding-down bolts, 10 ft. long, 2 in. square-iron.

Inlet and outlet pipes, 24 in. diam.

Two-lift Telescopic Gasholder.

Diameter, outer lift, 102 ft. Depth, 22 ft.

Diameter, inner lift, 100 ft. Depth, 221 ft.

Rise of crown, 4 ft.

Crown plate, 5 ft. diam., § in. thick.

Roof sheets, first ring next centre, No. 9; next and outer rings, No. 11; all the rest, No. 12 B. wire gauge.

Side sheets, outer lift, top and bottom tiers, No. 11; all the rest, No. 18 B. wire gauge. Inner lift, top and bottom tiers, No. 18; all the rest, No. 17 B. wire gauge.

Cup and grip, 8 in. wide, 15 in. deep, of angle-iron  $3 \times 8 \times \frac{3}{8}$  in.; plate, No. 7 B. wire gauge; edges stiffened with  $1\frac{1}{2} \times \frac{3}{2}$  in. half-round-iron;  $\frac{1}{4}$  in. rivets, 6 in. apart.

10 columns, 18 in. diam. at base, 14 in. at top; metal 1½ to ¾ in. thick, cast in 4 lengths.

4 holding-down bolts, 8 ft. long, 2 in. square wrought-iron. Inlet and outlet pipes, 24 in. diam.

Two-lift Telescopic Gasholder.

Diameter, outer lift, 112 ft. Depth, 26 ft. Diameter, inner lift, 110 ft. Depth, 26 ft.

Rise of crown, 6 ft.

Roof, trussed.

Roof sheets, centre plate ½ in. thick, next row ¼ in., next, 8-16ths in.; outer row, ¼ in.; next, 8-16ths in.; and the intermediate 7 rows, ¼ in. thick.

Side sheets, 8-16ths in. thick top and bottom rows; remainder, No. 12 B. wire gauge; the cup, 8 in.  $\times$  18 in., is formed of 2 rings of  $3 \times 8 \times \frac{3}{8}$  in. angle-iron, bottom and sides being  $\frac{1}{4}$  in. plate, having  $2 \times 1$  in. half-round bead at edge of plate.

Top curb, of two rings of angle-iron  $5 \times 9\frac{1}{2} \times \frac{1}{2}$  in.

Bottom curb, of 2 rings angle-iron  $5 \times 8 \times \frac{1}{2}$  in. placed 9 in. apart, between which bottom roller carriages are secured.

Vertical stays, inner lift, 28, 14 of which are of 2 angle-irons  $8 \times 8 \times \frac{1}{2}$  in. riveted on each side to a web plate 9 in. wide and  $\frac{1}{2}$  in. thick; the remaining 14 being of T-iron  $5 \times 8\frac{1}{2}$  in. trussed with three struts and a tie rod. Outer lift has 28 vertical stays of  $\frac{3}{8}$  in. guard-iron 5 in. wide, against which the guide pieces on the cup slide.

Centre column, 17 ft. 6 in. long and 2 ft. diam. of wroughtiron plates  $\frac{3}{8}$  in. thick,  $\frac{3}{4}$  in. rivets,  $2\frac{1}{2}$  in. pitch; this is secured to the under crown plate, which is 4 ft. in diam., by a ring of angle-iron  $5 \times 4 \times \frac{1}{2}$  in. and  $\frac{3}{4}$  in. rivets; at the lower end of the column are 2 rings of angle-iron,  $5 \times 4 \times \frac{3}{4}$  in., placed  $3\frac{1}{4}$  in. apart to form a jaw to receive ends of tension rods.

Main rafters, 14, of T-iron,  $4 \times 5 \times \frac{1}{3}$  in., trussed with six wrought-iron struts  $1\frac{1}{4}$ ,  $1\frac{1}{2}$ , and  $1\frac{3}{4}$  in. diam., and a  $1\frac{1}{4}$  in. diam. tension rod. Fourteen main tie rods of  $1\frac{3}{4}$  in. roundiron, extending from curb to bottom of centre column, and suspended in two places from the main rafters with  $\frac{1}{3}$  in. round rods; the main tie rods and the tension rods have each a wrought-iron coupling box with right and left hand threads.

Secondary rafters, 14, T-iron,  $3 \times 5 \times \frac{1}{2}$  in., trussed as above, with four struts  $1\frac{1}{4}$  and  $1\frac{1}{2}$  in. diam., tension rod  $1\frac{1}{4}$  in diam. with coupling box; these rafters extend from curb to within 21 ft. of the centre of holder, the inner ends being secured to a main brace bar or purlin,

Purlins, 7 rows between side and centre. The main purlin mentioned above is  $4\frac{1}{2} \times 4\frac{1}{2} \times 9$ -16ths in.; the one next curb,  $4 \times 3 \times \frac{1}{2}$  in.; and the remainder,  $3 \times 3 \times \frac{3}{8}$  in.; all of T-iron.

Columns, 14, of cast-iron, 2 ft. 6 in. diameter at bottom, 2 ft. at top, and 55 ft. 8 in. high, surmounted with a large ball 30 in. diam., with spiked finial.

Girders, 2 rows, each 2 ft. deep, and 10 in. wide, of 4 angle-irons  $8 \times 8 \times \frac{3}{8}$  in., with plate  $10 \times \frac{3}{8}$  in. top and bottom diagonal braces  $8 \times \frac{3}{8}$  in., at the intersection of which is a cast-iron spiked ball in two halves, 17 in. diam. across spikes.

Holding-down bolts, 4, 2 in. diam., 11 ft. 6 in. long. Inlet and outlet pipes, 24 in. diam.

Two-lift Telescopic Gasholder.

Diameter, outer lift, 120 ft. Depth, 24 ft. Diameter, inner lift, 118 ft. Depth, 24 ft.

Rise of crown, 6 ft.

Roof, untrussed, resting when down on timber framing in tank.

- Roof sheets, first or outside rows, \( \frac{3}{6} \) in. thick; second row, \( \frac{1}{2} \) in. third row, 8-16ths in.; fourth row, No. 8 B. wire gauge; crown plates, \( \frac{1}{2} \) in. thick and 6 ft. in diam.; inside row, next crown plate, 8-16ths in.; next, No. 8 B. wire gauge; and the remaining 10 rows of intermediate sheets, No. 11 B. wire gauge.
- Side sheets, inner lift, 12 courses high; top and bottom course, † in. thick; second course at top, 8-16ths in.; and the remainder, No. 12 B. wire gauge.
- Side sheets, outer lift, 12 courses high; top and bottom course, \$\frac{1}{4}\$ in. thick; second course at bottom, 8-16ths in.; and the remainder, No. 12 B. wire gauge. The thicker sheets in both inner and outer lift, riveted together with \$\frac{2}{3}\$ in. rivets, \$1\frac{1}{4}\$ in. apart centres, and the others with 5-16ths in. rivets, \$1\frac{1}{3}\$ in. apart, centres.
- Top curb, of 2 angle-irons, one at junction of roof with side sheets,  $5 \times 5 \times \frac{4}{5}$  in., and the other at the inner edge of outer row of sheets,  $4 \times 4 \times \frac{1}{2}$  in.; the two stiffened by gusset-pieces springing from the vertical stays.
- Bottom curb, of two 5 × 4 × § in.; angle-irons, riveted to the outside of the lower row of sheets, with § in. rivets, 6 in. apart. Between these two curbs, which are placed 2 in. apart, are fixed the 28 guide carriages and rollers.
- Cup and grip formed of rolled channel-iron  $8 \times 3\frac{1}{2} \times \frac{1}{2}$  in. riveted to the side sheets and rising and dip plates, with  $\frac{1}{2}$  in. rivets 4 in. apart. A half-round bead  $2 \times \frac{5}{8}$  in. being riveted to edge of rising plates, which are  $\frac{5}{8}$  in. thick and 18 in. deep.
- Vertical stays, 28, formed of two  $4 \times 4 \times \frac{1}{2}$  in. angle-irons and a web-plate between,  $\frac{3}{6}$  in. thick and 9 in. wide, secured with  $\frac{3}{6}$  in. rivets, 6 in. apart; at the upper end of these is attached a gusset-plate with angle-iron edges  $3 \times 3 \times \frac{3}{6}$  in., extending to the inner angle-iron curb of roof, to which and the outer curb it is riveted.
- Standards 14, in the form of the letter T, 4 ft. 2 in. × 8 ft. at bottom. tapering to 1 ft. 9 in. each way at the top; each standard 51 ft. high. Between the angle-iron framework of the standards is cast-iron trellis work, 1 in. thick, on one of its sides, and wrought-iron lattice work on the other; the standards are secured to cast-iron hollow base plates 6 in. deep; 4 holding-down bolts to each standard, 11 ft. 6 in. long, 2½ in. diam.

Lattice girders, 2 rows in the height; first or lower row, 27 in. deep; top row, 80 in. deep; formed of 4 angle-irons,  $8 \times 8 \times \frac{1}{2}$  in. wrought-iron tension bars,  $8 \times \frac{1}{2}$  in., and cast-iron struts.

Inlet and outlet pipes, 24 in. diam.

Two-lift Telescopic Gasholder.

Diameter, outer lift, 151 ft. 6 in. Depth, 40 ft. Diameter, inner lift, 149 ft. Depth, 40 ft. 8 in.

Crown trussed, rise 8 ft.

Roof sheets, outer row, 5-16ths in.; next row, 8-16ths in.; and the remainder No. 10 B. wire gauge, two centre plates \frac{3}{2} in. thick and 4 ft. 6 in. diam.

Side sheets, top and bottom rows in both lifts ½ in. thick, the remainder No. 11 B. wire gauge, ½ in. rivets, 1 in. centre; cup and grip 10 in. wide and 20 in. deep, Piggot's form; plates § in. thick, strengthened at edges with bead-iron.

Top curb, of 2 rings of angle-iron  $5 \times 5 \times \frac{1}{2}$  in., placed one above the other; the lower one is secured to a flat bar 10 in. wide and  $\frac{1}{2}$  in. thick, which is again connected by straps 4 in. wide and  $\frac{1}{2}$  in. thick to the top row of sheets.

Bottom curb, of 2 rings of angle-iron  $5 \times 4 \times \frac{5}{8}$  in. riveted to the outside of the bottom of row of sheets with  $\frac{5}{8}$  in. rivets. Between these two rings are fixed the bottom guide roller carriages.

Vertical stays, 32 in top lift of H-iron 12 in. deep, and 32 in bottom lift, of channel-iron 8 × 2½ × ½ in., attached to sheets, cups, and curbs with § in. bolts in upper lift, and § in. screwed pins in lower lift.

Centre column, 8 ft. 6 in. diam., 22 ft. long, of plates 7-16ths in. thick.

Roof framing, 24 main radial T-iron bars  $6 \times 4 \times \frac{1}{2}$  in. curved to roof, each with a main tension rod 2 in. in diameter at curb, and reduced to  $1\frac{1}{2}$  in. at the foot of centre column, and having a coupling box with right and left hand threads, 4 struts and 4 tension rods form the bracing to each main bar, the former of cross-iron  $4 \times 4\frac{1}{2} \times \frac{3}{2}$  in. placed vertically, and the latter of  $1, 1\frac{1}{6}, 1\frac{1}{4}$ , and  $1\frac{3}{6}$  in. round iron placed diagonally, the strongest section being nearest the centre column; 48 secondary radial

bars of 4 x 1 in. flat-iron, that is, 2 equidistant between the main radial bars, and extending from top curb towards centre a distance of 26 ft., and then for a further distance of 16 ft., in direction of the centre, another bar of the same dimensions is fixed. 17 rings or rows of purlins, divided equally from curb to centre, are fixed between main and secondary bars; the first row from centre being of 6 x 1 in. flat-iron; next 4 rows of angle-iron,  $1\frac{1}{4} \times 1\frac{1}{4} \times \frac{1}{4}$  in.; next row of angle-iron  $2 \times 2 \times 2$  $\frac{1}{2}$  in.; next row of T-iron  $3 \times 6 \times \frac{1}{2}$  in.; next 2 rows, which are subdivided in length by the secondary radial bars above mentioned, are of angle-iron 11 × 11 × 1 in.; next row extending from main bar to main bar is of I-iron  $8 \times 6 \times 1$  in.; next two rows are divided in 8 lengths between main bars by the two secondary bars, and are of  $1\frac{1}{2} \times 1\frac{1}{2} \times \frac{1}{2}$  in. angleiron; next row extending from main to main is of T-iron.  $4 \times 6 \times \frac{1}{2}$  in.; next row divided in 8 lengths as before of  $1\frac{1}{4} \times 1\frac{1}{4} \times \frac{1}{4}$  in, angle-iron, and the remaining 2 rows divided in 8 as before of  $2 \times 2 \times 1$  in. angle-iron; 8 bars of flat-iron 21 × 3 in. cross diagonally in each bay formed by the two main bars.

Columns, 16, of cast-iron, 88 ft. high, 8 ft. in diam. at base, and 2 ft. 8 in. at top, metal 1 in. thick; cast-iron channel guide up the column, 5 × 3 in. inside measure, weighing 56 lbs. per foot. Girders, 16, at top 4 ft. deep, 7 in. wide, of 4 angle-irons 8 × 8 × \frac{3}{6} in. and a top and bottom plate 7 in. wide by \frac{3}{6} in. thick; diagonal brace bars 4 × \frac{3}{6} in.; 16 intermediate girders 8 ft. 6 in. deep, 6 in. wide, of 4 angle-irons 2\frac{1}{2} × 2\frac{1}{2} × \frac{3}{6} in., and top and bottom plates 6 in. wide by \frac{3}{6} in. thick, diagonal brace bars 8 × \frac{3}{6} in.; at the intersection of the brace bars a cast-iron star 12 in. in diam. is riveted.

Holding-down bolts, 4, 2 in. square and 14 ft. long. Capacity, 1,400,000 cubic feet.
Inlet and outlet pipes 80 in. diam.

Two-lift Telescopic Gasholder.

Diameter, outer lift, 197 ft. 6 in. Depth, 86 ft. Diameter, inner lift, 195 ft. Depth, 36 ft. Crown, untrussed, rise 10 ft.

Roof sheets, centre plate ½ in. thick, 6 ft. diameter; row next centre of No. 7 B. wire gauge; row next curb, ½ in. thick; next row, 5-16ths in. thick; third row, No. 7 B. wire gauge, and the remaining rows of No. 11 B. wire gauge.

Side sheets, of inner lift in 18 rows; top row, ½ in.; bottom row forming cup, ¾ in.; second row from top and bottom, ½ in.; third row from top and bottom of No. 7 B. wire gauge; and the 12 intermediate rows of sheets of No. 11 B. wire gauge in thickness. Those of outer lift in 18 rows; top row forming cup, ½ in.; bottom row, 5-16ths in.; second from top, No. 9 B. wire gauge; second from bottom, 8-16ths in.; third from bottom, No. 9 B. wire gauge, and the 18 intermediate rows of No. 11 B. wire gauge in thickness.

Cup and grip, 10 in. wide, 18 in. deep, of channel-iron,  $10 \times 8\frac{1}{2} \times \frac{1}{2}$  in., rising and dip plates,  $\frac{3}{2}$  in. thick, with  $2\frac{1}{2} \times \frac{3}{4}$  in. bead riveted to edges.

Top curb, of 2 angle-iron rings, outer one  $6 \times 6 \times \frac{3}{4}$  in.; inner one,  $5 \times 5 \times \frac{5}{6}$  in., both double riveted to top and side sheets, with  $\frac{3}{4}$  in. rivets, 2 in. apart centre to centre.

Bottom curb, of 2 angle-iron rings,  $6 \times 5 \times \frac{5}{8}$  in., riveted to side sheets, with  $\frac{5}{8}$  in. rivets, 6 in. apart.

Vertical stays, 44, in upper lift of H-iron,  $8 \times 5 \times 5 \times 7$ -16ths in. secured to top and bottom rows of sheets and the outer angle-iron curb, but not to the intermediate sheets, except just at the centre, where there are two clips, 6 in. wide  $\times$  5-16ths in. thick, to which the sheet is riveted. Gusset pieces, 44, of 2 angle-iron frames,  $2\frac{1}{2} \times 2\frac{1}{2} \times \frac{3}{8}$  in., riveted to a 7-16ths in. web-plate placed between them and riveted together, and to the vertical stays, outer row of top sheets, and inner angle-iron curb with  $\frac{5}{8}$  in. rivets, 4 in. pitch. Vertical stays in lower or outer lift, 44, of channel-iron,  $8 \times 2\frac{1}{2} \times \frac{1}{2}$  in., riveted to bottom curb, and to the sheets half way up, with four  $\frac{3}{4}$  in. rivets, countersunk heads in the channel, and bolted to the channel-iron of grip with two  $\frac{7}{8}$  in. bolts.

Guide wheels, 22, at top lift of malleable cast-iron, 24 in. diameter, with steel axles or pins, mounted on wrought-iron carriages, 44 fixed under cup of upper lift, 22 on grip, and 44 on bottom curb of outer lift, all of malleable cast-iron, having steel pins and wrought-iron carriages.

Columns, 22, of cast-iron, 8 ft. diameter at bottom, and 2 ft. 6 in. at top, mounted on ornamental base 4 ft. square and 9 ft. 9 in. high, two entablatures and ornamental cap; 4 holding-down bolts to each column, 2½ in. diameter.

Girders, upper tier, 8 ft. 6 in. deep; lower tier, 8 ft. deep, of two frames of angle-iron,  $4 \times 4 \times 7$ -16ths in., with lattice bars,  $4 \times \frac{5}{8}$  in. riveted between them; the top, bottom, and ends of girders covered with a  $\frac{3}{8}$  in. plate 9 in. wide; rivets,  $\frac{3}{4}$  in., 4 in. apart centres; at the intersection of the diagonal braces with each other are fixed plates, 12 in. diameter and  $\frac{3}{8}$  in. thick.

Quality of iron, plate, angle, and T-iron of best South Staffordshire brands, the channel and H-iron of the best Belgian; the sheets of the very best South Staffordshire, equal to B. B. H. best.

Rivets, all sizes, of the best soft charcoal-iron. Those for the No. 11 B. wire gauge sheets, of No. 8 B. wire gauge in diameter and 1 in. pitch; and those for No. 7 B. wire gauge sheets, with § in. rivets 1½ in. apart centres.

Capacity, 2 million cubic feet.

Inlet and outlet pipes, 80 in. diam.

# Two-lift Telescopic Gasholder.

Diameter, outer lift, 200 ft. Depth, 25 ft. 8 in. Diameter, inner lift, 198 ft. Depth, 25 ft. 9 in.

Roof untrussed, and flat.

Roof sheets, centre plate  $\frac{3}{4}$  in., row next centre plate  $\frac{1}{2}$  in.; next row  $\frac{1}{5}$  in.; outer row next curb  $\frac{1}{2}$  in.; second row  $\frac{1}{4}$  in.; and the whole of the remaining rows  $\frac{1}{6}$  in. thick.

Side sheets, outer lift, bottom row 1 in.; next 8-16ths in.; top row 8-16ths in.; intermediate rows all 1 in. thick; inner lift, bottom and top rows 8-16ths in. thick; remainder 1 in. thick.

Top curb is a box girder 8 ft.  $\times$  2 ft. of  $\frac{3}{4}$  in. plates and  $4\frac{1}{2}$   $\times$   $4\frac{1}{4}$   $\times$   $\frac{1}{4}$  in. angle-irons in the inside corners, riveted together.

Bottom curb, of 2 angle-irons,  $4\frac{1}{2} \times 4\frac{1}{2} \times \frac{1}{2}$  in. riveted to a  $\frac{3}{4}$  in. plate 8 in. wide; the whole riveted to the lower sheet of holder.

Cup and grip formed of channel-iron  $8 \times 8 \times 8 \times \frac{5}{8}$  in. thick; rising and dip plates  $\frac{3}{8}$  in. thick and 15 in. deep; a  $1\frac{1}{2}$  inch half-round iron bead is riveted to edge of rising plate.

Columns, 28, 50 ft. long, 8 ft. diameter at bottom, and 2 ft. 4 in. diameter at top; metal 1½ in. thick at bottom and 1 in. at top. Capacity, 1½ million cubic feet.

Inlet and outlet pipes, 30 in. diam.

Three-lift Telescopic Gasholder.

Diameter, outer lift, 214 ft. Depth, 53 ft. Diameter, middle lift, 211 ft. Depth, 53 ft. 3 in. Diameter, inner lift, 208 ft. Depth, 58 ft. 6 in.

Rise of crown, 14 ft.

Roof, untrussed.

Roof sheets, outer row forming part of curb, \(\frac{3}{4}\) in. thick of steel plates 3 ft. wide; next row No. 7 B. wire gauge; then another row of No. 9 B. wire gauge; the remainder being all of No. 10 B. wire gauge; these latter riveted with 5-16ths in. rivets 1 in. pitch; the No. 7 B. wire gauge sheets riveted to the \(\frac{3}{4}\) in. steel curb plate by \(\frac{3}{4}\) in. rivets, \(2\frac{1}{2}\) in. pitch.

Side sheets of No. 11 B. wire gauge, secured to each other with 5-16ths in. rivets, 1 in. pitch, lap of sheets 1½ in.; the bottom and top rows of sheets in outer lift are ½ and 3-16ths in. thick respectively; in the middle lift 3-16ths in., and in the top lift 3-16ths and ½ in. respectively, being riveted to the other sheeting with § in. rivets, 1½ in. pitch, 1¾ in. lap. Piggot's cup and dip, the former of 7-16ths in. plate, and the latter of § in. plate, secured to adjoining sheets with § in. rivets, 1½ in. pitch, 2 in. lap; cup and dip 12 in. wide and 21 in. deep; edge of cup and dip stiffened by a 2½ × § in. flat-iron.

Top curb, formed by two  $\frac{3}{4}$  in. steel plates, one forming the outer row of sheets on the crown being 36 in. wide, the other forming top row of sheets on the side 12 in. wide, these are joined together at the angle with a  $5 \times 5 \times \frac{3}{4}$  in. angle-steel curb, and further stiffened at the inner edge of the crown plate with a  $6 \times 3 \times \frac{1}{2}$  in. angle-steel, all riveted together with  $\frac{7}{8}$  in. and 1 in. steel rivets, 4 in. pitch.

Bottom curb, formed by a plate  $\frac{5}{8}$  in. thick, and 15 in. wide, secured at right angles to the lower rows of sheets to a  $6 \times 3 \times \frac{1}{2}$  in. angle-iron with  $\frac{3}{4}$  in. rivets,  $5\frac{1}{2}$  in. pitch; another angle-iron of the same dimensions being placed 1 ft. 5 in. higher, forming a space in which are fixed the bottom roller carriages.

Vertical stays, 48, on lower and middle lifts are made of No. 10 B. wire gauge sheets bent in the form thus  $\_ \bigcap \_ 8 \times 4\frac{1}{2}$  in., riveted to the outside of the sheets, and on the inside opposite these are  $8 \times 8\frac{1}{4} \times \frac{1}{2}$  in. channel-irons, placed between two  $4 \times 8 \times \frac{1}{4}$  in. angle-irons, which are riveted through the sheets to the outside stays. The top or inner lift is stiffened by No. 8 B. wire gauge sheets of the same form as above, but are  $12 \times 9$  in., placed inside only.

Standards, 24, in the form of the letter H,  $20 \times 16$ . in. and 158 ft. 6 in. high above coping of tank, of wrought-iron formed of four  $8 \times 8 \times \frac{8}{8}$  in. angle-irons  $\frac{3}{8}$  in. web plate, and  $\frac{1}{2}$  in. inside and outside plates, having 5 tiers of struts from standard to standard, and 10 sets of diagonal braces. Two channel-irons  $8 \times 8 \times \frac{1}{2}$  in. riveted to each other back to back and to the standards, form the guides upon which the radial and tangential rollers work; the bottoms of standards are fastened to triangular shaped cast-iron base-plates, each secured to the tank with three  $2\frac{1}{2}$  in. bolts.

Capacity, 5½ million cubic feet.

Inlet and outlet pipes, 86 in. diam.


#### THE GOVERNOR.

An unnecessarily high pressure of gas in the mains and service-pipes is synonymous with a heavy leakage account. Ordinary valves are powerless to effect the desired pressure regulation, however well they may be attended to. No gas-works, therefore, whatever its size, should be without a station governor to control the initial pressure. When properly constructed it accomplishes this important object perfectly, however much the consumption on the one side and the density of the gas on the other may vary.

The construction of the governor is of the most simple character, consisting of a small cast-iron water-tank, through the bottom of which the gas from the regular holder enters, and makes it exit by means of a stand-pipe rising above the water level. This pipe may be either annular or rectangular in form. In the former case the gas enters by way of the central opening, and makes its exit by the annular space. In the latter arrangement the pipe is divided in two by a midfeather, one division being the inlet and the other the outlet for the gas; the inlet division of the pipe occupying the central position in the

tank. Within the tank is a floating bell or gasholder made of tinned sheet-iron, from the crown of which a conical or parabolic shaped valve is suspended by an eye-bolt. It is the raising and lowering of this valve within the inlet gas aperture, by reason of the gas exerting a pressure of greater or less force (according as the consumption varies) on the inner surface of the floating bell, that accomplishes the necessary regulation.

The holder may be balanced or buoyed up either by means of an air chamber within itself, placed round its lower curb (Fig. 108), and




consequently immersed in the water of the tank, or by chains secured to its crown outside (Fig. 102), passing over one or two pulleys and terminating in a rod carrying the required balance weights, the needed pressure being obtained by placing cast-iron or lead weights on the crown of the holder: or it may be weighted with water allowed to flow from a feed pipe into a tank formed by continuing the sides of the holder a few inches above the crown. The method of weighting by water is preferable to the other, as the pressure can be applied or removed in a more gradual manner, the opening in the supply and discharge taps

being regulated as desired.

The conical valve for increasing or diminishing the area of the gas aperture has generally given place to that in the form of a parabola; the latter requiring a shorter range to produce the necessary effect, and being more delicate and certain in its action. The parabola should be made twice its diameter in length, and of weight sufficient to resist without oscillation or blinking, whatever pressure may be exerted against it by the inflowing gas. With the like object it was formerly necessary to make the floating bell with an area twenty times greater than the area of the base of the valve; but with the improvements effected in governors this is not now required, and much less space is now occupied by the apparatus.

Serious accidents have arisen from the escape of gas by the tilting of the floating bell; and, to obviate this danger, improvements have been introduced in the construction of governors.

The governor of J. and J. Braddock (Fig. 102 in section) will show what has been done in this direction. The gas enters from above the valve chamber. Over the valve, and of the same area as its base, is a compensating chamber within the bell, which is supplied with gas through a small pipe enclosing the valve rod, so placing the bell and valve in equilibrium. The bell is actuated by the outlet pressure, through a small pipe attached to the outlet branch. It will thus be seen that if by accident the bell were tilted or rent, the quantity of gas escaping



would be limited to that which would be discharged through the two small pipes referred to.

Mr. F. W. Hartley introduced a safety and regulating plate over the valve to effect the same object, and obtained compensation by means of a small tank and holder placed alongside the governor, the holder being suspended from the chain carrying the counterpoise weights.


A more recent form of governor, by J. and J. Braddock, is shown in Fig. 104, which, amongst other advantages, occupies very little space, inasmuch as the usual large bell and tank are materially reduced in size. The governor has a chamber divided into two compartments, forming inlet and outlet. The two valves are connected together and counterbalance each other, and act in opposite directions. A pressure controlling tube, open at both ends, is fitted in the top of the outlet chamber, so as to admit gas from the outlet into the bell, above

the water level. As the consumption of gas decreases the pressure in the outlet chamber increases, and the bell is raised, so diminishing or shutting off, as required, the supply of gas. As the consumption of gas increases, the action is reversed. The governor is fitted with self-loading apparatus, which automatically changes the outlet pressure, according to the demand for gas.

Mr. D. Bruce Peebles employs the pressure of the inlet gas, supplied

through a small pipe having a dry regulator fixed upon it, to load the bell of the governor, which is enclosed in a gas-tight case; and the only adjustment required is by means of small weights to the regulator.

Mr. W. Cowan has introduced various improvements in governors, by which the adjusted pressure is maintained under all variations of



F1G. 104.

draught or changes at the inlet. (See Fig. 108.) He has also invented an "Automatic Pressure Changer," a most ingenious instrument for raising and reducing the pressure automatically at any given time, thus dispensing with the attendant, except on extraordinary occasions.

Mr. C. Hunt has adapted the ordinary throttle-valve to the purpose of a governor. By this plan a holder scarcely larger in diameter

than the main only is required. Within the supply-main leading from the works to the streets, the disc or throttle is accurately balanced on two small steel centres; the lever or radius arm by which it is actuated, being also inside the main, is attached to the centre of the disc. A small vertical pipe, communicating the holder with the main, serves to enclose the connecting-pipe attached to the radius arm and to the crown of the holder, and also conveys the gas into the latter. By means of this arrangement, a holder only 12½ inches in diameter, will actuate an 8-inch valve; and one only 17 inches diameter, an 18-inch valve.

In winter time the water in a governor tank is liable to freeze, particularly if the house containing it is in an exposed situation. A very efficient and simple remedy for this is provided by the steam stove. This is merely a cast-iron cylinder or pipe in the form of a pedestal, 2 ft. 6 in. to 3 ft. in height, and 10 or 12 in. in diameter, having a base, and an ornamental top or covering brightened by being ground and polished. The stove is placed on end on the floor of the governor room, in any convenient part, and a steam-pipe about  $\frac{3}{4}$  in.




Fig. 105.

in diameter, with stop-cock, is inserted through the bottom, in which is another stop-cock for letting off the water of condensation. In time of frost, by means of this stove, the atmosphere of the room can be maintained at an equable temperature, at a minimum expense. A piece of ordinary cast-iron pipe can be adapted to the purpose; on the other hand the stove is susceptible of any amount of ornamentation.

District or Differential Governor.—Gas pressure varies according to the elevation, increasing and decreasing at the rate of about one-tenth of an inch for each

10 feet of rise and fall respectively. It is thus obvious that if the pressure in the lower mains is sufficient, that in the higher mains (assuming them to be connected throughout) must be in excess.

For the supply of gas to varying levels, therefore, separate leading mains, with a station governor upon each, are highly advantageous, and should be employed wherever practicable.

District or differential governors, for the automatic regulation of the pressure in the mains at high altitudes considerably removed from the gas-works, are also of the utmost utility. These are produced both in the wet and dry form by most makers of gas apparatus. Fig. 105 shows the district governor made by D. Bruce Peebles and Co.

By doubling the amount of pressure, the consumption of gas is increased by about one-half. Leakage from a pipe is, of course, increased in the same ratio—i.e., in the proportion of the square root of the pressure.

### MAIN PIPES.

The leakage which arises in the distribution of gas is largely due to defective and badly jointed main pipes. Hence it is of the first importance to ensure that the pipes employed for that purpose are made of a good quality of metal, close in texture, free from defects of every kind, and as equal as possible in their sectional thickness.

To secure these three latter conditions, all cast-iron pipes 5 inches internal diameter and upwards should be cast vertically in dry sand moulds. Smaller sizes are usually cast in green sand and in inclined moulds. The pipes should be tested by hydrostatic pressure equal to at least 75 lbs. on the square inch (150 feet head of water), either at the place of manufacture or on the gas-works; and whilst under pressure they should be smartly rapped with a 3 lb. hammer from end to end. This will often reveal faults, such as sandy, porous, and blown places, not otherwise discernible. Bapping the pipes whilst on the ground will also indicate their character. If the sound emitted is clear and bell-like, the pipe may be considered free from defects. On the other hand, if dull and leaden, it is cracked or otherwise imperfect. All pipes that do not stand the tests should be rejected.

The metal of pipes, whilst compact and close, should not be excessively brittle and splintery, but such as may be readily chipped and drilled.

Cast-iron pipes below 3 in. diameter are 6 ft. long; 3 in. to 11 in. diameter, 9 ft. long; when 12 in. diameter and upwards they may be either 9 ft. or 12 ft. long. The socket is not included in these lengths.

Formula for calculating the weight of cast-iron pipes:—

 $W = 2.45 (D^3 - d^2).$ 

Where D = outside diameter of pipe in inches.

d =inside diameter of pipe in inches.

W = weight of a lineal foot of pipe in lbs.

It is usual to pay for any overweight in the pipes beyond the weight specified not exceeding 4 per cent.

TABLE.

Cast-Iron Gas Pipes, with Open Joints.

The weight of the socket, and bead on spigot, is equal to 9-10ths of a lineal foot of the pipe, and this is included in the weights given.

Internal Diameter of Pipe.	Thickness of Metal in Body of Pipe.	Length of Socket, inside measure.	Length of Pipe, not including Socket.	Weight per Pipe, inclusive of Socket and Bead.			
Inches.	Inches.	Inches.	Feet.	Cwts. qrs. lbs.			
1	5-16ths	$2\frac{1}{2}$	6	0 1 0			
11	5-16ths	2 }	6	0 1 10			
2	5-16ths	8	6	0 1 22			
2]	8-8ths	2 ± 3 3 8 8 4	6 6 6 9 9 9 9 9 9 9 9 9	0 2 17			
8	8-8ths	8	9	1 0 11			
4	8-8ths	4	9	1 1 19 2 0 7			
5 6 7 8	7-16ths	4 4	9	2 0 7			
6	7-16ths	4	9	2 1 21 8 0 27 8 2 19			
7	5-10ths	4	9	8 0 27			
8	5-10ths	4	9	8 2 19			
9 .	5-10ths	41	9	4 0 11			
10	9-16ths	41	9	5 0 <b>16</b>			
11	9-16ths	41	9	5 0 16 5 2 14 8 3 16			
12	5-8ths	41					
18	5-8:lis	41	12	9 2 12			
14	5-8ths	41	12	10 1 8			
15	5-8ths	41	12	11 0 4			
16	11-16ths	44	12	12 8 24			
17	11-16ths	44	12	18 2 24			
18	11-16ths	41	12	14 2 0			
19	8-4ths	44	12	16 2 24			
<b>2</b> 0	8-4ths	41	12	17 2 8			
21	8-4ths	5	12	18 1 20			
<b>22</b>	18-16ths	5	12	20 8 20			
23	18-16ths	5	12	21 8 8			
24	7-8ths	5	12	24 2 8			
80 86	1	5	12	85 0 0			
	lith	6	12	47 0 16			
42 48	1 ths	6	12	57 8 16 69 2 0			
48	1½th	6	12	69 <b>2</b> 0			

For the smaller sizes of pipes up to 8 in. diameter, the open jointing space is \( \frac{3}{6} \) in., and for larger diameters \( \frac{1}{2} \) in. wide all round. The following are the usual depths of the socket, inside measure, for the various sizes of open-jointed gas-pipes, plugged with yarn and lead:—

Diamet Up to 3 i	ter. nche	<b>.</b>						f Socket. ches.
4 to 8	21						4	**
9 to 20	"	•					41	,,
21 to 30	"				•	•	5	,,
82	••	and	upwa	rds			6	99

TABLE.

CAST-IRON GAS PIPES, WITH TURNED AND BORED JOINTS, HAVING A RECESS IN FRONT FOR LEAD.

The weight of the socket and thickened spigot is equal to  $1_{10}^{1}$  lineal foot of the pipe, and this is included in the weights given.

Internal Diameter of Pipe.	Thickness of Metal in Body of Pipe.	Length of Socket, inside measure.	Length of Pipe, not including Socket.	Weight per Pipe, inclusive of Socket and thickened Spigot				
Inches.	Inches.	Inches.	Feet.	Cwt. grs. lbs.				
1	5-16ths	21	6	0 1 1				
14	5-16ths	21	6 6 6 9	0 1 12				
2	5-16ths	8	6	0 1 24				
21	8-8ths	8	6	0 2 19				
8	8-8ths	8#	9	1 0 14				
4	8-8ths	4	. 9	1 1 22				
<b>5</b> 6 7 8 9	7-16ths	4	9	2 0 13 2 1 27				
6	7-16ths	43	9999	2 1 27				
7	5-10th	44	9	8 1 8				
8	5-10ths	41	9	8 8 0				
	5-10ths	41	9	4 0 28				
10	9-16ths	41	9					
11	9-16ths	41		5 1 0 5 8 1 9 0 4 9 8 0				
12	5-8ths	41	12	9 0 4				
18	5-8ths	41	12					
14	5-8ths	41	12					
15	5-8ths	5	12	11 0 24				
16	11-16ths	5	12	13 0 16				
17	11-16ths	51	12	18 8 20				
18	11-16ths	51	12	14 2 24				
19	3-4ths	51	12	16 8 24				
20	8-4ths	51	12	17 8 12				
21	8-4ths	51	12	18 2 24				
22	13-16ths	51	12	·21 1 0				
28	18-16ths	51	12	22 0 20				
24	7-8ths	5± 5± 5± 5± 5± 5±	12	24 8 24				
80	1	51	12	35 2 4				
36	1}th	6	12	47 8 16				
42	1,4ths	6	12	58 8 4				
48	1 <u>i</u> th	6	12	70 2 8				

When the turned and bored joint, on being tested, is found gastight, it is not necessary to fill the recess with lead. The usual filling material adopted under such circumstances is Portland or Roman cement. These cements, if kneaded with warm water, set quickly; with cold water not so soon.




Fig. 106.

# TABLE.

Dimensions of the Sockets of Turned Dimensions of the Sockets of Turned and Bored Cast-Iron Gas Pipes, with a recess in front. (Fig. 106.)

# TABLE.

and Bored Cast-Iron Gas Pipes, without a Recess in Front. (Fig. 107.)

Diameter of Pipe.	A	В	C	D	E	Diam. of Pipe.	A	В	c	D
Inches.	Inches.	In.	In.	In.	In.	Inches.	Inches.	Inches.	Inches.	
2	5-16ths	113	1	8	3	2	5-16ths	7	1/2	3
21	3-Sths	, Ā	16	31	13	21	8-8ths	10	10	31
31	3-8ths	14	8	84	4	3	3-8ths	1	6	84
4	3-8ths	1	3	31	7	31	3-8ths	11	4	34
5	3 Sths	170	110	4	15	4	3-8ths	11	11	4
	7-16ths 7-16ths	11	11	4	18	5	7-16ths	18	11	4
6 7 8 9		14	4	44	1	6	7-16ths	11/2	4	44
6	5-10ths	118	4	44	1	7	5-10ths	1,8	4	41
0	5-10ths	1a	18	41	116	8	5-10ths	14	18	41
10	5-10ths	18	*	41	13	9	5-10ths	111	7 8	44
11	9-16ths	170	7 8	41	1,2	10	9-16ths	17	7 1	44
	9-16ths	11	14	41	11	11	9-16ths	114	15	41
12	5-8ths	11	14	41	14	12	5-8ths	118	10	41
13	5-8ths	10	14	41	11	13	5-8ths	17	14	41
14	5-8ths	116	18	41	14	14	5-8ths	17	34	44
15	5-8ths	14	1	5	115	15	5-8ths	2 2	1	5
16	11-16ths	111	1	5	175	16	11-16ths		1	5
17	11-16ths	14	110	51	18	17	11-16ths	21	1,4	51
18	11-16ths	147	110	51	13	18	11-16ths	21	1,1	51
20	3-4ths	115	14	51	17	20	3-4ths	21	14	51




Fig. 107.

TABLE.
Cast-Iron Gas Pipes, with Flange Joints.

The weight of the flanges is equal to 1 lineal foot of the pipe, and this is included in the weights given.

				Flanges.						
Internal Diameter of Pipe.	Thickness of Metal in Body of Pipe,	Dia- meter across Flanges.	Thick- ness of Metal.	Number of Bolt Holes.	Dia- meter, centre to centre, of Bolt Holes.	Dia- meter of Bolts.	Length of Pipe outside the Flanges.	Weigh inc of the	lusi	ve -
Inches.	Inches.	Inches.	Inches.		Inches.	Inches.	Feet.	Cwts.	ars.	lbs.
1	5-16ths	4	178	8 1	27	₩.	6	0	ī	0
11	5-16ths	41	1 2%	8	8	4	6	Ó	1	11
2	5-16ths	6 <del>1</del>	10	4	44	10	6	0	1	22
21	3-8ths	7 <u>1</u> 71	18 19	4	51	i i	6	0	2	18
8	8-8ths	7₫	10	4	5 <u>1</u>	i	9	1	0	11
4	8-8ths	9	16	4	7	į	9	1	1	22
5	7-16ths	10 <del>1</del>	•	4	8 <u>1</u>		9	2	0	10
6	7-16ths	11 <u>;</u>	ŧ	4	91	8	999999	2 2 8	1	24
7	5-10ths	18	į	4	11	1	9	8	1	5
8	5-10ths	144	40 40 14	6	12	8	9	8	2	25
9	5-10ths	16	#	6	134	*	9	4	0	17
10	9-16ths	172	Ŧ	6	142	ŧ	9	5	0	22
11	9-16ths	18 <u>i</u>	Ŧ	6	157	1	9	5	2	20
12	5-8ths	194	18	6	161	1	12	8	8	24
18	5-8ths	201	18	6	171	1	12	9	2	20
14	5-8ths	211	1	8	181	- ž	12	10	1	16
15 16	5-8ths	221	1,	8	194	त्र व वर्ष वर्ष वर्ष ।	12	11 18	0	12
17	11-16ths	24	11/6	8 8	21	•	12 12	18	8	8 -
18	11-16ths	25	11/8		22 23	į	12	10	2	12
19	8-4ths	26 27	11	10 10	23	• •	12	16	8	12
20	8-4ths	28	ii	10	241	• •	12	17	2	24
21	3-4ths	29	ii	10	251	• •	12	18	2	8
22	13-16ths	30	14	10	261	*	12	21	Õ	8
28	13-16ths	30 31	117	10	271	· · · · · · · · · · · · · · · · · · ·	12	22	ŏ	ŏ
24	7-8ths	32	14	12	284	1	12	24	8	ŏ
80	1	38	110	14	841	1	12	35	ĭ	ŏ
86	ī, th	45	18	18	413	i	12	47	2	ŏ
42	1, ths	51	1	20	473	î	12	58	ĩ	š
48	11th	57	îį	24	531	î	12	70	ō	ă

Cast-iron in cooling from the molten condition shrinks one-eighth of an inch per foot.


Main Pipe Joints.—A host of joints for main pipes have been invented from time to time, which, though theoretically good, have not all proved very satisfactory in practice. The classes of joint generally in

use are the turned and bored, and the open joint. The ball and socket joint is employed under exceptional circumstances, as when the main has to be laid in the bed of a river or harbour, or across a narrow arm of the sea.

A difference of opinion exists among engineers as to which form of joint is best—the turned and bored, or the open joint filled with lead, rust cement, or other substance, metallic or otherwise. We, who have had large experience in both, and under most circumstances, prefer the turned and bored, both for ease in adjustment, economy, and efficiency.

In districts where the ground is extensively undermined and liable to subsidence, the vulcanized india-rubber joint (which is virtually an open joint) is the most suitable. (Fig. 111.)


Special pipes, such as bends, tees, and junctions are, for convenience sake, made with open joints. (Fig. 114.)



The turned and bored joint is shown in Fig. 108.

There is no difficulty in swinging round ordinary curves with a line of mains jointed in this manner; but when the radius of the curve is short, an occasional yarn and lead joint is required.


In specifying for pipes with these joints, care should be taken that the bored and turned surfaces are not made with too much taper; indeed, the nearer the surfaces approach to parallel lines without being absolutely parallel, the better they will fit.



The socket may either be bored flush up to the face, as in Fig. 107, or it may have a recess in front, as in Figs. 106 and 108. The latter is to be preferred, as it can be supplemented with lead or other filling should the turned joint prove defective.

Two examples of the open joint are given in Figs. 109 and 110.


The india-rubber joint (Fig. 111) is formed by passing a vulcanized ring of that material round the spigot end of the pipe, which is specially cast with a groove and bead to suit this description of joint.




When the pipe end is pushed forward into the socket, the ring is compressed or flattened, and butts against the raised bead. No other packing is necessary, so that it is an expeditious method of jointing, whilst the vulcanized india-rubber, unaffected by the presence of gas or moisture, is practi-

cally indestructible. The other advantages of this joint have already been referred to.

The ball and socket joint is shown in Fig. 112. This particular form is the invention of Mr. J. Z. Kay, and has been successfully employed for main pipes crossing through rivers and harbours where



F16. 112.



the ordinary rigid joint is inapplicable. The lead is first run in and caulked; and the connected pipes, being like a chain, can be paid out of a lighter, or other vessel, when they will find their own bed in the river bottom.

The expansion joint (Fig. 118) is useful in all cases where a line of main is exposed to varying temperatures, as in pipes placed against a wall or alongside a bridge, or in an open trench or channel.

Mill-board or engine-board coated with red or white lead, makes a good and durable joint for flanges.

A combination of asbestos and india-rubber woven sheeting, makes a superior flange joint, especially for steam purposes, as these substances resist the action of both heat and moisture. To prevent adherence to the iron (in the case of blank-flange and manhole joints that require to be frequently broken), the flange should be rubbed over with powdered black lead before placing the cover.

Metallic rings are commonly used for flange joints. These are best made with ‡ inch or § inch lead pipe, with the ends soldered evenly together; the ring is then covered with flax, and well smeared with red lead or paint. The pipe must not be beaten flat, but left round, so that when the joint is screwed up it may bed into any irregularities in the surfaces. The remaining space between the flanges is filled with rust or other cement.

Flange pipes can be jointed without the interposition of any packing material, by having the flanges faced in a lathe. In such case the surfaces are merely coated with white lead paint, and the joint tightened up.

Bolts used for jointing flanges, &c., should have a gummet of flax or tow, smeared with red or white lead, placed round their neck to bed under the head when screwed up.

Red and white lead should always be mixed with boiled linseed oil. Other oil can be made to answer, but not nearly so well.

The bends, tees, junction pipes, and other irregulars required in the distributing department of a gas-works, are shown on page 206.


Gas pipes should be free from excrescences, and moderately smooth on their inner surface.

They are better not coated internally with any kind of substance soluble in naphtha or other hydrocarbon liquid. Such coating is soon dissolved by the gas, and drains partially away into the drip wells; the residue collecting into viscid masses at different points, principally near to the joints. The coating can only be intended to reduce friction by rendering the surface joint smooth for the passage of the gas, because as a preservative to the iron, internally, it is not required. Its effect is to impede the flow. The slight deposit which takes place from the gas alone soon gives the metal a smooth coating. These objections do not, of course, apply to the internal coating of water-pipes.

It is only for appearance sake, as a rule, that a covering of this description can be recommended for the outside of cast-iron pipes. It often serves only to hide defects in the casting.

The reddish-brown oxide covering which cast-iron pipes acquire in a short time, when laid in ordinary soil, is one of the best perservatives of the metal. This covering is impervious to moisture, its effect being to arrest further corrosive action.

There are, however, circumstances where it is desirable and necessary to coat pipes externally, as, for example, when they are of




wrought-iron, and when, though of cast-iron, they are to be laid in soils intermixed with engine ashes, furnace slag, vitrified cinders, clinker, dross, scoriæ, or chemical refuse of any kind.

Wrought-iron and Steel Main Pipes.—Of recent years a considerable trade has sprung up in the manufacture of wrought-iron and steel main pipes of large diameter for foreign countries. Although the first cost of these is greater than that of the same sizes in cast-iron, yet owing to their being lighter and less liable to fracture, the reduced expense of freight and haulage to their destination makes their ultimate cost, length for length, materially less. The wrought-iron pipes are lap-welded, and those of the steel are riveted in the seam. They are generally in 15 feet lengths. The next table gives the usual thickness and weight of wrought-iron pipes.

TABLE.

Thickness and Weight of Wrought-iron Main Pipes.

Diameter Inside.	Thickness.	Weight per Foot.
Inches	Inches.	Pounds.
3 8½ 4 5 6 7 8 9 10 12 14	5-82 full. 5-82 full 8-16 8-16 8-16 1-4 bare. 1-4 bare. 1-4 1-4 5-16	6 7 9 104 13 18 20 244 26 33 48 50



The smaller sizes, 8 in.,  $8\frac{1}{2}$  in., and 4 in. diameter have screwed ends and sockets. The larger diameters may be either screwed or plain. In the latter case the "Kimberley" collar (Fig. 115) is employed for connecting them; this is also made of wrought-iron.

TABLE.
Weight of Lead required for Jointing Wrought-iron Main Pipes with
the "Kimberley" Collar.

Internal	Depth of Lead	Weight	Internal	Depth of Lead	Weight
Diameter	on each side	of	Diameter	on each side	of
of Pipe.	of Collar.	Lead.	of Pipe.	of Collar.	Lead.
Inches.	Inches.	Pounds.	Inches.	Inches.	Pounds.
5	12	82	10	14	16 <u>1</u>
6	12	10	11	14	18
7	12	112	12	14	20
8	12	183	14	2	26
9	12	15	16	2	80

The Laying of Main Pipes.—Special care is needed in the laying of main pipes. As a general rule the covering of soil over them should be at least 21 inches deep, to protect them from breakage by steam-rollers, the influences of heavy traffic and low and varying temperatures.

The excavation to receive the pipes should not be unnecessarily wide, as the less filling up that is required the better, not to mention the saving in cost.

The bottom of the trench on which the pipes rest should be even and firm, and if not so, then thoroughly consolidated by punning. The soil should be scooped out at the various points in the trench bottom, where the sockets come, so that the body of the pipe may lie solid throughout its length. In cases where this cannot well be done resort may be had to underpinning.

Each pipe should be laid with the proper inclination or fall, and securely jointed; all joints being proved either with gas or air under high pressure while the trench is open.

In roads or footpaths made with ashes or chemical refuse, the pipes should be carefully embedded in good common soil obtained for that purpose, or puddled round with clay—especially protecting the upper side with a thick covering.

It is worse than useless to place clay only underneath the pipe. When so placed, it serves to receive and retain the water, which, percolating through the material forming the ground, is charged with acid bisulphides and other deleterious compounds. The metal of the pipe thus lying, as it were, in a bath of acidulous liquid, is destroyed

sooner than it would be if no clay were present. The protection afforded by the clay should therefore be complete, all round the pipe, and particularly over its upper surface.

In refilling the trench, the soil should be shovelled in in layers, and rammed firmly and equally all round and above the pipes.

Gas pipes laid through arable land do it no harm, but rather good, inasmuch as they help to drain the land. The joints should be perfect, however, as the escape of gas is fatal to vegetable life.

When laying pipes with bored and turned joints, the spigot and socket ends, after being cleaned with cotton waste, are coated with thick paint composed of one part each white and red lead mixed with boiled linseed oil; the end is then inserted and driven home with a mallet, or, should the pipe be large, with a swing block. Or another pipe swung from the shear-legs may be used. In this case a wood shield should be laid against the socket to take the force of the blow.

In driving the pipes they will sometimes be found to spring back at every stroke. This may be due either to the surfaces being made too conical, in which case it is difficult to ensure a good joint; or there is a slight ridge or roughness on the inner edge of the bored part of the socket. Chip this off with a sharp chisel.

Red lead sets sooner and harder than white; and the following reason is given for preferring the white to the red for joints:—When an expansion or contraction takes place in the pipes, the red lead is liable to crack, and so cause a leakage; whereas the white lead is more tractable, and better adapts itself to the varying circumstances. An equal mixture of the two is preferable.


In placing pipes with open joints, twined gasket is caulked in all round so as to fill nearly half the length of the open space. A roll of tough plastic clay is then passed round and pressed against the secket face, and through a lip on the upper side molten lead is poured till the remaining space is filled. On the lead being set up with a blunt caulking tool and hammer the joint is complete.


The ladle should contain sufficient molten lead to fill the joint at one pouring, otherwise the adhesion of the metal throughout will not be perfect.

Molten lead, when heated to redness, will fly when poured upon a wet or damp surface.

Mains in level ground should be laid with a slight inclination, say 1 foot in 400 yards, and at each lowest point a syphon or drip-well

(Fig. 116), of cast-iron, should be placed underneath, and connected by a tube to the pipe to receive the liquid arising from condensation. Another form of syphon, with sockets to receive the main pipes, is shown in Fig. 117. In all cases where a main dips, a syphon is required at the place where the dip is reversed.





The liquor from these receptacles is pumped out periodically into a cask on wheels, and deposited in the tar-well on the gas-works.

In laying down mains in lieu of others of a smaller size, the difference in value between the two sizes of pipes only should be charged to capital account.

TABLE Giving the Weight of Lead in Pounds required for Jointing Cast-Iron Mains.

Diameter of	Depth of Lead	Weight of Lead	Diameter of	Depth of Lead	Weight of Lead in Pounds.
Pipe in Inches.	in Inches.	in Pounds.	Pipe in Inches.	in Inches.	
14 2 24 3 4 5 6 7 8 9	18 16 18 17 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	14 18 24 24 4 54 7 88 104 124	11 12 13 14 15 16 17 18 19 20	24 28 28 24 24 24 24 24 24 3	16½ 18½ 21 23½ 26 22½ 31 92½ 34 36½ 48

For pipes 11 to 8 inches in diameter the lead is assumed to be about \frac{1}{2}-inch thick; and in pipes 9 inches in diameter and upwards, \frac{1}{2}-inch thick.

In place of lead, rust cement and a mixture of beeswax and tallow are used for jointing mains. "Spence's metal" also is an efficient substitute, and its cost is considerably less.

Iron or Rust Cements for Flange and Open Socket Joints.

(1) 1 lb. of clean iron borings, pounded fine in a mortar.

2 oz. sal ammoniac (muriate of ammonia) in powder.

1 oz. flowers of sulphur.

Mix the whole together by pounding and keep dry. For use, mix one part with twenty of iron borings pounded, adding water to the consistency of mortar.

(2) 98 parts fine iron borings.

1 part flowers of sulphur.

1 part sal ammoniac.

Mix, and when required for use, dissolve in boiling water. This cement sets quickly.

If required to set slowly, which makes the better joint-

(8) 197 parts iron borings.

1 part flowers of sulphur.

2 parts sal ammoniac.

When required for use, mix with boiling water.

The iron borings used for making joints should be perfectly free from grease and oil.

The cubical content of the joint in inches, divided by 5, gives the weight in pounds of iron cement required.

Appliances used in Mainlaying.—In beginning to lay an extensive length of main pipes, considerable delay, and consequent loss, is often experienced at first, owing to a want of foresight in providing beforehand the necessary men, tools, and other appliances required. The following is an enumeration of what is necessary to be provided, varying according to the peculiarities of the district and the extent of the work to be done:—

One or two skilled main-layers.

A number of labourers according to the extent of the work.

A paviour and his labourer. A night watchman.

A pick and spade (and a tool, if clay) for each labourer.

A supply of picks, pick-handles, and wedges should be kept in stock . to replace broken ones.

A screen for separating stones and soil.

Shear-legs or tripod; or, what is better, if the mains are of large diameter, a moveable pipe-layer, supported on wheels, running on rails laid alongside of the trench.

Blocks, tackle, and ropes or chain.

A chain or clip to encircle the pipes.

Eight hand-spikes of wood, for moving the pipes about.

Two pieces of 2 or 8 inch wrought-iron tube (according to the size of main), on which to roll the pipe previous to lowering it to its place in the trench.

Two or four long iron bars, and two short ones.

Two planks for long and strong leverage.

Red and white lead, mixed with boiled oil, if turned and bored joints.

Some cotton waste and old cards to clean the joints, if turned and bored. A supply of spun yarn and lead, if open joints.

A wooden mallet for driving small bored and turned pipes.

Two or four oak blocks, strengthened with bolts or hoops, to lay against the pipe-sockets when driving

A 8 or 4 inch cast-iron pipe, to swing with a rope or chain from centre of shear-legs when driving, or a wooden spring block if preferred.

Wood plugs for the various sizes of pipes and branches.

India-rubber cloth bags for plugging the mains. (See Fig. 118.)

F16. 118.

A lead pot and two ladles.

Chisels and caulking tools.

Tarred rope for trying the joints and pipes.

A coke fire-grate for melting the lead and for use by the night watchman.

Three setts, with handles, for cutting any pipes required.

Two large hammers, 7 lbs. weight, and several smaller ones, 14, 2, and 8 lbs. each.

Screwing tackle.

Some fine flax for indifferent joints. .

A few casks of cement.

A bogie or hand-drag, and two or three hand-barrows.

Portable bench, with vice attached.

Covered hand-cart, under lock and key.

A supply of good soil for bedding the pipes, and to prevent the contact of ashes, if such should be present in the cutting.

A spirit-level and a straight-edge 10 or 14 feet long.

A supply of planking to cover up any part of the trench temporarily.

A box for the night watchman.

Two red signal lamps to warn passengers of the open trench during the dark hours.

Two stand-pipes for the signal lights.

Apparatus for proving the mains for leakage before filling up the trench.

Look up beforehand what bends, tees, thimbles, flanges, drip-wells, and other special castings will be required in the course of the work, and have them in readiness when needed.

In enlarging or replacing pipes, many services require to be coupled up and renewed, and in that case service-layers and tools should be in readiness.

#### EXPLOSIONS IN MAIN PIPES.

In the laying of large main pipes, due care and diligence should be exercised by the skilled and responsible officials in charge of such work. Calamitous explosions have occurred owing to neglect in these particulars.

Such an explosion took place in London in 1862, and again in 1880; and one in Manchester, in 1878, when a large cast-iron syphon-well was being attached to a main.

Coal gas when unmixed with air or oxygen, as is well known, is perfectly inexplosive, and is even incombustible. It is only when the gas comes in contact with the oxygen of the air, as at the burner for example, that it can be ignited; combustion being in fact the union in the presence of heat of the hydrogen and carbon of the gas with atmospheric oxygen.

Explosions of the kind referred to are produced by a mixture of gas and air in certain proportions. The explosive force of a compound of this character is greatest when gas is mixed with eight times its bulk of air.

Under ordinary circumstances it is impossible for air to become mixed with the gas in the street mains. This can only occur when a main is in course of being laid, or when a fresh junction is being made with an existing main.

In the case of the London explosions referred to, a new main was being laid. In order to allow of this being done, the gas was either wholly or partially shut off at the junction with the live main. Probably the gas was only partially excluded; and the limited quantity entering would, by the operation of the law of the diffusion of gases, gradually mix with the air existing in the new length of main, till it became charged throughout its course, with a dangerously explosive compound. On the application of a light, either accidentally or from intention, the mixture was ignited, with disastrous consequences to life and property.

It is not necessary that there should be the presence of actual flame to cause ignition. Dr. Frankland and other authorities have demonstrated the fact, well known to most gas engineers, that explosive mixtures of coal gas and air may be inflamed by a spark struck from stone or metal; that ignition may be caused by a spark produced from the hammer and chisel of a workman, or even from the tramp of a horse upon the pavement.

There is no absolute necessity that the gas should be excluded from such an extent of main pipes in course of being laid as to incur the risk of accident; because the main for a short space from the point where the junction is being made can readily be closed by the ordinary india-rubber valves. When the main is of such large diameter as to preclude the possibility of a valve of this kind being used, the utmost precaution is necessary to ensure the expulsion of the air before a light is applied to test the soundness of the joints.

Under any circumstances the application of a light is objectionable and unnecessary, as the joints can be proved when the main is under pressure by brushing them over with a solution of soap in water.

#### TESTING OF GAS-MAINS IN THE GROUND.

The reduction of the loss of gas by leakage during recent years is remarkable. It is safe to estimate that twenty to twenty-five years ago, the unaccounted-for gas averaged sixteen per cent. of the gas produced. At the present time the average is only one-half that figure, or eight per cent. This reduction is largely due to the closer attention that is given to the pressures by day and night; to the use of governors in street lighting; and to the better supervision that is exercised in the laying of mains and service-pipes.

It may be stated as a salutary rule, that the maximum initial pressure in a district during the hours of the heaviest consumption, should.

not exceed 20-tenths. When there is found to be a necessity for more, the trunk mains, or some of the most contracted mains branching therefrom, should be replaced by larger ones.

Considerable expense must be incurred in any systematic attempt to reduce leakage; but wherever in a district the unaccounted-for gas exceeds 10 per cent. of the make, the expenditure is not only justifiable on sanitary and other grounds, but is eventually found to be a good and profitable investment.

Various appliances have been devised for testing gas mains in the ground. Brothers' apparatus consists simply of two 80-light meters,




Fig. 119.

one of which registers the passage of gas in the usual way; and the other is made to act as an exhauster, either by continuing the spindle of the drum through the casing and attaching a handle to it, or by means of a small wheel geared into a larger one on the periphery of the drum—the former being actuated by a handle from the outside. The main having been severed, and the two ends carefully plugged, the exhauster inlet is connected to the live main, and the meter outlet to the dead section of main; the exhauster and meter also being joined. On the exhauster being gently turned, gas is drawn from the

live main, and forced through the meter into the length of main under test, and thus the amount of loss in a certain time and under a given pressure is indicated.

The great cost is in cutting the pipes, reinstating them, and finding the exact locality of the escape. To obviate the necessity of severing the pipes, a suggestion was made at the meeting of the Manchester District Institution of Gas Engineers in November 1879, that water-valves or traps which would also answer the purpose of drip wells, might be permanently placed at intervals in the line of mains. These traps, having a diaphragm extending to within a regulated distance of the bottom, on being charged with water, would form a hydraulic valve, shutting off the gas from any section of main as desired, and enabling a test to be made without difficulty and at reduced expense.

Acting on this suggestion, Mr. J. H. Lyon has introduced an improved syphon box or hydraulic valve, for attaching to mains, and by means of a leakage indicator affixed to stand pipes on each side of the box or valve, the quantity of gas escaping is readily ascertained. (See Fig. 119.)

TABLE

Showing the Average Cost per Yard of Laying Mains, 9 feet long each, with Turned and Bored Joints, and with Lead Joints, including the Total Fixpenses of Material (the Pipes excepted), Excavating, Beinstaing, and Maintaining the Ground for Six Months after Completion. Average Depth from the Surface of the Ground to the Upper Side of the Pipe, 1 foot 9 inches.

Diameter in Inches.	oi —		42	-	ຜ				10	5.	6.	و
Description of Joint.	Turned and Bored.	Lead.	Turned and Bored.	Lead.	Turned and Bored.	Lead	Turned and Bored.	Lead.	Turned and Bored.	Lead.	Turned and Bored.	Lead.
In ordinary ballast	-i⊗ •0	3.1 0.6	.0 .0	3. 1.	6. d.	3.L	9 1 3 3	-3 to	1. 1. 6.	₹ 64 40	1 d.	* ca
In roads macadamized with Welsh or limestone	0 11	1 8	1 0	1 6	1 2	1 6	1 7	1 11	1 9	2	1 11	8
In ordinary paved streets In bituminized streets	- 80	18 49	-8	3 3 3	⊔ 80 44 80	₩ 44	61	90	01 PO	68	01 r0	22 60 60 60 60
In footpaths made with sand	9	0 11	0 7	1 0	8 0	1 0	0 11	1 8	1 4	1 10	1 6	8
In footpaths flagged In footpaths asphalted	0 8 1 10	1 2 2	80	1 1 2 4	0 10 2 2	1 2 8	1 8 2 7	1 7 8 0	1 6 2 10	3 4	9 11	21.20
Diameter in Inches.	7.		80		66		92	ä	1	11.	21	13.
Description of Joint.	Turned and Bored.	Lead.	Turned and Bored.	Lead.	Turned and Bored.	Les d.	Turned and Bored.	Lead.	Turned and Bored.	Lead.	Turned and Bored.	Lead.
In ordinary ballaet	1 10	<b>43</b>	100 100 100 100 100 100 100 100 100 100	. d.	* 63	30 50	 	3.00 9.00	ಕ್ಕಡ ಕ್	8. d. 8 10	2. d.	9.44 49.00
Welsh or limestone	<b>c</b> 1	2 10	62	c9 C9	8	8	2 10	8 10	8 1	4 8	8 4	4 7
In ordinary paved streets In bituminised streets	6 10 10	89	31 <del>20</del>	28	88	7 2 6	8 9 1 9	4 8 0	∞ ∞ 4 ∞	48 84	8 7 11	4.0 01.0
In footpaths made with sand	1 7	69 69	111	8	8	9 10	2 4	8 4	8	89	8	4 0
In footpaths flagged In footpaths asphalted	28 28	88 50	04 FD	01.4 01.00	04 60 03 60	∞ <del>4</del>	ය ස ස ට	8 4 10	<b>84</b>	8 5	24	40

Diameter in Inches.	13.		14.		16.		Ä	16.	и	17.	7	18.
Description of Joint.	Turned and Bored.	Lead.	Turned and Bored.	Lead.	Turned and Bored.	Lead.	Turned and Bored.	Lead.	Turned and Bored.	Lead.	Turned and Bored.	Lead.
In ordinary ballast.  In roads macadamised with Welsh or limestone.  In ordinary paved streets.  In bituminized streets.  In footpaths made with sand or ashes.  In footpaths flagged.  In footpaths asphalted.	4∞ ∞ 10 0 ∞ ∞ 4	-4 6 60 4 40 -60 8 60 5 00		10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	್ಳೆ ಐ ಇ ಇ⊙ ಐ ಐರ್ ಪೈಟ ಡ ರ್≎ ⊱ ೞಐ	6 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	44 44 10 0 4 410 44 00 00 00 45	6 6 6 8 6 8 8 6 8 8 6 8 8 8 8 9 9 9 9 9	44 10 10 14 440 40 01 40 10 00 03	47 77 77 0 77 0 12 12 10 10 8 4 0 0 8 8 6 9 0	10 00 00 00 00 00 00 00 00 00 00 00 00 0	7. d. 7. 11 13 6 11 13 6 7 8 7 8 7 8 9 0 9 0
Diameter in Inches.	19.		96		.12	<b>.</b>	C4	Si.	<b>c</b> 1	<b>88</b>	<b>09</b>	3
Description of Joint.	Turned and Bored.	Lead.	Turned and Bored.	Lead.	Turned and Bored.	Lead.	Turned and Bored.	Lead.	Turned and Bored.	Lead.	Turned and Bored.	Lead.
In ordinary ballast	6 8 8 11 10 5 8 8 6 8 8 9 8 9 9 9 9 9 9 9 9 9 9 9 9 9	8 8 8 8 10 8 8 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	12 6 8 8 7 7 8 8 8 9 9 9 9 9 9 9 9 9 9 9 9 9	8. d. 8 10. 9 4 16 0 8 7 8 10 10 4	*⊕ ≻ ≻≅ ⊛ ⊕⊗ *9 ⊗ ♥ ♥ ♥ ♥	9. d. 9 4. 9 10 10 1 16 6 9 2 9 2 10 10	7 1 7 7 7 7 10 18 6 10 6 10 8 7 8 7	9.5 6.11 9.6 9.6 9.6 9.6 9.6 9.6 9.6 9.6 9.6 9.6	7. d. 7. d. 7. d. 8. 1. 13. 8. 7. 2. 7. 2. 7. 2. 7. 4. 4. 8. 10. 10. 8. 10. 10. 8. 10. 8. 10. 8. 10. 10. 10. 10. 10. 10. 10. 10. 10. 10	9. 4. 10. 6. 10. 6. 10. 9. 17. 8. 9. 10. 0. 11. 6.	7. 7. 7. 7. 14. 08. 1. 7. 4. 7. 7. 4. 7. 4. 7. 7. 7. 7. 7. 7. 7. 7. 7. 7. 7. 7. 7.	11 8 11 8 11 8 11 8 11 8 11 8 11 8 11

#### TABLE

Giving Weight and Cost per Yard of Cast-Iron Main Gas Pipes, 2, 8, and 4 inches diameter, at Rates from £4 to £10 per Ton. (Calculated to the nearest Penny.)

	···y··							
Diameter in Inches.		2.		8.			4	
Class of Joint.	Open. T.	B. Finge.	Open.	T. & B.	Finge.	Open.	T. & B.	Finge.
Weight per yard in lbs.	25 9	6 26	41	42	41	58	54	64
Cost per yard at ### 0 0 per ton. ### 4 5 0	011 0 011 1 1 0 1 1 1 0 1 1 1 1 1 1 1 1 1 1 1 2 1 1 1 3 1 1 1 4 1 1 1 5 1 1 1 6 1 1 1 7 7 1 1 1 8 1 1 1 7 7 1 1 1 8 1 1 1 9 1 1 1 10 1 1 10 1	d. 11110001111223888444455556667778888999910101111111111111111111111111	6.667788990111100111223884556667788999011110011122334455666778	5.0 6777889901111100111222224445566678899901001111011122222222222222222222222	8.11111111111001112222222222222222222222	111101122284456778990111101122844566778990110011228444444444444444444444444444444	110111288456678999111101122845566778991011100112888456667889991011100128888888888888888884444444444444	5.1222222222222222222222222222222222222

**TABLE** 

Giving Weight and Cost per Yard of Cast-Iron Main Gas Pipes 5. 6, and 7 inches diameter, at Rates from £4 to £10 per Ton. (Calculated to the nearest Penny.)

	<u>,</u>							
Diameter in Inches.		5.		6.			7.	
Class of Joint.	Open. T. é	B. Finge.	Ореп.	T. & B.	Finge.	Open.	T. & B.	Finge.
Weight per yard in lbs.	77 7	9 79	91	98	92	191	194	128
Cost per yard at 24 0 0 per ton. 4 10 0 per ton. 4 15 0 " 4 10 0 " 4 12 6 " 4 17 6 " 5 10 0 " 5 12 6 " 5 16 0 " 5 16 0 " 6 12 6 " 7 10 0 0 " 7 12 6 " 7 10 0 0 " 7 12 6 " 7 10 0 0 " 7 12 6 " 7 10 0 0 " 7 12 6 " 7 10 0 0 " 7 12 6 " 7 10 0 0 " 7 12 6 " 7 10 0 0 " 7 12 6 " 7 10 0 0 " 7 12 6 " 7 10 0 0 " 7 12 6 " 7 10 0 0 " 7 12 6 " 7 10 0 0 " 7 12 6 " 7 10 0 0 " 7 12 6 " 7 10 0 0 " 7 12 6 " 7 10 0 0 " 7 10 0 0 " 9 10 0 0 " 9 10 0 0 " 9 10 0 0 " 9 11 6 0 " 9 17 6 0 " 9 18 0 0 " 9 18 0 0 0 " 9 18 0 0 0 0 " 9 18 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	2 90 2 3 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	d. 91001234567890011012334566789101101101233456678910110110123345667891011011012334566789101101101233456678910110110112334566789101101101123345667891011011011233456678910110110112334566789101101101123345667891011011011233456678910110110112334566789101101123345667891011011011101111111111111111111111111	8.88.88.88.44.44.44.44.55.55.55.55.55.56.66.66.66.66.66.77.77.77.77.77.77.77.77	8888888811112844578910128567901101845689101102846789101124	7 8 7 10 7 11 8 0 8 1	9 10 10 0 10 2 10 8 10 5 10 6 10 8	10 8 10 5 10 6 10 8 10 10 10 11	8. 4. 4. 4. 101 1 1 2 4 6 8 9 1 1 1 2 4 6 7 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9

TABLE

Giving Weight and Cost per Yard of Cast-Iron Main Gas Pipes 8, 9, and 10 inches diameter, at Rates from £4 to £10 per Ton. (Calculated to the nearest Penny.)

#### TABLE

-Giving Weight and Cost per yard of Cast-Iron Main Gas Pipes, 11, 12, and 18 inches diameter, at Rates from £4 to £10 per Ton. (Calculated to the nearest Penny.)

Diameter in Inches.	1	11.			19,			18.	
Class of Joint.	Open.	T. & B.	Finge.	Open.	T. & B.	Finge.	Open.	T. & B.	Finge.
Weight per yard in lbs.	210	215	212	249	258	261	269	278	971
Cost per yard in lbs.  Cost per yard at  £4 0 0 per ton.  4 2 6  4 7 6  4 10 0  4 12 6  7 10 0  5 2 6  5 7 6  5 10 0  5 15 0  5 17 6  6 0 0  6 12 6  7 10 0  7 2 6  7 10 0  7 2 6  7 10 0  7 17 6  8 0 0  7 15 0  7 17 6  8 0 0  8 2 6  8 5 0  7 7 7 6  7 10 0  7 17 6  8 0 0  8 2 6  8 5 0  7 7 7 6  7 10 0  7 17 6  8 0 0  8 2 6  8 5 0  8 7 6  8 10 0  8 12 6  8 15 0  9 10 0  9 2 6  9 10 0  9 2 6  9 10 0  9 2 6  9 10 0  9 2 6  9 10 0  9 2 6  9 10 0  9 2 6  9 10 0  9 2 6  9 10 0  9 2 6  9 10 0  9 10 0  9 10 0  9 10 6  9 10 0  9 10	8. d. 7 6 7 9 8 8 2 8 8 8 11 9 2 4 9 7 7 9 10 11 10 11 11 11 11 11 12 5 12 8 12 11 13 12 13 15 15 16 8 16 16 16 16 16 16 16 16 16 17 17 17 18 18 18 18 18 18 18 18 18 18 18 18 18	8. d. 7 8 2 8 8 8 8 11 9 1 9 9 10 10 10 10 11 1 1 11 3 3 12 6 11 9 12 8 13 12 6 11 9 12 8 13 12 6 14 2 15 1 16 4 17 0 18 10 17 0 18 10 17 0 18 10 18 10 19 1 10 10 11 1 11 1 12 8 13 1 14 8 15 1 16 1 17 0 18 1 18 1 1	s. d. 7 7 10 8 0 8 8 6 8 9 9 0 9 3 9 5 9 11 10 2 10 5 10 8 10 10 11 1 11 2 4 11 7 11 10 12 1 11 2 6 13 9 13 0 13 8 13 6 14 2 14 5 14 1 15 1 16 4 16 7 17 0 17 0 17 0 17 0 17 0 17 0 17 0 17	s. d. 8 11 9 2 2 9 5 6 9 9 9 6 10 0 0 10 10 10 11 1 1 11 2 2 13 1 1 12 2 9 13 1 1 14 2 9 13 1 1 14 5 7 15 10 16 1 17 0 16 1 17 10 18 1 18 4 18 1 19 9 20 0 20 7 20 10 21 2 21 2 21 2 21 2 21 3 22 3 23 3 24 5 25 7 26 7 27 7 28 1 29 9 20 0 20 0 20 0 20 0 20 10 20 10 20 10 20 10 20 10 21 21 21 21 21 21 21 21 22 20 3 23 20 3 24 20 3 25 20 3 26 20 3 27 20 3 28 20 3 29 20 4 20 7 20 20 4 20 21 22 21 21	s. d. 9 0 9 4 9 17 9 11 10 5 11 0 5 11 10 5 11 10 5 11 10 5 11 11 10 12 2 13 10 14 1 14 1 15 3 16 16 11 16 6 16 16 11 17 6 16 16 11 17 6 16 17 9 18 11 19 9 20 1 20 4 20 7 20 11 21 22 21 6	s. d. 9 0 9 3 9 6 9 10 10 1 10 4 10 8 10 1 11 9 12 7 12 1 13 2 13 5 14 0 14 3 14 3 14 10 15 5 16 6 16 10 17 4 17 8 17 11 18 2 18 5 16 0 17 1 17 8 17 1 18 9 19 0 19 0 10 1 10 1	s. d. 9 77 9 11 10 3 10 6 6 10 10 11 1 5 11 9 12 10 11 18 8 6 13 10 14 1 1 14 5 14 9 15 6 16 10 17 15 11 17 9 16 16 10 17 17 19 18 19 6 6 19 10 20 1 20 5 20 9 21 4 7 21 7 21 1 11 22 3 6	s. d. 9 9 9 10 1 1 10 8 11 0 8 11 7 11 11 12 12 12 6 12 10 18 1 1 18 5 14 0 18 14 14 11 15 3 15 6 6 14 14 18 15 16 9 17 1 17 4 18 18 3 15 16 9 17 1 17 4 18 18 3 18 18 7 18 11 19 2 19 10 20 5 20 9 21 0 21 4 21 8 22 10 22 10 22 22 10 22 22 22 10 22 22 22 22 22 22 22 22 22 22 22 22 22	871 8. d. 9 8 0 10 0 7 110 11 12 111 6 111 10 1 112 1 112 5 113 0 118 4 118 114 8 114 6 115 2 115 5 116 0 116 4 116 117 7 17 10 18 2 117 7 17 10 18 2 18 5 20 0 0 20 3 7 20 10 21 2 22 1 5 22 2 3 2 23 0 4 23 2 3 0 4 23 2 3 0 4 2 23 1 6 2 2

TABLE

Giving Weight and Cost per Yard of Cast-Iron Main Gas Pipes, 14, 15, and 16 inches diameter, at Rates from £4 to £10 per Ton. (Calculated to the nearest Penny.)

#### TABLE

Giving Weight and Cost per Yard of Cast-Iron Main Gas Pipes, 17, 18, and 19 inches diameter, at Rates from £4 to £10 per Ton. (Calculated to the nearest Penny.)

Diameter in Inches.		17.	40		18.			19.	
Class of Joint.	Open.	T. & B.	Finge	Open.	T. & B.	Finge.	Open.	T. & B.	Fluge.
Weight per yard in lbs.	384	890	387	406	412	409	468	475	472
Cost per yard at  #4 0 0 per ton.  4 2 6  4 5 0 0  4 7 6 0  4 10 0 0  4 12 6  5 0 0 0  5 12 6 0  5 10 0 0  5 12 6 0  5 10 0 0  5 12 6 0  6 17 6 0  6 10 0 0  6 12 6 0  6 15 0 0  7 12 6 0  7 13 6 0  7 14 6 0  8 15 0 0  8 2 6 0  8 17 6 0  8 19 6 0  8 19 6 0  9 2 6 0  9 3 7 6 0  9 7 6 0  9 7 6 0	8. d. 13 8 14 2 2 14 7 7 15 5 15 10 16 8 8 16 9 17 2 2 17 7 18 0 0 19 8 20 7 21 0 0 22 3 22 3 7 24 0 5 24 10 25 8 8 29 2 7 30 0 5 0 80 10 81 8 18 18 18 18 18 18 18 18 18 18 18 1	s. d. 13 11 14 4 15 8 16 16 17 0 18 8 18 9 17 10 18 8 19 2 20 11 21 9 7 20 0 20 11 21 4 22 2 21 9 7 22 2 23 1 24 4 24 10 25 8 26 7 27 10 28 4 28 9 29 2 20 5 20 11 21 26 7 22 27 10 28 4 28 9 29 2 20 5 20 11 21 26 7 22 27 10 28 4 28 9 29 2 20 5 20 11 21 22 22 2 22 27 1 22 26 7 27 10 28 4 28 9 29 2 29 7 20 8 20 8 20 9 20 8 20 9 20 8 20 9 20 9	8. d. 18 10 14 8 15 11 15 6 6 15 11 16 5 16 15 17 8 17 8 18 22 18 7 19 10 20 4 20 9 21 2 22 11 23 4 23 9 24 2 25 6 4 26 11 26 4 26 9 27 22 27 8 28 1 6 28 11 29 4 29 10 30 8 30 8 11 11 52 5 11 12 11 11 11 11 11 11 11 11 11 11 11	8. d. 614 11 16 6 4 16 15 10 16 4 11 17 8 18 17 19 0 19 61 19 11 20 5 20 10 21 4 5 10 22 22 22 22 22 23 1 23 7 24 5 24 11 25 10 26 8 26 9 27 27 8 28 1 1 30 10 31 8 8 2 2 3 1 8 8 2 2 3 1 8 8 3 1 8 8 3 2 2 3 8 3 1 8 8 3 2 2 3 8 3 1 8 8 3 2 2 3 8 3 1 8 8 3 2 2 3 8 3 1 8 8 3 2 2 3 3 3 3 6 0 3 4 4 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	21 7 22 1 22 0 23 5 23 11 24 10 25 3 26 3 26 8 27 2 28 1 29 6 29 5 29 11 30 10	s. d. 14 7 16 1 16 0 16 5 16 11 17 10 18 9 19 8 19 8 19 20 1 20 1 20 1 20 20 1 21 11 22 10 23 1 24 2 25 7 26 6 26 1 27 10 28 9 29 2 24 8 25 7 26 6 27 10 28 8 28 9 29 2 20 1 20 1 21 1 22 1 23 1 24 2 25 7 26 6 26 1 27 10 28 8 28 9 29 2 20 1 20 2 20 1 20 2 20 1 20 2 20 1 20 2 20 2 20 3 20 3 20 3 20 3 20 3 20 3 20 3 20 3 20 3 20 4 20 5 20 6 20 7 20 1 20 1 20 2 20 1 20 2 20 1 20 2 20 2 20 2 20 3 20 3	s. d. 8 17 8 117 8 117 8 117 8 118 8 3 18 10 19 14 119 10 121 5 5 21 11 122 6 6 24 0 7 25 1 11 225 6 1 225 7 226 1 226 8 27 22 28 7 226 1 226 8 27 22 28 7 22 28 7 22 28 7 22 28 7 22 28 7 22 28 7 22 28 7 22 28 7 22 28 7 22 28 7 22 28 7 22 28 7 22 28 7 22 28 7 22 28 7 22 28 7 22 28 7 22 28 7 27 28 8 29 30 10 32 4 11 33 5 6 13 33 11 33 5 6 13 35 6 7 37 7 7 1 38 22 11 33 5 6 13 35 20 35 8 20 35 20	s. d. 11 17 6 18 7 19 1 19 7 20 8 21 9 22 10 22 20 8 21 9 22 20 23 10 22 20 23 10 22 20 23 10 22 20 23 20 20 20 20 20 20 20 20 20 20 20 20 20	8. d. 10 17 5 18 10 17 11 18 5 18 11 19 0 0 20 7 21 1 7 22 8 22 8 22 8 22 8 22 8 22 8 22 8 22
9 10 0 ", 9 12 6 ", 9 16 0 ",	82 7 88 0 88 5	33 1 38 6 38 11	82 10 83 8 83 8	34 5 84 11 85 4	34 11 35 5 35 10	34 8 35 2 35 7	39 8 40 3 40 9	40 8 40 10 41 4	40 0 40 7 41 1
9 17 6 , 10 0 0	88 10 84 8	84 5 84 10	84 1 84 7	35 10 36 8	86 4 86 9	36 1 86 6	41 8 41 9	41 11 42 5	41 7 42 2

TABLE

Giving Weight and Cost per Yard of Cast-Iron Main Gas Pipes, 20, 21, and 22 inches diameter, at Rates from £4 to £10 per Ton. (Calculated to the nearest Penny.)

TABLE

Giving Weight and Cost per Yard of Cast-Iron Main Gas Pipes, 28, 24 and 30 inches diameter, at Rates from £4 to £10 per Ton. (Calculated to the nearest Penny.)

TABLE

Giving Weight and Cost per Yard of Cast-Iron Main Gas Pipes 86, 42, and 48 inches diameter, at Rates from £4 to £10 per Ton. (Calculated to the nearest Penny.)

Diameter in Inches.	T	86.			42.		ı — —	48.	
Class of Joint.	Open.	T. & B. F	Inge.	Open.	T. & B.	Flnge.	Open.	T. & B.	Finge.
Weight per yard in lbs.	1820	1841	1380	1621	1646	1688	1946	1976	1961
Class of Joint.  Weight per yard in lbs.  Cost per yard at 24 0 0 per ton. 4 2 6 " 4 7 6 " 4 10 0 " 4 12 6 " 4 15 0 " 5 0 0 " 5 2 6 " 5 5 0 0 " 5 7 6 " 5 10 0 " 5 12 6 " 5 15 0 " 5 17 6 " 6 0 0 " 6 12 6 " 6 10 0 " 6 12 6 " 6 10 0 " 7 2 6 " 7 10 0 " 7 2 6 " 7 10 0 " 7 12 6 " 7 10 0 " 7 12 6 " 7 15 0 "	<del>  -</del>	T. & B. F 1841 : s. d. s 47 11 4 49 5 4 50 11 5 53 10 5 56 10 5 56 10 5 61 4 6 62 10 6	1880 1. d. 6. 197 0 0 60 50 51 11 151 51 51 51 51 51 51 51 51 51 51 51 51	5. d. 57 11 59 8 61 66 11 68 9 70 77 72 4 77 72 4 77 70 7 78 8 8 8 10 8 8 8 9 9 8 1 1 9 5 11 9 5 11 9 5 11 0 6 9 1 10 6 9 1 10 6 9 1 10 6 11 0	T. & B.  1646  s. d. 58 9 60 7 62 5 64 4 66 2 78 0 69 10 71 8 73 6 73 6 77 2 79 0 80 10 82 8 84 6 88 4 88 2 90 0 91 10 91 10 99 98 8 95 6 97 4 99 2 01 00 60 51 10 61 10 81	8. d. 58 4 60 2 61 11 63 9 65 7 6 69 8 71 1 72 11 72 11 72 11 72 11 72 11 72 11 72 11 9 96 82 0 83 10 85 88 87 6 89 91 11 94 99 96 85 10 05 11 10 05 11 10 05 11 10 05 11 10 10	1946  s. d. 69 6 71 8 73 10 75 11 78 22 80 4 82 6 84 8 86 10 89 1 99 11 104 83 106 5 108 7 110 4 112 11 115 1 1117 31 119 5 122 7 122 70 128 0 128 0 128 0 128 2 1	T. & B.  1976  s. d. 70 7 72 9 75 0 77 2 79 5 81 7 83 10 88 2 90 5 90 7 94 10 97 0 99 3 101 5 108 8 101 5 101 11 121 4 122 4 123 6 112 6 112 6 113 4 134 6 1	s. d. 70 0 72 8 74 5 76 7 78 9 81 0 88 2 4 87 6 89 91 11 94 1 1 96 8 6 8002 10 105 6 118 10 7 118 10 116 0 212 4 7 26 19 12 29 1 28 1 2 2 3 8 4
7 17 6 " 8 0 0 " 8 2 6 " 8 5 0 " 8 10 0 0 " 8 12 6 " 8 15 0 " 9 10 0 " 9 15 0 " 9 17 6 "	97 8 98 91 100 21 101 81 108 11 104 71 106 11 107 71 109 01 110 61 111 111	08 8 102 04 9 103 06 8 105 07 9 106 09 8 109 10 9 109 11 8 9 112 15 8 114 16 9 115 18 8 117	5 01 3 61 7 11 11 9 61 11 12 5 11 12 61 13 11 11 5 61 1 41 1 41 1 41 1 41 1 41 1 7 81	15 9 1 17 7 11 19 5 1: 21 8 1: 22 10 1: 22 6 1: 33 10 1: 22 6 1: 33 10 1: 33 10 1: 33 10 1: 35 8 1: 41 11: 42 11: 11	17 71 19 51 21 81 22 11 24 11 22 91 28 71 28 71 30 51 31 11 35 11 37 91 37 91 41 51 48 81 45 11	16 8 1 18 6 1 20 8 1 22 2 1 1 2 2 2 1 2 2 2 1 2 2 2 7 7 1 2 2 5 5 1 1 3 3 8 1 1 3 4 1 0 1 3 8 6 1 4 0 4 1 4 4 2 2 1 4 4 0 1	39 01 41 21 48 41 45 61 47 81 54 21 56 41 58 71 60 81 62 11 67 81 69 51 71 71	41 21 48 41 45 71 47 91 47 91 49 11 54 41 56 6; 58 91 66 11 68 21 66 7 71 69 91 72 01 74 21	40 1 42 8 44 5 44 6 8 48 10 553 2 555 5 757 9 61 11 64 1 66 6 670 8

Pressure, 1 inch. TABLE showing the Discharges of Gas in Cubic Feet per Hour. Specific Gravity '420. (Clegg, 4th Ed., p. 804

90,564 872,467 211,048 1179,773 118,173 118,173 118,173 118,173 113,847 111,384 11,478 প্ল 285,440 281,220 116,520 116,520 116,520 117,72 ଷ୍ଟ 201,966 1179,925 1187,714 1187 8 150,681 128,774 128,083 128,083 128,083 129,284 12,1948 12,1948 12,1948 12,1948 12,1948 12,1948 12,1948 12,1948 12,1948 12,1948 13,1948 14,194 9 124,982 107,950 88,117 76,204 68,286 68,286 68,181 77,682 86,187 14. DIAMETER OF PIPES IN INCHES. 84,758 73,298 65,703 59,875 51,904 48,879 89,288 89,587 89,288 89,598 89,517 11,528 11,538 11 3 65,475 42,6376 42,6376 42,6376 42,935 82,946 82,946 82,946 82,940 82,730 11,070 11,070 11,070 11,070 11,070 11,070 11,070 11,090 7,080 ö 50,518 41,334 35,757 35,757 32,259 22,259 22,259 22,259 22,259 22,259 22,259 22,259 22,259 22,259 22,259 23,259 23,259 24,259 26 ö 53,808 87,670 90,758 90,758 90,758 18,576 11,898 11,898 11,896 11 ø 98,168 28,969 21,027 119,051 115,096 112,089 112,089 112,089 9,526 9,526 6,416 ۲. 28,965 29,758 11,832 11,832 11,866 11,566 11 ø 21,263 116,867 11,648 11,648 9,260 6,206 6,125 4,725 4,807 4,807 4,807 4,807 8,647 8,647 1,967 ø. 13,160 11,1846 13,846 14,742 14,742 18,844 1 ::: ÷ 7,858 6,941 7,858 9,824 9,824 1,871 1,615 1,143 1,142 1,781 1,781 ထ 2,291 2,149 1,666 1,177 1,177 1,177 1,177 1,177 961 833 745 679 679 679 679 œ Length of of Pipes in Yards.

#### **TABLES**

Of the Discharge of Gas, in Cubic Feet per hour, through Pipes of various Diameters and Lengths at different Pressures.

By Thomas G. Barlow. Extended by Thomas Newbigging.

(The specific gravity of the gas is taken at 0.4, air being 1.)

The tables are calculated according to the formula given by Professor Pole in his valuable article\* "On the Motion of Fluids in Pipes."

Q =quantity of gas in cubic feet per hour.

l = length of pipe in yards.

d = diameter of pipe in inches.

h =pressure in inches of water.

s = specific gravity of gas, air being 1.

$$Q = 1850 \ d^2 \sqrt{\frac{h \ d}{s \ l}}$$

—i.e., multiply the pressure in inches of water by the diameter of the pipe, also in inches. Divide the product by the specific gravity of the gas multiplied by the length of the pipe in yards. Extract the square root of the quotient, which root, multiplied by the constant quantity 1350, and the square of the diameter of the pipe in inches, gives the number of cubic feet discharged in one hour.

Example.—It is required to find the number of cubic feet of gas of the specific gravity of  $\cdot 400$ , which will be discharged in one hour from a pipe 8 inches in diameter, and 1250 yards in length, under a pressure of 15-10ths, or  $1\frac{1}{2}$  inches head of water.

Thus—
$$(h d) = 8 \times 1.5 = 12$$
.

$$\left(\sqrt{\frac{h}{s}}\frac{d}{l} = \frac{12}{4 \times 1250}\right) = .024$$
, the square root being = .1549.

$$\left(1850 \ d^2 \sqrt{\frac{h \ d}{s \ l}}\right) = 1350 \times 64 \times 1549 = 13,383 \text{ cubic feet } = Q.$$

<sup>\*</sup> See "King's Treatise," Vol. II., p. 374, et seq.

## Diameter of Pipe, 0.5 Inch.

Length in yards.	10.	20.	80.	50.	75.	100.	150,
Quantity delivered							
with 01 in. pressure.	87.7	26.7	21.7	16.8	18.8	11.9	9.7
0-22 - ,,	58.4	87.7	80°6	23.8	19.5	16.8	13.8
0.8 ,,	65 · 2	46.8	87.7	29.1	23.8	20.7	16.8
0.4 ,,	75.2	58.8	43.2	83.7	27.5	23.8	19.5
0.5 ,,	84 · 8	59.4	48.6	37.4	80.7	26.7	21.7
0.6 ,,	92.1	65 1	53.3	41.1	83.7	29.0	23.8
0.8 ,,	106.7	75.4	61.4	47.5	88.8	88.7	27.4
1.0 ,,	119.1	84.8	68.8	59.3	43.2	87.7	80.8
1.2 ,,	180.6	92.1	75.2	58.3	47.5	41.1	88.7
1.5 ,,	146.1	108 · 2	84.8	65.1	53.3	45.9	87.8
1.8 ,,	159.9	118.0	92.1	71.5	58.3	50.6	41.1
20 ,,	168.7	119.1	97.2	75.2	61.4	58.8	43.5
2.5 "	188 · 6	138.8	108.6	84.3	68.8	59.4	48.6

#### Diameter of Pipe, 0.75 Inch.

Length in yards.	10.	20.	80.	50.	75.	100.	150.
Quantity delivered							
with 0.1 in. pressure.	104.8	78.8	60.0	46.6	87.9	82.9	26.9
0.2 ,	147.5	104.3	84.9	65.8	58.7	46.6	87.9
0.8 ,,	179.9	126.8	104.8	80.9	65.8	57.0	46.6
0.4 "	207.3	146.5	119.9	98.2	75.9	65.8	53.8
0.5 ,,	282.3	164.0	133.6	103.2	84.2	78.8	60.0
0.6 ,,	254.3	179.9	146.5	113.9	92.6	79.7	65 · 8
0.8 ,,	298.8	207.8	169.8	131.3	107.0	92.6	75 . 9
1.0 "	328.8	282.3	189.8	146.5	119.9	103.2	84.2
1.0 "	359.9	254.3	207.3	160.9	181.8	118.9	92.6
1.6 "	402.4	284.0	282.3	179.9	146.5	126.8	108.2
ī.ē. " I	441.1	811.3	254.8	192.2	160.9	188.9	118.9
6-0 " I	464.7	328.8	268.0	207.8	169.8	146.5	119.9
2.5 ,,	519.4	367.5	299.9	232.2	189.8	164.0	188 • 6

# Diameter of Pipe, 1 Inch.

Length in yards.	10.	20.	80.	50.	75.	100.	150.
Quantity delivered							
with 0.1 in. pressure	214.0	151.0	124.0	95.0	78.0	67.0	55.0
0-2 ,	802.0	214.0	175.0	185.0	110.0	95.0	78.0
0.8 ,,	368 · 5	260 5	214.0	165.0	185.0	117.0	95.0
0.4	426.6	801.0	245.7	190.0	156.0	135.0	110.0
0.5	476.5	887.5	274.0	213.3	172.8	151.0	128.0
0.6	522.4	868 · 5	801.0	233 · 5	190.8	164.7	185.0
0.8 ,,	603 · 4	426.6	348.8	270.0	220.0	190 · 8	155.2
10 ,	675.0	476.5	888.8	301.0	245.7	213.8	172.8
1.2	738 • 4	522.4	426 6	329 · 4	270.0	233 · 5	190.8
1.5 ,,	826 2	584.5	476.5	368.5	301.0	260.5	213.8
1.8 ,,	904.5	639.9	522.4	405.0	329·4	286 · 2	283 · 5
2.0 ,,	954.4	675.0	550.8	426.6	848.8	801.0	245 · 7
2.5 ,,	1,066.5	754.6	615.6	476.5	388·8	337.5	274.0

Diameter	of	Pipe,	1.25	Inches.
----------	----	-------	------	---------

Length in yards.	25.	50.	75.	100.	150.	200.	800.
Quantity delivered							
with 0.1 in. pressure.	286.0	167.0	187 · 0	118.0	96.0	84.0	68.0
0.2 ,,	883.0	286.0	192.0	167.0	187.0	118.0	96.0
0.8 , ,,	407.1	289.0	236.0	205.0	167.0	144.0	118.0
0.4 ","	470.8	833 · 2	272 · 1	236.0	192.0	167.0	187 · C
0.5 ,,	527.8	871.2	803.7	263 · 6	215.1	187.0	152.0
0.6 ,,	575.8	407 · 1	833 • 2	286 · 8	285 · 8	203.9	166 · 6
0.8 ,,	666.5	470.8	863.9	888 • 2	272 · 1	235.8	192.8
10 ,,	744.6	527 · 8	480.3	871.2	808 · 7	268.6	215 · 1
1.2 ,,	816.8	575.8	470.3	407 · 1	888 2	286.8	235 · 8
1.5 ,,	913.8	645.4	527.3	455.6	871.2	822.7	269 · 6
1.8 ,,	999.8	706 • 4	<b>5</b> 75 · 8	499.9	407.1	852.2	<b>286</b> · 8
2.0 ,,	1,054.6	744.6	607 · 5	527.3	480.8	871.2	808 · 7
2.5 ,,	1.179 1	833 • 2	679 2	588.5	480.9	415.5	889 · 6

# Diameter of Pipe, 1.5 Inches.

Length in yards.	25.	50.	75.	100.	150.	200.	800.
Quantity delivered							
with 0.1 in. pressure.	874.0	264.0	215.0	187.0	152.0	132.0	107.0
0.2 ,	528.0	374.0	804.0	264.0	215.0	187.0	152.0
0.8 ,,	643.9	458.0	874.0	322.0	264.0	229.0	187.0
0.4 ,,	741.1	525 4	428 · 2	874.0	804.0	264.0	215.0
0.5 ,,	829 • 2	586.2	479.9	413.1	839.5	295.0	239 · 0
0.6	911.2	643.9	525 4	455.6	870.5	821.9	261 · 2
0.8 ,,	1,050.9	741.1	607.5	525 • 4	428 · 2	870.5	808 · 7
1.0 ,,	1,175.5	829 · 2	677.3	- 686.2	479.9	418.1	339 · 5
1.2 ,,	1,287.9	911.2	741.1	643.9	525 4	455.6	870.5
1.5 ,,	1,439.7	1,017.5	829 · 2	719.8	586.2	507 · 2	418.1
1.8	1,576.4	1,114.7	911.2	789 · 1	648.9	555.8	455.6
2.0 ,,	1,661 5	1,175.5	959.8	829 2	677.3	586.2	479 · 9
2.5 ,,	1,858.9	1,815.2	1,072 · 2	929 · 4	759.8	656.1	584 · 6

# Diameter of Pipe, 2 Inches.

Length in yards.	50.	75.	100.	150.	200.	800.	500.
Quantity delivered							
with 0.1 in. pressure.	5 <b>40</b>	441	381	811	270	i 2220 i	170
0.2	763	628	540	441	881	811	241
03 ,	984	763	665	540	468	881	296
0.4 ,,	1,080	880	761	623	540	441	841
0.5 ,,	1,204	988	858	697	604	492	881
0.6 ` ,,	1.318	1,080	984	761	659	540	416
0.8 ,,	1,523	1,242	1,080	880	761	621	481
1.0 ,,	1,706	1,393	1,204	983	858	697	540
1.2 ,,	1,868	1,523	1,318	1.080	984	761	589
1.5 ,,	2,090	1,706	1,474	1,204	1.042	853	659
1.8 ,,	2,290	1,868	1,620	1,318	1,145	934	724
2∙0 ″,	2,414	1,971	1,706	1,393	1,204	983	761
25 "	2,700	2,208	1,906	1,555	1,850	1,102	858

## Diameter of Pipe, 2.5 Inches.

Length in yards.	50.	75.	100.	150.	200.	800.	500.
Quantity delivered							
with 0.1 in. pressure.	948	770	667	545	471	335	298
0.2 ,	1,835	1,090	943	770	667	545	421
0.8 ,,	1,628	1,335	1,172	943	819	667	516
0.4 ,,	1,882	1,540	1,833	1,090	943	770	596
0.5 ,,	2,109	1,721	1,485	1,215	1,055	861	667
0.6 ,	2,303	1,882	1,628	1,333	1,148	943	731
0.8 ",	2,666	2,177	1,882	1,540	1,333	1,088	844
1.0 ,,	2,978	2,430	2,109	1,721	1,485	1,215	943
1.2 ,,	8,265	2,666	2,303	1,882	1,628	1,833	1,029
1.5	8,653	2,978	2,582	2,109	1,823	1,485	1,148
1.8 ,,	8,999	3,265	2,827	2,308	2,000	1,628	1,266
2.0 ,,	4,219	3,443	2,978	2,490	2,109	1,721	1,883
2-5 ,,	4,717	3,848	3,333	2,717	2,354	1,924	1,485

## Diameter of Pipe, 3 Inches.

Length in yards.	100.	150.	250.	500.	750.	1000.	1250.
Quantity delivered							
with 0.1 in pressure.	1,054	859	666	471	884	888	298
0.2 ,,	1,440	1,214	942	666	543	471	875
0.3 ,,	1,823	1,487	1,158	815	666	576	529
0.4 ,,	2,102	1,713	1,332	942	768	666	596
0.5 %	2,345	1,920	1,482	1,054	859	744	666
0-6 ,,	2,576	2,102	1,628	1,152	942	815	789
0∙8 ,,	2,965	2,480	1,882	1.824	1,081	942	845
1.0 %	8,317	2,709	2,102	1,482	1,215	1.052	942
1.2 "	8,645	2,965	2,296	1,628	1,324	1,152	1,030
1.5 ,,	4,070	8,317	2,576	1,823	1,482	1,288	1,152
1.8 ,,	4,459	3,645	2,819	1,993	1,628	1,409	1,262
2.0 ,,	4.702	8,839	2,965	2,102	1,713	1,482	1,824
2.5 ,,	5,261	4,289	8,817	2,345	1,920	1,652	1,482

## Diameter of Pipe, 4 Inches.

Length in yards.	100.	250.	500.	750.	1000.	1250.	1500.
Quantity delivered							
with 0.1 in pressure.	2,160	1,366	966	788	683	611	557
0.2 ,,	8.054	1,932	1,366	1,114	966	864	788
0.8 ,,	8,787	2,366	1,673	1,866	1,183	1,058	966
0.4 ,,	4,820	2,722	1,982	1,576	1,366	1,222	1,114
0.5 ,,	4,817	8,046	2,160	1,761	1,526	1,366	1,245
0.6 ,,	5,270	8,346	2,354	1,932	1,672	1,496	1,366
0.8 ,,	6,091	8,845	2,722	2,225	1,932	1,728	1,576
1.0 %	6,826	4,820	3,046	2,484	2,160	1,982	1,761
1.2	7,474	4,730	3,346	2,722	2,354	2,115	1,922
1.5 ,,	8,359	5,270	8,787	3,046	2,635	2,354	2,160
1.8 "	9,158	5,789	4,082	3,346	2,894	2,592	2,354
2.0 "	9,655	6,091	4,320	8,521	3,046	2,722	2,484
2.5 "	10,800	6,826	4,817	8,981	3,413	8,046	2,786

## Diameter of Pipe, 5 Inches.

Length in yards.	100.	250.	500.	750.	1000.	1250.	1500.
Quantity delivered							
with 0-1 in. pressure.	3,540	2,245	1,587	1,296	1,122	1,000	910
0-2 - ,,	5,005	8,174	2,245	1,832	1,587	1,414	1,296
0.8 ,,	6,514	8,888	2,748	2,245	1,948	1,732	1,575
04 ,,	7,526	4,759	8,174	2,592	2,245	2,000	1,820
0.5 ,,	8,438	5,338	8,778	2,888	2,508	2,236	1,984
0.6 ,,	9,214	5,839	4,118	8,174	2,748	2,449	2,245
0.8 ,,	10,665	6,750	4,759	3,881	8,174	2,828	2,596
1.0 ,,	11,914	7,526	5,333	4,354	8,778	8,174	2,877
1.2 ,,	18,061	8,235	5,839	4,759	4,118	8,679	8,375
1.5 ,,	14,614	9,214	6.514	5,338	4,590	4,118	8,540
1.8 ,,	15,998	10,125	7,156	5,839	5,068	4,528	4,118
2.0 ,,	16,875	10,665	7,526	6,143	5,333	4,759	4,354
2.5 ,,	18,866	11,914	8,438	6,885	5,940	5,883	4,860

#### Diameter of Pipe, 6 Inches.

Length in yards.	250.	500.	750.	1000.	1250.	1500.	1750.
Quantity delivered							
with 0.1 in. pressure.	8,770	2,660	2,170	1,880	1,680	1,580	1,420
0·2 <sup>-</sup> ,,	5,820	3,770	8,180	2,660	2,870	2,170	2,010
0.8 ,,	6,580	4,620	8,770	8,270	2,920	2,660	2,460
0.4 ,,	7,540	5,320	4,340	3,770	3,860	3,060	2,840
0.5 ,,	8,408	5,970	4,860	4,210	8,770	8,430	3,180
0.6 ,,	9,185	6,512	5,320	4,620	4,130	8,770	8,460
0.8 ,,	10,648	7,528	6,124	5,320	4,740	4,340	4,020
1.0 ,,	11,858	8,408	6,858	5,929	5,320	4,860	4,500
1.2 ,,	13,025	9,185	7,528	6,512	5,832	5,297	4,929
1.5 ,,	14,580	10,803	8,408	7,290	6,512	5,970	5,500
1.8 ,,	15,941	11,275	9,185	7,970	7,139	6,512	6,026
2.0 ,,	16,816	11,858	9,720	8,408	7,528	6,853	6,360
2.5 ,,	18,808	13,268	10,838	9,380	8,408	7.679	7,096

# Diameter of Pipe, 7 Inches.

Length in yards.	250.	500.	750.	1000.	1250.	1500.	1750.
Quantity delivered				1		1	
with 0.1 in. pressure.	5,560	8,920	3,200	2,780	2,470	2,270	2,100
0.2 ,,	7,840	5,560	4,510	3,920	3,500	3,200	2,960
0.8 ,,	9,600	6,800	5,560	4,800	4,300	3,920	3,640
0.4 ,,	11,120	7,840	6,400	5,560	4,940	4,540	4,200
0.5 ,,	12,870	8,750	7,180	6,200	5,560	5,060	4,680
0.6	18,554	9,585	7,840	6,800	6,080	5,560	5,180
0.8 ,,	15,611	11,047	8,996	7,840	7,020	6,400	5,930
1.0 ,,	17,468	12,370	10,054	8,732	7,840	7,180	6,610
1.2	19,170	18,554	11,047	9,585	8,533	7,805	7,210
1.5	21,433	15,148	12,370	10,716	9,585	8,750	8,120
1.8 ,,	23,477	16,597	13,554	11,709	10,452	9,855	8,864
<b>2</b> ·0 ,,	24,740	17,463	14,288	12,370	11,047	10,054	9,860
2.5 ,,	27,651	19,567	15,942	13,825	12,870	11,292	10,452

## Diameter of Pipe, 8 Inches.

Length in yards.	250.	500.	750.	1000.	1250.	1500.	1750.
Quantity delivered with 0.1 in. pressure.	7,760	5,470	4,470	8,880	3,460	8,160	2,920
0.2 - ,,	10,940	7,760	6,810	5,470	4,880	4,470	4,180
0·8 ,, 0·4 ,,	18,400 15,520	9,450 10,940	7,760 8,940	6,700 7,760	5,980 6,920	5,470 6,820	5,050 5,840
0·5 ,, 0·6 ,,	17,280 18,922	12,200 13,383	9,900	8,640 9,450	7,760 8,480	7,020 7,760	6,520 7,150
0.8 ,,	21,851 24,865	15,379 17,280	12,614 14,083	10,940 12,162	9,780 10,940	8,940 9,900	8,260 9,287
1.2 " 1.5 "	26,767 29,894	18,922 21,082	15,379	13,383	11,923	10,886	10,109
1.8 ,,	82,746	23,155	18,922	16,330	14,602	13,388	11,800 12,35 <b>5</b>
2·0 ,, 2·5 ,,	84,560 88,621	24,365 27,302	19,872 22,291	17,280 19,267	15,379 17,280	14,088 15,725	18,040 14,602

#### Diameter of Pipe, 9 Inches.

Length in yards.	250.	500.	750.	1000.	1250.	1500.	1750.
Quantity delivered							
with 0.1 in. pressure.	10,400	7,380	6,850	5,200	4,650	4,250	8,950
0.2 ,,	14,760	10,400	8,500	7,380	6,480	6,000	5,620
0-8 ,,	18,000	12,780	10,400	9,000	8,800	7,380	6,800
0.4 ,,	20,800	14,760	12,700	10,400	9,300	8,500	7,900
0.5 ,,	23,182	16,500	13,420	11,900	10,400	9,680	8,800
0-6 ,,	25,369	17,933	14,760	12,780	11,400	10,400	9,650
0.8 ,,	29,806	20,667	16,988	14,760	13,100	12,000	11,050
1.0 ,,	82,805	23,182	18,918	16,408	14,760	13,420	12,380
1.2 ,,	85,867	25,369	20,667	17,983	16,064	14,658	18,559
1.5 ,,	40,181	28,409	23,182	20,011	17,933	16,500	15,200
1.8 ,,	48,959	81,055	25,369	21,979	19,683	17,933	16,621
2.0 ,,	46,364	82,805	26,681	23,182	20,667	18,918	17,600
2.5 ,,	51,882	86,632	29,858	25,916	23,182	21,105	19,574

## Diameter of Pipe, 10 Inches.

Length in yards.	500.	750.	1000.	1250.	1500.	1750.	2000.
Quantity delivered							
with 0.1 in. pressure.	9,560	7,800	6,750	6.050	5,520	5,100	4,780
0.2 - ,,	13,500	11,040	9,560	8,520	7,800	7,800	6,750
0.8 ;;	16,500	13,500	11,700	10,520	9,560	8,850	8,259
0.4 ,,	19,120	15,600	13,500	12,100	11,040	10,200	9,560
0.5 ,,	21,300	17,400	15,050	13,500	12,380	11,400	10,650
0.6 ;;	28,355	19,120	16,500	14.800	13,500	12,500	11,650
0.8 ;;	27,000	22,005	19,120	17,050	15,600	14,400	13,500
1.0 ,,	30,105	24,570	21,330	19,120	17,400	16,150	15,050
1.2 ,,	82,940	27,000	23,855	20,911	19,035	17,550	16,578
1.5 ,,	36,855	80,105	26,055	23,355	21,300	19,600	18,500
1.8 ,,	40,500	32,940	28,620	25,515	28,855	21,600	20,250
2.0 ,,	42,660	34,830	80,105	27,000	24,570	22,800	21,300
2.5 ,,	47,655	38,880	33,750	30,105	27,540	25,501	28,760

# Diameter of Pipe, 12 Inches.

Length in yards.	500.	750.	1000.	1250.	1500.	1750.	2000.
Quantity delivered							
with 0.1 in. pressure.	15,100	12,800	10,700	9,550	8,700	8,050	7,550
0.2 ,,	21,400	17,400	15,100	18,450	12,800	11,850	10,700
0.8 ,,	26,100	21,400	19,500	16,500	15,100	18,880	18,050
0.4 ,,	80,200	24,600	21,400	19,100	17,400	16,100	15,100
0.2	88,600	27,500	23,800	21,400	19,440	18,050	16,800
0.6 ;,	86,741	80,200	26,100	28,800	21,400	19,800	19,500
0.8 ;,	42,578	34,603	30,200	26,900	24,600	22,700	21,400
10 ,,	47,488	38,880	83,631	80,200	27,500	25,450	28,800
1.2 ,,	52,099	42,578	86,741	82,858	80,112	27,799	26,049
1.5 ,,	58,320	47,433	41,212	86,741	88,600	81,250	29,250
ī·8 ,,	63,763	52,099	45,100	40,896	86,741	84,020	31,881
2.0	67,262	54,820	47,483	42,578	38,880	86,100	83,600
2.5	75,232	61,430	53,071	47,488	48,851	40,240	37,519

# Diameter of Pipe, 14 Inches.

Length in yards.	500.	750.	1000.	1250.	1500.	1750.	2000.
Quantity delivered.							
with 0.1 in. pressure.	22,100	18,100	15,600	13,950	12,750	11,800	11,050
0.2 ,,	31,200	25,500	22,100	19,800	18,100	16,700	15,600
0.3 ,,	38,400	81,200	27,100	24,250	22,100	20,500	19.200
0.4 ,,	44,200	36,200	31,200	27,900	25,500	23,600	22,100
0.5 ,,	49,400	40,400	35,000	31,200	28,500	26,460	24,700
رُ <b>ن</b> 0·6	54,216	44,200	38,400	84,300	31,200	28,900	27,100
0.8	62,445	51,067	44,200	39,600	36,200	33,400	31,200
1.0 ,,	69.854	57,153	49,480	44,200	40,400	87,300	85,000
1.2 ,,	76,681	62,445	54,216	48,421	44,188	40,986	38,340
1.5 ,,	85,730	69,854	60,593	54,216	49,400	45,700	42,600
1.8 ,,	93,906	76,681	66,414	59,270	54.216	50,009	46,834
2.0 ,,	98,960	80,703	69,854	62,445	57,153	52,920	49,400
2.5 ,,	110,602	90,228	78,268	69.854	63,768	59,005	55,301

## Diameter of Pipe, 15 Inches.

Length in yards.	500.	750.	1000.	1250.	1500.	1750.	2000.
Quantity delivered.							
with 0.1 in. pressure.	26,300	21,400	18,600	16,600	15,200	14,000	13,150
0.2 ,	37,200	30,400	26,300	23,500	21,400	19,900	18,600
0.8 ,,	45,500	37,200	32,250	28,750	26,300	24,300	22,750
0.4	52,600	42,800	37,200	33,200	80,400	28,000	26.300
0.5 ,,	58,700	48,000	41,600	37,200	34,000	31,400	29,350
0.6 ,,	64,395	52,600	45,500	40,700	37,200	84,450	82,250
0.8 ,,	74,115	60,750	52,600	47,000	42,800	39,800	37:200
1.0 ,,	82,923	67,736	58,623	52,600	48,000	44,400	41,600
1.2 ,,	91,125	74,115	64,395	57,408	52,548	48,600	45.562
1.5 ,,	101,756	82,923	71,983	64,895	58,700	54,300	50,800
1.8 ,	111,476	91,125	78,914	70,470	64,395	59,535	55,586
2.0 ,,	117,551	95,985	82,923	74,115	67,736	62,800	58,700
2.5 ,,	131,523	107,223	92,947	82,923	75,937	70,166	65,610

#### Diameter of Pips, 16 Inches.

Length in yards.	500.	750.	1000.	1250.	1500.	1750.	2000.
Quantity delivered.							
with 0.1 in. pressure.	81,000	25,250	21,850	19,550	17,850	16,550	15,500
0-2 ,,	43,700	85,700	31,000	27,700	25,250	23,400	21,850
0.8 ,,	53,600	43,700	88,100	84,000	31,000	28,700	26,800
0.4	62,000	50,500	43,700	39,100	35,700	33,100	31,000
0.5	69,120	56,600	49,000	49,700	39,900	37,150	34,560
0.6 ,,	75,686	62,000	53,600	47,900	48,700	38,100	40,700
0.8 ,,	87,402	71,198	62,000	55,400	50,500	46,800	43,700
1.0 ,,	97,459	79,488	69,120	62,000	56,600	52,400	49,000
1.2 ,,	107,066	87,402	75,686	67,703	61,516	57,024	53,533
1.5 ,,	119,577	97,459	84,326	75,686	69,120	63,900	60,100
1.8 "	130,982	107,066	92,620	82,944	75,686	70,087	65,318
20 ,,	138,240	112,665	97,459	87,402	79,488	74,300	69,120
2.5 ,,	154,483	126,144	109,209	97,459	89,164	82,598	77,068

## Diameter of Pipe, 18 Inches.

Length in yards.	500.	750.	1000.	1500.	2000.	2500.	8000.
Quantity delivered							
with 0.1 in. pressure.	41,400	83,800	29,400	23,900	20,700	18,400	16,900
0.2	58,800	47,800	41,400	88,800	29,400	26,200	23,900
0.8	71,800	58,800	50,800	41,400	85,900	32,100	29,400
0.4 ,,	82,800	67,600	58,800	47,800	41,400	86,800	33,800
0.5 ,,	92,600	75,700	65,600	58,500	46,300	41,400	37,850
0.6 ,,	101,476	82,800	71,800	58,800	50,800	45,400	41,400
0.8 ,,	117,223	95,790	82,800	67,600	58,800	52,300	47,800
1.0 ,,	131,220	106,725	92,728	75,700	65,600	58,800	53,500
1.2 ,,	143,467	117,223	101,476	82,668	71.733	64.254	58,611
1.5 ,,	161,400	131,220	113,636	92,728	80,000	71,800	65,600
1.8 ,,	175,834	143,467	124.221	101.476	87,917	78,732	71,733
2.0 ,,	185,457	151,340	131,220	106,725	92,728	82,800	75,700
2.5 ,,	207,327	169,273	146,529	119,410	103,663	92,728	84,500

#### Diameter of Pipe, 20 Inches.

Length in yards.	500.	750.	1000.	1500.	2000.	2500.	8000.
Quantity delivered	71.000	44.000	00.020	01.000	25.000	24 222	22.000
with 0.1 in. pressure.	54,000 76,500	44,000 62,400	88,250 54,000	31,200 44,000	27,000 38,250	24,200 34,200	22,000 81,200
0.8 ,,	93,500	76,500	66,100	54,000	46,750	41,800	38,250
0.4 ,,	108,000	88,000	76,500	62,400	54,000	48,400	44,000
0.5 ,,	120,500	98,800	85,300	69,800	62,250	54,000	49,400
0.6 ,,	131,760	108,000	93,500	76,500	66,100	59,100	54,000
0.8 ,,	152,280	124,200	108,000	88,000	76,500	68,400	62,400
1.0 ,,	170,640	139,320	120,420	98,800	85,300	76,500	69,800
1.2 ,,	186,840	152,280	131,760	108,000	93,420	83,646	76,140
1.5 ,,	208,980	170,640	147,420	120,420	102,300	93,5CO	85,300
1.8 ,,	228,960	186,840	162,000	131,760	114,480	102,060	93,420
2.0 ,,	241,380	197,100	170,640	189,320	120,420	108,000	98,800
2.5 ,,	270,000	220,320	190,620	155,520	135,000	120,420	110,200

#### Diameter of Pipe, 22 Inches.

Length in yards.	500.	750.	1000.	1500.	2000.	2500.	8000.
Quantity delivered with 01 in. pressure.  02	68,600 96,800 118,800 137,200 153,500 168,577 193,406 216,275 237,184 265,280 290,697 306,444 342,381	56,000 79,200 96,800 112,000 122,500 158,122 176,418 193,406 216,275 237,184 249,598 279,655	48,400 68,600 84,000 96,800 108,200 118,800 137,200 152,895 168,577 187,525 203,860 216,275 242,280	39,600 56,000 68,600 79,200 88,600 96,800 112,000 122,500 136,560 152,895 168,577 176,418 197,326	34,300 48,000 59,400 68,600 76,800 84,000 96,800 108,200 118,265 132,000 145,054 152,895 171,190	30,700 43,400 53,300 61,400 68,400 75,000 86,500 105,850 118,800 130,026 137,200 152,895	28,000 39,600 48,400 56,000 61,200 68,600 79,200 88,600 96,703 108,200 118,265 122,500

# Diameter of Pipe, 24 Inches.

Quantity delivered with 0.1 in. pressure.		500.	750.	1000.	1500.	2000.	2500.	3000.
		01.000	20.200		12 144	VII. 222		
0.0	Messure.	84,000	68,600	59,500	48,500	42,000	37,500	34,300
0.2	99	119,000	97,000	84,000	68,600	59,500	53,400	48,500
0.3	11	145,500	119,000	103,000	84,000	72,700	65,200	59,500
0.4	33	168,000	137,200	119,000	97.000	84,000	75,000	68,600
0.5	27	187,500	155,000	135,600	108,600	93,800	84,000	77,500
0.6	27	208,396	168,000	145,000	119,000	103,000	92,000	84,000
0.8	27	240,900	196,655	168,000	137,200	119,000	106,000	97,000
1.0	12	269,049	219,283	189,734	155,000	135,600	119,000	108,600
1.2		294,710	240,900	208,396	170,294	146,966	131.414	
1.5	25	329,702	269,049	233,280	189,734			120,450
1.8	73	360,806	294,710	255,052		163,000	145,500	135,600
2.0	55				208,396	180,403	161,585	146,966
	27	380,946	311,040	269,049	219,283	189,734	168,000	155,000
2.5	11	425,347	347,587	300,931	245,721	212,284	189,734	172,000

## Diameter of Pipe, 26 Inches.

Length in yards.	750.	1000.	1500.	2000.	2500.	3000.	4000.
Quantity delivered	Turb to					1	
with 0.1 in. pressure.	85,000	73,500	60,000	52,000	46,500	42,500	36,750
0.2	120,000	104,000	85,000	73,500	65,800	60,000	52,000
0.8	147,000	127,000	104,0 0	90,000	80,600	73,500	63,500
0.4	170,000	147,000	120,000	104,000	93,000	85,000	73,500
0.5	189,000	165,000	134,000	116,000	104,000	94,500	82,500
0.6	208,000	180,000	147,000	127,000	114,000	104,000	90,000
0.8	240,013	208,000	170,000	147,000	132,000	120,000	104,000
1.0 "	268,304	232,621	189,000	165,000	147,000	134,000	116,000
1.2 "	293,857	254,615	208,072	179,782	160,617	146,928	126,851
1.5	328,536	284,731	232,621	201,000	180,000	165,000	142,000
18 ,,	360,385	312,109	254,615	220,666	197,121	179,782	156,054
2.0	879,641	328,536	268,304	232,621	208,000	189,000	165,000
2.5	424,359	367,777	300,245	260,091	232,621	213,000	184,000
3.0 ,,	465,334	402,456	328,536	284,731	254,615	232,621	201,000

#### Diameter of Pipe, 28 Inches.

Length in yards.	1000.	1500.	2000.	2500.	8000.	4000.	5000.
Quantity delivered							
with 0.5 in. pressure.	198,000	161,000	140,000	125,000	114,500	99,000	88,600
0.6 ,	216,866	176,752	153,362	136.533	124.891	107,956	96,314
0.8 ,,	249,782	204,271	176,752	157,701	143,942	124,891	111,978
10 ",	280,000	229,000	198,000	177,000	161,000	140,000	125,000
1·2 ,,	806,724	249,782	216,866	193,687	176,752	153,362	136,538
15 "	842,921	280,000	241,000	216,000	198,000	171,000	153,500
1.8 "	375,626	306,724	265,658	237.081	216.866	187,336	167,227
20 ,,	895,841	322,812	280,000	250,000	229,000	198,000	177,200
2.5 ,,	442,411	360,914	313,074	280,000	255,000	222,000	198,000
3.0 "	484,747	895,841	342,921	306,724	280,000	241,000	216,000

#### Diameter of Pipe, 80 Inches.

Length in yards.	1000.	2000.	3000.	4000.	5000.	7500.	10000.
Quantity delivered							
with 0.5 in. pressure.	234,000	166,000	135,000	117,000	105,000	86,000	74,500
0.6	257,580	182,250	148,230	128,790	115,182	94,041	81,405
0.8 ,,	296,460	210,195	171,315	148,230	182,435	108,185	94,041
1.0 ,,	832,000	234,000	192,000	166,000	149,000	121,500	105,000
1.2 ,,	364,500	257,580	210,195	182,250	162,810	132,435	115,182
1.5 ,,	407.025	287,000	234,000	203,000	182,000	149,000	128,500
1.8 ,,	445,905	315,657	257,580	222,345	199,260	162,810	140,940
20 ,,	470,205	381,695	270,000	284,000	210,000	172,000	149,000
2.5	526,095	371,790	303,750	263,000	234,000	192,000	166,000
<b>3</b> ·0 ,,	575,910	407,025	831,695	287,955	257,000	210,000	182,000
40 ,,	664,605	470,205	383,940	331,695	298,000	243,000	210,000

#### Diameter of Pipe, 36 Inches.

Length in yards.	1000.	2000.	8000.	4000.	5000.	7500.	10000.	
Quantity delivered								
with 0.5 in. pressure.	870.915	262,440	218,451	185,457	165,862	135,419	117,223	
06 ,	405,907	286,934	234,446	202,953	181,783	148,366	127,720	
0.8 ,,	468,892	330,674	271,013	234,446	209,952	171,285	148,366	
10 "	580,000	370,000	303,000	265,000	234,000	192,000	166,000	
1.2 ,,	573,868		330,674	286,934	257,016	209,952	181,783	
1.5 ,,	642,103	456,000	372,000	322,000	288,000	234,900	204,000	
1.8 ,,	703,339	496,886	405,907	351,669	314,928	257,016	222,199	
20 ,	741,830		428,000	872,000	332,000	271,000	234 000	
2.5 ,,	829,310	586,116	477,640	416,000	372,000	303,000	265,000	
3·0 <b>"</b>	908,042	642,103	524,880	454,546	407,000	332,000	288,000	
4·0 ,,	1,049,760	742,130	605,361	524,880	468,892	884,000	332,000	

The foregoing tables are calculated upon the basis of the specific gravity of the gas being ·400. The quantity of gas of any other specific gravity discharged may be ascertained by multiplying the quantity indicated in the table by ·6325 (the square root of ·400), and dividing by the square root of the specific gravity of the other gas.

Example.—If a 12-inch pipe, 1000 yards long, discharges 23,800 cubic feet of gas per hour, specific gravity '400 at '5 in. pressure, how much gas will the same pipe discharge, at the same pressure, when the specific gravity is '560?

$$\frac{28,800 \times .6825}{.7488} = 20,116$$
 cubic feet.

The quantity of gas discharged at any other pressure may be ascertained by multiplying the quantity indicated in the table by the square root of the new pressure, and dividing by the square root of the original pressure.

EXAMPLE.—If a quantity of gas equal to 23,855 cubic feet is discharged in one hour at a pressure of 1.2 inches, what quantity will be discharged through the same pipe at 2.2 inches pressure?

$$\frac{28,855 \times 1.4892}{1.0954} = 81,623 \text{ cubic feet.}$$

To facilitate these calculations, tables are annexed of the square roots of specific gravities from .850 to .700, rising .005 at a time; and of the square roots of pressures from 1-10th of an inch to 4 inches, rising 1-10th at a time.

TABLE.

Square Root of the Specific Gravity of Gas from .850 to .700.

Specific Gravity.	Square Root.	Specific Gravity.	Square Root.	Specific Gravity.	Square Root.	Specific Gravity.	Square Root.	Specific Gravity.	
*850 *855	·5916 ·5968	·425 ·430	·6519 ·6557	·495 ·500	·7085 ·7071	*565 *570	·7517 •7549	·685 ·640	·7969 ·8000
·860	.6000	435	6595	-505	·7106	-575	.7588	645	8081
.865	.6041	•440	•6688	.510	.7141	.580	.7616	-650	·8062
•370	.6088	•445	6671	.515	.7176	.585	·7648	-655	·8098
·875	6124	•450	·6708	.520	.7212	.590	·7681	.660	·8124
.880	•6164	•455	6745	.525	·7246	-595	•7718	•665	·8155
· <b>38</b> 5	•6205	•460	•6782	•580	•7280	.600	·7746	·670	·8185
·890	•6245	·465	·6819	•535	·7814	•605	•7778	•675	.8216
•395	·6285	·470	6856	•540	.7348	•610	.7810	.680	*8246
· <b>4</b> 00	•6325	475	•6892	.545	.7382	•615	·7842	·685	·8276
· <b>4</b> 05	•6864	•480	6928	•550	.7416	·620	·7874	.690	*8306
·410	•6408	•485	·6964	•555	•7449	·625	·7905	•695	•8387
·415 ·420	·6442 ·6481	•490	·7000	•560	·7483	-680	·7987	•700	·8 <b>3</b> 67

TABLE.

Square Root of Pressures, rising by Tenths of an Inch, from One-Tenth to Four Inches.

Inches and	Square	Inches and	Square	Inches and	Square
Tenths.	Root.	Tenths.	Root.	Tenths.	Root.
1-10th. 2-10ths. 8 " 4 " 5 " 6 " 7 " 8 " 9 " 1 inch. 1-1-10th. 1-2-10ths. 1-3 "	*3162 *4472 *5477 *6324 *7071 *7745 *8866 *8944 *9487 1:0000 1:0488 1:0954 1:1401 1:1882	1·5-10ths. 1·6 " 1·7 " 1·8 " 1·9 " 2 inches. 2·1-10th. 2·2-10ths. 2·8 " 2·4 " 2·5 " 2·6 " 2·7 "	1·2251 1·2649 1·3038 1·3416 1·3784 1·4142 1·4491 1·4832 1·5165 1·5491 1·5811 1·6123 1·6431	2·8·10ths. 2·9 ", 3 inches. 3·1·10th. 3·2·10ths. 8·8 ", 3·5 ", 3·6 ", 3·7 ", 3·8 ", 3·9 ", 4 inches.	1·6783 1·7029 1·7820 1·7866 1·7888 1·8165 1·8439 1·8978 1·9938 1·9498 1·9748 2·0000

Should it be required to find the pressure in inches of water to discharge a certain quantity of gas of given specific gravity in an hour, through a pipe the dimensions of which are known, the formula is—

$$h = \frac{Q^2 \ s \ l}{(1350)^2 \ d^5}$$

i.e., multiply the square of the number of cubic feet of gas to be discharged in one hour by the specific gravity of the gas, and by the length of the pipe in yards; divide the product by the square of the constant number 1350, multiplied by the diameter in inches raised to the fifth power, and the quotient is the pressure.

EXAMPLE.—It is required to find the pressure in inches of water to discharge in an hour 12,000 cubic feet of gas, specific gravity .5, through a pipe 8 inches in diameter and 1900 yards long. Then,—

$$\frac{\mathbf{Q^2 \times s \times l}}{1350^2 \times d^5} = \frac{\mathbf{144,000,000 \times \cdot 5 \times 1900}}{\mathbf{1,822,500 \times 32,768}} \times \frac{\mathbf{136,800,000,000}}{\mathbf{59,719,680,000}} = \left\{ \begin{array}{l} \mathbf{2.8 \ ins.} \\ \mathbf{nearly.} \end{array} \right.$$

If the diameter of a pipe is required which will discharge a given quantity of gas under a given pressure, we have the formula—

$$d = \sqrt[8]{\frac{Q^2 s l}{(1350)^3 h}}$$

This can easily be calculated by a table of logarithms—thus,—  $\log d = \frac{1}{8} (2 \log Q + \log s + \log l - 2 \log 1850 + \log h)$  Example.—It is required to find the diameter of a pipe 1240 yards long, to discharge 48,000 cubic feet of gas, of the specific gravity 4, in one hour, with a pressure of 2 inches. Then,—

Therefore d = 13 inches, nearly.

The following axioms are worth remembering:-

1. The discharge of gas will be doubled when the length of the pipe is only one-fourth of any of the lengths given in the tables.

2. The discharge of gas will be only one-half when the length of the pipe is four times greater than the lengths given in the tables.

3. The discharge of gas will be doubled by the application of four times the pressure.

Handy Rule for jinding (approximately) the Content of a Pipe in Gallons and Cubic Feet.

Rule.—Multiply the square of the diameter of the pipe in inches by the length in yards, and divide by 10 for gallons, and by 60 for cubic feet.

Example.—A pipe is 6 in. diameter and 400 yards long, what is the content? then—

$$6^2 \times 400 \div 10 = 1440$$
 gallons.  
 $\div 60 = 240$  cubic feet.

### SERVICE-PIPES AND FITTINGS.

In the term service-pipes are included all pipes branching out of the mains to consumers' meters, and for the supply of public and private lamps.

Leakage or unaccounted for gas is due more to defects in servicepipes than to all the other causes combined. The leaks are chiefly caused in the pipe by corrosion, or at its junction with the main. Such being the case, it is clear that the utmost care should be devoted to the habilitation and maintenance of this portion of the distributory plant.

Service-pipes are of cast-iron, wrought-iron, and lead. The use of cast-iron pipes for this purpose is, as a general rule, confined to the supply of gas to large establishments, where the diameter of the pipe required exceeds 2 inches. The smaller sizes are too fragile to bear the overhead traffic, and the number of joints is objectionable. Such services as are of less bore than 3 inches are usually of wrought-iron, or lead.

Wrought-iron pipes or tubes are chiefly employed for services. They can be obtained of any convenient length, and are easily and expeditiously fixed.

Wrought-iron tubes and fittings, such as tees, bends, elbows, ferrules, sockets, &c., should be perfectly cylindrical, with no ribs or flat places, and internally as smooth as possible. The welding should be scarcely discernible from the other parts, and the screw should be equally deep throughout the thread.

In laying wrought-iron pipes, the coupling or socket at the end, and which is supplied along with the pipe, should always be removed, the thread painted with red or white lead paint, and then replaced.

Lead pipes have their advantages, though they require more care in laying; and to prevent their sagging in the ground, wood lags have to be placed underneath them throughout their length.

On the other hand, they can be laid with fewer joints; the only jointing places being the connections with the main and the meter, unless the premises to be supplied is beyond the ordinary distance from the main. When taken up, also, to be renewed, the old metal is of more value than old iron.

All service-pipes, whether of wrought-iron or lead, when laid in the ground, should be protected from the oxidizing influences of the soil, moisture, and air, by being encased in a  $\sqcup$ -shaped or V-shaped channel of wood or other material, filled, after the pipe has been laid therein, with a mixture of hot pitch and tar. This prolongs their life-

indefinitely, and prevents leakage, and consequently is well worth the trifling extra cost and trouble entailed.

It is not possible always to see whether a wrought-iron service-pipe is worn out or not, unless it is taken up out of the ground. The under part of the pipe will often be found completely oxidized, when the upper surface is sound and good. The rust forms a shell which crumbles on being disturbed, but when untouched is sufficient to prevent the immediate escape of gas.

The tinning or galvanizing of the surface of wrought-iron pipes adds greatly to their durability in sandy soil impregnated with saline matter.

Various processes have been devised for covering iron with a thin layer of oxide to protect it from corrosion either in the soil or when exposed to the atmosphere, and they are peculiarly valuable when applied to wrought-iron tubes and fittings.

Mains should be drilled, not cut with a chisel, for the insertion of service-pipes. The full sectional thickness of the metal is thus preserved, and the hole is a true circle in form.

Several makers supply drilling apparatus which secures immunity from leakage in attaching the service-pipe to the main; and it is easily applied and used.

All service-pipes should, if possible, be laid with a slight fall to the main to admit of the condensed moisture draining away thereto. When the pipe is of great length, and a continuous inclination to the main is impracticable, a small drip-well, commonly called a bottle-syphon (Fig. 30 on page 249) should be attached at the lowest point.

The service-cleansers of D. Hulett and Co. (Fig. 120), of W. & B.



Fig. 120.

Cowan (Fig. 121), and of Hutchinson Bros. (Fig. 122), are exceedingly useful for removing water and other obstructions from service-pipes.


All abrupt angles, such as square elbows, whether in mains, services, or internal fittings, owing to the resistance they offer to the regular and even flow of the gas, act as condensers, and diminish the available pressure. Their use should, therefore, be discarded wherever practicable; bends or round elbows being much more

preferable. For the same reason the internal surface of pipes should be as smooth as possible. No pipe should be put in use without careful examination and the removal of all existing roughnesses. 2-inch cast-iron pipes as mains,

1-inch wrought-iron pipes as services, and

1-inch lead or composition pipes for internal supply, should be utterly abandoned.

The first are a grievous source of direct leakage, owing to breakages at their junction with the service-pipes; the whole three, if used to



any great extent, entail high initial pressure, which is synonymous with a heavy leakage account.

If the distance from the main to the meter does not exceed 80 yards, the following sizes of service-pipes will supply the number of lights named:—

Wronght-iron

1	to	10	lights	(consuming s	ay 4 c. ft. p	er hour each)		Tube. ‡ inch.
11	,,	80	,,	,,	,,	1,		1 ,,
81	,,	60	,,	,,	,,	"	•	1 <del>1</del> ,,
61	,,	120	,,	••	,,	,,		1½ ,,
121	,,	200	,,	,,	,,	,,	•	2,,

The above sizes allow for partial contraction of the area of the pipe by corrosion or deposition.

TABLE.

# Weight per Foot of Wrought-Iron Tubing For Gas, Water, and Steam.

G.	<b>A8.</b>		w	ATER.		STEAM.				
Internal Diameter.	We per l	ight Foot.	Internal Diameter.		ight Foot.	Internal Diameter.	Weight per Foot.			
Inches.  1 1 1 2 2 2 2 1	Lbs. 0 1 1 2 8 4	Ozs. 14½ 5½ 15 10 2½ 6½ 10½	Inches.  1 11 12 2	Lbs. 0 1 2 2 3 4 6	Ozs. 15 71 1 14 9 14 4	Inches.	Lbs. Oss 0 15½ 1 8 2 8¾ 3 4 4 0 5 8 7 9			

TABLE.

## Weight of Wrought-Iron Gas Tubes and Fittings.

Internal			3	ľubes.					Fittings.					
Diameter Inches.		eight p 00 feet.		Weight per 1000 feet.				Weight of 10 Elbows.		Weight of 10 Tees.		Weight of 10 Crosses.		
1 1 1 1 1 2 2 2 2 2 3 3 4	Cwts. 0 0 0 0 1 1 2 2 3 8 4 5 6 7 8	Qrs. 1 1 2 3 0 2 1 3 0 0 1 0 1 2	Lbs. 0 14 6 6 22 26 11 7 12 21 26 5 19 20 14	Tons. 0 0 0 0 0 0 1 1 1 1 1 2 2 2 8 8 4 4	Cwts. 2 8 5 8 12 17 8 8 11 19 2 10 14 1 18 5	Qrs. 2 3 2 0 0 1 1 0 0 1 1 1 0 3 3 0 0	Lbs. 0 4 9½ 1 8 26 14 8 14 8 22 22 4 0	Lbs.  1 1 2 4 6 10 15 15 22 90 46 55 78 101 126	Ozs. 1 7 13 15 6 4 10 8 12 6 2 2 10 8	Lbs. 1 1 2 8 5 7 12 16 20 27 82 50 68 85 121 144	Ozs. 0 8 4 0 4 10 15 7 0 8 15 8 5 0	Lbs. 1 1 2 3 5 9 14 18 21 81 41 51 80 88 129 158	Ozs. 8 14 8 4 11 2 11 10 4 4 4 10 12 0	

TABLE.										
Pitch of the	Whitworth	Taps at	nd Dies	for Gas	Tubing.					

Internal Diameter of Pipe.	External Diameter of Pipe.	Number of Threads per Inch.	Internal Diameter of Pipe.	External Diameter of Pipe.	Number of Threads per Inch.
i	·385	28	2	2.347	11
i i	•520	19	21	2.467	11
1	·665	19	21	2.587	11
i	·882	14	2	2.794	11
. ž	1.034	14	$2\frac{1}{2}$	8.001	11
I 1	1.302	l ii l	2	3.124	11
11	1.492	l ii l	24	8 · 247	11
11	1.650	l ii k	21	3.367	īī
1	1.745	l ii l	2 <del>1</del> 21 3	3.485	īī
11	1.882	l ii l	81	8.698	îĩ
1	2.021	l ii l	31	8.912	īī
14	2.047	l ii l	84	4.125	ii
1 <u>1</u>	2.245	l îî l	4	4.339	îî

Uniformity in the screws or threads of service-pipes and fittings is greatly to be desired, a large proportion of the leakage being due to the want of this. The screwed joint may be too slack, in which case leakage often follows; on the other hand, when a socket is too small to receive the screwed end of a pipe, instead of running the tap into the one, or the dies over the other, careless workmen are often content to let the joint pass, provided they succeed in getting a single thread to bite. The natural settlement of the ground, the traffic over the surface, or the first keen frost, disjoints the connection and an escape follows.

To Calculate the Required Size of Service-Pipes.—The following table gives the theoretical diameter required for pipes which have to supply a certain number of burners at distances from the street main. The table is calculated by the formula,—

$$d = \sqrt{\frac{Q^3 s l}{(1850)^2 h}}$$
 being the same as that used in the determination

of the quantities of gas delivered by large pipes.

As, however, the actual discharge from small pipes is less than the calculated quantity, the tabular number must be increased by one-


third if the service-pipe is of lead, and by one-half if of wrought iron. When of the latter material, it is not advisable to put in the ground a pipe of less than  $\frac{\pi}{2}$  inch in diameter.

EXAMPLE of the Manner of Using the Table.—Supposing there are 40 lights to be supplied at the distance of 70 feet from the main, the tabular number opposite 70 and under 40 is .78540. To this add one-third if a lead service, making .98058, and one-half if a wroughtiron service, making 1.10810. The sizes of pipes next above the numbers are 1 inch and 1½ inch respectively, and these are the sizes required.

TABLE

Showing the Internal Diameter of Pipes, in Decimals of an Inch, to Supply Lights at Certain Distances from the Main.

Lá			m l	Mai	n in		Number of Lights, each Burning Five Feet per Hour, with a Pressure of One Inch.										
			eet.			١	8.	5.	10.	15.		20.	25.	80.			
5	_	_					·15457	18882	·24912	•2942	4	82876	·85946	·38894			
10	•	•	•	•	•	: 1	17682	·21691	.28617	.8866		87765	41291	•44415			
15	:	:	:	:	:		19176	23524	·81084	• 3650		40956	•44779	·48167			
20	:		:			. (	·20311	·24916	.32872	*8866	6	48881	47429	·51019			
80	:	:					22027	·27020	.35649	·4198	32	47045	.51488	•55329			
40	:	:			•	. 1	·23331	.28620	•37760	•444]	15	49830	.54488	.58605			
50	:					. 1	·24396	.29927	.39483	·4644	11	•52105	56970	·61280			
60						.	·25302	·81024	.40950	•4816	37	·54041	.59086	.63556			
70						.	·26094	•32010	·42231	•4967	75	.55788	60986	65546			
80						.	26802	·32876	·43375	•5125	55	·57241	62585	·67011			
90						.	27489	.33660	·44408	•5223	35	.58606	64077	·68925			
100						. 1	28023	·84377	·45854	•5334	18	.59854	65442	·70998			
L 50						. i	•30391	.37281	·49185	∙570€	54	64909	.70970	·76339			
200						.	·82191	·39489	·52098	•6128	31	·68753	.75178	80860			
250							*83660	·41291	·54476	•6407	77	·71891	·78604	*84550			
						.	·84901	· <b>4282</b> 5	•56507	664	57	·74561	81528	·87691			
<b>3</b> 00	_		_	_			N	how of T.ir	abta cook	Pomis	- TH	no Woot	non Honn	 			
====		s ír	om		in i	 n	Num	ber of Li		Burnir sure of			per Hour,	with			
====		s ír		Ma		 a	Num	ber of Lip		sure of		Inch.	per Hour,	with 800.			
		s ír	om	Ma		n.	 	·	a Press	of	Öne 15	Inch.		800.			
L		s ír	om	Ma.			40.	50.	100 -625	). 577	One 15	O.	200.	800.			
L.		s ír	om	Ma.		_	40.	50. ·47490	100 -625	). 577 581	78 .88	911 775 698	200. ·82581 ·94862 1·0288	800. •9752			
5 10		s ír	om	Ma ·	in i	<u> </u>	40. ·49381 ·49892	50. ·47480 ·54484	100 -625 -718	). 577 381	78 ·88 ·91	911 775 698	200. ·82581 ·94862	9752 1·1157			
5 10 15		s ír	om	Ma ·	in i	<u> </u>	40. ·43381 ·49832 ·54041	· 47480 · 54484 · 59086	100 100 100 100 100 100 100 100 100 100	577 381 354 571	78 ·88 ·91	911 775 693 123	200. ·82581 ·94862 1·0288	9752 1·1157 1·2099 1·2815			
5 10 15 20		s ír	om	Ma ·	in i	<u>:</u>	40. ·43381 ·49832 ·54041 ·57241	50. -47490 -54484 -59086 -62585	100 100 100 100 100 100 100 100 100 100	). 577 381 954 571 546	.78 .83 .91	911 775 693 123 33	200. ·82581 ·94862 1·0288 1·0897	9752 1·1157 1·2099 1·2815			
5 10 15 20 30		s ír	om	Ma ·	in i	<u>:</u>	40. ·43381 ·49632 ·54041 ·57241 ·62076	50. -47490 -54484 -59066 -62585 -67872	100 100 100 100 100 100 100 100 100 100	). 577 981 954 971 646 948	·78 ·88 ·91 ·97 1·06	911 775 698 123 33 56	200. -82581 -94862 1-0288 1-0897 1-1817	9752 1·1157 1·2099 1·2815 1·3898 1·4721			
5 10 15 20 30 40		s ír	om	Ma	in i	:	40. ·43381 ·49832 ·54041 ·57241 ·62076 ·65753	50. -47490 -54484 -59066 -62585 -67872 -71891	100 -625 -718 -779 -825 8 -895 - 948 - 991	577 881 954 571 546 648 177	.78 .88 .91 .97 1.06 1.11	911 775 698 123 33 56 65	200. -82581 -94862 1-0288 1-0897 1-1817 1-2517	9752 1·1157 1·2099 1·2815 1·3898 1·4721 1·5898			
5 10 15 20 30 40 50		s fr	om	Ma	in i	:	40. ·43381 ·49892 ·54041 ·57241 ·62076 ·65753 ·68753	50. -47490 -54484 -59086 -62585 -67872 -71891 -75172	100 100 100 100 100 100 100 100 100 100	577 881 954 571 546 648 177 96	78 ·78 ·83 ·91 ·97 1·06 1·11 1·16	911 6698 1123 33 56 65 99	200. -82581 -94862 1-0288 1-0897 1-1817 1-2517 1-9089	9752 1·1157 1·2099 1·2815 1·3898 1·4721 1·5898 1·5965			
5 10 15 20 30 40 50 60		s fr	om	Ma	in i	:	40.  -43381 -49832 -54041 -67241 -62076 -65753 -68753 -71907	5047480 -54484 -59066 -62586 -67872 -71891 -75172	100 100 1 ·625 2 ·718 6 ·825 8 ·895 9 ·991 3 1 ·026 6 1 ·060	0. 577 981 954 571 546 948 95 96 96	78 ·88 ·91 ·97 1·05 1·11 1·16 1·20 1·24 1·28	911 775 698 123 33 56 65 99 778	200. -92581 -94862 1-0288 1-0897 1-1817 1-2517 1-3089 1-3574	9752 1·1157 1·2099 1·2815 1·3898 1·4721 1·5898 1·5965 1·6464			
5 10 15 20 30 40 50 50 70		s fr	om	Ma	in in	:	40.  -43381 -49832 -54041 -67241 -62076 -65753 -68753 -71907 -73540	5047480 -54484 -59086 -62585 -67872 -71891 -75172 -77926	100 100 100 100 100 100 100 100 100 100	377 381 354 371 346 348 347 36 36	78 ·88 ·91 ·97 1·05 1·11 1·16 1·20 1·24	911 775 698 123 33 56 65 99 778	200. -82581 -94862 1-0288 1-0897 1-1817 1-2517 1-3699 1-3574 1-3999	9009752 1-1157 1-2099 1-2815 1-3898 1-4721 1-5898 1-5965 1-6464 1-6910			
5 10 15 20 30 40 50 50 70 80 90		s fr	om	Ma	in in	:	40.  -43381 -49832 -54041 -57241 -62076 -65753 -68753 -71907 -73540 -75530	50. -47490 -54484 -59086 -62585 -67872 -71891 -75172 -77928 -80406 -82585	100 - 625 - 718 - 779 - 825 - 981 - 991 - 1 026 - 1 066 - 1 1 066 - 1 1 106 - 1 1 118	577 1881 1954 1671 1646 1648 177 196 196 196 196 196 196 196 196 196 196	78 ·88 ·91 ·97 1·05 1·11 1·16 1·20 1·24 1·28	911 775 693 123 33 56 65 999 778	200. - 82581 - 94862 1 - 0288 1 - 0897 1 - 1817 1 - 2517 1 - 3089 1 - 3874 1 - 3999 1 - 4378	300. -9752 1·1157 1·2099 1·2815 1·3898 1·4721 1·5898 1·6844 1·6910 1·7318			
5 10 15 20 30 40 50 50 70 80 90		s fr	om	Ma	in i	: : : : : : : : : : : : : : : : : : : :	40. -49892 -54041 -67241 -6276 -68753 -71907 -73540 -77381	50. -47480 -54484 -59086 -62588 -67872 -71892 -71922 -80486 -82588 -84550	100 100 100 100 100 100 100 100 100 100	577 577 581 554 646 648 177 66 96 96 95	78 ·78 ·88 ·91 ·97 1·06 1·11 1·16 1·20 1·24 1·28 1·31	911 775 698 123 33 56 65 99 778 774 21	200. -92581 -94862 1-0288 1-0897 1-1817 1-2517 1-3089 1-3574 1-3999 1-34721	300. -9752 1·1157 1·2099 1·2815 1·3898 1·4721 1·5898 1·5965 1·6464 1·6910 1·7313 1·7681			
5 10 15 20 30 40 50 50 70 80 90 100	ght	s fr	om	Ma	in in		40. -49881 -49882 -54041 -57241 -62076 -68753 -68753 -71507 -73540 -75580 -77381 -78978	50.  -47490 -54484 -59096 -62585 -67872 -71891 -75172 -80406 -82586 -84586	1000 1000 1000 1000 1000 1000 1000 100	577 577 581 554 564 648 177 36 36 36 36 36 36 36 36 36 36 36 36 36	78 ·78 ·88 ·91 ·97 1·06 1·11 1·16 1·20 1·24 1·31 1·34	911 7775 698 123 33 566 65 999 778 774 21 000 332	200	300. -9752 1·1157 1·2099 1·38196 1·4721 1·5965 1·6464 1·6910 1·7818 1·7681 1·7681			
5 10 15 20 30 40 50 50 70 80 90 100 150	ght	s fr	om	Ma	in it	: : : : : : : : : : : : : : : : : : : :	40. -49381 -49892 -54041 -57241 -62076 -65753 -71907 -78540 -77580 -77581 -78978 -85649	50. -47480 -54484 -59086 -62586 -67872 -71891 -75172 -77922 -80400 -82585 -84556 -86353 -93688	1000 1000 1000 1000 1000 1000 1000 100	577 577 581 554 554 548 548 56 56 56 56 56 56 58	.78 .88 .91 .97 1.06 1.11 1.16 1.24 1.28 1.31 1.46	911 7775 698 123 38 556 65 999 774 221 000	200. -92581 -92682 1-0268 1-0897 1-1817 1-2517 1-3089 1-3574 1-3999 1-4378 1-4721 1-5035 1-6805	9752 1·1157 1·2099 1·2815 1·3898			



## PRICE LIST OF WROUGHT-

No.	INTERNAL DIAMETER. INCHES.	18	1	8	1	3	1
1 2 8 4 5 6 789	Tubes, 2 to 14 feet long, per foot Pieces, 12 to 28½ inches long, each Do. 3 to 11½ " Longscrews, 12 to 23½ " 3 to 11½ " Bends " Springs, not Socketed "	a. d. 0 2 0 4 0 2 0 5 0 4 0 5 0 4	s. d. 0 2½ 0 5 0 8 0 7 0 5 0 6½ 0 5	s. d. 0 8 0 7 0 4 0 9 0 6 0 7 0 6	s. d. 0 4½ 0 9 0 6 0 11 0 8 0 8 0 7	s. d. 0 6 1 0 0 8 1 2 0 10 0 11 0 9	s. d. 0 81 1 4 0 11 1 6 1 0 1 3 0 11
10 11 12 18 14 15	Socket Union (10), Pipe Do. (11) Elbows, Wrought-Iron Tees Crosses Plain Sockets	0 6 0 6 0 10 0 1½	2 0 0 6½ 0 6½ 1 0 0 1½	2 6 0 7 0 7 1 0 0 2	3 0 6 8 0 9 1 5 0 3	4 0 0 10 1 0 1 9 0 84	5 6 1 2 1 3 2 8 0 4
16 17 18 19 20 21 22 23	Diminished Sockets Flanges Cape (18), Plugs (19) Backnuts (20), Nipples (21) Union Bends Round Elbows, Wrought-Iron	0 8 0 2 0 1 0 7	0 8 0 9 0 3 0 2 2 6 0 7	0 4 0 10 0 3 0 2 8 0 0 8	0 5 1 0 0 4 0 3 8 9 0 9	0 6 1 2 0 5 0 3½ 5 0 1 0	0 7 1 4 0 6 0 4 6 3 1 4
24 25 26 27 28 29	Iron Main Cocks	2 8	2 3	2 9 4 6 8 6 5 0 1 0 0 7	3 6 5 6 4 0 6 6 1 4 0 8	4 6 7 6 5 6 9 0 1 8 0 10	6 6 10 6 7 6 13 0 2 0 1 2
30 31 32 33 84	Syphon Boxes, 1 Quart          Do.       2 "         Do.       8 "         Do.       4 "         Malleable Cast Round Elbows       .	0 6	0 63	0.7	11 0	12 0 16 0 20 0 21 0 0 10	13 0 17 0 22 0 28 0 1 2

(85) Tongs or Nippers, (86) Stocks, Dies, and Taps, at prices as quoted by the manufacturer.

If Tubes are required to be of longer length than 14 feet, they are charged at the next higher rate.

Tubes of intermediate diameters charged at the price of the next larger size.

Springs; if socketed, sockets added at list prices.

## IRON TUBING AND FITTINGS, &c.

1	ł	11		1	2	-	2	2	1	2	1	2	3	1	8	8	1	.	4
2 1 1 1 1 1	d. 11 8 1 0 8 9 4	1 2 1 2 2 2	đ. 204 608	1 2 2 3 2 8	d. 6 6 0 3 6 8	1 8 2 4 3 4 8	d. 9 0 8 0 0 8 8	2 4 4 5 4 0 5	d. 7 6 0 6 6 6	8. 8 6 4 7 5 10 7	a. 8 9 0 6 0	8. 4 7 6 8 6 12 10	<b>a.</b> 0 6 0 6 0 0	8. 4 9 7 10 7 16 12	d. 6 0 0 0 6 0	5 11 8 12 8 25 19	d. 6 6 6 6 0	7 14 9 15 10 82 26	d. 0 6 0 6 0 6
6 1 1 8 0	9 9 9 0 6	2 2 8	0 8 6 6 7	9 8 8 4 0	0 0 6 9	10 3 8 5 1	0 6 9 8 0	12 5 6 10 1	0 6 0 6 6	14 8 9 16 2	0 6 0 6	16 11 12 21 3	0 0 6 0	18 14 16 80 8	0 0 6 0 6	22 22 24 42 5	0 0 0 0	28 28 30 50 6	0 0 0 0
0 1 0 0 8 1	9 6 8 6 6 6	1 0 1 0 10	1 9 0 8 0 6	1 2 1 0 11 8	1 0 0 10 6	1 2 1 1 18 8	8 6 8 0 6	3 2 1 16 6	0 9 0 9 0 6	8 5 2 2 19 10	0 0 6 8 0	6 3 8 22 18	0 9 6 0 0	5 8 4 8 25 16	0 6 9 6 0	7 10 7 4 30 25	0 0 0 6 0	9 11 10 5 36 32	0 6 0 6 0
8 15 10 19 2	6 0 0 0 4 8	19 18 28 8	0 6 0 0 0 2	14 25 17 86 8	0 6 0 6 9	18 82 22 42 4	0 0 0 0 0 8	27 47 38 60 4 4	0 0 0 9 9	36 60 54 85 6	0 0 0 0 0 0	44 90 62 105 7	0 0 0 0 6 6	50 110 70 120 9	0 0 0 0 0 0	75 140 100 180 12 12	0 0 0 0 0 0	90 190 160 280 14 14	0 0 0 0
14 18 24 25 1	0 0 0 0 9	19 25 27	0 0 0 0 8	15 21 26 29 8	6 0 6 0	16 23 28 81 8	0 0 0 0 6	18 25 32 84 5	0 0 0 0 6	30 35 38 38	.000	35 40 42 12	.000	40 45 47 15	0 0 0	50 54 80	. 0 0	56 60 40	

1	Gas tubes and fi	ttings,	per cent.
Discount <	Galvanized	do.	do.
Discount	Steam and water	do.	do.
	Galvanized	d <b>o.</b>	do.

Iron Cocks over 2 inches at special discounts.

## PUBLIC LIGHTING.

The height of a lamp pillar or column (Fig. 124), measured from




Fig. 124.

Frg. 125.

the surface of the ground to the centre of the flame, should not exceed 10 feet.

A \{\frac{2}{3}}\)-inch or even a \{\frac{1}{2}}\)-inch lead pipe is not suitable for placing in the interior of a lamp column. In cold districts, in winter, the condensed moisture in a pipe of this small bore becomes frozen, filling up the entire length with solid ice in a very short space of time. This is probably due to the wavy irregularities in the pipe preventing the water from draining rapidly away.

Galvanized wrought-iron pipe is best for lamp columns, and for placing against a wall for the supply of a bracket lamp; and ½-inch is the smallest size that should be used. In situations exposed to cutting winds, and where the frost is keen, ½-inch wrought-iron pipes are best.

If the service-pipe at the entrance to the base of a lamp column has not very ample fall to the main, the water of condensation, unable to drain quickly away, will inevitably be frozen at that point during frost, and, by accretion, will eventually interrupt the passage of the gas.

It is not unusual to find one-half the public lights in some districts extinguished at night when a severe frost prevails. This is simply due to mismanagement, as it would not occur if attention were paid to the matters indicated above.

Seventy yards is the maximum distance apart at which public lamps should be placed.

A new and entirely novel form of lamp post (Fig. 125) has been introduced by J. & J. Braddock. It consists of four 1-inch wrought-iron tubes held together at three points, in addition to the base, by cast-iron binders, one of the tubes being used as the service-pipe for conveying the gas to the burner. Panels may be fixed at the foot, or it can be left open, as desired. No ladder-arm is required, as the tubes, on any side, form a square support for a ladder to rest against. The tubes are continued down through the visible base, and are screwed into a cast-iron plate underground. Altogether, the standard has a neat appearance, and, owing to its lightness—under 2 cwt.—and the ease with which it can be taken to pieces and set up again, it is specially adapted for export.

The ordinary four-sided lamp is the most serviceable for general use. It is 14 inches square at the widest part, and made of tinned copper.

The street lamps designed by Mr. Sugg (Fig. 126) and Mr. Bray (Figs. 127 and 128), with clusters of flat-flame burners, and the lamp and regenerative burner of Herr F. Siemens (Fig. 129) have much

improved the lighting of streets and squares wherever they have been introduced; and have proved, at the same time, that efficient street







Frg. 127.

illumination by means of gas is perfectly attainable where there is a willingness on the part of towns' authorities to incur the expense.

The earlier street lamps were constructed with opaque reflecting tops, and the glazed tops were afterwards introduced as an improve-



Fig. 128.



F10. 129.

ment. When the whole of the light is reflected downwards, the fronts of the houses, except for a short space above the height of the lamp column, are placed in a state of utter darkness, and to passengers



Fig. 130.



Frg. 131.

walking along the streets the gloomy canopy overhead. rendered all the more sombre and distressing from the concentrated light underneath, has an unearthly and depressing effect.

On the other hand, where the main thoroughfares of a large town are lighted with the capacious lamps. above described, with semi-transparent crowns, admitting of the radiation of a portion of the light on the house fronts, the effect is pleasing and satisfactory.

The incandescent gas-light is growing in vogue for street lighting, and nothing in artificial illumination can exceed it either as regards efficiency or economy. provided due care and intelligence are exercised in settling the design of the lamp with a view to controlling the air supply, and in applying the adjustment necessary to counteract the effects of vibration caused by traffic.

Those produced by the Denayrouze Light Syndicate are of a remarkable type, as giving the highest illuminating duty per cubic foot of gas yet attained. They are specially constructed and largely in use for

lighting public streets, squares, and other wideareas. The burners are admirably adapted for ranging in groups or clusters, and give excellent results in this way, the groups being in two, three, five, and eight lights, with a consumption per burner varying from eight to ten cubic feet.

The square at the bottom of the usual form of lamp is generally in two or three parts, one of them being hinged on the outer edge, for raising when the lamp has been lighted by the pole. It is a common occurrence to find a portion of the bottom missing altogether, and the flame, thus exposed to the action of the wind, is in a state of constant oscillation. whereby much of the illuminating power of the gas is sacrificed.

The supply of gas to ordinary public lamps is usually fixed at 5 cubic feet per hour for -common gas up to 17 candles value; for cannel gas up to 80 candles value, the supply per hour varies from 4 to 8 cubic feet.

A regulator to each lamp is a necessity in order to secure this measured supply or a near approximation to it; and not less so to obtain the best illuminating effect from the gas. Borradaile's regulator, which is well known, is shown in section in Fig. 180.

Hutchinson Bros.' lamp service cleaner (Fig. 131) is a handy instrument, easily applied, for clearing out obstructions of all kinds, both from services and fittings.

Satisfactory public lighting, as between gas companies and local authorities, is best secured by the adoption of a good average meter-system, and the application of a regulator to every lamp.

Weight and Thickness of Glass for Public Lamps.

No. of the Glass or Weight in Ounces per Square Foot			:	Thickness in Decimals of an Inch.		No. of the or Weight in per Square	Our	1068	ı	Thickness in Decimals of an Inch		
12					·059	21					·1 <b>00</b>	
18					·068	24					·111	
15					.071	26					·125	
16					·077	32					·154	
17					·083	36					·167	
19					·091	42					·200	

Rule to find the Length of Day and Night.

Day.—The hour of sunset, doubled, is the length of the day. Night.—The hour of sunrise, doubled, is the length of the night.

Rule to find the Hours of Sunrise and Sunset.

Deduct the hour of sunset from 12; the difference is the hour of sunrise and vice eversa.

The Moon's Rising and Setting.

At	4	days	old,	the Moon set	s abo	ut 10 o'c	clock	at	night.	
Αt	5	,,	"	"	,,	11	,,		,,	
Αt	6	,,	,,	"	,,	12	"			
Αt	7	,,	"		,,	1 o'	clock	in	the mornin	ıg.
.At			" t	he Moon rise	s "	6	• • •	in	the evening	ζ.
Δt		17	"	"	,,	7≵	,,		,,	-
At		"	,,	,,	"	81	,,		,,	
Ąt		,,	",	17	"	10	,,	at	night.	
At		,,	**	,,	79	11	,,		"	
.At	20	**	**	**	••	12	••			

TABLE

Showing the Consumption of Gas by One Burner per Month, and for the Twelve Months, during the Average Hours of Burning from Sunset throughout the Year.

·.	d Bunset.	stroH to	lo strof danoi	8	Consumption of Gas by One Burner per Month, and for the whole Year. Lamps assumed to be Lighted from Sunset to Sunries, and Private from Sunset until Nine o'Clock.	of Gas by	mption of Gas by One Burner per Month, and for the whole Year. Lamps assumed to be Lighted from Sunset to Sunries, and Private from Sunset until Nine o'Clock.	ted from Sunset unt	Burner per Month, and for the Lighted from Sunset to Surrie from Sunset until Nine o'Clock	or the who Sunrise, an Slock.	ole Year. id Private	Public Street Lamps	100
Month.	earl e	Darstion darnal to	or of H	8 Cub	8 Cubio Feet per Hour.	St Cub per E	24 Cubic Feet per Hour.	4 Cubi	Cubic Feet per Hour.	44 Cubic Feet per Hour.	ic Feet Tour.	5 Oab	5 Cubic Feet per Hour.
	Averag	маэм	dmaN giN	Public Lamps.	Private Lamps.	Public Lamps.	Private Lamps.	Publio Lampa.	Private Lamps.	Public Lamps.	Private Lamps.	Public Lampa.	Private Lamps.
	b. m.	d. E.	ج ان م	o. ft.	o. ft.	o. ft.	o. ft.	9. ft.	o. ft.	o. ft.	o. ft.	o. #:	o. ft.
Rehmery		14.	411	1288	328	1438	88	1644	88	1850	3	350	4
March	9	12 19	883	1146	220	1337	815	1528	8	1719	9	1910	450
April	6 57	9	2062	988	185	1082	216	1180	246	1327	277	1475	908
May	7 46		242	286	116	847	184	8	15	989	178	1210	161
June	8 16	8	196		:	8	:	88	:	878	:	976	:
July	œ ι	0;	212	3 5	:	92.5	:	200	:8	928	:8	98	:
August			ž	18.5	25	1904	26	1800	2 C	1552	200	967	<b>8</b> 8
September . October			<b>4</b>	883	28	1474	88	1684	33	1895	38	2010	200
November . December .	4 8 8 8	15 46 17 0	473 527	1419 1581	413	1655 1846	481 564	1892 2106	644 644	2128 2872	619 726	2666 2635 2635	888
Total for the year.	:	:	4327	18,981	92979	15,144	8475	17,908	8978	19,472	4468	21,635	4960

# TABLE

Showing the Number of Hours during which Gas is usually Burned in each Month, Quarter, and Year, according to the Times of Lighting and Extinguishing.

*.11	Total of Yea	277 498 1078 11443 11808 22173 4527 727 472 269
	Obristmas.	178 265 867 867 143 683 728 1421 1431 683 683 641 648 648
	samie adoiM	2 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8
•	10mmusbiM	880 880 880 880 880 880 880 880 880
	Lady-Day.	102 188 278 868 458 548 638 1305 1205 126 68
	December.	80 1111 142 173 204 286 686 687 106 75
Christmas Quarter.	Иочешрет.	68 92 1158 1168 1168 110 110 80 80
50	October.	81 62 98 184 155 186 217 421 421 189 49
2.	September.	841 845 845 845 845 845 845 845 845 845 845
Michaelmas Quarter.	August.	14 40 40 71 102 1138 164 164
×	Jaja.	18 14 106 106 
ie.	Jane.	:::æ88888 ::::
Midsummer Quarter.	May.	
<b>A</b>	.lirqA	: 4 28 28 28 28 28 28 28 28 28 28 28 28 28
<b>b</b>	Marob.	31 62 98 1155 1155 1186 882 40 40 9
Lady-Day Quarter.	February.	83 61 89 117 1173 201 411 98 70 42 14
	January.	65 96 1127 1158 1189 1280 1281 127 127 144
	Times of Lighting and Extinguishing.	If lighted at dusk and extinguished at— guished at— 7 7 8 8 9 9 9 10 112 112 112 112 112 112 112 112 112

\* A deduction of one-sixth may be made for moonlight nights; and in the case of private lamps not being lighted on Sundays, deduct one-seventh.

### CONSUMERS' GAS METERS.

Gas Meters are either "Wet" (Figs. 182 and 188), or "Dry" (Figs. 184 and 185).

The wet meter has a measuring wheel or drum enclosed in an iron case charged with water up to a certain level, called the "water-line."




Fig. 182.




Fig. 133.

The drum is divided into compartments similar to the station meter; and the measurement and indication, or registration, of the gas passing through it are performed in the same manner.

The dry meter has usually a case of tinned iron. This is divided into compartments by a central partition and two or more moveable





Fig. 184.



F16. 185.

diaphragms with prepared flexible leather sides. The gas enters and leaves these compartments alternately through valves whose passages are made to open and close at the proper moment. The alternate expansion and contraction of the inner and outer spaces (after the

now altogether inadmissible; and even two-light meters should only be sparingly used. The low price at which gas is sold encourages its extended consumption; and the houses are becoming fewer in number every day where this small size is sufficient to afford an adequate supply, at reasonable pressures, to the quantity of lights in regular use.

The regular periodical inspection of meters is a point of the utmost importance, and ought never to be neglected. The indices of meters in dwelling-houses, &c., should be noted, and water supplied to the proper level wherever deficient, at least once every six weeks. The meters in mills, manufactories, and large establishments of every kind where the consumption of gas is heavy, should be inspected for the like purpose once every fourteen days.

The Inspector should always be provided with a supply of leather washers for the different screws and plugs, to replace any that are worn out.

Meters in cold and exposed positions should be protected by a suitable covering during frost, to prevent interruption to the supply of gas by the water becoming frozen. Woollen rags or wrappings of any kind will answer the purpose.

Greenall and Heaton's "Positive" Meter (Fig. 188) differs in construction from those above described. The meter has two measuring



Fig. 188.

cylinders, each divided into two separate chambers by a hollow cylindrical piston, sealed with glycerine within the annular space between the inner and outer parts of the cylinders. The chambers are connected by the gas-ways to the respective valve ports. The

length of the stroke of the pistons is fixed and definite, so that the displacement of gas at each stroke is the same and does not vary. One piston is set half a stroke in advance of the other, and thus each carries the other over the centre. The glycerine seal is not affected by the initial pressure, but only by the slight differential pressures above and below the pistons: In other words, only the slight pressure which is required to actuate the meter.

The motive power meter is but rarely required; but it is exceedingly



Fig. 139.

useful in certain positions, where the pressure, from some unavoidable cause, is insufficient to afford an adequate supply of gas. In construction it is like an ordinary meter, but instead of the gas pressure being the motive power, the gas is exhausted from the main by the measuring wheel. This is set in motion by a descending weight, attached to which is a cord wound on a drum revolving in bearings on the top of the meter case, the drum being geared to the shaft of the measuring wheel, which through the back of the case. The speed of the meter, and consequently the pressure of gas obtained, are regulated by the Parkinson's motive power meter is shown in

weight aforementioned. Fig. 139.

The "prepayment" or "slot" meter, of which there are various forms, is an ingenious device for extending the sale of gas amongst small consumers. By the addition of a simple mechanism contained in a box attached to the ordinary wet or dry meter, and on dropping a penny through a slot therein, a quantity of gas of the value of the penny is allowed to pass to the burner. When the gas thus paid for is consumed, the supply ceases until another prepayment is made.

By another arrangement, on prepayment of a given sum—say 4d. for 100 cubic feet—an extra dial on the meter is set to pass the quantity of gas; and when this is consumed, a valve shuts off the supply, unless, in the meantime, a further payment has been made, and the dial is reset.

Variations in the dimensions of unions for equal sized meters are a source of expense in the case of changing from one make to another.

The Board of Trade in their Annual Report for 1888 suggested that the unions of gas meters throughout the trade should be made of uniform size, and the following table gives the dimensions proposed.

TABLE.

Sizes of Meter Unions as suggested by the Board of Trade in 1888.

		Boss.			Cap.		Lining.
Size of Meter.	Mean Diameter of External Screw.	No. of Threads per inch. Whit- worth.	Internal Diameter.	Mean Diameter of Internal Screw.	No. of Threads per inch. Whit- worth.	Height of Cap.	External Diameter to enter Boss.
Lights.	Inches.		Inches.	Inches.		Inches.	Inches.
0	0.70	19	0.50	0.66	19	0.40	0.50
1	0.88	19	0.57	0.84	19	0.40	0.55
2 8 5	0.88	19	0.57	0.84	19	0.40	0.55
8	0.98	19	0.69	0.94	19	0.20	0.65
5	1.15	14	0.88	1.10	14	0.20	0.81
10	1.45	11	1.02	1.40	11	0.60	1.08
20	1.80	11	1.42	1.75	11	0.60	1.40
80	2.05	11	1.22	2.00	11	G·70	1.58
50	2.25	11	1.80	2 · 20	11	0.70	1.75
60	2.45	11	2.00	2.40	11	0.80	1.98
80	3.00	11	2.30	2.95	11	1.00	2.28
100	8.00	11	2.80	2.95	11	1.00	2 28
150	3.68	9	3.05	3.65	9	1.50	8.08

Testing Meters.—For the verification of gas meters by a public Inspector under the "Sales of Gas Act," a somewhat elaborate set of apparatus is required.

For ordinary use in testing meters in a gas-works, the following may be provided (see Fig 140):—A standard gasholder of 10 cubic feet capacity. A proving bench. An overhead water cistern. A float of lights, and thermometers for taking the temperature of the air and water.

In testing, it is important to secure uniformity in the temperature of the air or gas in the test holder, the water in the tank, and the air in the room—viz., 60° Fahr.; otherwise corrections for varying temperature have to be made.

Place the meter to be tested on the proving bench, charge it with water to the proper water-line (if a wet meter), and connect it with the holder and to the float of lights (if gas is being used).

See that the pointer of the small metal drum above the index in the

wet meter, or of the small circle on the index plate of the dry meter, coincides with one of the figures marked thereon. If it does not, pass a quantity of gas through till the necessary adjustment is effected.

Next, fill up the test holder till the 0 line of the scale upon it is exactly opposite its pointer.

This being done, turn on the gas or air, and allow the meter to work till the small metal drum has made one or more revolutions, taking




Fig. 140.

care to close the stop-cock when the pointer of the drum is exactly over the figure from which the start was made.

The meter registration is then compared with that of the holder scale. If they correspond, the meter is exactly correct; but if the scale on the holder indicates less or more than the small drum on the meter, the percentage of error is calculated; or it can be ascertained on reference to the Table.

## TABLE.

Showing the Percentage of Error in Meters according as their Registration differs from the Indications of the Test Gusholders.

The sign + is used to indicate fast, and - to indicate slow.

Meters not exceeding 2 per cent. fast, or 3 per cent. slow, are correct within the meaning of the "Sales of Gas Act."

Meter R 1 F	egistering loot.	Meter R 2 F	egistering Feet.	Meter R 3 I	egistering Feet.		egistering ?eet.
Reading of Scale of Gas- holder.	Amount of Error.	Reading of Scale of Gas- holder.	Amount of Error.	Reading of Scale of Gas- holder.	Amount of Error.	Reading of Scale of Gas- holder.	Amount of Error.
Foot. 0'90 '91 '92 '93 '94 '95 '96 '97 '98 '99 1'00 '01 '02 '03 '04 '05 '06 '07 '98 '07 '98 '110 '111 '12	Per Cent. + 11·11 + 9·89 + 8·70 + 7·25 + 6·26 + 4·17 + 3·90 + 2·04 + 1·01 - 1·97 - 2·92 - 4·74 - 5·66 - 6·54 - 7·40 - 9·91 - 10·07	Feet. 1:80 :81 :82 :83 :84 :85 :86 :87 :89 1:90 :91 :92 :98 :96 :97 :98 :99 2:00 :01 :02 :03 :04 :05 :06 :07 :08 :09 2:10 :11 :12 :13 :14 :15 :18 :19	Per 11:05:99 99:01:15:05:99 99:00:05:05:99 99:00:05:05:05:05:05:05:05:05:05:05:05:05:	Feet. 2 '70	Per Cent. + 11·11 + 10·30 + 9·99 + 9·99 + 8·70 + 7·58 + 7·758 + 7·758 + 7·758 + 6·68 + 6·68 + 6·68 + 6·68 + 4·53 + 4·53 + 4·17 + 2·78 + 1·85 +	Feet. 8:10 -11 -12 -18 -16 -16 -17 -18 -19 8:20 -21 -22 -23 -24 -25 -26 -27 -28 -29 8:30 -31 -32 -33 -34	Per Cent  - 8 * 22  - 8 * 84  - 4 * 16  - 4 * 46  - 5 * 86  - 5 * 86  - 5 * 86  - 6 * 86  - 7 * 11  - 7 * 77  - 7 * 98  - 8 * 86  - 9 * 86  - 9 * 86  - 10 * 18

Meter Re 5 F	gistering eet.	Meter Re	egistering eet.	Meter R	egistering leet.		egistering Feet.
Reading of Scale of Gas- holder.	Amount of Error.	Reading of Scale of Gas- holder.	Amount of Error.	Reading of Scale of Gas- holder.	Amount of Error.	Reading of Scale of Gas- holder.	Amount of Error.
Fees. 4 · 50 · 51 · 52 · 58 · 55 · 56 · 57 · 58 · 58 · 68 · 68 · 68 · 68 · 68 · 68	Per Cent. + 11.11.11.11.11.11.11.11.11.11.11.11.11.	Feet. 5 * 023	Per Cent 0 · 60 - 0 · 79 - 0 · 60 - 0 · 79 - 1 · 188 - 1 · 57 - 1 · 196 - 2 · 184 - 2 · 53 - 2 · 72 - 2 · 184 - 2 · 53 - 2 · 72 - 3 · 66 - 3 · 66 - 4 · 60 - 4 · 60 - 4 · 60 - 5 · 60 - 6 · 60 - 6 · 60 - 6 · 60 - 6 · 60 - 6 · 60 - 7 · 24 - 7 · 7 · 7 · 7 · 7 · 7 · 7 · 7 · 7 · 7	Feet. 6	Per Cent 9 '75 - 9 '91 - 10 '07 - 10 '28 - 10 '55 - 10 '71 - 10 '87 - 11 '08 - 11 '19	holder.  Feet. 9 '00	Per Cent. + 11·11·11·11·11·11·11·11·11·11·11·11·11·

	egistering eet.	Meter R 20 I	egistering Peet.		egistering Feet.		egistering leet.
Reading of Scale of Gas- holder.	Amount of Error.	Reading of Boale of Gas- holder.	Amount of Error.	Reading of Scale of Gas- holder.	Amount of Error.	Reading of Scale of Gas- holder.	Amount of Error.
Feet. 90·16 18 20·20 24 24 26 28 20·80 32 34 36 38 30·40 42 44 46 48 20·50 62 64 66 68 20·70 72 74 76 82 84 86 88 20·90 92 94 96 98 21·00 02 114 16	Per Co-nt.	Feet. 21:20 :24 :24 :26 :28 21:30 :32 :34 :36 :36 :36 :40 :42 :44 :46 :48 :21:50 :54 :56 :58 21:60 :62 :64 :66 :68 21:70 :74 :78 21:80 :88 21:90 :94 :96 :98 :92:00 :04 :16 :16 :18 :22:20	Per Cent 5 *68 - 5 *78 - 5 *58 - 6 *02 - 6 *19 - 6 *28 - 6 *19 - 6 *28 - 6 *54 - 6 *68 - 6 *68 - 7 *15 - 7	Feet. 22:24 26 28 22:80 82:80 88 22:40 444 46 248 22:50	Per Cent. — 10·07 — 10·15 — 10·28 — 10·41 — 10·55 — 10·68 — 10·71 — 10·95 — 11·10 — 11·11	Foet. 27 00 02 04 06 08 27 10 12 12 14 16 18 27 20 24 24 26 28 27 80 82 44 46 46 27 50 56 66 66 27 70 72 76 68 27 80 92 84 96 88 27 90 92 88 90 98 28 90	Per Cens. + 11·11 + 10·98 + 10·78 + 10·62 + 10·64 + 10·64 + 10·38 + 10·30 + 10·21 + 10·06 + 9·89 + 9·81 + 9·87 + 9·41 + 9·97 + 9

	egistering Feet.	Meter Re 80 I	egistering Feet.		egis <b>teri</b> ng Peet.		egistering Feet.
Reading of Scale of Gas- holder.	Amount of Error.	Reading of Scale of Gas- holder.	Amount of Error.	Reading of Scale of Gas- holder.	Amount of Error.	Reading of Scale of Gas- holder.	Amount of Error.
holder.  Feet. 28:04 06:08 98:10 114 16:18 28:20 24 24 26:28 28:50 824 84 86 48 28:40 44 46 48 28:50 52 54 56 56	Per Cens. + 6:99 + 6:99 + 6:99 + 6:69 + 6:69 + 6:69 + 6:69 + 6:69 + 6:69 + 6:69 + 6:59	Feet. 29 · 06 29 · 10 · 12 · 14 · 16 · 18 29 · 20 · 22 · 24 · 56 · 38 29 · 40 · 42 · 46 · 46 · 54 · 56 · 58 29 · 60 · 62 · 62	Per Cent. + 8:09 + 8:02 + 2:98 + 2:88 + 2:81 + 2:54 + 2:53 + 2:48 + 2:53 + 2:54 + 2:53 + 2:11 + 1:97 + 1:69 + 1:69 + 1:42 + 1:42 + 1:35 + 1:42 + 1:35 + 1:28	Feet. 80·12 ·14 ·16 ·18 80·20 ·22 ·24 ·26 ·28 80·30 ·32 ·34 ·36 ·36 ·42 ·44 ·46 ·48 30·50 ·52 ·54 ·56 ·56 ·58 80·60 ·64 ·64 ·66	Per Cent 0 · 40 - 0 · 47 - 0 · 53 - 0 · 66 - 0 · 78 - 0 · 99 - 0 · 99 - 1 · 96 - 1 · 12 - 1 · 19 - 1 · 18 - 1 · 18 - 1 · 16 - 1 · 17 - 1 · 18 - 1 · 19 - 1 · 18 - 1 · 19 - 1 · 18 - 1 · 19 - 1 · 19 - 1 · 19 - 1 · 19 - 1 · 19 - 1 · 19 - 1 · 19 - 1 · 19 - 1 · 19 - 1 · 19 - 1 · 19 - 1 · 19 - 1 · 19 - 1 · 19 - 1 · 19 - 2 · 19 - 2 · 19 - 2 · 19	Feet. 81-16 - 18 81-20 - 22 - 24 - 26 81-80 - 32 - 34 - 46 - 48 81-50 - 52 - 54 - 56 - 68 81-70	Per Cent 3.72 - 8.79 - 8.85 - 8.97 - 4.08 - 4.16 - 4.22 - 4.28 - 4.40 - 4.46 - 4.58 - 4.64 - 4.76 - 4.88 - 4.94 - 5.00 - 5.06 - 5.12 - 5.18 - 5.24 - 5.86
28 · 60 · 62 · 64 · 68 · 68 · 28 · 70 · 74 · 76 · 78 28 · 80 · 82 · 94 · 94 · 98 · 98 · 98 · 98 · 98 · 98 · 98 · 98	+ 4.89 + 4.75 + 4.67 + 4.63 + 4.45 + 4.31 + 4.31 + 4.17 + 4.10 + 8.96 + 8.81 + 8.69 +	·64 ·68 ·68 ·29·70 ·72 ·74 ·76 ·78 ·98 ·84 ·86 ·88 ·29·90 ·92 ·94 ·96 ·98 ·90 ·04 ·04 ·06 ·08 ·08	+ 1·21 + 1·14 + 1·08 + 0·98 + 0·81 + 0·67 + 0·60 + 0·63 + 0·47 + 0·20 + 0·20 + 0·13 + 0·20 - 0·13 - 0·13 - 0·07 - 0·18 - 0·20 - 0·27 - 0·38	*68 30.70 .72 .74 .76 .80.80 .82 .84 .86 .88 .80.90 .92 .94 .96 .08 .08 .96 .08 .91 .00 .02 .04 .06 .08 .04 .06 .08	- 2·22 - 2·28 - 2·34 - 2·40 - 2·47 - 2·53 - 2·60 - 2·60 - 2·72 - 2·78 - 2·85 - 2·97 - 3·16 - 3·16 - 3·22 - 3·24 - 3·24 - 3·24 - 3·24 - 3·26 - 3·36 - 3·36	724 -74 -76 -78 -78 -81 -80 -84 -86 -88 -91 -90 -94 -96 -98 -96 -06 -08 -08 -82 -10 -12 -14 -16 -18	- 5·42 - 5·48 - 5·54 - 5·60 - 5·72 - 5·78 - 5·90 - 6·02 - 6·02 - 6·19 - 6·19 - 6·31 - 6·37 - 6·48 - 6·54 - 6·64 - 6·65 - 6·67 - 6·77 - 6·77

Reading of Scale of Gasholder.  Feet. Per Cent. Feet. Per Cent.	Reading Amount
Feet. Per Cent. Feet. Per Cent. Feet. Per Cent	of Gas- holder. Error.
82·20         - 6·88         88·24         - 9·81         ************************************	Feet. Per Cent. 37·04 + 7·99 .06 + 7·93 .08 + 7·87 .10 + 7·82 .12 + 7·76 .16 + 7·84 .18 + 7·59 .19 + 7·47 .24 + 7·41 .26 + 7·44 .28 + 7·30 .37·30 + 7·24 .32 + 7·18 .34 + 7·18 .38 + 7·07 .38 + 7·07 .38 + 7·18 .38 + 7·07 .37·40 + 6·96 .44 + 6·90 .44 + 6·84 .46 + 6·72 .37·50 + 6·66 .52 + 6·61 .54 + 6·55 .56 + 6·50 .58 + 6·44 .37·60 + 6·38 .64 + 6·37 .66 + 6·31 .70 + 6·10 .71 + 6·90 .71 + 6·90 .72 + 6·90 .73 + 6·90 .74 + 5·98 .76 + 5·98 .78 + 5·98 .98 + 5·31 .98 + 5·31 .98 + 5·31 .98 + 5·31

Meter Re 40 I	egistering Feet.	Meter R 40 I	egistering Feet.	Meter R	egistering Feet.	Meter R	egistering Feet.
Reading of Scale of Gas- holder.	Amount of Error.						
Feet. 88:08	Per Cent. + 5.04	Feet. 39·12	Per Cent. + 2.25	Feet. 40·16	Per Cent. - 0.40	Feet. 41 · 20	Per Cent. - 2.91
88.10	+ 4.98	·14	+ 2.20	.18	- 0.45	.22	- 2.96
•12 •14	+ 4·98 + 4·87	·16	+ 2.15	40.20	- 0·50 - 0·55	·24 ·26	- 8·06 - 8·06
.16	+ 4.82	89.20	+ 2.04	-24	- 0.60	.28	- 3·10
•18	+ 4.76	.22	+ 1.99	•26	- 0.65	41.30	- 8.15
88 20	+ 4.71	·24	+ 1.94	•28	- 0.70	.32	- 3.19
•22	+ 4.65	26	+ 1.88	40.80	- 0.75	*84	- 8·24
24	+ 4·60 + 4·54	99·30	+ 1.83 + 1.78	·82 ·84	- 0·79 - 0·84	·86 ·88	- 8·29 - 3·84
•28	+ 4.49	•32	+ 1.78	-86	- 0.89	41.40	- 8.88
88.80	+ 4.44	.84	1.68	.88	- 0·94	·42	- 3.43
•82	+ 4.88	•36	+ 1 63	40·40	- 0.99	•44	- 8.47
·84	+ 4.88	.88	+ 1.57	•42	- 1:04	·46	- 8.52
·86 ·88	+ 4·28 + 4·22	89·40 ·42	+ 1.52 + 1.47	·44 ·46	- 1·09 - 1·14	·48 41·50	- 8·57 - 3·61
88.40	+ 4·22 + 4·17	- 41	+ 1·47 + 1·42	·48	- 1·12 - 1·19	-52	- 3·66
•42	+ 4·11	•46	+ 1.87	40.50	- 1.24	•54	- 8.71
•44	+ 4.06	•48	+ 1.82	•52	- 1.28	•56	- 8.75
•46	+ 4.00	89.50	+ 1.26	•54	- 1.88	.58	- 3.80
•48	+ 8.95	.52	+ 1.21	.56	- 1.88	41.60	- 8.85
88·50 •52	+ 3·90 + 3·84	·54 ·56	+ 1·16 + 1·11	·58 40·60	- 1·48 - 1·48	·62 ·64	- 8·90 - 8·94
•54	+ 8.78	.58	¥ 1.06	-62	- 1.58	.66	- 8·99
•56	+ 8.78	89.60	+ 1.01	-64	- 1.57	•68	- 4.08
•58	+ 8.68	·62	+ 0.96	•66	- 1.62	41.70	- 4.08
88.60	+ 3.63	·64	+ 0.91	.68	- 1.67	.72	- 4.12
·62 •64	+ 8.57	.66	+ 0.86 + 0.81	40·70 ·72	- 1·72 - 1·77	·74 ·76	- 4·17 - 4·21
-66	+ 8·52 + 8·46	·68 39·70	+ 0·81 + 0·75	.74	- 1.82	.78	- 4·21 - 4·26
•68		33.10	+ 0.70	•76	- 1.86	41.80	- 4·81
88.70	+ 8·41 + 8·86	.74	+ 0.65	•78	- 1.91	.82	- 4.86
.72	+ 8.81	.76	+ 0.60	40.80	- 1.96	*84	- 4.40
•74	+ 3.25	.78	+ 0.55	.82	- 2.01	*86	- 4.45
·76 ·78	+ 8·20 + 8·14	89·80 ·82	+ 0.50 + 0.45	·84 ·86	- 2·06 - 2·10	·88 41·90	- 4·49 - 4·54
88.80	+ 8.09	-84	+ 0·45 + 0·40	-88	- 2·10 - 2·15	.92	- 4·58
₩.82	+ 8.04	∙86	+ 0.85	40.90	- 2.20	•94	- 4.68
•84	+ 2.99	•88	+ 0.80	.92	- 2.25	.96	- 4.67
•86	+ 2.98	39.90	+ 0.25	.94	- 2.30	.98	- 4.72
*88	+ 2.88	.92	+ 0.20	.96	- 2.84	42:00	- 4.76
88·90 ·92	+ 2·82 + 2·77	·94 ·96	+ 0.15	·98 41·00	- 2·89 - 2·44	·02 ·04	- 4·81 - 4·85
-94	+ 2·77 + 2·72	.98	+ 0.10	•02	- 2.49	.08	- 4·90
.96	+ 2.67	40.00	Nil.	.04	- 2.58	-08	- 4.94
.98	+ 2.61	.02	- 0.05	∙06	- 2.58	42.10	- 4.99
89.00	+ 2.56	·04	- 0.10	.08	- 2.63	12	- 5:03
·02 ·04	+ 2.51	·08	- 0·15 - 0·20	41·10 ·12	- 2·68 - 2·72	·14 ·16	- 5·12 - 5·12
•06	+ 2·46 + 2·40	40.10	- 0.20	12	- 2·72	.18	- 5.13
•06	+ 2.85	10 10	- 0.80	•16	- 2.82	42.20	- 5.21
89.10	+ 2.30	•14	- 0.85	•18	- 2.87	.22	- 5.26

	egistering Feet.		egistering Feet.	Meter Re	egistering Feet.		egistering Feet.
Reading of Scale of Gas- holder.	Amount of Error.	Reading of Scale of Gas- holder.	Amount of Error.	Reading of Scale of Gas- holder.	Amount of Error.	Reading of Scale of Gas- holder.	Amount of Error.
Feet. 42:44 -26 -28 -28 -28 -28 -28 -28 -28 -38 -38 -38 -38 -42:40 -48 -48 -48 -48 -48 -48 -48 -48 -48 -48	Per Cent 5:85 - 5:85 - 5:85 - 5:48 - 5:65 - 5:65 - 5:66 - 5:76 - 5:80 - 5:88 - 6:06 - 6:16 - 6:16 - 6:28 - 6:38 - 6:38 - 6:50 - 6:46 - 6:50 - 6:50 - 6:68 - 6:68 - 6:68 - 6:68 - 6:68 - 6:68 - 6:88	## 100	Per Cant. 8	Feet. 44:33 - 34 - 38 - 38 - 38 - 44:40 - 42 - 44 - 48 - 48 - 44:50 - 52 - 54 - 56 - 62 - 64 - 66 - 68 - 44:70 - 78 - 78 - 78 - 44:80 - 82 - 94 - 98 - 98 - 45:00	Per Cent 9 '75 - 9 '88 - 9 '87 - 9 '91 - 9 '88 - 9 '97 - 9 '91 - 10 '08 - 10 '07 - 10 '11 - 10 '19 - 10 '23 - 10 '43 - 10 '47 - 10 '51 - 10 '55 - 10 '59 - 10 '68 - 10 '77 - 10 '79 - 10 '84 - 10 '87 - 10 '91 - 10 '95 - 10 '95 - 10 '95 - 10 '95 - 11 '07 - 11 '11	Feet. 45·00	Per Cent. + 11·11 + 11·06 + 10·91 + 10·91 + 10·96 + 10·76 + 10·76 + 10·62 + 10·62 + 10·57 + 10·63 + 10·33 + 10

	egistering Feet.		egistering Feet.		egistering Feet.	Meter R 50	egistering Feet.
Reading of Scale of Gas- holder.	Amount of Error.	Reading of Scale of Gas- holder.	Amount of Error.	Reading of Scale of Gas- holder.	Amount of Error.	Reading of Scale of Gas- holder.	Amount of Error.
Feet.	Per Cent.	Feet.	Per Cent.	Feet.	Per Cent.	Feet.	Per Cent.
46.04	+ 8·60 + 8·56	47·08 47·10	+ 6·20 + 6·16	48·12 ·14	+ 8.86 + 8.86	49·16 ·18	+ 1·71 + 1·67
·08	+ 8·56 + 8·51	12	+ 6.11	.16	+ 8.82	49.20	+ 1.68
46.10	+ 8.46	•14	+ 6.07	•18	8.77	.22	+ 1.59
·12	+ 8.41	•16	+ 6.02	48.20	+ 8.78	•24	+ 1.55
·14	+ 8.37	•18	+ 5.98	•22	+ 8.69	.26	+ 1.50
•16	+ 8.32	47.50	+ 5.93	•94	+ 8.65 + 8.60	•28	+ 1:46 + 1:42
•18	+ 8.28	.22	+ 5·89 + 5·84	·26 ·28	+ 8.60 + 8.56	49·80 •82	
46·20 ·22	+ 8·23 + 8·18	·24 ·26	+ 5·84 + 5·80	48.30		.84	+ 1·38 + 1·84
•24	+ 8·18 + 8·18	.28	+ 5.75		+ 8.52 + 8.48	-86	
•26	8.09	47.80	+ 5.71	•84	+ 8.44	•88	+ 1·29 + 1·25
∙28	+ 8·09 + 8·04	-82	+ 5.67	•36	+ 3.39	49.40	+ 1.21
46.30	+ 7.99	•34	+ 5.62	-88	+ 8.35	•42	+ 1.17
·82	+ 7.94	•36	+ 5.58	48.40	+ 8.81	•44	+ 1.18
•84	+ 7.90	.38	+ 5.58	•42	+ 8·27 + 8·22	•46 •48	+ 1.09
•36 •38	+ 7·85 + 7·81	47:40	+ 5·49 + 5·44	·44 ·46	+ 8.22   + 8.18	49.50	+ 1.01
46.40	+ 7·81 + 7·76	-44	+ 5·44 + 5·40	•48	+ 8.18	-52	+ 0.97
•42	7.71	•46	+ 5.95	48.50	+ 8.09	•54	+ 0.98
•44	+ 7.67	•48	+ 5.81	52	+ 8.05	.56	+ 0.89
•46	+ 7.62	47.50	+ 5.26	•54	+ 8.01	•58	+ 0.85
•48	+ 7.58	.52	+ 5.22	•56	+ 2.96	49.60	+ 0.81
46.50	+ 7.53	•54	+ 5.17	•58	+ 2.92	-62	+ 0.77
.52	+ 7.48	-56	+ 5.13	48.60	+ 2.88 + 2.84	·64 ·66	+ 0.73 + 0.68
•54 •56	+ 7·44 + 7·89	·58 47·60	+ 5.08	·62 •64	+ 2·80	-68	+ 0.64
•58	+ 7.85	-62	+ 5.00	•66	+ 2.75	49.70	+ 0.60
46.60	+ 7.30	•64	+ 4.95	.68	2.71	.72	+ 0.56
-62	+ 7.25	•66	+ 4.91	48.70	+ 2.67	•74	+ 0.52
•64	+ 7.21	•68	+ 4.86	.72	+ 2.68	•76	+ 0.48
•66	+ 7.16	47.70	+ 4.82	.74	+ 2.59	•78	+ 0.44
.68	+ 7.12	•72	+ 4.78	•76	+ 2.54	49·80 •82	+ 0.40
<b>-46</b> ·70	+ 7.07	•74	+ 4·78 + 4·69	•78 48·80	+ 2·50 + 2·46	·84	+ 0.86 + 0.82
·72 ·74	$\begin{array}{c c} + & 7.02 \\ + & 6.98 \end{array}$	·76 ·78	+ 4·69 + 4·64	-82		•86	+ 0.52
•76	+ 6.93	47.80	+ 4.60	.84	+ 2.88	•88	+ 0.24
•78	+ 6.89	* 82	+ 4.66	-86	1 1 2.00	49.90	+ 0.50
46.80	+ 6.84	.84	+ 4.51	∙88	+ 2·29	•92	+ 0.16
-82	+ 6.79	-86	+ 4.47	48.90	1 + 2 20	•94	+ 0.13
<b>'84</b>	+ 6.75	.88	+ 4.42	•92	+ 2.21	•96	+ 0.08
*86	+ 6.70	47.90	+ 4.88	•94	+ 2·17 + 2·12	.98	+ 0.04
-88 -46 90	+ 6.66	·92 •94	+ 4·84 + 4·80	·96 ·98	+ 2.12 + 2.08	50·00 •02	Nil. - 0:04
92	+ 6.26	96	+ 4·80 + 4·25	49.00	+ 2.04	•04	→ 0.08
-94	+ 6.52	98	+ 4.21	20.02	+ 2.00	•06	- 0.13
•96	+ 6.47	48.00	4.17	·04	1.96	•08	- 0.16
•98	+ 6.48	.02	4.18	•06	+ 1.91	50.10	- 0.50
47.00	+ 6.88	•04	+ 4.08	.08	+ 1.87	•12	- 0.24
.02	+ 6.84	•06	+ 4:04	49.10	+ 1.83	•14	- 0.28
•04	+ 6·29 + 6·25	108	+ 8.99	·12 ·14	+ 1·79 + 1·75	·16 ·18	- 0·82 - 0·86
•06	+ 6.25	48.10	+ 8.95	.14	T 7.10	.10	_ U.00

	egistering Feet.		egistering Feet.		egistering Feet.	Meter R 50	egistering Feet.
Reading of Scale of Gas- holder.	Amount of Error.	Reading of Scale of Gas- holder.	Amount of Error.	Reading of Scale of Gas- holder.	Amount of Error.	Reading of Scale of Gas- holder.	Amount of Error.
Feet. 50 200 224 226 228 232 344 246 248 50 50 42 24 24 24 24 24 24 24 24 24 24 24 24	Per Cent 0 · 40 - 0 · 44 - 0 · 52 - 0 · 60 - 0 · 60 - 0 · 68 - 0 · 69 - 0 · 69 - 0 · 69 - 0 · 69 - 0 · 69 - 0 · 69 - 0 · 69 - 0 · 69 - 1 · 69 - 0 · 69 - 1 · 69 - 1 · 11 - 1 · 12 - 1 · 12 - 1 · 13 - 1 · 14 - 1 · 16 -	Feet. 51:24	#44498761559260976008751599206014181122298834445155826607477815944813144867655489	Feet. 52:70 •76 •85 •90 •95 58:00 •15 •20 •25 •80 •45 58:50 •65 •70 •75 •80 •96 •16 •16 •25 •80 •35 •40 •15 •80 •65 •70 •75 •80 •96 •65 •70 •75 •80 •96 •65 •70 •75 •80 •96 •65 •70 •75 •80 •96 •65 •70 •75 •80 •96 •65 •70 •75 •80 •96 •65 •70 •75 •80 •96 •96 •96 •96 •96 •96 •96 •96 •96 •96	Per Cont	Feet. 55:30 - 85 - 40 - 45 - 55:50 - 65 - 60 - 65 - 90 - 95 - 90 - 95 - 10 - 15 - 20 - 25	Per Cent 9·59 - 9·67 - 9·75 - 9·88 - 9·91 - 10·17 - 10·15 - 10·31 - 10·39 - 10·63 - 10·63 - 10·63 - 10·71 - 10·79 - 10·87 - 10·95 - 11·11:

Moter Registering 100 Feet.		Meter Registering 100 Feet.		Meter Registering 100 Feet.		Meter Registering 100 Feet.	
Reading of Scale of Gas- holder.	Amount of Error.	Reading of Scale of Gas- holder.	Amount of Error.	Reading of Scale of Gas- holder.	Amount of Error.	Reading of Scale of Gas- holder.	Amount of Error.
Feet. 90.00	Per Cent. + 11.11	Feet.	Per Cent. + 7.98	Feet. 95.80	Per Cent. + 4.98	Feet. 97·95	Per Cent. + 2.09
.05	+ 11.05	92.65	+ 7·98 + 7·87	.85	+ 4.98 + 4.87	98.00	+ 2·09 + 2·04
•10	+ 10.99	•75	7.82	•40	+ 4.82	.05	+ 1.99
•15	+ 10.92	•80	+ 7.76	45	+ 4.76	.10	+ 1.94
·20 ·25	+ 10.80	·85 ·90	+ 7·70 + 7·64	95·50 ·55	+ 4·71 + 4·65	·15 ·20	+ 1.88
-80	+ 10.74	-95	+ 7.59	.60	+ 4.60	.25	1.78
•85	+ 10.68	98.00	+ 7.58	.65	+ 4.54	.80	+ 1.78
:40	+ 10.62	.05	+ 7.47	•70	+ 4.49	.85	+ 1.68
90.50	+ 10.56 + 10.50	·10 ·15	+ 7·41 + 7·86	·75 ·80	+ 4·48 + 4·38	·40 ·45	+ 1.68
55.55	+ 10.44	.20	+ 7·86 + 7·80	-85	+ 4·38 + 4·33	98.20	+ 1.62
.60	+ 10.88	•25	+ 7.24	.80	+ 4.28	.55	+ 1.47
.65	+ 10.81	.80	+ 7.18	•95	+ 4.22	.60	+ 1.42
·70 •75	+ 10·25 + 10·19	·85 ·40	+ 7.18	96·00 •05	+ 4·17   + 4·11	·65 ·70	+ 1.82
-80	+ 10.18	•45	+ 7·07 + 7·01	•10	+ 4·11 + 4·06	-75	+ 1.26
·85	+ 10.07	93.50	+ 6.95	•15	+ 4.00	-80	1.21
.90	+ 10.01	.55	+ 6.90	•20	+ 8.95	-85	+ 1.16
91·00	+ 9.89	·60 ·65	+ 6.84 + 6.78	•25 •80	+ 8.89	·90 ·95	+ 1.11
31.00	+ 9.83	.70	+ 6·78 + 6·72	35	+ 8·84 + 8·78	88.00	+ 1.01
·10	+ 9.77	•75	+ 6.66	•40	+ 8.78	99.00	+ 0.96
•15	+ 9.71	-80	+ 6.61	•45	+ 8.68	.10	+ 0.91
.20		.85	+ 6.55	96.50	+ 8.68	15	+ 0.86
·25 ·80	+ 9.59	·90 ·95	+ 6.50	·55 ·60	+ 8·57 + 8·52	·20 ·25	+ 0.81
-85	+ 9.47	94.00	+ 6.44 + 6.88	-65	+ 8·52 + 8·46	-80	+ 0.75
•40	+ 9.41	•05	+ 6.82	•70	3.41	.85	+ 0.65
•45	+ 9.85 + 9.29	·10	+ 6.27	•75	+ 8.36	•40	+ 0.60
91.50	+ 9·29 + 9·29	·15 ·20	+6.16	·80 ·85	+ 8.81	45	+ 0.55
.60	+ 9·28 + 9·17	•25	+6.10	.90	+ 3·25 + 3·20	99.50	+ 0.45
-65	止 0・11	.80	+ 6.04	.95	+ 8.14	.60	∓ 0·40
·70	+ 9.05	*85	+ 5.98	97.00	+ 3.09	•65	+ 0.85
·75 ·80	ו שמים 🕂	·40 ·45	+ 5.93	.05	+ 8.04	·70 ·75	+ 0.30
·85	+ 8.98 + 8.87	94.50	+ 5·87 + 5·82	·10 ·15	$\begin{array}{c c} + & 2.99 \\ + & 2.93 \end{array}$	.80	+ 0.50
-90	+ 8.81	•55	+ 5.76	-20	+ 2.88	-85	+ 0.15
.95	+ 8.76	.60	+ 5.71	•25	+ 2.82	•90	+ 0.10
92.00	+ 8.70	·65	+ 5.65	.80	+ 2.77	.95	+ 0.05
·05	+ 8.64 + 8.58	·70 ·75	+ 5.60 + 5.54	·85 ·40	+ 2.72   + 2.67	100.00	Nil. - 0.05
.15	+ 8.52	•80	+ 5.49	•45	2.61	.10	<b>-</b> 0·10
∙20	+ 8.46	•85	+ 5.48	97.50	+ 2.56	15	<b>-</b> 0·15
25	+ 8·40 + 8·84	.90	+ 5.37	•55	+ 2.51	.20	- 0.20
·80 ·85	+ 8.84 + 8.29	95·00	+ 5·31 + 5·26	·60 ·65	+ 2·46 + 2·40	·25 ·80	- 0·25 - 0·80
.40	+ 8.23	∞·05	+ 5.20	.70	+ 2.85	•35	- 0.85
-45	+ 8.17	•10	+ 5.15	•75	+ 2.30	•40	- 0.40
92.50	+ 8.11	•15	+ 5.09	.80	+ 2.25	*45	- 0.45
·55 ·60	+ 8.05	·20 ·25	+ 5·04 + 4·98	·85 ·90	+ 2·20 + 2·15	100.50	- 0·50 - 0·55

Meter Registering 100 Feet.		Meter Registering 100 Feet.		Meter Registering 100 Feet.		Meter Registering 100 Feet.	
Reading of Scale of Gas- holder.	Amount of Error.						
Feet. 100 · 60	Per Cent. - 0.60	Feet. 103 · 25	Per Cent. - 3:15	Feet. 105 · 90	Per Cent. - 5.57	Feet. 108 55	Per Cent. - 7.88
•65	- 0.65	100 20	- 8·19	100 90	- 5.62	100.60	- 7·92
•70	- 0.70	.35	- 8.24	106.00	- 5.66	.65	- 7.96
.75	- 0.75	•40	- 8.29	∙05	- 5.71	.70	- 8.00
•80	- 0.79	•45	- 8.84	.10	- 5.75	•75	- 8.05
•85	- 0.84	108.50	- 8.38	•15	- 5.80	.80	- 8.09
·90 ·95	- 0·89 - 0·94	·55 ·60	- 8·48 - 8·47	·20 ·25	- 5.84	·85	- 8·13 - 8·17
101.00	- 0·94 - 0·99	-65	- 8·52	-30	- 5·88 - 5·98	·90 ·95	- 8.22
•05	- 1.04	.70	- 8.57	-85	- 5·98 - 5·98	109.00	- 8·26
.10	- 1.09	.75	- 8.61	•40	- 6.02	105.05	- 8·30
•15	_ I·14	-80	- 3.66	•45	- 6.06	·ĭŏ	- 8.84
•20	<b>- 1·19</b> .	∙85	_ 8·71	106 · 50	- 6.10	•15	<b>—</b> 8·38
•25	- 1.24	.80	- 8.75	•55	- 6.12	•20	- 8·42
.80	- 1.28	.95	- 3.80	•60	- 6.19	•25	- 8.47
·85 ·40	- 1·88	104.00	- 8·85 - 8·90	·65	- 6·24 - 6·28	·30 ·35	- 8:51 - 8:55
•45	- 1·48	.10	_ 3.94	.75	- 6.38	•40	- 8·59
101 · 50	- 1.48	.15	_ 8·99	-80	- 6.87	•45	- 8.64
•55	- 1·53	.20	- 4·03	-85	- 6.41	109.50	- 8·68
•60	_ 1·57	•25	_ 4·08	-90	- 6.45	•55	- 8.72
•65	- 1.62	-80	- 4.13	•95	- 6.20	-60	<b>8.76</b>
•70	- 1.67	-85	_ 4.17	107.00	- 6.54	.65	- 8·80
•75 •80	- 1·72 - 1·77	·40 ·45	- 4·21 - 4·26	·05	- 6.59	.70	- 8·84 - 8·89
-85	- 1·82	104.50	- 4·81	.15	- 6·68 - 6·68	•75 •80	- 8·93
.80	- 1·87	•55	- 4·36	.20	- 6.72	-85	8.97
•95	- 1·9i	-60	- 4.40	•25	- 6.76	.90	- 9.01
102.00	- 1·96	•65	- 4·45	.30	- 6.80	•95	<b></b> 9·05.
.05	- 2·01	•70	<b>4.49</b>	35	- 6.85	110.00	- 9.09
·10	- 2.06	.75	- 4.54	•40	- 6.89	·10	- 9.18
•15 •20	- 2.10	.80	- 4·63	100.50	- 6.94	•20	- 9·26 - 9·34
•25	- 2·15 - 2·20	·85 ·90	- 4·67	107.50	- 6·98 - 7·02	·30 ·40	- 9.42
.80	- 2·25	.95	4.72	.60	7.06	-50	- 9.51
•85	- 2·30	105.00	- 4.76	-65	- 7.11	-60	- 9·59·
•40	<b>- 2.84</b>	-05	- 4.81	.70	- 7.15	.70	- 9.67
•45	<b>– 2·39</b>	∙10	- 4.85	•75	- 7.20	∙80	9.75
102.50	- 2.44	•15	- 4.90	-80	- 7.24	.90	- 9.83
•55	- 2.49	•20	- 4.94	·85	- 7.28	111:00	- 9.91
•60 •65	- 2·58 - 2·58	·25 ·80	- 4·99 - 5·08	·90 ·95	- 7·32 - 7·87	·10 ·20	- 9·99 - 10·07
.70	- 2.68	-85	- 5.08	108.00	7.41	-80	- 10.15
•75	- 2.68	.40	- 5.12	.05	7.45	·40	- 10.23
·80	- 2.72	•45	- 5.17	•10	- 7.49	-50	- 10.31
85	<b>- 2</b> ·78	105 · 50	- 5.21	.15	- 7.54	.60	- 10.39
.80	- 2.82	•55	- 5.26	•20	- 7.58	•70	- 10.47
•95	- 2.87	•60	- 5.30	•25	- 7.62	.80	- 10.55
108:00	- 2·91 - 2·96	•65	- 5.85	:80	- 7·66	.90	- 10·63 - 10·71
·05 ·10	- 8·01	•70 •75	- 5·39 - 5·44	·35 ·40	- 7·71 - 7·75	112·00 ·10	- 10·71 - 10·79
.15	- 8.08	-80	- 5.48	-45	7.79	•20	- 10.87
·20	- 8.10	-85		108.50	- 7.83	.80	- 10.96

Note.—Any other quantity may be calculated by the rule of proportion, thus:—

Meter registering . . . . . . 100·00 feet Reading of scale of test gasholder . . 89·95 ,,

Difference . . . . . . 10.05 ,,

89.95:100::10.05:11.17 fast.

And Meter registering . . . . . . 100.00 feet Reading of scale of test gasholder . . 112.55 ,,

112.55: 100::12.55:11.15 slow.

#### TABLE

Showing the Dilatation of Gas in Contact with Water and Saturated with Aqueous Vapour, for given Temperature. (Professor Airey.)

(Used in making Corrections for Temperature in the Testing of Gas Meters.)

Temperature in Fahrenheit's Scale.	Percentage of Dilatation.	Temperature in Fahrenheit's Scale.	Percentage of Dilatation.	Temperature in Fahrenheit's Scale.	Percentage of Dilatation.
81 · 40	0	54.88	51	74.80	11
88 • 54	à	56.24	6	75.94	111
85.70	1	58.12	64	77.23	12
87.84	14	60.02	7	78 · 81	124
89.91	2	62.00	7	80.40	18
42.05	21	68 · 77	8	81 · 94	18 <del>1</del>
44.17	8	65 · 68	81	88 • 44	14
46 · 22	81	67:48	9	84.88	144
48 · 25	4	69 · 18	94	86.89	15
50.82	41	70.90	10	87 - 88	15 <del>1</del>
52.86	5	72.60	101	89.20	16

Note.—The table shows the percentage of increase of the volume of gas above its volume at the temperature of 81.4° Fahr.

### INTERNAL FITTINGS.

The advantages of an ample supply of good and pure gas are frequently neutralized by the defective manner in which premises are fitted internally.

Bad gas-fittings are generally the result of cupidity or ignorance. They are a common cause of complaint from consumers, who are often ready to attribute the inefficient light which they afford to a want of pressure or purity, or a low illuminating power in the gas.

In the matter of internal fittings, the gas manager, by judgment and tact, can exercise a useful supervision even without the aid of statutory powers; and his advice in regard to the sizes of pipes, and the kind of burners and lamps to be used in different situations, will generally be accepted and acted upon.

The following regulations (with such additions and modifications as may be found necessary) may be adopted with advantage by gas Authorities.

# Regulations as to Internal Fittings.

- 1. The Company's (or Local Authority's) servants will in all cases lay on the service-pipe, conveying the same through the outer wall of the premises to be supplied with gas.
- 2. The main-cock must be attached to the end of the service-pipe within the building, and close to the outer wall.
- 8. The gas meter must be placed perfectly level, either on the floor or on a substantial support, and within 2 ft. 6 in. of the main-cock.
- 4. The piping attached to the meter, whether inlet or outlet, must not be smaller in internal diameter than that of the meter unions.
- 5. The following are the sizes of the meters, and their measuring capacity, from which the number of lights which they supply can be readily calculated:—

Size Met	ers.					_	Size nlet : Outle Inche	and et.				Cap	easuri pacity voluti bic Fe	per on.				Ca	deasuring spacity per Hour. spic Feet.
2-1	ight						à						4,8						12
8	-	_					ā		_				i						18
8 5	**	•	•	•	-	٠	- 2	•	•	•	•	•	ï	-		- 1			80
10	"	•	•	•	•	•	٠,*	•	•	•	•	•	•	•	•	•	•	•	60
	"	•	٠	•	•	•	÷	٠	•	•	•	•	3	•	•	•	•	•	90
15	**	•	٠	•	•	•	1	•	•	٠	•	•		٠	•	٠	٠	•	
20	**						11						1	•	•	•			120
30	**						11						14						180
50	"	_					1#						24						800
		•	•	•	-	-	ĩi	-	-	٠	•	•	8						360
60 80	,,	•	•	•	•	•	13	•	•	•	•	•	4	•	•	•	:	•	480
-00	,,	•	٠	٠	•	•		•	•	•	•	•	3	•	•	•		•	600
100	,,	•	٠		•	٠	2	•	•	•	•	•	5	•	٠	•	•	•	
150	"						8			•	•		7		•			٠	900
200	"						8						10						1200
250							4	_		_	_	_	124						1500
300	11	•	•	•	•	•	ā	•	•	•	•	•	15			-	-	-	1800
	,,	•	•	•	•	•	7	٠	•	•	•	•	20	•	•	•	•	•	2400
400	٠,	•	•	•	•	•	7	•	•	•	•	•		•	•	•	•	•	3000
500	,,	•	٠	•	•	•	5	•	•	•	•	٠	25	•	•	٠	•	•	
600	**	•	•	•	•	•	5	•	•	•	•	•	30	•	•	•	•	•	8600

To ascertain the number of lights which any size of meter will supply, divide the measuring capacity per hour by the quantity of gas per hour which each jet is estimated to consume. Example: What number of lights, consuming 4 cubic feet of gas per hour, will a

20-light meter supply? Then, 
$$\frac{120}{4} = 80$$
 lights.

6. The following are the sizes and lengths of iron, lead, or composition tubes to be used according to the number of ordinary lights:—

Internal Diam of Tubing. Inches.	ete	r				Gr	eatest Len allowed. Feet.	gth							0	reatest No. f Burners allowed.
ł							20									8
ä							30									6
į.	-			-			40									12
. i	•	•	•	. •	•	•	50			-						20
ı*	•	•	•	•	•	•	70	•	•	•	•	•	•	•	•	35
11	•	•	•	•	•	•	100	•	•	•	•	•	•	•	•	60
11	•	•	•	•	•	•	150	•	•	•	•	•	•	•	•	100
78	•	•	•	•	•	•		•	•	•	•	•	•	•	•	100
2		•			•	•	200	•	•	•		•	•		•	200

Tubing of 1-inch bore is not allowed to be used.

- 7. The tubes or pipes must be laid with proper fall, and in such a manner that they are easily accessible, and protected from liability to damage. Attention is to be given to leaving a space round them at such places as wall crossings, &c., where fracture or crushing of the pipes might be caused by the subsidence of the building. The joinings of the tubes and pipes are to be made in the most solid and substantial manner; and carefully rounded bends (not elbows) are to be used wherever the direction of a pipe is changed.
- 8. Floor boards covering pipes must be secured with screws, so that they may be easily removed to afford access to the pipes, especially at the points of connection.
- 9. On the completion of the work of fitting, and before the piping is covered up, notice thereof must be given in writing to the gas manager (the requisite form for that purpose being obtained at the gas office), who will cause an inspection to be made of the work, and if found in accordance with the regulations herein contained, it will be passed by the Company (or Local Authority), and the gas turned on.
- 10. If the regulations are not conformed to in every respect, the Company (or Local Authority) reserve the right to refuse a supply of gas until the necessary alterations are made.
  - 11. Gas-fitters complying with these regulations have their names

registered on the Company's (or Local Authority's) list of approved fitters, and they are at liberty to designate themselves "Authorized Gas-Fitters." Repeated negligence will cause the license to be withdrawn.

A handy and useful apparatus for testing the soundness of gasfittings, has been devised by Harrison and Sheard. It consists of a small force pump and a King's pressure-gauge, in which mercury is employed instead of water; the two being connected together on one base board, and provided with a coupling for ready attachment to the fittings to be tested.

To use the apparatus, air is forced, by means of the pump, into the fittings until the pressure therein is equivalent to, say, 12 inches of water, as indicated on the dial of the gauge. The pump is then shut off by means of a stopcock, and it is noted whether the pressure is maintained or falls away. If the pointer remains stationary, the fittings are sound; while if it goes back, there is a leakage.

To facilitate the discovery of leakages, gas may be forced into the fittings, by connecting an inlet pipe on the pump, by means of indiarubber tubing, with any convenient gas supply; when the gas escaping through the defective fittings at a high pressure, enables the locality of the leakages to be readily discovered.

Ordinary sitting rooms are best lighted by means of a central chandelier. When the room is of large dimensions, wall brackets may be added. A bracket at each side of the mantelpiece has a tasteful appearance, and lights are handy in that position.

The jets of chandeliers and brackets should be not less than 86 inches from the ceiling.


A tea-spoonful of salad oil added on the top of the water in the tube of a water-slide pendant, tends, in a great measure, to prevent or retard evaporation of the water.

Burners arranged in the horizontal position are not usually effective, and are not to be recommended except on the conditions noted hereafter. The flames of such have an unpleasant pulsatory or tremulous motion, very disagreeable when fixed on a level with or but slightly above the eye of the spectator, due to the upward current of air striking the underside.

The arrangement is bad for another reason—viz., the flame is

prevented from receiving its due supply of oxygen on all sides, and as a consequence, the combustion is imperfect; bad illumination, and a deposit of unconsumed carbon on the ceiling being the result.

It is not, however, to be assumed that lights placed in the horizontal or the inclined position are never effective. They can be rendered so



F16. 141.

by causing the tails of the flames to impinge one upon the other, and by making provision in the construction of the pendant for the air current to play upon the upper surface of the flame.

The question of the efficient ventilation of rooms where gas is being consumed is one of importance both to the gas producer and the user. The subjecthas been a comparatively neglected one, although it deserves to occupy greater prominence.

Ventilating globe and other lights of various designs have been introduced by Sugg, Cowan, Bray, Strode, Wenham (whose lamp is also regenerative), and other makers, with highly satisfactory results. Fig. 141 shows Cowan's ventilating globe light; and Fig. 142, the ventilating sunlight as made by Strode.

Gas burners are made with a precision unknown in the earlier days of gas lighting, and great improvements have been effected in their construction.

The old iron burner, which at one time was generally in use, robbing the flame

of a proportion of its heat, has been supplanted by those made either wholly from steatite, lava, enamel, or other refractory non-conducting material, or tipped with these substances.

These are not only more efficient in action, but they are less subject to blocking, and they are more durable.

The burners made by Geo. Bray & Co. are so well known as to need no recommendation, their merits being universally recognized; but it is only fair that the important services which these makers have

rendered to the gas industry in this and other departments should be freely acknowledged.

Shades, moons, or globes, as they are variously named, have kept pace with the improvements in burners, being constructed not only of better and purer materials than formerly, but according to scientific principles.

At one time they were invariably made with the bottom openings about 2 inches in diameter; the effect being to direct the current of air upon the flame, lowering the temperature, impairing the illuminating effect, and causing an unpleasant flickering.

These have given place to globes with openings at least 4 inches in diameter, whereby the foregoing defects are entirely obviated, whilst the concave sides also act as reflectors of the light in the downward



direction, especially below 45° from the horizontal. As Professor Lewes points out: " "In order to gain any true idea of illuminating effect, it is necessary to take the light emitted over all the working angles, and not on the horizontal plane."

Globes made of good and suitable materials, and untinted, diffuse the light without seriously obstructing it. even when the test is applied on the

horizontal plane. This is particularly noticeable with the "holophane" globe recently introduced, and with the pure white opal globes.

For estimating (approximately) the number of burners required to light churches, public halls, and other large buildings, divide the floor area in feet by 60, and the quotient will be the number of flat-flame burners, consuming 16-candle gas, required for effective lighting.

Thus: A room is 80 ft. long and 56 ft. wide.

Then,  $-80 \times 56 = 4480$  sq. ft. area, and

= 74 burners consuming 5 cubic feet of gas per hour each.

The Welsbach system of incandescent gas-lighting marks a notable advance in artificial illumination. The Welsbach lamp consists of a Bunsen burner, over which is suspended a mantle, composed of a

<sup>\*</sup> Cantor Lecture, Society of Arts, delivered Nov. 80, 1896.

textile filament coated with certain rare refractory oxides. On lighting the burner, the textile portion is consumed, leaving the refractory portion in position, and this at once becomes incandescent, giving out a strong steady light. The fragility of the mantle was a hindrance to its early adoption, but this has proved to be less of a drawback than was at first anticipated, as is shown by the fact of the wide application of the system. The saving of gas that is effected by its use, the increase in illuminating effect, and the comparative coolness of the light, with other advantages, have earned for it a deserved reputation.

To obtain the maximum of light from a burner, the pressure, when that is in excess in the mains, as it must necessarily be, should be controlled and regulated in the passage of the gas to the point of ignition.

This cannot be accomplished satisfactorily by checking either the taps on the fittings, or the stopcock at the meter, because there is a continual variation of pressure according to the consumption that is in progress.

The house governor or regulator was invented to achieve that end. It may be fixed on the pipe leading from the meter outlet, or what is better, on the principal pipe supplying each floor level of the premises.

The regulator is automatic in its action; and when weighted to afford the required pressure for all the burners in use, it will continue to give a practically uniform supply, however much the pressure in the mains may vary, or whether the whole or only a portion of the burners being supplied through it may be alight at one time. Sugg's regulator burner, Peebles's "Needle" governor burner, and the "Acme" regulating burner of Wright, are examples of regulation applied close to the point of consumption.

It is a clearly established fact that the lower the pressure (provided there is just sufficient) at which gas can be burned, the better the light. If, instead of being advantageously consumed, the gas is forced through the burners into the atmosphere, the carbon is rapidly oxidized by the excess of air drawn into the flame by the heavy pressure, with the usual unsatisfactory results as regards illumination.

Dr. Letheby found that a vulcanized india-rubber tube of about 80 ft. in length, reduced the power of a weak gas to the extent of nearly 25 per cent., by absorbing the illuminating hydrocarbons.

Varnish to Prevent the Escape of Gas through India-Rubber Tubing.

1½ parts treacle.

2 ,, gum arabic.

7 ,, white wine.

81 ,, strong alcohol.

First dissolve the treacle and gum in the white wine, and afterwards add the alcohol very slowly, constantly stirring the mixture to prevent the gum from being thrown down.

# LEAD AND COMPOSITION PIPES FOR GAS.

Weights per Yard, and Longths usually Manufactured.

				L	IGHT					1				H	BAVY				
	ameter inside.			¥	eight er ard.			Bu	ths of ndles ually actured.		uneter nside.			p	eight er rd.			Bun	hs of dies ally otured.
ł	inch.			0	114				yards.	1	inob.			0	15			67	yards.
1000	,, ,, ,,	:	:	1 2 2 8	2 0 4 8 8	:	:	60 82 25 28 28	;; ;; ;;	40.00	" "	:	:	1 2 8 8 6	6½ 10 0 12 0	:	:	46 16 20 19 20	" " "
1; 1; 1; 2	" " "	:	:	8 12 18	0	:	•	16 10 5	" " "	11 11 2	" "	:	:	10 14 21	0	:	:	12 9 5	1) 2) 1)

### BRASS TUBE, PLAIN-WEIGHT PER FOOT.

Diamete Inches 1-4th								Wei lbs. ·06 or	OE.	Diameter Inches								lbs.	Veight. oz. or 8.00
T-2911	•	•	•	•	•	•	•				٠	•	•	•	•	•	•	- 30	or o w
5-16ths								·15	2.40	1 inch								•59	9.44
8-8ths								·19	8.04	11,,,								•81	12.96
7-16ths								•21	8.86	11,								1.00	16.00
1-half								•25	4.00	14 ,,								1.12	17.92
9-16ths								•81	4.96	2 ,,						-		1.25	20.00
5-8ths	-		Ĺ					·87	5.92	21 ,,								1.50	24.00
8-4ths		Ċ	·					•48	6.88	8 ,,	:	·		:		:	·	1.87	29.92

The size of brass and copper tube is measured by the outside diameter.

# BRASS TUBE, SPIRAL AND FLUTED—WEIGHT PER FOOT.

Diamete Inches 8-8ths					Spira. Teigh oz.					luted, leight. oz. 24	Diameter. Inches. 8-4ths.	_			Spire Veigh os.				Fluted, Weight.
7-16ths	:	·			81					81	7-8ths				71	:	:	:	. ř
1-half				•	84	•	•	•	•	81	1 inch				9				. 8
9-16ths	•	•	•	•	43	٠	•	•	•	4	11 ,,		•	٠	12				. 11
5-8ths	•	•	•	•	Ð	•	•	•	•	D	1½ ,,	٠	٠	٠	15	•	•		. 14

#### SOLDERS.

Fine Solder is an alloy of 2 parts of block tin and 1 of lead (melts at 860° Fahr.). This is used for fine work—such as soldering the drums of meters, for pewter, &c.

Glazing Solder.—Equal parts of block tin and lead. Used for lead.

**Plumbing Solder.**—1 part block tin, 2 lead. For all kinds of plumbers' joints and for tin and zinc.

Solder for Copper.—Hard: 3 parts brass, 1 zinc. Soft: 8 brass, 1 zinc.

Brazing Solder or Spelter.—Hard: 1 part copper, 1 zinc. Soft: 4 parts copper, 8 zinc, 1 block tin. For fine brass work: 1 part silver, 8 copper, 8 zinc.

Solder for Steel.—19 parts silver, 8 copper, 1 zinc.

Pewterers' Soft Solder.—2 parts bismuth, 4 lead, 8 tin. Common: 1 part bismuth, 1 lead, 2 tin.

#### FLUXES FOR SOLDERING.

Iron and steel	Borax or sal ammoniac.
Tinned iron	Resin or chloride of zinc.
Copper and brass	Sal ammoniac or chloride of zinc.
Lead and composition pipes	Resin and sweet oil.
Zinc	Chloride of zinc.

### FOR TINNING BRASS OR IRON.

½ oz. muriatic acid.

1 oz. mercury.

doz. ground block tin.

Mix together, and dilute the whole with a small quantity of cold water. Apply with the finger or a cork.

#### BRAZING.

The edges of the articles, either iron or brass, to be brazed are scraped thoroughly clean, covered with the brazing solder or spelter in the form of borings or turnings sprinkled over with powdered borax, and exposed to the heat of a clear fire till the solder flows. A smokeless coke or gas fire is best for the purpose. In brazing iron, a covering of loam is sometimes placed over the solder, to exclude the air, till it melts.

#### BRONZE.

1 quart common vinegar.

2 ozs. sal ammoniac.

1 oz. blue stone (sulphate of copper).

The sal ammoniac and blue stone are well pounded, and then allowed to dissolve in the vinegar. The solution, when ready, is laid on with a common brush, black-leaded whilst damp, and then polished. Lacquer is then applied as described hereafter.

Green Bronze.

To imitate the antique.

1 quart common vinegar.

2 ozs. verdigris.

1 oz. sal ammoniac.

Boil for a quarter of an hour, filter through paper, and dilute with water. Immerse the article to be bronzed until it acquires the green tinge desired; then wash carefully, and dry in sawdust.

Bronze Powders.

These can be purchased from any dealer in artists' material. They are prepared as follows:—

Copper Bronze Powder.

Strips of copper are dissolved in nitric acid in a glass vessel, and then strips of iron are added, when the dissolved copper is precipitated in the form of a very fine powder. This powder is washed with water and dried, and is then ready for use.

Gold Bronze Powder, or Aurum Mosaicum,

Is the basis of many bronze powders. Any desired colour can be produced by mixing it with the common dry pigments. Thus a red bronze powder is obtained by grinding red lead with it; and a green by the use of verdigris. It is prepared in the following manner:—

One pound of tin is melted in a crucible, and then poured cautiously into an iron dish containing half a pound of mercury. When cold it is reduced to powder, mixed with seven ounces of flowers of sulphur, and eight ounces of sal ammoniac, and triturated in a mortar. The mixture is then calcined in a flask, which expels the sulphur, mercury, and ammonia, and leaves a residuum in the form and colour of a bright flaky gold powder.

#### Size for Bronze Powders.

The size is made by boiling four ounces of gum animi to every pound of pure linseed oil in a flask, until the mixture is of the consistency of cream; after which it is diluted with turpentine as required.

The article to be bronzed is coated, by means of a soft brush, with this size; and when nearly dry, a piece of soft leather is wrapped round the finger, dipped into the powder, and rubbed gently over it; or it may be laid on with a camel's-hair pencil, and then left to dry thoroughly; after which all the loose powder is brushed off.

The bronze may also be mixed with a strong solution of isinglass, and applied in the moist state, like varnish, with a brush. This latter mode, however, is not suitable for articles exposed to the weather.

For Silvering Metals.

Nitrate of silver 10 parts.

Common salt 10,

Cream of tartar 80 ,,

Moisten with water when ready to apply, and lay the mixture on with a soft brush.

# LACQUER AND VARNISH.

The solution of spirits of wine and shellac, known as "simple pale" lacquer, is the basis of most other lacquers. The two ingredients in their proper proportions, as stated overleaf, are put into a jar or bottle, and allowed to remain for forty-eight hours, being briskly shaken three or four times during the interval. At the expiration of the time named, most of the shellac will be dissolved. The mixture is then carefully strained through filtering paper, to free it from grit and other foreign substances, and to remove any particles of undissolved shellac that may remain.

Different tints or shades, producing red, green, yellow, &c., are obtained by mixing with the pale lacquer various colouring ingredients, such as dragon's blood, arnotto, gamboge, turmeric, saffron, &c. The proper way of adding these is to stir them in a cup with a small quantity of the pale lacquer, afterwards straining the whole through a piece of thin cloth or gauze, and filtering if necessary.

The article to be lacquered is heated slightly by means of a steam

kettle or stove; or it may be held over a hot iron plate till just as hot as to allow of its being touched by the finger without burning. The heat must not be greater than this. The lacquer is then applied with a soft camel's-hair brush.

Simple Pale Lacquer.

1 pint of spirits of wine.

4 ozs. of shellac.

Fine Pale Lacquer.

1 pint of spirits of wine.

1 oz. of pure white shellac.

1 dr. of gamboge.

2 drs. of Cape aloes.

Fine Pale Lacquer, for Silvered or Tinned Work.

1 pint of spirits of wine.

1 oz. of pure white shellac.

Gold Lacquer.

1 pint of spirits of wine.

3 ozs. of shellac.

1 oz. turmeric.

2 drs. of arnotto.

2 drs. of saffron.

Deep Gold Lacquer.

1 pint of spirits of wine.

3 ozs. of shellac.

½ oz. of turmeric.

4 drs. of dragon's blood.

Red Lacquer.

1 pint of spirits of wine.

4 ozs. of shellac.

4 drs. of dragon's blood.

1 dr. of gamboge.

#### Yellow Lacquer.

- 1 pint of spirits of wine.
- 2 ozs. of shellac.
  - 2 drs. of gamboge.
  - 4 drs. of Cape aloes.

### Green Lacquer for Bronze.

- 1 pint of spirits of wine.
- 4 ozs. of shellac.
- 4 drs. of turmeric.
- 1 dr. of gamboge.

#### Iron Lacquer.

- 1 quart of turpentine.
- 1 lb. of pitch.
- 2 ozs. of shellac.

### To Clean Old Brass Work for Lacquering.

Boil a strong lye of wood ashes, and strengthen with soaplees; put in the brass work, and the old lacquer will come off. Next dip it in a solution of nitric acid and water strong enough to remove the dirt; wash it immediately in clean water; dry well, and lacquer.

# Varnish for Iron Work.

Boil a quantity of gas tar for four or five hours, till it runs as this as water; add one quart of turpentine to a gallon of the tar, and beil another half hour. Apply the varnish whilst hot.

#### Golden Varnish.

Pulverize 1 drachm of saffron and \( \frac{1}{2} \) a drachm of dragon's blood, and put them into 1 pint of spirits of wine. Add 2 ounces of gum shellac and 2 drachms of Soccotrine aloes. Dissolve the whole by gentle heat. Yellow painted work, varnished with this mixture, will appear almost equal to gold.

### Glue Cement to Resist Moisture.

- 1 part glue.
- 1 part black resin.
- 1 part red ochre.

Mix with the least possible quantity of water.

# COAL GAS TESTING APPLIANCES AND METHODS.

A gas may have a high illuminating power, and yet contain impurities that ought to be removed. Purity is not always in the ratio of illuminating power.

#### TESTS FOR IMPURITIES.

The tests for the detection of impurities in coal gas, after it has undergone the different processes of purification, are the following:—

Test for Ammonia.—Expose yellow turmeric paper slightly moistened with water, or litmus paper first reddened by any weak acid, to a jet of unlighted gas for about a minute. If the yellow colour of the turmeric be turned to brown, or if the blue of the litmus be restored, ammonia is present.

Turmeric and litmus papers may be purchased at the chemist's, or they can be prepared as follows:

Turmeric Paper.—Six parts by weight of spirits of wine are added to one of turmeric powder in a stoppered bottle, and well shaken up occasionally for three days. A portion of the clear fluid is then poured on a plate, and pieces of unsized white filtering paper well soaked therein. These are then dried in air, cut into strips half an inch wide and two inches long, and kept for use in a bottle away from the light.

Litmus Paper.—Six parts by weight of water to one of powdered litmus, shaken well together, allowed to stand for several days, and then filtered. Pieces of white filtering paper are then thoroughly soaked in the solution, dried, and cut into strips, which should be kept in a close stoppered bottle, excluded as much as possible from the air and light. Should it be desired to redden the solution, add (after filtration) a small quantity of very dilute sulphuric acid, gradually, drop by drop, until the pink or neutral tinge is obtained.

Test for Carbonic Acid.—Make a solution of pure barytes, and pass the gas through it. If carbonic acid be present, carbonate of barytes will be precipitated; or pass the gas through clear lime water, and carbonate of lime will be precipitated.

It may also be detected by adding to water impregnated with the gas a few drops of sulphuric acid, when minute bubbles of carbonic acid gas will be rapidly disengaged.

Lime Water is prepared by agitating slaked lime with distilled water in a bottle or other vessel. It is then allowed to stand until the excess of lime has been deposited, when the clear liquid is poured off, and filtered through filtering paper.

Test for Sulphuretted Hydrogen.—Moisten a piece of writingpaper with a solution of acetate of lead in distilled water, and expose it for not less than a minute to a jet of unlighted gas. If sulphuretted hydrogen be present, the paper will be browned or blackened.

A solution of nitrate of silver is a more delicate test than the above. This requires to be kept in a bottle coated outside with tinfoil, and placed in a drawer or other dark place to protect it from the influence of the light.

Lead paper may be made of white filtering paper soaked in the acetate of lead solution, then dried, cut into slips, and kept in a well-corked bottle for use. But the solution applied to the paper at the time of making the test is preferable.

The Gas-Works Clauses Act, 1871, Schedule A, contains the following regulations in respect of the apparatus and mode of testing for this impurity:—

Apparatus.—"A glass vessel (Fig. 143) containing a strip of bibulous paper moistened with a solution of acetate of lead, containing 60 grains of crystalized acetate of lead dissolved in one fluid ounce of water.


Mode of Testing.—"The gas shall be passed through the glass vessel containing the strip of bibulous paper moistened with the solution of the acetate of lead for a period of three minutes, or such longer period as may be prescribed; and if any discoloration of the test paper is found to have taken place, this is to be held conclusive as to the presence of sulphuretted hydrogen in the gas."



Fra 149

Test for Sulphur.—The sulphur present in gas, due to compounds other than sulphuretted hydrogen, notably bisulphide of carbon, is estimated by burning a jet of the gas at the rate of one cubic foot, or


half a cubic foot, per hour, for 24 hours, from a Leslie or other burner arranged within the wide end of a trumpet tube whose upper and smaller end is inserted in a condenser, from the opposite end of which a tube carries off the uncondensed vapour, and creates a current through the apparatus. (See Fig. 144.) Through the lower and wide end, where the burner is fixed, a supply of air, to support combustion, enters, carrying with it the vapour of ammonia from liquid ammonia or pieces of the carbonate contained in a suitable receptacle surrounding the burner. ammonia combining with the sulphurous acid from the gas-flame, is deposited within the con-




F10. 144.

denser as sulphite and sulphate of ammonia, from which the quantity of sulphur per 100 cubic feet of gas is calculated.

Mr. J. T. Sheard's method of estimating carbonic acid in coal gas consists in passing a definite volume of gas through a solution of







Frg. 1454.

barium hydrate of known strength, which absorbs the carbonic acid out of the gas; the amount of free hydrate remaining after the operation being determined by titration with deci-normal hydrochloric

acid. Either the volume or the weight of impurity that has been absorbed can thence be calculated.

The gas absorption tube is of the form shown in Fig. 145; the straight part above the bulbs being filled with glass beads.

To make a test, two absorption tubes are charged with 20 or 80 cubic centimetres each, of a barium hydrate solution, the strength of which has been accurately determined by titration with deci-normal acid, and which should be approximately of equal strength, with The apparatus being connected up as shown, Fig. 145A, 500 c.c. of gas are drawn by means of the aspirator slowly through the liquid, and followed immediately, without stopping the current, by an equal quantity of air, which is done by slipping off the indiarubber tube at the inlet of the apparatus, as the water running from the aspirator passes the mark of a 500 c.c. flask, and then running out a further quantity of 500 c.c. into another flask held in readiness. The bulbs are then washed down with water free from carbonic acid. a few drops of the phenol-phthalein (sufficient to impart a distinct purple red colour to the liquid) added, and the whole titrated with deci-normal hydrochloric acid—the acid being added a few drops at a time, with frequent agitation of the liquid until the colour is destroyed. The amount of barium hydrate that has been neutralized is equivalent to the amount of carbonic acid absorbed from 500 c.c. of gas; from which the percentage of the impurity present, or its weight per cubic foot of gas, can be determined.

Example.—Two gas absorption tubes charged, respectively, with 80 c.c. and 20 c.c. of barium hydrate solution. One cubic centimetre of the barium hydrate having previously been found by experiment as

equivalent to 1.09 of  $\frac{N}{10}$  acid.

Equivalent of barium hydrate employed . . . 82.7 c.c. . . 21.8 c.c.

 $\frac{N}{10}$  acid required to neutralize resultant liquid. 21.6 c.c. . . 21.4 c.c.

11·1 c.c. 0·4 c.c.

Then.-

$$\frac{11.5 \text{ c.c.} \times 0.0022 \text{ grm.} \times 100}{0.914 \text{ grm.}} = 2.77 \text{ per cent. by volume of CO}_{2}$$

$$\frac{11.5 \text{ c.c.} \times 0.0022 \text{ grm.} \times 15.482 \text{ grs.} \times 28,815 \text{ c.c.}}{500 \text{ c.c.}} = 22.1$$

grains of CO, per cubic foot of gas.\*

These calculations may be shortened by employing the factor 0.241 for percentage by volume, and 1.92 for grains per cubic foot. Thus—

$$11.5 \times 0.241 = 2.77$$
 per cent. by volume of CO<sub>3</sub>  $11.5 \times 1.92 = 22.1$  grains of CO<sub>3</sub> per cub. ft. of gas.

A complete test can be made in fifteen minutes, and perfectly accurate results obtained.

The apparatus is equally applicable to the estimation of ammonia and sulphuretted hydrogen in the gas, the former being absorbed by sulphuric acid of deci-normal strength and the latter by a 10 per cent. solution of sulphate of copper. When sulphuretted hydrogen is passed into an aqueous solution of cupric sulphate, a precipitate of cupric sulphide is deposited and free sulphuric acid is formed in the solution, previously neutral. After filtering out the precipitate, the acidity of the solution can be determined by titration with deci-normal ammonia, using methyl orange as indicator. Each cubic centimetre of  $\frac{N}{10}$  ammonia required to neutralize the solution represents 1.48 grains of sulphuretted hydrogen per cubic foot of gas. Likewise each c.c. of  $\frac{N}{10}$  acid neutralized by the ammonia in the gas represents 1.48 grains of ammonia per cubic foot of gas.

The manipulation of the apparatus is the same as above described for carbonic acid, and all three impurities may be determined in the same sample of gas. For this purpose one absorption tube is charged with acid for absorbing ammonia, followed by one containing cupric sulphate for sulphuretted hydrogen, and this by the tubes containing barium hydrate for carbonic acid. 500 c.c. of gas are drawn through

<sup>\*</sup> It may be explained that—

<sup>0.0022</sup> grm. is the weight of CO<sub>2</sub> to which 1 c.c. of  $\frac{N}{10}$  acid is equivalent.


<sup>0.914</sup> grm. is the weight of 500 c.c. of CO, saturated with moisture.

<sup>15.432</sup> grs. is the value of 1 gramme. 28,315 c.c. is the value of 1 cubic foot.

the whole series, followed by 1,000 c.c. of air to clear the apparatus. The subsequent treatment will be understood from what has gone before.

Harcourt's Colour Test.—This is one of the most useful apparatus in the gas manager's laboratory for determining with ease and celerity the amount of bisulphide of carbon, sulphuretted hydrogen, and carbonic acid in coal gas. The following is a description of the test, and directions for its use.

Testing for Bisulphide of Carbon.—The arrangement of the colour test is shown in Fig. 146; the fire-clay cylinder being represented.



F10. 146.

by dotted lines. The bulb, which is filled with platinized pumice, is to be so adjusted that it may be about an inch above the burner, and in the middle of the cylinder.

To use the apparatus, turn on first the upper stopcock, sending gasthrough the bulb at the rate of about half a cubic foot an hour, as may be judged by lighting the gas for a moment at the end of the horizontal arm, when a flame about an inch in length should be produced. Raise the cylinder, which will be supported by the pressure of the wires, light the burner, and turn down the flame till it forms a blue non-luminous ring. Lower the cylinder, and place the small clay pieces upon it round the neck of the bulb.

A testing may be made five minutes after the burner is lighted, except when the apparatus is first used, when the gas should be allowed to flow through the bulb for a quarter of an hour, or a little longer, and any number of testings one after another as long as the heat is continued.

The mode of testing is as follows:—Lay a piece of white paper on the table by the side of the burner, and fix a piece of cardboard upright in the brass clip; the cardboard serves as a background against which to observe the colour of the contents of the glasses, and should receive a side light, and be as clear as possible from shadows. Fill one glass (once for all) up to the mark with standard coloured liquid, and cork it tightly. Dilute some of the lead syrup with twenty times its volume of distilled water, and fill the other glass up to the mark with a portion of the liquid thus prepared. Insert the caoutchour plug with capillary-tube and elbow-tube, and connect, as shown in the figure, with the bulb and aspirator, placing the two glasses side by side.

The aspirator should be full of water at starting, and the measuring cylinder empty. Turn the tap of the aspirator gradually; a stream of bubbles will rise through the solution of lead. Turn off the tap for a minute, and observe the liquid at the bottom of the capillary-tube. If it gradually rises, the india-rubber connections are not air-tight, and must be made so before proceeding. Avoid pressing the plugs into the glass or the aspirator while they are connected, which would drive up the lead solution into the inlet-tube. When the connections are air-tight, let the water run into the measuring cylinder in a slender stream until the lead solution has become as dark as the standard. As the ascending bubbles interfere somewhat with the observation of the tint, it is best to turn off the tap when the colour seems almost deep enough; compare the two; turn on the tap, if necessary, for a few moments, then compare again; and so on, till the colour of the two liquids is the same.

The volume of water which the measuring cylinder now contains is equal to the volume of gas which has passed through the lead solution.

This volume of gas contained a quantity of sulphur as carbon bisulphide which, as lead sulphide, has coloured the liquid in the test-

glass up to the standard tint. The standard has been made such that, to impart this tint to the volume of liquid, 0.0187 grain of lead sulphide must be present, containing 0.0025 grain of sulphur. Hence, supposing the measuring cylinder, each division of which corresponds to 1-2000th cubic foot, to have been filled to the 30th division, 80-2000ths cubic foot of gas contained 0.0025 grain of sulphur. From this ratio the number of grains of sulphur existing as bisulphide in 100 cubic feet of the sample of gas tested can easily be calculated.

The following table gives the relation between (V) the divisions of the measuring cylinder filled with water, and (S) the grains of sulphur existing as bisulphide in 100 cubic feet of gas. Since gas contains besides carbon bisulphide, some other sulphur compounds which are not transformed into sulphuretted hydrogen by the action of heat, and which contain sulphur amounting ordinarily to 7 or 8 grains in 100 cubic feet, this quantity must be added to that found by the test, if it is wished to know approximately the total amount of sulphur.

-	•	_	_	-
"	•		ъ.	

								500								
							8=	<b>-</b>								
								v								
v			S	v			8		V			8	v			S
10			50.0	88			15-1		56			8.9	79			6.3
11			45.4	84			14.7		57			8.8	80			6-2
12			41.7	85			14.3		58			8.6	81			6.3
18			88.2	86			13.9		59			8.5	82			6.1
14			35.7	37			18.5		60			8.3	83			6.0
15			83.3	88			13.2		61			8.2	84			6.0
16	-		81.3	89			12.8		62			8.1	85			5.9
17		-	29.4	40			12.5		63			7.9	86			5.8
18		·	27.8	41	:		12.2		64			7.8	87			5-7
19	:	·	26.3	42			11.9		65			7.7	88			5.7
20	•	Ī	25.0	48			11.6		66	-	Ī	7.6	89	-	-	5.6
21	•	•	23.8	44	•	•	11.4		67	:	•	7.5	90	-	-	5.6
22	•	•	22.7	45	•	•	11.1		68	:	Ī	7.4	91	-		5.5
23	•	•	21.7	46	•	•	10.9		69	:	•	7.2	92	•	•	5.4
24	•	•	20.8	47	•	•	10.6		70	•	•	7.1	93	•	•	5.4
25	•	•	20.0	48	•	•	10.4		71	•	•	7·0	94	•	•	5.3
26	•	•	19.2	49	•	•	10.2		72	•	•	6.9	95	•	•	5.8
27	•	•	18.2	50 50	:	•	10.0		73	•	•	6.9	96	•	•	5.2
28	•	•	17.9	51	•	•	9.8		74	•	•	6.8	97	•	•	5.2
29	•	•	17.2	52	•	•	9.6		75	•	•	6.7	98	•	•	5.1
30	•	•	16.7	58	•	•	9.4		76	•	•	6.6	99	•	•	5.1
81	•	•	16.1	54	•	•	9.2		77	•	•	6·5	100	•	•	5.0
	٠	•			•	•	9.1		78	•	•	6.4	150	•	•	3.3
82	•	٠	15.6	55	٠	•	a.T		10	•	•	0.4	190	•	•	0 0

For the next testing, the test-glass is to be disconnected and recharged. The water in the measuring cylinders is poured back into the aspirator. The colour of the standard is unaffected by exposure to light, but deepens if the liquid is warmed, returning to its original shade as the liquid cools. If, therefore, the glass containing the standard has been in a warm place, it must be let cool before testing.

The liquid which has been used becomes colourless after being exposed to the light for a few hours, and may thus be used over and over again for 20 times or more, if it is not allowed to absorb carbonic acid from the air. The best mode of working is to have two well-corked flasks, into one of which the coloured liquid is emptied while the glass is re-charged from the other.

Testing for Sulphuretted Hydrogen and Carbonic Acid.—The apparatus may also be used without the bulb-tube and stand to test the amount of sulphuretted hydrogen or carbonic acid in gas at any stage in its purification.

The gas is led in this case directly into the test-glass, which is charged with lead solution for sulphuretted hydrogen, and with a saturated solution of barium hydrate (baryta water) for carbonic acid.

When the gas contains more than 50 grains of sulphur as sulphuretted hydrogen in 100 cubic feet, a smaller cylinder, containing 1-200th cubic foot, is used to measure the volume of liquid run from the aspirator. The divisions on the smaller cylinder are tenths of the corresponding divisions on the larger cylinder; therefore when it is used the numbers under S in Table I. must be read as whole numbers by omitting the decimal points.

To estimate carbonic acid a standard liquid containing a definite amount of suspended barium carbonate is used for comparison. The glasses are placed side by side on a blackened board or piece of paper and with a black background behind them. The passage of the gas should be interrupted, and the test-glass slightly shaken once or twice to wash down any particles of carbonate which may cling to the sides of the glass above the surface of the liquid. The standard should also be shaken before the comparison is made, in order that the precipitates may be in a similar condition. When the two liquids are judged to be equally white and opaque, the volume of water in the measuring cylinder gives the volume of gas which has precipitated a known weight of barium carbonate. Table II. gives the relation between (V) the divisions of the large measuring cylinder filled with water, and (C) the volume of carbonic acid in 100 volumes of gas. When

the gas contains more than '72 per cent. of carbonic acid, the smaller measuring cylinder should be used, and the values of (C) multiplied by moving the decimal point one place to the right.

			,			•	ΓAI	BLE I	I.					
v			C	V			C	v			σ	v		O
10			.72	88			.22	56			.13	79		.09
11			·65	84			•21	57			·13	80		-09
12			.60	85			•21	58			·12	81		-09
18			.55	86			.20	59			.12	82		.09
14		•	.61	87			.20	60			·12	83		.09
15			.48	38			·19	61			·12	84		.09
16			.45	89			.18	62			·11	85		.08
17			.42	40			·18	63			•11	86		-08
18			.40	41			·17	• 64			.11	87		·08
19			.88	42			·17	65			·11	88		108
20			.86	48			·17	66			·11	89		.08
21			•84	44		. •	·16	67			·11	90		.08
22			.33	45		١.	·16	68			.11	91		.08
28			·81	46			·16	69			·10	92		.08
24			.30	47			.15	70			·10	93		.08
25			-29	48			.15	71			·10	94		.08
26			·28	49			-15	72			·10	95		.08
27			·27	50			·14	78			·10	96		07
28			·26	51			·14	74			·10	97		.07
29			.25	52			·14	75			·10	98		•07
80			-24	58			·14	76			.09	99		·07
81			·28	54			-18	77			.09	100		•07
82	•		.22	55	•	•	·18	78	•	•	.09	150		.05

After each testing the glass and capillary-tube should be cleaned with a little dilute hydrochloric acid and well rinsed with distilled water. The turbid liquid is poured into a flask, which should be kept well corked, containing an excess of crystallized barium hydrate. After the suspended precipitate has subsided, the clear liquid is poured off, or, if necessary, filtered, into another flask, also kept well corked, from which it may be poured into the test-glass when required. Care should be taken not to expose the solution to the air longer than necessary.


Notification of the London Gas Referees.—These instructions as to the times and mode of testing for purity and illuminating power are applicable, primarily, to the Metropolis; but, secondarily, they will be found useful by every gas manager, the description of the modus operandi of testings, as well as of the appliances, being full and precise. They are as follows:—

Times and Mode of Testing for Purity.—"The testings for purity shall extend over not less than fifteen hours of each day, and shall be made upon ten cubic feet of gas. The gas shall be tested

successively for sulphuretted hydrogen, ammonia, and sulphur compounds other than sulphuretted hydrogen in the manner hereinafter prescribed. These testings must be started between 9 a.m. and 5.80 p.m., and must be concluded before 9 a.m. on the following morning. They are concluded by the action of an automatic lever-tap attached to the meter, which stops the passage of the gas when ten cubic feet have passed. A clock connected with the lever-tap is stopped at the same moment, leaving a record of the time; and the tap of an ærorthometer is turned, leaving a record of the final conditions under which the gas was measured by the meter.

"The liquids in the sulphur and ammonia tests, and the slips of paper in the tests for sulphuretted hydrogen then contain the sulphur and ammonia which were present in the gas supplied to the testing place during the day which ended at 9 a.m. The chemical examination of these liquids may be made on the following day, that is to say, after 9 a.m.

I. Sulphuretted Hydrogen.—"The gas shall be passed as it leaves the service-pipe through a small governor and thence through an apparatus (Fig. 147) in which are suspended slips of bibulous paper, impregnated with basic acetate of lead.



"The test-paper from which these slips are cut is to be prepared from time to time by moistening sheets of bibulous paper with a solution of one part of sugar of lead in eight or nine parts of water, and holding each sheet while still damp over the surface of a strong solution of ammonia for a few moments. As the paper dries all free ammonia escapes.

"If distinct discoloration of the surface of the test-paper is found to have taken place, this is to be held conclusive as to the presence of sulphuretted hydrogen in the gas. Fresh test-slips are to be placed in the apparatus every day.

"In the event of any impurity being discovered, one of the test slips shall be

placed in a stoppered bottle and kept in the dark at the testing-place; the remaining slips shall be forwarded with the daily report.

- II. Ammonia.—" The gas which has been tested for sulphuretted hydrogen shall pass next through an apparatus consisting of a glass cylinder filled with glass beads, which have been moistened with a measured quantity of standard sulphuric acid. A set of burettes, properly graduated, is provided.
- "The maximum amount of ammonia allowed is 4 grains per 100 cubic feet of gas; and the examination of the liquid shall be made so as to show the exact amount of ammonia in the gas.
- "Two test-solutions are to be used—one consisting of dilute sulphuric acid of such strength that 25 measures (septems) will neutralize 1 grain of ammonia; the other a weak solution of ammonia, 100 measures of which contain 1 grain of ammonia.
- "The correctness of the result to be obtained depends upon the fulfilment of two conditions:—
  - 1. "The preparation of test-solutions having the proper strength.
  - 2. "The accurate performance of the operation of testing.
- "To prepare the test-solutions the following processes may be used by the Gas Examiner:—
- "Measure a gallon of distilled water into a clean earthenware jar, or other suitable vessel. Add to this 94 septems of pure concentrated sulphuric acid, and mix thoroughly. Take exactly 50 septems of the liquid and precipitate it with barium chloride in the manner prescribed for the sulphur test. The weight of barium sulphate which 50 septems of the test-acid should yield is 18.8 grains. The weight obtained with the dilute acid prepared as above will be somewhat greater, unless the sulphuric acid used had a specific gravity below 1.84.
- "Add now to the diluted acid a measured quantity of water, which is to be found by subtracting 18.8 from the weight of barium sulphate obtained in the experiment, and multiplying the difference by 726. The resulting number is the number of septems of water to be added.
- "If these operations have been accurately performed, a second precipitation and weighing of the barium sulphate obtainable from 50 septems of the test-acid will give nearly the correct number of 18.8 grains. If the weight exceeds 18.9 grains, or falls below 13.7 grains, more water or sulphuric acid must be added, and fresh trials made, until the weight falls within these limits. The test-acid thus prepared should be transferred at once to stoppered bottles, which have been well drained and are duly labelled.

"To prepare the standard solution of ammonia, measure out, as before, a gallon of distilled water, and mix with it 50 septems of strong solution of ammonia (sp. gr. 0.88). Try whether 100 septems of the test-alkali thus prepared will neutralize 25 of the test-acid, proceeding according to the directions given subsequently as to the mode of testing. If the acid is just neutralized by the last few drops, the test-alkali is of the required strength. But if not, small additional quantities of water, or of strong ammonia solution, must be added, and fresh trials made, until the proper strength has been attained. The bottles in which the solution is stored should be filled nearly full and well stoppered.

"The mode of proceeding is as follows:-Take 50 septems of the testacid (which is greatly in excess of any quantity of ammonia likely to be found in the gas), and pour it into the glass cylinder, so as to well wet the whole interior surface, and also the glass beads. one terminal tube of the cylinder with the gas supply, and the other with the meter, and make the gas pass at a rate of not more than twothirds of a cubic foot per hour. Any ammonia that is in the gas will be arrested by the sulphuric acid, and a portion of the acid (varying with the quantity of ammonia in the gas) will be neutralized thereby. At the end of each period of testing, wash out the glass cylinder and its contents with distilled water, and collect the washings in a glass vessel. Transfer one-half of this liquid to a separate glass vessel, and add a quantity of a neutral solution of litmus, or other indicator in ordinary use, just sufficient to colour the liquid. Then pour into the burette 100 septems of the test-alkali, and gradually drop this solution into the measured quantity of the washings collected, stirring constantly. As soon as the colour changes (indicating that the whole of the sulphuric acid has been neutralized), read off the quantity of liquid remaining in the burette. To find the number of grains of ammonia in 100 cubic feet of the gas, multiply by 2 the number of septems of test-alkali remaining in the burette, and move the decimal point one place to the left.

"The remaining half of the liquid is to be set aside, in case it should be desirable to repeat the volumetric analysis. This portion of the liquid is to be used in either of the two following cases:—

"1. If the analysis of the first portion of the liquid show an excess

of impurity, the Gas Examiner shall forthwith give the notice provided for in the Acts of Parliament (The Gaslight and Coke Company Act, 1876, sect. 40, and others); and if the Company think fit to be represented by some officer, the second portion of the liquid shall be examined in his presence.

"2. If the analysis of the first portion of the liquid should miscarry, or the Gas Examiner have any reason to distrust the result, he shall be at liberty to make an analysis of the second portion, provided that before doing so he give notice to the Company in order that they may, if they think fit, be represented by some officer.

"Unless thus used it is to be preserved, in a bottle properly labelled, for a week.

#### III. Measurement of Gas and of the Rate of Flow.

"The gas, which has been tested for Sulphuretted Hydrogen and Ammonia, shall pass next through a meter by means of which the rate of flow can be adjusted, and which is provided with a self-acting movement for shutting off the gas when ten cubic feet have passed, for stopping a clock so as to indicate the time at which the testings terminated, and for turning the tap of the recording Aerorthometer. The Gas Examiner shall enter in his book the time thus indicated, as also the time at which the testings began.

"The clock required is a good pendulum clock, with a wire passing transversely through the case behind the pendulum. Outside the case a lever arm is clamped to the wire, so that when liberated the arm will drop and turn the wire. Inside the case an arm is clamped to the wire, and at the end of the arm a flexible wire is fastened; when the lever drops, this flexible wire is brought into gentle frictional contact with the pendulum so as to stop it without shock.

"The clock should be wound from the front, and both hands should be mounted so that they can be set independently also from the front. It is desirable that the clock should be able to go for a week with one winding.

### IV. Sulphur Compounds other than Sulphuretted Hydrogen.

- "The testing shall be made in a room where no gas is burnt other than that which is being tested for sulphur and ammonia.
- "The apparatus to be employed is represented by the diagram (Fig. 148), and is of the following description:—The gas is burnt in a small




Fig. 148.

Bunsen burner with steatite top, which is mounted on a short cylindrical stand, perforated with holes for the admission of air, and having on its upper surface a deep circular channel to receive the wide end of a glass trumpet-tube.

"Pieces of sesqui-carbonate of ammonia, from the surface of which any efflorescence has been removed, are to be placed round the stem of the burner. The index of the meter is to be then turned forward to the point at which the catch falls, and will again support the lever tap in the horizontal position. The lever is then made to rest against the catch so as to turn on the gas. The index is then turned back to a little short of zero, and the burner lighted. When the index is close to zero the trumpettube is placed in position on the stand

and its narrow end connected with the tubulure of the condenser. At the same time, the long chimney-tube is attached to the top of the condenser.

"As soon as the testing has been started, a reading of the Aerorthometer is to be made and recorded. The mechanism for stopping the clock is then to be connected with the lever tap of the meter, so that both may be stopped at the same moment, when ten cubic feet of gas have passed through the meter. The time at which the testing begins is to be recorded.

"After each testing, the flask or beaker which has received the liquid products of the combustion of the ten cubic feet of gas, is to be emptied into a measuring cylinder and then replaced to receive the washings of the condenser. Next the trumpet-tube is to be removed and well washed out into the measuring cylinder. The condenser is then to be flushed twice or thrice by pouring quickly into the mouth of it 40 or 50 cubic centimetres of distilled water. These washings are brought into the measuring cylinder, whose contents are to be well mixed and divided into two equal parts.

"One-half of the liquid so obtained is to be set aside, in case it

should be desirable to repeat the determination of the amount of sulphur which the liquid contains. This portion is to be examined under the same conditions as have been prescribed for the examination of the second portion of the liquid obtained from the apparatus used in testing for Ammonia; unless thus previously used, it is to be preserved, in a bottle properly labelled, for one week.

"The remaining half of the liquid is to be put into a flask, or beaker covered with a large watch-glass-treated with hydrochloric acid sufficient in quantity to leave an excess of acid in the solutionand then raised to the boiling point. An excess of a solution of barium chloride is now to be added, and the boiling continued for five The vessel and its contents are to be allowed to stand till the barium sulphate settles at the bottom of the vessel, after which the clear liquid is to be as far as possible poured off through a paper The remaining liquid and barium sulphate are then to be poured on to the filter, and the latter well washed with hot distilled water. (In order to ascertain whether every trace of barium chloride and ammonium chloride has been removed, a small quantity of the washings from the filter should be placed in a test-tube, and a drop of a solution of silver nitrate added; should the liquid, instead of remaining perfectly clear, become cloudy, the washing must be continued until, on repeating the test, no cloudiness is produced.) Dry the filter with its contents, and transfer it into a weighed platinum crucible. Heat the crucible over a lamp, increasing the temperature gradually, from the point at which the paper begins to char, up to bright redness. When no black particles remain, allow the crucible to cool; place it when nearly cold in a desiccator over strong sulphuric acid, and again weigh it. The difference between the first and second weighings of the crucible will give the number of grains of barium sulphate. Multiply this number by 11 and divide by 4; the result is the number of grains of sulphur in 100 cubic feet of the gas.

"This number is to be corrected for the variations of temperature and atmospheric pressure in the manner indicated under the head of Illuminating Power, with this difference, that the mean of the Aerorthometer readings found at the beginning and at the end of any testing shall be taken as the reading for that testing. The reading at the beginning of the testing is to be made by the Gas Examiner, who, before leaving the testing place, will set the columns of mercury

level in the two tubes of the instrument, and will connect the levertap of the Aerorthometer with that of the meter. The fall of the lever of the meter will release a similar lever turning a tap which closes the tube of the Aerorthometer. The reading of the Aerorthometer as it stood at the end of the testing will require a small correction for the difference in level of the mercury in the two tubes, which is to be made in the following manner:—

"Let R be the correct reading,  $r_1$  the actual reading of the Aerorthometer,  $r_2$  the reading of the companion tube, h the mean height of the Barometer in units of the Aerorthometer scale, a figure which will be printed on each instrument. Then

$$R = r_1 \times \frac{h + r_1 - r_2}{h}$$

"The correction by means of the Aerorthometer reading may be made most simply and with sufficient accuracy, in the following manner:—

"When the Aerorthometer reading is between '955—'965, '966—'975
'976—'985, '986—'995, diminish the number of grains of sulphur by 4, 3, 2, 1 per cent.

"When the Aerorthometer reading is between '996-1'005, no correc-

tion need be made.

"When the Aerorthometer reading is between 1.006—1.015, 1.016—1.025, 1.026—1.035, increase the number of grains of Sulphur by 1, 2, 3 per cent.

"Example:— Grains of Barium Sulphate from		Aerorthometer reading 1-018
5 cubic ft. of Gas	4:3	
Multiply by 11, and divide by 4	11	
	4)47.3	
Grains of Sulphur in 100 cubic		
ft. of Gas (uncorrected)	11.82	
Add 11.8 $\times \frac{100}{100} =$	•24	
Grains of Sulphur in 100 cubic		$\mathbf{Result:}$
ft. of Gas (corrected)	12.06	12·1 grs.

"The Aerorthometer reading is the reciprocal of the Tabular Number. The Gas Examiner shall, not less often than once a month, compare the Aerorthometer reading with the reciprocal of the Tabular Number deduced from observations of the Barometer and Thermometer, and if there is a difference of more than one-half per cent. the instruments are to be readjusted.

- "As to the Maximum Amounts of Impurity in each Form with which the Gas shall be allowed to be Charged.
- "Sulphuretted Hydrogen.—By the Acts of Parliament all gas supplied must be wholly free from this impurity.

"Ammonia.—The maximum amount of this impurity shall be 4 grains per 100 cubic feet.

"Sulphur Compounds other than Sulphuretted Hydrogen.—The maximum amount of sulphur with which gas shall be allowed to be charged shall be 17 grains in every 100 cubic feet of gas."

### "Times and Mode of Testing for Illuminating Power.

- "The standard to be used in testing the illuminating power of gas shall be a Pentane 10-candle Lamp, which has been examined and certified by the Gas Referees. A Fig. and description of the lamp is given at pages 830 and 831. The residue of pentane in the saturator shall, at least once in each calendar month, be removed. It shall not be used again in any testings.
- "The pentane to be used in this lamp shall be prepared as described, and shall show when tested the properties specified.
- "All pentane provided by the Gas Companies will be examined and certified by the Gas Referees, and will be sent to the testing places in one-pint cans, which have been both sealed and labelled by them; and no pentane shall be used in the testing places other than that which has been thus certified.
- "The testings for illuminating power shall be three in number daily. But if the average of three testings falls below the prescribed illuminating power, a fourth testing shall be made.
- "The Photometers to be used in the testing places shall be the Table Photometer.
- "The several parts of the apparatus stand upon a well-made and firm table, 5 ft. 6 in. by 8 ft. 6 in., and 2 ft. 5 in. high. The upper surface of this table is smooth, level, and dead black. Upon this are placed or clamped in the positions shown:—
- "(1) The Gas Meter; (2) The Gas Governor; (8) The Regulating Tap; (4) The 'Sugg's London Argand, No. 1' Burner; (5) The Connecting Pipes; (6) The Pentane Ten-Candle Lamp; (7) The Photoped; (8) The Aerorthometer: (9) The Stop-Clock; (10) Dark Screens.
- [All these several parts are described in great detail in the notification.]

"The air-gas in the lamp is to be kept burning so that the flame is near its proper height for at least ten minutes before any testing is made. At the completion of every testing the air-gas is to be turned out; but, if the interval between two testings does not much exceed one hour and the Gas Examiner is present during the interval, he may, instead of turning it out, turn it down low.

"The gas-burner attached to each Photometer shall be a standard burner corresponding to that which has been deposited with the Warden of the Standards in accordance with Section 97 of The Gaslight and Coke Company Act, 1876. The following is a descrip-


tion of the standard burner to be used:-

"This was designed by Mr. Sugg, and was called by him 'Sugg's London Argand, No. 1."

A full-sized section (here given half size) is appended (Fig. 149), in which A represents a supply pipe, B the gallery, C the cone, D the steatite chamber, E the chimney.

The following are the dimensions of those parts of the burner upon which its action depends:—

			Inch.
Diameter of supply-pipes .			0.08
External diameter of annular			
tite chamber			0.84
Internal diameter of annulars	tea	tite	
chamber			0.48
Number of holes		24	
Diameter of each hole			0.045
Internal diameter of cone-			
At the bottom			1.5
At the top			1.08
Height of upper surface of con			
of steatite chamber above fi			
gallery			0.75
Height of glass chimney .			6
Internal diameter of chimney			17
•			



- "Each burner shall bear a distinctive number. No burner shall be used for testing the illuminating power of gas that does not bear the lead seal of the Gas Referees.
- "A clean chimney is to be placed on the burner before each testing.
- "The gas under examination is to be kept burning, so that the flame is about the usual height, for at least fifteen minutes before any testing is made; and no gas shall pass through the meter attached to the Photometer except that which is consumed by the standard burner in testing or during the intervals between the testings made on any day, and that which is used in proving the meter.
- "The paper used in the photoped of the Photometer shall be white in colour, unglazed, of fine grain, and free from water marks. It shall be as translucent as is possible consistently with its being sufficiently opaque to prevent any change in the apparent relative brightness of the two portions of the illuminated surface, when the head is moved to either side. This paper should, when not in use, be covered, to protect it from dust; and, if it has been in any way marked or soiled, a fresh piece is to be substituted.
  - "Each testing shall be made as follows:--
- "The index of the regulating tap shall be so turned that the gas flame gives rather less light on the photoped than the standard, and shall then be gradually turned on until equal illumination has been obtained. The position of the index shall then be noted. Next, the tap shall be so turned that the gas flame appears to give rather more light than the standard, and shall then be turned off until equality is again attained, and the position of the index shall be again noted. The double operation shall be repeated. The mean of the four index positions shall be taken as that which gives true equality of illumination. The index shall be set to this mean position, the quality of illumination verified, and the time that the hand of the meter takes to make two complete revolutions shall be observed.
- "In order to make this observation, a stop-clock shall be used, by which the time which has elapsed since the clock was started can be read with an accuracy of at least half a second. The clock shall be started at the moment when the meter-hand points either to zero or to some other convenient mark, and a note shall be immediately made of the mark chosen. Exactly at the completion of the second turn of the meter-hand the Gas Examiner shall stop the clock. The

time of two revolutions thus indicated by the clock is to be read to the nearest half second and found in the table, A, given herewith. From this and the reading of the Aerorthometer, or a determination of the tabular number, the illuminating power of the gas is to be obtained, either directly or by interpolation. Only one figure after the decimal point need be entered when the result is above 16; where a lower result is found, both figures should be noted and entered. A table, B, giving the Tabular Numbers for different temperatures and pressures is appended.

- "The method of finding the illuminating power from the table by interpolation, may be illustrated by the two following examples:—
- "I. Time 1 min. 53 sec. Reading of Aerorthometer, 1.073. By the table the illuminating power corresponding to this time of consumption and to the reading 1.070 is 16.12, while for the reading 1.080 it is 16.27. Thus, in this part of the scale, when the reading is 10 degrees higher the illuminating power is greater by 0.15 candle. Hence, when the reading is 8 degrees above 1.070, the corresponding illuminating power is  $16.12 + \frac{3}{10} \times 0.15 = 16.165$  candles and the number to be returned is 16.2.
- "II. Time 2 min.  $1\frac{1}{2}$  sec. Reading of Aerorthometer, '984. The numbers in the table under '980 are 15.81 for 2 min. 1 sec., and 15.94 for 2 min. 2 secs.; therefore the number corresponding to  $1\frac{1}{2}$  sec. is the half-way number 15.875; the number found similarly under '990 is 16.085. The increase for 10 degrees is here 0.16; the number corresponding to the reading '984 is accordingly  $15.875 + \frac{4}{10} \times 0.16 = 15.989$ ; and the number to be returned is 15.94.
- "If, in very exceptional circumstances, the Aerorthometer scale or the tables do not include the conditions that are met with, the Gas Examiner shall determine the illuminating power by means of one or other of the formulæ printed below the tables.
- "The Gas Examiner shall, at least once a week, compare the stopclock with the standard clock in each testing place.
- "The Gas Examiner shall enter in his book the particulars of every testing of illuminating power made by him at the testing places, during or immediately after such testing; and in the case of any testing which he rejects he shall also state the cause of rejection. No testing is to be rejected on the ground that the result seems improbable."

TABLE A, giving the ILL vield the Light of 16 Candles, and from Readings
Barometer, The through the meter of one-sixth of a cubic foot of gr
be found in the lines. In the corresponding line and column is fo
Illuminating Po

	<del></del>	Н	1.050	1.000	1.070	1.000	1,000	1.100	1.110
Aerorthome	eter	Н	1.050	1.060	1.070	1.080	1.090	1.100	1.110
Tabular l	Number	Ш	.953	•944	•935	·926	·918	.909	·901
Minute.	Seconds. 44		14.56	14.70	14.84	14.98	15.11	15 • 25	15.39
	45	11	14.70	14.84	14.98	15.12	15 · 26	15· <del>4</del> 0	15.54
	46	Н	14.84	14.98	15·12	15.26	15 · 41	15.55	15.69
	47	П	14.98	15 · 12	15.27	15.41	15.55	15.69	15.84
1	48	П	15.13	15.26	15.41	15.55	15.70	15.84	15.98
	49	Н	15.26	15.41	15.55	15.70	15.84	15.99	16.13
	50		15.40	15.22	15 · 69	15.84	15 · 99	16·18	16.28
	· <b>51</b>		15.54	15.69	15.84	15.98	16 · 18	16.28	16.43
1	52	П	15.68	15.88	15.98	16.18	16.58	16.48	16.28
	58	Н	15.82	15.97	16·12	16.27	16 · 42	16.57	16.72
	54	П	15.98	16.11	16.26	16.42	16.57	16.72	16.87
	55		16·10	16.25	16.41	16.26	16.71	16.87	17.02
1	56	П	16.24	16.89	16.22	16.70	16.86	17.01	17 · 17
	57	Ш	16 <b>·3</b> 8	16· <b>54</b>	16.69	16.85	17.00	17·16	17.32
	58		16.28	16· <b>6</b> 8	16.83	16.99	17 · 15	17.31	17 • 46
	59	Ш	16.66	16.82	16.98	17·14	17 · 29	17 · 45	17.61
2	0		16.80	16.96	17.12	17.28	17.44	17.60	17.76
2	1	li	16.94	17:10	17.26	17:42	17 · 59	17 · 75	17.91
	2		17.08	17:24	17:41	17.57	17 · 78	17.89	18.05
	8		17.22	17.38	17.55	17.71	17.88	18.04	18.20
	4	Ш	17.86	17.58	17 · 69	17.86	18.02	18·19	18.35
2	5	Ш	17.50	17.67	17.88	18.00	18·17	18.38	18.20
	6	Ш	17.64	17.81	17.98	18•14	18·81	18:48	18.65
	7		17.78	17.95	18·12	18-29	18· <b>4</b> 6	18.63	18.80
	8		17.92	18.09	18.26	18·48	18.60	18.77	18.94
2	9		18.06	18.28	18.40	18.58	18.75	18.92	19.09
	10		18.20	18.37	18.55	18.72	18.89	19.07	19.24
	11		18.34	18.51	18.69	18.86	19·04	19·21	19.39
	12		18.48	18.66	18.83	19.01	19·18	19.36	19.54
		4		<del>`</del>					

Time in Seconds.

7.5 × Tabular Number.

atures, and under different Atmospheric Pressures.

			ж, апи		anner en		T				
Bar.	Ther. 40°	36°	68°	70°	72°	7 <b>4</b> °	76°	78°	80°	82°	84°
28:0	•979	917	•912	•907	•902	·897	·892	·887	•881	•875	•870
28·1	•983	921	•916	·911	•905	•900	•895	•890	·884	·879	·873
28·2	•986	924	•919	·914	∙909	•904	-898	.893	-887	∙882	•876
28.8	•990	928	.922	•917	•912	•907	•902	•896	·891	•885	•880
28·4	.993	981	926	·921	•915	•910	•905	.900	·894	.888	.883
28.2	•997	984	.929	·924	818	·914	•908	•903	·897	•892	·886
28.6	1.001	988	·9 <b>32</b>	•927	·922	•917	·912	.906	.901	·895	.889
28.7	1.004	941	•986	·931	•925	·9 <b>2</b> 0	·915	-909	·904	·898	-893
28.8	1.007	1944	•999	•984	•929	•924	•918	•918	•907	·901	·896
28.9	1.011	1948 -	·942	•937	•932	•927	•921	.916	•910	•905	-899
29·0	1.014	1951	•946	·941	•935	.980	•925	•919	914	-908	•903
29·1	1.018	1954	•949	·944	.989	.933	·928	•923	•917	•911	∙906
29·2	1.021	1958	•952	•947	·942	•937	•981	•926	•920	·914	∙909
29.8	1.025	1961	•956	•950	•945	•940	•935	•929	•923	•918	•912
29·4	1.028	1964	•959	•954	949	•948	•988	•932	•927	•921	•915
29.5	1.032	1968	•962	•957	•952	·947	•941	•936	•930	•924	<b>'919</b>
29.6	1.036	1971	•966	•960	•955	•950	·944	•939	.938	•927	922
29.7	1.039	1974	•969	·964	•959	•958	·948	•942	•987	·981	-925
29.8	1.048	1978	·972	•967	•962	•957	•951	·946	•940	·934	•928
29·9	1.046	1981	·978	•970	·965	•960	•954	•949	•943	•987	•932
30.0	1.050	1985	·979	•974	·968	•963	•958	•952	•946	·941	•935
80·1	1.058	1988	•983	•977	.972	•966	•961	•955	•950	•944	•938
30·2	1.057	1991	·986	.980	•975	•970	•964	·95 <b>9</b>	•958	•947	·941
80.8	1.060	1995	.989	•984	•978	•978	•968	•962	•956	• 950	•945
80.4	1.064	1998	•998	•987	•982	•976	•971	•965	•959	•954	·948
80.2	1.067	1:01	•996	.880	•985	•980	•974	·969	•968	•957	•951
80.6	1.071	1005	.999	∙994	•988	.983	•977	•972	•966	•960	•954
80·7	1.074	1008	1.008	·997	•992	•986	•981	•975	.969	.963	•957
80.8	1.078	1011	1.006	1.000	•995	•990	•984	•978	•972	-967	•961
30.9	1.081	1015	1.009	1.004	•998	•993	•987	.982	•976	•970	·964
81.0	1.082	1018	1.013	1.007	1.002	.996	·991	•985	•979	•978	•967
				<u> </u>							

<sup>\*\*\*</sup> The numbers height of the barometer in inches, t the temperature on the Fahrenheit scale, and a the id V the corresponding volume at 60° and 30 inches pressure, V = rn.

#### MODE OF TESTING THE PRESSURE AT WHICH GAS IS SUPPLIED.

"Testing of pressure shall be made by unscrewing the Governorand Burner of one of the ordinary public lamps, in such street or part of a street as the Controlling Authority may from time to time appoint. and attaching in their stead a portable pressure gauge.

"Each testing place is provided with a gauge prescribed for this purpose by the Referees, consisting of an ordinary pressure gaugeinclosed in a lantern, which also holds a candle for throwing light upon the tubes and scale. The difference of level of the water in the twolimbs of the gauge is read by means of a sliding scale, the zero of which is made to coincide with the top of the lower column of liquid.

"The Gas Examiner having fixed the gauge gas-tight, and as nearly as possible vertical on the pipe of the lamp, and having opened: the cocks of the lamp and gauge, shall read and at once record the pressure shown. From the observed pressure one-tenth of an inch is to be deducted to correct for the difference between the pressure of gas at the top of the lamp column and that at which it is supplied tothe basement of neighbouring houses.

#### THE GAS REFEREES' STREET LAMP PRESSURE GAUGE.

"This instrument (Fig. 150) has been designed by the Gas Referees, in accordance with Section 6 of The Gaslight and Cokeand other Gas Companies Acts Amendment Act, 1880, for the purpose of testing in any street at any hour the pressure at which gas is supplied. Its construction and mode of use are as follows :-

"Within a lantern provided with a handle for carrying and feet for resting on the ground, is placed a. candle-lamp, to give light for reading the gauge. In front of the candle-lamp is a sheet of opal glass, and in front of this a glass U-tube, partly filled with coloured water, and communicating at one end with the air, at the other with a metal pipe, which passes through the bottom of the lantern. In order to read easily and accurately the difference of level of the liquid in the two limbs, a scale divided into tenths of an inch is made to slide between them with sufficient friction to retain it in any position. The zero of the scale having been brought level with the surface of the liquid which is pressed upon by the gas, the height.



-above this of the surface which is pressed upon by the air can be read directly. The lantern is closed in front by a glass door, at each side of which is a reflector for throwing light upon the scale of the gauge. Above each limb of the U-tube is a tap, which can be closed when the instrument is not in use, to prevent the liquid being accidentally spilt.

"To make a testing of pressure the governor and burner of a street lamp are to be removed, and the pressure gauge is to be screwed on to the gas pipe, by which it is supported. The cock is then turned on, and a reading made. If on turning off the cock the level of the liquid is unchanged, or changes slowly, the reading is correct; but if the level changes quickly, the junction between the lamp and the gauge must be made more perfect, and the testing repeated. A small leakage is immaterial, provided the cock is turned fully on.

"The pressure at the top of the lamp column is greater by about -0.1 inch than that at the main, which is the pressure required. Accordingly a deduction of 0.1 inch from the observed pressure is to be made.

### METERS.


"Each of the meters used for measuring the gas consumed in making the various testings is constructed with a measuring drum which allows one-twelfth of a cubic foot of gas to pass for every revolution. A hand is fastened directly to the axle of this drum, and passes over a dial divided into one hundred equal divisions. The dial and hand are protected by a glass. In the meter employed in testing the purity of gas, the pattern of dial for showing the number of revolutions and the automatic cut-off hitherto in use shall be retained, but in the meter employed for testing illuminating power, only the dial above described is needed. The stop-cock may be either attached to the meter or separate.

"The meters used for measuring the gas consumed in making the various testings, having been certified by the Referees, shall, at least once in seven days, be proved by the Gas Examiners by means of the Referees' one-twelfth of a cubic foot measure. A description of this instrument, with directions how to use it, is here given.

"No meter other than a wet meter shall be used in testing the gas under these instructions.

## THE GAS REFEREES' ONE-TWELFTH OF A CUBIC FOOT MEASURE.

"This instrument is represented in Fig. 150a; it consists of a vessel of blown glass of a cylindrical form, with rounded ends.



terminating in short tubes about 40 millimetres in diameter outside, which tubes are reduced at their outer ends to about 20 millimetres in diameter outside. Lines are etched round each tubular neck in such positions that the capacity of that portion of the vessel behuleni between these marks is exactly one-twelfth of a cubic foot when the glass is at the ordinary temperature. No correction is needed for the cubical expansion of the glass. The two tubular necks of the instrument pass through two boards

placed below and parallel to the top of a small four-legged table. For convenience, the upper one of these two boards is made in two parts, and hinged to the legs.

"Into each end of the instrument a glass tube, about 8 millimetres in diameter outside, is fitted, gas and water tight, by means of indiarubber corks, in such positions that the inner end of the upper tube lies exactly in the plane of the mark at its end of the instrument, while that of the lower is about 1 mm, below the mark.

"The upper tube terminates in a T, each branch of which is provided with a stop-cock.

"A separate stand carries two shelves, the upper one about 40 millimetres below the level of the upper mark, and the lower one below the level of the lower mark. The lower shelf is adjustable, and must be so placed that the action about to be described shall take place.

"A water-vessel is provided having a capacity of about one-tenth

of a cubic foot. It should be made of brass or copper; tinned on the inside. It has a tubulure near the bottom, to which is fitted a metal tap. The end of the tap is to be turned slightly downwards, and is to have a diameter outside of about 8 millimetres. The size of the way through the tap and of the connections is such that when a meter is being proved in the manner to be described, the water fills the instrument from one mark to the other in about one minute. The water vessel has a tubulure in the cover, to which a narrow glass tube is fitted by means of a cork, so that air may enter or escape. The end of the tube is bent round upon itself in the form of a crook, so as to exclude dust and dirt. An india-rubber tube connects the tube at the base of the measure with the stop-cock of the water vessel. An ordinary chemical thermometer is provided for taking the temperature of the water.

"The pipe supplying gas to each meter is provided, near the meter, with a three-way stop-cock carrying a short branch pipe, so formed that it either connects the gas supply only with the branch pipe, the meter only with the branch pipe, or the gas supply with the meter, in which latter case the branch pipe is cut off from both. The index of the tap shows which communication is open. In order to avoid sending the gas used in proving the sulphur meter through the sulphuretted hydrogen and ammonia apparatus, a separate gas supply is provided. The branch pipe is so shaped as to be convenient for the attachment of an india-rubber tube.

"In order to put the instrument in adjustment the water vessel is placed upon the upper shelf, the water is poured into it until it rises about one-quarter of an inch in the upper narrow tube. One branch of the glass T is then connected by an india-rubber pipe with the branch of the three-way stop-cock. This is now turned so as to connect the branch pipe with the gas supply, and the water vessel is placed on the lower shelf. The water will run back into the vessel. The flow should cease when the water has just begun to descend in the lower tube; if not, the height of the lower shelf must be adjusted until this is the case.

"The space above the upper mark is always filled with gas, and that below the lower mark with water, so that the capacity of these portions of the instrument has no effect upon the measurements. The narrow tubes are so small that a variation of even an inch of the level at which the water stands in them has no appreciable effect upon the meter reading.

"The apparatus shall only be used in proving a meter when the temperature of the meter, and of the water in the water vessel, have been found not to differ by more than two degrees Fahrenheit.

"In order to prove the meters used in the various testings, the position of the index is taken when the instrument has been put in adjustment and filled with gas as described. The tap of the water vessel is turned off, and the pressure of the gas in the instrument reduced to atmospheric pressure by momentarily opening the tap in the free branch in the glass T. The water vessel is placed upon the upper shelf, its tap turned on, and one-twelfth of a cubic foot of gas is discharged through the meter. Fig. 150a represents this operation in progress. The three-way stop-cock is then turned so as to fill the instrument with gas which is reduced to atmospheric pressure as before, and a second, and again a third quantity is discharged through the meter. Should the hand attached to the axle of the measuring drum have travelled in the three revolutions as much as one division beyond the point from which it started, some water must be removed from the meter; if the travel of the meter hand is as much as one division short of this point, some water must be poured in. The operation is then to be repeated until the error is found to fall within the specified limits."

### ILLUMINATING POWER.

For testing the illuminating power of gas in accordance with the general statutory provisions the Bunsen photometer is used; and the Letheby-Bunsen (Fig. 151) or the Evans enclosed form of the apparatus is that generally adopted.

The standard candle is a sperm candle, six of which weigh 1 lb., and each burns 120 grains of sperm per hour.

The gas is supplied through an experimental meter, and burns at one end of a graduated bar, and the candle at the other; a moveable disc of prepared paper being placed between the two.

This disc, which is contained within a sliding box or carriage, fitted with two reflectors, is moved between the two lights until its opposite sides are equally illuminated, whereupon the illuminating power of the gas is read off by the operator on inspection of the figures on the graduated bar.

The bar is graduated in accordance with the law that lights which equally illuminate an object are to each other as the square of their distance from such object. Thus, assuming that the distance from

the disc to the gas flame is 80 inches, and to the candle flame 20 inches, then  $80^{\circ}=6400$ , and  $20^{\circ}=400$ , or as 16 to 1, the illuminating value of the gas as compared with the candle.

The following apparatus are also required, viz.:—A governor to regulate the gas pressure; a clock striking every minute; a King's pressure-gauge; a candle balance and weights; a thermometer and a barometer.

The apparatus is arranged and fixed on a substantially-made table, placed in the photometer room. This room may be conveniently made



Fig. 151.

about 10 or 12 feet square, and should be ventilated; but currents of air which would affect the steadiness of the gas and candle flame must be guarded against. Provision is made to exclude the daylight; and the walls are coloured a dull black.

Statutory Regulations for Testing the Illuminating Power of Gas.

The provisions in Schedule A of the Gas-Works Clauses Act, 1871, in regard to the apparatus for, and the mode of testing the Illuminating Power of gas, are as follows:—

Regulations in respect of Testing Apparatus.

"The apparatus for testing the illuminating power of the gas shall consist of the improved form of Bunsen's photometer, known as Letheby's open 60-inch photometer, or Evans's enclosed 100-inch photometer, together with a proper meter, minute clock, governor, pressure gauge, and balance.

"The burner to be used for testing the gas shall be such as shall be prescribed.

"The candles used for testing the gas shall be sperm candles of six to the pound, and two candles shall be used together."

Mode of Testing for Illuminating Power.

The gas in the photometer should be lighted at least fifteen minutes before the testings begin and kept continuously burning from the beginning to the end of the tests.

Each testing should include ten observations of the photometer, made at intervals of a minute

The consumption of the gas should be carefully adjusted to 5 cubic feet per hour.

The candles are lighted at least ten minutes before beginning each testing, so as to arrive at their normal rate of burning, which is shown when the wick is slightly bent, and the tip glowing. The standard rate of consumption for the candles is 120 grains each per hour. Before and after making each set of ten observations of the photometer, the Gas Examiner weighs the candles; and if the combustion shall have been more or less per candle than 120 grains per hour, he makes the calculations requisite to neutralize the effects of this difference.

The average of each set of ten observations is taken as representing the illuminating power of that testing.

The disc used in the Photometer is either the Leeson or the Bunsen disc. The chimneys should be cleaned daily.

The rate of burning of the gas in each burner should be 5 cubic feet per hour—a rate of consumption which is shown by the long hand of the meter making exactly one revolution per minute for several minutes consecutively.

Instead of weighing the candles, the Examiner may observe the time in which 40 grains are burnt. This should not exceed 10.5, or fall short of 9.5 minutes.

At the time of each testing the Examiner observes and records the temperature of the gas, as shown by the thermometers attached to the meters, and also the height of the barometer. The volumes of the gas operated upon during the testings may be corrected from these data (the standard of comparison being, for the barometer, 80 inches, and for the thermometer, 60 degrees) by means of the Table B (ante). Suppose, for example, the thermometer stands at 54 degrees, and the barometer at 80.3 inches: multiply the quantity of gas consumed by the corresponding tabular number—the product will be the corrected volume of the gas—i.e., the volume the gas—would have occupied when measured over water at the standard temperature and pressure. Thus—

Volume of gas consumed . . . . 5 cubic feet. Tabular number for barometer and thermometer 1.025.

Then  $1.025 \times 5 = 5.125$ , the corrected volume.

Instead of thus correcting the volume of gas consumed, the same object may be attained by dividing the observed illuminating power by the tabular number.

The calculations for working out the corrections, &c., for the illuminating power of the gas proceed in the following manner:—Add the observations together, and divide the sum by 10 to get the average; then as two candles are used, multiply by two, to get the illuminating power of the gas if tried against one candle. Then, as the standard rate of the consumption of the candles (viz., 120 grains) is to the average number of grains consumed by each per hour, so is the above-obtained number to the actual illuminating power. Finally, the correction for temperature and pressure is made by dividing the illuminating power by the tabular number. For example -(taking the tabular number as 1.025):—

#### Observations-

```
1st minute-7.8 Consumption of the 2 candles in
                        7.8
            2nd
                               10 minutes.
            8rd
                        8.1
                               = 41 grains.
                   ,,
            4th
                        8.2
                   ,,
            5th
                        8.8
            6th
                         8.5
                                123 = consumption of 1 candle
            7th
                         8.6
                               per hour.
                   ,,
            8th
                         8.4
            9th
                         8.3
           10th
                         8.6
                     10)82.6
Average, by 2 candles=8.26
Average, by 1 candle=16.52
Consumption by
                        128 grains.
  candle per hour
                       4956
                      8304
                     1652
Standard con-
  sumption
                 120)203196
Correction for
 temp. & pres.
                1025)16933(16.5 = corrected Illum. Power in
                      1025
                                    candles.
                       6683
                       6150
                        5880
```

The foregoing calculation can be shortened as follows:-

Average, by 2 candles . . . = 8.26 Consumption by 2 candles in 10 minutes 41 grains.

> 826 3804 2)3866

Tabular number . . 1025 ) 16988 (16.5 = corrected Illum. Power in 1025 | 6888 | 6150 | 5880

### PHOTOMETER TABLE.

Calculated for One Candle. (Sugg.)\*

				<u> </u>					
Con-			Grains pe	r Hour Co	nsumed b	y the Spe	m Candle	•	
of Gas									
Feet per								1	
Hour.	110	111	119	118	114	115	116	117	118
	<del></del>								
	1.01851	1.02777	1.08708	1.04629	1.05555	1.06481	1.07407	1.08833	1 · 09259
4.6	•99637	1.00548	1.01449	1.02355	1.08260	1.04166	1.05072	1.05978	1.06884
4.7	•97517	•98404	•99290	1.00177	1.01068	1.01950	1.02836	1.08728	1.04609
4.8	95486	96354	•97222	.88090	.96958	•99826	1.00694	1.01562	1.02480
4.9	•98587	•94387	•95238	.96088	.96988	•97789	.88689	·99489	1.00840
5.0	·91666	•92500	•93888	•94166	•95000	.95838	96666	·97499	·98888
5.1	·89869	.90686	•91508	•92320	98187	99954	•94771	•95588	96405
5.3	·88141	188942	*89748	90544	191846	92147	92948	98750	94551
5.8	·86477	187264	88050	*88836	189622	90408	91194	91981	•92767
5.4	*84876	*85648	*86419	·87191	187962	*88784	189506	•90277	91049
5.5	·88888	·84090	·84848	*85606	*86868	-87121	·87878	•89636 I	-89898
Con-			Oreins no	- Hone Co	neumad h	y the Sper	m Candla		
sumption			Creme he		unod D	1 me pher	Canale		
of Gas				T					
Feet per	119	120	121	122	123	124	125	126	127
Hour.	110		1		120				
4.5									
4.5	1.10185	1.11111	1.12087	1.12962	1.13888	1.14814	1.15740	1.16666	1.17592
4.6	1.07789	1.08695	1.09601	1.10507	1.11418	1.12818	1.18224	1.14130	1.15096
4.7	1.05496	1.06883	1.07269	1.08156	1.09042	1.09929	1.10815	1.11702	1.12588
4·8 4·9	1·08298 1·01190	1.04166	1.05034 1.02891	1.05902	1.06770	1.07688	1.06506 1.06292	1.09875	1.10243
5.0	99166	1.00000	1.00888	1.08741	1.04591	1.05442	1.04166	1.07142	1·07998 1·05832
5.1	•97222	98089	98856	99678	1.00490	1.01807	1.02124	1.02941	1.08758
5.2	95852	96158	96955	97756	98557	99358	1.00160	1.00961	1.01762
5.8	•98558	94839	95125	95911	96698	97484	98270	99056	•99842
5.4	•91820	92592	98864	94185	94907	95679	98450	97222	97993
5.5	.90151	90909	91666	.92424	98181	.88888	94696	95454	96212
	<u> </u>		<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	
Con-			Grains p	er Hour C	on <b>sumed</b> l	y the Spe	rm Candle	١.	
sumption						-			_
of Gas Feet per			1	1			1	1	
Hour.	128	129	130	131	132	133	184	185	1
			<u> </u>	<u></u>					
4.5	1.18618	1.19444	1.20370	1.21296	1 · 22222	1.28148	1 · 24074	1 · 25000	
4.6	1.15942	1.16847	1.17758	1 18659	1.19565	1.20471	1.21876	1 22282	
4.7	1.18475	1.14861	1.15248	1.16134	1.17021	1.17907	1.18794	1.19680	::
4∙8	1.11111	1.11979	1.12847	1.13715	1.14583	1.15451	1.16819	1.17187	
4.9	1.08848	1.09698		1.11894	1.12244		1.18945	1 · 14795	::
5.0	1.06666	1.07500	1.08888	1.09166	1.10000		1.11666	1.12500	::
5.1	1.04575	1.05392		1.07026	1.07843		1.09477	1.10294	
5:2	1.02564	1.08865	1.04166	1.04967	1.05769	1.06570	1.07371	1.08173	••
5.8	1.00628	1.01415		1.02967	1.03778		1.05345	1.06182	
5.4	98765	•99537		1.01080	1.01851	1.02623	1.08395	1.04168	
5.5	•96969	97727	•98484	99242	1.00000	1.00757	1.01515	1.02272	
	1	1	1	1	1		1	i	Į.

 $<sup>^{\</sup>circ}$  Mr. Sugg has also published, in book form, a series of useful photometrical tables from 9.5 to 20 candles.

Rule.—Multiply the number standing beneath the number of grains consumed by the candle, and opposite the number of feet consumed by the gas-burner, by the illuminating power as read off from the scale of the photometer; the product is the correct value of the gas reduced to the standard of 120 grains per hour and 5 cubic feet per hour.

### THE AERORTHOMETER.




Fig. 152.

The Aerorthometer (Fig. 152) invented by Mr. A. Vernon Harcourt, is an ingenious instrument for correcting the observed volume of any portion of gas to its normal volume —i.e., the volume it would have under standard conditions of temperature and pressure. A reading of this instrument furnishes a number expressing the ratio between the observed and the normal, or corrected, volumes of any gas, and serves instead of reading a barometer and thermometer and calculating or referring to a table.

It consists of a bulb and stem, like a thermometer, containing air enclosed over mercury. The mercury stands at a certain height in the stem, and rises and falls as the enclosed air contracts or expands with changes of temperature and atmospheric pressure. The volume of the air is read off by means of a scale engraved on the stem and on the wood behind it. Each degree of the scale marks a portion of the stem whose capacity is one-thousandth part of the volume of the enclosed air when under a pressure

of 30 inches of mercury and at a temperature of 60° Fahr. The line at which the mercury stands under these conditions is figured accordingly 1000; and any other reading of the instrument, at a different pressure or temperature, gives the volume to which the thousand volumes have been expanded or contracted. A small drop of water having been passed into the bulb, the expansion caused by a rise of temperature includes that due to the increased tension of aqueous vapour.

In order that the volume of air enclosed in the bulb of the Aerorthometer may be measured under the atmospheric pressure, a second tube is placed by the side of the graduated stem, which is of the same calibre and connected with the same reservoir of mercury, but open above. By the pressure of a screw upon the leathern top of the reservoir, the mercury is raised in both tubes; and when the mercury stands at the same level in both, the enclosed air is under the atmospheric pressure. By being painted white, the bulb is protected from the action of radiant heat.

Since the volume of any portion of gas contained in a holder or passing through a meter near which an Aerorthometer is placed, bears the same relation to the volume the gas would occupy under standard conditions as the volume read on the stem of the Aerorthometer bears to 1000, the figures expressing the corrected volume of the gas may be obtained by multiplying the observed volume by 1000, and dividing it by the Aerorthometer reading. Thus, if n represents the number read upon the instrument, v the observed volume or rate of passage of the gas, and V the corrected or normal value, then  $V = v \frac{1000}{n}$ .

The instrument must stand or be suspended in a vertical position near the meter or holder whose registration it is to be used to correct. To make a reading, the screw is to be turned (if necessary) until the mercury stands at a lower level in the open tube than in that which is graduated. Then the screw must be turned slowly in the opposite direction until the mercury is exactly level in both tubes. The level of the mercury read upon the graduated tube gives the required number.

# FOREIGN AND OTHER (PROPOSED) HOME STANDARDS OF LIGHT.

The sperm candle has long been considered an unsatisfactory standard, owing chiefly to the shade of colour emitted by it differing somewhat from that of the gas, and the inequality of its rate of consumption.

Various standards of light have been advocated from time to time to supersede the candle; but none of these have hitherto been adopted in this country.



The Carcel lamp is the standard in France; the light, equal to 9.6 standard sperm candles, being produced by purified colza (rape) oil, burning at the rate of 648 grains per hour. The upper portion of this lamp is shown in section in Fig. 158; and the dimensions of its various parts are as follows:—

External diameter of hurner . ·9055 inches. Internal diameter of air-tube . 6.692 External diameter of air-tube. 1.7912Total length of chimney . . 11.4170 Length from base to neck of chimney . 2.4015 External diameter of chimney at level of neck . 1.8508 External diameter of chimney at top. 1.8885Mean thickness of the glass . .0787

The wick used is that known as "light-house wick," and the plait is composed of 75 strands; a piece 4 inches long weighing 55.5 grains. When the consumption of oil is less than 586 grains, or exceeds 710 grains per hour, the trial is cancelled.

The German normal paraffin candle is equal to 1.05 standard sperm candles. It has a diameter of 20 millimetres, and is made of the purest possible paraffin, with an addition of 2 per cent. of stearine. Its wick is

of 24 cotton threads plaited as uniformly as possible.

The Hefner-Altenick unit equals 0.88 standard sperm candle, being the illuminating power of a freely burning flame, in still pure air, supplied by a section of solid wick, and fed with amylacetate; the wick-tube being circular, and of German silver, measuring

8 millimetres internal and 8.8 millimetres external diameter, and 25 millimetres high; the flame being 40 millimetres high, measured from the edge of the wick-tube, at least ten minutes after lighting the lamp.




Fig. 154.

"Mr. Keates invented a moderator lamp consuming sperm oil, and yielding a light equal to 10 sperm candles, which he advocated as a suitable standard.

Fig. 155.

The most ingenious standard proposed is that of a portion of the gas-flame itself. The credit of the conception is shared by both Mr. Fiddes and Mr. John Methven, who, unaware of each other's investigations, conducted a series of experiments on the same lines.

In the course of his photometrical observations, Mr. Fiddes found that if a circular hole about ½-inch diameter were made at a given height in an opaque chimney, and this placed over an argand flame in lieu of the usual glass chimney, the amount of light passing through the hole was a constant quantity, notwithstanding variations in the illuminating power of the gas.

Mr. Methven's researches led him to a similar conclusion; his later experiments showing that the amount of light (equal to two standard

candles), passing through a slot 1 inch long and  $\frac{1}{4}$  inch wide, in an opaque screen, is constant with gases ranging from 15 to 20 candles power; and that, when either common or cannel gas is carburetted



Fig. 156.

with gasoline (light petroleum spirit, boiling point below 120° Fahr.), the amount of light vielded by a flame 21 inches long is constant, whatever the illuminating power of the gas employed. As the result of this latter discovery, Mr. Methven uses a shorter and wider slot for the carburetted gas. Fig. 154 shows the Methyen standard with the long and short slots combined on the same slide for the ordinary and carburetted gas respectively. Fig. 155 shows the carburettor fitted with bye-pass arrangement, so that when connected to the gas-pipe supplying the Methven standard, either ordinary gas or carburetted gas may be used. Photometrical observations are greatly simplified by the ease with which it can be used, the saving of time which it effects, and the avoidance of that distraction of mind on the part of the operator which is inseparable from the employment of candles.

In the Pentane standard of Mr. A. Vernon Harcourt, the gas employed for producing the light is "a mixture of air with that portion of American petroleum which, after repeated rectification, distils at a temperature not exceeding 122° Fahr. The liquid thus obtained consists almost entirely of pentane, the fifth member of the series of paraffines." Burning at the rate of ½ a cubic foot per hour, this gas gives a flame which yields a light equal to that of the standard candle.

standard lamp on a different principle to that above referred to, in which, instead of a mixture of pentane and air, pentane only is burned.

The lamp, shown in Fig. 156, resembles an ordinary spirit lamp, with the chimney added to keep the flame steady, and raise the temperature of combustion. A wick is employed, not, as in the ordinary lamp, at the point of ignition, but several inches from it; its use being to convey the liquid pentane by capillary action to the part of the tube where volatilization of the pentane takes place by the warmth conducted downwards from the flame. The wick is enclosed in a tube jacketed by another tube to produce a steady temperature; and this again is covered by the larger tube with the contracted upper end, as shown. The chimney is moveable for adjustment at any required height.

To put the lamp in action, first remove the lower tube, and having warmed the inner tubes, light the pentane vapour, as it rises in the smaller one. Put on the large tube with the chimney attached; and the top of the flame, on raising the wick slightly, will pass into the chimney.

Two narrow slots are cut in the chimney on opposite sides, so that the tip of the flame is visible through either of them. When the chimney is set at a definite height above the lower tube, and the flame is adjusted so that its tip is between the upper and lower limits of the slots, the centre portion of the flame appearing between the lower tube and the chimney, gives a definite quantity of light.

The 10-candle Pentane Argand, which is the latest proposed standard, is the result of the combined efforts of Mr. A. Vernon Harcourt and Mr. Dibdin, and was recommended to Parliament in 1895 by "The Standards of Light Committee," as a trustworthy standard for official use in testing the illuminating power of the gas supplied by the London Gas Companies.

A description of Mr. Dibdin's apparatus, Fig. 157, is given in Section IX. of the appendix of the Committee's Report as follows:—

The apparatus used in producing this standard consists of two separate portions, viz., the burner and the carburettor.

The burner is a specially constructed tricurrent Argand burner; the annular steatite ring being perforated with 42 holes, each hole being 0.71 millimetre in diameter. The three air currents are: (1) The central current rising inside the steatite to the inner portion of the flame; (2) a current rising outside the steatite, and caused to impinge upon the flame by an inner metal perforated and incurved cone, the top of which is level with the top of the steatite. (3) An outer current rising on the outside of the above cone, and between

that cone and the glass chimney. The inner perforated cone is punctured with ten apertures, 0.25 inch in diameter, which are provided for the purpose of equalizing the two outer currents of air as may be required to suit the height of the flame.

The glass chimney is carried in the groove provided on the outer cone, which answers the purpose of a gallery; the dimensions of the chimney being 6 inches high and  $1\frac{1}{2}$  inches inside diameter.




Fig. 157. Dibdin's 10-Candle Pentane Argand.

Measurements of Burner.

Number of holes													
Diameter of holes					٠				٠	0.71	mm.	= 0.028	ins.
Inside diameter of													
Outside diameter o													
Diameter of inside	of	met	al	001	10 (	at t	op			23.62	**	= 0.930	99
Chimney, length										152.40		= 6.000	
Height of cut-off	iar	nete	r			•				38·10	19	= 1.200	
Height of cut-off	•	•	•	•	•		•	•	•	54.61	11	= 2.150	"

The centre of the flame to be immediately over the terminal of the photometer-bar.

The top of the flame should be maintained as nearly as possible at 8 inches above the steatite, this point being indicated by the wires crossing the blue glass screens carried on each side of the burner on the metal supports. The flame is steadied by the small air directing cone situated centrally beneath the steatite, the apex being 0.08 inch below the metal support carrying the steatite.

On the side of the burner to be presented to the photometer disc, a metal screen  $8\frac{1}{2}$  inches in height is placed and screwed securely to the base plate. The middle portion of this screen is cut away so as to leave above the top of the steatite burner an opening 2·15 inches in height and 1·4 inches in width, the lower portion of this opening being exactly level with the top of the steatite. The light emitted horizontally through this opening by the flame produced by the combustion of the gaseous mixture of atmospheric air and pentane, formed in the carburettor described below, is used as the standard of light. It is equal to the light emitted by 10 parliamentary sperm candles.

The lower portion of the screen has an opening 1 inch wide by 2.8 inches in height, to allow free access of air to the under portion of the burner.

The position of the burner in relation to the photometer disc is to be fixed by the burner fitting gas-tight into a faced joint attached to the photometer at the required point; and the burner is to be set at such a height that the centre of the illuminated disc and the bottom edge of the cut-off shall be in the same horizontal plane. The length of the connection between the burner and carburettor may be varied, but should not be more than 5 feet. The centre of the flame is to be immediately over the terminal point of the photometer-bar.

The carburettor for the 10-candle Pentane Argand consists of a circular vessel constructed of tinned plate, 208.2 mm. (8 inches) in diameter, and 50.8 mm. (2 inches) in depth, having a spiral division 25.4 mm. (1 inch) in width. This division is made by soldering a strip of metal, 4 ft. 6 in. in length and 2 inches wide, gas tight, to the under side of the top of the carburettor; so that when the top is fixed on, the bottom of the strip comes close to the bottom of the vessel, and is sealed by the pentane, so that the air has to pass over pentane for a distance of about 4 ft. 6 in. and becomes thoroughly saturated. At

the end of the spiral division, near the side of the carburettor, a bird fountain is fixed for charging the carburettor, and keeping it charged at a constant level with liquid pentane. The lower end of the liquid fountain tube is closed, and rests upon the bottom of the tank. Through the side of the tube, which is 0.4 inch (10.1 mm.) in diameter, 16 holes, 1 mm, in diameter, are bored close to the bottom. and through these the pentane enters the carburettor. At the inside of the inlet tube, 1 inch from the lower end, a small tube, 8 mm. in diameter and 20 mm. in length, is connected thereto and turned upwards. The fountain inlet tube is carried up through the top of the carburettor, and continued in the form of a bulb having a capacity of about 200 c.c. Stopcocks are provided at the top and bottom of the bulb, for convenience in filling with pentane; and the portion above the upper stopcock is opened out in a funnel shape for the same purpose. When the carburettor is being charged, the gas must be extinguished to avoid the risk of the vapour firing and causing an explosion.

The inlet for gas or air is at the side of the carburettor and at the terminal of the spiral division, the outlet being placed in the centre of the vessel so that the air or gas may travel over the liquid pentane throughout the whole length of the spiral division, and thus become fully charged with the volatile vapour of the pentane.

When using this standard the pentane must be visible in the fountain bulb.

Mr. A. Vernon Harcourt's new 10-candle pentane lamp, Fig. 158, (for the sale of which Alexander Wright and Co., Limited, have been appointed sole agents), embodies the latest and ripest ideas of what is required in a perfect standard of light, viz.: That it should be simple in construction, efficient in action, and easy of manipulation. In this instrument, besides other marked improvements in the direction of simplicity, the pentane is fed to the burner by gravitation from the vessel on the upper end, thus ensuring great regularity of flame, a matter, obviously, of the utmost importance in a light standard.

The inventor gives the following instructions for putting the lamp in action:—

The lamp, having been placed in the position it is to occupy, with the reservoir of pentane half full upon the bracket, is levelled by observing that the height of the pentane against the glass is the same on both sides. Its height is then adjusted so that the bottom of the chimney-tube is at the same height above the bench or table as the centre of the disc or photoped. The distance between the top of the burner and the bottom of the chimney-tube is set at 47mm. (1.85-inches), and is accurately centred, by means of a cylindrical wooden block. To light the lamp, the two stopcocks of the reservoir are



FIG. 158. HARCOURT'S 10-CANDLE PENTANE BURNER.

opened, and the india-rubber tube is alternately pressed and relaxed a few times, that pentane vapour may pass The pinchcock, which has been into it. closed, is then gradually opened, and the lamp is lit. The top of the flame should rise about an inch above the bottom of the chimney-tube. The light given by the flame below the chimney-tube is the same as long as the top of the flame, looked at horizontally through the talcwindow, is above the bottom of the window, and does not reach the crossbar. To put out the lamp, the stopcocks and pinchcock are closed. The original adjustments need only be repeated when the lamp has been moved. The small cone which is placed round the flame, to steady and screen it, has its opening turned in the direction in which the beam of light is to go. If the lampblack coating should be rubbed off the inside of the cone, it must be renewed. The lamp should be lit a quarter of an hour before it is used, and the height of the flame adjusted from time to time

by a small movement of the pinchcock.

## JET PHOTOMETERS.

The three following instruments, which are each employed to determine the illuminating value of gas, though only approximately correct in their indications, are yet sufficiently trustworthy to render them useful and valuable auxiliaries to the more absolute method of testing already described.

Their great recommendations are their portability, and the ease and celerity with which the illuminating power can be ascertained by their aid.

Their action depends on the relation which the specific gravity of the gas bears to its illuminating power. The flame being kept at a given height, the pressure required, and therefore the rate of consumption, will vary according to the density of the gas and its consequent illuminating value.

### The Jet Photometer.

Lowe's jet photometer, as improved by Sugg and Kirkham (Fig. 159), affords a ready means of ascertaining, by a momentary inspection,





Fig. 159.

whether the gas being produced is uniform in quality. The apparatus consists of a King's gauge of delicate construction, with its semi-circular scale indicating the pressure. A steatite jet having a fine orifice is fixed at the top of this, and the gas issuing therefrom, and being lighted, gives a flame which should be constantly maintained at 7 inches.

The scale shown in Fig. 160 is for gas of 14 to 19 candles illuminating power. The same scale is used for 20, 25, or 80 candle gas, but with a different jet, and a lesser consumption per hour, the gauge pointing to the place where the figure 16 stands, but with the number changed to 20, 25, or 80, conforming to the standard quality of the gas to be supplied according to the Special Act of Parliament.

The range of the jet is necessarily short. It is correct at the gauge point, but with a slightly increasing error on the numbers above and below—the error being against the gas in going up, and in favour of it in going down. This is due to variations in the pressure—increasing or diminishing—at the point of ignition. Within the degrees marked on the scale, however, this error is not important.

The gas-tap is shown on the right side of the instrument. The small cylinder on the left side is in communication with the water-cistern in the body of the gauge, and contains a compensator, which,



on being screwed up or down as required, adjusts the water-line, so that the pointer of the gauge stands at zero when the gas-tap is closed.

## Sugg's Illuminating Power Meter.

This instrument is shown in Fig. 161, and, as the name indicates, is used for ascertaining the illuminating power of gas. The mode of putting it in operation is as follows:—Having filled it up to the water line scratched on the glass in the small box on the right side, connect it to the gas supply with a piece of metal tube. The inlet is a ground

union joint, fixed in the centre of the back of the instrument. Turn the lever so as to make the gas pass through the measuring-drum, and let it get rid of all the air, or other kind of gas in it. Light the



Frg. 161.

burner and adjust the flame to 8 inches in height. Then, when the large hand arrives at 16, change the position of the lever, so as to make the gas pass to the burner without going through the measur-The large hand will then stop ing-drum. at 16. Wind up the clock by means of the remontoir on the top of the meter just in the rear of the dial ring. Start the clock by moving the slide which is on the left of the meter, close to the governor. Then, when the hand of the clock is passing any one of the divisions of the minute, change the position of the lever of the bye-pass, so as to make the gas pass through the meter. When the hand has made one complete revolution, stop the meter by means of the lever, in the manner before described, and read off the illuminating power. The minute clock should not be stopped either before or

after the observation, unless it is desired to put the clock entirely at rest.

Thorp and Tasker's Jet Photometer.

This is an ingenious and handy instrument (Fig. 162), for enabling the illuminating value of the gas to be ascertained from inspection at any time and place. It is well understood that the quantity of gas passed in a given time will bear a proportion to the size of the orifice (this is the principle on which the aërorheometer is made—a useful instrument by the same inventors for indicating the quantity of gas consumed by different burners, &c.); and further that the gas-flame being maintained at a given height, the quantity of gas consumed, and the pressure, will vary as the illuminating power. A moveable or floating disc inside the glass tube regulates the size of the orifice, and its position in the tube, corresponding to the graduations of the scale at the side, indicates the illuminating value.

## VARIATIONS IN THE ILLUMINATING POWER OF GAS.



Fra. 162.

Most gas managers, in the course of their experience, must have observed variations, sometimes considerable, in the illuminating power of their gas, for which they have been unable satisfactorily to account. These variations are unquestionably due, to a great extent, to changes of atmospheric pressure. When the pressure is augmented, the luminosity is increased, and vice versā. To determine this point, Dr. Frankland instituted a series of important experiments, of which the following are the results:—

Pressure Inches of					m	um	Observed insting Power.
80	·2 .						100.0
28	. 2						91.4
26	. 2					-	80.6
	.2	-	-	-	-		78.0
22	.2		•	Ī	-	·	61.4
	·2 :	•	•	•	•	•	47.8
	·2 :	•	•	•	•	•	87.4
	•2	•	•	•	•	•	29 • 4
	2	•	•	•	•	•	19.8
	.2		•		•	•	12.5
10		•	•	•	•	•	0.0
10	. 6	•	•	•		•	9. <b>0</b>

The diminution of luminosity follows a fixed and definite law, which may be thus expressed: The decrease in illuminating power is directly proportional to the decrease of atmospheric pressure. Of 100 units of light emitted by a gas-flame burning in air, 5·1 units are extinguished by each reduction of 1 mercurial inch of atmospheric pressure. On the other hand, if a lightless flame be made to burn under augmented pressure it becomes luminous.

The chief cause of the difference is the increase in the volume, and therefore decrease of the density, of those heavy hydrocarpons to which the luminosity of a gas-flame is attributed when the atmospheric pressure is reduced, and vice versā.

### TABLE

Showing the Percentage of Loss of Light by Mixing Air with Coal Gas.

Per Cent. Air.				L		of Light. r Cent.	Per Ce	nt.				L	osa Pe	of Light. or Cent.
1.						6	8							58
2.						11	9							64
8.						18	10							67
4 .						26	15							80
5.		:	:			88	90			•			:	98
6.		•	Ī	-		44	80		-	•	Ċ	•	Ī	98
7 .		:	:		:	58	40		Ċ				:	100

#### TABLE

Comparing (approximately) the Specific Gravity of Gas (Air being 1.000) with the Illuminating Power in Standard Sperm Candles.

No. of Cndls.	Spec. Grav.	No. of Cndls.		Spec. Grav.	No. of Cndls.		Spec. Grav.
10 equal to	about '880	20 equal	to about	508	80 equal	to	about '678
11 ,,	.392	21	,,	.522	81	••	·69 <b>4</b>
12 .,	· <b>405</b>	22	,,	·587	82	••	·708-
18 ,,	· <b>416</b>	28	•	·550	88	••	·722
14 ,,	·480	24	**	·565	84	••	·738
15 ,,	·448	25	**	•585	85	••	·755
16 ,,	· <b>4</b> 55	26	,,	.605	86	••	·775
17 ,,	· <b>468</b>	27	,,	·6 <b>2</b> 5	87	,,	.790⋅
18 ,,	·482	28	,,	·645			
19 ,,	· <b>49</b> 5	1 29	**	•662	Į		

### THE SPECIFIC GRAVITY OF GAS.

Specific Gravity a Test of Quality.

If coal gas is free from carbonic acid, sulphuretted hydrogen, and air, specific gravity is a proper test of quality; the denser it is, the greater will be its illuminating power—increase in weight and light-giving property being due to the presence of a larger proportion of olefiant gas and the other richer and heavier hydrocarbons.

Ordinary Method of Determining the Specific Gravity.

The apparatus required in determining the specific gravity of gasare a thin glass globe of about 100 cubic inches capacity, with two stopcocks on opposite sides, a good air-pump, and a very delicate-balance. The experimental room should also be furnished with a barometer, showing the atmospheric pressure, and thermometers indicating the temperature both of the air and gas. The method of manipulation is as follows:—

First.—Open the two stopcocks; the globe will then be full of air at the atmospheric pressure and temperature. Carefully weigh the globe while in this state, and make a note of the weight.


Second.—Attach the globe by one of the stopcocks to the airpump, close the other stopcock, and exhaust it as perfectly as possible. Having closed the stopcock, remove the globe and weigh it in its exhausted state. Suppose that it now weighs 31.5 grains less than before, then these 31.5 grains represent the weight of the air abstracted.

Third.—Now attach the globe either to an experimental gasholder or to a gas-pillar connected by a pipe to the main, and fill the globe with the gas. When full, remove it and weigh it a third time. Suppose that the weight is now 14.2 grains more than when in its exhausted state, then these 14.2 grains represent the weight of the contained gas. Then, as 31.5 (the weight of the air) is to 14.2 (the weight of the gas), so is 1.000 (the specific gravity of the air) to the specific gravity of the gas. Or divide the weight of the gas by the weight of the air, and the quotient is the specific gravity of the gas: thus-

 $\frac{14 \cdot 2}{81 \cdot 5} = \cdot 450, \text{ specific gravity of the gas compared with air as unity, or } 1 \cdot 000.$ 

Dr. Letheby's Method of Determining the Specific Gravity.

With Dr. Letheby's apparatus (Fig. 168) the use of the air-pump is dispensed with. It consists of a similar glass globe about six inches in diameter, furnished with two stopcocks, to one of which is attached a glass tube half an inch in diameter and 7 inches long, fitted with a jet for burning the gas, and having a thermometer inside of the tube to indicate the temperature. The other stopcock can be attached by a suitable nozzle to a gaspillar, and in practice the gas is kept flowing through the apparatus, being consumed from the jet at the upper end. The exact weight of the globe when full of air at mean temperature and pressure is engraved upon it; and a counterpoise weight is provided, exactly equal to the weight of the globe when exhausted.



necessary to be observed in the shutting of the cocks, because if the



Fig. 163.

upper one were first closed, the gas within the globe would be at the pressure of the gas within the main, instead of that of the atmosphere. The globe is then placed in the balance, and a sufficient number of grains and fractional parts added to the pan containing the counterpoise weight to equalise the beam. Suppose that it takes fifteen grains, then these represent the weight of the gas, and say that the globeful of air weighs 85 grains, then—

$$\frac{15}{85}$$
 = 429, the specific gravity of the gas.

But it is necessary in making such observations to correct the volume of gas to mean temperature and pressure, and to allow for the moisture present in all aëriform bodies in contact with water. To these points the observations which follow apply.

# CORRECTIONS FOR TEMPERATURE, BAROMETRIC PRESSURE, AND MOISTURE.

Owing to the contraction and expansion which take place in the bulk of all aëriform bodies, due to the variations in atmospheric temperature and pressure, it is necessary, when estimating and comparing their volume, to adopt one common temperature and barometric pressure as the standard. The mean temperature of 60° Fahr. and 30 inches of mercury have been adopted as the most convenient, and to this standard their volume is accordingly reduced. For example:

Correction for Temperature.—All aëriform bodies expand 1-491·4th part of their volume at 82° Fahr. for every degree of increase of temperature (1-278rd of the volume of the gas at 0° Centigrade for each degree of the same scale). Now suppose it is required to ascertain what volume 1000 cubic feet of gas at 68° will occupy at 60° the mean temperature. We know by the above-mentioned law that a quantity of gas which at 82° is 491·4 parts, will at 60° become 519·4 (60-82=28+491·4=519·4) and at 68°, 527·4 (68-82=36+491·4=527·4), then—

$$\frac{1000 \times 519 \cdot 4}{527 \cdot 4} = 984 \cdot 88 \text{ cubic feet.}$$

Or, again, if it is required to know the volume which 1000 cubic feet of gas at 56° will occupy at 60°, then—

$$\frac{1000 \times 519 \cdot 4}{515 \cdot 4} = 1007 \cdot 76$$
 cubic feet.

Correction for Pressure.—The amount of decrease or increase in volume is inversely as the pressure. To ascertain what volume 1000 eubic feet of gas at 28.5 inches will occupy when the mercury stands at 30 inches, the mean barometric pressure, then—

$$\frac{1000 \times 28 \cdot 5}{80} = 950 \text{ cubic feet.}$$

Or, again, if it is desired to ascertain the volume which 1000 cubic feet of gas at 80.6 inches will occupy at 30 inches, then—

$$\frac{1000\times30\cdot6}{30}=1020 \text{ cubic feet.}$$

Or,

Correcting at Once for Temperature and Pressure.—Suppose it is required to ascertain what volume 1000 cubic feet of gas at 72° temperature and 29.8 inches pressure will occupy at standard temperature and pressure, then—

$$1000 \times \frac{519.4}{591.4} \times \frac{29.8}{30} = 970.90$$
 cubic feet.

Correction for Moisture.—It has been proved by experiment that one cubic inch of permanent aqueous vapour at the mean temperature of 60°, and the mean pressure of 80 inches, weighs 1929 grains; and the following Table, founded on the researches of Dalton and Ure, and given by Faraday in his "Chemical Manipulation," shows the proportion by volume of aqueous vapour existing in any gas standing over or in contact with water, at the different temperatures indicated, and at a mean barometric pressure of 80 inches.

Temp Deg. Fa	). hr.		 roportion of Vapour in ne Volume of Gas.	Temp Deg. F	•	O	oportion of Vapour in ne Volume of Gas.	Tem Deg. F	p. ahr		roportion Vapour in Ine Volum of Gas.	
40			.00933	54			·01588	68			·02406	
41			.00973	55			.01586	69			·02483	
42			.01018	56			·01640	70			·02566	
43			.01058	57			.01698	71			· <b>02</b> 653	
44			.01098	58			.01758	72			.02740	
45			.01188	59			.01810	78			.02830	
46			.01178	60			.01866	74			.02923	
47			.01218	61			.01923	75			.03020	
48	•	:	.01258	62			-01980	76			.03120	
49		:	.01298	63			.02060	77			.03220	
50		·	.01888	64			.02120	78	-		·03328	
51	•		.01880	65			.02190	79			.03423	
52		i	01426	66			.02260	80			.03533	
53			·01480	67			.02330	_				•

To determine by means of this table the quantity of aqueous vapour present, it is necessary to multiply the volume of the gas by the tabular number corresponding to the temperature, thus:—Suppose 100 cubic inches of gas weigh 16 grains at the temperature of 72°, and at mean barometric pressure, then, according to the table, the volume of aqueous vapour present is—

$$100 \times .02740 = 2.74$$
 cubic inches.

This corrected to mean temperature will be

$$2.74 \times \frac{491.4 + 28}{491.4 + 40} = 2.678$$
 cubic inches.

Now, with respect to the volume of the gas, 100 cubic inches at 72° are equal to—

$$100 \times \frac{491 \cdot 4 + 28}{491 \cdot 4 + 40} = 97.7$$
 cubic inches at a temperature of 60°

Hence 97.7 - 2.678 = 95.022 cubic inches, the volume of dry gas at mean temperature and pressure.

To arrive at the weight of the volume of dry gas, the volume of aqueous vapour must be multiplied by 1929 grains, the weight of a cubic inch of permanent aqueous vapour, as before stated, and the product deducted from the total weight of 16 grains; thus—

$$16 - (2.678 \times .1929) = 15.488$$
 grains.

Then for the weight of 100 cubic inches of dry gas we have-

$$\frac{15 \cdot 488 \times 100}{95 \cdot 022} = 16 \cdot 298 \text{ grains.}$$

And as 100 cubic inches of air at mean temperature and pressure weigh 31 grains, we have—

$$\frac{16.298}{81}$$
 = .525, as the specific gravity of the gas.

If, instead of making the correction for moisture, it is preferred to dry the gas as it passes into the globe, this may be done by causing it to flow through a glass tube, half an inch in diameter and about 18 to 20 inches long, containing pieces of dry calcium chloride; that substance having a strong affinity for moisture. Before using, the chloride of calcium should be fused in an earthenware crucible at a low temperature, then poured on a clean stone surface, and as soon as cold, broken in pieces and put in the tube. The gas in passing through the tube to fill the globe should be made to travel slowly; about 15 minutes being the usual time allowed.

Wright's Method of Determining the Specific Gravity.

For ascertaining the specific gravity of gas, Mr. Wright used a light balloon (Fig. 164), capable of containing one cubic foot or 1728 cubic inches.

His directions for performing the experiment are as follows:—

Expel the air from the balloon by folding it in the form in which it is first received, ascertain the weight of the balloon and car, fill the balloon with gas, insert the stopper, and put as many grains \* in the car as will balance it in the air; add the number of grains which it carries to the weight of the balloon, and deduct the amount from the tabular number corresponding to the degree of



F10. 164.

temperature indicated by the thermometer, and the pressure indicated by the barometer (pp. 814-15); divide the result by the tabular number due to the temperature and pressure of the gas (to ascertain which, allow the gas to blow upon the bulb of the thermometer until the mercury is stationary), and the first three figures are the specific gravity.

### EXAMPLE I.

Weight of balloon and grains in car, 560.

Then-

$$\frac{924-560}{959} = .879, \text{ the specific gravity.}$$

### EXAMPLE II.

Temperature of the air	•			80.5 in. Tabular number,	1005
Barometer				80.5 in.	1067.
Temperature of the gas Barometer always the san	ne	as a	ir	62° Tabular number,	1012.

Weight of balloon and grains in car, 560.

<sup>\*</sup> The weights used are not troy grains, 100 of them being equal to 58.56 troy grains; they are each equal to 1.728 cubic inches of air, when the barometer is at 30 inches, and the thermometer at  $60^{\circ}$ .

Then-

$$\frac{1067 - 560}{1012} = .501$$
, the specific gravity.

Lux's Specific Gravity Apparatus.

The gas-balance, shown in Fig. 165, for determining the specific gravity of illuminating gas, is the invention of Mr. Frederick Lux.




Fig. 165.

It is constructed on the principle of the common lever-balance, with a curved scale attached by means of a coupling-rod to the standard. The scale is graduated from 0 to 1; and the tongue or pointer, moving in close proximity thereto, enables the operator to take a direct reading of the specific gravity of the gas under examination.

Instead of consuming the gas through the vertical tube, a pipe can be arranged to convey the gas to the photometer for the purpose of testing its illuminating power.

To Find the Weight in Pounds of any Quantity of Gas at 60° Fahr. and 80 in. Bar., the Specific Gravity being known.

RULE.—Multiply the quantity in feet by the specific gravity, and the product by .07497 (weight of a cubic foot of air), and the answer will be the weight of gas in lbs. avoirdupois.

Example.—What is the weight of 9400 cubic feet of gas, its specific gravity being .480?

 $9400 \times \cdot 480 \times \cdot 07497 = 888 \cdot 26$  lbs. of gas.

TABLE.

Weight of 1000 Cubic Feet of Coal Gas of Different Specific Gravities at 60° Fahr. and 80 Inches Bar., Saturated with Moisture.

Specific Gravity. Air 1:000	Weight per 1000 Cubic Feet. lbs.	Specific Gravity. Air 1:000	1000 Cubic Feet.	Specific Gravity. Air 1:000	1000 Cubic Feet
.880	28 · 489	•470	85.285	•560	41.988
•385	28.863	•475	35·610	565	42.358
•390	29 · 238	•480	<b>35·985</b>	•570	42.732
•895	29.618	•485	36.860	•575	48 · 107
•400	29.988	•490	86 • 735	•580	48 • 482
•405	80.868	•495	<b>87·1</b> 10	•585	43.857
•410	80.788	•500	87 • 485	•590	44 • 232
•415	81 · 113	•505	37 · 860	•595	44.607
•420	81 • 487	·510	88 • 285	.600	44.982
•425	31·86 <b>2</b>	•515	88 · 610	•605	45 • 357
•430	82 • 287	•520	88.984	•610	45.732
· 485	82.612	*525	89 · 859	•615	46 · 107
•440	82 · 987	•530	89·78 <b>4</b> ,	•620	46 · 481
•445	33 · 362	•585	40 · 109	•625	46 · 856
·450	83 · 737	•540	40·484	•630	47 · 281
·455	84.111	•545	40.859	•635	47.608
•460	94·486	-550	41 · 284	•640	47.981
· <b>4</b> 65	34.861	•555	41.608	•645	48 - 356

## TABLE OF VARIOUS GASES.

THEIR DENSITY, SPECIFIC GRAVITY, AND WEIGHT,
DRY AND SATURATED WITH MOISTURE,
AT THE STANDARD BAROMETRIC PRESSURE OF 80 INCHES.

Name.	Symbol.	Density.	Gravity. Air	Weight of I	Cubic Foot rains.	Cubic Fe to 11b.av1	et equal dupois.
			1.000.	At 82° F. Dry.	At 60° F. Saturated.	At 82° F. Dry.	At60°F Satrtd.
Hydrogen	H	1.000	-0698	89.15	86.89	178 · 80	192·86
drogen	CH.	7.985	•554	812.61	290 · 57	22.89	24.09
Ammonia	NH.	8.510	-590	383 · 17	309 · 68	21.01	22.60
Acetylene	C.H.	12-970	•899	507.58	471.99	18.79	14.83
Carbonic Oxide	co l	18.965	•968	546.73	508 • 19	12.80	18.77
Olefiant Gas	C.H.	13.970	•969	546.93	508:37	12.80	18.77
Nitrogen	N.	14.020	•9721	548 . 88	510.19	12.75	18.72
Air		14 · 422	1.000	564.62	524.82	12.40	18.84
Nitrio Oxide	NO	14.990	1.039	586 - 86	545 • 49	11.98	12.83
Oxygen	ō	15.960	1.1066		580.78	11.20	12.05
Sulphuretted Hydrogen		16.990	1.178	665.16	618 • 27	10.52	11.32
Carbonic Acid	CÒ.	21.945	1.522	859 • 15	798 - 58	8.15	8.76
Nitrous Oxide	N.O	22.000	1.525	861.80	800.58	8.18	8.74
Sulphurous Acid	SO.	31.950	2.257	1,250.84	1.162 66	5.59	6.02
Chlorine	Čľ	35.870	2.452	1.884.74	1,287 · 11	5.06	5.44
Bisulphide of Carbon .	CS.	87.965	2.632	1,486.33	1,881.55	4.71	5.07

### THE ENRICHMENT OF COAL GAS.

When a higher illuminating power than that yielded by the gas produced from ordinary bituminous coal is desired, some method of enrichment is resorted to.

Cannel was formerly the only medium employed for this purpose, and it is the best and simplest, inasmuch as the gas from it is a more regular and durable enricher than any other, and does not require any special and separate apparatus for its production, but of recent years other methods of enrichment by means of oil of different kinds have been introduced, owing to their being less costly.

It does not follow, however, that cannel is or will be entirely abandoned for enrichment purposes. All depends upon the price, and there are already signs that a return to its more general use may result from the increased market value of its rivals.

Gas enrichment is of less pressing concern to-day than it was at one time, because the principles of economical lighting are now better understood and more widely applied, resulting in the introduction of improved burners, and the better regulation of the pressure at or near to the point of consumption.

The incandescent gas-light, also, has shown how a vastly increased illuminating power may be obtained without resorting to enrichment, with, at the same time, a striking economy in gas consumption.

The chief advantage derived from enrichment is the assistance it lends towards preventing the deposit of naphthalene, the richer gas tending to keep this hydrocarbon suspended within it in the gaseous form.

The following is a résumé of the various enriching methods employed:

The Peebles Process consists in cracking or decomposing oil in iron retorts at a temperature of  $1750^{\circ}$  Fahr., and washing the resultant gas by the fresh oil, which is afterwards decomposed in a similar manner. Blue oil, having a specific gravity of  $\cdot 85$ , is generally used. Its illuminating value as an enriching agent is about 90 candles per 5 cubic feet of the gas. The yield of coke is  $5\frac{1}{2}$  cwt. to the ton.

The Maxim-Clark System is a method of carburetting by means of gasoline volatilized in a copper retort heated by steam. The volatilized gasoline passes into a small holder traversed also by the gas to be enriched. One gallon of gasoline, having a specific gravity of .68, suffices to raise 8000 cubic feet of 15 to 17 candle gas by one candle.

The Whessoe-Munich Method of enrichment is by means of benzol. This is volatilized in a vessel heated by steam, and fitted with ribbed trays covered with cloth, on to which the benzol drops. It is claimed as one of the advantages of this system that it is only necessary to pass a portion of the coal gas through the carburettor, and that such portion, being enriched, acts as an enricher for the rest. The quantity of benzol required to enrich 1000 cubic feet of gas one candle is 3 ounces.

The Dvorkovitz System enriches by means of solar distillate oil, specific gravity .886. This is cracked or decomposed in iron retorts heated to a bright red, and the gas so produced, mixing in the proportion of 3 per cent. with ordinary coal gas of 15 to 16 candles value, raises the illuminating power about 1½ to 2 candles. The inventor claims a high value for the residual tar and oil.

Carburetted Water Gas.—The plant here is used both for gas making and gas enriching\*. It consists of three vessels or shells, called the generator, the carburettor, and the superheater. The gas is made by admitting steam at about 100 lbs. pressure through a bed of incandescent coke. The steam being decomposed into its constituent gases oxygen and hydrogen, the resultant oxygen combines with the carbon of the coke forming carbonic acid, which, rising through the higher layers of incandescent coke, is reduced to carbonic oxide, and this mixing with the hydrogen forms what is called "water gas." This is non-luminous, and is afterwards enriched in the carburettor with oil, which imparts to the gas its light-giving properties. The gas thus enriched is passed through the superheater to "fix" the oil vapours.

The Dinsmore System of enriching with the hydrocarbons present in the tar has already been referred to, page 54.

<sup>\*</sup> Gas is, of course, produced in all the other processes, but this is a gas producer on a large scale.

### PUBLIC ILLUMINATIONS.

In provincial towns the Gas Manager is usually called upon to arrange and superintend the illuminations that are given to celebrate any great national or local event. On such occasions the following particulars will be found useful:—

Mode of Supply and Price of Gas.—Illumination devices are generally supplied with gas direct from the main, without the intervention of a meter to register the consumption. Where the illuminations are anything like universal, the fixing of meters is altogether impracticable.

Taking the consumption of each jet \* to be at the rate of one cubic foot of gas per hour, which is a fair average, including loss by leakage and trial lighting, the following will be the rate of charge according to the price per 1000 cubic feet:—

At per 1000. 6s. 6d.	.070 -4	1.3		h	At per 1000. 4s. 2d.	.050	of 14	ist *	homm
		ıu.	per jet * per	nour.		000	oi ia.	per jet* per	nour.
6 5	·077	,,	,,	"	4 1	.049	"	1)	**
64	·076	,,	,,	,,	4 0	·048	,,	17	**
68	·075	"		,,	8 11	.047	,,	,,	"
6 8 6 2	·074				8 10	.046			
6 1	.078	.99		"		·045	"	,,	**
6 0		"	"	"	8 8	.044	"	**	**
	.072	"	"	"			"	27	"
5 11	·071	"	19	,,	8 7	.043	"	,,	91
5 10	·070	,,	23	,,	8 6	·042	٠,	19	,,
59	.069	**	39	22	8 9 8 8 8 7 8 6 8 5 8 4	·041	,,	,,	**
58	.068	,,		,,	8 4	.040	11	"	"
	.067				8 8	.039	"	"	
5 6	.066	"		"	3 2	.038			"
5 5		**	**	"	8 1	.037	"	"	17
5 0	.065	"	**	**			"	,,	**
5 4	.064	,,	**	1)	8 0	.086	77	,,	**
5 7 5 6 5 5 5 4 5 3 5 2 5 1	.068	,,	,,	,,	2 11	.032	,,	,,	,,
<b>5</b> 2	.062	"	,,	"	2 10	.034	,,	,,	,,
<b>5</b> 1	.061	,,	"	"	29	.033	"	"	"
5 0	.060		• • • • • • • • • • • • • • • • • • • •		28	.032			
4 11	.059	"	17	"	2 7	.031	**	**	"
		"	11	**	2 6	1000	"	**	**
	.058	**	"	,,	2 0	.030	**	,,	**
4 9	.057	"	11	**	2 5 2 4	.029	"	,,	"
48	.056	,,	,,	**	2 4	· <b>02</b> 8	**	"	,,
47	.055	,,		,,	28	.027	,,	,,	**
4 6	.054	"	,,	"	22	.026	"	,,	,,
4 5	.058				2 1	.025			
4 4	.052	,,	,,	,,	2 0	.024	,,	"	"
		"	"	"		V24	"	**	**
48	.051	,,	"	,,	1				

\* By the term "jet," as here used, is meant the small gas-flame at each hole drilled or punched in the pipes forming the different devices.

When the ordinary No. 1, 2, and 3 fish-tail burners are employed, the consumption may be reckoned at the rate of 3, 4, and 5 cubic feet per hour each respectively, and charged accordingly.

It is proper to stipulate that no illumination should amount to less than 50s.

Service or Supply Pipes.—It is the usual rule for the Gas Authorities to convey at their own cost a service-pipe from the main, and from 8 to 12 feet up the front of the building to be illuminated, provided the whole length of pipe required does not exceed 86 feet. A charge is made for any additional length. The expense of fixing the devices in their position is also charged. To the end of the pipe in front of the building a stopcock is attached for shutting off or regulating the supply of gas.

Care should be taken to have the pipes of ample capacity, otherwise the illumination will be poor and ineffective.

When the building to be illuminated is large, it is advisable to run up a service-pipe at each end, and one in the centre, connecting them together in the front; each pipe, of course, having a distinct connection with the main in the street.

The service-pipes should be laid with a slight fall to the main; and the use of all abrupt angles—such as square elbows—should be avoided, bends being employed instead.

The service-pipes are temporary only, being lent by the Gas Authorities, and are removed by them when the illuminations are over.

**Devices.**—The devices are paid for by the private inhabitants, or the Local Authorities, or by both, as the case may be.

They may consist of—

Initial and other letters, single-lined—thus, A —and double-

lined—thus,

Mottoes-straight, curved, or circular.

Lanterns with coloured Devices.

Laurel Scrolls.

Garlands.

Festoons.

True Lovers' Knots.

Stars of various kinds.

Mitres.

Crescents.

Crosses.

Plumes, as Prince of Wales' Feathers.

Aureoles.

Crowns.

Shields.

Anchors.

Masonic Emblems.

Heraldic Crests.

Corporation Arms.

Other Devices suitable to the particular occasion.

The devices are made by the manufacturers of gas-fittings, wroughtiron tubing, and others, and are supplied to Gas Authorities and the Trade at about the following prices:—

Single-lined Letters, in Iron or Copper, fitted with Strong Union Couplings.

18	of Lette inches	r.					Size of Ing the inch	alet. bore .					11s.	Prior	each.
24	11						ŧ "		•		•	•		6	**
80	"	•	•	•			,,	•	•	•	٠	•	==	6	,,
86	"	•	٠	•	٠	•	,,	•	٠	•	•	•		Ď	**
42	93	•	•	٠	•	•	ģ ",	•	•	٠	•	•		Ŏ	"
48	**	•	٠	٠	•	•	<u>ŧ</u> "	•	•	٠	•	•		Ď	,,
54	***	•	٠	٠	٠	٠	· · · · · · · · · · · · · · · · · · ·	•	•	٠	•	•		0	**
60	11						ž "			•			80	0 '	99

Double-lined Letters, in Iron or Copper, fitted with Strong Union Couplings.

Lengti 18	h of Lette inches	er.				of Inlet.			126	Price	
24	19				ì	"			15	0	,,
80					Ĭ.	"			17	6	"
86	"				Į.	"			20	0	"
42	"				į	"			24	0	"
48	11				Ì	"			28	0	"
54	"				ì	"			38	0	99
60	**				1	"			40	0	,,

Brunswick Stars and Stars with Eight points, Made of Wrought-Iron Welded Pipe, and fitted with Strong Union Couplings.

Diameter.		•	Size of Inlet.				Price with Star Centre.				Price with Shield Centre.				Price with Plume Centre.				
8	feet			1 inc	h bore			2	8. 0	Ŏ.			2 2	Ö			2 17	Ö	
4	,,			14	>>			2	19	0			2 15	0	•		8 10	0	
5	"			11	,,			8	6	6			8 10	0			45	0	
6	"			1 <del>1</del>	,,			4	15	0			5 0	0			5 15	0	
7	"			11	"			6	8	6			6 10	0			7 5	0	
8	"			2	"			7	7	Ō			7 15	Ō			8 10	Õ	

Crowns and plumes cost about one-third more than Stars.

Scrolls, garlands, heraldic crests, and other devices, at prices varying according to the elaboration of the design.

Wrought-iron pipes, drilled, and with star jets inserted, are supplied at about the ordinary list price.

The devices may be "home-made," and if so will be less expensive; but unless constructed by skilled and tasteful workmen, they will present a scraggy, irregular appearance when lighted up.

Illuminated Borders.—A very pretty effect, easily managed, and one that gives a rich fulness to the central illumination of a building. is obtained by running wrought-iron tubing along the principal angles. with holes drilled in the tube at distances about 6 inches apart, and having small jets or star burners inserted. The burners may be placed wider apart, and globes made use of. These prevent the lights from being extinguished by the wind, and also heighten the general effect. In this case a short piece of brass tube, with elbow-socket and gallery, must be inserted. Globes ground all over, or white opal globes, or white and coloured globes arranged alternately, show to the best advantage.

Coloured Fires.—A display of coloured fires, at intervals, from prominent points of elevation, adds greatly to the effect of an illumination.

The following are some excellent recipes for their production:—

Lilac Fire.
Chlorate of potash
Purple Fire.
Oz. Drms.   Oz.
Yellow Fire.
Os. Brms.         Nitrate of soda

	$\boldsymbol{B}$	lue	or	$\boldsymbol{B}$	<b>en</b> g	al	F	ire.						
Dry nitrate of potash											6 p	arts, o		Drms. 101
Sulphur	: :		·	·	÷	·					2 -	,,	8	9 į
Tersulphide of antimon	у.	•	•	٠	٠	•	٠	•	•	•	1	**	1	12
	7	Vei¢	ht,	1 11	). ;	COS	t, 1	S.						
		-		0	r									
Ammonic sulphate of c											۰.	arts, o		Drms.
Chlorate of potash .	oppe		:	:	:	:	:	:	:	:	6	marus, o	6	7
Shellac											Ĭ	"	1	1
	We	aigh	t, 1	lb.	; 00	st,	2s.	8d.						
			Gr	een	F	ire								
2711												4		Drma.
Nitrate of baryta	•	•	٠	•	٠	٠	•	•	•	•	77 P	arts, o	2 1 1 2	
Chlorate of potash	:	: :	:	:	:	•	:	:	:	:	5	"	õ	
Charcoal or lamp black											8	"	0	
Metallio arsenic	•		•	•	•	٠	•	•	•	٠	2	**	0	5
	W	igh	t, 1	lb.	; 00	et,	1s.	6đ.						
		•	•	_	r									
				•	•						_			Drms.
Nitrate of baryta		•	•	•	٠	•	•	•	•	•	9 p	arts, o	r 10 8	10 9
Chlorate of potash	: :	•	:	:	•	:	:	:	•	•	14	"	î	18
on the second					-				•	•		"	_	
	W	eigh	<b>5</b> , 1	ID.	; 00	) BT,	18.	60.	•					
		0	rin	nso	n i	Fir	re.							_
Nitrate of strontia .											80 n	arts, o		Drms.
Sulphur								Ċ	:	Ċ	221		2	14
Chlorate of potash .		•	٠	•	•	•	٠				20	"	8	
Charcoal or lamp black		•	•	•	•	•	•	•	•	•	5	"	0	10
	W	eigh	t, 1	lb.	; 00	et,	18.	6d.	ı					
			$R_i$	ed	Fi	re.								
					_ •								Os.	Drms.
Nitrate of strontia .		•	٠	•	٠	٠	٠	٠.	٠	٠		arts, o		0 2
Sulphur	: :	•	:	:	:	•	:	:	:	:	13 5	)) 4)	8 1	8
Charcoal or lamp black				•					•	•	8	3),	ō	11
Sulphide of antimony	•	•	•	•	•	•	•	٠	•	•	4.	,,	1	0
	W	sigh	t, 1	lb.	; 00	et,	18.	6 <b>d</b> .						
				C	r									
Mitmeta of strengtic				_							Δ.			Drms.
Nitrate of strontia . Shellac	:		•	•	•	•	•	•	•	٠	9 p	arts, o	r 10 8	10 9
Chlorate of potash			:	:	:	:	:	:	:	:	11	3) ))	ı	
<u>-</u>	W.	eigh	. 1	114		5 <b>6</b> 4	1-	د ۾			•		-	
	44	or R II	w, 1	ID.	,	JB6,	TR.	ou.	•					

#### White Indian Fire.

											Drms.
Nitrate of potash									24 par	ts, or 11	10
Sulphur									7 ,	. 8	6
Sulphur	io	(rea	lgs	ur)					2 ,	. 1	0
		•	-						-		

Weight, 1 lb.; cost, 1s.


In no case should the chlorate of potash be ground along with the sulphur, as ignition, caused by the friction, might ensue.

The ingredients should be reduced to the finest powder (excepting the shellac, which should only be beaten into small fragments) by bruising them in a mortar made of hard wood, the chlorate of potash being ground separately. They should then be intimately mixed together, by passing them three or four times through a hair sieve. When mixed, keep the material in a close-stoppered bottle, to prevent spontaneous combustion. All the ingredients must be perfectly dry to insure success.


The mixtures are best fired in hemispherical dishes, or ladles made of beaten iron, about 5 inches diameter and 2½ inches deep in the centre. The fumes arising from the different fires should be avoided.

A pound in weight of any of the mixtures is sufficient for a fire (though any quantity may be used); and the cost varies from 1s. to 2s. 3d. each. The ingredients can be obtained from almost any chemist and druggist.


## ILLUMINATION DEVICES.



Figs. 166 to 179.




2.






BRITANNIA RULES THE WAVES




Figs. 196 to 202.







Figs. 208 and 204.




Figs. 205 to 211.














Figs. 220 and 221




Figs. 922 to 224.




Figs. 225 and 226.






Figs. 230 and 231.



Figs. 232 and 233.



# THE USE OF GAS FOR PURPOSES OTHER THAN LIGHTING.

The use of gas for cooking, heating, and motive power has made rapid strides of recent years; and the steady increase that is taking place in the consumption of gas for purposes other than illumination is a matter of interest. Twenty to twenty-five years ago this consumption was only beginning to make itself felt, yet within the brief period which has elapsed, large industries, giving employment to much capital and many workpeople, have been called into existence to produce the machinery and appliances required, to describe which would need a treatise in itself. These, which are of the most numerous and varied kind, are of great excellence, whilst improvements are constantly being effected therein.

For domestic and greenhouse use there are numberless heating stoves of superior design and workmanship, and in cooking stoves and ovens there is equal variety.

The uses to which gas may be advantageously put in every branch of trade where heat is required, are only limited by the number of such trades. For example, in coffee roasting, in the manufacture of confectionery, the baking of bread, the finishing of shoes, in dentistry, in the production of jewellery, in wire welding, tempering steel, enamelling, and many others.

The gas-engine already successfully competes with the steam motor for all purposes where the power required to be exerted is intermittent and within moderate limits.

For handiness in application, and cleanliness and safety in use, gas, as a fuel, is unsurpassed. The use of gas in these ways means a saving of time and labour, and is an important step towards the solution of the smoke difficulty in towns.

Taking its advantages in these respects into account, there is economy in its employment even when, as in scattered districts, its price per 1000 cubic feet may be considered high. In towns where the price of gas is comparatively low, there is a positive economy in its adoption, beyond the special recommendations named.

The manufacture of gas-engines was at first confined to the smaller sizes, from one man power to 10-horse power, but now larger sizes equal to as high as 100-horse power are being made.

In adopting this motor, neither boiler nor chimney are required, and hence it can be employed in buildings, and in out-of-the-way

corners in establishments where a steam engine is altogether inadmissible. It is always available for work on the opening of a tap, and it goes on working continuously day and night with the least possible attention. Moreover, the percentage efficiency of the gas-engine is greatly in excess of that evolved by the steam motor.

As a ventilating agent the gas-flame is of the greatest use, and in rooms where the means of ventilation are provided it promotes their efficiency, though it has not been employed in this direction as extensively as its merits deserve. In spacious assembly rooms in which crowded meetings are held, the gas "Sunlight," or the "Regenerative" light, with their ventilating tubes, may be recommended as superior to any other method of artificial lighting.

One of the best methods—perhaps the very best method—of reducing the proportion which capital expenditure in gas-works bears to revenue, is to cultivate a day consumption of gas, by affording facilities for and encouraging in every legitimate way the use of gas for cooking, heating, ventilating, and motive power. It is interesting to ascertain approximately, and to keep a permanent record of, the proportion of gas consumed in the daytime as compared with the night. To do this it is necessary to take the stock of gas in the holders at 8 a.m., 8 p.m., and 12 midnight.

This policy, if pursued to a successful issue, is virtually to reduce the percentage of capital in the proportion of such consumption, because the plant is brought to bear in earning profit during the daylight as well as in the lighting hours.

If local governing Authorities (or some of them) in possession of gas-works had the real, permanent good of their respective communities at heart—or were less narrow and short-sighted in their views—instead of appropriating large gas profits in aid of rates (a policy which, besides being unjust, always tends to waste and extravagance), would aim at reducing the selling price of the gas, they would, by so doing, give encouragement to the establishment and growth of what may be termed The Minor Industries, whose success, and even existence, are so largely dependent upon a cheap, cleanly, and handy fuel for heating and motive power purposes.

This wise policy of selling gas at cost price (including, of course, interest on capital) has a three-fold advantage, inasmuch as it promotes the day consumption, it goes a long way towards abolishing the smoke nuisance, and it broadens the base of the general prosperity by the encouragement it gives to the growth of a variety of trade interests.

#### THE RESIDUAL PRODUCTS.

One, and not the least important, of the duties of the Gas Manager is to do what in his power lies to promote the interests of the Undertaking under his charge, by utilizing the residual products of gas manufacture to the utmost extent.

It is a remarkable fact that there are no waste products in a properly conducted gas-works. The coke, breeze, tar, ammoniacal liquor, sulphur, spent lime, retort carbon, and even the clinker and ash from the furnaces are all marketable, and therefore of more or less value. The flue gases from the retort stack are even utilized for the generation of steam, and for heating the air supply to the combustion chamber where the regenerative system is applied.

Coke and Breeze.—Coke, as ordinarily produced, is not well adapted for domestic use for kitcheners, for use in greenhouses, or stoves in general; and, in consequence, its sale is often restricted. To render it suitable for these purposes, it requires to be broken into pieces of smaller and more uniform size.

Wherever means have been adopted for this purpose, the article has been found to command a ready sale; and instead of mountains of coke in every available corner of the works, the material is, as a rule, cleared out almost as quickly as it is produced.

The labour, inconvenience, and waste attendant on stacking are thus avoided, the premises can be kept in better order, and the revenue is augmented.

For breaking the coke by hand, a hammer of the form shown in Fig. 285, with a chisel edge at one end, and four prongs at the other may be recommended.

A machine for breaking coke is made by Smith, Beacock, and Tannett, of Leeds. This is used by Mr. Sellers at the York Gas-Works, who gives the cost, and describes the advantages attending its use.

"The engine (a 4-horse vertical) and breaker, and fitting up of same, cost £148; being, for the engine, £108, the breaker, £28, and fitting up, £7. By placing the engine and breaker upon one frame, so that both could be moved upon one set of wheels, the cost would be materially reduced, and the working very much improved. The machine, when at full work; will break 20 tons of coke per day. We

have one man to look after the engine, and two to feed the machine; but as the first named is not fully occupied with the engine, he assists the other two in helping carters to put the broken coke into bags, &c., the net cost of all which adds 9d. per ton to the price. Then in breaking a ton of coke, about 1 cwt. passes through the screen, and is sold as breeze at 1s. 6d. per ton, or, sav. 1d. per cwt. The real result, therefore, of breaking coke stands thus: We sell our unbroken coke at 10s. per ton, and broken at 10s. 8d.:



Fig. 285.

the 8d. added being 9d. per ton for labour. and coke converted into breeze by breaking. less 1d. received for breeze per ton of coke broken. The cost of maintenance of engine and breaker we consider is more than recouped by, first, the saving of labour that would have been employed in loading the coke if it had not been broken; secondly. the saving of the cost in labour and depreciation of stacking the coke if it were not sold: and, thirdly, the advantage gained in getting rid of the coke, so as to enable us to maintain our price of 10s. per ton, for upon our annual make of coke for sale a reduction of 1s. per ton would inflict a loss of ·£500 a vear."

Another excellent coke breaker is that devised by Thomas and Somerville. This machine requires very little power to drive it, and the waste of coke by its use is remarkably small. At a trial of the machine at the Old Kent Road works, the following results were obtained:-

	8	•	a.
500 feet of gas consumed by a 2-horse power gas	<b>!-</b>		
engine, at cost price of gas delivered in holder		0	9
Oil and cotton waste		0	6
Two men supplying machine with large coke, an	d		
shovelling up broken, at 4s. 6d	. !	9	0
Interest and wear and tear (say)		0	8
		_	
Total per day	. 1	0	6
	•	_	
			Ω -

	8.	d.
For 80 tons of coke broken per day at the rate of .  And for loss by dust and waste, 1 cwt. with price of	0	11/2
coke at (say) 18s. 4d. per ton	0	8
Cost of breaking per ton .	0	9 <del>1</del>

The coke thus manipulated finds a ready and constant market as quickly as it is produced, the result being an average net gain of 1s. 6d. per ton of coke.

Coke, immediately on being slaked with water, weighs about 15 per cent. more than when unslaked; the bulk of the moisture, however, evaporates—about 8 per cent. only being retained.

A ton of coke is about a chaldron and a half.

A chaldron of coke varies in weight from 121 to 15 cwt.

For the quantity of coke produced by different coals, see the tables on pages 12, 18, 16, and 17.

Coal Tar.—The yield of tar from coal per ton in gas-works ranges up to 12 gallons, and from cannel up to about 17 gallons. The average production in gas-works throughout the country will not exceed 11 gallons per ton. The total production of coal tar in the United Kingdom is probably about 600,000 tons.

The utilization of the tar for its products is not pursued at many gas-works, though it is done at a few, and if well managed it is a source of profit.

Considerably more skill and care are required in the distillation of tar than in the manufacture of sulphate of ammonia; nevertheless, it is safe to predict that before many years have elapsed, this branch of practical chemistry will be widely practised on those gas-works where there is space and convenience.

The manufacture on gas-works may be wisely restricted to the distillation of the tar for the light and heavy oils, and the production of anthracene and pitch.

The principal dangers to be apprehended in the process are the leaking or boiling over of the stills and the firing of vapours, causing conflagration, and the stoppage of the pipe passages with accretions of solid matter, chiefly naphthalene, resulting in explosion; but these dangers can be minimized, or altogether averted, under proper supervision and by the use of efficient apparatus.

The specific gravity of tar produced from ordinary coal ranges from 1.120 to 1.150; that from cannel coal, from .980 to 1.060.

#### TABLE

Showing about the Average Proportion of the several Products obtained from the Distillation of 10,000 gallons of Coal Tar. (Dr. Letheby.)

Ammoniacal liquor 40 per cent. benzole 90		240 0 gals. 84 4 ,, 53 1	Solvent naphtha Last runnings . Dead oil			41.8 gals. 12.0 3018.7
,, ,,	Pitch	99 I ,,	86 tons		•	9010.1 ,,
	Piton			5.		

### TABLE

Showing the Average Percentage of the Products Obtained from 100 Tons of Coal Tar. (Roscoe.)

									1	2	
		,							8.0		per cent
Light oils and o Heavy oils, napl									1·5 85·0	0·8 25·0	"
Pitch Water and loss	:	:	·	:	:	:	:	:	50·0 10·5	60·0 12·2	"
,									100.0	100.0	

Mr. C. Greville Williams remarks ("King's Treatise," Vol. III., p. 281) that—"The working results to be obtained from a charge of 1200 gallons vary so greatly, according to the nature of the tar and the care with which the distillation has been made, that it is exceedingly difficult to give any average which will be satisfactory to distillers in different parts of the country. The following figures are placed side by side as extreme cases":—

					shire: n Smith.)		(" C	London : hemistry as ed to the Arts [anufactures.")
Ammoniacal liqu	ıor			gallons	80			50
First light oils				"	88			20
Second light oils				"	157			20
Creosote oils .				,,	104			250
Anthracene oils				"	229			50
Pitch				tons	8.25			4

The following yield of bye-products from each ton of tar distilled is given by Mr. Colson from his own working:—

Crude naphtha, 80	p.o.,	at	120°	C.				6.79 gals.
Carbolic acid, crud								8·50 `,,
Heavy naphtha, 20	p.o.	, at	160°	C.				<b>3·55</b> ,,
Creceote								58·04 ,,
Ammoniacal liquor								
								33 · 91 lbs.
Anthracene, 33 p.c.								
Pitch								12·67 cwts.

The coals used were best Derbyshire, 78 per cent.; South Yorkshire, 18 per cent.; Nottinghamshire Cannel 9 per cent., and, carbonized at fairly high heats, the mixture yielded 10,486 cubic feet of 17-candle gas, 12·1 gals. tar and 82·8 gals. ammoniacal liquor of 10-oz. strength per ton. The sulphate made per ton of coal was 29·82 lbs.

Tar Pavement.—This is made of the breeze, ashes, and clinker of gas-works and mill furnaces, along with shingle or coarsely ground granite, mixed with coal tar.

A coke fire is first made on the ground, and the solid ingredients cessed in a heap round and over it; layer after layer being gradually added as the heat penetrates through the mass, until sufficient bulk of the material is ready.

If preferred, or if a large quantity of material has to be dried and heated, a raised sheet-iron floor may be made, supported on bricks, with the coke fire underneath; or a permanent fire-brick floor may be constructed, ramified with flues underneath leading to a chimney, and having a fire grate at one end.

In the meantime, whilst the solid ingredients are being dried and heated, the tar is being boiled, and, when ready, the two are taken and mixed together in small heaps (say about three ordinary barrow loads) in the proportion by measure of 1 part tar to 7 parts solid.

The whole is then turned over immediately whilst hot, and thoroughly mixed, until every particle of the solid ingredients has received a coating of tar.

The mixed material is then sorted into three separate heaps of graduated fineness, by passing it through two sieves with \frac{3}{4}-inch and \frac{3}{5}-inch meshes respectively. It is now ready for use, and may be laid down at once or kept in stock for a short time until required.

It is preferred by some to sort the solid ingredients before mixing with the tar, as the latter is liable to clog the sieves. In this case an ordinary screen,  $\frac{3}{4}$  inch between the bars, and supported at an angle, is employed; and all that passes through it is afterwards riddled through a  $\frac{3}{4}$ -inch sieve.

The three different grades of material are then dried and made hot as described, and thoroughly mixed with hot tar in these proportions:—

1.	Coarse material	{1 part tar {9 parts solid	or 24	gals.	tar to	1	ton	solid.
2.	Riddlings	1 part tar 7 parts solid	or 80	•	,,	1		,,
8.	Fine material	1 part tar	or 86	:	,,	1		"

The footpath being properly kerbed, the upper edge of the stones standing 8 inches above the solid bottom of the path, the rough prepared material, No. 1, is put down 2 inches thick; then No. 2 about inches inch thick, and finally No. 8 about inches thick. Each layer as it is put down is rolled with a 10-cwt. roller until thoroughly consolidated. Corners which cannot be reached by the roller, must be consolidated by punning. Derbyshire spar or fine granite sprinkled over the surface improves the appearance of the pavement.

Three tons of the rough (No. 1) and 1½ tons of the fine prepared material (Nos. 2 and 3) will cover 60 square yards, or a footpath 2 yards wide and 30 yards long.

Ammoniacal Liquor.—The amount of liquor obtained up to the outlet of the scrubbers per ton of coal carbonized, varies from 15 to 45 gallons of 10-oz. strength, depending on the class of coal used, and the efficiency of the apparatus for arresting the ammonia.

The product of ammoniacal water or liquor, when treated with sulphuric acid, is sulphate of ammonia; when treated with muriatic or hydrochloric acid, it is muriate of ammonia or sal ammoniac.

The manufacture of sulphate of ammonia from the ammoniacal liquor is fast becoming general in gas-works, and properly so, as the process is both simple and profitable. That it must be more profitable to use the liquor at the place of production than at a distance away, is evident, taking into account the saving of the cost of transport of a bulky material. The estimated annual make of sulphate of ammonia in the United Kingdom is 180,000 tons.

The apparatus required in its manufacture is neither complicated nor costly; the process is free from danger (though fatal accidents have occurred through carelessness, or the use of imperfect appliances), and an intelligent labourer can learn it in a week's time.

Sulphate of ammonia is manufactured either by the continuous or the intermittent system, and there is much to be said in favour of each.

In the continuous system (see Figs. 236, 287, and 288), the crude ammoniacal liquor is first pumped up into an overhead supply tank, and thence flows in a regulated stream into a tubular heater, the




Fig. 236.




Fig. 237.




Fig. 288.

liquor traversing the tubes which are surrounded by the hot waste gases from the saturator. In this way, raised to boiling point, it goes forward into the column still, which is supplied with steam at a regulated pressure.

The upper portion of the still consists of a series of trays having each a cast-iron hood, through the serrated edges of which the heated gas travels and parts with its free ammonia. Descending into the liming chamber of the still the liquor mixes with the cream of lime supplied thereto by means of a force pump. The limed liquor then flows into the lower portion of the still, or into another smaller still adjoining, and passing over and through a second series of trays and hoods with serrated edges, the fixed ammonia is liberated.

The term "free ammonia" is not strictly accurate, but it is well understood as referring to the ammonia in combination with the feeble acids sulphuretted hydrogen and carbonic acid, as ammonia, sulphide and carbonate, and which is liberated by boiling. The "fixed ammonia," on the other hand, is that which exists in combination with hydrochloric, sulphuric, and other strong acids, as ammonia chloride, theocyanate, sulphate, theosulphate, and ferrocyanide. This is not expelled by boiling, but is liberated from these salts by decomposition in the presence of cream of lime. The proportion of free ammonia in the liquor is about 70 per cent., and of fixed ammonia about 30 per cent. of the whole.

The ammonia and other gases escape by the pipe rising from the cover of the still, and passing first through a baffle box, to have the moisture removed, they go forward into the saturator. This is made either of solid virgin lead or is a wood vessel lead-lined, and contains weak sulphuric acid, which on being sufficiently saturated with the incoming ammonia gas, precipitates sulphate of ammonia in the vessel. The sulphate is then fished out with a scoop, or is discharged by mechanical means, on to a lead draining table.

The spent liquor flowing from the still should not contain more than '008 per cent. of ammonia. It is run into a cooling and depositing tank, and thence overflows into the drain.

The waste gases, after traversing the heater, are conveyed away by a pipe to the condenser, and forward, either through an open purifier containing oxide of iron, or through a Claus plant for the recovery of the sulphur.

In actual practice the intermittent system is a simpler process, the heat being applied directly to a boiler containing ammoniacal liquor. The firing is continued until the ammonia is driven off, when the

residuary water is run out of the boiler and the vessel re-charged with ammoniacal liquor. Steam is generated at the same time that the ammonia is driven off, and the two together conducted to the saturator, from which point the processes are similar.

The strength, and consequent value of ammoniacal liquor, is commonly ascertained by Twaddel's hydrometer, and also by the quantity of sulphuric acid of the specific gravity 1845 required to neutralize the ammonia contained in one gallon.

Each degree of Twaddel is equal, as nearly as possible, to 2 oz. of acid per gallon of the liquor; hence arises the description of its value:—

Water of 5 degrees Twaddel is called 10-oz. liquor.

And so on, at the rate of 2 ounces for each degree, so that 10-oz., 12-oz., or 14-oz. liquor means ammoniacal liquor of such a strength that 10-oz., 12-oz., or 14-oz. of sulphuric acid, of the specific gravity of 1845, are required to neutralize the ammonia contained in a gallon of it. Each ounce strength is equal to .847 oz. ammonia per gallon of liquor.

To convert degrees of Twaddel's hydrometer into specific gravity, multiply the number of degrees by 5, and add 1000 to the product.

Example.—Twaddel  $6 \times 5 + 1000 = 1080$  specific gravity.

To convert specific gravity into degrees of Twaddel, deduct 1000 from the specific gravity, and divide the remainder by 5.

Example.—Specific gravity 1080—1000÷5=6 degrees of Twaddel. To determine the weight of a gallon of ammoniacal liquor of any strength find the specific gravity by the above rule. This will represent the number of ounces avoirdupois in weight per cubic foot. Divide by 16 to ascertain the number of pounds per cubic foot, and by 6.25 (gallons per cubic foot) for the weight of a gallon of the liquor.

Example.—Required weight per gallon of 10-oz. liquor (5° Twaddel),

 $(5 \times 5) + 1000 = 1025$ , specific gravity and weight per cubic foot in ounces avoirdupois.

 $\frac{1025}{16} = 64.063$  lbs. per cubic foot.

 $\frac{64.068}{6.25}$  = 10.25 lbs. weight per gallon of 10-oz. liquor.

Or the weight may be found more expeditiously by the rule given immediately after the next table on page 880.

It is well known that the greater the proportion of ammoniacal gas contained in a pure solution, the less the density or specific gravity of such solution. How, then, it may be asked, is the apparent contradiction to be explained, that the larger the quantity of ammonia contained in gas liquor, the greater the density?

The explanation is to be found in the circumstance that gas liquor is not a solution of ammonia pure and simple, but contains other gases in solution, and in combination with the ammonia in the form of salts, which increase its specific gravity; and the more ammonia liquor contains, the greater is its power of arresting and absorbing such other gases.

It is by reason of this latter-mentioned fact that Twaddel's hydrometer is tolerated as a gauge of the strength and value of the ammoniacal liquor of gas-works. At the best, however, its employment for this purpose is very unsatisfactory.

The method of testing by saturating the liquor with sulphuric acid is an improvement on the hydrometer; but even that is imperfect, as has been pointed out by Mr. Greville, who ascertained by experiments on nine different samples of liquor that an average of 22.5 per cent. of the ammonia present in combination was not indicated by the acid.

The mode of testing by Mr. Thomas Wills meets the difficulty. His plan is to mix with the liquor a caustic alkali for which the acids of the salts contained in the liquor have a stronger affinity than for the ammonia with which they are combined. On the mixture being strongly heated, the salts are decomposed in presence of the caustic alkali, and the ammonia being driven off in the gaseous state and conveyed into a solution of sulphuric acid is secured as sulphate of ammonia. This and the other methods of testing are fully detailed by Mr. Hartley in his brochure on "Ammonia Liquor Tests."

TABLE

Showing the Specific Gravity, Weight per Cubic Foot, Weight per Gallon, and Ounce Strength of Ammoniacal or Gas Liquor of different degrees Twaddel.

Degrees. Twaddel Liquor.	Specific Gravity and Weight per Cubic Foot in Ounces Avoirdupois.	Weight per Gallon. lbs.	Ounce Strength.	Degrees Twaddel Liquor.	Specific Gravity and Weight per Cubic Foot in Ounces Avoirdupois.	Weight per Gallon. lbs.	Ounce Strength.
0	1000	10.0	0	124	1062 · 5	10.625	25
	1002.5	10.025	i	18	1065	10.65	26
1 1	1005	10.05	2	184	1067 • 5	10.675	27
14	1007.5	10.075	2 3 4 5 6 7	14	1070	10.7	28
2	1010	10.1	4	144	1072.5	10.725	29
24	1012.5	10.125	5	15	1075	10.75	80
8	1015	10.15	6	151	1077.5	10.775	81
84	1017.5	10.175	7	16	1080	10.8	32
4	1020	10.2	8	164	1082.5	10.825	88
41	1022.5	10.225	9	17	1085	10.85	84
5	1025	10.25	10	173	1087 • 5	10.875	35
51	1027 5	10.275	11 -	18	1090	10.9	36
6	1080	10.3	12	184	1092.5	10.925	37
64	1082.5	10.325	18	19	1095	10.95	88
7	1035	10.35	14	194	1097.5	10.975	89
73	1037.5	10.375	15	20	1100	11.0	40
8	1040	10.4	16	201	1102.5	11.025	41
84	1042.5	10.425	17	21	1105	11.05	42
9	1045	10.45	18	211	1107.5	11.075	43
93	1047.5	10.475	19	22	1110	11.1	44
10	1050	10.5	20	221	1112.5	11 · 125	45
101	1052.5	10.525	21	23	1115	11.15	46
11	1055	10.55	22	231	1117.5	11 · 175	47
113	1057 5	10.575	23	24	1120	11.2	48
12	1060	10.6	24	25	1125	11.25	50

It will be seen by the above that the weight of the liquor in pounds avoirdupois per gallon is obtained by simply placing the decimal point after the first two figures of the number representing the specific gravity. Thus, liquor of 1025 specific gravity is 10.25 lbs.; and of 1087.5 specific gravity is 10.875 lbs. weight per gallon.

Each degree of Twaddel represents 350 grains above the weight of distilled water. Consequently, 5 degrees represent 1750 grains, or 1 lb.; 20 degrees, 7000 grains, or 1 lb.

In Beaumé's Hydrometer, which was the first instrument of the kind, the divisions are equidistant; and it has two modes of graduation according as it is intended for liquids heavier or lighter than water. This instrument is the one principally in use on the Continent.

Beaumé's Hydrometer Compared with Specific Gravity. For Liquids Heavier than Water.

Degrees Beaumé.	Specific Gravity.	Degrees Beaumé.	Specific Gravity.	Degrees Beaumé.	Specific Gravity
0	1.000	26	1.206	52	1.520
i	1.007	27	1.216	58	1.535
2	1.013	28	1.225	54	1.551
<b>2</b> 3	1.020	1 29	1 · 235	55	1.567
4	1.027	80	1.245	56	1.583
5	1.034	81	1.256	57	1.600
6	1.041	82	1.267	58	1.617
7	1.048	88	1.277	59	1.684
4 5 6 7 8 9	1.056	84	1.288	60	1.652
	1.063	85	1 · 299	61	1.670
10	1.070	86	1.810	62	1.689
11	1.078	87	1.821	68	1.708
12	1.085	88	1.333	64	1.727
18	1.094	89	1.845	65	1.747
14	1.101	40	1.857	66	1.767
15	1.109	41	1.869	67	1.788
16	1.118	42	1.381	€8	1.809
17	1.126	48	1.895	69	1.831
18	1.134	44	1.407	70	1.854
19	1.148	45	1.420	71	1.877
20	1.152	46	1.434	72	1.900
21	1.160	47	1.448	78	1.944
22	1.169	48	1.462	74	1.949
23	1.178	49	1.476	75	1.974
24	1.188	50	1.490	76	2.000
25	1.197	51	1.495	11	1

Beaumé's Hydrometer Compared with Specific Gravity.
For Liquids Lighter than Water.

Degrees Beaumé.	Specific Gravity.	Degrees Beaumé.	Specific Gravity.	Degrees Beaumé.	Specific Gravity
10	1.000	27	0.898	44	<u>0</u> ⋅811
11	0.998	28	0.890	45	0.807
12	0.986	29	0.885	46	0.802
18	0.980	80	0.880	47	0.798
14	0.978	81	0.874	48	0.794
15	0.967	82	0.869	49	0.789
16	0.960	88	0.864	50	0.785
17	0.954	84	0.859	51	0.781
18	0.948	85	0.854	52	0.777
19	0.942	86	0.849	58	0.778
20	0.986	87	0.844	54	0.768
21	0.980	88	0.889	55	0.764
22	0.924	39	0.834	56	0.760
23	0.918	40	0.830	57	0.757
24	0.918	41	0.825	. 58	0.758
25	0.907	42	0.820	59	0.749
26	0.901	48	0.816	60	0.745

Sulphur Recovery.—Claus's plant, made by C. and W. Walker, for the recovery of sulphur in a marketable form from the sulphuretted hydrogen passing from the saturator in the manufacture of sulphate of ammonia, is not only efficient for the purpose, but it possesses the further merit of simplicity.

The hot gases from the saturator are passed through the heater of the sulphate plant, where they are partially cooled in heating the liquor flowing towards the still, and thence through the condenser where they are cooled to the temperature of the air. They then pass into the air inlet box into which air is pumped in the proportion of 24 parts air to the sulphuretted hydrogen. The mixture of gas and air then enters the kiln; which is of wrought-iron lined with fire bricks. and having a fire brick grate on which rests a layer of loose broken fire bricks covered with a layer of hydrated oxide of iron about three feet deep. Passing down through the oxide of iron, the oxygen of the air combines with the hydrogen of the H2S, forming water, leaving the sulphur to unite with the iron, forming sulphide of iron, which is immediately reoxydized by the air. The reaction takes place with such rapidity, that the mass of oxide becomes incandescent, the heat so caused volatilizing the sulphur, which goes forward with the other gases through the fire brick grating at the bottom of the kiln into the depositing chamber. This chamber is built of ordinary brickwork. excepting the portion nearest the kiln, which has a lining of fire brick. A number of transverse baffle walls in the chamber retard the flow of the gas and finely divided sulphur, cooling the latter and causing its deposition.

The chamber is covered with slate slabs, and in the side walls are doorways for clearing out the sulphur at intervals.

The waste gas remaining passes through a cast-iron scrubber filled with limestone, down which a small stream of water is constantly flowing, and in this any sulphurous acid gas which may be present is arrested. Finally, an open purifier filled with oxide of iron receives the spent gas, and arrests any H<sub>2</sub>S that may have escaped decomposition, whilst the remaining innocuous gas escapes into the air.

Should there be an excess or insufficiency of air delivered into the kiln with the foul gases, the outlet gas of the chamber will contain traces of sulphurous acid or sulphuretted hydrogen, which are taken up respectively by the limestone scrubber and the oxide purifier.

Under proper conditions of working, the yield of marketable sulphur

reaches 90 per cent. of the sulphur passing into the kiln, and is of very pure quality.' In Figs. 286, 287, and 288, are shown C. and W. Walker's sulphate of ammonia plant, and the Claus sulphur recovery plant alongside.

Cyanogen.—Within recent years the development of the cyanide process of gold extraction has caused more attention to be paid to the recovery of the cyanogen, which has long been known to be present among the crude products of the distillation of coal in gas manufacture. There are three methods at present in use for obtaining this residual product in a marketable form. They are all based upon the conversion of the cyanogen, which exists in the raw gas chiefly as hydrocyanic acid, into a ferrocyanide of an alkali.

By the first method, the production of Prussian blue in the oxide of iron purifying material is facilitated; and after the oxide is spent, ferrocyanide of potash or soda is obtained by lixiviating the spent material with the requisite alkaline liquid. The conditions most favourable for the absorption of cyanogen by oxide of iron are, however, opposed to economical purification from sulphuretted hydrogen, so that this method of recovery is not one to be recommended.

By the second method, a salt of iron is added to the ammoniacal liquor employed in scrubbing the gas in the ordinary scrubbers or washers, whereby ferrocyanide of ammonium is formed in the liquor; whence, after the ammonia has been distilled off, it can be recovered by precipitation with copperas, or other iron salt, and subsequent conversion by an alkali, into alkaline (sodium or potassium) ferrocyanide. After separating out the ferrocyanide, any sulphocyanide contained in the ammoniacal liquor may also be recovered by precipitation with a salt of copper.

By the third method of recovery, a special scrubber is employed after the ordinary apparatus for the extraction of the ammonia and before the purifiers proper. In this vessel the gas is scrubbed with a solution of soda holding an iron salt or salts in suspension. Ferrocyanide of sodium is thereby formed directly in the scrubbing liquid, whence it can be obtained, but in a very crude and impure form, by simple evaporation.

It should be added that only in very few instances has the recovery of cyanogen been attempted on any large scale. Moreover the amount to be recovered is so very small that it is doubtful whether, except in special circumstances, its recovery would be financially successful. The total amount available for recovery varies with different coals and conditions of carbonization. It may be taken as equivalent to from 1 lb. (or even less), to 8 or 4 lbs. of ferrocyanide (yellow prussiate) of potash per ton of coals, the higher amounts only being reached when very high heats are employed.

Applications of Sulphate of Ammonia in Agriculture.—Mr. W. Arnold gives the following general directions for the application of sulphate of ammonia in agriculture, and a list of the crops for which it is most suitable:—

Sulphate of ammonia is one of the most powerful fertilizers known to modern science. It is especially rich in nitrogen; and when used either by itself or in conjunction with farmyard manure, its good effects are written so plainly in better quality and largely increased yield of corn, that no farmer who has once used it will ever give it up, but will, on the contrary, annually increase its use upon his farm.

When bought at first hand from a gas-works, sulphate of ammonia is guaranteed to contain more than twenty per cent. of nitrogen. Hence its excellent effect upon all corn crops, which is chiefly expended in increasing the yield of grain, but not the straw; and there is, therefore, much less risk of "lodging" from heavy rains. This is a very important advantage. Then, manure rich in nitrogen increases the proportion of gluten in cereals; and this increase is stated by Boussingault to be as much as 10 per cent. With an increase, therefore, of 10 per cent. in quality and of 20 per cent. in yield, the use of sulphate of ammonia ought to be increased tenfold, to the great advantage of the English farmer, for both may be done.

The most suitable dressing is one of from 2 to 8 cwt. per acre, mixed with an equal weight of fine dry earth or sand, and applied early in the spring (say March or April), in moist or showery weather. It should be thoroughly mixed in a barn or dry shed; and, if at all lumpy, beaten with a shovel, and passed through a 45-mesh riddle. It should be carefully sown by hand; or, if in large quantities, with a manure drill. If wheat is to be grown entirely with sulphate of ammonia, it is better to put it on in two dressings—one half in autumn, and the other half in spring.

Upland or meadow grass, wheat, barley, oats, rye, colza, hemp, mangel-wurzel, cabbages, hops, garden produce generally, and beetroot (when grown for sugar), are the crops most largely benefited by this manure; simply because nitrogen, which is its dominant element,

enters largely into their composition. For instance, colza, hemp, and beetroot require each of them 70 lbs. per acre of nitrogen to produce a full and healthy crop; wheat, 58 lbs.; and barley, oats, and rye, 85 lbs. per acre each.

Beans, peas, sainfoin, or clover, in which potash is the dominant element, are not benefited by an application of sulphate of ammonia; but almost all other crops that can be grown will richly repay its use.

In the case of a crop thinned out by wireworm, the ravages of birds or insects, or by a severe winter, the application of 2 cwt. of sulphate of ammonia early in the spring, and lightly harrowed in, will, in many cases, cause a crop that looked only fit to plough up, to tiller freely, and grow away into a full yield of corn for the district.

Mr. Magnus Ohren states the exact quantity of sulphate of ammonia which he considers is required for different crops, as follows:—

For Grass Land.—1½ cwt. per acre; to be put on the land in the month of April, before or after a shower of rain.

For Wheat, Oats, and Barley.—1 cwt. per acre for wheat, in April; 1 cwt. per acre for oats, in April; 1½ cwt. per acre for barley in April.

For Vines.—1 bushel on the vine border, lightly forked in, in the months of March, April, May, and September. This quantity (1 bushel) to be for the nourishment of four vines.

For Onion Beds.—A good sprinkling over the beds two or three times during the growth of the onions.

For Potatoes.—1\frac{1}{2} cwt. per acre as a top dressing, before the haulms appear above ground.

For Greenhouse Plants.—A large teacupful in a bucket of water, to water the greenhouse plants with twice a week. Not to be used, however, for heaths, rhododendrons, or orchids.

For Peach, Apricot, Plum, Currant, and Gooseberry Trees.—A similar solution to that given for greenhouse plants, in the months of March, April, and May. Rose trees and garden plants generally are benefited by the use of the solution. Celery, cabbages, and cauliflowers also grow well when watered with the solution.

For the Raising of Healthy Plants from Seeds.—Sprinkle a good quantity of the sulphate on the seed beds, and then water them a week before sowing the seeds. Melons and cucumber plants also are much benefited by the sulphate of ammonia.

Note. - All vegetation, excepting heaths, rhododendrons, and

orchids, is rendered more luxuriant, healthier, and consequently freer from the destructive attacks of insects, by the use of sulphate of ammonia. In the spring of the year vegetation requires a condensed antiseptic and nourishing food to enable it to withstand the blighting effects of the north-easterly winds, which, being the least electrical of all the winds, lower its vitality, and thus conduce to disease.

The comparative manurial value of equal weights of sulphate of ammonia and nitrate of soda, based on their nitrogen contents, is as follows:—

Sulphate.			Nitrate.
Containing 24 per ce Ammonia.	nt.	9	5 per cent. purity.
1.000	• •		0.792
1.268			1.000

Spent Oxide of Iron.—The oxide of iron used in gas purification may be considered as "spent" when the quantity of free sulphur contained in it ranges between 45 and 55 per cent. by weight of the whole bulk of the material.

Although by continuing to use it the proportion of sulphur can be increased, it is not economical to do this beyond a certain point, as the purifiers would have to be changed more frequently, and the labour required for that purpose would be out of proportion to the benefit derived. If, however (see ants pp. 109 and 110), a small proportion of air or oxygen is sent through the purifiers along with the gas, revivification in situ is effected, and the oxide can be charged with 75 per cent. of free sulphur.

In addition to the sulphur, the spent oxide usually contains a small percentage of salts of ammonia, and some insoluble cyanides of iron, which are of value.

The spent oxide is generally sold at per unit of contained sulphur.

Mr. Andrew Stephenson has devised a handy apparatus (Fig. 289) for estimating the amount of sulphur in the oxide, and gives the following instructions for using the same:—

Weigh 100 grains of spent oxide, dry at 212° Fahr., and weigh to ascertain moisture; put the dried material in the test-tube, A, which is provided at the bottom with a filter of cotton wool.

Bisulphide of carbon is then blown from the holder, B, into the test-tube, A, on top of the spent oxide. It percolates the mass

gradually, and dissolves out the sulphur; the solution finding its way by gravitation into the flask, C, which is placed in a water-bath.

The Bunsen burner is then lighted, and the application of heat soon vaporizes the bisulphide of carbon from the flask, C. The vapour finds its way through the connecting tube into the condenser, and is recovered in the receiver, D, under water, ready for further use.

The sulphur is left in the flask (the weight of which has been previously noted); and when all the bisulphide of carbon is driven off, the quantity of sulphur may be ascertained.

Fit the filter in the test-tube with care. If too tight, it will prevent filtration; if too loose, it will permit some of the oxide to pass through.




Fig. 239.

Three or four times the bulk of the oxide is about the proportion of bisulphide of carbon necessary to dissolve out all the sulphur.

It must always be borne in mind that bisulphide of carbon is very inflammable, and in the gaseous state when mixed with air in certain proportions it is explosive. The bisulphide in the holder, B, should be covered with water.

It is best to melt the sulphur in the flask before weighing, to drive off all bisulphide of carbon.

Gas Lime: Its Composition, and Use in Agriculture.—In a valuable paper on gas lime, published in the Journal of Gas Lighting,\*\*.

Professor Voelcker states that a copious supply of air is necessary to transform the injurious sulphur compounds contained in the material into fertilizing agents.

When exposed to the air (and the longer it is kept exposed thebetter), gas lime is in some respects superior to quick lime as a manure.

The oxygen of the atmosphere destroys the offensive smell, and changes the sulphuret of calcium in it—first into sulphite, and finally into sulphate of lime or gypsum, well known as a valuable fertilizing substance.

In addition to its chemical virtues, gas lime exercises a beneficial mechanical effect upon land, by rendering stiff, heavy, clayey land more porous and friable, and by consolidating light sandy soils.

The crops which are particularly benefited by gas lime are—clover, sainfoin, lucerne, peas, beans, vetches, and turnips. It is a useful fertilizer for permanent pasture, destroying the coarser grasses, and favouring the growth of a sweeter and more nutritious herbage.

It kills moss, heath, feather grass, and other plants characteristic of peaty land, its application to which cannot be too strongly recommended.

As a general rule, two tons per acre is the quantity of gas lime which ought to be put on land.

The proper time for its application is in the autumn or winter.

During the period of storage, the heap should be turned over onceor twice to ensure its complete exposure to the air.

The following is an analysis by Professor Voelcker of a sample of gas lime, kept long enough to be used with safety as a manure.

# Composition of Gas Lime (Dried at 212° Fahr.).

																P	er Cent.
Water of combin	atio	n s	ınd	8.	littl	<b>e</b> o	rga	nic	m	tte	r.						7.24
Oxides of iron an	id al	lun	aine	١, ١	with	tr	800	s of	! p	hos	ph	oric	8.0	id			2.49
Sulphate of lime	(gy	рвт	ım)								٠.						4.64
Sulphite of lime	•	٠.												,			15.19
Carbonate of lim	е																49.40
Caustic lime .																	18.23
Magnesia and all	alie	86															2.53
Insoluble siliceor	18 M	at	ter													•	0.28
																	100:00

In fresh gas lime the proportion of water varies usually from 30 to 40 per cent.

#### TABLE

Showing the results Obtained by the application of certain Manures to Land. (Mr. Wilson, of Largs.)

Manure.	Produce of the Lot in lbs.	Pounds of Hay per Acre.	Increase per Acre over that Untouched.
Left untouched	420	3860	_
21 barrels of quicklime	602	4816	1456
1 ton of lime from gas-works	651	<b>59</b> 08	1848
41 cwt, of wood charcoal powder	665	5320	1960
2 bushels of bone dust	698	5544	2184
18 lbs. of nitrate of potash	742	5936	2576
20 lbs. of nitrate of sods	784	6272	2912
10 bushels of soot	819	6552	3192
28 lbs. of sulphate of ammonia	874	6776	8416
100 gals, of ammoniacal liquor from	945	7562	4202

The land was a piece of three years' old pasture, of uniform quality, divided into 10 lots of 20 perches each. All the lots were manured at the same time with the articles given in the table, and the grass cut and made into hay in July. Each application cost the same.

Ammoniacal liquor is best applied at the following strength:-

The proper time for its application is in the spring, after the grass has commenced growing, and during cloudy weather. It may be sprinkled on the land as water is applied to the streets of towns to lay the dust.

# COAL PRODUCTS.

Tubls of the Principal Substances Obtained in the Manufacture of Coal Gas, and in the Utilization of the Residual Products arising therefrom.

Name of Product.	Formula or Symbol.	Reaction.	Specific Gravity Water = 1.	Boiling Point. Degraes Fahrenheit.	Remarks.
Acetic Acid	C, H, O,	Acid. Neutral	1.062 .698 (a.ir = 1)	248°	Contained in coal tar.
	•				bons in coal gas, but in very small propor- tion. Its own bulk absorbed by water. This hydrocarbon in combination with copper produces a compound of a highly explosive nature, giving rise to obstructions in copper pines, and in the attemnt to remove which
Acridene	C, H, O.	Alkaline Aoid	::	::	dangerous accidents have occurred. One of the coal tar alkaloids. The colouring principle of the madder root. Derived from authracene by the addition of
Alifaceous Oils	A1, (NH,), 48C	Neutral 1, +24 H, 0	::	::	a atoms of O, and the abstraction of 2 atoms of H. Contained in coal far. Obtained by adding a solution of sulphate of
Ammonia	NH,	Alkaline	·69 (air = 1)	270	ammonia to one of suphate of alumina.  13 Vol. H. I woll. N. Exists in coal gas both in  4 true state and in combination.
					copper and brass fittings and in burning with the gas forms nitric acid. Water at common temperature absorbs 788 times its volume of the gas, its removal is therefore easily effected. Test, moistened tumerio
Ammoniscal Liquor		Alkaline	:	:	paper.  The aqueous portion of the condensed coal products, being a solution, chiefly of carbonate, sulphide, and sulphoceanide of am
					monium. Average yield of coal, 25 gals. per ton of 8-or. liquor, equal to 4° Twaddel.

Name of Product.	Formula or Symbol.	Beaction.	Specific Gravity Water = 1.	Bolling Point. Degrees Fahrenheit.	Bemarks.
Amyl	C <sub>1</sub> TH <sub>2</sub>	Neutral	4.9 (air = 1)	:	5 vols. C, 11 vols. H. A constituent (hydro-carbon) of coal gas. Belongs to the sloohol
Amylene	O, H,	Neutral	2·4 (air = 1)	As a liquid	radical series of hyd 24 vols. C, 5 vols. H. O in coal gas, of the ol
Amylhydride	C, H,	Neutral	2.49  (air = 1)	:	also a constituent of coal tar. 22 vols. C, 6 vols. H. Of the marsh gas series
Anilene	C, H, N	Alkaline	1.080	.098	of nydrocarbons. The base of all the dyes bearing this name, and is otherwal by the cation of second
Anthracene	C,4 H,0	Neutral	1-147	.089	hydrogen on nitro-bengole. Contained in the least volatile portion of the coal oils. The colouring principal of mad-
Anthraguinone	C14 H, O.	Aoid	::	::	der, alizarene, is derived from this substance. Derived from anthracene. A coat tar product. Said to be the most powerful agent known for reducing tem-
Aqueous Vapour	H <sub>a</sub> 0	Neutral	.622 (air = 1)	:	perstures in fevers. A constituent of raw gas, and removed, though not entirely, by condensation.
Toluola. Benzol, Benzene, or Phene	о, н.	Neutral	98.	176°	Remarkable for its solvent power for eacut- chone, gutta-percha, resins, and fats. Used also for preparing varnishes, for removing
Benzol Vapour, or Bicar- buretted Hydrogen.	о, н,	Neutral	2·7 (air = 1)	:	grease spots, and cleansing soiled white kid gloves. It is the chief constituent of naphtha, and, treated with nitric acid, yields nitro-benzole, from which anilene is derived. 8 vols. C, 8 vols. H. One of the hydrocarbons existing in coal gas. Slightly absorbed by water; easily condensed by cold. Like the other richer hydrocarbons, it is absorbed by vulcanized india-ribber tubing.
Bicarburetted Hydrogen,					0

Name of Product.	Formula or Symbol.	Besction.	Specific Gravity Water = 1.	Boiling Point. Degrees Fahrenheit.	Remarks.
Bisulphide of Carbon	so.	Acid	2.64 (air = 1)	The liquid	The liquid One of the impurities in ocal gas; and one of the most difficult to eliminate. Not
					Removable by sulphide of calcium (foul lime) in the purifiers.
Bisulphuret of Carbon, see Bisulphide of Carbon.		:			
Bruplio Acid Butyl	C, H,	Acid Neutral	8.94 (air = 1)	::	Contained in coal tar.  4 vols. C, 9 vols. H. A hydrocarbon existing in coal gas, and belonging to the alcohol
Butylene, Tetrylene, Dite- tryl. or Oil Gas.	O. H.	Neutral	Neutral   1.94 (air = 1)	:	radical series.  2 vols. C, 4 vols. H. A hydrocarbon found in coal gas, and of the oleflant gas series. It
Butyl-hydride	0, H,	Neutral	Neutral Gas 2. (air = 1) Liquid ·600	:	is also a constituent of coal tar.  2 vols. C, 5 vols. H. A hydrocarbon existing in coal gas, and belonging to the marsh gas series. It exist also as a colourless liquid.
Butyrio Acid	C, H, O,	Aoid	.978	814°	and is the lightest of all known liquids; its specific gravity being only '600. One of the acids of coal tar,
Caproylene, see Hexylene. Carbolic Acid, Phenic	C, H, O	Aoid	1.065	870°	Contains valuable antisepticand disinfecting
Acid or Fhenol.	0	:	:	::	is obtained from coal tar. This element is the basis of the illuminating or analities of one of an arms of the illuminating
					gen its particles are heated to incendescence, and emit intense light. Afterwards uniting with the oxygen of the atmosphere to form carbonic acid, one of the products of the
					combustion of coal gas. The solid deposit upon the interior surface of gas-retoria is almost pure carbon, and is need in the construction of the Bunsen galvanic battery, and for the carbon points of candles producing the are alsotric light.

Remarks.	A salt produced by the chemical combination of ammonia with carbonic acid gas. When exposed to the atmosphere, it gradually at-	tracts more earbonic acid from the sir, and becomes bicarbonate of ammonia, which is used by bakers, instead of yeast, in preparing light and spongy cakes.  yol. C vapour, 1 yol. O. The presence of this impurity in common coal gas to the extent of only 1 per cent, will diminish the light shout 5 nor sent. Soluble in the own.	volume of water. Is entirely removed from gas by the use of lime. Test, lime water. you. O vapour, y vol. O. Exists in coal gas in small proportion. 100 vols. water absorb about 2-43. Test, an ammoniacal solution	of subchloride of copper.  A constituent of coal tar.	Do. Do.	Do. Do.		eure of cost gas. Consisse manny of carbon. A constituent of coal tar, contained in the light oil.	Includes all the hydrocarbons existing in coal	Volatile hydrocarbons existing in coal gas are liable to be condensed by extreme cold, hence the importance of preventing the gas	from being subjected to a temperature below 50° Fahr. A constituent of coal tar.
Bolling Point. Degrees Fahrenheit.	:	:	:	205°	463°	:	:	864°	•		412°
Specific Gravity Water = 1.	:	1.63 (air = 1)	·967 (air = 1)	<b>:</b> ;	1.081	:	:	.987	:		:
Reaction.	:	Aoid	:	Alkaline	Alkaline	Neutral	:	Alkaline	:		Alkaline
Formula or Symbol.	(NH4)2 COs	<b>°</b> 00	8	C, H, N	C, H, N	C1.8 H1.8	• :	C, H,, N	:	:	O, H, N
Name of Product.	Carbonate of Ammonia .	Garbonio Aoid, called also Black Damp.	Oarbonio Oxide.	Cospitene	Chinolene	Chrysens	Coke	Collidene	Condensable Hydro- carbons.		Coridene

Name of Product.	Formula or	Reaction.	Specific Gravity	Bolling Point. Degrees	Remarks.
Creceote, or Dead Oil .	:	:	:	Fabrenbeit.	Obtained in large quantities in the distillation of of coal tar. Used in the preservation of
		•			timber, such as railway sleepers, &c. It is also useful as a fuel, and in combination with caustic soda and tallow, as a dip for
Cresylic Acid, or Cresol .	О, Н.О.	Aoid	:	897°	washing sneep. One of the coal tar acids.
Grude Naphtha	:	Neutral	:	:	The first naphtha obtained in the distillation of coal tar, and which comes over at a tem-
Oryptidene	C,, H,, N	Alkaline	:	625°	perature from 180° to 310° Fabr. One of the coal tar alkaloids.
Cumene	O, H,	:	<b>;</b> :	831°	A constituent of coal tar, obtained from the
Cumidene	C, H,s N	Alkaline	896.	4.87°	one of the coal tar alkaloids.
Oumole	С, Н,	Neutral	Liquid .870 Gas 4.15 (air = 1)	808°	A constituent both of coal gas and tar of the benzole series of hydrocarbons, 44 vols. C,
Oyanogen	C, N,	:	1.8 (air = 1)	:	6 vols. H. 1 vol. N, 1 vol. C. Produced during the de- structive distillation of coal, but, with the
					exception of a very small proportion, which passes into the gas, is condensed and carried into the far well along with the anmoniscal liquor. Not readily absorbed by water; but he also les and alkaine sulphides. Com-
					bined with iron it forms Prussian blue, and is the cause of the bluish-green colour in spent lime. It is used in the cyanide process
					of gold extraction. In union with sumu- nium sulphide, it forms sulpho-cyanide of ammonium, a substance used by photo-
Oymidene	Q, H, N	Alkaline	:	483°	stituent of the toys known as "Pharaoh's Serpents." It is a highly poisonous gas. An alkaline body contained in coal tar.

Name of Product.	Formula or Symbol	Reaction.	Specific Gravity Water = 1.	Boiling Point. Degrees Fahrenheit.	Remarks.	_
Oymole or Cymene	C10 H14	Neutral	Liquid :861 Gas 4:68 (air = 1)	849°	A constituent both of coal gas and tar; of the benzele series of hydrocarbons. 5 vols. C,	
Dead Oil, see Creceote.					A CORP. TT.	•
Decyle	Coo Han	Neutral Neutral	:::	:::	Constituent of coal tar. Do. do.	JAO J
Disulphide of Carbon, see Bisulphide of Carbon.			:	:		27/ (277/
Ditetryl, see Butylene. Elsyl, see Oleflant Gas.						CHISTER
Ethyl	C, H	Neutral	$8 \cdot (air = 1)$	:	A constituent of coal gas. 2 vols. C, 5 vols. H.;	А
Ethylamene	C <sub>2</sub> H <sub>7</sub> N	Alkaline	:	09	2.15 vois, soluble in 100 vois, water. A constituent of odal tar.	\D
Ethylene, see Oleflant Gas.						шд
Ethyl-hydride	Cs He	Neutral	1.04  (air = 1)	•	A constituent of coal gas. I vol. O, 3 vols. H;	
Eupion	:	:	:	:	Obtained from coal tar, and proposed to be need as a substitute for chloroform.	G 13.
Fire-damp, see Light Car- buretted Hydrogen.						
Green Oil	:	:	:	:	This follows the dead oil in the distillation of coal tar, and mixed with resin and oil, is used for making railway grease. Lamp	
Heptylene, see Enanthy- lene.					black, from which printers' ink is propared, is also made from it.	

Name of Product.	Formula or Symbol.	Reaction.	Specific Gravity Water - 1.	Boiling Point. Degrees Fahrenheit.	Remarks.
Hexyl	Ce Hus	Neutral	:	 	A constituent of coal gas.
Hexylene, or Caproylene.	C, Hu	Neutral	:	160°	A constituent of coal ter, contained in the
Hexyl-hydride	C, Hu	Neutral	:	154°	ugnt our. A constituent of coal gas.
Hydrio Sulphide, see Sulphuretted Hydrogen.  Hydride of Amyl, see Hydride of Butyl, see Butyl-hydride.  Hydride of Butyl, see Hydride of Ethyl, see Ethyl-hydride.  Hydride of Ethyl, see Ethyl-hydride.  Hydride of Haxyl, see Hydride of Haxyl, see Horyl-hydride.  Garburetted Hydride.  Hydride of Methyl, see Methyl-hydride.  Carburetted Hydrogen.  Hydride of Octyl, see Octyl-hydride.		:	÷	:	•
Hydride of Phenyl, see Benzole.					
Hydride of Propyl, see Propyl-hydride.					
Hydrocarbons	:	:	:	:	The different compounds of carbon and hydrogen, gaseous or volatile and condensable contained in illuminating gas and in coaltar, constituting the light-giving material of the former and the rich and valuable produces of the latter.

Name of Product.	Formula or Symbol.	Reaction	Specific Gravity Water = 1.	Boiling Point. Degrees Fahrenheit.	Remarks.
Hydrogen	HCN	Acid	.0691 (air = 1)	::	Obtained from coal tar.  The lightest known substance in nature. 100 vols. water absorb 1.98. One of the chief constituents of coal gas, in which it exists to the extent of 12 to 50 per cent. Pure
Eydrosulphosyanic Acid. Hydrosulphuric Acid, see Sulphuretted Hydrogen.	B (0N) H	Acid	i	ı	hydrogen gres scarcely any light during combustion, but when solid substances are suspended in the flame, which has the high temperature of 5898° Fahr., considerable light is emitted.  Obtained from coal tar.
Klumine, see Acetylene . Leucolene, or Quinclene .	Co H, N	Alkaline	:	456°	Obtained from coal tar.
Lepidene.	C10 He N	Alkaline	1.078	610	Do. do. obtained from the
Light Carburetted Hydro- ken, also named Marsh Gas, Pit Gas, Fire Damp,	7H 0	Neutral	·56 (air = 1)	:	heavy oil.  A constituent of coal gas to the extent of 30 to 60 per cent. 4 vol. C vapour, 2 vols. H. Not condensed by cold, and not easily de-
and Hydride of Methyl. Light Oil.	:	i	:	;	composed by heat. 100 vols. water absorb The oil that follows the crude naphtha, and precedes the crossote or dead oil in the destructive distillation of coal tar. It is
Liquid Ammonia	C₁ ∺,	Alkaline Alkaline	.980	306.	nsually reclistified along with the crude naphths for obtaining benzole. The two are also used for making black varnish, or for burning in the common naphtha lamp. A solution of ammonia gas in water. A constituent of coal tar, contained in the light oil.

Name of Product.	Formula or Symbol.	Beaction.	Specific Gravity Water = 1.	Boiling Point. Degrees Fabrenheit.	Remarks.
Mesitylene	C <sub>9</sub> H <sub>13</sub>	:	:	825°	A constituent of coal tar, obtained from the
Methyl	Cs Hs	Neutral	1.04  (air = 1)	:	light oil. 1 vol. C, 8 vols. H. 100 vols. water absorb
Methylamene	C H, N C H,	Alkaline Neutral	.484 (air = 1)	::	alcohol radical series of hydrocarbons.  Alcohol radical series of hydrocarbons.  A constituent of coal gas of the oleflant gas series of hydrocarbons.  Series of hydrocarbons. \$\frac{1}{2}\$ vol. \$\frac{1}{2}\$ vol. \$\frac{1}{2}\$
Methyl-hydride, see Light Carburetted Hydrogen. Mirbane, Essence of, see Nitro-bensole. Muriate of Ammonia, or (when sublimated) Sal Ammoniae.	NH8 HCL or NH4 CL	Alkaline	:	:	The important salt which is produced from ammoniacal liquor when the latter is saturated with muriatic or hydrocholoric soid.  Nearly all the medicinal preparations of ammonia are obtained from this salt.
Naphtha, see Crude		_			also in fixing the colours in woollen.
Naphtha. Naphthalene Naphthalene Vapour	С <sub>10</sub> Н <sub>8</sub>	Neutral Neutral	1·153 4·42 (air = 1)	4140	5 vols. C, 4 vols. H. A constituent of cosl tar. 5 vols. C, 4 vols. H. Not soluble in water, but by naphtha and cosl tar. Chickly de-
Naphthylamene	C10 H9 N	Neutral	:	:	posited by cold.  A compound produced from naphthalene.
Nitrio Aoid	HNO	Aoid	1.61	Not constant.	A small proportion of this soid is formed when nitrogen is burnt with coal gas.
Nitro-bensol, Nitrobensene, or Essence of Mirbane.	Ce Es NOs	Neutral	:	:	The substance produced by the action of fuming nitric acid on benzole naphths, and which is used for the manufacture of aniline colours. It is also used as an odour resembling oil of bitter almonds, to perfume some and flavour confectionery.

Name of Product.	Formula or Symbol,	Reaction.	Specific Gravity Water = 1.	Bolling Point. Degrees Fahrenheit.	Remarks.
:	4	:	.9713 (arr = 1)	:	100 volt. water absorb 1'48 vol. The presence of nitrogen in coal gas is sometimes due to irregularity in the working of the exhauster, by which a vacuum is created, and air drawn in through the fissures of the reforts. The nitrogen contained in the coal, and which is eliminated by distillation, is evolved in combination with hydrogen as ammonia. Its effect is to injure the illuminating power.
Octyl	Ce His Ce His Ce His	Neutral Neutral Neutral	-1 i i	246°	A constituent of coal gas.  Do. do. contained in the light oil.
Enanthylene	C, H14	Neutral		210°	Obtained from coal tar, from the light oil.
Olefiant Gas, Ethylene, or Elayl.	C2 H2	Neutral	.968 (air = 1)	•	I vol. C, 2 vols. H; 100 vols. water absorb 16. Condensable by cold and great pressure. Exists in ocal gas in proportions varying from 8 to 27 per cent., and contributes greatly to its illuminating power. It contains twice as much carbon as light carburetted hydrogen. Test, brown or fuming
	•	:	1·105 (air = 1)		suppurious soid. 299 vols. absorbed by 100 vols. water. The presence of oxygen in oosl gas is due (like nitrogen) to the drawing in of air through the retorts and apparatus by too rapid working of the exhauster, and also to the opening of the retorts and purifiers for charging and discharging. 2 per cent. of air injures the illuminating power of the gas to the extent of 10 per cent.; 7 per cent. of air diminishes the light one-half, whilst about 25 per cent. of air practically de-

Name of Product.	Formula or Symbol.	Reaction.	Specific Gravity Water = 1.	Boiling Point. Degrees Fahrenheit.	Remarks,
Paraffin	C <sub>17</sub> H <sub>58</sub> to C <sub>57</sub> H <sub>56</sub>	Neutral	0.28.	:	A colourless, solid, orystalline, fatty substance, chiefly obtained from the tar from Boshead cannel. It is manufactured into candles,
					giving a brilliant white light; and oil of high lubricating properties is made from it. Paraffin oil will only burn in the presence of a wick, and is therefore perfectly safe.
Farankphinalene, see Anthracene. Parvolene, see Cumidene. Pentahirolene	Cus Hus N	:	:	:	constituent of coal tar, obtained from the
Pentylene	Ce Hie	:	:	<b>8</b>	neavy ou. A constituent of coal tar, contained in the light oil.
Phlorylic Acid, or Phlorol Picolene . Pit Gas, see Light Carbu- retted Hydrogen.	08 His O Ce H <sub>1</sub> N	Acid Alkaline	:66	<b>434</b> ° <b>87</b> 8°	Do. do. contained in the light oil.
Pittacal	:	:	:	:	Found in the heaviest portions of the coal tar
Pitch	:	:	•	:	The residue remaining of the distillation of coal tar, of which it constitutes about 68 one can be used to be
Propyl	S H	Neutral	2.97 (air = 1)	:	asphalting. stituent of coal ga
Propylene, or Titylene .	C <sub>b</sub> H <sub>c</sub>	Neutral	1-466 (air = 1)	:	H. Not soluble in water. A constituent both of coal gas and coal tar. Condensed by cold and pressure. Of the
Propy-bydride	C, H	Neutral	Neutral   1.522 (air = 1)	:	oleitant gas series of hydrocarbons. 14 vol. C, 3 vols. H. A constituent of coal gas, of the marsh gas gettes of hydrocarbons. 13 vols. C, 4 vols. H.

Name of Product.	Formula or Symbol.	Reaction.	Specific Gravity Water = 1.	Boiling Point. Degrees Fahrenheit.	Remarks,
Pyrene	Oto Hio	Neutral	:	:	A constituent of coal tar. White crystalline body.
Pyridene, see Pyrrhidene. Pyrrhidene	C, H, N	Alkaline	996.	243°	A constituent of coal tar, contained in the light oil.
Pyrrol	C, H, N	Alkaline	1.077	2710	A constituent of coal tar, contained in the light oil.
Quinolene, see Leucolene. Rosolic Acid. Rubidene. Sal Ammonisc see Muri.	Cis His Os Cii Hir N	Aoid Alkaline	::	446°	Do. do. Do. do.
ste of Ammonia. Spent Lime, see also Sul- phide of Calcium.	:	:	:	3	The foul lime of the purifiers. Used as a manure or top dressing for land.
Spent Oxide of Iron	:	:	:	:	The hydrated peroxide of iron, employed in abstracting the sulphuretted hydrogen from
Sulphate of Ammonia (N H4) sSO4	OS5 (N H4)	:	:	:	up gas, naving become charged with free sulphur to the extent of 40 to 75 per cent, by a succession of foulings and revivification, is used by the manufacturing chemists for making sulphuric soid.  The valuable salt produced by the neutralization of the ammonia from ammoniacal liquor with sulphuric acid. Largely used as a manue, and, by the addition of a solu-
Sulphide of Calcium, or Spent Lime.	:	:	:	:	tion of sulphate of alumina, in the manu- facture of ammonia alum.  The "fonted" lime of the purifiers, and which is efficacious in absorbing from the gas the bisulphate of earbon impurity, and the sul- phr compounds other than sulphrested
Sulphide of Carbon, see Bisulphide of Carbon					hydrogen.

Name of Product.	Formula or Symbol.	Reaction.	Specific Gravity Water = 1.	Bolling Point. Degrees Fahrenheit.	Remarks.
Sulphocyanogen	SCN	:	:	:	A constituent of raw gas.
Sulpho-hydrocarbons	:	:	:	:	Sulphur impurities existing in coal gas.
Sulphur	Ø	:	:	570%	In the best gas-producing coals the amount of sulphur present rarely exceeds 1½ per cent, generally it is much less. In the process of distillation about one-half the contained sulphur remains in the residual coke, whilet the other half is volatilized, and, combining with H and C, constitutes impurities requiring removal.
Sulphuret of Carbon, see Blaulphide of Carbon. Sulphuretted Hydrogen .	H, S	Aoid .	1·1747 (air = 1)	:	The chief impurity in raw or crude coal gas. It is entirely removed by the use of lime or exide of iron. It is an inflammable gas, and generates sulphurous acid in burning. I voi. of water at 60° absorbs 3°28 vols. of the gas. Test, sociate of lead or nitrate of silver in
<b>B</b> ulphurio Acid	Hs 804	Aoid	1.845	838°	solution.  This, which is the most important and useful of all the acids, is largely manufactured time the sulphur contained in the spent oxide of iron, after having been used in the purification of coal gas from sulphuretted
Sulphurous Acid (or Sulphur Dioxide).	SO	Aoid	2·247 (air = 1)	:	hydrogen. This gas is produced when sulphur and its compounds are burnt. Hence, illuminating gas containing sulphur yields it during com-
					ousagon. In equatity given out, nowever, even with the most impure gas (say, with 40 grains sulphur in the 100 feet), is so inappreciable as to be perfectly innocuous in its effects, especially where the smallest attention is naid to ventilation.

Remarks.	The well-known complex, viscid liquid, produced in the destructive distillation of coal, and from which a great variety of valuable products is obtained. It consists almost entirely of hydrocarbon compounds, with a varying proportion of solid carbon. Tar, on distillation, yields on an verage—  2.4 per cent, ammoniacal liquor  1.6  1.9  2.9  3.9  6.0  1.0  1.0  1.0  1.0  1.0  1.0  1.0	A constituent of coal tar.  A constituent both of coal gas and tar. Of the benzele series of hydrocarbons. 3½ vols. C, 4 vols. H. Not soluble in water.	A constituent of coal tar, obtained from the	neavy ou. A constituent of coal tax. Produced as aqueous vapour, in more or less	It is also one of the products of the combus- tion of coal gas, from the union of the hydro- gen of the gas with the oxygen of the sir. The base of xylidene, obtained from the light oil. Used in the preparation of searlet dyes.	A constituent both of coal gas and tax. Of the benzole series of hydrocarbons. 4 vols. C, 5 vols. H. Not soluble in water.
Bolling Point. Degrees Fahrenheit.	:	388° 232°	:	484° 212°	282°	259°
Specific Gravity Water = 1.	Ordinary Coal Tar. 1-120 to 1-150 Cannel Coal Tar -980 to 1-060	Liquid .870 Gas 8 · 179 (air = 1)	:	1.000	:	Liquid :867 Gas 8:662 (air = 1)
Reaction.	:	Alkaline Neutral	:	Alkaline Neutral	:	Neutral
Formula or Symbol.	:	C, H. N C, H.	C16 Ha1 N	C <sub>19</sub> H <sub>19</sub> N H <sub>2</sub> O	Cs H10	Ce Hio
Name of Product.	Tar	oyangen. Toluidane Toluole	Tritylene, see Propylene.	Viridene	Zylene	Kylole

TARLE	OF	ELEMENTARY	SHESTANCES
INDUE	OI.	ELEMENTAKI	DUDGIANCES.

Names of Elements.	Symbols.	Atomic Weights.	Names of Elements.	Symbols.	Atomic Weights
Aluminium	Al	27.04	Mercury (Hydrarg.).	Hg	199.8
Argon	· A	20	Molybdenum	Mo	95.9
Antimony (Stibium)	Sb	119.6	Nickel	Ni	58.6
Arsenio	As	74.9	Niobium	Nb	98.7
Barium	Ba	136 · 86		N	14.01
Beryllium	Be	9.08	Osmium	Os	195
Bismuth	Bi	207.5	Oxygen	+ O	15.96
Boron	В	10.9	Palladinm	Pd	106.2
Bromine	Br	79.76	Phosphorus	P	30.96
Cadmium	Cd	111.7	Platinum	; Pt	194.3
Cæsium	Cs	132.7	Potassium (Kalium).	K	39.08
Calcium	Ca	39.91	Rhodium	Rh	104 · 1
Carbon	. C	11.97	Rubidium	Rb	85.2
Cerium	' Ce	141.2	Ruthenium	Ru	103.5
Chlorine	Ci	35.37	Samarium	Sm	148.9
Chromium	Cr	52.45	Selenium	Se	78.87
Cobalt	Co	58.6	Scandium	Sc	43.97
Copper (Cuprum)	Cu	63 · 18		Si	28.3
Didymium	D	145	Silver (Argentum) .	Ag	107.66
Erbium	E	166	Sodium (Natrium) .	Na	23
Fluorine	F	19.06		Sr	87.3
Gallium	Gu	69.6	Sulphur	S	81.98
Germanium	Ge	71.9		Ta	182
Gold (Aurum)	Au	196.8	Tellurium	Te	126.3
Helium	He	2	Thallium	Tì	203.7
Hydrogen	H	ī !	Thorium	Th	231 . 96
Indium	In	118.4		Sn	117.3
Iodine	I	126.54		Ti	48
Iridium	Ir	192.5	Tungsten (Wolfram)	w	183.6
Iron (Ferrum)	Fe	55.88	Uranium	Ü	239.8
Lanthanum	La	138.5	Vanadium	Ť	51.1
Lead (Plumbum)	Pb	208 - 89	Ytterbium	Υb	171.7
Lithium	Li	7.01	Yttrium	Ŷ	89.6
Magnesium	Mg	23.94	Zino	Źn	64.8
Manganese(Manganium		54.8	Zirconium	Zr	90.48

# CHEMICAL AND OTHER MEMORANDA.

The compounds of the non-metallic elements with the metals and with each other have names ending in "ide" or "uret"; as Fe S, sulphide or sulphuret of iron.

When two or more atoms or equivalents of the non-metallic elements enter into combination, the number of atoms or equivalents is expressed by prefixes.

Mon. . . means 1 atom, as N<sub>2</sub> O, nitrogen mon-oxide.

Di, bin, or bi means 2 atoms, as N<sub>2</sub> O<sub>3</sub>, nitrogen di-oxide, or bin-oxide of nitrogen: CS<sub>3</sub>, bi-sulphide or di-sulphide of carbon.

Tri or ter . means 8 atoms, as N<sub>2</sub>O<sub>3</sub>, nitrogen tri-oxide; Sb<sub>2</sub>S<sub>3</sub>, ter-sulphide of antimony.

Tetr. . . means 4 atoms, as N<sub>2</sub> O<sub>4</sub>, nitrogen tetr-oxide.

Pent or penta means 5 atoms, as N<sub>2</sub> O<sub>3</sub>, nitrogen pent-oxide; PCl<sub>3</sub>, penta-chloride of phosphorus.

Sesqui . . means 1½ atoms (=2 to 3), as Fe<sub>2</sub>O<sub>3</sub>, sesqui-oxide of iron. Proto or prot means first, as Fe O, prot-oxide of iron.

Sub . . . means under, as Cu. O, sub-oxide of copper.

Per . . . means the highest, as H Cl O4, per-chloric acid.

The terminations "ic" and "ous" are used for acids; the former representing a higher state of oxidation than the latter.

When a substance forms more than two acid compounds, the prefixes "hypo," under, and "hyper" above, are used.

The smaller number, as H<sub>2</sub>, placed to the right of, and slightly below a symbol is called the exponent, and indicates the number of times that the combining weight of the substance has to be taken. When the symbol is without a number—thus, H—the number one is understood. The small numbers modify only the symbol immediately preceding, but larger numbers prefixed to the symbol modify all that follow as far as the next comma or + sign: thus 2H<sub>2</sub> SO<sub>4</sub> signifies that four of hydrogen, two of sulphur, and eight of oxygen, or, more correctly, that two of sulphuric acid (H<sub>2</sub> SO<sub>4</sub> being the formula for sulphuric acid) are to be taken.

A base is a compound which will chemically combine with an acid.

A salt is a compound of an acid and a base.

When water is in combination with acids or bases, they are said to be hydrated.

Alkalies neutralize acids, forming salts.

Alkalies turn vegetable reds to blue, and yellows to brown.

Acids turn vegetable blues to red, and browns to yellow.

A simple or elementary substance is a body that cannot be resolved or separated into any simpler substances—as oxygen, carbon, iron.

A compound substance is one consisting of two or more constituents—as water, carbonic acid gas, olefant gas.

The equivalent number or atomic or combining weight expresses the relation that subsists between the different proportions by weight in which substances unite chemically with each other.

The equivalent or combining weight of a compound is the sum of the combining weight of its constituents.

Specific gravity expresses the difference that subsists between the weights of equal volumes of bodies. Gases are usually compared with air as 1.000, liquids and solids with water as 1.000.

So far as chemists have been able to discover, there are about 70 elementary or simple substances.

No compound body contains all the elementary substances. Most compounds are composed of two, three, or four elements.

#### LIST OF SUBSTANCES

Simple and Compound, frequently mentioned in connection with the Manufacture and Purification of Coal Gas and the Residual Products resulting therefrom.

Nar	ne of	Subst	ance.			Symbol.
Acetylene					•	$C_2H_2$
Ammonia						NH <sub>8</sub>
Aniline .						$C_6H_7N$
Aqueous va	pour					H <sub>2</sub> O
Benzole .						$C_aH_a$
Bisulphide						CŠ <sub>2</sub>
Bisulphide	of iro	n .				Fe S <sub>2</sub>
Butylene						$C_4$ $H_8$
Carbon .						C
Carbolic ac						$C_6H_6O$
Carbonate	of am	moni	ia.			$(NH_4)_2 CO_3$
Carbonate						Ca CO.
Carbonic a						CO <sub>2</sub>
Carbonic o	xide .					co
Cyanogen	•					$C_2 N_2$
Hydrogen						H
Hydrochlor						HCl
Light carb	urette	d hy	drog	en		CH.
Muriate of						NH <sub>8</sub> HCl, or NH <sub>4</sub> Cl
Naphthaler	ae .					C <sub>10</sub> H <sub>8</sub>
Nitrogen						N
Nitric acid						HNO,
						U

~ .							~ **
Olefiant	gas	•	•	•	•	•	$C_2H_4$
Oxygen	•	•		•		•	0
Oxide of	calciv	ım (	cau	stic	lim	e)	Ca O
Oxide o						ic į	K <sub>2</sub> O
Oxide of	sodiu	m (d	aus	tic	sod	a)	Na <sub>2</sub> O
Peroxide	of ir	on					Fe <sub>2</sub> O <sub>8</sub>
Protoxid	le of i	ron					Fe O
Protosul	phide	of i	ron		•		Fe S
Protochl	oride	of n	nan	gan	ese		Mn Cl <sub>2</sub>
Propyler	ne .	•		•			CaH
Sesquist	ılphid	e of	iro	n			Fe, S,
Sulphur							S
Sulphate	e of a	nmo	onia				$(NH_4)_2 SO_4$
Sulphide	e of ce	lciu	m				Ca S
Sulphur							H <sub>2</sub> S
Sulphur							H <sub>8</sub> SO <sub>4</sub>
Sulphur							SO,
Water .							H, O
Weldon							CaO <sub>2</sub> , MNO <sub>2</sub>

To ascertain the proportion, by weight, of the different substances in a compound, multiply the atomic weight of each substance by the exponent.

For example: Take olefiant gas, C<sub>2</sub> H<sub>4</sub>, which, as its formula indicates, consists, by weight, of two atoms of carbon combined with four atoms of hydrogen—

Atomio	Weight.		Exponent.		Proportion by Weight.			
$\mathbf{C}$	12	×	2	=	24	or	85.715	per cent.
$\mathbf{H}$	1	×	4	=	4	or	14.285	- ,,

So that 24 grains, or 24 ounces, or 24 pounds of carbon, combine with 4 grains, or 4 ounces, or 4 pounds of hydrogen to form 28 grains, or 28 ounces, or 28 pounds, and so on, of olefant gas.

Spirits of hartshorn .

# COMMON NAMES OF CERTAIN CHEMICAL SUBSTANCES.

Nitric acid. Aqua fortis . A mixture or nitric and hydrochloric Aqua regia . acids, so called from its property of dissolving gold. Sulphate of copper. Bluestone, or blue vitriol Oxide of iron. Bog ore . Calomel . Chloride of mercury. Chloroform . Chloride of formyle. Carbon dioxide. Choke-damp. Common salt Chloride of sodium. Copperas, or green vitriol . Sulphate of iron. Corrosive sublimate. Bichloride of mercury. Sulphate of alumina and potash. Dry alum Sulphate of magnesia. Epsom salts. Ethiops mineral Black sulphate of mercury. Light carburetted hydrogen. Fire-damp Sulphide of lead. Galena . Glauber's salts . Sulphate of soda. Gonlard water . Basic acetate of lead. Iron pyrites. Bisulphide of iron. Jeweller's putty. Oxide of tin. King's yellow Sulphide of arsenic. Laughing gas Protoxite of nitrogen. Lime. . . Oxide of calcium. Lunar caustic Nitrate of silver. Mosaic gold . Bisulphide of tin. Muriate of lime . Chloride of calcium. Nitre, or saltpetre Nitrate of potash. Oil of vitriol . Sulphuric acid. Oxide of potassium. Potash Realgar Sulphide of arsenic. Red lead . Oxide of lead. Rust of iron . Oxide of iron. Sal ammoniac Muriate of ammonia. Soda . . . Oxide of sodium.

Ammonia.

#### CHEMICAL SUBSTANCES—Continued.

Hydrochloric or muriatic acid. Spirit of salt. Stucco, or plaster of Paris . Sulphate of lime. Sugar of lead. . . Acetate of lead. . Crude borax. Tincal Verdigris . . . Basic acetate of copper. Vermilion. . . . Sulphide of mercury. Volatile alkali . Ammonia. Wad . . . Black oxide of manganese. Water Oxide of hydrogen.

White vitriol. .

#### TABLE OF VARIOUS GASES.

Sulphate of zinc.

Their Specific Gravity, Weight, and Solubility in Water.

60° Fahr. 80 in. Barometer.

Light carburetted hydrogen	Name.	Specific Gravity. Air equal 1.000	Cubic Foot in	of a Cubic	Number of Cubic Ft. equal to 1 lb.	Solubility. 100 Vols. of Water absorb.
Oxygen         1:1056         '08479952         598·59         11:79         2:99Vote           Sulphuretted hydrogen         1:1747         '09009949         630·69         11:09         323·26         "Nitrous oxide         1:527         '1171209         819·84         8:53         77·78         "Carbonic acid         1:529         '1172743         820·92         8:52         100·20         "Sulphurous acid         2:247         '1723449         1206·41         5:80         4276·60         "Chlorine         2:470         '189449         1326·14         5:27         236·80         "	Light carburetted hydrogen . Ammonia		· 0428753 · 045258 · 0741689 · 0742456 · 07449871 · 0767	300·12 316·77 519·18 519·71 521·49 536·90	23·32 22·09 18·48 18·46 18·42 13·03	72,720 · ,, 2 · 43 ,, 16 · 15 ,, 1 · 48 ,,
	Oxygen Sulphuretted hydrogen Nitrous oxide Carbonic acid Sulphurous acid	1·1056 1·1747 1·527 1·529 2·247	·08479952 ·09009949 ·1171209 ·1172748 ·1723449	593·59 680·69 819·84 820·92 1206·41	11·79 11·09 8·53 8·52 5·80	2·99Vols 828·26 ,, 77·78 ,, 100·20 ,, 4276·60 ,,

To reduce a volume of gas of any specific gravity to pounds avoirdupois, multiply the volume by the sp. gr. and by '0767. Example.—Required the weight of 1500 cubic feet of gas whose specific gravity is .520.

$$1500 \times .520 \times .0767 = 59.826 \text{ lbs.}$$

To find the weight in pounds avoirdupois of a cubic foot of air at different temperatures, and under different pressures.

$$W = \frac{1.8258 \times B}{459 + T}$$

Example.—Required the weight of a cubic foot of air, the barometer being at 29.5 inches, and the temperature 84° Fahr.

$$\frac{1.8258 \times 29.5}{459 + 84} = .072 \, \text{lb.}$$

Luting for Experiments in Chemistry.—For temporarily securing the joints of chemical vessels, glass stoppers, &c., use equal parts by weight of linseed meal and whiting made into a stiff paste with water. The two substances should be well triturated in a mortar, and the water added till of the proper consistency.

Pieces of vulcanized india-rubber tubing are very suitable for joining the ends of glass and earthenware tubes. The india-rubber is slipped over the ends, and secured with pack-thread.

India-rubber capsules for bottle necks, having a hole through them for the insertion of glass tubes are handier, and more likely to be gastight, than the ordinary corks.

# AVERAGE COMPOSITION OF LONDON GAS BY VOLUME.

(Dr. Letheby, 1866.)

							,	•							
Constituent	8.						•		amon G er Cent.						nnel Gas. Per Cent.
Hydrogen									46.0						27.7
Light carburette	d	hyd	iro	gen					39.5	•	•	•		•	50.0
Olefiant gas .				•				•	3.8		•	•	•	•	13.0
Carbonic oxide			•			•	•	•	7.5	•	•			•	6.8
Carbonic acid									0.7						0.1
Aqueous vapour				•					2.0			•			2.0
Nitrogen	•		٠.	•	•	•	•	•	0.2	٠	•	•	•	•	0.4
								•	100.0					-	100.0

## (Professor Vivian B. Lewes, 1894.)

Constituents.	c	alight an Coke Company. Per Cent.	đ	-	South Setropolit Company Per Cent.		C	mmercial ompany. Per Cent.
Hydrogen		53.36			52.22			52.96
Unsaturated hydrocarb	ons	8.58			3.47			8.24
Saturated hydrocarbons		82.69			34.76			84.20
Carbon monoxide		7.05			4.23			4.75
Carbon dioxide		0.61			0.60			0.75
Nitrogen		2.50			4.23			4.10
Oxygen	•	0.21			0.49	:		0.00
								<del></del>
		100.00			100.00			100.00

#### TABLE.

Tests made by Professor Vivian B. Lewes, showing the quantity of light obtained per cubic foot of 16-candle gas consumed, proving the advantage of the regenerative and incandescent lights, and the loss which attends the use of ordinary burners.

Bu	rner.										Candle Units.
Regenerativ	e and	In	can	de	ice:	at					7 to 10.00
Standard A	rgand										8.20
Ordinary A	rgand										2.90
Flat Flame	Ño. 7										2.44
Do.	No. 6										2.15
Do.	No. 5										1.87
Do.	No. 4										1.74
Do.	No. 8										1.68
Do.	No. 2										1.22
Do.	No. 1										0.85
Do.	No. 0										0.59

## TABLE,

Indicating the Comparative Salubrity of the Several Illuminating Materials.

The flame of coal gas, and the flames of several combustible bodies that gave an amount of light equal to it, were burned separately in given quantities of atmospheric air, and the times were noted at which the flames were extinguished by the contamination of the air. The following were the results:—

Colza oil .						was extinguished	in	71	minutes
Olive oil .						)) II		72	**
Russian tallow	•			•		,, ,,		75	,,
Sperm oil						,,		76	,,
Stearic acid						•1 11		77	,,
Wax candles						,, ,,		79	17
Spermaceti car	ndl	86				" "		83	,,
Coal gas .						,, ,,		98	,,
Cannel Gas (28	ca	nd	les)		•	,, ,,	1	52	"

From which it appears that the atmosphere of a confined room lighted

by cannel gas will support life twice as long as the atmosphere of the same room lighted equally by tallow candles.

#### TABLE.

## RELATIVE VALUES OF ILLUMINATING AGENTS

In respect of their Heating and Vitiating Effects on the Atmosphere, when Burning so as to give the Light of 12 Standard Sperm Candles. (Dr. Letheby.)

	Vat	ounds of er Heat lo Fahr	ed			C	Oxygen onsume abic Fee				cid	rbonic Produc bic Fee			(0	Air Vitiated ubic Feet).
Cannel gas .		1950				`.	8.30	•			٠.	2.01	•		٠.	50.2
Common gas .		2786					5.45					8.21				80.2
Sperm oil .		2335	-	-			4.75					3.33		-		88.3
Benzole		2326	Ĭ				4.46					3.54			-	88.5
Paraffin	-	3619		·	-	•	6.81	-		-	-	4.50		-		112.5
Camphene .	•	3251	•	•	•	•	6.65	Ť	•	•	•	4.77	Ţ	Ī	Ī	119.2
Sperm candles	•	8517	•	•	٠	•	7.57	•	•	•	•	5.27	•	•	•	181 · 7
Wax candles.	•	3831	•	•	•	•	8.41	•	•	•	•	5.90	•	•	•	149.5
Stearic candles	•	3747	•	•	•	•	8.82	•	•	•	•	6.25	•	•	•	156.2
Tallow candles		5054	•	•	•	•	12.06	:	•	•	:	8.73	:	•	:	218.8

#### TABLE.

Calorific Power of Various Photogenic Compounds. (F. J. Evans.)

Name of Gas, &c.		ubic Fee to ne Pound	•	Con	ds of Vaised by the sumpt	l° ion	of		Co	unds of Water raised 1° by the nsumption of lb. of Gas.
Hydrogen		180.0			300					54,000
Newcastle coal gas, sp. gr. 410		82.4			650					21,060
Cannel gas, sp. gr. 500		26.5			760					20,140
Oil gas, sp. gr. 825	•	16.69	•	•	1200		•	•	•	20,028
Sperm candles, 6 to the lb.								1	lb	of candles. 17,587
Sperm oil, burnt in a lamp									1	lb. of oil. 16,490

TABLE.

Combustion, Temperature, Explosive Power, and Mechanical Power of Gases. (LETHEBY).

Closed Vestal.  With Ox. With Air  Deg. 19,086 7,852 19,384 7,300 21,384 7,300 21,387 7,177 21,387 7,177 21,387 7,177 21,387 7,177 21,387 7,177 21,387 7,177 21,089 16,187 17,645 6,167 18,101 7,645 6,167 19,046 7,189 11,238 6,635 11,238 6,635 20,968 6,947 11,238 6,635			Open Flame. With Oz. With Air. Deg. Deg. 14,180 5,744 14,180 5,782 16,582 5,289 16,582 5,289 17,146 5,142 17,146 5,142 17,146 5,142 17,146 6,142 17,146 6,142 17,146 6,142 17,146 6,143 18,888 4,388	Ox. Used. With Ox. With Air.  Lbe. Deg. Deg. 7,754 14,130 6,225 6,225 6,220 16,522 6,230 16,522 6,230 16,522 6,339 6,340 17,146 6,142 7,14	Per 1b. Open Flame.  Oc. Os. Used. With Or. With Air.  Libe. Deg. Deg. Deg. C. 7764 6.236 14,180 6.236 16,535 6.230 16,535 6.230 16,532 6.230 16,532 6.230 16,532 6.230 16,532 6.230 16,532 7,769 17,146 6.340 7,569 12,719 6.340 7,569 12,719 6.359 6.340 6.341 6	Per lb.   Per lb.   Cable Foot   Car. Used.   With Ox. With Air.   Lbs.   Lbs.   Lbs.   Lbs.   Lbs.   Lbs.   Lbs.   Lbs.   Caple For lb.   Lbs.   L	Per lb.   Per lb.   Gubic Foot Ox. Used.   With Ox. With Air.
4 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2			With Ox. With Air.  Dec. Dec. Dec. 14,510 14,180 16,525 16,525 16,525 16,525 17,146 17,146 17,146 18,588 18,488 18,488 18,488 18,488 18,488 18,488	Lbs. Deg. With Ox. With Air. Lbs. Deg. T.754 14,130 5,224 6,525 6,237 6,528 6,230 16,522 6,239 6,329 6,329 6,315 17,146 6,142 7,746 17,146 6,142 7,746 17,146 6,142 7,746 17,146 6,142 7,746 17,146 6,142 7,746 17,146 6,142 7,746 17,146 6,142 7,746 17,146 6,142 7,746 17,146 6,142 7,746 17,146 6,142 7,746 17,146 6,142 7,746 17,146 6,142 7,746 6,142 7,746 6,142 7,746 6,142 7,746 6,142 7,746 6,142 7,746 6,142 7,746 6,142 7,746 6,142 7,746 6,142 7,746 7,746 6,142 7,746 6,142 7,746 7	Bubetanoe.  Lbs. Lbs. Lbs. Lbs. Lbs. Lbs. Lbs. Lb	1bs. Lbs. Lbs. Deg. With Ox. With Air. Lbs. Lbs. Lbs. Deg. Deg. By 7.754 14,510 5.21,824 1.586 6.225 16,525 6.235 18,187 8,188 6.225 16,525 6.235 18,187 8,188 6.225 16,525 6.235 18,197 1,351 6.514 17,146 6,142 18,197 8,860 6.514 17,146 6,142 18,197 8,860 6.514 18,197 8,860 6.514 18,197 1,351 18,197 1,351 18,197 1,351 18,197 1,351 18,197 1,351 18,197 1,351 18,197 1,351 18,197 1,351 18,197 1,351 18,197 1,351 18,197 1,351 18,197 1,351 18,197 1,351 18,197 1,351 18,197 1,351 18,198 18,351 18,	Cubic Lbs. Lbs. Lbs. Lbs. Deg. With Ox. With Air. Feet. 467 62,080 389 7,754 14,510 6,744 878 21,327 2,876 6,220 16,525 6,232 878 21,327 2,876 6,220 16,525 6,232 878 21,327 2,876 6,220 16,525 6,232 878 21,327 2,876 6,220 16,525 6,232 878 21,327 2,876 6,220 16,522 6,232 878 21,327 3,168 6,220 16,522 6,232 899 18,197 1,251 6,914 17,146 6,142 871 4,325 8,926 6,120 7,544 6,122 8,926 12,714 6,132 6,326 6,326 6,132 6,326 6,132 6,326 6,132 6,326 6
Q 0004-144400CF-004-1-00		Dec. 5,144 5,144 5,142 5,142 5,142 5,142 6,142 6,088 6,088 6,088	Dec. 14,510 5,744 14,510 6,744 16,625 6,239 17,146 6,142 17,146 6,142 16,529 12,719 6,358 15,368 15,368 6,088 18,488 6,088	Libs. Deg. Deg. 7,754 14,510 5,744 6,878 14,180 4,762 6,230 16,523 6,239 6,230 16,523 6,329 6,394 17,146 5,142 7,669 12,719 6,342 7,669 12,719 6,368 4,388 6,142 13,488 6,098 6,098 6,142 13,488 6,098 6,098 6,142 13,488 6,098	Lbb. Lbb. Deg. Deg. 926 6,876 14,510 5,744 996 6,878 14,130 4,762 1,685 6,235 16,525 6,237 1,387 6,230 16,522 6,238 1,381 6,914 17,146 5,142 8,860 7,569 1,719 6,585 1,123 4,846 16,230 4,814 6,143 8,288 925 6,914 13,380 6,916 14,380 6,228 6,098 6,916 14,380 6,228	Lbs.         Lbs.         Lbs.         Deg.         Deg.           62,080         389         7,754         14,510         5,744           28,513         986         5,878         14,180         4,768           21,844         1,566         6,225         16,583         6,237           21,827         3,186         6,230         16,522         5,389           21,827         3,168         6,230         16,522         5,389           18,197         1,381         5,914         17,146         5,142           4,825         380         7,569         12,719         5,589           6,130         1,289         4,845         15,289         4,814           7,444         671         5271         18,688         5,988           6,712         18,287         5,142         18,488         5,098	Cubic         Libe.         Libe.         Libe.         Deg.         Deg.           467         69,080         329         7,754         14,510         5,744           826         23,513         996         6,878         14,130         4,762           878         21,344         1,586         6,225         16,525         6,337           878         21,387         3,168         6,230         16,523         6,239           878         21,387         1,351         5,914         17,146         5,142           909         18,197         3,860         -5,915         17,146         5,142           890         1,8197         3,860         -5,915         17,146         5,142           890         1,8197         3,860         -5,915         17,146         5,142           890         6,130         1,239         4,845         15,280         4,814           689         6,130         1,239         4,846         15,280         4,814           680         7,744         6,771         13,688         4,814           671         5,771         13,688         4,888           671         5,771         13,688
Quyuna Quid on		447.74 47.74 47.74 47.74 47.77 47.88 47.88 47.88 47.88 47.88 47.88 47.88 47.88 47.88 47.88 47.88 47.88 47.88 47.88	14,510 5,744 14,180 4,782 16,535 5,237 16,523 5,239 17,146 5,142 17,146 5,142 17,146 5,142 12,719 5,358 16,368 4,388 18,488 5,088	6,978 14,510 5,744 6,925 14,925 14,925 16,525 6,237 16,525 6,237 6,239 16,523 6,239 6,349 17,146 6,142 7,646 17,146 6,142 7,646 16,271 18,688 4,888 6,142 18,289 18,719 6,288 6,271 18,688 6,028 6,142 18,289 6,028 6,142 18,289 6,028 6,142 18,289 6,028 6,142 18,289 6,028 6,142 18,289 6,028 6,142 18,289 6,028 6,142 18,289 6,028 6,142 18,289 6,028	929 7,754 14,510 5,744 1,586 6,225 16,536 5,239 2,376 6,220 16,523 5,239 1,361 6,914 17,146 5,142 3,860 7,591 12,719 5,838 1,239 4,845 15,230 4,814 650 6,916 12,719 5,838 826 7,591 13,719 5,838 827 7,838 4,845 16,230 4,814 660 6,916 14,320 6,228	62,080 328 7,754 14,510 5,744 21,513 4,782 21,513 1,565 6,225 16,565 6,217 21,327 21,827 14,180 4,782 21,827 21,827 21,827 15,186 6,220 16,522 5,239 18,197 1,351 6,914 17,146 5,142 18,197 8,800 7,569 12,719 5,569 14,22 4,325 6,142 12,299 4,645 16,280 4,314 7,444 671 6,271 18,689 4,386 6,712 926 6,142 18,498 5,028	467         69,080         329         7,754         14,610         5,744           826         23,613         996         6,878         14,180         4,783           878         21,324         1,686         6,225         16,536         5,231           878         21,327         2,876         6,226         16,523         5,239           878         21,327         2,876         6,220         16,522         5,239           878         21,327         1,461         6,230         16,522         5,239           899         18,197         1,461         6,914         17,146         6,142           871         4,825         380         7,669         12,719         6,866           689         6,120         1,239         4,845         15,280         4,814           680         7,444         6,713         9,968         4,814         6,098         4,814           680         7,744         6,713         9,968         4,814         6,098         4,814           681         7,744         6,713         9,568         4,814         6,098         4,814
ಪ್ರಿಸ್ತಿಸ್ತರ್_್ರಿಸ್ ಎಸ್ಎಸ್ ಎಸ್ ನಿಸ್ತ್ : : :		7,4,762 6,233 6,142 7,142 7,142 8,356 7,038 8,038 6,038 8,038	14,180 16,586 16,588 17,146 17,146 17,146 17,146 18,588 18,688	6,878 14,180 4,768 6,225 16,656 6,217 6,230 16,622 5,239 6,230 16,622 5,239 6,914 17,146 5,142 7,669 12,719 6,142 4,946 16,230 4,514 6,271 13,688 4,388 6,142 18,688 4,388 6,142 18,688 6,098	986 5 878 14,180 4,768 2,376 6,225 16,585 6,237 8,168 6,230 16,522 5,238 1,351 6,914 17,146 5,142 8,860 6,591 12,719 6,142 8,860 7,569 12,719 6,183 1,239 4,846 15,280 4,814 6,71 5,271 18,688 4,888 926 6,142 18,888 926 6,916 14,320 6,228	29,513 996 5,878 14,190 4,768 21,344 1,556 6,226 16,586 5,239 21,327 13,	826 25,513 996 5,878 14,130 4,782 878 21,344 1,565 6,225 16,535 5,237 878 21,327 2,376 6,220 16,522 5,239 878 13,137 1,251 6,5914 17,146 5,142 871 4,325 820 16,915 17,146 5,142 871 4,325 820 7,569 12,719 6,356 6,350 7,569 6,120 7,569 4,814 650 7,569 7,569 4,814 650 7,569 7,56
999900-000-000000-··		5,237 5,142 5,142 5,142 6,358 4,388 5,088 5,088	16,556 6,217 16,522 6,239 16,522 6,239 17,146 6,142 17,146 6,142 17,146 6,142 18,719 6,886 15,288 4,886 18,488 6,088	6,225 16,536 5,217 6,230 16,523 5,238 6,394 17,146 5,42 7,569 12,7146 5,142 7,569 12,719 5,858 4,846 12,29 4,814 5,271 13,688 4,884 5,274 13,689 5,098	1,666 6,225 16,526 5,217 2,376 6,226 16,528 5,238 1,251 5,914 17,146 5,142 8,860 5,915 17,146 5,142 8,860 7,569 17,719 6,5182 1,239 4,846 16,280 4,814 6,71 6,271 13,688 4,888 926 6,916 14,380 6,228	21,344 1,665 6,225 16,536 6,217 21,327 2,376 6,220 16,522 6,228 21,377 1,361 6,914 17,146 6,142 18,197 3,800 7,569 12,719 6,326 6,142 6,142 1,229 1,229 4,314 7,444 671 6,271 18,688 4,388 6,712 926 6,142 18,498 6,928	878 21,344 1,686 6,225 16,635 5,217 878 21,324 1,686 6,225 16,632 5,239 878 21,327 8,376 6,230 16,632 5,239 890 18,197 8,660 5,914 17,146 5,142 871 8,325 820 1,239 4,845 15,239 4,845 6,93 7,444 671 5,514 13,718 6,386 4,814 671 5,719 18,688 4,888 4,888 4,888
888554546456468		65,289 6,142 6,142 7,142 8,856 6,088 8,008 8,008	16,593 5,289 16,523 5,289 17,146 5,142 17,146 5,142 12,719 5,886 16,388 4,388 18,488 5,098	6,230 16,532 5,239 6,230 16,522 5,238 6,914 17,146 6,142 7,569 12,719 5,886 4,846 15,220 4,814 5,271 13,688 4,886 5,121 13,688 4,886 6,142 18,689 6,098	2,876 6,220 16,522 5,238 8,168 6,220 16,522 5,238 1,346 6,914 17,146 5,142 8,860 5,915 17,146 5,142 1,289 4,845 15,719 5,558 671 5,71 13,688 4,884 825 6,142 13,488 6,098 660 6,916 14,920 5,228	21,827 2,876 6,230 16,522 5,229 21,327 3,168 6,230 16,522 5,238 18,197 3,860 5,914 17,146 5,142 4,825 320 7,569 12,719 5,586 6,130 1,239 4,846 15,290 4,814 7,444 671 5,271 18,688 4,388 6,712 925 5,142 18,498 5,028	878         21,327         2,876         6,230         16,522         5,238           9678         21,327         8,168         6,230         16,622         5,238           909         18,197         1,351         6,914         17,146         5,142           909         18,197         3,860         6,916         17,146         5,142           871         4,925         390         7,669         12,719         5,358           689         6,130         1,239         4,845         15,280         4,814           689         7,444         6,90         7,444         6,90         4,814           6710         926         7,444         6,00         4,814           6710         926         7,444         6,00         4,00
8000-000-0000000 · ·		288 241,25 241,45 241,858 25,028 288 288 288	16,522 5,233 17,146 5,142 17,146 5,142 12,130 4,814 15,280 4,814 13,688 4,388 18,488 6,028	6,230 16,522 5,238 6,914 17,146 5,142 7,569 12,719 6,586 4,845 16,280 4,814 5,271 13,688 4,888 6,48 18,488 5,088	8,166 6,230 16,522 5,528 1,551 5,914 17,146 5,142 8,860 7,669 12,719 5,868 1,239 4,846 15,280 4,814 671 5,871 18,688 4,888 925 6,142 14,920 5,228	21.827         3,168         6,230         16,552         6,238           18,197         1,451         6,914         17,146         6,142           18,197         3,860         6,914         17,146         6,142           4,825         320         7,569         12,719         6,586           6,120         1,289         4,645         16,280         4,814           7,444         671         6,271         36,88         4,886           6,712         926         6,142         18,498         6,028	878         81,587         8,168         6,280         16,522         6,528         6,528           909         18,197         1,361         6,914         17,146         6,142           909         18,197         3,860         7,569         12,714         6,142           871         4,825         320         7,569         12,719         6,586           689         6,120         1,289         4,844         671         6,868         4,814           689         7,144         671         5,868         4,814         671         8,814           680         7,744         671         5,868         4,814         6,806         4,814
~ • • • • • • • • • • • • • • • • • • •		6,142 6,142 6,142 6,028 6,028	17,146 5,142 17,146 5,142 12,730 5,142 15,730 4,814 13,688 4,388 13,488 5,028	6,914 17,146 6,142 6,915 17,146 6,142 7,669 12,719 6,558 4,846 16,290 4,814 6,271 13,688 4,388 6,48 13,488 6,098 6,148 13,488 6,098	1,351 6,914 17,146 6,142 3,860 6,915 17,146 6,142 320 4,845 15,280 4,814 671 5,271 18,688 4,888 926 5,142 18,486 6,098 660 6,916 14,320 6,228	18,197 1,251 5,914 17,146 5,142 18,197 3,860 5,915 17,146 5,142 4,825 820 7,569 12,719 5,356 6,130 1,239 4,845 6,1280 4,814 671 5,271 13,688 4,388 6,712 925 5,142 18,488 5,028	909 18,197 1,251 5,914 17,146 5,442 909 18,197 8,860 - 5,915 17,146 5,142 871 4,825 820 7,569 12,719 6,886 689 6,120 1,239 4,845 15,280 4,814 680 7,444 671 5,888 4,888 485 6,719 925 6,142 18,688 4,888
5-500-00000 · ·		5,142 6,388 6,028 6,028	17,146 5,142 12,719 5,858 15,280 4,814 13,688 4,888 18,488 5,028	, 6,915 17,146 6,432 7,569 12,719 5,358 4,845 18,220 4,514 5,271 13,688 4,388 5,48 13,488 5,098 6,48 13,590	3,560	18,197 3,860 5,915 17,146 6,432 4,925 320 7,569 12,719 5,358 6,130 1,229 4,846 13,719 6,358 7,444 671 5,271 13,688 4,388 6,712 926 5,142 18,498 5,028	909 15,197 5,600 6,915 17,146 6,142 371 4,825 320 7,669 12,719 5,856 689 6,130 1,239 4,845 15,280 4,814 689 7,444 671 995 6,142 13,688 5,098
		2,4,4,7,7 8,6,0,8,14,8,0,0,0,0,0,0,0,0,0,0,0,0,0,0,0,0,0,0,	15,280 4,814 15,280 4,814 13,688 4,888 18,488 5,028	7,568 12,719 5,858 4,845 15,280 4,814 5,271 13,888 5,028 5,142 18,488 5,028	1,339 4,846 15,390 4,814 671 6,542 18,686 4,814 925 5,142 18,488 5,098 660 6,816 14,930 5,228	4,825 8320 7,569 12,719 6,586 6,149 12,729 4,814 7,444 671 6,271 18,688 4,888 6,712 926 6,712 18,488 6,028	57.1 4.825 820 7,569 12,719 6,586 6,180 1,271 6,980 4,814 6,180 1,289 4,645 15,280 4,814 6,180 6,180 6,180 6,119 6,921 13,688 4,988 6,180 6,119 6,925 6,149 18,486 6,098
်က်လေးက်လေက်ကြောက်လော်လုံင်		4,4,6 6,088 888 888 888 888	13,688 4,388 13,488 5,028	5,271 13,688 4,388 5,271 13,688 4,388 5,142 18,488 5,028	1,523 3,725 11,520 4,512 925 5,142 18,488 6,028 650 6,816 14,320 5,228	7,444 6711 5,271 13,688 4,988 6,712 925 5,142 18,498	630 7,444 671 5,271 18,688 4,388 485 6,719 925 5,149 18,488 6,098
		5,08 5,08 5,08 5,08 5,08	18,488 5,028	5,142 18,488 5,028	925 5,142 18,488 5,028 650 6,816 14,320 5,228	6,712 925 5,142 18,488 5,028	435 6.712 925 5.149 18.488 5.098
		6,228	4 000	200 7 000 14 000	650 6,816 14,320 5,228		Complete and the complete of t
4 C U U U U			14,320 5,228	0,010 12,000 0,000		21,060 650 6,816 14,320 5,228	618 21,060 650 6,816 14,820 5,228
୍ର ପ୍ରଥାନ୍ତି		5,121	14,826 5,121	6,503 14,826 5,121	760 6,508 14,826 5,121	760 6,508 14,826 5,121	20,140 760 6,508 14,826 5,121
4 4 6		4,641	11,486 4,641	6,363 11,436 4,641	1 507 6,368 11,486 4,641	9,547 819 6,363 11,436 4,641	9,547 819 6,363 11,436 4,641
38	-	150,4	13,500 4,051	0,130 10,500 4,551	1,037 0,130 10,000 4,031	12,929 1,097 0,130 13,500 4,051	12,929 1,097 0,130 13,500 4,051
3	_	28	16,074	0,100 14,0/4 0,100	7 194 1,040 12,074 0,100	10,248 0,100 1,200 14,014 0,100	10,248 0,100 1,200 14,014 0,100
		4 4 18	14.599 4.418	6.088 14.599 4.418	6.088 14.599 4.418	6.088 14.599 4.418	815 17,589 6,088 14,599 4,418
	199		12,921	12,921	4.995 12.921	15,809 12,921	829 15.809
	.818		15,885	15,885	6,061 15,885	17,050 6,061 15,885	17,050 6,061 15,885
		_	15,815	15,815	6,143 15,815	18,001 6,143 15,815	627 18,001 6,143 15,815
	,239		16,522	16,522	6,220 16,522	21,327 6,220 16,522	878 21,327 6,220 16,522
	: 683,		16,522	16,522	6,220   16,522	21,327 6,220   16,522	878 21,327 6,220 16,522
		_	16,830	16,830	6,123 15,830	17,752 6,123 15,830	801 17,752 6,123 15,830
	1,937	_	15,363	15,363	6,088 15,868	17,280 6,088 15,868	801 17,280 6,088 15,363
	3,026	_	18,929	18,929	5,447 18,829	14,544 5,447 18,829	948 14,544 6,447 18,829

TABLE.

Heats of Combustion with Oxygen.

Substance.	British Thermal Units of Heat.	Pounds of Water at 212° Fahr. Evaporated per Pound of Substance
		-
Hydrogen	. 61,500	63.66
Alcohol	. 12,968	13.42
Benzene	18,600	19.25
Carbon bisulphide	6,152	6.87
Carbon burning to carbonic scid	. 12,906	13.36
Carbon burning to carbonic oxide	. 2,495	2.58
Carbonic oxide burning to carbonic acid .	. 4,478	4.63
Charcoal, wood	12,455	12.90
Coal anthracite	15,600	16.14
Coal hest hituminous	15,504	16.05
Coke produced from ditto	14,375	14.88
Coal average quality	. 13,600	14.08
		18.25
Ethylene	21,500	22.25
Granhita	14,067	14.56
Light cerharetted hydrogen or merch gen	24.020	24.86
Lignite	11,710	12.12
Dignite	21,375	22.12
Olive oil	17.784	18.41
Doet dev	9,983	10.88
Detuclenm	. 20,272	20.98
Describes	. 20,272	21.94
Calaban	4,082	4.17
	1,002	16.86
	. 16,282	20.25
Turpentine	. 19,566	8.10
W00u, ary	7,022	8.10
Wood, dry         Cubic Feet per           Coal gas, 17 candles.         32 227           Water gas         22 862           Producer gas         14 369           Producer water gas         13 478	21,696	22.46
Water can 90.960	6,649	6.88
Dradman see	1 907	1.96
Producer gas	1,897	
rroducer water gas   13.478	983	1.02

The British standard unit of heat (thermal unit) is the amount of heat required to raise the temperature of 1 lb. avoirdupois of water 1° Fahrenheit.

The French standard unit of heat (calorie) is the amount of heat required to raise the temperature of 1 kilogramme of water 1° Centigrade.

The number of British units of heat required to evaporate 1 lb. of water at boiling point, 212° Fahr., is 966; and at 62° Fahr., 1116.

The number of French units of heat required to evaporate 1 kilo. of water at boiling point, 100° Cent., is 586.7; and at 16.6° Cent., 620.1.

One British unit of heat = .0251996 French units.

One French unit of heat = 3.96882 British units.

The total heating power of any fuel, expressed in British units,  $\div$  966 = lbs. of water at 212° Fahr. evaporated per lb. of fuel.

EXAMPLE:—1 lb. of hydrogen yields in combustion 61,500 units of heat.

Then:  $-\frac{61,500}{966} = 68.66$  lbs. of water at 212° Fahr. evaporated per lb. of hydrogen.

#### DISTILLED WATER.

(At 62° Fahr.)

1 pint = 84.65 cubic inches, or 1.25 lbs.

1 gal. = 277.274 cubic inches, or 10 lbs.

11.2 gals., or 1.792 c. feet = 1 cwt.

224 gals., or 85.84 c. feet = 1 ton.

1 cubic inch = 252.45 grs. or .036075 lb.

12 ,, inches = .434 lb.

1 ,, foot = 6.25 gals., or 1000 ozs., or 62.5 lbs.

1.8 , , = 1 cwt.

35.84 cubic feet = 1 ton.

1 cylindrical inch = .02842 lb.

12 ,, inches = .341 lb.

1 ,, foot = 5 gals., or 49.1 lbs.

2.282 ,, feet = 1 cwt. 45.64 .. .. = 1 ton.

Centre of pressure 3 depth from surface.

Water is at its maximum density at  $39 \cdot 2^{\circ}$  Fahr. (4° C.), and expands 1-10th part of its bulk on freezing.

# SPECIFIC HEAT OF SUBSTANCES.

The meaning implied in the term "specific heat," or more correctly "calorific capacity," is the quantity of heat required to raise the temperature of a substance 1° (independently of the unit of mass and scale of temperature); water being taken as the standard of comparison.

For example: the specific heat of mercury is .08882, by which is to be understood that thirty times as much heat is required to raise water to a given temperature as an equal weight of mercury. In other words, the quantity of heat which would raise the temperature of any given weight of mercury through 1°, would only raise the temperature of a like weight of water through .08882°.

Iron, cast . . . . . Iron, wrought . . .

#### SPECIFIC HEAT OF SOLIDS AND LIQUIDS. /Water en 1 \

	(Water a	s 1.)		
Acetic acid	·6589	Lead		.0314
Alcohol (sp. gr. '793)	-622	Lime, burned		.217
Aluminium	•2143	Lithium		9408
Antimony, cast	.05077	Magnesium		·2499
Arsenic		Manganese		·1217
Bees-wax	•45	Marble, white		·21585
Benzine	.3952	Mercury		03332
Birch	•48	Nickel		·10863
Bismuth	.03084	Oil, olive		3096
Brass	•09391	Oil, sweet		•31
Brick, common	•2	Oil of turpentine .		· 472
Brick, fire	-22	Palladium		·05928
Cadmium	.05669	Phosphorus		·18949
Chalk, white	21485	Pine		•65
Charcoal, animal, calcined .	26085	Platinum		.03243
Charcoal, wood	.24111	Potassium		· 1696
Clay, white, burned	185	Selenium		.07616
Coal	.2777	Silicon, crystallized		·1774
Cobalt	·1 <b>0</b> 696	Silicon, fused		· 175
Copper	.09215	Silver		.05701
Diamond	·14687	Sodium		·2934
Ether	•5207	Spermaceti		•32
Glass	19768	Steel		·1175
Gold	.03244	Sulphur		·20259
Graphite	·20187	Sulphuric acid		•333
Ice		Tellurium		·04737
Iodine	.05412	Thallium		.0336
Iron cest	12983	Tin		•05695

# SPECIFIC HEAT OF GASES AND VAPOURS.

Tin

Zinc .

12983

11879

.05695

.09555

		O 10 - TT 4 -4	0	C
		Equal Weights.	Specific Heat of	Specific Heat of Constant Volumes.
(	Air	0.2374 .	0.2374 .	0.1687
Simple	Oxygen	0.2175 .	. 0.2405 .	0.1559
	Nitrogen	0.2438 .	0.2370 .	0·17 <del>4</del> 0
gases.	Hydrogen	3 · 4090 .	0.2359 .	2·4096
	Chlorine	0.1210 .	0.2962 .	. <b>. –</b>
Vapour.	Bromine	0.0555 .	0.3040 .	. <b>. –</b>
v apour.	Binoxide of nitrogen	0.2815	0.2406 .	—
- (	Carbonic oxide	0.2450 .	. 0.2370 .	0.1768
I	Carbonic acid	0.2163 .	0.3307 .	. 0.1714
	Sulphuretted hydroge		. 0.2857	
t	Sulphurous anhydrid		. 0.3414	. 0.1246
Compound /		0 1845 .	. 0.2338	0 1210
gases.	Hydrochloric acid		. 0 2333 .	–
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Nitrous oxide	0.2262 .		–
1	Nitric oxide	0.2317 .	0.2406 .	· · —
	Ammonia	0.5083 .	0.2966 .	
	Marsh gas	0.5929 .	0.3277 .	0.4683
	Olefiant gas (ethylene	o) . 0·4040 .	0.4106 .	—
	Water (steam)	0 · 4805 .	0.2984 .	0.3337
- 1	Ether	0.4810 .	1.2296 .	0.8411
1	Chloroform	0.1567 .	0.6461 .	
}	Alcohol	0.4584 .	0.7171 .	0.3200
Vapours. {	Turpentine	015061 .	2.8776 .	—
- 1	Bisulphide of carbon	. 0.1570	. 0.4140 .	· · · · · ·
i	Benzole	0.3754 .	1.0114	•
1		0 4125 .	0.8244 .	
	Acetone			—

			TAB	LE,				
Showing the B	Expansion	of L	iquids i	r Volume	from	8 <b>2</b> °	to 212°	Fahr
1000 parts of	water .				. bec	ome	1046	
• ,,	oil					"	1080	
**	mercury					,,	1018	
11	spirits of	wine .				"	1110	
,,	air		• • •		•	**	1878 to 1	875
			TAB	•				
Showing the	Lineal E	Expans veratur	ion of M a from B	letals prod <b>2º to 212º</b>	luced Fab	by R r	aising th	e ir
Zinc	-	part in	•	Gold .	L. COTO	•	1 part	in 690
Lead		-	351	Bismuth	• •		-	719
Tin (pure)		"	403	Iron .	: :	: :	, ,,	812
Tin (impure) .		"	500	Antimony			, ,,	928
Silver		"	524	Palladiun	ι.		, ,,	1000
Copper		"	581	Platinum	•		, ,,	1100
Brass		"	584	Flint glas	8.	•	,,	1248
			TAB	LE,				
Showing	the Rela	tive P	ower of 1	Metals for	Cond	uctin	g Heat.	
Gold			)00 I	Iron .		_		874-9
Silver			73	Zinc .	: :	•		868
Copper			398-2	Tin	: :	•		903.8
Platinum			881	Lead .		•		179.6
			TAB	LE.				
Showing	the Rela	tive P	ower of	Metals fo	r Re	flecti	ng Heat.	
			•	Radiatio	•		•	
211041114,9	Intens	REPARTS						
	Intens	316A OI		Polished 1				80
Silver plate .	Intens	: :	·97 ·95	Polished p				
Silver plate . Gold	Intens	: : :	·97	Polished p Steel . Zinc .		m .		88
Silver plate . Gold Brass	Intens	: : :	·97 ·95 ·98 ·86	Steel .		m .	· · ·	
Silver plate . Gold Brass Speculum metal	Intens	: : : : : : : : : : : : : : : : : : :	·97 ·95 ·98	Steel . Zinc .		m .		
Silver plate . Gold Brass Speculum metal	Intens	: : : : : : : : : : : : : : : : : : :	·97 ·95 ·98 ·86	Steel . Zinc . Iron .		m .		. ·80 . ·88 . ·81 . ·77
Silver plate . Gold Brass Speculum metal Tin	Intens		·97 ·95 ·98 ·86 ·85	Steel . Zinc . Iron .		m .		83
Silver plate . Gold Brass Speculum metal Tin		egrees F	97 95 98 98 86 85 <b>TAB</b>	Steel . Zinc . Iron	olatinu · · ·	m .	Degree	
Silver plate . Gold Brass Speculum metal Tin		9grees F 1247	97 95 98 98 86 85 <b>TAB</b>	Steel . Zinc . Iron	olatinu	m .	Degree	. · ·88 · · ·81 · · ·77 s Fahr.
Silver plate		egrees F 1247 797	97 95 98 86 85 TAB: Melting	Steel . Zinc . Iron . LE.  Points.  Phosphor Platinum	olatinu	m .	Degree 1 82	. ·88 · ·81 · ·77 s Fahr.
Silver plate . Gold Brass . Speculum metal Tin Aluminium . Antimony Bismuth		egrees F 1247 797 504	97 95 98 86 85 TAB: Melting	Steel . Zinc . Iron	olatinu	m .	Degree 1 82 1	. ·88 . ·81 . ·77 s Fahr. 11 27 96·4
Silver plate . Gold Speculum metal Tin Aluminium . Antimony . Bismuth Bronze		egrees F 1247 797 504:	97 95 98 86 85 TAB: Melting	Steel . Zinc . Iron	olatinu	m .	Degree 1 82 1	s Fahr.
Silver plate		egrees F 1247 797 504- 1652	97 95 98 86 85 TAB: Melting	Steel . Zino . Iron	us .	m .	Degree 1 32 1 18 . 203 to 2	s Fahr. 11 27 36 4 82 04 08
Silver plate Gold Speculum metal Tin  Aluminium . Antimony Bismuth Bronze Butter Copper		9 egrees F 1247 797 504- 1652 91	97 95 98 86 85 TAB: Melting	Steel . Zinc . Iron	us .	m .	Degree	s Fahr. 11 27 364 4 32 34:08
Silver plate . Gold . Brass . Speculum metal Tin . Aluminium . Antimony . Bismuth . Bronze . Butter . Gopper . Gold		egrees F 1247 797 504: 1652 91 2102 2192	97 95 98 86 85 TAB: Melting	Steel . Zinc . Iron . Iron	us .	m .	Degree 1 32 18 . 203 to 2	s Fahr. 11 27 96 4 82 04-08 20
Silver plate . Gold		egrees F 1247 797 504- 1652 91 2102 2192 2156	97 95 98 86 85 TAB: Melting	Steel . Zino . Iron . Iron	us .	m .	Degree	s Fahr. 11 27 96.4 82 20 31
Silver plate . Gold		egrees F 1947 797 504 1652 91 2102 2192 2193	97 95 98 96 98 85 TAB: Melting	Steel . Zino . Iron . Iron	us .	m .	Degree	s Fahr. 127 96 4 82 94 08 20 31 52 36
Silver plate Gold Brass Speculum metal Tin Aluminium Antimony Bismuth Bronze Butter Copper Gold Ditto, coined Ioe Iodine	De	egrees F 1247 797 504 1652 91 2102 2192 2156 82 237	97 95 98 96 98 85 TAB: Melting	Steel . Zinc . Iron	nas	m .	Degree	s Fahr. 11 27 96 4 20 81 20 81 80 49
Silver plate . Gold	De	egrees F 1247 797 504: 1652 91 2192 2192 2156 82 237:	97 95 98 96 98 85 TAB: Melting	Steel Zino Iron Iron Iron Points.  Phosphor Platinum Potassium Silver Sodium Spermace Stearine Steel Sulphur Tin Wax, whi	us	m .	Degree	s Fahr. 11 27 86.4 82 24.08 20 30 30 40 50 40 50 50 50 50 50 50 50 50 50 50 50 50 50
Silver plate Gold Brass Speculum metal Tin Aluminium Antimony Bismuth Bronze Butter Copper Gold Ditto, coined Ioe Iodine	De	egrees F 1247 797 504 1652 91 2102 2192 2156 82 237	97 95 98 96 98 85 TAB: Melting	Steel . Zinc . Iron	us	m .	Degree	s Fahr. 11 27 96.4 20 81 52 80 81

#### THE GAS INDUSTRY.

Initiation, Development and Progress.—The manufacture and distribution of coal gas may be justly described as one of the important industries of the world. Like railways and the electric telegraph, it is a product of the 19th century; for, though coal gas was actually used for illuminating purposes by William Murdoch, the inventor of gas lighting, as early as 1792, at Bedruth, in Cornwall, and in 1797 at his house at Old Cumnock, Ayrshire, it was not until well into the first decade of the present century that gas began to be generally applied in the lighting of streets, factories, and dwelling-houses.

The illumination of the Soho Works, Birmingham, to celebrate the Peace of Amiens, took place in 1802. These works belonged to Boulton and Watt, and Murdoch was employed as manager to the Firm. The first application of gas to the interior lighting of large premises was made by Murdoch in Salford, in 1805, at the cotton manufactory of Phillips and Lee; and the first street lighted with gas was Pall Mall, London, in 1807. The first gas Company incorporated by Act of Parliament was the "Chartered" (now the Gaslight and Coke), London, in 1812.

Although in its earliest use coal gas was restricted to the purpose of affording artificial light, no long time elapsed before its value as a heating medium began to be realized. Winsor, one of the pioneers of gas lighting, claimed as an important advantage of the new invention or discovery that gas, besides its light-giving qualities, could be used both for cooking food and warming dwellings, and as early as 1825 attempts were made to apply it for these purposes. It was not, however, till later on in the century that anything like a practical application of gas was made to the cooking of food. Mr. J. Sharp, of Southampton, about the year 1840, began to construct ovens heated by gas for cooking and baking, and these he used for many years, giving public lectures, in the course of which he practically demonstrated their usefulness and value.

Gas, however, in those days was higher in price than now; and, although it was evident that it served most efficiently for culinary operations, its cost militated against its extensive adoption in this direction. The prejudice against it was strong, also, on account of the supposed liability of any food cooked by its means to be tainted with the flavour of the gas itself. This operated against its use; and though

the prejudice was founded on ignorance of the facts, it is not a matter of wonder that such an idea was entertained, seeing that, even at the present day, in spite of the strongest evidence to the contrary, the same belief is still widely accepted, and still operates with many as a bar to its adoption.

Gas has won for itself an important place as an agent for obtaining motive power. It was from the very first a matter of observation, and not unfrequently of dire and unsought experience, that when gas and atmospheric air were mixed in certain proportions, and the mixture fired, an explosion was the result. Attempts were soon made to utilize the force thus exerted by confining the explosive compound in a suitable cylinder, and exploding it to obtain prime movement as in the steam engine. After many more or less successful attempts by different inventors, and the expenditure of much ingenuity, the 'Lenoir' gas-engine, so named after its inventor, was produced (1860), and thus was solved the problem of how to utilize an explosive mixture of gas and air as a prime motor. From that time down to the present the patent records contain the description of many inventions of this character, and gas-engines of great power and efficiency are now produced.

It is occasionally a subject of remark by uninformed or hostile critics, that no important improvements have been effected in gas manufacture since the earlier days of its introduction. If this were so, it would either speak well for the inventors of this art, or badly for their successors in the industry. The statement, however, is altogether wide of the truth. True, the method of producing the gas. as in the earlier days, is by distillation of the coal in closed retorts, and the purification, storage, and distribution of gas are effected in apparatus and plant which, in their main features, do not greatly differ from the earlier forms. But it is obvious that a similar invidious comparison might be made in regard to all the most notable inventions. The chief characteristics of an industry are retained, whilst the processes undergo improvement and modification. As a matter of fact, great improvements have been effected in the plant and apparatus for the manufacture of illuminating gas, whilst the mechanical and chemical principles involved in its production and use are now carefully investigated by gas engineers, and are yearly becoming better understood.

Illuminating Power.—In England, Wales, and Ireland the gas

actually supplied to consumers varies in illuminating power from 14 to 22 standard candles, according to the quality of the coal used; the higher figure above 16 candles being obtained by an admixture of cannel, or shale, with the ordinary bituminous coal, or the use of oil as an enricher. In Scotland the range of illuminating value is from 22 to 80 candles.

Cost Price.—The average cost of producing and distributing illuminating gas in England is about two-thirds of the selling price. Taking a selling price of, say, 2s. 6d. per 1000 cubic feet, the cost of producing and distributing the gas, including the net expenditure on coal (after deducting the income from residuals) and working expenses, will be 1s. 8d. per 1000 cubic feet. Analyzing this figure, the expenditure on coal will be 1s. 8d., and deducting the value of the residuals, at present prices, which is equal to 7d., there is left 8d. as the net cost of the coal. The balance of 1s. 1d. is made up by the working expenses, which include wages, salaries, purifying materials, repairs and renewals, rates and taxes, printing and stationery, and incidental expenses. The difference of 10d. between the prime cost of the gas, 1s. 8d., and its selling price of 2s. 6d. is absorbed in the payment of the interest and dividend on the invested capital in the case of a Company, and in the instance of the Undertaking belonging to a Local Authority, in the discharge of the interest on the annuities and borrowed capital (if any), and the provision of a sinking fund.

Selling Price.—The selling price of gas per 1000 cubic feet ranges throughout England, Wales, and Ireland from 1s. 6d. to 6s., and in Scotland from 3s. to 8s. 4d., with a few of the smallest concerns charging as much as 10s. per 1000 cubic feet. Taking into consideration, however, that in Scotland gas of a higher illuminating power is supplied than in the other portions of the kingdom, that a smaller consumption per consumer is the consequence, and calculating the price at per theoretical unit of light, the actual difference in price is not so great as appears at first sight. The practical advantages, however, of the higher illuminating powers may be questioned, and certainly they are not proportionate to the cost of producing the richer gas.

Capital Employed.—The Capital of a Gas Undertaking represents or includes (1) the amount of money that has been expended on obtaining an Act of Incorporation, if it be a Statutory Company; (2) the cost of the land for the site of the works, and the engineering expenses incurred; (8) the cost of the general manufacturing,

purifying and storing plant; and (4) the cost of the distributing pipes and accessories; with (5) an added sum as a floating or working capital to meet current outlay before the revenue begins to accrue.

The amount of the various items making up the aggregate, necessarily varies under different conditions. For example, take the first—the money expended on obtaining an Act of Incorporation. When a Company have had to contend with and overcome persistent and strong opposition, the cost of their Act will exceed the cost of one obtained under more favourable conditions, to the extent of 100, 200, or even 800 per cent. Again, the cost of land is a varying factor, and the expense of the erection of works is often increased by the character of the site and its subsoil. It is true that in the case of a large Company, these several items, even when greatly in excess of a normal amount, do not increase the total capital outlay by any material percentage; but on small and moderate-sized undertakings they are often peculiarly burdensome.

But there are other circumstances more distinctly marked than these, which contribute to the variations in the relative amount of capital expended by different Companies. The character of the district of supply is one of them. The district of some Companies is thickly populated with a high class of consumers throughout. Others, again, have a scanty population, and of a poorer class; and although the plant and mains of this latter may be less extensive, yet the proportion of its capital to the production and rental will usually be in excess of the other, whilst there is this paradoxical result in the instances referred to, that those who are least able to afford it have often necessarily to pay a higher price for the gas.

In many instances, Companies have wide expanses of country to canalize with miles of mains, on some of which, except at the terminus, there is scarcely a consumer. Again, the district may be a manufacturing one, with mills and workshops consuming gas only during four or five months in the year. The proportion of capital in such case has frequently to be large to provide plant to meet the principal gas demands within a limited period of time. It is no unusual thing, under such circumstances, to find that during nearly one half of the year, seven-tenths of the whole plant is standing unproductive.

In contrast to these, there are towns whose gas consumption is comparatively steady all the year round. Take, as an example, the inland watering-places and fashionable sea-side towns. Into these,

there is during the summer and autumn seasons, an influx of visitors who consume a large quantity of gas. Such is proved by the fact that the heaviest daily make in these places is generally in the months of August, September, or October. This tends to equalize the consumption in the different seasons, because the resident inhabitants consume their proportion of gas during the winter and early spring months, when the visitors are absent. It is fair to conclude that, owing to this regular and steady consumption, the plant is almost continuously employed, and therefore a smaller capital in proportion to the yearly production is required than in those places where the heavy consumption is spasmodic and brief.

But although this spasmodic consumption appears, at first sight, a serious drawback, in practice it does not always necessitate a higher price for the gas, and a much larger capital outlay than is required by those concerns whose consumption or sale of gas is steadier; for in some of the large manufacturing towns the mill consumption is so enormous that, by straining the plant for limited periods, the disadvantage is counterbalanced.

There can be no question that expensive engineering tends to an undue inflation of the capital account. A want of engineering skill in the construction of works has precisely the same effect; for here, as in other matters, extremes meet.

Considerable thought will always be given by a capable and conscientious engineer to the proper arrangement of works. He will so perfect his designs that the works shall not be squandered or sprawling over the site, occupying unnecessary space, but compact and harmonious, so that the different processes in gas making may be conveniently carried on, and economical in the working.

Whilst it is not necessary or desirable that the buildings of a gas-works should be as strong as a castle, it is equally objectionable to set up unstable and flimsy structures that entail an annual heavy expenditure for repairs, constituting a perpetual tax, enhancing the cost of working.

Excessive and unnecessary ornamentation is to be eschewed in all works of this kind. All ornamentation, however, is not useless. Blank thick walls, for example, are not necessarily stronger than others well proportioned—thinner and lighter in parts, but strengthened by suitable projections that add to the beauty of a building by breaking the dull uniformity. The same argument holds good as respects design in apparatus. Taste should not be neg-

lected; and there is ample scope for the exercise of good taste in most departments of a gas-works.

On a closer examination of the question, it will be apparent that there occur times in the history of most gas undertakings when the capital expenditure is either below or in excess of the average, viz.—when the margin of its producing, storing, and distributing resources is closely worked up, and enlargement is required, then the capital compared with the production is low. But extensions have to be carried out. These must necessarily be of such extent as to provide a margin for future increased consumption, and, being larger than the immediate requirements of the district, the capital is swelled out of proportion. This is especially true of times when trade is brisk, and labour and materials are dear. Then extensions are costly, and, singular to say, it is at such times that they are most frequently made. Under such circumstances, unless resort can be had to a reserve fund to maintain the dividends, a sacrifice of a portion of the statutory interest has to be submitted to or the price of the gas increased.

But this condition of things is by no means inevitable. One of the evidences of good administrative skill in the conduct of a gasworks is the ensuring that extensions are carried out systematically and with foresight, and in as gradual a manner as may be, not postponing them to the very last extremity; in other words, starving the concern—wearing it threadbare—which is the worst policy possible for the undertaking and all associated with it, including both shareholders and consumers.

The capital of gas-works in the hands of Corporations and other Local Authorities is, as a rule, in excess of that of Companies; but this arises from causes well understood. Many towns' Authorities have within comparatively recent years become possessed of gas-undertakings by purchase from the Companies who previously owned them; and, as in most cases they have had to pay the full market price for the concern, amounting to from twenty to twenty-eight years' purchase of the annual profits, and even more in some instances, the result is that the capital outlay is large—with this compensatory advantage, however, that the percentage of interest to be paid on such capital is not more, but usually less, than that paid by the Company on the smaller capital. As time goes on, and extensions of the Corporation works are made, these are carried out with an expenditure, though not necessarily less than that of a Company, yet

bearing a lower rate of interest, and consequently pressing less heavily on the resources of the undertaking.

But this remark needs qualification. In the case of Local Authorities becoming possessed of such works, a sinking fund has to be provided out of the profits to redeem the capital within a given period. Fifty years was formerly a usual term to allow; but there is a tendency (especially on the part of the Local Government Board), to restrict the term to thirty and even twenty years. The result is that the annual charge for interest and sinking fund is in excess of the rate at which a Company under the Auction Clauses can raise its additional capital. True, the sinking fund eventually wipes out the capital liability, and the present generation of overburdened consumers have to be consoled by the knowledge that posterity will reap the benefit of their self-sacrifice.

The immediate effect of an excessively large capital outlay by a Gas Company is, as has been already remarked, either a sacrifice by the shareholders of a proportion of the statutory dividends, or an augmentation in the selling price of the gas; and not unfrequently, when the capital is greatly in excess, both these undesirable results are experienced.

One of the best, perhaps the very best method of reducing the proportion which capital expenditure bears to revenue, is to cultivate a day consumption of gas, by affording facilities for, and encouraging in every legitimate way the use of gas for cooking, heating, and motive power. This policy, if pursued to a successful issue, is virtually to reduce the percentage of capital in the proportion of such consumption, because the plant is brought to bear in earning profit during the daylight as well as in the lighting hours.

It is unreasonable to expect that the capital of Gas Companies, and the selling price of gas, can ever be uniform throughout the country. It would be just as reasonable to expect that the general rates of different districts can be equalized. All the causes above pointed out, and others not touched upon, militate against such a result.

The "Auction Clauses."—These clauses, which are now, and for many years past have been, introduced into the Bill of every Gas Company making application to Parliament for money powers, are, without doubt, an ingenious and fairly satisfactory device for securing the economization of capital.

They provide that the additional stock or share capital required

shall be raised by public auction or tender, instead of, as formerly, by the allotment of the stock or shares to the existing shareholders pro rata at par.

The immediate result of this is that there is no inducement to the Company to issue and expend more capital than is, from time to time, absolutely necessary.

A limited amount of ordinary stock is put up to competition, and this bearing, say, a seven per cent. standard dividend, commands (in a well-managed Company) a premium in the market of at least 50 per cent. In other words, £100 par value of stock or shares sells for, say, £150, being thus sold and bought to yield about 4 to  $4\frac{2}{3}$  per cent. interest.

The 50 per cent. or whatever premium is realized, forms part of the capital for extensions of works, but is not entitled to dividend. In this way the importation of non-dividend bearing capital into the concern is advantageous to the general body of consumers, whilst at the same time it tends to give stability to the undertaking.

The "Sliding Scale."—This is not inserted compulsorily in Gas Bills, as are the auction clauses, but at the option of the Company applying to Parliament. A standard selling price for the gas, and a standard rate of dividend being given, it is provided that for every penny of a reduction in the price of the gas below the standard, the Company are empowered to pay a quarter per cent. above the standard dividend, or one per cent. for a reduction of fourpence, and vice verså, if the selling price of the gas is raised.

It is assumed, though it is by no means always the case, that the margin of profit earned after making the reduction, is sufficient to allow of the increased dividend to which the shareholders are entitled; otherwise, of course, it cannot be paid, unless there is a balance in hand of revenue that can be drawn upon.

The effect of the sliding scale is to confer a greater benefit on the consumers than on the shareholders; because a reduction of a penny per 1000 cubic feet on the total quantity of gas sold often amounts to a sum four times larger than that represented by the additional quarter per cent. dividend to which the shareholders are entitled by reason of the reduction. In point of fact, the sliding scale creates a virtual partnership between the gas consumer and the gas proprietor, to the advantage of the former.

The combined effect of the auction clauses and the sliding scale has

been to induce the exercise of economy, both in the expenditure of capital and in the general working of the undertaking, and so to secure a gradual reduction in the selling price of the gas.

No doubt the Companies who were enabled to adopt the sliding scale of price and dividend in the early days of its inception, are to be congratulated on the results they have achieved in the way of enhanced dividends by its application and working; but there is less room for congratulation to any who adopt it now, with the closer limitations which prevail in fixing the initial or standard price.

It is clear, also, that Companies seeking powers at a time when coal and materials generally are low in price, are placed at a disadvantage as compared with other Companies applying to Parliament in a time of inflated prices. Notwithstanding all experience, one of the ruling characteristics of average human nature is to conclude that that which actually exists will scarcely ever again be modified to any large extent. Injustice may, therefore, unintentionally, be meted out to one Company, and more than justice to another; and so, when the reaction comes, the circumstances of the first suffer impairment, whilst the other is glutted with a run of good fortune. This want of equal justice in the incidence of the sliding scale, whilst inevitable, is sufficient to convince any disinterested observer that its indiscriminate advocacy is a mistake. It is, moreover, a curious and interesting commentary on the action of the sliding scale that, in spite of the inducement which it offers for a low selling price, there are both Gas Companies and Local Authorities who, without it, can produce and sell gas at a price as low as, or even lower than, those who boast its possession.

Sundry Useful Notes.—In choosing the site for a gas-works, consideration should be had to its position, which should be at the lowest, or nearly the lowest, part of the district, to obtain the advantage of the natural increase in the pressure of the gas in travelling to the higher levels.

It should, if possible, be alongside a railway, navigable river, or canal, for convenience in the delivery of coal and other materials, and the disposal of such of the residuals as are despatched to a distance.

The buildings and plant should be so set out on the land as to admit of future extensions being made with ease and economy.

The design of a structure should be in keeping with the purpose for which the structure is intended.

The term "Structural Value" has reference to the amount of capital expended upon works in their construction.

"Commercial Value" is the value of the net annual profits which a Firm or Company can make by the use of their works.

Capital is best spent on substantial tanks and apparatus. Mere ornament should be a secondary consideration.

The average cost of gas-works in provincial towns is about £1 per head of the population. In very large towns it will amount to more, and in very small towns it will scarcely reach that sum.

The capital of most gas-works per million cubic feet of gas produced per annum is from £500 to £700; or at the rate of about 10s. to 14s. per 1000 cubic feet. Reckoned on the *maximum* production of gas in 24 hours, the capital will amount to about 2s. 8d. to 2s. 8d. per cubic foot, or, say, £112 to £188 per 1000 cubic feet.

The capital of a well-managed Gas Company of average size, does not usually amount to more than four times the annual gas rental. Vice versa, the gas rental should be at least one-fourth of the capital.

The population per mile of main is usually about 2000 people. In densely populated towns it will rise to 8000; but in fashionable residential places, where the houses stand more apart, the population per mile of main will fall below 1000.

The usual consumption of gas per mile of main in large towns ranges from 2½ to 5 millions of cubic feet per annum; and in small towns from 2 to 8 millions.

The gas rental per mile of main usually ranges from £400 to £600 per annum.

The average consumption per head of the population in large towns is about 2000 cubic feet per annum; in small manufacturing towns about 1600 cubic feet, and in agricultural towns about 1000 to 1200 cubic feet per annum.

The usual annual increase in the consumption of gas is from 5 to 10 per cent. In rapidly growing districts it will range higher.

### TABLE.

Showing the Time in which the Yearly Consumption of Gas will be Doubled, at Different Annual Rates of Increase.

Rate per cent. of Increase per ann.	Time in which the Consumption will be Doubled.	Rate per cent. of Increase per ann.	Time in which the Consumption will be Doubled.	Rate per cent. of Increase per ann.	Time in which the Consumption will be Doubled.
2 21 3 8 4 4 41 5	85 years, 1 day. 95 years, 26 days. 28 years, 164 days. 20 years, 54 days. 17 years, 246 days. 15 years, 273 days. 14 years, 75 days.	6 <u>4</u> 7 7 <u>4</u> 8	12 years, 845 days. 11 years, 327 days. 11 years, 2 days. 10 years, 89 days. 9 years, 213 days. 9 years, 2 days. 8 years, 181 days.	9 91 10 101 11 111 112	8 years, 16 days. 7 years, 283 days. 7 years, 100 days. 6 years, 844 days. 6 years, 284 days. 6 years, 184 days. 6 years, 184 days.

Handy Rule for Converting Capital per Million Cubic Feet into Capital per Thousand Cubic Feet.

Point off all the figures after the hundreds as decimals, and multiply by two.

EXAMPLE.—The capital of a gas undertaking is £625 per million cubic feet of gas sold (or produced) per annum, what is the capital per 1000 cubic feet?

THEN.— $6.25 \times 2 = 12.50$ ; say, 12s. 6d. per 1000 cubic feet.

## GOLDEN RULES FOR GAS MANAGERS.

Keep up the heats of the retorts.

Keep up the efficiency of the meters.

Keep down the pressure in the mains.

Keep down the arrears in the yas ledger.

These rules are as applicable to-day as they were on the first day they were penned, as they embody all the philosophy of gas management. A strict adherence to the advice which they give will ensure the success of any gas undertaking, just as a disregard of them will result in loss and disaster.

It has been attempted (with little success, and less reason) to impugn the utility of the third rule. To keep down the pressure in the daytime is, it is alleged, to discourage the use of gas for cooking and heating. But, surely, to make such a remark is to betray an amount of dulness not easy to understand. The meaning of the rule is obvious. It is not advised that the pressure should be kept down to an abnormal extent. Whatever pressure is required either by day or night must, of course, be maintained; the rule indeed implies as much, but it implies something more—its object is to discountenance the maintenance of a wasteful pressure, and all pressure in excess of actual requirements is wasteful. Verbum sat sapienti.

#### COEFFICIENTS

#### OF THE

Number, Dimensions, and Cost of the various Buildings, Apparatus, Machinery, and Plant of a Gas-Works.

It is an almost impossible task to give a series of coefficients of the number, dimensions, and cost of Buildings, Apparatus, Machinery, and Plant, applicable to the individual case of every Gas-Works in the United Kingdom. That such is the fact will be clear when the variations in size, character of subsoil, design (whether substantial or otherwise), and situation of such Works, are taken into consideration.

Again, although the cost based on the prices of labour and materials ruling at the present time may be applicable, it is evident that the figures will necessarily vary with the fluctuations in the market prices, and the effect of competition.

And neither is it possible to fix with perfect accuracy a standard of prices as a basis that will apply even under existing circumstances, as such prices vary, less or more, in different parts of the country.

At the best, it is only an approximation that can be given, and an attempt in this direction is made as follows:—

# Prices on which the Coefficients of Cost are based.

				ab											Average.
Skilled labour .							•		•				٠.		10d. per hour.
Unskilled ditto	٠		·	•		•	•	٠.	•		٠.	•	•	•	4d. to 6d. per hour.
Bricksetting, labor	our	on	ly		•	•	•	•	٠	٠	٠,	•	٠	•	1s. 8d. per sq. yd. 9" thick.
Retort setting, la	bot	n c	lac	y											22s. per mouthpiece.

	Materials.	Average.
Selected best presse	d bricks	
Common bricks, bes	<b> </b>	90s. per 1000.
Ties or budment .	me	50s. per ton.
Ordinary lime	bricks, as silica, &c.	19a ditto
Building sand		la. per load.
Sheet lead for flashi	ing	18s. 6d. per cwt.
Fire-bricks		60s. per 1000.
Superior refractory	bricks, as silica, &c	85s. ditto.
Fire-clay, ground .		20s. per ton.
Clay retorts 21" × 1	15"	4s. per lineal foot.
Cast-iron pipes 2" to	o 4" diameter	£5 58. per ton.
Ditto 5" to	0 8" ,,	£5 ditto.
Ditto 17// ex	o 16" "	£1 108. U100.
Specials, cast-iron	nu upwatus	£8 to £11 ditto
Wrought-iron tub	g and jointing pipes is given es according to list prices, v	with 60 per cent. discount.
Ditto	fittings	ditto.
	and Materials combined.	Average.
Stock brickwork, 9"		5s. 6d. per square yard.
Common ditto, best,	, 9" thick	3s. 9d. ditto.
Superior dressed sto	nework	8s. per cubic foot.
Kuppie	ditto	10s. per cubic yard.
Flooring 9// floor		38. to 38. od. per square yard.
Paying with 511 and	RII satta	
Portland cement con	orete 1 in 9	10s. per onbig ward.
Ditto ditto	1 in 7	12s. ditto.
Ditto ditto	1 in 5	14s. ditto.
Ditto ditto	n firing only	. 15g. ditto
Ditto small o	eastings	£10 to £12 ditto.
Plain cast-iron colu	pastings	£7 5s. to £7 15s. ditto.
Ditto ditto	nxing only	10s. to 15s. ditto.
been or wrought ir	on in bars with forged en roef work	
Ditto	ditto fixing only .	£2 ditto.
Ditto		and
	channel .	£15 ditto.
Ditto	ditto fixing only .	£2 ditto.
Steel or wrought-iro	on roofs, per square yard o	d floor
area covered, but	not including slating	14s. to 17s.
Steel or wrought in	on in bars, with forged en	ds, for
	pparatus generally	
Ditto lixing	only	£2 ditto £18 per ton.
Ditty Ditty	only	£1 ditto.
Ditto	in sheets and plates	cold-
21000	straightened and punci	ned . £18 ditto.
Ditto	rivets and fixing	£2 10a, 10d, ditto
Ditto	in rolled iron girders .	£6 to £6 10s. ditto.
Ditto	fixing only	15s. ditto.
Ditto	riveted girders	£11 to £12 ditto.
Ditto		
Chart land Cold	fixing only	10s. to 15s. ditto.
Sheet lead flashing	fixing only	£6 to £6 10s. ditto 16s. ditto £11 to £12 ditto 10s. to 16s. ditto 10s. to 16s. ditto 10s. 6d. per owt.

It is on these average prices current that the coefficients of cost to be now given are based.

### Capacity of the Works.

A Gas-Works capable of producing a maximum of 680,000 cubic feet of gas per day of 24 hours is taken as a basis, and this size of works is adopted as being, though comparatively small, about a fair average, and to give a wider applicability to the figures than they would have had a very large works been assumed.

Using 190 as the multiplier, this is equivalent to an annual production of 120 million cubic feet. Reasonable allowance is also made for future growth in the consumption.

The site of such a works will comprise 2 to 8 statute acres of land. It is assumed that the site is fairly level and such as to admit of its being fully utilized.

This extent of land is capable of containing, without inconvenient crowding, provided the works are laid out with judgment, the whole of the manufacturing, purifying, and storage buildings and apparatus required for the above make of gas per day, and also the buildings and plant for the manufacture of sulphate of ammonia, the recovery of sulphur, and the distillation of tar.

The cost of the apparatus in each case includes erection.

The buildings are assumed to be neat and substantial.

Estimating the production from each mouthpiece or retort (oval or D shaped  $21" \times 15" \times 10$  feet long) at 6000 feet of gas per day of 24 hours on the average—

The number of mouthpieces required is Add by way of surplus to meet contingencies	•	105 21
Total mouthpieces required .		126

The retorts are assumed to be in settings of sixes or sevens, and are throughs.

Cost.	Description.	Cost rech the Ma: (24 hours') duction Cubic	r. daily Gas pro-	Cost per Mouth- piece.
£	•	£	в. d.	£ s. d.
10,080	Stage Floor Retort House with retort stack 20 feet wide, 20 feet space on each side. Retort settings, two dwarf chimneys, generator furnaces, all ironwork (including foul main round the inside of the house), tools, and implements; also covered coal stores to contain six weeks' stock of coal calculated on the maximum days' consumption, with railway communication.		0	80 0 0
6,255	Stage Floor Retort House and coal stores only, as above		-	. 49 18 0
3,825	Retort Stack and two Dwarf Chimneys built up from basement, with generator furnaces, retort settings, and ironwork	! :		
2,520	Brickwork of Retort Stack and two dwarf chimneys, generator furnaces.	6 1	3	80 7 0
1,800	retorts, and settings, but no ironwork.  Ironwork only of stack complete, includ-	4 0	0	2000
•	ing hydraulic and foul mains	2 1	8	10 7 0
680	Retorts, including labour in setting and all fire-clay materials (no ironwork)	1 0	0	500
680	Generator Furnaces and ironwork of	1 0	0	. 500
7,000	Ground Floor Retort House with retort stack 20 feet wide, 20 feet space on each side, retort settings, two dwarf chimneys, all ironwork (including foul main round the inside of the house), tools, and implements; also covered coal store to contain four weeks' stock of coal calculated on the maximum day's consumption, with railway communication.		: <b>8</b>	55 10 0
4,190	Ground Floor Retort House and coal			
2,810	Retort Stack, two dwarf chimneys, and retort settings, with iron mountings	6 18	8	38 5 0
1,606	Brickwork of retort stack, two dwarf chimneys, retorts, and settings, but no	4 9	0	22 5 0
1,194	ironwork	2 11	0 .	. 12 15 0
680	draulic and foul mains	1 18	0 .	9 10 0
2,000	Retorts, including labour in setting and fire-clay materials (no ironwork) Railway Communication with an ad-	1 0	0	500
460	joining line of railway. This is an uncertain item, but say as an average Condenser. This may be of any form, vertical or horizontal (the respective cost will not vary to any great extent), with connections and bye-pass mains	8 2	6 .	16 0 0
	and valves complete	0 14	6.	. –

Cost.	Description.		Cubic I	eet xim	ım)
£				8,	
535	Boiler and Exhauster House. Chimney and se two boilers	tting for		17	0
300	Steam Boilers of the Cornish type, two in nu steel and of ample size to supply steam for ex sorubbers, washer-scrubber, pumps, sulphate a and any other purpose on the works 18'0" × 5'6' mountings and connections.	hausters, pparatus		9	6
930	Exhauster. Capacity 40,000 cubic feet per hodirect, with its own steam engine, with governections, bye-pass mains and flap-valve of Duplicate exhausters are desirable in case of	nor, con- complete	•	10	c
1,325	down  Tower Scrubbers, two in number, 9 feet in diam 44 feet high each, with pent-house in addition filling, liquor and water distributors, washer,	a. Wood		10	6
570	Washer Scrubber with steam engine, connecting pass mains and valves. Capacity, 700,000 cubic			2	0
<b>50</b> 0	day  Tur and Ammoniacal Liquor Wells, two in no one divided in two. These are assumed to be ground, built of bricks in Portland coment	oe under mortar;	•	18	0
80	capacity equal to four weeks' production of liquor; with separator	tar and	. 0 . <b>0</b>	16 2	0 6
	Foot of	er Square Purifying rea. s. d.			
3,780	Purifying House. Ground floor house with cellar and six purifiers 20 ft. square × 5 ft. deep, and litting apparatus for purifier lids, wood grids, one centre valve, two 4-way change valves, and all connections 18 in. diameter, complete.		6	0	0
1,260 400	House only, as above	10 6	2	0	Õ
4,800	pillars	3 4	0	12	6
1,780 300	for oxide of iron and lime	0 0 16 6	7	12 3	6 0
2,520	belting, and steam engine 0  Purifiers. Six vessels, 20 ft. square × 5 ft. deep in two sets. The first four with centre valve, and the two last with 4-way valves; with wood grids, lifting	2 6	0	9	6
	tackle for covers, and all connections . 1	1 0	4	0 2	0 F

Cost.	Description.	Cost I Cubic Fe (maxis produced	et of	Gas	
£		į	E s.	đ.	
500	Station Meter House, with accommodation for two station				
425	meters, and two station governors	C	16	0	
	and mountings, complete; capacity, 40,000 cubic feet per hour	c	13	6	
	Cost per 1000 Cubic feet Capacity.				
	£ s. d.				
5,040			8 0	0	
7,040	Gasholders, two in number, two-lift, telescopic, 120 feet diameter, 40 feet deep, capacity 480,000 cubic each, together 860,000 cubic feet, equal to 32 hours' (1½) days' production; with stand			-	
286	pipes and valves 8 0 0 Station Governors, 16-inch, two in number,	1	.1 3	6	
400	with bye-pass, connections, and valves.  Foundations of Apparatus throughout		0 7	6	
815	the works.  Connections, valves, and mains, throughout the works 16 in. diameter. Tar		0 12	6	
	pipes, water-pipes, &c		0 10		
65 1,700	Weighbridge at entrance		0 2	0	
1,100	and furnishing		2 14	0	
700	Boundary Wall, Drains, yard paving, and conveniences.		1 2	0	
21,000	Distributing Plant. Assuming that the outlay on mains, valves, syphons, and service pipes, amounts to 30 per cent. of the total capital expenditure, which is a fair				
500	average, then the cost will be.  Sulphate of Ammonia Apparatus, capacity 5 to 7 tons liquor per 24 hours and appurtenances; including two cast-iron purifiers, 10' 0" × 5' 0" × 5' 0", hydraulic change valve and wood roof on pillars, overhead liquor tank to hold 10 tons, lead-lined acid store tank, and acid	3	3 6	8	•
150 140 310 280	supply tank with elevator, pipes, taps, &c		0 16 0 12 0 4 0 10 0 9	6	; ;

Description.	Capital Amount.	Per- centag	e.	Cost per 1000 Tubic Feet of Gas (maximum) roduced per Day.
The Capital of, say, £70,000 would be dis- tributed as under.	£			£ s. d.
Land, law, parliamentary, and engineering expenses  Floating capital	6,300 4,900	9		10 0 0 7 15 6
Buildings (including a stage floor house, the brickwork of the retort stack, the gasholder tanks, tar wells, and founda-	2,500	,	••	7 10 0
tions of apparatus).  Apparatus and machinery (including the ironwork of retort stack, gasholders, and	22,400	82	••	85 11 0
the apparatus generally)	15,400	22		24 9 0
&c	21,000	80		88 6 8
Total	£70.000	100		111 2 2
Dividing the £70,000 Capital under the Heads of the Different Departments.  Land, law, parliamentary, and engineering				
expenses	6,300	9		10 0 0
Floating capital	4,900	7		
Manufacturing	16,100	23	•.•	25 11 0
washer scrubber, purifiers, &c.)	9,100	13		14 9 0
Storing	12,600	18		00 0 0
Storing	21,000	30		88 6 8
Total	£70.000	100	••	111 2 2

### MISCELLANEOUS.

### BRICKS AND BRICKWORK.

Usual Dimensions of Bricks.

9 inches long; 41 inches broad; 22 inches thick.

Weight of 1000 common clay bricks, about 31 tons.

Weight of 1000 fire-clay bricks, about 3½ tons.

805 common clay bricks weigh about 1 ton.

800 fire-clay bricks weigh about 1 ton.

32 bricks laid flat will pave one square yard.

52 bricks laid on edge will pave one square yard.

Number of bricks in a cubic yard, without mortar, 416.

Number of bricks in a cubic yard, with mortar, 384.

In England, brickwork is generally calculated by the square rod.

A rod of brickwork measures  $16\frac{1}{2}$  feet  $\times$   $16\frac{1}{2}$  feet  $\times$   $1\frac{1}{8}$  feet = 306 cubic feet, or  $11\frac{1}{3}$  cubic yards.

A rod of brickwork = 272 superficial feet,  $1\frac{1}{2}$  bricks, or  $19\frac{1}{2}$  inches thick, which is called the *standard* thickness.

Number of bricks in a rod of brickwork, allowing for waste, 4500.

To reduce brickwork from superficial feet of 9 inches thick to the standard thickness of  $18\frac{1}{2}$  inches, deduct one-third.

To reduce brickwork from cubic feet to superficial feet of the standard thickness of 13½ inches, deduct one-ninth.

To reduce brickwork from cubic feet to rods, divide by 306.

To reduce brickwork of more than 1½ bricks thick to superficial feet of the standard thickness of 13½ inches, multiply the area in feet by the number of half bricks in thickness, and divide the product by 3.

To reduce brickwork footings to superficial feet of the standard thickness of  $18\frac{1}{3}$  inches, multiply the length by the height of the courses, in feet, and the product by the number of half bricks in the mean breadth, and divide by 3. When the number of courses is odd, the number of half bricks in the middle course is the mean. When the number of courses is even, the mean breadth is found by taking half the sum of half bricks in the upper and lower courses.

#### Bond in Brickwork.

English bond is the strongest, and is a course of stretchers and a course of headers alternately, or one course of headers and one course of stretchers.

Flemish bond is a header and stretcher laid alternately in the same course.

Hoop-iron, when used as bond, should be well tarred and sanded, and bedded in Portland cement.

A rod of brickwork in ordinary buildings requires about-

1 cubic yard of lime.

23 cubic yards of sand.

A rod of brickwork in a gasholder tank requires about—

12 cubic yards of blue lias lime.

24 cubic yards of sharp river sand.

A rod of brickwork requires about-

13 cubic yards of Roman or Portland cement.

13 cubic vards of sharp river sand.

A cubic yard of quicklime . . . weighs about 1460 lbs.

,,	,,	blue lias quicklime	,,	,,	1470 "
,,	,,	Portland cement .	,,	,,	2416 ,,
,,	,,	Roman cement .	,,	,,	1700 ,,
		drag gand			9490

The above materials, when made into mortar, lose about one-third of their bulk.

### Fire-Clay.

The value of fire-clay consists chiefly in the proportion of the alumina to the fusible matter (viz., oxide of iron, and the alkalies of magnesia, potassa and soda, &c.) and to the silica; these being the principal ingredients of which it is composed. The larger the proportion of alumina to the fusible matter, the more refractory the clay. Of two clays containing alumina and fusible matter in the same proportions, that which contains the least silica is the more refractory.

The celebrated clays of Stourbridge, Newcastle-on-Tyne, different parts of Yorkshire, Scotland, and a few other places, are valuable in the manufacture of bricks, tiles, and retorts used in furnaces for the distillation of coal.

The table on next page will be found useful in this connection.

TABLE

Exhibiting the usual Constituents of the Chief English and Foreign Fire-Clays.

Locality.	Silice.	Alumina.	Peroxide of Iron.	Peroxide Peroxide of Man- Iron. ganese.	Phos. phate of Iron.	Lime.	Mag- nesia.	Potassa.	Boda.	Titanio Acid.	Water, Organic Matter, &c.	Total.
Stourbridge	65.87	98 · 48	99.9	:	:	83.	88.	1.26	8.	88.	:	ള
Plympton, Devonshire.	74.03	21.37	1.94	:	:	OF:	98.	1.82	8	:	:	8
Newoastle-on-Tyne	64.63	29.78	3.23	:	-:	.42	.41	1.09	-24	8	:	8
Burton-on-Trent	80.89	86.09	3.06	:	:	.65	.14	8.	1.88	:	:	8
Wortley, near Leeds .	65.25	29.71	8.07	:	:	07	.61	.43	1.13	.41	:	8
Derbyshire	48.08	86.89	3.56	:	:	:	:	1.88	:	:	10.89	8
Hedgerley, Bucks	84.65	8.86	4.26	:	:	1.90	8.	:	:	:	:	8
Poole, Dorsetshire	59.82	84.83	2.82	:	:	.48	83	8.33	:	:	:	8
Monmouthshire	75.30	16.80	1.00	:	:	8	:	:	:	:	8.9	8
Pembrokeshire	88.43	9	1.50	:	:	8.17	:	:	:	:	:	8
Dinas, Glamorganshire	97.62	1.40	•49	:	:	66.	:	97.	91.	:	:	8
Kilmarnock, Scotland .	58.92	98.66	2.49	:	:	68.	8.	1.14	1.08	:	:	8
Perceton, Scotland	62.20	86.00	8.	8	<u>ş</u>	99	8	:	:	:	:	8
Govan, Scotland	60.20	87 - 70	1.10	:	:	1.00	:	:	:	:	:	8
Етапов.	66.10	19.80	:	:	:	:	:	:	:	:	14.10	8
Невве	47.50	84.87	1:24	:	:	:	1.00	:	:	:	15.89	용
Bavaria	45.79	28.10	6.55	:	:	:	:	:	:	:	19.26	8

Authorities-Berthier, Cowper, Salvett, Muspratt, Richardson, Kitt, and Grover. • Windsor bricks.

### TABLES.

Showing the Number of Bricks in Walls of different Areas, from \( \frac{1}{4} \) a Brick up to 4 Bricks thick. Reckoned at 4500 Bricks to the Rod (272 feet super.), allowing for Waste.

TABLE I .- From 1 to 50 Superficial Feet.

Area of Wall. Sup.Feet.	h Brick on Bed.	1 Brick Thick.	Bricks Thick.	2 Bricks Thick.	24 Bricks Thick.	8 Bricks Thick.	84 Bricks Thick.	4 Bricks Thick.
1	6	11	17	22	28	33	39	44
2	ıĭ	22	33	44	55	66	77	88
3	17	33	50	66	83	99	116	132
3 4	22	44	66	88	110	132	154	176
5	28	55	83	110	138	165	198	221
6	33	66	99	132	165	199	232	265
ž	39	77	116	154	193	232	270	309
8	44	88	132	176	221	265	309	353
· 9	50	99	149	199	248	298	847	397
ıö	55	110	165	221	276	381	386	441
îĭ	61	121	182	248	803	864	425	485
12	66	132	199	265	831	397	463	529
13	72	143	215	287	858	480	502	574
14	77	154	232	309	886	463	540	618
15	83	165	248	831	414	496	579	662
16	88	176	265	353	441	529	618	706
17	94	187	281	375	469	568	656	750
18	99	199	298	397	496	596	695	794
19	105	210	814	419	524	629	783	838
20	110	221	881	441	551	662	772	882
21	116	232	347	463	579	695	811	926
22	121	243	864	485	607	728	849	971
23	127	254	881	507	634	761	888	1015
24	132	265	897	529	662	794	926	1059
25	132	276	414	551	689	827	965	1103
26	148	287	430	574	717	860	1004	1147
27	149	298	447	596	744	898	1042	1191
28	154	309	463	618	772		1081	1285
29	160	320	480	640	800	926 960	1119	1279
30	165	320 331	496	662	827	998	1158	1824
81	171	342		684	855	1026	1197	1368
82	171		518	706	882	1026	1235	1412
33	182	853 864	529 546	728	910	1099	1255	1456
34	188	375	568	750	938	1125	1313	1500
85	198	386	579	772	965	1158	1851	1544
86	195	397	596	794	998		1390	1588
87					1020	1191		1682
38	204	408	612	816 838	1020	1224	1428	1676
39	210	419	629			1257	1467	1721
40	215	430	645 662	860 882	1075	1290	1506	1765
41	221 <b>226</b>	441 452	678	904	1103 1131	1324	1544	1809
42						1857	1583	
43	232	468	695	926	1158	1390	1621	1853 1897
44 44	237	474 485	711	949 971	1186	1423	1660	1941
45	248		728	971	1213	1456	1699	
46	248	496	744		1241	1489	1737	1985
	254	507	761	1015	1268	1522	1776	2029
47	259	518	778	1037	1296	1555	1814	2074
48	265	529	794	1059	1324	1588	1853	2118
49	270	540	811	1081	1851	1621	1892	2162
50	276	551	827	1103	1379	1654	1930	2206

Showing the Number of Bricks in Walls of different Areas, from \(\frac{1}{2}\) a Brick up to 4 Bricks thick. Reckoned at 4500 Bricks to the Rod (272 feet super.), allowing for Waste.

TABLE II .- 51 to 100 Superficial Feet.

Area of Wall. Sup. Feet.	l Brick on Bed.	l Brick thick.	ll Bricks thick.	2 Bricks thick.	21 Bricks thick.	8 Bricks thick.	8j Bricks thick.	4 Bricks thick.
51	281	563	844	1125	1466	1688	1969	2250
52	287	574	860	1147	1484	1721	2007	2294
53	292	584	877	1169	1461	1754	2046	2338
54	298	596	893	1191	1489	1787	2085	2382
55	303	607	910	1213	1517	1820	2123	2426
56	309	618	926	1235	1544	1853	2162	2471
57	814	629	943	1257	1572	1886	2200	2515
58	320	640	960	1279	1599	1919	2239	2559
59	325	651	976	1301	1627	1952	2278	2603
RÖ	831	662	993	1823	1654	1985	2316	2647
61	836	678	1009	1846	1682	2018	2355	2691
62	842	684	1026	1368	1710	2051	2398	2785
63	847	695	1042	1890	1787	2085	2432	2779
63 64	858	706	1059	1412	1765	2118	2471	2824
65	858	717	1075	1434	1792	2151	2509	2868
66	864	728	1092	1456	1820	2184	2548	2912
67	369	739	1108	1478	1847	2217	2586	2956
68	375	750	1125	1500	1875	2250	2625	3000
69	881	761	1142	1522	1908	2283	2664	3044
70 H	886	772	1158	1544	1939	2316	2702	3088
71	392	783	1175	1566	1958	2349	2741	3132
72	397 1	794	1191	1588	1985	2382	2779	8177
73	403	805	1208	1610	2013	2415	2818	3221
74	408	816	1224	1632	2040	2449	2857	3265
75	414	827	1241	1654	2068	2482	2895	8809
76	419	838	1257	1676	2096	2515	2934	8853
77	425	849	1274	1699	2128	2548	2972	8897
78	480	860	1290	1721	2151	2581	3011	8441
79	486	871	1307	1743	2178	2614	3050	3485
8ŏ	441	882	1324	1765	2206	2647	3088	3529
81	447	898	1340	1787	2238	2680	3127	3574
82	452	904	1357	1809	2261	2718	3165	8618
88	458	915	1378	1831	2289	2746	3204	8662
84	463	926	1390	1859	2316	2779	3248	8706
85	469	988	1406	1875	2344	2813	8281	8750
86	474	949	1423	1897	2371	2846	3320	8794
87	480	960	1439	1919	2899	2879	8358	3838
88	485	970	1456	1941	2426	2912	8897	3882
89	491	982	1472	1963	2454	2945	8436	3926
90	496	993	1489	1985	2482	2978	3474	3971
91	502	1004	1506	2007	2509	8011	8518	4015
92	507	1015	1522	2029	2537	8044	8551	4059
93	513	1026	1539	2051	2564	8077	8590	4103
94	518	1037	1555	2074	2592	3110	3629	4147
95	524	1048	1572	2096	2619	3143	8667	4191
96	529	1059	1588	2118	2647	3176	8706	4285
97	535	1070	1605	2140	2675	8210	3744	4279
98	540	1081	1621	2162	2702	3243	8783	4824
99	546	1092	1688	2184	2730	3276	3822	4368
100	551	1108	1654	9206	2757	1 33 <b>0</b> 9	8860	4419

Showing the Number of Bricks in walls of different Areas, from \( \frac{1}{2} \) Brick up to \( 4 \) Bricks thick. Reckoned at \( 4500 \) Bricks to the Rod (272 feet super.), allowing for Waste.

TABLE III .- From 110 to 600 Superficial Feet.

Area of Wall. Sup. Feet.	d Brick on Bed.	1 Brick thick.	li Bricks thick.	2 Bricks thick.	2½ Bricks thick.	8 Bricks thick.	8½ Bricks thick.	4 Bricks
110	607	1213	1820	2426	3033	3640	4246	4853
120	662	1324	1985	2647	3309	3971	4632	5294
180	717	1434	2151	2868	3585	4301	5018	5735
140	772	1544	2316	3088	3860	4632	5404	6176
150	827	1654	2482	3309	4136	4963	5790	6618
160	882	1765	2647	3529	4412	5294	6176	7059
170	988	1875	2813	3750	4688	5625	6563	7500
180	993	1985	2978	3971	4963	5956	6949	7941
190	1048	2096	3143	4191	5239	6287	7335	8382
200	1108	2206	3309	4412	5515	6618	7721	8824
210	1158	2816	3474	4632	5790	6949	8107	9265
220	1213	2426	3640	4853	6066	7279	8493	9706
230	1268	2537	3805	5074	6342	7610	8879	10,147
240	1824	2647	3971	5294	6618	7941	9265	10,588
250	1879	2757	4136	5515	6893	8272	9651	
260	1484	2868	4301	5735	7169	8603	10,037	11,029
270	1489	2978	4467		7445	8934	10,423	11,471
280	1544	8088	4632	5956	7721	9265	10,809	11,912
290	1599	8199		6176	7996	9596		12,353
			4798	6397		9926	11,195	12,794
800	1654	8809	4963	6618	8272		11,581	13,235
310	1710	8419	5129	6838	8548	10,257	11,967	13,676
320	1765	8529	5294	7059	8824	10,588	12,353	14,118
330	1820	3640	5460	7279	9099	10,919	12,789	14,559
840	1875	8750	5625	7500	9875	11,250	18,125	15,000
350	1930	8860	5790	7721	9651	11,581	18,511	15,441
860	1985	3971	5956	7941	9926	11,912	13,897	<b>15,882</b>
370	2040	4081	6121	8162	10,202	12,243	14,283	16,32 <del>4</del>
880	2096	4191	6287	8382	10,478	12,574	14,669	<b>16,765</b>
890	2151	4301	6452	8603	10,754	12,904	15,055	17,206
400	2206	4412	6618	8824	11,029	13,235	15,441	17,647
410	2261	4522	6788	9044	11,305	13,566	15,827	18,088
420	2816	4632	6949	9265	11,581	13,897	16,218	18,529
480	2371	4743	7114	9485	11,857	14,228	16,599	18,971
440	2426	4853	7279	9706	12,132	14,559	16,985	19,412
450	2482	4963	7445	9926	12,408	14,890	17,371	19,858
460	2587	5074	7610	10,147	12,684	15,221	17,757	20,294
470	2592	5184	7776	10,368	12,960	15,551	18,143	20,785
480	2647	5294	7941	10,588	19,235	15,882	18,529	21,176
490	2702	5404	8107	10,809	18,511	16,213	18,915	21,618
500	2757	5515	8272	11,029	13,787	16,544	19,301	22,059
510	2813	5625	8438	11,250	14,063	16,875	19,688	22,500
520	2868	5735	8603	11,471	14,338	17,206	20,074	22,941
580	2923	5846	8768	11,691	14.064	17,537	20,460	23,382
540	2978	5956	8984	11,912	14,890	17,868	20,846	23,824
550	8083	6066	9099	12,132	15,165	18,199	21,232	24,265
560	9088	6176	9265	12,353	15,441	18,529	21,618	24,706
570	3143	6287	9430	12,574	15,717	18,860	22,004	25,147
580	3199	6897	9596			19,191		
590	8254			12,794	15,993		22,390	25,588
600	8309	6507 6618	9761 9926	18,015 18,235	16,268 16,544	19,522   19,853	22,776 23,162	26,029 26,471

Showing the Number of Bricks in Walls of different Areas, from \( \frac{1}{4} \) a Bricks up to 4 Bricks thick. Reckoned at 4500 Bricks to the Rod (272 feet super.), allowing for Waste.

TABLE IV .- From 610 to 2000 Superficial Feet.

Sup. Feet.         on Bed.         thick.         th	Bricks thick. 26,912 27,353 27,794 28,235 28,676 29,118 29,559 80,000 30,441 30,882
620         3419         6838         10,257         13,676         17,096         20,515         23,934         23,934         23,934         23,934         23,934         24,930	27,358 27,794 28,235 28,676 29,118 29,559 30,000 30,441 30,882
620         3419         6838         10,257         18,676         17,096         20,515         23,934         6           630         3474         6949         10,423         13,897         17,371         20,846         24,920         9           640         3529         7059         10,588         14,118         17,647         21,176         24,706         9           650         3585         7169         10,754         14,398         17,923         21,507         25,092         9           660         3640         7279         10,919         14,559         18,199         21,838         25,478           670         3695         7890         11,085         14,779         18,474         22,169         25,864	27,358 27,794 28,235 28,676 29,118 29,559 30,000 30,441 30,882
630	27,794 28,235 28,676 29,118 29,559 80,000 30,441 30,882
640 3529 7059 10,588 14,118 17,647 21,176 24,706 650 3585 7169 10,754 14,388 17,923 21,507 25,092 660 8640 7279 10,919 14,559 18,199 21,888 25,478 670 3695 7890 11,085 14,779 18,474 22,169 25,864	28,235 28,676 29,118 29,559 80,000 30,441 30,882
650   3585   7169   10,754   14,338   17,923   21,507   25,092   5   660   8640   7279   10,919   14,559   18,199   21,838   25,478   5   670   3695   7890   11,085   14,779   18,474   22,169   25,864   5   670	28,676 29,118 29,559 80,000 30,441 30,882
660   8640   7279   10,919   14,559   18,199   21,838   25,478   5670   3695   7890   11,085   14,779   18,474   22,169   25,864   5670   18,474   22,169   25,864   5670   18,474   22,169   25,864   5670   18,474   22,169   26,864   5670   18,474   22,169   26,864   5670   18,474   22,169   26,864   5670   18,474   22,169   26,864   5670   18,474   22,169   26,864   5670   18,474   22,169   26,864   5670   18,474   22,169   26,864   5670   18,474   22,169   26,864   5670   18,474   26,864   18,474   26,864	29,559 80,000 30,441 80,882
670   3695   7890   11,085   14,779   18,474   22,169   25,864   1	29,559 80,000 30,441 80,882
	30,441 30,882
680   3750   7500   11,250   15,000   18,750   22,500   26,250   3	80,882
	81,324
	81,765
	82,206
740   4081   8162   12,243   16,324   20,404   24,485   28,566	82,647
	33,088
760   4191   8382   12,574   16,765   20,956   25,147   29,338	33,529
770   4246   8493   12,739   16,985   21,232   25,478   29,724	33,971
780   4901   8603   12,904   17,206   21,507   25,809   30,110	34,412
790   4857   8713   13,070   17,426   21,783   26,140   30,496	84,853
800   4412   8824   18,235   17,647   22,059   26,471   30,882	85,294
810   4467   8934   13,401   17,868   22,835   26,801   31,268	35,735
820   4522   9044   13,566   18,088   22,610   27,132   81,654	86,176
830   4577   9154   13,732   18,309   22,886   27,463   32,040	86,618
840   4632   9265   13,897   18,529   23,162   27,794   82,426	87,059
850   4688   9375   14,063   18,750   23,438   28,125   32,818	87,500
860   4743   9485   14,228   18,971   23,713   28,456   33,199	87,941
970   4798   9596   14,393   19,191   23,989   28,787   33,585	38,382
880   4853   9706   14,559   19,412   24,265   29,118   88,971	38,824
890   4908   9816   14,724   19,682   24,540   29,449   84,857	39,265
900    4963   9926   14.890   19,858   24,816   29,779   <b>84,748</b>	89,706
910   5018   10,037   15,055   20,074   25,092   30,110   35,129	40,147
920   5074   10,147   15,221   20,294   25,368   30,441   35,515	40,588
930   5129   10,257   15,386   20,515   25,648   30,772   85,901	41,029
940   5184   10,368   15,551   20,785   25,919   81,108   86,287	41,471
950   5239   10,478   15,717   20,956   26,195   31,434   37,678	41,912
960   5294   10,588   15,882   21,176   26,471   31,765   37,059	42,358
970    5349   10,699   16,048   21,397   26,746   82,096   87,445	42,794
980   5404   10,809   16,213   21,618   27,022   32,426   37,881	43,235
990   5460   10,919   16,379   21,838   27,298   32,757   38,217	43,676
1000   5515   11,029   16,544   22,059   27,574   83,088   38,608	44,118
1100   6066   12,132   18,199   24,265   30,331   36,397   42,463	48,529
1200   6618   13,235   19,853   26,471   83,088   89,706   46,324	52,941
1300   7169   14,338   21,507   28,676   35,846   43,015   50,184	57,358
1400   7721   15,441   23,162   30,882   38,603   46,324   54,044	61,765
1500   8272   16,544   24,816   33,088   41,360   49,682   57,904	66,176
1600   8824   17,647   26,471   35.294   44,118   52,941   61.765	70,588
1700   9375   18,750   28,125   37,500   46,825   56,250   65,625	75,000
1800 9926 19,853 29,779 89,706 49,632 59,559 69,485	79,412
1900   10,478   20,956   31,484   41,912   52,390   62,868   78,846	88,824
2000   11,029   22,059   38,068   44,118   55,147   66,176   77,206	88,235

Showing the Number of Bricks in Walls of different Areas from \( \frac{1}{2} \) a Brick up to 4 Bricks thick. Reckoned at 4500 Bricks to the Rod (272 feet super.), allowing for Waste.

TABLE V.—From 2100 to 250,000 Superficial Feet.

rea of Wall. Sup. Feet.	Brick on Bed.	1 Brick thick.	1½ Bricks thick.	2 Bricks thick.	2½ Bricks thick.	3 Bricks thick.	31 Bricks thick.	4 Bricks thick.
2100	11,581	23,162	34,743	46,324	57,904	69,485	81,066	92,64
2200	12,132	24,265	86,897	48,529				97,08
2300	12,684	25,368	38,051	50,735	63,419	76,103		101,47
2400	13,235	26,471	39,706	52,941	66,176	79,412		105,88
2500	13,787	27,574	41,360	55,147		82,721		110,29
2600	14,338	28,676	43,015	57,353		86,029		114,70
2700	14,890	29,779		59,559				119,1
2800	15,441	30,882	46,324	61,765		89,338		128,5
2900	15,998	31,985	47,278	63,971		92,647		127,9
3000	16,544	33,088	49,632			95,956	111,949	132,8
3100	17,096		51,287			99,265	115,809	136,7
		34,191		68,382		102,574		
3200	17,647	35,294		70,588		105,882		141,1
3300	18,199		54,596					145,5
3400	18,750							150,0
3500	19,301	38,603			96,507	115,809		154,
3600	19,853							158,8
3700	20,404					122,426	142,831	168,5
3800	20,956				104,779	125,738	146,691	167,6
3900	21,507			86,02	107,537	129,044	150,551	172,0
4000	22,059		66,176	88,235		132,353		176,4
4100	22,610	45,221	67,831	90,441				180,8
4200	23,162							185,2
4300	23,713							189,7
4400	24,265					145,588		194,1
4500	24,816				124,081			
4600	24,368				126,838			198,5
4700	25,919							202,9
4800	26,471	52,941						207,8
4900	27,022	54,044						211,7
5000	27,574							216,1
10,000	55,147							220,5
15,000	82,721	110,294						
20,000		165,441	248,162					661,7
	110,294	220,588				661,765		882,8
25,000	137,868	275,735		100000000000000000000000000000000000000				1,102,9
30,000	165,441	330,882				992,647	1,158,088	1,323,5
35,000	193,015	386,029				1,158,088	1,351,103	1,544,1
40,000	220,588	441,176		882,353	1,102,941	1,323,529	1,544,118	1,764,7
45,000	248,162	496,324		992,647	1.240,809	1.488.971	1.737.132	1,985,2
50,000	275,735	551,471	827,206	1,102,941	1,378,676	1,654,412	1,930,147	2 205 8
55,000	303,309	606,618	909,926	1,213,235	1,516,544	1,819,753	2.123.162	2,426,4
60,000	330,882	661,765	992,647	1.323.529	1.654.412	1.985.294	2.316.176	2,647,0
65,000	358,456	716,912	1,075,368	1.433.824	11.792.279	[2.150.735]	2.509.191	9 867 6
70,000	386,029	772,059	1,158,088	1,544.118	11.930.147	2.316.176	12.702.206	3,088,
75,000	413,603	827,206	1,240,809	1.654.412	2:068.015	2.481.618	2 895 921	3,308,8
80,000	441,176	882,353	1,323,529	1,764,706	2.205.889	2.647.059	13.088.235	9 500 4
85,000	168,750	937,500	1,406,250	1,875,000	2.343.750	2.812.500	3,281,250	3,750,0
90,000	496,324	992,647	11.488.971	1.985.294	12 481 618	9 977 941	13 474 265	0 070 1
95,000	523,897	1,047,794	1,571,791	2.095 589	2 619 495	3 149 990	3,667,279	4.101
100,000	551,471	1.102.941	1.654.419	2.905.980	0.757.950	3 308 60	3,860,294	4,191,
150,100	827,206	1.654.410	2 481 618	2 308 804	4 196 000	4 000 000	5,790,441	4,411,
200,000	1.102.941	2 905 880	3 309 804	4.411.765	5 514 700	e e 17 e 4	7,720,588	6,617,6
	1,378,676	4,200,002	0,000,024	3,411,760	0,014,700	0,017,04	1,720,000	8,823,

### MORTAR AND CONCRETE.

### Mortar.

		MI	or ca	<i>'</i> .						
									By Measu	re.
Lime									1 part	
Sharp river sand.									3 part	s.
									•	
			or,							
Lime									1 part	
Sand									2 part	s.
Blacksmith's ashes	or	clin	ker.	gro	und	1.			1 part	
	_								•	
	15		. м	orta	r					
	( ()	u i se	101	or ia	<b>,</b> .					
Lime									1 part	
Coarse sand									4 part	s.
									•	
Hu	drau	lic	Lin	ie N	Tort	ar.				
113		•••								
Best blue lias lime									1 part	i.
Clean sharp river s										
-										
			or,							
Best blue lias lime						•		•	1 part	
Burnt clay					•				2 part	s.
			or,							
Best blue lias lime										
Puzzolana										
Clean sharp sand.	•	•	•	•	•	•	•	•	6 part	s.
	Cer	men	t M	orta	ır.					
									_	
Cement, Portland									_	
Clean sharp sand.	•	•	•	٠	•	•	•	•	3 par	ts.

The lime should be fresh burnt, and not more than sufficient of the mortar for a day's work prepared at once. The cement mortar should only be made as it is being used.

Con	crete.				
Blue lias lime concrete (for foun	dations)	<b></b> -		Ву	Measure.
Gravel, shingle, broken stone,	bricks,	or old	l ret	orts,	
1½ to 2 inches cube			•	. 6	parts.
Clean sharp sand					
Blue lias or other hydraulic li					
Portland cement concrete (for ta					_
Gravel, shingle, broken stone,			l ret	orts,	
1½ inches cube					7 parts.
Clean sharp sand					
Portland cement					_
Mastic Cement	for Bu	ilding	8.		
1 part red lead.	ĺ	1	art	red l	ead.
5 parts ground lime.		5 լ	arte	whi	ting.
5 parts sharp sand	1	10	parts	sha	rp sand.
Mix with boiled linseed oil.	Mi	_	-		inseed oil.
	<b>'.</b>				•

Clean sharp sand (not having its particles rounded by attrition) should always be used in the composition of mortar when it can be procured; but, otherwise, clean well-burnt ashes may be substituted.

In preparing ordinary mortar it is desirable to mix a small proportion of smithy ashes with the lime and sand. On this subject Mr. Graham Smith remarks ("Engineering Papers," p. 20): "The importance of the admixture of ashes with mortar to be atmospherically dried will be shown by the following results:—The bricklayers' mortar, with common bricks, after a lapse of 84 days, broke with 570 lbs.; when sand was substituted in place of ashes—that is, when the proportions were 1 slaked lime, 2 sand, and no ashes—it only required 257 lbs. to tear asunder the bricks. These are the averages of three experiments. This is no doubt attributable to the ashes being porous; they thus allow greater facilities for the absorption of carbonic acid from the atmosphere."

The more sand that can be incorporated with the lime, the better the mortar, provided the necessary degree of plasticity is preserved.

A load of mortar is equal to one cubic yard.

A hod of mortar measures 9 in.  $\times$  9 in.  $\times$  14 in.

Two hods of mortar are nearly equal to a bushel.

The mortar in a rod of brickwork (4500 bricks) is taken at 1½ cwt. of chalk lime and 2 loads of sand, or 1 cwt. of stone lime and 2½ loads of sand.

### Handy Multiplier for Wrought-Iron.

If the area in square inches of the cross section of any specimen of wrought iron be multiplied by 8.34, the product will be the weight in pounds of a lineal foot of such specimen.

FLAT BAR IRON.—Weight in lbs. of a Lineal Foot.

Breadth			1	hickness	in Parts	of an Inc	h.		
in Inch <b>es.</b>	1-4th.	5-16ths.	8-8ths.	7-16ths.	1-half.	5-8ths.	8-4 <b>t</b> hs.	7-8ths.	1
1	•835	1.044	1.253	1.461	1.670	2.088	2.506	2.923	3.340
11	.989	1.174	1.409	1.644	1.878	2.348	2.818	8 · 287	3.756
$1\frac{\hat{i}}{4}$	1.044	1 305	1.566	1.826	2.088	2.609	8 · 132	8.658	4.176
13	1.148	1 · 435	1.722	2.009	2.296	2.870	8.444	4.018	4.592
1 👸	1.252	1.566	1.879	2.192	2.504	8.181	3.758	4.884	5.008
14	1.358	1.696	2.085	2.374	2.716	3.892	4.070	4.749	5.432
17	1.462	1.827	2.192	2.557	2.924	8.653	4.384	5.114	5.848
17	1.566	1.957	2.348	2.740	3.132	8.914	4.696	5.479	6.264
2	1.671	2.088	2.505	2.922	8.842	4.175	6.010	5.845	6.684
21	1.775	2.218	2.662	3 · 105	8.550	4.485	5.324	6.210	7.100
2 <del>1</del>	1.880	2.348	2.818	3 · 288	3.760	4.696	5.636	6.575	7.520
2	1.984	2.479	2.975	8.470	8.968	4.957	5.950	6.941	7.936
2 }	2.088	2.609	3.131	3.653	4.176	5.218	6.262	7.306	8.352
2 å	2.193	2.740	3.288	8.836	4.386	5.479	6.576	7.671	8.772
27	$2 \cdot 297$	2.870	3.444	4.018	4.594	5.740	6.888	8.036	9.188
27	$2 \cdot 402$	8.001	3.601	4.201	4.804	6.001	7 · 202	8.402	9.608
8	2.506	8.181	3.758	4.884	5.012	6.262	7.516	8.767	10.024
31	2.715	3 392	4.071	4.749	5.430	6.784	8.142	9.498	10.860
8 <u>i</u>	2.928	3.653	4.384	5.114	5.846	7.306	8.768	10.228	11.692
82	$8 \cdot 182$	3.914	4.697	5 479	6.264	7.828	9.894	10.959	12.528
4	3.341	4.175	5.010	5.845	6.682	8.350	10.020	11.690	13.364
41	3.549	4 · 486	5.323	6.210	7.098	8.871	10.646	12.421	14.196
4į	3.758	4.697	5.636	6.575	7.516	9.393	11.272	13.151	15.032
47	3.966	4.958	5.949	6.941	7.932	9.915	11.898	13.881	15.864
5	4.175	5.219	6.263	7.806	8.350	10.487	12.526	14.612	16.700
54	4.384	5.479	6.576	7.671	8.768	10.958	13.152	15.348	17.536
5]	4.593	5.741	6.889	8.037	9.186	11.480	13.778	16.073	18.372
54	4.801	6.001	7.202	8.402	9.602	12.002	14.404	16.804	19.204
6	5.010	6.262	7.515	8.767	10.020	12.524	15.030	17.535	20.042

ROUND BAR IRON.—Weight in lbs. of a Lineal Foot.

Diameter in Inches.	Weight in lbs.	Diameter in Inches.	Weight in lbs.	Diameter in Inches.	Weight in lbs.	Diameter in Inches.	Weight in lbs.
1	•040	15	6.870	81	25 · 400	44	55.640
į.	·163	12	7.970	3₹	27 · 475	44	58 • 688
¥	.363	11	9.150	88	29 · 625	47	61.820
į	•650	2	10.406	81	81.870	5	65 • 040
š	1.006	24	11.750	8 <u>1</u> 8 <u>1</u>	84 · 175	51	68 - 330
ä	1.456	21	18 106	8	<b>36 · 575</b>	51	71.700
ž	1.990	23	14.670	' 8 į	39.056	5	75 150
1"	2.590	21	16 256	4	41.620	5 į	78·700
~ · 14	3.300	24	17 · 925	41	44.260	54	82.300
14	4.070	23	19.600	4 4	46 · 990	54	86.006
17	4.920	21	21 · 500	48	49.790	51	89.800
1 ]	5.860	8 '	28 · 406	4.	52 · 675	6	98.650

# SQUARE BAR IRON.

Weight in lbs. of a Lineal Foot.

Side in Inches.	Weight in lbs.	Side in Inches.	Weight in lbs.	Side in Inches.	Weight in lbs.	Side in Inches.	Weight in lbs.
ł	.052	12	8.82	81	82.72	41	71.60
Ĭ	•208	12	10.28	81	85.28	4#	75.36
i	•469	12 12	11.74	8	88.16	4 <del>2</del> 43	79.54
i	-832	2 ຶ	13.86	81	40.92	5	83.44
i	1.304	21	15.08	84	44.01	54	87.90
â	1.876	24	16.91	8	46.96	51	92.40
ž	2.557	2	18.84	87	50.38	5	96.67
1°	8.340	21	20.86	4	58.44	5 4	101.04
Īı	4.227	2	23.10	41	56.97	5	105.87
īį	5.216	28	25.25	41	60.32	54	110.80
1	6.314	2) 2)	27.70	41 43	64.08	53	115.48
îį	7.504	8	80.02	41	67.64	6	120.08

### SHEET IRON AND STEEL.

Weight of a Superficial Foot in Pounds and Fractions, with Corresponding Number and Thickness of Birmingham Wire Gauge.

No. of Birmingham Wire Gauge.	Thickness in Parts of an Inch. Board of Trade	Squa	ht per re Foot lbs.	No. of Birmingham Wire Gange.	Thickness in Parts of an Inch. Board of Trade	Weight per Square Foot in lbs.		
	Standard.	Iron.	Steel.		Standard.	Iron.	Steel.	
. 1	•300	12.00	12:240	19	·041	1.64	1.673	
ā	•284		11.587	20	·035	1.40	1.428	
2 3	•260		10.608		082	1.28	1.306	
4	•238		9.710	22	028	1.12	1.142	
5	•220	8.80		23	.025	1.00	1.020	
<u>6</u> ·	•203	8.12			022	0.88	0.898	
7	·180	7.20		25	.020	0.80	0.816	
Ŕ	•165	6.60		26	·018	0.72	0.734	
4 5 6 7 8 9	•148	5.92			·016	0.64	0.653	
10	·135	5.40		28	•014	0.56	0.571	
îĭ	•120	4.80			.013	0.52	0.530	
12	·109	4.86			012	0.48	0.490	
13	.095	3.80			·010	0.40	0.408	
14	.083	3.32			-009	0.36	0.367	
15	.072	2.88			•008	0.32	0.326	
16	•065	2.60			·007	0.28	0.286	
17	•068	2.32			.005	0.20	0.240	
18	000	2.00			•004	0.16	0.163	

At a Special Meeting of the Iron Trade, held on February 28, 1896, it was resolved that the Standard of Measurement for Iron of all descriptions shall in future be the Birmingham Gauge. It was

further decided that the annexed table of decimal equivalents be adopted as corresponding with the number on the Gauge.

	No. B. G.		Decimal Equival'nts of an Inch.	No. B. G.	Frac- tions of an Inch.	Decimal Equival'nts of an Inch.	
	000	3	•5	14		.0785	`
( )	00		•4452	15		0699	1
1.	0		·3964	16	1,9	.0625	l .
i i	1		.3532	17		.0556	1
}	2		.8147	18		.0495	1
Plates	1 2 3		2804	19		·044	1
1 '		1	·25	20		·0392	1
1 1	4 5	.:	· 2225	21		.0349	1
į.	6		·1981	22	3 g	03125	Sheets
	7		.1764	23	**	0278	1
ſ	8		.157	24		.0247	l l
- 1	8 9		1398	25	::	.022	1
Sheets -!	10	i i	125	26		.0196	1
	11		·1113	27		0174	1
	12		.0991	28	9,4	015625	1
C)	13		.0882	29	***	.0189	1
	10	••	, 3332	30		0123	,

### STEEL.

# Weight of One Foot of Round Steel.

Diameter in Inches.	ł	8	1	8	2	3	1	11	11	18	11	18	12	15	2
Weight per Foot in lbs.	·167	•373	•669	1.04	1.05	2.05	2·67	3.38	4.18	5.06	6.02	7.07	8.2	9•41	11·71

# WEIGHT IN POUNDS OF A SUPERFICIAL FOOT OF IRON, COPPER, AND BRASS.

Thickness by the Birming- ham Wire	Iron.	Copper.	Brass.	Thickness by the Birming- ham Wire	Iron.	Copper.	Brass.
Gauge.	108.	108.	108.	Gauge.	108.	108.	108.
1	12.50	14.50	13.75	16	2.50	2.90	2.75
2	12.00	13.90	13.20	17	2.18	2.52	2.40
2 3	11.00	12.75	12.10	18	1.86	2.15	2.04
	10.00	11.60	11.00	19	1.70	1.97	1.87
5	8.74	10.10	9.61	20	1.54	1.78	1.69
4 5 6 7	8 · 12	9.40	8.93	21	1.40	1.62	1.54
7	7.50	8.70	8.25	22	1.25	1.45	1.87
. 8	6.86	7.90	7.54	23	1.12	1.30	1.28
9	6.24	7.20	6.86	24	1.00	1.16	1.10
10	5.62	6.20	6.18	25	.90	1.04	.99
11	5.00	5.80	5.50	26	.80	.92	-88
12	4.38	5· <b>0</b> 8	4.81	27	.72	-83	.79
13	3.75	4.34	4.15	28	•64	.74	.70
14	3.12	3.60	3.43	29	•56	64	·61
15	2.82	3 · 27	3.10	30	•50	•58	• 55

# WEIGHT OF A SUPERFICIAL FOOT OF VARIOUS METALS.

Thickness in Inches.	Wrought Iron.	Cast Iron.	Steel.	Copper.	Brass.	Lead.	Zino.	Thickness in Inches.
	lbs.	lbs.	lbs.	lbs.	lbs.	lbs.	lbs.	
1-16th.	2.528	2.844	2.552	2.891	2.374	3.708	2.344	1-16th.
1-8 <b>t</b> h.	5.052	4.687	5.104	5.781	5 · 469	7.417	4.687	1-8th.
3-16ths.	7.578	7.031	7 · 656	8.672	8.308	11.125	7.031	3-16ths.
1-4th.	10.104	9.375	10.208	11.568	10.988	14.883	9.875	1-4th.
5-16ths.	12.680	11.719	12.760	14.458	81.672	18.542	11.719	5-16ths.
8-8ths.	15.156	.14.062	15.812	17.844	16 · 406	22 · 250	14.062	3-8ths.
7-16ths.	17.682	16.406	17.865	20.234	19.141	25 · 958	16.406	7-16ths.
1-half.	20.208	18.750	20.417	28 · 125	21.875	29.667	18.750	1-half.
9-16ths.	22.784	21.094	22.969	26.016	24 · 609	33.375	21.094	9-16ths.
5-8ths.	25 260	28 · 437	25.521	28.906	27 · 844	87.083	23 · 487	5-8ths.
11-16ths.	27.786	25.718	28.073	31.797	80.078	40.792	25.781	11-16ths.
8-4ths.	30.812	28 · 125	30.625	34 688	82.818	44.500	28 · 125	3-4ths.
18-16ths.	82.889	30.469	88 · 177	87.578	85 • 547	48 208	80.469	13-16ths.
7-8ths.	85 865	82.812	85.729	40.469	88 · 281	51.917	82.812	7-8ths.
15-16ths.	37.891	85 · 156	88.281	43.859	41.016	55 625	85 · 156	15-16ths.
1 inch	40.417	87.500	40.888	46 250	48.750	59.888	37.500	1 inch.

# WEIGHT IN PARTS OF A POUND OF A SPHERE IN. DIAM. OF VARIOUS METALS.

Brass Bronze.	Copper Hammered.	Iron Cast.	Iron Wrought.	Steel.	Lead.	Tin.	Zinc.
156 159	·167	·135	·145	·147	·214	·189	·183

# HOOP IRON.

Weight of 10 Lineal Feet.

Width in Inches and Parts.	å	1	7	1	11	11	13	13	12	2	21	21	23	8
No. of Gauge .	21	20	19	18	17	16	15	15	14	18	13	12	11	11
Weight in lbs. & Decimal Parts.	· <b>68</b> 5	·885	1 · 24	1.60	2.05	2.78	3.40	3·72	4.72	6.06	6.83	8.96	10·85	11.84

# TAPER ANGLE IRON, OF EQUAL SIDES.

Length of Sides in Inches.	Thickness of Edges.	Thickness of Root.	Weight of One Lineal Foot in lbs. and Decimal Parts.
4 3 24 24 21 2 14	in.  in.  in.  in.  in.  in.  in.  in.	å in.  †  fr  fr  fr  fr  fr  fr  fr  fr  fr	14·0 10·375 8·25 6·5 5·0 3·875 3·25 2·625

### TAPER T-IRON.

Width of Top Table in Inches.	Total Depth in Inches.	Thickness of Top Table at Root.	Thickness of Top Table at Edges.	Uniform Thickness of Rib.	Weight of One Lineal Foot in lbs.
3 3 2 2 3 3	34 26 3 21 11 11	din. Te Te te te te te te	\$ in. \$ 25 \$ 25 \$ 26 \$ 4	175 in. 22 176 2 full 3	8·0 8·0 5·25 6·5 3·5 2·875

### WEIGHT OF CORRUGATED IRON ROOFING.

B.W. Gauge.	Size of Sheets.	Per Square.	Super. Feet per ton.
16	6 feet × 2 feet to 8 feet	$\times$ 3 feet $\times$ 31 cwt.	800
18	6 ,, × 2 ,, 8 ,,	× 3 ,, × 2‡ ,,	1000
20	6 ", × 2 ", 8 ",	× 8 ,, × 1¾ ,,	1250
22	6 " × 2 " 7 "	$\times$ 2½ ,, $\times$ 1½ ,,	1550
24 `	6 ,, × 2 ,, 7 ,,	$\times$ 2½ ,, $\times$ 1½ ,,	1880
26	6 , × 2 , 7 ,	× 2½ ,, × 1 ,,	2170

# WEIGHT IN POUNDS OF NUTS AND BOLT-HEADS.

Diameter of Bolt in Inches.	ŧ	3		8	3	7 8	1	11	13	12	2	23	8
Weight of Hexagon Nut and Head.	·017	.057	·128	•267	•430	•730	1 · 10	2·14	<b>3·7</b> 7	5.62	8.75	17·2	<b>2</b> 8·8
Weight of Square Nut and Head.	· <b>02</b> 1	· <b>0</b> 70	•164	·321	•553	·88 <b>2</b>	1.81	2·56	4 · 42	7· <b>0</b> 0	10 · 50	21 ·0	36·4

# WHITWORTH'S SCREWS WITH ANGULAR THREADS.

Diameter in Inches.	Number of Threads per Inch.	Diameter in Inches.	Number of Threads per Inch.	Diameter in Inches.	Number of Threads per Inch.
# 10 + 4 F	40 24 20 18 16 14 12 11 10 9 8 7	18 h 4 7 1 1 2 2 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2	6 6 5 5 4 4 4 4 4 4 4 4 4 4 3 3 4 4	3 5 1 5 1 5 5 5 5 5 6	8± 8± 8± 8± 8± 8± 8± 8± 8± 8± 8± 8± 8± 8

Angle of threads 55° in every instance.

The threads do not intersect at their sides, but are rounded off one-sixth both at top and bottom, making their depth equal to twothirds of the pitch.

The number of threads to the inch in square-threaded screws is generally half the number of those in angular-threaded screws, and the depth equal to the space between the threads.

## WEIGHT OF CHAINS.

Diameter of	Weight per	Diameter of	Weight per	Diameter of	Weight per
Link	Lineal Foot	Link	Lineal Foot	Link	Lineal Foot
in inches.	in lbs.	in inches.	in lbs.	in inches.	in lbs.
10 4 40 10 20 10 20 10 41	·38 ·63 ·91 1·38 1·50 2·38 8·00 8·67 4·50	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5·38 6·16 7·16 8·16 9·38 10·50 11·88 13·16 14·50	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	16:00 17:66 19:25 20:83 24:17 28:33 82:50 88:83

To Find the Safe Load on Chains.

 $\sqrt{\frac{(\text{Diam. of link in eighths of an inch})^2}{8}}$  = safe load in tons.

 $(8 \times \text{weight to be raised}) = \text{diam. of link in eighths of an inch.}$ 

# WEIGHT AND STRENGTH OF ROUND ROPES OF HEMP AND WIRE.

	Hemp.			Iron Wire.			Steel Wire.	
Girth or Circum- ference in Inches	Weight per Fathom of Six Feet in lbs.	Weight	Circum-	Weight per Fathom of Six Feet in lbs.	Weight	Circum-	Weight per Fathom of Six Feet in lbs.	Weight
1 1 1 2 2 2 2 2 3 3 4 4 5 5 6 6 6 7 7 5 8 8 5 9 9 10 10 10 10 10 10 10 10 10 10 10 10 10	15 -26 -25 -25 -25 -25 -25 -25 -25 -25 -25 -25	11122234 56784 911244 110222 11244 11022 1224	*11112222222235888888444444444444444444444444	-56 1 1 2 2 4 3 4 4 3 5 5 6 6 7 7 4 8 8 9 10 112 13 14 15	114 34 44 55 66 67 84 104 114 113 114 118 118 118 118 118 118 118 118 118	1 14 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 11 12 12 12 12 12 12 12 12 12 12 12 12	2½ 3½ 44 45½ 6½ 7½ 10 11½ 112½ 15½ 172 19 22½ 22½ 30½ 30½ 40
11½ 12	34·38 37·44	261 29	48 44 5 5 6	16 18 20 25 32 38	26# 30# 32 38 45# 54			ı

To find the Breaking Weight of Round Ropes of Hemp, Iron Wire and Steel Wire.

Hemp  $\frac{(\text{circum. ins.})^2}{5}$  = breaking weight in tons.

Iron wire (circum. ins.)<sup>2</sup>  $\times$  1.5 = breaking weight in tons. Steel wire (circum. ins.)<sup>2</sup>  $\times$  2.5 = breaking weight in tons.

Factor of safety for hemp, iron, and steel ropes =  $\frac{1}{6}$ .

To find the Weight of Hemp Ropes.

(Circum. ins.)<sup>2</sup>  $\times$  26 = weight in lbs. per fathom.

### ALLOYS OF METALS.

Yellow brass, 2 parts copper, 1 zinc.

Rolled brass, 82 parts copper, 10 zinc, 1.5 tin.

Brass casting, common, 25 parts copper, 2 zinc, 4.5 tin.

Gun metal, 8 parts copper, 1 tin.

Copper Flanges for pipes, 9 parts copper, 1 zinc, 0.26 tin.

Bell metal, 8 parts copper, 1 tin.

### IRON TO RESIST THE ACTION OF FIRE.

The following mixture of iron is recommended for fire bars, furnace plates, gas retorts (iron) and any other ironwork required to resist the action of fire:—

80 per cent. Ridsdale.

20 per cent. Siemens Steel Scrap.

This is said to make a kind of pyrostatic iron, the high fusion point being due to the small percentage of carbon present in the mixture.

TABLE
Of the Velocity and Force of the Wind.

Miles per Hour.	Feet per Second.	Pressure in lbs. per Square Foot.	Description.
1	1.47	· 006	Hardly perceptible.
2	2·98	·020	Just perceptible.
3	4·4	·044	
4	5·87	·079	Gentle breeze.
5	7·38	·123	
10 15	14·67 22·0	1.107	Pleasant breeze.
20	29.34	1.968	Brisk gale.
25	36·67	3·076 j	High wind.
30	44·01	4·429 j	
35	51·34	6·027 j	
40	58·68	7·873 j	
45	66·01	9.996	Very high wind.
50	78·85		Storm or tempest.
60	88.02	17.718,	Great storm.
70	102·71	24·153 }	Hurricane.
80	117·86	81·490 ;	
100	146.7	49.200	TTALLICANO.

The pressure or force of the wind is as the square of its velocity.

The square of the velocity of the wind in feet per second  $\times$  .002288 = pressure in lbs. per square foot.

The wind pressure upon a cylindrical surface is one-half, and on a spherical surface one-fourth that which is exerted on a flat surface.

# SPECIFIC GRAVITY AND WEIGHT OF VARIOUS SUBSTANCES.

Name of Substance.	Specific Gravity and Weight per Cb. Ft. in Ounces.	Weight per Cub.Foot in lbs.	Name of Substance.	Specific Gravity and Weight per Cb. Ft. in Ounces.	Weight per Cub.Foot in lbs. Avoirdu- pois.
Alcohol, pure	790	49.38	Gold, pure	19,360	1,210
Ash (timber)	752	47	,, standard	17,728	1,108
Asphalt, prepared	2,496		Granite	2,688	168
Basalt	2,992		Gravel	1,840	115
Bath stone	1,792		Grindstone	2,096	181
Beech	688		Gun metal	8,784	549
Birch	704		Gypsum	2,804	144 56·75
Bitumen	992 960		Ice	908	448
Boxwood	8,240		Iron, cast	7,168 7,680	480
Brass, cast	8,480		Lead	11,392	712
Brick	2,080	130	, white	8,168	198
Brickwork	1,792		Limestone, lias	2,496	156
Cement, Portland	1,424	89	", magnesian.		178
Roman	960	60	Lime, quick	864	54
Chalk	2.368	148	Mahogany, Honduras .		40
Charcoal, Oak	836	21	Spanish .	720	45
Clay	1,920	120	Maple	784	49
Clay puddle	2,560		Marble	2,720	170
Coal, anthracite, solid .	1,280		Marl	1,728	108
" bituminous	1,200	75	Masonry	2,240	140
,, cannel, Scotch	1,248	78	Mercury	18,584	849
" " Wigan	1,280	80	Mortar	1,760	110
", ", N'castle	1,812	82	Mud	1,600	100
,, stored in usual }	832	52	Naphtha	848	58
way	-		Oak, English	800	50
Coke from coking	800	50	" American, red	864 944	54
ovens			Oil, linseed	912	59 57
,, irom gas-works ; slaked	515	32·2	" olive	928	58
Amore man manha i			" sperm	880	55
unslaked	448	28	" tallow	896	56
Concrete	1.920	120	", colza	912	57
Copper, cast	8.640	540	Paving.	2.560	160
, sheet and wire .	8,800	550	Peat	1,280	80
Cork	240	15	Pebble stone	2,704	169
Earth, loam	1,600		Petroleum	880	55
Zbony	1,200		Pitch	1,152	72
31m	560	85	Platinum, pure	19,520	1,220
Fir, red pine and spruce	560	85	" hammered .	20,480	1,280
"American	464	29	,, wire	20,800	1,300
" larch	544		Portland stone	2,096	131
Fire-Clay, natural burned in blocks	2,400		Quartz	2,640	165
lag, Yorkshire	2,080 2,288	148	Sand, damp	1,888	118 90
Plint	2,200		"dry	1,440   2,528	90 158
reestone	2,240		Shale	2,592	162
lass, crown	2,496		Shingle	1,520	95
plate	2,880		Silver, pure	10,480	655
flint.	2,992	187	" standard	10,528	658

# SPECIFIC GRAVITY AND WEIGHT OF VARIOUS SUBSTANCES—Continued.

Name of Substance.						Sp. Gr. and Weight per Cb. Ft. in Ounces.	Weight per Cub.Foot in lbs. Avoirdu- pois.	Name of S		Sp. Gr. and Weight per Cb. Ft. in Ounces.	Weight per Cub.Foot in lbs. Avoirdu- pois.		
Slate .	_					 2,880	180	Trap				2,720	170
Snow .						 128	8	Water, pure				1,000	62.5
Steell.						 7,840	490	,, Sea			.1	1,024.8	64.05
Sulphur						2,000	125	Whinstone			٠,	2,752	172
Sycamor	е					592	87	Willow				448	28
Tar .						1.040	65	Yew				800	50
Tile .						1.792	112	Yorkshire fla	ė		.i	2,288	148
Tin .						7,860		Zinc	<del>.</del>		-	7,040	440
			-	-	-		the who					5,664	354

### MISCELLANEOUS ARTICLES.

Bale of flax (Russia)				5 to 6 cwt.
Barrel bulk				5 cubic feet.
Barrel of tar				261 gallons.
Battens	•			Boards 7 inches wide.
Bushel of coal .	•			80 lbs.
Bushel of coke .				45 ,,
Cable's length .				240 yards.
Cask of black lead				11½ cwt.
Chaldron of coal.				$25\frac{1}{9}$ ,,
,, coke				12½ to 15 cwt.
Cord of wood				128 cubic feet.
Deals				Boards 9 inches wide.
Dozen				12 articles.
Faggot of steel				120 lbs.
Fodder of lead				19 <del>1</del> cwt.
Gross				12 doz.
Hundred of deals .				120 in number.
,, nails .				120 ,,
Keel of coals				21 tons 4 cwt.

Load of bricks			. 500 bricks.
,, inch boards .			. 600 square feet.
,, 2-inch planks .			. 800 square feet.
" lime			. 32 bushels.
,, new hay			. 19 cwt. 32 lbs.
,, old hay			. 18 .,
,, straw		•	. 11 ,, 64 ,,
,, sand			. 86 bushels.
,, squared timber			. 50 cubic feet.
" unhewn	•		•
,, tiles			.1000 tiles.
Mat of flax (Dutch)			. 126 lbs.
Pig of ballast	•		. 56 ,,
Planks	•		. Boards 12 inches wide.
Quire of paper		•	. 24 sheets.
Ream of paper			. 20 quires, or 480 sheets.
Roll of parchment	•		. 60 skins.
Sack of coals	•		. 224 lbs.
Score	•		. 20 articles.
Sheet of paper folded into			
2 leaves is termed.			. folio size.
4	•	•	. 4to, or quarto.
0 ,, ,,	•	•	. 8vo, or octavo.
10	•	:	. 12mo, or duodecimo.
10	•	•	16 ma
10	•	:	10 ma
04	:		. 24 mo. ,,
40	•		. 48 mo. ,,
Square of planking			. 100 superficial feet.
Thousand of nails	•		.1200 nails.
Ton shipping			. 40 cubic feet.
Truss of old hay		•	. 56 lbs.
,, new hay			
			. 60 ,,

#### OFFICE MEMORANDA.

Books Required in the Keeping of a Gas Company's Accounts.

- 1. Ledger (general).
- 2. Cash Book (general).
- 8. Gas Register, or Ledger, sometimes called "The Consumers' Ledger."
- 4. Mill Register, or Ledger.

This book is devoted to the accounts of all the largest consumers, such as millowners, and the proprietors of other large establishments of any kind where the consumption of gas is heavy. They are handier classed together by themselves, than mixed up with smaller consumers.

### 5. Removals Book.

In this book is kept an account of all changes of residence that have taken place amongst consumers during each quarter, the substitution of meters, and the consumption of gas by temporary consumers, &c. It is a most useful record, and prevents confusion by interlineations in the regular register.

## 6. Quarterly Summary.

The several pages in the three foregoing books are added up and then brought together here, quarterly, in order to ascertain the total consumption, amount due, &c. By means of this book it is easy to compare the totals of the different quarters during a number of years.

### 7. Journal.

Containing entries of all goods sold from the works, with the exception of gas. Separate columns should be arranged for "Fittings, &c.," "Residual Products," "Miscellaneous," and "Total." At the end of each quarter the separate amounts of all accounts remaining unpaid are transferred to the

8. Arrears Fittings, &c., Book,

Which is entered up at the end of every quarter, and shows the amount remaining due (arrears included) for Fittings, Residual Products, and Miscellaneous.

9. Daily Receipt (Cash) Book,

In which is entered the amount of each separate payment made to the company on account of "Gas," "Meter-Rents," "Fittings, &c.," "Residual Products," and other miscellaneous items.

10. Stock-Taking Books,

For taking the quarterly stock of gas consumed through each meter. Two or more are always required, according to the number of consumers. The one used (we will suppose) on Monday is left at the office that night to be entered up into the Register by the clerk on the day following; and so on alternately.

11. Black Book,

In which a record of all bad debts is kept.

12. Collector's Book.

In some cases checks only are used with counterfoil.

13. Receiving Book,

In which all delivery notes for goods received by the company are copied daily. The regular invoice, when received, is checked by this book.

14. Wages and Time Book,

Containing, in separate columns, a daily account of the number of hours worked by each man, the kind of work, and the place where employed, with the amount due as wages at the end of each week.

- 15. Stores Book, A.
- 16. Stores Book, B.

In the one is kept a record of goods sold out of stock, and in the other of goods used out of stock for repairs and extension of plant. The one may be said to relate to revenue; the other chiefly to capital.

#### 17. Stores Ledger,

Into which the entries in the previous two books are posted to the credit of the several accounts (such as "Meters," "Lead Pipe," "Wrought-iron Fittings," &c.), and the items from the several invoices are posted to the debit of the several accounts. At the end of each half year the balance of each account represents the stock on hand. This latter is proved to be correct or otherwise by the result of the actual stocktaking.

# 18. Carbonizing Book-Daily and Weekly Statements,

Containing a record of the state of the station-meter taken twice in the 24 hours (in large works the state of the meter is recorded every hour); the quantity of coal and cannel used daily, the production of gas per ton, and the total daily production; the number of benches at work, stokers, &c. Each page serves for a week, and is then added up; an additional line is left at the foot of the page, on which is entered, for comparison, the particulars of the total of the corresponding week of the previous year.

#### 19. Public Lamp Register,

Gives particulars of the number of lamps lighted each night; the hours of lighting and extinguishing; the hours burning per lamp, the total hours burning; a column into which the number of hours, weekly, can be added, and another for remarks.

#### 20. Test Register,

For noting the results of the different tests of the illuminating power and purity of the gas.

- 21. Shareholders' Register and Address Book.
- 22. Seal Register and Dividend List.
- 28. Register of Calls.
- 24. Register of Transfers.

#### 25. Transfer Certificate Book,

Containing certificates of the registration of shares, to be torn out, leaving counterfoil behind.

#### 26. Invoice Book,

With blank leaves, into which are gummed all invoices for goods received.

#### 27. Minute Book.

A lettered index at the beginning of this book is handy.

A few other account-books of a less important character may be useful; but the above are indispensable in a well-regulated gas company.

Discount for Early Payment of Gas Bills.

The custom of allowing discount to consumers on gas bills paid either during the first month after the expiration of a quarter, or within a period of 21 or 80 days from the date of the delivery of the account, is very general amongst gas companies.

The most common allowance is at the rate of 10 per cent. on the amount due for gas consumed (excluding the meter-rent), but the premium varies throughout the country from 5 to 20 per cent.; some companies adopting a graduated scale of discounts according to the quarterly consumption.

The practice, wherever adopted, has been found highly beneficial, saving labour in collecting, and reducing the percentage of bad debts.

#### FORMS.

Renouncement of Proposed New Issue on the Transfer of Old Shares.

I, John Thompson, of Tipping Street, Newcastle, hereby renounce my right to any of the new Shares about to be issued by the ———Gas Company, in favour of William Jones, of Broad Street, Manchester.

(Signed) John Thompson.

To the Secretary of the ——— Gas Company.

Jan. 1, 18-

#### Renunciation of Shares Newly Allotted.

Signed by the said
John Wilson in the
presence of
(Here Witness signs.)
Signed by the said
William Jackson in
the presence of
(Here Witness signs.)

JOHN WILSON.

WILLIAM JACKSON.

Declaration for Loss of Sealed Share Certificates.

I, —, of —, do hereby solemnly and sincerely declare that I am possessed of and entitled to---in the ---- Company. \_\_\_\_\_, and that the said \_\_\_\_\_ are bona fide my property, and that they are not pledged or assigned to any person or persons whomsoever for money advanced thereon, or for any consideration whatever. And I further declare that I have made diligent search for the ———, and can nowhere find the same. And I make this solemn declaration conscientiously believing the same to be true, and by virtue of the provisions of an Act made and passed in the 5th and 6th years of the reign of His late Majesty King William the Fourth, intituled "An Act to repeal an Act of the present Session of Parliament, intituled 'An Act for the more effectual abolition of Oaths and Affirmations taken and made in various departments of the State, and to substitute declarations in lieu thereof,' and for the more entire suppression of voluntary and extra judicial Oaths and Affidavits, and to make other provisions for the abolition of unnecessary Oaths."

Declared at ——, this —— day of ———, One thousand eight hundred and ——, before me.

[The above Declaration is to be made before a Commissioner to administer Oaths in Chancery in England. Any person making a false Declaration is declared guilty of a misdemeanour.]

Indemnity for Loss of Share Certificates or Dividend Warrant.
Company.
Whereas ——, in the Company called the ——, numbered ——, being the property of ——, the undersigned, h— by accident been lost or destroyed, and the said Company have consented to give ——, on being indemnified for so doing. Now, in consideration of the said Company so granting to me, the said ——, a ——, we the undersigned —— and —— do hereby severally and respectively undertake and agree to save harmless and keep indemnified the Directors for the time being of the said Company of and from all losses, damages, and expenses which they, any or either of them, may sustain, incur, or be put unto, for or in consequence of their so granting such new —— ; and also from and against all claim or claims to be at any time hereafter made upon the said Company for or in respect of the original —— by any person or persons whomsoever.  Dated this —— day of ——, One thousand eight hundred and ——.
Authority to Pay Dividends.
Company,
Payment of Dividends.
I, the undersigned, —, of —, being a shareholder of and in the undertaking called the — Company, do hereby request that all Dividends and Interest due to me on the Stock or Shares now registered, or that may hereafter be registered in my name may be paid to —, of —, until further notice, whose receipt shall be a sufficient discharge to the Company for the payment of the same.
Signature
Data

Certificate Showing that Income-Tax has been Deducted.

This is to certify that on paying to John Brown the sum of £45, being the amount of one year's Dividend (or, one half year's Dividend, as the case may be) on Shares (or Stock) to December 31st, 18——, I deducted for Income-Tax the sum of 18s. 9d.

Pro the A——B——Gas Company,
WILLIAM JONES,
Secretary.

#### Form of Proxy.

#### TERMS FOR LEASES, ETC.

<b>England</b>	and	Ireland.
----------------	-----	----------

Scotland.

Lady Day .	•	March 25th.	Candlemas		Feb. 2nd.
Midsummer		June 24th.	Whitsunday		May 15th.
Michaelmas		Sept. 29th.	Lammas .		August 1st.
Christmas .		Dec. 25th.	Martinmas		Nov. 11th.

When a Scottish' term falls on Sunday, the Monday following is considered term day.

# LAW TERMS.

#### England and Ireland.

Hilary or Le	nt		Begins,	Jan. 11th.	Ends, Jan. 31st.
Easter .			,,	April 15th.	,, May 8th.
Trinity .			,,	May 22nd.	" June 12th.
Michaelmas			1,	Nov. 2nd	" Nov. 25th.

(11 1	
Scotland.	,
Candlemas Begins, Jan. 15th Ends, Feb. 8r	
Whitsunday , , May 12th ,, June 2	
Lammas , June 17th. , , July 5th	
Martinmas , Nov. 24th , Dec. 20	th.
SIZES OF DRAWING PAPER.	
	ft. In.
Antiquarian 4 4 $ imes$ 2 7   Double Crown . 3 6 $ imes$	1 8
,, extra 4 $8 \times 3$ 4   Imperial 2 $6 \times$	1 10
Double Elephant 3 4 $\times$ 2 3   Super Royal . 2 3 $\times$	1 7
Atlas $2\ 10 \times 2 \ 2    $ Royal $2\ 0 \times 10 \times$	1 7
Columbia 2 10 $\times$ 1 11   Medium 1 10 $\times$	1 5
Elephant 2 $3\frac{3}{4} \times 1$ $10\frac{1}{4}$ Demy 1 $8 \times 1$	1 3
TABLE OF COLOURS.	
Used in Mechanical and Architectural Drawing.	
Work. Colour.	
Brickwork in plan or section . Carmine or crimson lake.	
Brickwork in elevation Venetian red or crimson lake n	nixed
with burnt sienna.	
Brickwork to be removed by al-	
terations Burnt umber.	
Concrete works Sepia with darker markings.	
Clay Burnt umber.	
Earth Burnt umber.	
Flintwork Prussian blue.	
Granite Purple madder or pale Indian	ink.
Stone generally Yellow ochre or pale sepia.	
Slate Indigo and lake or Prussian b	lue.
English timber (oak excepted) . Raw sienna.	
Oak Burnt sienna or Vandyke brov	vn.
Fir and other light timber Indian yellow or raw sienna.	
Mahogany Indian red.	
Cast iron Payne's grey or neutral tint.	
Wrought iron Prussian blue.	
Steel, bright Indigo with a little lake.	
Brass Gamboge or Roman ochre.	
Gun metal Dark cadmium.	
Lead Pale Indian ink, tinged with in	digo
Meadow land Hooker's green.	~g∪.
O-1-1/11.	
oky enects Codatt blue.	

The presence of any slight greasiness, preventing the laying on of the colours evenly, may be counteracted in its effects by dissolving a little prepared ox-gall in the water with which the colours are mixed. The brush should always be used in mixing colours; the latter being rubbed in separate divisions of the slab.

#### EPITOME OF MENSURATION.

Of the Circle, Cylinder, and Sphere.

The areas of circles are to each other as the squares of their diameters.

The diameter of a circle being 1, its circumference equals 8.1416.

The diameter of a circle multiplied by 8.1416 equals its circumference.

The diameter of a circle is equal to .81881 of its circumference.

The square of the diameter of a circle being 1, its area equals -7854.

The diameter of a circle squared and multiplied by '7854 equals its area.

The internal circumference of a cylinder multiplied by its length or height equals its concave surface.

The area of the end of a cylinder multiplied by its length equals its solid contents.

The area of the internal diameter of a cylinder multiplied by its depth equals its cubical capacity.

The square of the diameter of a sphere multiplied by 8.1416 equals its convex surface.

The cube of the diameter of a sphere multiplied by .5286 equals its solid contents.

The capacity of a cylinder 1 foot in diameter and 1 foot in length equals 4.895 imperial gallons.

The capacity of a cylinder 1 inch in diameter and 1 foot in length equals .084 of an imperial gallon.

The capacity of a cylinder 1 inch in diameter and 1 inch in length equals .002832 of an imperial gallon. Hence—

The capacity of any other cylinder in imperial gallons is obtained by multiplying the square of its diameter by its length, and by the number of imperial gallons contained in the unity of its measurement.

The capacity of a sphere 1 foot in diameter equals 8.268 imperial gallons.

The capacity of a sphere 1 inch in diameter equals '001888 of an imperial gallon. Hence—

The capacity of any other sphere in imperial gallons is obtained by multiplying the cube of its diameter by the number of imperial gallons contained in the unity of its measurement.

#### Of the Square, Rectangle, and Cube.

The side of a square equals the square root of its area.

The area of a square equals the square of one of its sides.

The diagonal of a square equals the square root of twice the square of its side.

The side of a square is equal to the square root of half the square of its diagonal.

The side of a square equal to the diagonal of a given square contains double the area of the given square.

The area of a rectangle equals its length multiplied by its breadth.

The length of a rectangle equals the area divided by the breadth; or the breadth equals the area divided by the length.

The side or end of a rectangle equals the square root of the sum of the diagonal and opposite side to that required, multiplied by their difference.

The diagonal in a rectangle equals the square root of the sum of the square of the base and perpendicular.

The solidity of a cube equals the area of one of its sides multiplied by the length or breadth of one of its sides.

The length or breadth of a side of a cube equals the cube root of its solidity.

The capacity of a 12-inch cube equals 6.232 imperial gallons.

# Of Triangles and Polygons.

The sum of the squares of the two given sides of a right-angled triangle is equal to the square of the hypotenuse.

The difference between the squares of the hypotenuse and given side of a right-angled triangle is equal to the square of the required side.

The area of a triangle equals half the product of the base multiplied by the perpendicular height.

The side of any regular polygon multiplied by its apothegm, or perpendicular, and by the number of its sides, equals twice the area.

#### Of Ellipses. Cones, and Frustums.

The square root of half the sum of the squares of the two diameters of an ellipse, multiplied by 3:1416, equals its circumference.

The product of the two axes of an ellipse, multiplied by '7854, equals its area.

The solidity of a cone equals one-third of the product of its base multiplied by its altitude or height.

The squares of the diameters of the two ends of the frustum of a cone added to the product of the two diameters, and that sum multiplied by its height and by 2618, equal its solidity.

Table of Common Fractional Parts and Equivalent Decimals.

Common Fractional Parts.	Decimals.	Common Fractional Parts.	Decimals,	Common Fractional Parts.	Decimals
1-100th	·01	9-14ths	•6428	7-10ths	.7
1-90th	·0111	11-14ths	·7857	9-10ths	•9
1-80th	·0125	18-14ths	•9285	1-9th	•1111
1-70th	0143	1-18th	077	2-9ths	.2222
1-60th	•0166	2-18ths	•1538	4-9ths	•4444
1-50th	.03	8-18ths	·2307	5-9ths	.5555
1-40th	.025	4-18ths	·8076	7-9ths	.7777
1-90th	.0988	5-13ths	·8846	8-9ths	.8888
1-20th	-05	6-18ths	•4615	1-8 <b>th</b>	125
1-19th	.0526	7-18ths	-5384	8-8 <b>ths</b>	.875
1-18th	.0555	8-18ths	·6153	5-8ths	•625
1-17th	.0588	9-18ths	6928	7-8ths	.875
1-16th	.0625	10-13ths	•7692	1-7 <b>th</b>	148
8-16ths	·1875	11-18ths	8461	2-7ths	2857
5-16ths	·8125	12-13ths	·928	8-7ths	4285
7-16ths	•4875	1-12th	•0833	4-7ths	.5714
9-16ths	-5625	5-12 <b>ths</b>	·4166	5-7ths	.7148
11-16ths	•9875	7-12ths	•5883	6-7ths	*8571
18-16ths	·8125	11-12ths	·9166	1-6th	1666
15-16ths	•9375	1-11th	.0909	5-6ths	.833
1-15th	.0686	2-11ths	·1818	1-5 <b>t</b> h	•2
2-15ths	1888	8-11 <b>ths</b>	•2727	2-5ths	•4
4-15ths	-2666	4-11ths	•8686	8-5ths	.6
7-15ths	•4666	5-11ths	·4545	4-5 <b>ths</b>	-8
8-15ths	·5883	6-11ths	•5454	1-4th	•25
11-15ths	•7888	7-11ths	·6863	8-4ths	•75
18-15ths	·8666	8-11ths	.7272	1-8rd	•8333
14-15ths	•9888	9-11ths	·8181	2-3rds	.6666
1-14th	·0714	10-11ths	.808	1-half	•5
8-14ths	·2142	1-10th	1	1	1
4-14ths	·2857	8-10ths	i •8		1

#### ARITHMETICAL AND ALGEBRAICAL SIGNS.

- = The sign of Equality, and signifies equal to, as 2 added to 8 = 5.
- + ,, Addition ,, plus or more, as 4 + 6 = 10.
- ,, Subtraction ,, minus or less, as 6-4=2.
- $\times$  ,, Multiplication ,, multiplied by, as  $5 \times 8 = 15$ .
- $\div$  ,, Division ,, divided by, as  $8 \div 4 = 2$ . or  $\frac{8}{4} = 2$

: :::, Proportion, : signifies is to, or to, :: signifies so is.

Thus, 2:8::4:6 signifies that as 2 is to 8 so is 4 to 6.

Evolution, or the Extraction of Roots.

- $\checkmark$  The sign of the Square Root (termed the Radical sign), as  $\checkmark$  16 = 4, i.e., the square root of 16 is equal to 4.
- $\checkmark$  , Cube Root, as  $\checkmark$  64 = 4, i.e., the cube root of 64 is equal to 4.

Involution, or the raising of Powers.

- $4^2$  signifies to be squared, as  $4^2 = 16$ . The small figure is termed the Index or Exponent.
- $4^8$  ,, to be cubed, as  $4^8 = 64$ .
- ——A vinculum placed over two or more figures, thus  $\overline{3+5}$ , signifies that they are to be taken as one quantity. Thus:
- $\overline{8+5} \times 4 = 82$ , signifies that 8 plus 5 multiplied by 4 = 82, and
- $\sqrt{5^2-8^2}=4$ , signifies that 5 squared, minus 8 squared, and the square root of the remainder = 4, and
- $\sqrt[3]{\frac{20 \times 12}{80}}$  = 2, signifies that 20 multiplied by 12, divided by 80, and the cube root of the quotient = 2, and
- $\frac{24 \times 6 + 12 \times 8 \times 4}{12} = 60, \text{ signifies that 24 multiplied by 6, and 12}$ multiplied by 8, added together, multiplied by 4 and divided by 12, the quotient = 60.
- [] () Brackets; e.g. 12 [8 + (4 × 2)] = 1, signify that the product of 4, multiplied by 2, added to 8, and the total subtracted from 12, leaves 1.

- . . . is used to signify the word therefore.
- · . · is used to signify the word because, or since.
  - ? is used in the Chain Rule to signify how many.

#### APPROXIMATE MULTIPLIERS FOR FACILI-TATING CALCULATIONS.

Square inches  $\times .007 = \text{square feet.}$ 

Square feet  $\times$  ·111 = square yards.

Square yards  $\times$  .0002067 = statute acres.

Square yards  $\times$  .000000328 = square miles.

Statute acres  $\times$  .0015625 = square miles.

Square links  $\times$  .4856 = square feet.

Square feet  $\times 2.3 = \text{square links}$ .

Square feet  $\times$  188.346 = circular inches.

Circular inches  $\times$  .00456 = square feet.

Links  $\times$  ·22 = yards.

Links  $\times$  .66 = feet.

Feet  $\times 1.5 = links$ .

Cubic inches  $\times$  .00058 = cubic feet.

Cubic inches  $\times$  .01688 = litres.

Cubic feet  $\times$  .087 = cubic yards.

Cubic feet  $\times$  2200 = cylindrical inches.

Cylindrical inches  $\times \cdot 0004546 = \text{cubic yards}$ .

Cylindrical feet  $\times$  .02909 = cubic yards.

Cubic feet  $\times 6.232$  = imperial gallons.

Imperial gallons  $\times$  ·1604 = cubic feet.

Cubic inches  $\times$  .003607 = imperial gallons.

Imperial gallons  $\times$  277.8 = cubic inches.

Imperial gallons  $\times 4.541 = litres$ .

Cubic feet  $\times$  .779 = bushels.

Cubic inches  $\times$  .00045 = bushels.

Bushels  $\times$  .0476 = cubic yards.

Bushels × 1.284 = cubic feet.

Bushels  $\times$  2218·2 = cubic inches.

Lineal feet  $\times$  '00019 = statute miles.

Lineal yards  $\times \cdot 0006$  = statute miles.

Statute miles  $\times$  .869 = mean geographical miles.

Mean geographical miles  $\times 1.151 = \text{statute miles}$ .

Pounds avoirdupois  $\times$  7000 = grains.

Pounds avoirdupois  $\times$  ·82286 = pounds troy.

Pounds troy  $\times 1.2158 = \text{pounds avoirdupois.}$ 

Grains  $\times$  .0001429 = pounds avoirdupois.

Pounds avoirdupois  $\times .009 = cwts$ .

Pounds avoirdupois  $\times .00045 = tons$ .

Pounds on square inch  $\times$  144 = pounds on square foot.

Pounds on square foot  $\times \cdot 007$  = pounds on square inch.

Miles per hour  $\times 1.467$  = feet per second.

Feet per second  $\times$  .682 = miles per hour.

Diameter of circle  $\times 8.1416 = \text{circumference}$ .

Circumference of circle  $\times$  ·81881 = diameter.

Diameter of circle  $\times$  .8862 = side of equal square.

Circumference of circle  $\times$  ·2821 = side of equal square.

Diameter of circle  $\times$  .7071 = side of inscribed square.

Circumference of circle  $\times$  ·2251 = side of inscribed square.

Area of circle  $\times$  ·6366 = side of inscribed square.

Side of square  $\times$  1·128 = diameter of equal circle.

Side of square  $\times 3.545 = \text{circumference of equal circle.}$ 

Side of square × 1.414 = diameter of circumscribing circle.

Side of square  $\times 4.448 =$  circumference of circumscribing circle.

Square of diameter  $\times .7854$  = area of circle.

Square root of area  $\times 1.12837$  = diameter of equal circle.

Square of diameter of sphere  $\times 3.1416 = \text{convex surface}$ .

Cube of diameter of sphere  $\times .5236 = solidity$ .

Diameter of sphere  $\times$  .806 = dimensions of equal cube.

Diameter of sphere  $\times .6667 = length$  of equal cylinder.

One atmosphere = 14.7 pounds on square inch.

,, = 2116 pounds on square foot.

= 29.922 inches of mercury.

= 83.9 feet of water.

Each 1000 cubic feet of coal gas in a holder  $\times 87 = (approximate)$  weight of gas in pounds.

The atomic weight of an elementary gas × '0691 = its specific gravity.\*

Half the atomic weight of a compound gas or vapour  $\times .0691 = its$  specific gravity.

<sup>\*</sup> Exceptions to this rule occur in the case of the vapours of phosphorus and arsenic, whose atomic weights must be doubled, and in those of mercury, zinc, and cadmium, the atomic weights of which must be halved.

# TABLE OF DIAMETERS, CIRCUMFERENCES, AND AREAS OF CIRCLES, AND SIDES OF EQUAL SQUARES.

Diam.	Circum- ference.	Area.	Side of Equal	Diam.	Circum- ference.	Area.	Side of Equal
ł	·7854	.0490	Square. 2215	182	48 · 197	148 489	Square. 19·185
ì	1.5708	·1968	•4481	14	48 982	158 • 988	12.406
į	2 8562	•4417	·6646	141	44.767	159 • 486	12.628
1	8.1416	·7854	-8862	141	45 · 558	165 180	12.860
11	8.9270	1.2271	1.1077	144	46.888	170.878	18.071
11	4.7124	1.7671	1.8298	15	47 · 124	176 - 715	18.298
1	5.4978	2.4052	1.5508	151	47.909	182.654	18.514
2	6.2832	8.1416	1.7724	151	48 · 694	188 · <b>692</b>	18.786
21	7 · 0686	8 · 9760	1.9989	152	49 • 480	194·828	18 · 957
2	7.8540	4 · 9087	2 · 2155	16	50·265	201 · 062	14·174
23	8 · 6894	5 · 9395	2·4870	16 <del>1</del>	51.061	207 · 394	14·400
8	9 · 4248	7.0686	2.6586	164	51· <b>836</b>	213 · 825	14.622
8 <u>1</u>	10.210	8 · 2957	2.8801	162	52.621	220 · 858	14·848
81	10.995	9.6211	8.1017	17	58 • 407	226 · 980	15.065
88	11.781	11.044	8 8282	171	54.192	233 · 705	15.286
4	12.566	12.566	8.5448	174	54.978	240 · 528	15.508
41	18.851	14.186	8.7668	172	55.768	247 · 450	15.780
44	14 · 187	15.904	8.9880	18	56 548	254 · 469	15.951
42	14.922	17.720	4.2095	181	57:384	261 · 587	16.178
5	15.708	19.685	4.4310	181	58 119	268 · 808	16.894
51	16.498	21.647	4.6525	182	58.905	276 · 117	16.616
51	17·278 18·064	23·758 25·967	4·8741 5·0956	19 19 <del>1</del>	59·690 60·475	288 · 529 291 · 089	16·837 17·060
5 <u>‡</u> 6	18 849	28 274	5.8172	194	61 · 261	291 069	17.280
6 <u>1</u>	19.635	80.679	5.2888	194	62.046	806·855	17.502
61	20.420	88 · 188	5.7608	20	62 832	814·160	17.724
61	21.205	85.784	5.9819	201	63.617	322 · 068	17.945
7	21.991	88.484	6.2084	201	64 402	330 064	18.167
71	22.776	41.282	6.4850	203	65 188	338·168	18.388
7	28 - 562	44 · 178	6 · 6465	ี่ ฉัง	65 - 978	846 · 861	18.610
71 ,	24.847	47.178	6.8681	212	66 · 759	354 · 657	18.831
8 `	25 · 182	50 · 265	7.0897	21	67 · 544	868 . 051	19.068
81	25.918	58 · 456	7.8112	214	68 · 829	871 · <b>548</b>	19.274
8	<b>₽6</b> • 703	56.745	7.5828	22	69.115	880 · 188	19:496
8 <u>#</u>	27·4 <del>89</del>	60 · 132	7.7544	221	69 · 900	388 · <b>822</b>	19·718
9	28 · 274	<b>6</b> 8 · 617	7 · 9760	224	70 · 686	397 · <b>608</b>	19•939
91	39.029	67 · 200	8.1974	222	71 · 471	406 · 498	20 · 161
91	29.845	70.882	8.4190	28	72 • 256	415.476	20.882
94	80.680	74.662	8 · 6405	281	78 • 042	424 · 557	20.604
10	81.416	78·5 <b>4</b> 0	8.8620	284	78 827	488 · 781	20.825
101	82.201	82.516	9.0886	282	74.618	448.014	21.047
101	82.966	86.590	9.3051	24	75.898	452 · 890	21.968
10 <del>1</del> 11	88.772	90.762	9.5267	241	76 188	461 · <del>8</del> 64	21.490
	84·557 85·848	95 · 038 99 · 402	9·7482 9·9698	241	76·969 77·754	471 · 486 481 · 106	21·712 21·983
11 <u>1</u> 111	86 · 128	300.000	10.191	242 25	78 · 540	490 875	22 · 155
111	86.918	108.484	10.418	251	79 825	500.741	22 100
12	87 · 699	118.097	10.684	254	80.110	510.706	22.598
12 <del>1</del>	88 484	117.859	10.858	251	80.896	520.769	22.819
121	89.270	122.718	11.077	26	81.681	580.980	28.041
123	40.055	127 - 676	11.299	261	82.467	541 · 189	28.262
18	40.840	132.732	11.520	261	83 - 252	551 - 547	28 · 484
181	41.626	187 · 886	11.742	262	84 · 087	562 · 002	28.708
18	42.411	143 · 139	11.963	27	84 823	572 · 556	28 927
-							

Diam.	Circum-	Area.	Side of Equal	Diam.	Circum-		Side of
Dining	ference.	Arus.	Square.	Diam.	ference.	Area.	Equal Square.
27±	85 · 608	583 · <b>2</b> 08	24·149	413	181 · 161	1869 · 00	86.999
27	86 · 894	593.958	24.370	42	181 · 947	1885 • 44	37.220
271	87 · 179	604 · 807	24 · 592	421	182 · 782	1401 98	37 · 442
28	87.964	615 · 758	24.818	421	133 518	1418.62	87.663
281	88·750 89· <b>585</b>	626 · 798 637 · 941	25·035 25·256	422	134 · 303	1485 · 96	87 885
284 284	90.931	649 182	25 478	431	185 · 088 185 · 874	1452·20 1469·18	38·106 38·328
267 269	91 · 106	660 - 521	25 699	484	186 659	1486 · 17	88 549
291	91.891	671 - 958	25.921	434	187 • 445	1508 - 80	88.771
291	92.677	683 · 494	26 · 143	44	138 · 230	1520.58	88.998
294	98 • 462	695 · 128	26.364	441	189.015	1537 . 86	89.214
80	94 · 248	706 · 860	26 · 586	444	139 · 801	1555 · 28	89 · 486
30 <u>1</u>	95.088	718 690	26 · 807	442	140 586	1572.81	<b>39 · 657</b>
801	95.818	780.618	27.029	45	141 · 872	1590 · 48	89 · 879
802	96·604 97·389	742·644 754·769	27·250 27·472	451 451	142·157 142·942	1608 · 15	40.110
81 81 <del>1</del>	98 · 175	766 - 992	27 - 693	453	143 728	1625 · 97 1648 · 89	40·822 40·543
811	98.968	779 - 818	27.915	46	144.518	1661 - 90	40.765
81	99.745	791 - 782	28 · 186	461	145 · 299	1680.01	40.986
82	100.581	804 249	28.358	461	146.084	1698 · 23	41.208
821	101.816	816 · 865	28.580	467	146 · 869	1716.54	41 · 429
824	102 · 102	829 · 578	28.801	47	147 · 655	1784·94	41.651
824	102 887	842.890	29:023	471	148 440	1758 • 45	41.878
88	103 · 672	855 · 800 868 · 808	29·244 29·466	473	149 · 226	1772 • 05	42.094
85 <u>1</u>	104·458 105·248	881 · 415	29 687	472 48	150·011 150·796	1790·76 1809·56	42·816 42·587
88 <u>1</u> 88 <u>1</u>	106 230	894 · 619	29.909	481	151.582	1828 • 46	42.759
84	106 - 814	907 - 922	80.181	481	152 867	1847 • 45	42.980
84±	107 - 599	921 · 928	80.352	483	158 · 158	1866 - 55	48.202
841	108 - 885	984 · 822	80.574	49	158 988	1885 · 74	48 428
8 <del>4</del>	109 · 170	948 · 419	80.795	491	15 <b>4·728</b>	1905 · 03	48.645
85	104.956	962 · 115	81.017	493	155 · 509	1924 · 42	43 867
851	110.741	975 • 908	31.238	492	156 294	1948 • 91	44 088
851	111·526 112·812	989·800 1003·79	81·460 81·681	50 50 <del>1</del>	157·080 157·865	1963·50 1983·18	44·810 44·581
85 <u>2</u> 36	118.097	1017 - 87	31.903	501	158.650	2002 96	44.758
86±	118 888	1032.06	32.124	50 <del>2</del>	159 486	2022 84	44 . 974
361	114.668	1046 · 89	82.349	51	160.221	2042 - 82	45.196
861	115 • 458	1060 · 78	32.567	51 <u>‡</u> .	161.007	2062 90	45.417
87	116 · 289	1075 • 21	82.789	513	161.792	2083 · 07	45 · 639
371	117.024	1089 · 79	88.011	512	162.577	2103 · 85	45.861
874	117.810	1104 · 46	83 282	52	163 863	2128 · 72	46:082
87 <b>2</b> 88	118 · 595 119 · 380	1119 <b>·24</b> 1184·11	83·454 83·675	52 <u>1</u> 521	164·148 164·934	2144·19 2164·75	46·304 46·525
881	120 · 166	1149.08	83.897	523	165 · 719	2185 · 42	46.747
881	120 951	1164 · 15	34.118	53	166 - 504	2206 · 18	46.968
882	121.787	1179 - 32	84 · 340	581	167 · 290	2227 · 05	47 · 190
89	122.522	1194.59	84.561	581	168 · 075	2248.01	47:411
89 <u>1</u>	123 · 807	1209 · 95	34 · 783	58 <del>2</del>	168 · 861	2269 · 06	47·633
891	124.098	1225 · 42	85.005	54	169 · 646	2290 · 22	47 . 854
892	124.878	1240·98	85 226	541	170.431	2311 · 48	48.076
40	125·664 126·449	1256 · 64 1272 · 39	85 · 448 85 · 669	541 543	171 · 217 172 · 002	2332 · 83 2854 · 28	48 • 298 48 • 519
40 <u>1</u> 401	127 284	1268-25	85 891	54 <u>%</u> 55	172 788	2875 88	48.741
401	128.020	1804 20	36.113	55±	178.578	2397 · 48	48 962
41	128 · 806	1820 · 25	86 · 834	551	174.358	2419 22	49.184
411	129.591	1336 · 40	86 · 555	552	175 144	2441.07	49 · 405
414	130.376	1852-65	86·777	56	175 · 929	2463 · 01	49 · 627

Diam.	Circum- ference.	Area.	Side of Equal Square.	Diam.	Circum- ference.	Area.	Side of Equal Square.
56 <del>1</del>	176 · 715	2485 . 05	49.848	71	928 • 058	8959 · 20	62:920
56 <del>1</del>	177.500	2507 · 19	50.070	713	228 - 889	8987 · 18	63.141
562	178 · 285	2529 · 42	50.291	713	224 - 624	4015 · 16	68 - 863
57	179.071	2551 · 76	50.518	712	225 · 409	4048 · 28	68 - 545
57±	179.856	2574 · 19	50.785	72	226 · 195	4071 . 51	68-806
571	180 · 642	2596 · 72	50.956	721	226 - 980	4099 · 88	64.028
57	181 · 427	2619 · 85	51·178	721	227 · 766	4198-25	<b>64 · 94</b> 9
68	182 · 212	2642.08	51.899	723	228 · 551	4156 . 77	64 · 471
58 <u>1</u>	182.998	2664 91	51.691	78	229 · 886	4185 · 39	64 · 692
581	188 • 788	2687 · 83	51 842	781	280 · 122	4214 · 11	64.914
584	184·569 185·354	2710·85 2788·97	52·064 52·285	781	280 · 907	4942.92	65 · 185
59 59 <del>1</del>	188 · 189	2757·19	52·250	78 <del>2</del> 74	281 · 698 282 · 478	4271 · 88 4800 · 85	65 · 367 65 · 578
59å	186 925	2780 · 51	52.729	742	238 268	4829 • 96	65 - 800
59 <b>1</b>	187.710	2808 • 92	52.950	741	234 · 049	4859 • 16	66.022
60	188 496	2827 · 44	58 - 172	742	284 884	4888 47	66 243
60±	189 · 281	2851 · 05	58.898	75	285 • 620	4417.87	66 465
60i	190.066	2874 · 76	58.615	75±	236 · 405	4447 · 87	66 - 686
602	190.852	2898 • 56	58.886	75	237 · 190	4476 . 97	66.908
61	191 · 687	2922 · 47	54·048	751	287 · 976	4506 · 67	67 · 129
614	192 · 423	2946 · 47	54 · 279	76	238 · 761	4586 · 47	67 · 851
61	193 · 208	2970 · 57	54.501	761	239 · 547	4566.86	67.572
614	198 · 998	2994 · 77	54.728	761	240.382	4596.35	· 67·794
62	194.779	8019 • 07	54.944	76 <del>2</del>	241 · 117	4696 • 44	68.016
62 <u>1</u>	196 664	8048 • 47	55·166	77	241 · 908	4656 • 68	68 · 287
621	196·350 197·185	3067·96 8092·56	55·887 55·609	77½ 77%	242 · 688 248 · 474	4686 · 92 4717 · 30	68 · 459 68 · 680
62 <b>2</b> 68	197 920	8117 · 25	55·830	774	244 259	4747·79	68 902
68 <del>1</del>	198.706	8142.04	56.052	78	245.044	4778 - 37	69 123
684	199.491	8166.92	56 278	781	245 · 890	4809 05	69 845
682	200 277	8191.91	56 · 495	781	246 · 615	4889 · 88	69.566
64	201.062	8216 · 99	58.716	782	247 · 401	4870.70	69.788
641	201 · 847	8242 - 17	56.988	79	248 · 186	4901 68	70.009
641	202 · 633	8267 · 46	57·1 <b>59</b>	79 <del>1</del>	<b>248</b> ·971	4982 · 75	70 · 231
642	208 • 418	3292 · 83	57·881	791	249·757	4968 · 92	70· <b>45</b> 3
65	204 204	8818.81	57·608	792	250.542	4995 · 19	70.674
651	204 989	8343·88	57·824	80	251.328	5026 56	70·896
661	205·774 206·560	8369 56 8895 83	58·046 58·267	801	252·118 252·898	5058·01 5089·58	71·119 71·889
66 <u>2</u> 66	200 300	8421.20	58 489	80 <u>3</u> 80 <del>2</del>	258 684	5121 24	71.562
66±	208 · 181	8447 • 16	58.710	81	254 · 469	5158.00	71.782
664	208.916	8478 28	58.932	81±	255 • 255	5184 · 86	72.005
662	209 · 701	8499 · 39	59.154	811	256.040	5216.82	72.225
67	210-487	8525 · 66	59.875	812	256 825	5248 · 87	72:449
07±	211 . 272	8562.01	59 · 597	82	257:611	5281·02	<b>72·66</b> 8
67	212.058	8578 • 47	59.818	821	258 · 396	5818·27	72 · 892
672	212.843	8606 08	60.040	823	259 · 182	5345 62	78 · 111
68	218 • 628	8681 · 68	60.261	822	259 · 967	5870 · 07	78 · 885
681	914.414	8658 • 44	60.488	88	260.752	5410.62	78.554
681	215 199	8685 · 29	60.704	881	261 · 588	5443·26	73·778 78·997
68 <b>2</b> 69	215·985 216·770	8712 · 24 8789 · 28	60·926 61·147	881 882	262·328 268·109	5476·00 5508·84	74 221
69±	217.555	8766·48	61 · 369	84	268 109	5541.78	74 440
694	218 · 341	8798 · 67	61.591	841	264 679	5574.81	74 664
693	219 · 126	8821.02	61.812	841	265 · 465	5607 . 95	74 · 884
70	219-912	8848 · 46	62.984	842	266 · 250	5641 · 18	75 107
70±	220 - 697	8875 · 99	62 · 255	85	267 · 036	5674.51	75 827
70	221 · 482	8908 · 68	62 · 477	851	267 · 821	5707 · 94	75 · 650
70 <u>ž</u>	222 · 268	8931 · 86	62 · 698	851	268 · 606	5741·47	75.770

Diam.	Circum- ference.	Area.	Side of Equal Square.	Diam.	Circum- ference.	Area.	Side of Equal Square.
852	269 · 392	5775 • 09	75.994	991	811 · 808	7786 - 62	87 - 968
86	270 · 177	5808 · 81	76.218	991	812.599	7775.65	88 · 179
86 <u>1</u>	270.968	5842 68	76·487	994	818·87 <b>4</b>	781 <b>4·79</b>	<b>88·401</b>
86 <del>1</del>	271.748	5876 • 55	76 • 656	100	814 · 160	7854 · 00	88 • 622
862	272 · 583	5910·57	76 · 860	1001	814·9 <b>4</b> 5	7893·81	88 - 844
87	278 · 819	5944·69	77.099	100	815 · 780	7982 · 78	89 • 065
871	274 · 104	5978·9 <b>0</b>	77.323	100	816.216	7972 • 21	89 · 287
87	274 · 890	6013 · 21	77 · 542	101	817.801	8011.86	89 · 508
874	275 · 675	6047 · 62	77.766	1012	818 · 067	8051 · 57	89.780
88	276 · 460	6082 · 18	77 · 965	101	818 872	8091 88	89 - 952
881	277 · 246	6116.74	78 · 209	1012	819 657	8181 · 29	90.178
881	278 · 081	6151 · 44	78 428	102	820 · 448	8171 · 80	90.895
88 <u>#</u>	278 · 817	6186 25	78 652	1021	321 · 228 322 · 014	8211:40	90·616 90·888
89	279 · 602	6221 · 15	78·871 79·095	1021	822 799	8251·60 8291·86	91.059
89 <u>1</u>	280·387 281·178	6256·15 6291·25	79.055	10 <del>22</del> 108	328 584	8882.80	91 281
891	281 958	6326 · 44	79 515	1081	824 · 870	8872 80	91.502
89 <u>7</u> 90	282 744	6361 · 74	79.758	1084	825 155	8413·40	91.794
901	283 · 529	6897 · 18	79.982	1084	825 941	8454 . 09	91.946
901	284 · 814	6482 62	80.201	104	826 · 726	8494 . 88	92.167
90 <del>1</del>	285 100	6468 21	80 425	1041	827 - 511	8585 · 77	92.889
91	285 - 885	6503 89	80.644	104	828 297	8576 . 76	92.610
91 <sub>2</sub>	286 · 671	6539 · 68	80.868	1044	829 082	8617.85	92.882
911	287 - 456	6578 · 56	81.087	105	829 · 868	8659 · 08	93.063
914	288 • 241	6611.54	81.811	105±	880 658	8700.31	98 • 275
92	289 · 027	6647 · 62	81.580	1051	881 • 488	8741 · 69	98 · 496
921	289 · 812	6683 · 80	81.754	1052	832 · 224	8788 17	98.718
921	290 · 598	6720 • 07	81.978	106	888 . 009	8824 • 75	98 · 940
922	291 · 883	6756 - 45	82 · 197	106 <del>1</del>	888 - 794	8866 42	94 · 161
98	292 · 168	6792 - 92	82-416	106	884 · 580	8908 • 20	94 · 388
981	292.954	6829 • 49	82·640	106	835 • 865	8950 · 07	94 · 604
98	298 · 799	6866 • 16	82 · 859	107	836 • 151	8992 · 04	94 826
982	<b>294</b> · 585	6902.92	83 · 083	107 <u>2</u>	336 · 986	9084 · 11	95 · 047
94	<b>295</b> ·810	6989·7 <b>9</b>	83 · 802	107	887 • 722	9076 27	95 · 269
94 <u>1</u>	296 · 095	6976 • 75	83.526	1072	338 · 506	9118.54	95· <b>49</b> 1
941	296 · 881	7018-81	83 · 746	108	889 · 292	9160.90	95.712
943	297 • 666	7050 • 97	83 · 970	1081	840.077	9208 36	95 · 934
95	298 • 452	7088 · 23	84 189	108	340.863	9245 • 92	96.155
951	299 · 237	7125 · 58	84.418	1082	841 · 648 842 · 484	9288·58 9331·38	96·8 <b>77</b> 96·5 <b>96</b>
951	800.022	7168 • 04	84.632	109	848 219	9374.18	96.820
952	800 · 808	7200 • 59	84.856	1091	844.005	9417:14	97.041
96 96 <del>1</del>	801 · 598 802 · 379	7288 · 24 7275 · 99	85·077 85·299	109½ 109¾	844.789	9460-19	97.968
96 <u>1</u>	803 164	7818·84	85 • 520	110	845 · 576	9508 · 84	97 · 485
96 <del>2</del>	808 949	7851.78	85.742	120	376.992	11809.76	106.848
97	804 · 785	7889 - 82	85.964	180	408 · 408	13278 - 26	115.284
971	805 • 520	7427 · 96	86 185	140	489 248	15393 · 84	124 · 079
971	306 306	7466 20	86 407	150	471.240	17671.50	182 985
973	807.091	7504 - 54	86.628	160	502 656	20106 · 24	141.798
98	807 · 876	7542.98	86.850	170	584.079	22696 • 06	150.659
981	808 - 662	7581 · 51	87.071	180	565 488	25446 96	159.521
981	309 · 447	7620 · 14	87 · 293	190	596.904	28852 94	168 · 383
982	810 · 238	7658 · 87	87.514	200	628 • 820	81416.00	177·247
99	811.018	7697 . 70	87.786	800	942 • 480	70686 · 00	<b>265·869</b>

#### WEIGHTS AND MEASURES.

Troy Weight.

The pound troy is the weight of 22.815 cubic inches of distilled water at the temperature of 62° Fahr., the height of the barometer being 30 inches.

Troy weight is used in philosophical experiments, and in weighing gold, silver, and jewels. The fineness of gold and silver coins means the proportion of the precious metal which they contain. This is expressed in 1000ths of their total weight, or in carats—24ths of their total weight. British gold coins are 22 carats fine, or 0.916\frac{2}{3}; silver coins, 0.925. Gold, if pure, is said to be 24 carats fine; if there be one of alloy with 28 carats of pure gold, it is 23 carats fine, and so on downwards. The alloy in gold and silver coins consists of copper. The true weight of a sovereign is 123.274 grains consisting of—pure gold, 11 parts or 118.001 grains; copper, 1 part or 10.278 grains. Silver coin consists of—pure silver, 222 parts; copper, 18 parts. The weight of a shilling is 87\frac{1}{4} grains. 24 pence are made from an avoirdupois pound of copper.

#### Septem and Decigation.

The word septem (seven) is descriptive of the weight of the 1000th part of a decigallon of distilled water at 62° Fahr., and under a barometric pressure of 30 inches.

A decigallon of water is the tenth part of a gallon, and as a gallon of water at the above temperature and pressure weighs 70,000 grains (10 lb. avoirdupois), it follows that the tenth part, or a decigallon, must weigh 7000 grains (1 lb.).

Each decigallon is divided into 1000 septems; and therefore the septem of pure water weighs 7 grains.

Apothecaries Weight.											
				Drams,			Grains.	gr.			
			or Drachms.			1	=	20	scr.		
		Ounces.		1	=	8	=	60	dr.		
Pound.		1	=	8	=	24	=	480	oz.		
1	=	12	=	96	=	<b>2</b> 88	=	<b>576</b> 0	lb.		

The sign of the scruple is  $\vartheta$ ; the dram,  $\mathfrak{Z}$ ; the ounce,  $\mathfrak{Z}$ .

This weight, which is now abolished, was formerly used for compounding medicines. The grain, ounce, and pound are equal to those of troy weight. Drugs are bought and sold by avoirdupois weight.

#### Avoirdupois Weight.

			····F		,			
						Ounces.		Drams. dr.
			]	Pounds	•	1	=	16 oz.
	8	tones.		1	=	16	=	256 lb.
Qu	arters.	1	=	14	=	224	=	8584 st.
Cwts.	1 =	2	=	<b>28</b>	=	448	=	7168 qr.
Ton. $1 =$	4 =	8	=	112	=	1792	=	28672 cwt.
1 = 20 =	80 =	160	=	2240	=	<b>35840</b>	=	578440 ton.
	1 lb. av	oirdup	ois	= 700	9 OO	rains tro	y.	
	1 oz. av	oirdup	oois	=48'	7.5	grains ti	oy.	
100	) ozs. av	oirdup	ois	$= 91_{7}$	7-tl	is ozs. ti	oy.	

The imperial pound avoirdupois is the standard unit by means of which all commodities, except gold, silver and precious stones, are weighed, and is equal to the weight of one-tenth of an imperial gallon, or of 27.7274 cubic inches of distilled water at the temperature of 62° Fahr., and when the barometer stands at 30 inches. A certain piece of platinum of this standard weight is kept in the Exchequer Office at Westminster.

Lineal or Long Measure.

						Feet.	Inches.					
•					Pe	erches	or	Yards.		1	=	12
•						Poles.	1	=	8	=	86	
			C	hains	3.	1	5 <del>1</del>	=	16 <del>1</del>	==	198	
	Fu	rlon	gs.	1	=	4	=	22	=	66	=	792
Mile.		1	=	10	=	40	=	220	=	660	=	7920
1	=	8	=	80	=	<b>820</b>	=	1760	=	<b>52</b> 80	=	68860
		11	link	= 7:	92 i1	ches.						

100 links = 1 chain, or 66 feet, or 22 yards.

1 league = 8 geographical or nautical miles.

- 1 hand = 4 inches.
- 1 fathom = 6 feet.
- 1 military pace =  $2\frac{1}{2}$  feet.
- 1 geometrical pace = 5 feet.
- 1 geographical or nautical mile = 1.15 statute miles.
- 1 geographical degree = 60 geographical or nautical miles.
- 1 Admiralty knot = 6080 feet.

The yard is the imperial standard measure of length, and is the distance, at the temperature of 62° Fahr., between two marks on a certain bar kept in the Exchequer Office, Westminster.

#### Cloth Measure.

						Nails.		Inches.
			Q	uarter	s.	1	=	21
•		Yards.		1	=	4	=	9 .
Ell.		1	_	4	=	16	=	86
1	=	11	=	5	=	20	=	45

The yard is the same as in long measure, but differs in its divisions and sub-divisions.

#### Yarn Measure-Cotton.

		_ ~ ~					
			Yards.				
		Hanks.		1	=	120	
Spindle.		1	=	7	=	840	
1	=	18	=	126	=	15120	

#### Yarn Measure-Linen.

						Cuts.		Yards.
				Hears.		1	=	800
		Hasps.		1	=	2	=	600
Spindle.		1	. =	6	=	12	=	8600
<b>1</b>	=	4	=	24	=	48	=	14400

#### Square Measure.

					•			Sq. Fe	e <b>t.</b>	Sq. Inches.
			1	Sq. Poles	or	Sq. Yar	ds.	1	=	144
				Perches		1	=	9	=	1296
Statute	Sq.	Roo	ls.	1	=	80 <del>1</del>	=	272 <del>1</del>	=	<b>39204</b>
Acre.		1	=	40	=	1210	=	10890	=	1568160
1	=	4	=	160	=	4840	=	48560	=	6272640
			1	square m	ile	= 640 st	atut	e acres.		

In round numbers, \(\frac{1}{2}\)d. per square yard is £10 per statute acre (actually, £10 1s. 8d.).

	4,840	square	yards make 1	statute acre.
	6150.4	- ,,	,,	Scotch acre.
	7,840	,,	,,	Irish acre.
	4,000	,,	,,	Devonshire acre.
Customary	4,000	,,	"	Somersetshire acre.
Measure.	5,760	,,	,,	Cornwall acre.
	7,840	,,	"	Lancashire acre.
	10,240	,,	"	Cheshire acre.
	10,240	**	"	Staffordshire acre.

To Reduce Statute Measure to Customary.

Multiply the number of perches statute measure, by the square feet in a square perch statute measure; divide the product by the square feet in a square perch customary measure, and the quotient will be the answer in square perches customary.

To Reduce Customary Measure to Statute.

Multiply the number of perches customary measure, by the square feet in a square perch customary measure; divide the product by the square feet in a square perch statute measure, and the quotient will be the answer in square perches statute.

Square Measure-Land.

			_	8	q. Per	Sq. Links	
			Sq. Chains.		1	=	625
	Sq. Roods.		1	=	• •	=	10000
Acre.	1	=	2.5	=		=	25000
1	= 4	=	10 ·	=		=	100000

The chain with which land is measured is 22 yards long.

Solid or Cubic Measure.

		Cubic Feet.		Cubic Inches.
Cubic Yard.		1	=	1728
1	=	27	=	46656

Liquid Measure.

		239,000	1.2000	Pints.		Gills.
		Quarts.		1	=	4
Gallon.		1	=	2	=	8
1	=	4	=	8	=	82

The standard measure of capacity, both for liquids and dry goods, is the imperial gallon, being equal to a volume of distilled water of

277.274 cubic inches, weighing 10 lbs. avoirdupois, at the temperature of 62° Fahr., and 30 inches atmospheric pressure.

Liquid Measures used by Apothecaries.

	Wine Measure.										Quart	Pints.	
									Gallor	ıs.	1	=	2
						T	ierce	8.	1	==	4	=	8
				I	Hhds.		1	=	42	=	168	=	386
		E	unch.		1	=	11	=	68	=	<b>252</b>	=	<b>504</b>
	Pipes.		1	=	11	=	2	=	84	=	886	==	672
Tun.	1	=	11	=	2	=	8	=	126	=	504	=	1008
1 =	2	=	8	=	4	=	6	=	252	=	1008	=	2016

Ale and Beer Measure. Quarts. Pints. Gallons. 1 = Firkins. 1 = 4 = Kildkns. 1 = 9 = 86 = 2 = 18 =Barrels. 1 = 72 = 144Hhds. 1 4 = 86 = 144 = 288 $1\frac{1}{2} =$ 6 = 54 = 216 = 482 Punch. 1 = 8 = Butt. 1 = 11 =2 = 4 = 8 = 72 = 288 = 576  $1 = 1\frac{1}{2} = 2 =$ 8 6 = 12 = 108 = 432 = 864=

#### Dry Measure.

							•				Gallons.		Pints.
									Pecks.		1	=	8
						]	Bushe	ls.	1	=	2	=	16
				Qu	arter	s.	1	=	4	=	8	=	64
]	Lo	ads	or '	Weys.	1	=	8	=	<b>32</b>	=	64	=	<b>512</b>
Last	ŧ.		1	=	5	=	40	=	160	=	<b>820</b>	=	2560
1		=	2	=	10	=	80	=	820	=	640	=	<b>5120</b>
				8 bu	shels	=	1 sack	<b>=</b>	3.85 cub	ic f	eet.		

12 sacks = 1 chaldron = 46.2 cubic feet.

The imperial bushel contains 80 lbs. avoirdupois of distilled water, and its content is 2218.192 cubic inches, or 1.283 cubic feet.

#### Table of Time.

			·	Minutes.		Seconds.
		Hours.		1	=	60
	Days.	1	=	60	=	8600
Week.	1 :	= 24	=	1440	=	86400
1 =	7 :	= 168	=	10080	<u>-</u>	604800

28 days = 1 lunar month.

28, 29, 80, or 81 days = 1 calendar month.

1 common year = 865 days, or 52 weeks 1 day.

1 leap year = 866 days, or 52 weeks 2 days.

1 Julian year = 865 days 6 hours.

1 solar year = 865 days 5 hours 48 minutes 49 seconds.

80 degrees = 1 sign.

12 signs = 1 circle of the zodiac.

#### CIRCULAR AND ANGULAR SPACE.

60'' (seconds) = $1'$ (minute).	l 60°	= 1 sextant.
60' = 1° (degree). 80° = 1 sign	90°	$= \left\{ \begin{array}{l} 1 \text{ quadrant.} \\ 1 \text{ right angle.} \end{array} \right.$
$45^{\circ}$ = 1 octant.	860°	= A circle.

The earth moves through 860° in 24 hours, therefore 15° = 1 hour, and 1° = 4 minutes.

# TIME IN WHICH ANY SUM DOUBLES ITSELF, AT RATES OF INTEREST BOTH SIMPLE AND COMPOUND.

Rate of		ich the sum is oled, at	Rate of		Years in which the sum is doubled, at			
Interest per cent.		Interest per cent.	Simple Interest.	Compound Interest.				
1 2 2 3 8 8 8 4 4	100 50 40 381 287 25 22;	69 · 6608 85 · 0028 28 · (701 28 · 4498 20 · 1488 17 · 67808 15 · 7478	5 6 7 8 9 10 11	20 162 147 121 111 10 911 81	14·2067 11·8957 10·2448 9·00646 8·04328 7·27254 6·64189 6·11626			

# FRENCH WEIGHTS AND MEASURES— DECIMAL SYSTEM.

			Weigh	ts.		•	•
	French.		•			English.	
Milligramme	$=\frac{1}{1000}$ or	·001	gramm	е	=	0.01548	grains.
Centigramme	$= \frac{1}{100}$ OI	.01	,,	:	=	• 0.1548	٠ ,,
Décigramme :	$= \frac{1}{10}  0$	· ·1	,,	:	=	1.5482	,,
					1	15.482949	,,
					- 1	0.648	dwt.
Gramme :	= 1				_ J	0.08215	oz. troy.
GRAMME :	= 1		"		_ )	0.08527	oz. avoir.
					- 1	0.0022	lb.
					- 1	0.000019	7 cwt.
					(	154.82	grains.
Décagramme :	= 10		gramm	es :	= {	0.8527	oz. avoir.
					(	· 0·022	lb. ,,
					(	1,548-28	grains.
Hectogramme	= 100		,,	:	<del>-</del> {	8.527	ozs. avoir.
					(	0.22046	lb. "
					1	15,482.849	grains.
					١	$82 \cdot 15$	ozs. troy.
						<b>85·27</b> 89	" avoir.
Kilogramme :	= 1,000		,,	=	={	2.2046	lbs.
•			•			<b>2</b> ·679	" troy.
					- 1	0.01968	cwt.
					1	0.00098	ton.
					(	22.046	lbs. avoir.
Myriagramme	=10,000		,,	=	= {	0.1968	cwt.
					(	0.00984	ton.
Quintal	= 100,0	0 <b>0</b> gra	mmes :	==		20·46 lbs. or 1	cwt. 3 qrs.
						241 lbs.	
Millier or bar	= 1,000,0	00	,,	= 2		04.62 lbs. or 19	cwt. 2 qrs.
						203 lbs.	

The Gramme is the unit of measures of weight, and is the weight of a cubic centimetre of distilled water at its maximum density (39° Fahr.) in vacuo, at sea level in the latitude of Paris, barometer 29.922 inches.

		F	Engl	ish.				French.				
Grain	•	•	•	•	•	•	=	0.064799	grammes.			
Dwt	•		•	•	,		==	1.555	,,			
$\mathbf{Dram}$	•	•	•	•	•	•	=	1.771846	,,			
Ounce,	tro	у.	٠	•	•	•	=	81.1085	"			
Ounce,	avo	oirdi	ıpoi	8.	•	•	=	<b>28·84</b> 96	,,			
Pound		,,		•	•	•	={	458·59 0·454	,, kilogramme.			
Pound,	tro	y	•	•	•	•	={	878·226 0·878226	grammes. kilogrammes.			
Cwt.	•	•	•	•	•	•	=	<b>50·8</b>	"			
Ton .	•	•	•	•	•	•	_={	1,016.05 1.01605 1 tonne × .	tonnes. 984.			

# Lineal or Long Measure.

	French.					English.	
					(	0.08987	inch.
Millimètre	$=\frac{1}{1000}$ or •	001 m	ètre	•	= {	0.00828	foot.
				٠	(	0.00109	yard.
					(	0.8987	inch.
Centimètre	$=\frac{1}{100}$ or	·01	,,	•	= {	0.0328	foot.
					(	0.0109	yard.
					(	8.9871	inches.
Décimètre	$= \frac{1}{10}$ or	•1	,,		= {	0.8281	foot.
					Ų	0.1098	yard.
					i	89 · 87079	inches.
3/					- 1	$3 \cdot 2808992$	feet.
METRE	=	1	"	•	= 1	1.09868805	6 yards.
					(	0.00062	mile.
					1	393·707 <b>9</b>	inches.
D/		10	. 11		1	$92 \cdot 809$	feet.
Décamètre	=	10 n	aètre:	в.	= 1	10.986	yards.
					(	0.0062	mile.
					1	8,987 • 079	inches.
TT and and Man		100			1	$828 \cdot 09$	feet.
Hectomètre	=	100	,,	٠	= {	109.36	yards.
					(	0.06214	mile.

***************************************									_		<del>1</del> 03
		Fr	ench.						Englis	ıh.	
٠.									89,870.79	_	inches.
Kilomèt	ro.	_		1 00	Λ	14			8,280.9		feet.
	10			1,00	υm	etr	95.	=	1,098-68		yards.
									0.6218	RΩ	mile.
									(898,707·9	,,	inches.
Myriam	d+ma		4.		^				82,809.0		
J110III	me	=	10	0,00	U	,,	•	= .	10.986.8		feet.
									6.2188	00	yards.
Ligne or	line			_	_			_			miles.
Pouce or	inch	= 1	12 line		•	•	•	_	0.0888		inch.
Pied or f	oot	= ]	12 pone	Seg.	•	•	•	_	1.0658	_	inches.
Toise =	6 Fre	nch	feet	00	•	•	•	=	12.7899	6	,,
The M	<b>Iè</b> tre	is t	he nni	· · of	1;	•	•	=	76.74		22
part of 9	0° of	the	moridia	, OI	ш	AST	me	asur	76.74 e, and is the	10 n	illionth
Ţ 05 U	0 01	<b>.</b>	Engl	ш.							
			Tangr	1841.					French		
T1								(	25.89954		imètres.
Inch .	• •	•	• •	•		•		_ ]	2.54		imètres.
								1	0.254		mètre.
Foot .								'	0.0254	mètı	re.
Yard .	•	•	• •	•	•	•	•	=	0.8048	,,	
Fathom	•	•	• •	•	•	•	•	=	0.9144	,,	
Pole .	• •	•	• •	•	•	•	• .	=	1.8287	mètr	es.
Chain	• •	•	• •	•	•	•	•	=	5.0291	,,	
	• . •	•	• •	•	•	•	•	=	20.116	"	
Furlong								_ 1	201.16	,,	
					•	•	•	- {	0.20116		nètre.
Mile .				_				_ (	1,609.815	mètr	
			•	•.	•	•	•	= {	1.609815		
			_	Sq	uare	3 M	eası	ıre.			TC OT CD.
			Frenc	h.					English		
Milliare	=	<b>=</b> { 1	000 0	r ·(	001	are	1) _	_ (	155.00	sq.	ins.
		lo	r sq.	déca	mèt	re.	} -	- {	1.0764		feet.
								(	0.1196	,,	yard.
								(1	l,550·ó		ins.
Centiare	)		_					- 1	10.764		feet.
or sq.	} =	= {	idécar	r	01	pa	• )	_ ]	1.1960832	92	vards.
mètre.	)	(	décar	nètr	e ,	•	. } :	٦-	0.03954		perch.
	•							ı	0.00099		rood.
								(	0.00025		acre.
								•		2 1	
										- 41	

	French.	English.	
•		(15,501.0	sq. ins.
		107.64	,, feet.
Déciare	$= \begin{Bmatrix} \frac{1}{10} \text{ or } \cdot 1 \text{ sq. déca-} \\ \text{mètre} \qquad \cdot \qquad \cdot \end{Bmatrix} = 7$	11.96088	,, yards.
Deciare	mètre	0.8954	,, perch
	`` (	0.0099	,, rood.
	<u>.</u>	<b>0.0025</b> : .	,, acre.
•	_	/ 1,076.4	,, feet.
A== == == \		119.6058	,, yards.
ARE OF BU	= 1 sq. décamètre. =	8.954	,, prchs.
decametre.	. , -	. 0.099	,, rood.
•		0.0247	,, acre.
		1;196:038	,, yards.
Décare	$= \left\{ egin{matrix} 10 &  ext{ares} &  ext{or} &  ext{sq.} \\  ext{d\'ecam\`etres} & . & . \end{matrix}  ight\} = .$	89.54	,, prchs.
Decare	décamètres }	0.99	", rood.
		0.2471	,, acre.
•		11,960.3	,, yards.
Hectare	(100 ares or sq.\)	895.4	,, prehs.
TTCOMME	$= \left\{ \begin{array}{ccc} 100 & \text{ares or sq.} \\ \text{décamètres} & . \end{array} \right\} = \left\{ \begin{array}{c} 100 & \text{ares or sq.} \\ \text{decamètres} & . \end{array} \right\}$	9.89	,, roods.
•	•	2.4712	,, acres.

The are, which is a square décamètre, is the unit of square measure.

		En	glish	١.		French.					
Square inch	•						=	645.187	sq.	millimètres. mètre.	
Square foot				•			=	0.0929	,,	,,	
Square yard		•		٠.		•	=	0.8361	,,		
Square perch							=	25.292	,,	mètres.	
Square rood						•	=	1,011.7	,,	,,	
Square acre							=	4,046.7	,,	,,	
Square mile						•	=	2.59	,,	kilomètres.	

#### Solid Measure.

French. English.

Millistère = 
$$\left\{\begin{array}{ccc} \frac{1}{1000} \text{ or } \cdot 001 \text{ stère} \\ \text{ or cubic mètre} \end{array}\right\} = \left\{\begin{array}{ccc} 61 \cdot 028 & \text{ cubic inches.} \\ 0 \cdot 035817 & \text{,, foot.} \end{array}\right\}$$

Centistère =  $\left\{\begin{array}{ccc} \frac{5}{100} \text{ or } \cdot 01 \text{ stère} \\ \text{ or cubic mètre} \end{array}\right\} = \left\{\begin{array}{ccc} 610 \cdot 28 & \text{,, inches.} \\ 0 \cdot 35817 & \text{,, foot.} \end{array}\right\}$ 

```
English.
                          French.
                                                                   6,102.8
                                                                                        cubic inches.
                   = \left\{ \begin{array}{ccc} \frac{1}{10} & \text{or } \cdot 1 & \text{stère} \\ \text{or cubic mètre} \end{array} \right\} = \left\{ \begin{array}{ccc} \frac{1}{10} & \text{or } \frac{1}{10} & \text{stère} \\ \frac{1}{10} & \text{or } \frac{1}{10} & \text{stère} \end{array} \right\}
                                                                          8.5817.
                                                                                                 feet.
                                                                                           ,, yard.
                                                                          0.1808
                = \left\{ \begin{array}{ccc} 1 & \text{stere or cubic} \\ \text{metre} & \cdot & \cdot \end{array} \right\} = \left\{ \begin{array}{ccc} 61,028 \cdot 0 \\ 85 \cdot 817 \\ 1.000 \end{array} \right. 
                                                                                           ,, inches.
                                                                                           " feet.
                                                                                           " yards.
                                                                          1.808
Myriastère = 10,000
                                                            = 18.080 \cdot 224
     The Stère, which is a cubic mètre; is the unit of solid measure.
                          English.
                                                                        French.
                             = \begin{cases} 0.000016886 \text{ stère or cubic mètre} \\ 16,886.0 \text{ cubic millimètres}. \end{cases}
Cubic inch .
Cubic foot . .
                                        0.028815
                                                               stère or cubic mètre.
1,000 cubic feet =
                                          28.815
                                                               stères or cubic mètres.
Cubic yard . . =
                                          0.7645181
                                                               stère or cubic mètre.
                        Dry and Fluid Measure (Capacity.)
                                                                          English.
Millilitre = \begin{cases} \frac{1000}{1000} \text{ or } \cdot 001 \text{ litre} \\ \text{or cubic décimètre} \end{cases} = \begin{cases} \end{cases}
                                                                   0.0610
                                                                                  cubic inch.
                                                                   0.00022 imperial bushel.
Centilitre = \left\{\frac{1}{100} \text{ or } \cdot 01 \text{ litre or } \right\} = \left\{
                                                                   0:61028 cubic inch.
                                                                   0.0022
                                                             6·1028 cubic inches.
                                                                                  imperial bushel.
                                                                                   imperial bushel.
                                                                 61.028 cubic inches.
 gallon.
                                                                   0.0275
                                                                                                bushel.
                                                               610.28 cubic inches.
Décalitre =  \begin{cases} 10 \text{ litres or cubic} \\ \text{décimètres.} \end{cases} = \begin{cases} 0.028 & \text{cubic inches.} \\ 0.858 & \text{,, foot.} \\ 2.2 & \text{imperial gallons.} \end{cases} 
                                                                                                bushel.
```

	French.	Engl	ish.
		<b>6,102.8</b>	cubic inches.
Haatalitra —	(100 litres or cubic)	8 · 58171	,, feet.
Heccounte =	{100 litres or cubic décimètres } =	<b>22·0</b>	imperial gallons.
	,	2.751	,, bushels.
	{1,000 litres or cubic décimètres }	85.8171	cubic feet.
Kilolitre =	enhic décimètres =	220.02	imperial gallons.
	(capic decimestes.)	27.512	,, bushels.
	{10,000 litres or cubic décimètres .} =	858 • 171	,, cubic feet.
Myrialitre =	anhic décimètres =	2,202 · 15	imperial gallons.
	(ouble deciments)	275 • 121	,, bushels.
The Litre,	which is a cubic décime	ètre, is the un	it of measures of
capacity.			
	English.	Fren	ch.
<i>~</i>			

		French.								
Cubic inch	•	•	•	•	•	•	•	=	0.016386	litre.
Cubic foot	•	•						=	28.315	litres.
1,000 cubic	fee	ŧ.		•		•		=	28,815.0	,,
Imperial pir	ıt		•					=	0.5676	litre.
Imperial gal	llon	١.						=	4.541	litres.
Imperial bu	she	1			•	•	•	=	86·828	"

#### MONEY TABLES.

#### France.

Name.									English Value.
Centime	•			•	•	•	•	=	19 or 095d.
Franc			centi						9 <del>1</del> d.
Sou	=	5	,,					=	18 or ·475d.
Napoléon	=	20	franc	B				=	15s. 10d.

Accounts are kept in francs and centimes. For convenience in reckoning, a sou may be taken as equal to  $\frac{1}{2}$ d., a franc as 10d., and 25 francs as 20s.

# Belgium.

The Belgian currency is in centimes and francs, having the same English money value as those of France.

To convert centimes per cubic mètre into pence per 1,000 cubic feet, and vice versa.

Centimes per cubic metre  $\times$  2.7 = pence per 1,000 cubic feet. Pence per 1,000 cubic feet  $\times$  .87 = centimes per cubic metre. To convert centimes per litre into pence per 1,000 cubic feet, and vice versa.

Centimes per litre  $\times$  2,700 = pence per 1,000 cubic feet. Pence per 1,000 cubic feet  $\times$  00087 = centimes per litre.

#### UNITED STATES OF AMERICA.

	Name.									I	Inglish Value.
Cent.			•	•	•	•	•	•	•	=	₫d.
Dollar	= 100	cents	•	•	•	•	•	•	•	=	4s. 2d.
44, or	4.8 do	lars, or	: 4 d	lolle	irs !	80 c	ent	g .		=	£1
Dollar										=	£1

To convert dollars and cents per 1,000 cubic feet into pence per 1,000 cubic feet, and vice versa.

Dollars and cents per 1,000 cubic feet  $\times$  50 = pence per 1,000 cubic feet.

Pence per 1,000 cubic feet  $\times .02 =$  dollars and cents per 1,000 cubic feet.

TABLE.

Foreign and Colonial Equivalents of English Money.

(Actual or Approximate.)

Country.	Powed Sterling, Equal to,—	Brilling, Equal to,—	PENNY, Equal to,—
Argentine Republic	10 Patacon or Dollars	50 Centimos	. 4 Centimos.
Austria	101 Florins	{ Florin, or 50 } Kreutzers.	4 Kreutzers.
Belgium	25 France	11 Francs	10 Centimes. 3 Centenas.
Brazil	10 Milreis	Heis	40 Reis.
Canada	4 Dollars 5 Pesos	25 Cents 25 Centavos	2 Cents. 2 Centavos.
China {	5 Dollars, or 81 Taels, or 35 Mace	25 Cents, or 13 Mace	2 Cents, or 1½ Candareen.
Columbia	5 Pesos 20 Krons	25 Centavos 1 Krona	2 Centavos. 8½ Ore.
Ecuador Egypt	5 Pesos	25 Centavos 5 Piastres	2 Centavos.
Finland	25 Marks	1 Marks	Paras. 10 Penni.
France	25 Francs	11 Francs	10 Centimes. 8½ Pfennig.
Greece	25 Drachmæ	Pfennig	10 Lepta.
Holland	12 Florins	60 Cents	5 Cents.
Hungary	101 Florins	Kreutzers	4 Kreutzers.
India {	10 Rupees and 4)	9 Annas	8 Pies.
Italy	25 Lira	11 Lira	10 Centesimi. 2 Sen.
Japan	12 Florins	60 Cents	5 Cents.
Malta	12 Scudi	7 Tari, 4 Grani .	12 Grani.
Mexico	5. Pesos or 5 Dols.	25 Centavos	2 Centavos.
Norway	20 Krona	1 Krona	84 Ore.
Paraguay	6 Dollars	36 Centena	3 Centena.
Persia	2½ Toman	12 Shahis	1 Shahi.
Peru	5 Sol	21 Dineros	2 Centos.
Portugal	5 Milreis	24 Testoes	20 Reis.
Russia	61 Silver Roubles	48 Copecks	4 Copecks.
Spain.	26 Pesetas	11 Pesetas	10 Centimos.
weden	20 Krona	1 Krona	81 Ore.
Switzerland Funis	25 Francs 40 Piastres	11 Francs	10 Centimes.
Furkey	120 Piastres	6 Piastres	Paras.
Juited States	4 Dollars	25 Cents	2 Cents.
Uruguay	5 Pesos	25 Centavos	2 Centavos.
Venezuela	5 Pesos	25 Centavos	2 Centavos.

# INDEX.

Abrupt angles in pipes and fittings to be avoided, 243.

Absorption of the hydrocarbons by india-rubber tubing, 285.

"Acme" regulating burner, 285.

Act, 1871, Gas Works Clauses, 293, 318.

on testing for purity, 293.

on testing for illuminating power, 318.

Act, 1859, Sales of Gas, 260, 264, 266.

provisions as to stamping meters, 260.

Advantages of using an exhauster, 85.

a station governor, 192.

Aerorthometer, A. V. Harcourt's, 322.

Air and gas, loss of light by mixing, 336.

permanent gases expanded by heat, 75. water, as cooling agents, compared, 80.

Airey's table showing the dilatation of gas in contact with water, 279.

Aitken and Young's analyzer, 82.

Algebraical and arithmetical signs, 468, 469.

Allen's Beale's exhauster, 86.

Alloys of metals, 453.

Ammonia, affinity for water, 90, 92, 390.

carbonate of, 393.

caustic, purification by, 113.

impurity in coal gas, 103, 104.

liquid, 379, 397.

muriate of, or sal ammoniac, 375.

sulphate, of, 375 to 378.

yield of, per ton of coal, 378.

test for, 292, 296, 302.

Ammoniacal liquor, 375 to 381.

Beaume's hydrometer, 380, compared with specific gravity, 381. quantity of, obtained to outlet of scrubbers, 375.

result of application of, to land, 389.

specific gravity and weight of, 378, 380.

strength of, 378.

testing by saturation, 379.

to convert Twaddel into specific gravity, 378.

Twaddel's hydrometer, 378.

Wills' method of testing, 379.

Analyses of coals and cannels, 16, 17.

furnace gases, 51.

the ash of a good Newcastle coal, 14.

Analyzer, Aitken and Young's, 82.

Anderson's combined washer and scrubber, 100.

exhauster, 86, 87.

washer, 91.

Angle of repose of earths with horizontal line, 139.

Angles in mains, services, and internal fittings, 243.

Angular and circular space, 480.

Annular atmospherical condenser, 78.

Kirkham and Wright's, 78.

Warner's, 78.

Annular or ring tanks, 134, 139, 164.

Anthracite or glance coal, 11.

weight per cubic yard, 27.

Apparatus for coal testing, 23.

required for testing meters, 264. illuminating power testing, 309.

Approximate multipliers for facilitating calculations, 469, 470.

Architectural and mechanical drawing, colours used in, 464.

Area of coal measures in the United Kingdom, 11.

Area required for atmospherical condensation, 80.

for purifiers, 119.

Areas, etc., table of, 471 to 474.

Argand, Sugg's, London, 310.

Arithmetical and algebraical signs, 468, 469.

Arnold on the application of sulphate of ammonia in agriculture, 384.

Arson (M.) on masonry tank walls, 145.

Ascension or stand pipes, 58, 59.

choking of, 59.

Ash in coal and coke, 12 to 14, 16, 17.

Ash pan, furnace, 55, 56.

Ashes in mortar, 445.

Atmospherical condensation, 76.

annular condensers, 78.

area required for, 80.

atmospherical and water condensers combined, 80.

Graham's condenser, 77.

horizontal condensers, 76, 77.

Auction clauses, the, 424.

Aurum mosaicum, or gold bronze powder, 288.

Authorized Gas Fitters, 282.

Automatic pressure changer, Cowan's, 195.

Braddock's, 194, 195.

Average meter system for public lighting, 256.

Average yield of bituminous coal, 27.

Axioms worth remembering, 241.

Balance and weights, experimental, 318.

Ball and socket joint for main pipes, 204.

Bar, graduated photometer, 317.

Bars, grate or fire, and bearing, 56.

Barker's mill for distributing water in scrubbers, 95.

Barometer and thermometer used in testing illuminating power, 318.

Battery or tubular condenser, 79.

Beale's exhauster, 85.

Beaume's hydrometer, 380, 381.

Bench, single and double retort, 31, 34.

clear space in front of, 33.

flues and draught, 49.

Binney's observations on coal, 14.

Birmingham wire gauge, thickness of the, 447.

Birmingham gauge, 447, 448.

Bisulphide of carbon, purification from, 107.

test for, 297, 305.

Bituminous coal, 11. average yield of, 27.

weight per cubic yard, 27.

Blue or Bengal fire, 350.

Boiler and engine, steam, 88.

Bolts and nuts, 205, 450.

Bond in brickwork, 437.

Books required in the keeping of a Gas Company's accounts, 457 to 460.

Borders, illuminated, 349.

Bored and turned joints for main pipes, 8, 200, 201, 203.

Botley's carburetting arrangement, 74.

Box's table of the mean temperature of every tenth day, 76.

Brackets and chandeliers, height of, 282.

Braddock's public lamp column, 252, 253.

station governors, 193 to 195.

Brass or iron, mixture for tinning, 287.

Brass tube, plain, spiral and fluted, weight per foot, 286.

Brass work for lacquering, to clean, 291.

"Brasses" in coal, 15, 19.

Bray's street lamps and burners, 9, 253, 254.

ventilating globe lights, 283. burners for internal lighting, 283.

Brazing, 287.

Breeze and coke, 370.

weight per cubic yard, 27.

Bremond on naphthalene, 73.

Bricks and brickwork, 436 to 443.

Bond in brickwork, 437.

number of bricks in walls of different areas, 439 to 443. usual dimensions of bricks, 436.

Brick and puddle tanks, 139, 141, 145 to 158.

Brick retorts, 39.

Brickwork in retort settings, 40.

Bridge and dip pipes, 59, 64, 65.

Brin's oxygen process in purification, 110.

British standard unit of heat, 414.

Bronze, 288, 289.

copper bronze powder, 288.

gold bronze powder, or aurum mosaicum, 288.

green, 288.

powders, 288.

size for bronze powders, 289.

Brown or lignite coal, 12.

Brunswick Stars, 348.

Buckstaves for retort bench, 54.

Bunsen photometer, the, 317, 318.

Burner, "Needle" governor, 285.

Burners, number required for lighting large buildings, 284.

objections to horizontal, 282. standard, 310, 318.

Bye-pass mains and valves, 101.

Caking coal, 11.

Calcining spent lime, Hislop's process for, 105.

Calcium sulphide, purification by, 107.

Calorie (French), 414.

Calorific power of various photogenic compounds, 412. Candle, standard sperm, 317, 319.

balance and weights, 308.

corrections in consumption of, 319.

Cannel, 11, 14, 17.

and coals, analysis of, 12 to 14.

ash in, 14. origin of, 15.

weight of per cubic yard, 27.

Capacity of gasholders, 174.

of coal stores, 18.

of tar and liquor wells, 101.

Capital of gas works, 420.

Carbon in coal, 12, 13.

in retorts, deposition of, 51.

Carbonic acid, test for, 292, 300. Sheard's apparatus, 294.

Carboniferous series, 10.

Carbonizing, fuel for, 52 to 54.

Carburetted water gas, 345.

Carburetting condensers, 82.

methods of, 74.

Carcel lamp, the, 324.

Cast, wrought-iron, and steel gasholder tanks, 134, 139, 144, 148, 161.

Casting of main pipes, 197.

Cast iron pipes, 197.

cost of laying, 217, 218. weight and cost of, per yard, 219 to 227.

weight of lead for jointing, 210.

Cast-iron retorts, 4, 38, 43.

duration of, 44.

Fraser's ribbed, 38.

Cathels' washer, 91.

Caustic ammonia, purification by, 113.

Caustic soda and sulphide of sodium, purification by, 112.

Cement for jointing retort mouthpieces, 57.

for steam joints, 90.

for stopping leaks in boilers, 90.

glue to resist moisture, 291.

iron or rust, 211.

mastic for buildings, 445.

mortar, Portland, 144.

or luting for retort lids, 58.

Portland, 144, 200.

Cement—continued.

Roman, 200.

Centigrade thermometer compared with Fahrenheit and Reaumur, 83, 84.

Centre and other change valves, 122.

Chains, safe load on, 451.

weight of, 451.

Chandeliers and brackets, height of, 282.

Change valves, 122.

Changer, Cowan's Automatic Pressure, 195.

Channel condenser, water, 80.

Charging shovels, 70.

Chemical and other memoranda, 404 to 417.

common names of certain chemical substances, 408, 409.

elementary substances, 404.

expansion of liquids from 32 deg. to 212 deg. Fahr., 417. expansion of metals, on a rise in temperature, 417.

luting, for experiments in chemistry, 410.

melting points of various substances, 417.

relative power of metals for conducting and reflecting heat, 417. specific gravity, weight, and solubility in water, of various gases, 409.

specific heat of solids, liquids, vapours and gases, 416. substances, simple and compound, 406.

Cherry coal, 11.

Chief kinds of coal, 11.

Chimney stalks for retort houses, 50.

rule for size of, 50.

Choking of ascension pipes, 59.

Circular and angular space, 480.

Circumferences, etc., table of, 471 to 474.

Cistern for tar and lipuor, elevated, 102.

Classification of limestones, 124.

Claus' process of purification by ammonia gas, 113.

water, memoranda relating to, 415.

Clay, fire, 437, 438.

constituents of, 438.

Clay puddle, 144.

Clay retorts, 4.

temperature of carbonization with, 43. thickness of, 38.

Clegg's continuous stoking machinery, 5, 71.

Clegg, Samuel, one of the chief pioneers of gas lighting, 2.

Cleland's slow speed condenser, 79.

Cleland and Korting's steam jet exhauster, 88. Coal, 10 to 29.

analyses of, 12 to 14.

analysis of the ash of a good Newcastle, 14.

anthracite or glance, 11.

ash in, 12, 13, 14.

bituminous, 11.

"brasses" in, 15.

brown or lignite, 12.

caking, 11.

carbon in, 12, 13.

cherry, 11.

chief ingredients of which it is composed, 12, 13.

chief kinds of, 11, 12.

coke, production of, from, 12 to 14.

Cumberland, 11.

Derbyshire, 11, 13.

deterioration of, by exposure, 15.

gases occluded in, 20.

geological position of, 10.

glance or anthracite, 11.

Gloucestershire, 11, 13.

hydrogen in, 12.

in hot climates, deterioration of, 18.

iron pyrites in, 15, 19.

Lancashire, 11, 12.

lignite or brown, 12.

measures, area of, in the United Kingdom, 11.

nitrogen in, 12, 13.

Newcastle, 12.

oxygen in, 12, 13.

parrot or cannel, 11.

production of coke from, 12, 13, 14.

products, 390 to 403.

Scotch, 11, 13.

sheds, 18.

Somersetshire and other, 11.

specific gravity of, 12 to 14, 25.

splint, 11.

Staffordshire, 11.

storage, 18.

sulphur in, 12 to 15.

testing, 21.

Coal-continued

value of, in pounds of sperm, 28. volatile matter in, 12 to 14.

Welsh, 11, 13.

Wigan, 12.

yield of sulphate of ammonia per ton, 378.

Yorkshire, 11.

Coating and painting of gasholders, 171.

of main pipes, 205.

Coefficients: Cost of gas-works, 429 to 435.

Cockey's apparatus for raising purifier lids, 121. washer-scrubber, 100.

Coke and breeze, 370.

breaking hammer, 370, 371. breaking machinery, 370, 371. slaking or quenching of, 52. sulphur in, 15.

weight per cubic yard, 27.

Coloured fires for illumination, 349 to 351.

blue or Bengal, 350. crimson, 350.

erimson, 350

green, 350. lilac, 349.

mixing the ingredients for, 351.

purple, 349. red, 350.

white Indian, 351.

yellow, 349.

Colours of high temperatures, 43.

used in mechanical and architectural drawing, 464.

Colson on the bye-products from a ton of tar, 373.

Columns, height of lamp, 252.

Combined atmospherical and water condenser, 80.

Combustion, temperature, explosive power, and mechanical power of gases, 413.

Commercial and structural value, 427.

Common names of certain chemical substances, 408, 409.

Comparison of Fahrenheit's, Reaumur's, and the Centigrade thermometers, 83, 84.

Compensating meters, 260.

Hunt's 261.

Sanders and Donovan's, 260, 261.

Urquhart's "Reliance," 261.

Warner and Cowan's, 260.

Composite tanks, 159.

Composition of gas lime and its use in agriculture, 387, 388.

Composition pipes, 286.

Concrete and mortar, 444, 445.

Concrete tanks, 147, 159.

Condensation, 72 to 80.

expansion of air and permanent gases by heat, 75.

extent of, 72.

loss of illuminating property in coal gas on exposure to the temperature of freezing point, 72.

mean temperature of every tenth day in the year, 76.

naphthalene, formation of, 73.

rapid or sudden as well as excessive, 72.

relative effects of water and air as cooling agents, 80.

rules for calculating the area required for atmospherical condensation, 80.

temperature as affecting registration, 75.

Condensers, 76 to 84.

Aitken and Young's analyzer, 82.

annular atmospherical, 78.

area required for, rule for calculating, 80.

battery or tubular, 79.

bye-pass mains and valves for, 101.

carburetting, 82.

Cleland's slow-speed, 79.

combined atmospherical and water, 80.

dry scrubbers as condensers, 81.

Graham's horizontal, 77.

horizontal atmospherical, 76, 77.

Kirkham and Wright's annular, 78.

Pelouze and Audouin, 81.

precipitating chambers, 81.

St. John and Rockwell apparatus, 82.

tubular or battery, 79.

underground, 81.

vertical atmospherical, 78.

Warner's annular, 78. water channel, 80.

Condensable hydrocarbons, 72 to 75.

Conducting heat, relative power of metals for, 417.

Connecting pipes for purifiers, 123.

Consumers' gas-meter, 259 to 279.

apparatus required for testing, 264. compensating, 260.

Consumers' gas meters-continued.

dilatation of gas in contact with water, 279.

dry meter, description of the, 259.

effect of over-driving the meter wheel, 261.

Greenall and Heaton's "Positive," 262.

Hunt's meter, 261.

inspection of, 262.

percentage tables for testing, 266 to 279.

protection of from frost, 262.

provisions of sales of Gas Act, 1859, as to stamping, 264.

sizes of meters desirable to be used, 261.

testing, 264.

Urquharts "Reliance," 261.

Warner and Cowan's, 260.

wet meter, description of the, 259.

Consumption and pressure, 197.

Consumption of gas by one burner per month and for 12 months, 257.

of gas per head of population, 427.

of gas per mile of main, 427.

Contraction of cast-iron pipes in cooling, 202.

Cooking, use of gas for, 368. Copper bronze powder, 288.

Corrections for temperature, pressure, and moisture, 312, 319, 320

in consumption of gas and standard candle, 319.

Cost of gas works, 429 to 435.

Counterbalancing of gasholders, 166.

Cowan's automatic changer, 195.

governor, 195. ventilating globe lights, 283.

Coze's system of inclined retorts, 5, 36, 37.

Crimson coloured fire, 350.

Crosley's pressure and exhaust registers, 133.

Crossley Brothers' "Otto" gas-engine, 9.

Cubic foot measure, one-twelfth Referees', 315.

Cumberland coal, 11.

Cyanogen recovery, 383.

D-shaped retorts, 38, 39.

Dalton and Ure's table of aqueous vapour in gas, 339.

Damp or wet coals, result of using, 18.

Damper to control draught, 49.

Day and night, rule to find the length of, 256.

Decigallon and septem, 475.

Decimal and fractional parts, 467.

Decimal system of weights and measures, 481 to 486.

Dempster's exhauster, 86.

Denayrouze burners for street lighting, 255.

Density of various gases, 343.

Deposition of carbon in retorts, 51.

Derbyshire coals, 11, 13.

Deterioration of coal by exposure to weather, 15.

in hot climates, 18.

Devices for public illuminations, 347, 352 to 367.

coloured fires, 349 to 351.

illuminated borders, 349.

prices of, 348.

Devonian rocks, 10.

Diameters, etc., table of, 471 to 474.

Dibdin's 10-candle pentane argand, 327 to 330.

Differential or district governors, 196, 197.

Dilatation of gas in contact with water, 279.

Dimensions of the principal materials in gasholders in actual working, 175 to 192.

Dinsmore system of gas making, 54.

Dip in the hydraulic main, 64.

Dip-pipes, 59, 60, 64.

Dip-well for sealing pipes, 101.

Disc for testing illuminating power, 311, 819

Discount for early payment of gas bills, 460.

Distance apart of public lamps, 253.

District or differential governors, 196, 197.

Donkin's exhauster, 86.

Double retort benches, 31.

Douglas's instructions for preparing concrete, 143.

Draught and flues, 49.

Drawing papers, sizes of, 464.

Drip or syphon wells, 209, 210.

Drory's main thermometer, 82.

Drum or measuring wheel of meter, 130, 131, 259 to 261.

Dry meter, description of the, 259.

Dry or stand-pipe wells for gasholder tanks, 144.

Dry scrubbers as condensers, 81.

Drying gas, effect of, 73, 74.

Dulong on the burning of hydrogen, carbon, and carbonic oxide, 50.

Duration of retorts, 42 to 44.

Durham coal, 11, 12.

Dvorkovitz system of coal gas enrichment, 345.

Earths, natural slope of, 139.

and rocks, weight of various, 139.

"Eclipse" washer-scrubber, 97, 99.

Effect of over-driving a meter wheel, 261.

of small and bad pipes and fittings, 279.

Elementary substances, table of, 404.

Elevated tar and liquor cistern, 102.

Elevating apparatus for purifying material, 115, 116.

Engine and boiler, steam, 88 to 90. gas, 368.

Enrichment of coal gas, 344, 345.

carburetted water gas, 345.

Dinsmore system, 54.

Dvorkovitz system, 345.

Maxim-Clark system, 344.

Peebles process, 344.

Wheesoe-Munich method, 345.

Epitome of mensuration, 465 to 467.

Equivalents of English money, foreign and colonial, 487.

Evans' calorific power of various photogenic compounds, 412.

enclosed photometer, 317. Evaporation from water-slide pendants, to prevent, 282.

Evils attending the use of small pipes, etc., 244, 279.

Examples of construction of gasholders, 175 to 192.

of gasholder tanks, 149 to 166.

Excavations for gasholder tanks, 135 to 139.

Exhausters, 85 to 88.

advantages of using, 85.

Allen's Beale's, 86.

Anderson's, 86.

Beale's, 85.

bye-pass mains and valves for, 101.

Cleland and Körting's steam jet, 88.

Dempster's, 86.

Donkin's Beale's, 86.

governor for, 88.

Gwynne's Beale's, 86.

rotatory and reciprocating, 85,87.

Waller's, 86.

Expansion joints for main pipes, 204.

of air and permanent gases by heat, 75.

of liquids in volume from 32 deg. to 212 deg. Fahr., 417. of metals, 417.

Experimental governor, 318.

meter, 317.

Explosions in main pipes, 213.

Fahrenheit thermometer compared with Reaumur's and the Centigrade, 83, 84.

Faija on Portland cement, 144.

Farmer's rule, relation between production per ton and illuminating power, 29.

Fiddes' analyses of coals, 13.

proposed light standard, 325.

Fire-clay, 437, 438.

constituents of the chief English and foreign, 438.

retorts, 38. Fire or grate bars, 56.

Fires, coloured, for illuminations, 349 to 351.

Fittings, internal, 279 to 291.

service, 242 to 251. Flange joints for main pipes, 202, 204, 205.

Fletcher (Thomas), application of gas to industrial uses, 9.

Floor, retort house, 33.

ground, 31. stage, 31.

Flues and draught, 49.

Fluxes for soldering, 287.

Force and velocity of the wind, 453.

Foreign and other (proposed) home standards of light, 324 to 331.

Foreign equivalents of English money, 487.

Forms, 460 to 463.

authority to pay dividends, 462.

certificate showing that income-tax has been deducted, 463.

declaration for loss of sealed share certificates, 461.

indemnity for loss of share certificates or dividend warrant, 462. of proxy, 463.

renouncement of proposed new issue on the transfer of old shares, 460.

renunciation of shares newly allotted, 461.

Foulis's stoking machinery, 5, 71.

Fractional parts and equivalent decimals, 467.

Frankland (Professor) on the volumes of various gases absorbed by 100 volumes of water, 100.

on variations in illuminating power, 335.

Fraser's ribbed iron retorts, 38.

Freezing of water in gasholder tanks and cups, 170.

of water in governor tanks, 196.

Freezing point, loss of illuminating property in coal gas on exposure to the temperature of, 72.

French Carcel lamp, 324.

standard unit of heat, 414.

weights and measures, 475 to 487

Frost, protection of meters during, 262. public lights during, 253.

Fuel for carbonizing, 52, 53.

tar as, 52, 53.

Furnace gases, analysis of, 51.

Furnaces, generator and regenerative, retort, 38, 44.

Gadd's principle of guiding holders, 8, 169.

Galvanized pipes, 243.

Gas and air, expansion of by heat, 75.

cost price of coal gas, 420.

dilatation of, in contact with water, 279.

increase in illuminating power by drying, 73, 74.

loss of illuminating property in, on exposure to the temperature of freezing point, 72.

selling price of coal gas, 420.

value of, per cubic foot in grains of sperm, 27.

Gas-engine, 368.

Gas industry of the United Kingdom, the, 418 to 427.

initiation, development and progress, 418.

illuminating power of gas, 419.

cost price of gas, 420.

selling price of gas, 420.

capital employed, 420.

the "auction clauses," 424. the "sliding scale," 425.

sundry useful notes, 426.

Gas production, 30.

Gaseous hydrocarbons, 72.

Gases occluded in coal, 20.

various, their specific gravity, weight, and solubility in water, 409 Gasholders, 166 to 192.

at the South Metropolitan Works, 7.

at Windsor Street, Birmingham, 8.

capacity of, 174.

counterbalanced, 166.

dimensions of the principal materials in, 175.

examples of construction of, 175 to 192.

painting of, 171.

precautions to be observed in the working of, 170.

pressure of, to ascertain, 173.

Gasholders—continued. recipe for coating, 171. rise in the crown of, 167. single lift, 166, 175 to 182. telescopic, 166, 182 to 192. trussed and untrussed roofs, 167. weight of, to ascertain, 172. without upper guide framing, 168. Gasholder tanks, 134 to 166. annular or ring, 134, 139, 164. Arson (M.) on masonry walls of, 145. brick and puddle, 139, 141, 145 to 158. cast, wrought iron and steel, 134, 139, 144, 148, 161. cement mortar for, 143. composite, 159. concrete, 147, 159. Douglas's instructions for preparing concrete, 143. dry wells, 144. examples of construction of, 149 to 166. excavations for, 135, 139. Faija on Portland cement, 144. hydraulic lime mortar for, 142. leakage of water from iron, 144. materials of which tanks are constructed, 139. natural slope of earths, 139. Pole (Dr.) on masonry walls of, 145. puddle, clay for, 144. steel, 163. stone, 139, 160. thickness of walls of, 145. weight of various earths and rocks, 139. wrought-iron, 139, 148, 162. Gas lime, 387 to 389. its composition, and use in agriculture, 387 to 389. results obtained by applying certain manures to land, 389. Gas managers, golden rules for, 428. Gas meters, consumers', 259 to 279. apparatus required for testing, 264 compensating, 260. dilatation of gas in contact with water, 279. dry, description of the, 259. effect of overdriving the measuring wheel of, 261. Greenall and Heaton's "Positive" meter, 262.

Hunt's compensating, 261.

Gas meters—continued.

inspection of, 262.

percentage tables for use in testing, 266 to 279.

protection of, from frost, 262.

provisions of Sales of Gas Act, 1859, as to stamping, 264.

Sanders and Donovan's, 260, 261.

sizes of, desirable to be used, 261.

testing of, 264.

to ascertain the number of lights a meter will supply, 281.

Urquhart's "Reliance," 261. Warner and Cowan's, 260.

wet, description of the, 259.

Gas production, 30.

Gas works, buildings and apparatus of a, 422.

capital of, 420 to 424.

cost of, 427.

design of, 422.

ornamentation in, 422.

site for a, 426.

Gas Works Clauses Act, 1871, on testing for illuminating power, 818. on testing for purity, 293.

Gauges, pressure, 132 to 134.

coloured water for, 132.

differential, 132.

King's, 132

Referees' street lamp, 313.

to clean the glass tubes of, 133.

Generator and regenerative furnaces, 38, 44.

Siemens', 45.

Webber on, 45.

Glance or anthracite coal, 11.

Glass for public lamps, weight and thickness of, 256.

Globe and sun lights, ventilating, 283.

Gloucestershire, coals, 11, 13.

Glue cement to resist moisture, 291.

Gold bronze powders, or aurum mosaicum, 288.

lacquer, 290.

Golden rules for gas managers, 428.

Governor, district or differential, 196, 197.

Exhauster, 88.

k

experimental, 318.

for internal fittings, 285.

Peebles's, 196, 197.

pressure and consumption, 197.

Governor, station, 192 to 196.

advantages of the, 192.

Braddock's, 193 to 195.

construction of the, 192.

Cowan's, 195.

Cowan's automatic pressure changer for, 195.

freezing of water in tanks of, 196.

Hartley's improvements in, 194.

Hunt's, 195.

Peebles's, 194.

steam stove for governor house, 196.

valves useless as governors of pressure, 192.

variations of pressure according to level, 196.

Graduated bar of photometer, 317, 318.

Graham's horizontal condenser, 77.

Grate bars and bearers, 56.

Gravity, specific, and weight of various substances, 454, 455. to convert into Twaddel, 378.

Green bronze, 288.

Green coloured fire, 350.

Greenall and Heaton's "Positive" meter, 262.

Greville on the testing of ammoniacal liquor, 379.

Gwynne's Beale's Exhauster, 86.

H or bridge pipes, 59, 64, 65.

Hammer for breaking coke, 370, 371.

Handy multiplier for wrought-iron, 446.

rule for finding the content of a pipe in gallons and cubic feet, 241.

Harcourt's aerorthometer, 322.

colour test, 296 to 301.

proposed pentane gas standard light, 326 to 331.

Harrison and Sheard's apparatus for testing gas fittings, 282.

Hawkins' method of carburetting air used in purification, 110.

Heat-conducting power of metals, 417.

expansion of air and permanent gases by, 75. specific, of solids and liquids, 416.

Heating, use of gas for, 368.

Heats of combustion with oxygen, 414.

Heats of retorts, 43.

Height of brackets and chandeliers, 282.

of lamp columns, 252.

of retort-house chimneys, 50.

Hemp ropes, to find the weight of, 452.

Henry (Dr.), inventor of purification by lime, 2.

table of quality of gas at different periods of distillation, 26.

Hills (F. C.), and purification by oxide of iron, 6.

experiments on purification by means of ammonia, 113.

Hislop's process for calcining spent lime, 105.

Holders, gas, 166 to 192.

capacity, 174.

counterbalanced, 166.

dimensions of the principal materials in, 175.

painting of, 171.

precautions to be observed in the working of, 170.

pressure of, to ascertain, 173.

recipe for coating, 171.

rise in the crown of, 167.

single lift, 166, 175 to 182.

telescopic, 166, 182 to 192. trussed and untrussed roofs, 167.

weight of, to ascertain, 172.

without upper guide-framing, 168.

Horizontal burners, objectionable, 282.

condensers, 76, 77.

Hours, number of, during which gas is usually burned, 258.

Hughes's classification of limestones, 124.

Hulett's service cleanser, 243.

Hull's table, showing geological position of coal, 10.

Hunt's Birmingham Corporation gasholders, 8.

compensating meter, 261. station governor, 195.

Hutchinson's lamp service cleanser, 255, 256.

street service cleanser, 243, 244.

Hydraulic centre-valve, 122.

Hydraulic lime mortar for gasholder tanks, 142.

Hydraulic lute for purifier covers, 119.

Hydraulic main, 60.

dip in the, 64. size of the, 60.

the "Livesey," 60.

Hydrocarbon and other gases and vapours, 61 to 69. Hydrocarbons absorbed by india-rubber tubing, 285.

condensable, 62.

gaseous, 62 volatile, 62.

Hydrogen in coal, 12, 13.

Hydrometer, Beaumé's, 380, 381.

Hydrometer—continued. Twaddel's, 378 to 380.

Illuminating power, 309 to 321.

and specific gravity of gas, 336.

and value of gas in grains of sperm, 27.

apparatus for testing the, 309, 317.

Bunsen photometer, 317, 318.

calculations for corrections in the consumption of gas and the standard candle, 320.

candle balance and weights, 318.

corrections for temperature and pressure, 312, 320.

disc for testing, 311, 319.

experimental governor, 318.

experimental meter, 317.

from different coals and cannels, 16, 17.

graduated bar of photometer, 317, 318.

impurities and, 292.

instructions of Referees on testing for, 309 to 312.

King's pressure gauge, 318.

Kirkham and Sugg's scale for jet photometer, 333.

Letheby-Bunsen photometer, 317, 318.

loss of, on exposure to freezing point, 72.

Lowe's jet photometer, 332.

mode of testing for, 309, 318.

pressure and, 285.

Referees' 1-12th cubic foot measure, 315.

standard burners for testing, 317, 318.

standard sperm candle, 317, 319.

statutory regulations for testing, 318.

Sugg's illuminating power meter, 333, 334.

Sugg's photometer table, 321.

thermometer and barometer, 318.

Thorpe and Tasker's jet photometer, 334.

throughout the country, 419.

variations in the, 335.

various proposed standards of lights, 324.

Illuminating power meter, 333, 334.

Illumination devices, 347, 352 to 367.

Brunswick stars, 348.

coloured fires, 349 to 351.

crowns, garlands, plumes, scrolls, etc., 347, 348.

Illumination devices—continued.

illuminated borders, 349.

letters, single and double lined, 348.

mode of supply and charge for gas, 346.

service or supply pipes, 347.

Illuminations, public, 346 to 367.

Impurities and illuminating power, in coal gas, 292.

tests for the detection of, 292 to 307.

Incandescent burners for street lighting, 255.

Inclined retorts, 5, 36, 37.

India-rubber tubing, absorption of the hydrocarbons by, 285.

varnish for, 286.

Ingredients, chief, of which coal is composed, 12, 13.

Inspection of consumers' meters, 262.

Instructions for preparing concrete, 143.

of the London Gas Referees, 301.

Internal fittings, 279 to 291.

absorption of the hydrocarbons by india-rubber tubing, 285.

Bray's ventilating globe lights, 283.

burners in the horizontal position, objectionable, 282.

Cowan's ventilating globe lights, 283.

effect of small and bad pipes and fittings, 279.

globes and moons, 284.

handy rule for estimating the number of burners for lighting large buildings, 284.

Harrison and Sheard's apparatus for testing fittings, 282.

height of chandeliers and brackets, 282.

lighting of ordinary rooms, 282.

Peeble's "Needle" governor burner, 285.

pressure and illuminating power, 285.

regulations as to, 280 to 282.

regulator or governor for, 285.

salad oil in water slide pendants, to prevent evaporation, 282. sizes and lengths of pipes for number of lights supplied, 281.

sizes of meters for number of lights supplied, 281.

Strode's ventilating sun light, 283. Sugg's ventilating globe lights, 283.

varnish to prevent the escape of gas through india-rubber tubing, 286.

ventilating globe and sun lights, 283.

ventilation of rooms, 283.

Welsbach incandescent lighting, 284.

Wenham's regenerative lamp, 283.

Wright's "Acme" regulating burner, 285.

Iron and brass, mixture for tinning, 287. breaking weight of ropes of iron and steel wire, 452. contraction of cast-iron in cooling, 202. corrugated iron roofing, 450. flat bar, 446. handy multiplier, for wrought, 446. hoop iron, 449. lineal expansion of metals, 417. nuts and bolt heads, 450. round bar, 446. safe load on chains, 451. sheet iron and steel, 447. square bar, 447. steel, 447, 448. taper angle-iron of equal sides, 450. taper T-iron, 450. to resist the action of fire, 453. weight of a sphere one inch in diameter, 449. weight of a superficial foot of iron, 448. weight of chains, 451. Whitworth's screws with angular threads, 451. Iron and steel gasholder tanks, 134, 139, 144, 148, 161. leakages of water from, 144. Iron, lead, and composition pipes for internal supply, 281. Iron, oxide of, purification by means of, 106, 107. Iron pyrites in coal, 15, 19. Iron retorts, 4, 38, 43. dimensions of, 38. duration of, 44. Fraser's ribbed, 38. scurfing of, 44. temperature suitable for, 44. weight of, 38. Jet photometers, 331 to 334. Lowe's, 332. scale for, 333. Thorp and Tasker's, 334. Jet, steam, exhauster, 88. Jointing retort mouthpieces, 57.

Kay's ball and socket joint for mains, 204.

Jointing space in main pipes, 199.

service pipes, 242.

Joints of main pipes, 8.

```
Keates' moderator lamp as a proposed standard of light, 325.
Kilns for lime burning, 126 to 129.
"Kimberley" joint for wrought-iron main pipes, 207.
King's (Alfred) pressure gauge, 308.
       turned and bored joints for main pipes, 8.
Kirkham and Sugg's improved Lowe's jet photometer, 332.
       scale for jet photometer, 333.
Kirkham and Wright's annular condenser, 78.
Kirkham, Hulett, and Chandler's washer-scrubber, 97, 98.
Körting and Cleland's steam jet exhauster, 88.
Lacquer and varnish, 289 to 291.
       deep gold, 290.
       fine pale, 290.
       gold, 290.
       green, 291.
       iron, 291.
       red, 290.
       simple pale, 290.
       yellow, 291.
Lacquering brasswork, 291.
Laming's experiments in purification by means of ammonia, 113.
Lamp, the Carcel, 324.
      Keates' moderator, 325.
Lamp columns, 252.
       distance apart of, 253.
      height of, 252.
       size of pipe in, 253.
Lamps, street, 252.
      average meter system for, 256.
       Bray's, 253, 254.
      regulators for, 255, 256.
       Siemens's, 253, 254.
       Sugg's, 253, 254.
      supply of gas to, 255.
      thickness and weight of glass for, 256.
Lancashire coals, 11, 12.
Law terms, 463, 464.
Laycock and Clapham's washer-scrubber, 97, 99.
Layers of purifying material in purifiers, 119.
Lead and composition pipes, 286.
      lengths and weight per yard, 286.
Lead, molten, 209.
       red and white, 205, 209.
```

weight of, for jointing mains, 210.

Lead paper, to prepare, 293.

Lead rings for flange joints, 205.

Lead service pipes, 242.

Leakage in boilers, cement for stopping, 90.

indicator, Lyon's, 215, 216.

main pipes, 214.

of water from iron gasholder tanks, 144.

service pipes and fittings, 243, 244.

Leases, terms for, 463.

Length of day and night, rule to find the, 256.

Letheby (Dr.), composition of London gas (1866), 410.

method of determining the specific gravity of gas, 337. combustion, temperature, explosive power, and mechanical power

of gases, 413. on proportion of products from coal tar, 373.

on purification of gas, 109.

on values of different illuminating agents, 412.

Letheby-Bunsen photometer, 317, 318.

Lewes (Professor), on the light emitted from globes, 284.

composition of London gas (1894), 411.

light obtained per cubic foot from 16-candle gas, 411.

Lids and lid fasteners for retorts, 57, 58.

retort, luting for, 58.

purifier, apparatus for raising, 120 to 122.

self-sealing retort, 58.

Lifting apparatus for purifier covers, 120 to 122.

Light, loss of, through mixing air with gas, 336.

Light, standards of, 309 to 331.

Lighting of large buildings, 284.

of ordinary rooms, 282.

public, 252 to 258.

Lights, coloured, 349 to 351.

number of, supplied by different diameters and lengths of pipe, 244.

number of, supplied by different sized meters, 280, 281. ventilating globe and sun, 283, 284.

Lignite or brown coal, 12.

Lilac-coloured fire, 349.

Lime, 104 to 106, 124 to 129.

burning, 125.

gas, or spent, 387.

Hislop's process for calcining spent, 105.

hydraulic, 142.

kilns, 126 to 129.

Lime—continued.

preparation of, for purifying, 105.

purification by, 104.

quantity of, required to purify the gas obtained from cannel and coal, 106.

quick, 105.

weight and measurement of, 106.

Lime water, to prepare, 293.

Limestones, classification of, 124.

their composition and specific gravity, 124, 125.

Liquids, expansion of, 417.

Liquids, solids, vapours and gases, specific heat of, 415, 416.

Liquor, ammoniacal, 375 to 381.

Litmus paper, to prepare, 292.

Livesey and Tanner's tar screen, 64.

Livesey's experiments in purification by ammonia, 113.

gasholder, without guide framing, 7, 168.

hydraulic main, 60.

hydraulic seal, 170.

scrubber, 93.

South Metropolitan gasholders, 7.

washer, 92.

London Argand, No. 1, Sugg's, 310.

London gas, composition of (1866), 410.

ditto (1894), 411.

London Gas Referees' 1-12th cubic foot measure, 315.

instructions for testing, 301.

pressure gauge, 313. sulphur test, 293, 305.

Loss of illuminating property in coal gas on exposure to freezing point, 72.

of light on mixing air with gas, 336.

Lute or seal, depth of, for purifier covers, 119.

Luting for retort lids, 58.

of joints in chemical experiments, 410.

Lux's specific gravity apparatus, 342.

Lyon's leakage indicator, 215, 216.

Machinery used for charging and discharging retorts, 71. used for coke breaking, 370, 371.

Main, hydraulic, dip in the, 64.

Main laying, 208 to 213.

appliances used in, 211.

average cost per yard of, 217, 218.

Main pipes, 197 to 241.

appliances used in laying, 211.

average cost per yard of laying, 217, 218.

ball and socket joints for, 204.

casting of, 197. coating of, 205.

discharge of gas per hour through, 229 to 241.

dimensions of sockets of, 201.

drip or syphon wells for, 209, 210.

expansion joints for, 204.

explosions in, 213.

flanged joints of, 202, 204, 205.

formula for calculating the weight of, 198.

iron or rust cement for joint of, 211.

jointing space in, 199.

joints of, 8.

"Kimberley" joints for wrought-iron, 207.

laying of, 208.

leakage from, 214.

Lyon's leakage indicator for, 215, 216.

metal of, 197.

open joints for, 199, 203, 209.

overweight in, 198.

recess for lead in front of turned joint, 201, 203.

red and white lead for joints of, 205, 209.

should be drilled, not cut, for the insertion of the service pipes, 243.

testing of, 197.

testing of, in the ground, 214 to 216.

turned and bored joints, 8, 200, 201, 203.

vulcanized india-rubber joints for, 204.

weight and cost per yard of, 219 to 227.

weight of lead required for jointing, 210.

wrought iron and steel, 207. Mains, consumption of gas per mile of, 427.

population per mile of, 427. rental per mile of, 427.

Main thermometer, Drory's, 82.

Malam's arrangement of purifiers, 115, 118.

improvements in the wet gas meter, S.

Mann's scrubber, 95.

Masonry tank walls, 141, 145 to 161.

Mastic cement for buildings, 445.

Materials in gasholders, dimensions of, 175.

of which gasholder tanks are constructed, 139.

Mean temperature of every tenth day in the year, 76.

Measure, Referees' cubic foot, 317.

Measuring wheel or drum of a meter, 130, 131, 259.

Measures and weights, 475 to 487.

decimal system of, 481 to 486.

Maxim-Clark system of carburetting coal gas, 344.

Mechanical and architectural drawing, colours used in, 464.

Melting points, table of, 417.

Memoranda, chemical and other, 404 to 417.

miscellaneous articles, 455, 456.

office, 457 to 464.

relating to water, 415.

Mensuration, epitome of, 465 to 474.

approximate multipliers, 469.

arithmetical and algebraical signs, 468.

circle, cylinder, and sphere, 465.

diameters, circumferences, areas of circles, and sides of equal squares, 471 to 474.

ellipses, cones, and frustums, 467.

evolution, or the extraction of roots, 468.

involution, or the raising of powers, 468.

square, rectangle, and cube, 466. triangles and polygons, 466.

Metals, expansion of, 417.

heat, conducting power of, 417.

power of, for reflecting heat, 417.

Meter, average system, for public lighting, 256. station, 129 to 131.

Meters, consumers', 259 to 279.

apparatus required for testing, 264.

compensating, 260.

dry meter, description of the, 259.

effect of overdriving a measuring wheel, 261.

Greenall and Heaton's "Positive," 262.

Hunt's compensating, 261.

inspection of, 262.

Parkinson's motive power, 263.

percentage tables used in testing, 266 to 279.

prepayment, 263.

protection of, from frost, 262.

provisions of Sales of Gas Act, 1859, as to stamping, 264.

Sanders and Donovan's, 260, 261.

size of meters desirable to be used, 261.

sizes of meter unions, table of, 264.

Meters-continued.

testing of, 264.

Urquhart's "Reliance." 261.

Warner and Cowan's, 260.

wet meter, description of the, 259.

Methven's proposed standard of light, 325.

Meyer and Playfair (Drs.), on the gases occluded in coal, 20.

Miller's table of amount and specific gravity of gas at different periods of distillation, 26, 27.

Millboard for jointing flanges, 204.

Miscellaneous articles, memoranda, 455, 456.

Mixing of air and gas, effect of, 336.

Mixing the ingredients for coloured fires, 351.

Mixture for tinning brass and iron, 287.

Moderator lamp, Keates', 325.

Moisture, corrections for, 338 to 340.

glue cement to resist, 291.

in coal, effects of, 15, 18. Moon's rising and setting, 256.

Mortar and concrete, 444, 445.

blue lias lime concrete, 445.

cement mortar, 444.

coarse mortar, 444.

hydraulic lime mortar, 444.

mastic cement for buildings, 445.

Portland cement concrete, 445.

Morton's self-sealing retort lids, 5.

Motive power gas-meter, 263. Motive power, use of gas for, 368.

Mountings of retort bench, 54 to 61.

bridge pipes, 59, 64, 65.

buckstaves, 54, 55.

coke slaking apparatus, 54, 55.

dip pipes, 59, 60.

furnace ash pans, 55, 56.

hydraulic main, 60.

lids and lid fasteners, 56 to 58.

retort mouthpieces, 56, 57.

Mouthpieces, retort, 56, 57.

Multiplier for wrought-iron, 446.

Multipliers for facilitating calculations, 469.

Murdoch (William), and the invention of gas lighting, 1.

Muriate of ammonia, 375.

Naphthalene, 73 to 75.

Bremond on, 73.

deposits, remedies for, 74.

Natural slope of earths, 139.

"Needle" governor burner, Peebles's, 285.

Newcastle coals, 11, 12.

New red sandstone, 10.

Night and day, to find the length of, 256.

Nitrogen in coal, 12, 13.

Northumberland coal, 11, 12.

Number of bricks in walls of different areas, 439 to 443.

Number of burners required to light large rooms, 284.

Number of hours during which gas is usually burned, 258.

Objections to burners placed horizontally, 282.

Odling (Dr.) on purification, 108.

Office memoranda, 457 to 487.

approximate multipliers, 469, 470.

arithmetical and algebraical signs, 468.

authority to pay dividends, 462.

books required in the keeping of a gas company's accounts, 457 to 460.

certificates showing that income-tax has been deducted, 463. colours used in mechanical and architectural drawing, 464.

declaration for loss of sealed share certificates, 461. discount for early payment of gas bills, 460.

epitome of mensuration, 465 to 467.

French weights and measures, 481 to 486.

indemnity for loss of share certificates or dividend warrant, 462. law terms, 463.

renouncement of proposed new issue on the transfer of old shares, 460.

renunciation of shares newly allotted, 461.

sizes of drawing paper, 464.

terms for leases, 463.

weights and measures, 475 to 487.

Ohren on the application of sulphate of ammonia in agriculture, 385. Oil, salad, to prevent evaporation from water slide pendants, 282.

Old red sandstone, 10.

Ornamentation in Gas-Works, 422.

"Otto," the, gas-engine, 9.

Oval retorts, 38, 39.

Ovens and retorts of fire bricks and tiles, 39.

Oxidation of pipes, 205, 243.

Oxide of iron, 106.

average composition of native bog ore, 107. precautions required in using fresh, 107. purification by, 6, 106.

spent, 386.

Oxygen, in coal, 12, 13.

pure, use of in purification, 110 to 112.

Paper disc for testing gas, 311, 319.

Paper, lead, to prepare, 293.

litmus, to prepare, 292.

turmeric, to prepare, 292.

Paper, sizes of drawing, 464.

Parkinson's motive-power gas-meter, 263.

Parrot or cannel coal, 11.

Patterson's (R. H.), discoveries in purification, 106, 109, 112.

Pavement, tar, 374.

Pease's system of wire rope gearing for gasholders, 8, 169.

Peclet's table, showing the relative effects of water and air as cooling agents, 80.

Peebles's district or differential governor, 196, 197.

"Needle" governor burner, 285.

station governor, 194.

Peebles process of enriching coal gas, the, 344.

Pendants evaporation from water slide, 282.

Pentane gas; Dibdin's 10-candle argand, 328.

Harcourt's proposed standard lamps, 326, 330.

Percentage of error in meters, table of, 266 to 279.

Permian series, 10.

Photometer, Bunsen's, 317, 318.

Evans' enclosed, 317.

illuminating power meter, Sugg's, 333, 334.

Letheby-Bunsen, 317.

Lowe's jet, 332.

Thorp and Tasker's jet, 334, 335.

Pipes and fittings, effect of small and bad, 279.

sizes of, for internal supply, 281.

Pipes, ascension, choking of, 59.

brass, plain, spiral and fluted, 286.

bridge and dip, 59, 60, 64, 65.

connecting, for purifiers, 123.

galvanized, 243.

lead and composition, 286.

main, 197 to 241.

service, 242 to 251.

```
Playfair and Meyer (Drs.), on the gases occluded in coal, 20. Pole (Dr.), on gasholder tank walls, 145.
```

Population per mile of main, 427.

Portland cement, 144, 200.

concrete, 444.

mortar, 445.

Pouillet's table of colours corresponding to high temperatures, 43.

Powders, bronze, 288size for, 289.

Precautions required in the working of gasholders, 170.

Precipitating chambers, 81.

Prepayment gas-meter, 9, 263.

Pressure changer, Cowan's automatic, 195.

Braddock's, 194, 195.

Pressure, consumption and, 197.

illuminating power and, 285.

variation of, according to level, 196.

Pressure gauges, 132 to 134.

coloured water for, 132.

differential, 132.

King's, 132.

Referees' street lamp, 313.

to clean the glass tubes of, 133.

Pressure and exhaust registers, 133, 134.

Cowan's, 134.

Crosley's, 133. Wright's, 134.

Pressure and temperature, corrections for, 312, 320.

Pressure of gasholders, to ascertain, 173.

Pressures, square root of, from 1-10th to 4 inches, 240.

Price list of wrought-iron tubes and fittings, 250, 251.

Producing power of various kinds of coals and cannels, 16, 17.

Production of coke from coal, 12 to 14, 16, 17.

of gas from coal, 16, 17.

per retort mouthpiece, 43.

Products, coal, 390 to 403.

residual, 370 to 389.

Protection of meters from frost, 262.

Public illuminations, 346 to 367.

coloured fires, 349 to 351.

devices for, 347, 352, to 367.

illuminated borders, 349.

mode of supply and price of gas, 346.

price of devices, 348.

Public illuminations—continued.

service or supply pipes, 347.

Public lighting, 252 to 258.

average meter system for, 256.

consumption of gas by one burner throughout the year, 257.

Denayrouze incandescent lights, 255. distance apart of public lamps, 253.

during severe frost, 253.

galvanized pipes for lamp columns, 253.

height of lamp columns, 252.

Hutchinson's lamp service cleanser, 255, 256.

lamp columns, 252.

number of hours during which gas is usually burned, 258. rule to find the length of day and night, 256.

size of service pipes, 253.

Sugg's, Bray's, and Siemen's lamps and burners, 253, 254. weight and thickness of glass for public lamps, 256.

Puddle and brick gasholder tanks, 144.

Puddle, clay, 144.

Purification, 103 to 115.

bog ore, average composition of, 107.

by ammonia in closed vessels, 112 to 115.

by caustic soda and sulphide of sodium, 112.

by lime (oxide of calcium), 104.

by lime, sulphide of calcium, and oxide of iron, combined, 107.

by oxide of iron, 106. Brin's process, 110.

Claus' process of, 113.

classification of the best known limestones, 124.

extraction of bisulphide of carbon, 107.

instructions for preparing lime for purifiers, 105.

method of revivification of oxide of iron, in situ, 109.

Hislop's process for calcining the spent lime, 105.

impurities in crude coal gas, 103.

Letheby (Dr.) on, 109. Odling (Dr.) on, 108.

Patterson's (R. H.) researches in, 106, 109, 112.

precautions required in using fresh oxide of iron, 107.

removal of impurities by condensers, washers, and scrubbers, 104.

use of air in, 109.

use of oxygen in, 110.

weight and measurement of lime, 106.

Purifiers, 115 to 124.

## Purifiers-continued.

apparatus for raising the lids or covers, 120 to 122.

centre and other change valves, 122.

construction and arrangement of, 115 to 118.

depth and best form of, 116, 117.

depth of water lute, 119.

Malam's arrangement of, 115, 118.

number of layers of purifying material, 119.

rule for determining the size of, 119.

sieves, trays, or grids, for lime and oxide of iron, 120.

size of connecting pipes, 123.

water lute for covers and hydraulic centre valve, 119.

Purifying house, 115 to 118.

arrangement of 115.

elevator for lime and oxide, 115, 116.

ventilation of, 115.

Purple coloured fire, 349.

Pyrites, iron, in coal, 15, 19. Pyrostatic iron, 453.

Quantity of ash in coal and coke, 12 to 14, 16, 17.

brickwork in retort settings, 40.

carbon, hydrogen, nitrogen, and oxygen in coal, 12, 13.

gas, and coke obtained from coal and cannel, 16, 17.

gas, per ton, and illuminating power, relation between, 29.

of sulphur in coal, 12, 13, 16, 17. volatile matter in coal, 12, 13.

Radiation from retort bench, 42.

Rake for discharging retorts, 70.

Rapid or sudden condensation, 72.

Reaumur's thermometer compared with Fahrenheit's and the Centigrade, 83, 84.

Recipe for tinning iron and brass, 287.

Reciprocating and rotatory exhausters, 85 to 87.

Red-coloured fires, 350.

Referees: 1-12th cubic foot measure, 315.

instructions of the, 301.

on aqueous vapour in gas, 74.

pressure gauge for street lamps, 313.

remarks on dry gas, 74.

sulphur test, 305.

Reflecting heat, power of metals for, 417.

Regenerative and generator furnaces, 5, 38, 44 to 49.

Regenerative and generator furnaces-continued.

Webber on, 45.

or gas firing, 5, 38, 45 to 49.

Registers, pressure and exhaust, 133, 134.

Cowan's, 134.

Crosley's, 133.

Wright's, 134.

Registration as affected by temperature, 75.

Regulating burner, Wright's "Acme," 285.

Peebles's "Needle," 285.

Regulations as to internal fittings, 280 to 282.

statutory, as to testing, 292, 318.

Regulator or governor for internal fittings, 280 to 282.

Relation between quantity of gas per ton and illuminating power, 29.

Relative value of different coals and cannels, 28, 29.

illuminating agents, 412. "Reliance" meter, 261.

Rental per mile of mains, 427.

Residual products, 370 to 403.

ammoniacal liquor, 375 to 381.

average percentage products obtained from coal tar, 373.

coke and breeze, 370 to 372.

coke breaking hammer and machinery, 370, 371.

coke produced from different coals, 12, 13, 16, 17.

coke, weight of a chaldron of, 455.

coke, weight of, slaked and unslaked, 52.

Cyanogen, 383.

retort carbon, 51, 370, 392.

Sellers on coke breaking, 370.

spent lime, 387.

spent oxide of iron, 386.

sulphur recovery, Claus's system, 382.

tar, 372.

tar pavement, 374.

total production of tar and ammoniacal liquor in the United Kingdom, 372, 375.

utilization of the tar, 372.

yield of liquor and tar per ton of coal, 24, 27.

yield of sulphate of ammonia, 378.

Retort house, 30 to 35.

Retorts and settings, 38 to 49.

cast-iron, 4, 38, 43.

cements for joining clay retorts and mouthpieces, 57, 58. clay retorts, 38.

Retorts and settings—continued. colours corresponding to various high temperatures, 43. different forms of, 39. dimensions of retorts and settings, 38, 41. duration of clay and iron, 42 to 44. fire-brick retorts, 39. flues and draught for, 49. Fraser's ribbed iron, 38. fuel used for carbonizing coal in, 52 to 54. "gaiting" retorts, 42. heat of retorts for efficient carbonization, 43. hints on the setting of, 40 to 42. "letting down" and "standing off" of, 42. materials of which retorts are made, 38. quantity of brickwork in retort settings, 40. regenerative and generator furnaces for, 5, 38, 44 to 49. scurfing retorts, 51. segmental, 39. setting of retorts, 41. single retorts, 39. tar as fuel for, 52 to 54. thickness of, 38. "through" or double retorts, 40. usual number of retorts in an oven, 41. Retort bench mountings, 54 to 61. ascension or stand pipes, 58, 59. bridge and dip pipes, 59, 64, 65. buckstaves, 54. cements for jointing retorts, mouthpieces, and lids, 57, 58. coke slaking arrangements, 54, 55. dry mains, 65. furnace ash-pans, 55, 56. furnace frames and doors, 53, 56. grate bars, 56. hydraulic main. 60. lids and lid fasteners, 57. mouthpieces, 56. self-sealing lids, 58. tie rods, 56. Retort house, 30 to 35. chimney stalk for, 50. clear space in front of benches, 33. dimensions of, 34.

for inclined retorts, 33, 34.

Retort house—continued. paving of floor of, 33. roof of, 35. rule for the size of chimneys, 50. ground floor, 30, 31. stage floor, 32. ventilation of, 32. Retort-house tools and machinery, 70, 71. ash-pan, rake, and shovel, 70. auger, 70. charging scoop, 70. Clegg's arrangement for continuous carbonization, 5. discharging rake, 70. machinery for charging and discharging retorts, 71. pricker and fire tongs, 70. shovels, 70, 71. Retort stack, 35. buckstaves and tie rods for, 54. buttress walls, 36. chimney stalk, 50. coke slaking arrangements on, 54. dimensions of, 35. for inclined retorts, 36. main flue of, 36. Ring or annular tanks, 134, 139, 164. Rocks and earths, weight of various, 139. Roofs of retort houses, 35. Rooms, lighting of large, 284. ordinary, 282. Ropes, hemp and wire. 452. breaking weight of, 452. weight and strength of, 452. Roscoe (Professor) on the proportion of products obtained from coal tar, 373. Rotatory and reciprocating exhausters, 85 to 87. Round ropes of hemp and wire, 452. retorts, 38, 39. Rule for area of atmospherical condensation, 80. for estimating the number of burners required for lighting large buildings, 284. for area of purifiers, 119. for roughly estimating the amount of coal required to produce a given quantity of gas, 27.

for size of retort-house chimney stalk, 50.

```
Rule-continued.
```

specific gravity being known to find weight and quantity of gas, 342.

to ascertain the weight of gasholders, 172.

to calculate the discharge of gas through main pipes, 229.

to calculate the required size of service pipes, 246.

to determine the capacity of station meters, 130.

to find the content of a pipe in gallons and cubic feet, 241.

to find the length of day and night, 256.

to find the hours of sunrise and sunset, 256.

to find the pressure of gasholders, 173.

to find the weight of hemp ropes, 452.

Rules for Gas Managers, golden, 428.

to convert Fahrenheit into Reaumur and Centigrade, and conversely, 83.

St. John and Rockwell apparatus, 82.

Sal ammoniac, 398, 401.

Salad oil in water slide pendants to prevent evaporation, 282.

Sales of Gas Act, 1859, provisions of, as to stamping meters, 264. Salubrity, comparative, of different illuminating agents, 411.

Sand for mortar, 142 to 144, 444.

Sanders and Donovan's compensating meter, 260.

Saturation, testing ammoniacal liquor by, 379.

Scale for Lowe's jet photometer, 333.

Scoop for charging retorts, 70.

Scotch coal, 11, 13.

Scrubbers, 92 to 101.

Anderson's combined washer and, 100.

Barker's mill for distributing water in, 95.

bye-pass mains and valves for, 101.

dry scrubbers as condensers, 81.

filling material for the, 92.

Green's canvas screens for, 93.

Kirkham, Hulett, and Chandler's "Standard" washer-scrubber, 97, 98.

Laycock and Clapham's "Eclipse" washer-scrubber, 97, 99. Livesev's improvements in the, 93.

Mann's, 95.

number of volumes of various gases which 100 volumes of water can absorb, 100.

open, 81.

quantity of ammoniacal liquor obtained to outlet of, 375. rule for determining the size of tower, 96.

Scrubbers-continued.

tower, 92.

water distributing apparatus for the, 94.

Scurfing retorts, 51.

Self-sealing retort lids, 58.

Sellers on coke-breaking, 370.

Separator for tar and ammoniacal liquor, 102.

Septem and decigallon, 475.

Service pipes and fittings, 242 to 251.

abrupt angles to be avoided in, 243.

processes for preserving, 243.

casing for, when laid in ground, 242.

cast-iron, wrought-iron, and lead, 242.

Cowan's service cleanser, 243, 244.

diameter of, to supply lights at certain distances from mains, 244, 246 to 248.

Hulett's service cleanser, 243.

Hutchinson's service cleanser, 243, 244.

leakage from, 242, 243.

pitch of the Whitworth taps and dies for, 246.

price list of, 250, 251.

sizes of, for supplying lights, 244, 246 to 248.

syphon or drip well for, 243, 249.

tinned or galvanized, 243.

to calculate the required size of, 246.

uniformity in the screws or threads of, desirable, 246.

weight of wrought-iron tubes and fittings, 245.

Settings, retort, 40.

Sheard on the temperature of gas in the retorts, 69.

Sheard's carbonic acid, ammonia, and sulphuretted hydrogen testing apparatus, 294 to 296.

Sheds for the storage of coal and cannel, 18.

Shoubridge's charging apparatus for inclined retorts, 37.

Shovels, retort house, 70.

Sides of equals squares, etc., table of, 471 to 474.

Siemens's regenerative furnaces, 45.

street lamps and burners, 253, 254.

Signs, arithmetical and algebraical, 468, 469.

Silvering metals, mixture for, 289.

Single-lift gasholders, 166, 175 to 182.

Single retort benches, 30.

Site for a gas works, 426.

Size for bronze powder, 289.

Sizes of drawing paper, 464.

```
Sizes of mains, services, meters, and internal pipes desirable to be
           avoided and used, 244.
Slaked and unslaked coke, weight of, 52.
Slaking arrangements for coke, 54, 55.
Sliding scale, the, 425.
Slope of earths with horizontal line, natural, 139.
Sloping retort settings, 5, 36, 37.
Slow speed condenser, Cleland's, 79.
Smith, Beacock, and Tannett's coke breaking machine, 370.
Smith (Watson), on the bye-products from 1200 gallons of tar, 373.
Smith (Graham), on mixing ashes with lime for mortar, 445.
Smithy ashes for mortar, 445.
Soldering, fluxes for, 287.
Solders, 287.
       brazing or spelter, 287.
       fine, 287.
       for copper, 287.
       glazing, 287.
       pewterer's, 287.
       plumbing, 287.
      steel. 287.
Solids, liquids, gases, vapours, specific heat of, 415, 416.
Solubility in water of various gases, 100, 409.
Solutions to prepare, test, 292.
Somersetshire coals, 11.
Somerville and Thomas's coke-breaking machine, 371.
Specific gravity, of coal, and to determine the, 12 to 14, 16, 17, 25.
      apparatus, Lux's, 342.
       of gas, 336 to 343.
       a test of quality of gas, 336.
       Beaume's hydrometer compared with, 381.
      corrections for temperature, pressure, and moisture in taking.
           338 to 340.
      illuminating power and, compared, 336.
       Letheby's (Dr.) method of determining the, of gas, 337.
       Lux's apparatus, 342.
      of ammoniacal liquor, 378 to 380.
       of gases at end of each hour of distillation, 27.
       of limestones, 124.
       of various gases, 343.
       of various substances, 454.
       ordinary method of determining the, of gas, 336.
       specific gravity being known to find the weight of a quantity
       of gas, 342.
```

Specific gravity—continued.

square roots of, from, 350 to 700, 239.

to convert Twaddel into, 378.

weight and solubility in water of various gases, 100, 409.

Wright's method of determining the, of gas, 341.

Specific heat of solids, liquids, gases and vapours, 415, 416.

Spent lime, composition and use of in agriculture, 387, 388.

Hislop's process for calcining, 105.

Spent oxide of iron, 386, 387.

quantity of free sulphur in, 107, 386.

salts of ammonia and insoluble cyanides in, 386.

Stephenson's apparatus for estimating the sulphur in, 386, 387.

Sperm candle, the standard, 317, 319.

Sperm, value of coal and gas in pounds and grains of, 27, 28.

Spiral and fluted brass tube, weight per foot, 286.

Splint coal, 11.

Spontaneous ignition of coal, 19.

Square roots of pressures from 1-10th to 4 inches, 240.

Square roots of the specific gravity of gas from 350 to 700, 239.

Stack, retort, 35.

Stacking of coal, 15.

Staffordshire coals, 11.

Stage floor retort houses, 31.

Stalks, rule for size of retort-house chimney, 50.

Standard burners, 317, 318.

sperm candle, the, 317, 319.

unit of heat, 50. washer-scrubber, 97, 98.

Standards of light, foreign and proposed, 324 to 331.

Carcel lamp, 324.

Dibdin and Harcourt's 10-candle pentane standard, 327 to 330.

Fiddes, 325.

German normal paraffin candle, 324.

Harcourt's pentane standard, 326.

Harcourt's 10-candle pentane lamp, 330, 331.

Keates' moderator lamp, 325.

Hefner-Alteneck unit, 324.

Methven's standard, 325.

Station governor, 192 to 196.

advantages of the, 192.

Braddock's, 193 to 195.

construction of the, 192.

Cowan's, 195.

Cowan's automatic pressure changer for, 195.

Station governors—continued. freezing of water in tanks of, 196. Hartley's improvements in, 194. Hunt's, 195. Peebles', 194. steam stove for governor house, 196. valves useless as governors of pressure, 192. variations of pressure according to level, 196. Station meter, 129 to 131. bye-pass mains and valves for, 131. cylindrical and rectangular, 130. mountings of, 130. registering mechanism, 130. rule to determine capacity of, 130. tell-tale apparatus, 130. Station meter house, 129. Statutory regulations for testing, 292, 318. Steam boiler and engine, 88. cement for metallic joints, 90. cement for stopping leaks in boilers, 90. diameters of cylinders of steam engines, 89. horse power of steam boilers, 89. Steam jet exhauster, 88. Steam stove for governor house, 196. Stephenson's apparatus for estimating the sulphur in spent oxide, 386, 387. Stone gasholder tanks, 139, 160. Storage of coal and cannel, 18. of gas, 166. tar and ammoniacal liquor, 101 to 103. Stove, steam, for governor house, 196. Strength of ammoniacal liquor, 375. Strode's ventilating sun lights, 283. Structural and commercial value, 427. Sudden or rapid condensation, 72. Sugg's argands for street lighting, 9. flat-flame burners, 9. illuminating power meter, 333, 334. London argand, No. 1, 313. photometer table, 309, 318. regulator burner, 285.

ventilating lights, 283. Sulphate of ammonia, 375 to 379.

street lamps and burners, 253, 254.

Sulphate of ammonia—continued.

Arnold on the application of, in agriculture, 384.

Ohren, ditto, 385.

yield of, per ton of coal, 378.

Sulphide of calcium, purification by, 107.

Sulphide of sodium and caustic soda, purification by, 112.

Sulphur compounds in gas, test for the, 305.

sulphur in cannel, coal, and coke, 12 to 17.

spent oxide of iron, 107, 386.

Sulphur recovery, Claus's process, 382.

Sulphur test, the Referees, 293.

Harcourt's, 296 to 301.

Sulphuretted hydrogen, test for, 293, 300, 302.

Sun and globe lights, ventilating, 283.

Sundry useful notes, 426, 427.

Syphon or drip wells, 209, 210, 243, 249.

Tanks, gasholder, 134 to 166.

annular or ring, 134, 139, 164.

Arson (M.), on masonry walls of, 145.

brick and puddle, 139, 141, 145 to 158.

cast, wrought-iron, and steel, 134, 139, 144, 148, 161.

cement mortar for, 143.

composite, 159.

concrete, 147, 159.

Douglas's instructions for preparing concrete, 143.

dry wells, 144.

examples of construction of, 149 to 166.

excavations for, 135, 139.

Faija on Portland cement, 144.

hydraulic lime mortar for, 142.

leakage of water from iron, 144.

materials of which tanks are constructed, 139.

natural slope of earths, 139.

Pole (Dr.), on masonry walls of, 145.

puddle, clay, for, 144.

steel, 163.

stone, 139, 160.

thickness of walls of, 145.

weight of various earths and rocks, 139.

wrought-iron, 139, 148, 162.

Tanks or wells, content of, for each foot in depth, 103.

Tar and liquor separator, 102.

Tar as fuel, 52.

```
Tar-continued.
       coal, 372.
       pavement, 374.
       products from, 373.
       utilization of, 373, 390.
       yield of, per ton of coal, 372.
Tar pavement, 374, 375.
       formation of, 374, 375.
       furnace, 374.
       preparation of materials for, 374.
Tar well, 101 to 103.
       capacity of, for different sized works, 101.
       content of circular wells for each foot in depth, 103.
       dip well for sealing pipes, 101.
       elevated cast-iron cistern, 102.
       tar and liquor separator, 102.
Technical quantities of miscellaneous articles, 455.
Telescopic gasholders, 7, 166, 182 to 192.
       counter balanced, 166.
       precautions necessary in the working of, 170.
Tell-tale apparatus for station meters, 130.
Temperature and pressure, corrections for, 312, 320.
       as affecting registration, 75.
       for carbonization, 43.
       of clay retorts, 43.
       of gas in the bridge pipe, 65 to 69.
       of gas in the retorts, 65 to 69.
       of iron retorts, 44.
Temperatures, colours of high, 43.
Terms for leases, etc., 463.
Test, Referees' sulphur, 305.
Testing ammoniacal liquor, 379.
       coal, 21.
       illuminating power, apparatus for, 309, 317.
       instructions of the Referees on, 301, 309.
       of main pipes, 214.
       of meters, 264 to 279.
        statutory provisions on, 292, 318.
Tests for the detection of the impurities in coal gas, 292 to 309.
       ammonia, 292.
        bisulphide of carbon, 296, 305.
        carbonic acid, 292, 300.
        Gas-Works Clauses Act, 1871, on, 293, 318.
        Harcourt's colour test, 297 to 301.
```

Tests for-continued.

sulphur compounds, 305.

sulphuretted hydrogen, 293, 300, 302.

test solutions, to prepare, 292.

Thermal unit (British), 414.

Thermometer and barometer, used in testing illuminating power, 318.

Thermometer, Drory's main, 82.

Thermometers, comparison of different, 83, 84.

Thickness of the Birmingham wire gauge, 447.

Thickness of gasholder tank walls, 145.

Thomas and Somerville's coke breaking machine, 371.

Thorp and Tasker's jet photometer, 334.

Through retorts, 40.

Time in which a sum doubles itself at simple and compound interest,

in which consumption of gas doubles by compound growth, 428. Tinned or galvanized iron pipes, 243.

Tinning iron or brass, 287.

Tools, retort house, 70.

Tower scrubbers, 92 to 97.

Trammel used in the construction of gasholder tanks, 140.

Trays or grids for purifiers, 120.

Trias, Permian and Carboniferous series in England and Wales, 10.

Trussed and untrussed gasholder roofs, 167.

Tubes, brass, weight per foot, 286.

wrought-iron fittings, and, 245.

price list of, 250, 251.

Tubular, or battery condenser, 79.

Turmeric paper, to prepare, 292.

Turned and bored joints for main pipes, 8, 200, 201, 203.

Twaddel's hydrometer, 378 to 380.

to convert into specific gravity, 378.

Underground condensers, 81.

Uniformity in the screws or threads of pipes and fittings, 246.

Unions for meters, table of, 264.

Unit of heat, standard, 50.

Untrussed and trussed gasholder roofs, 167.

Urquhart's "Reliance" meter, 261.

Use of gas for purposes other than lighting, 368, 369.

Useful notes relating to gas works, 418.

buildings and apparatus of a gas-works, 426.

calorific power of various photogenic compounds, 412.

Useful notes—continued.

capital of gas-works, 420.

comparative salubrity of illuminating materials, 411.

conduct of gas-works, 423.

consumption of gas per mile of main, 427.

consumption of gas per head of population, 427.

cost of gas-works, 420, 427.

golden rules for gas managers, 428.

London gas, composition of, 410, 411.

ornamentation in gas-works, 422.

population per mile of main, 427.

relative value of illuminating agents in respect of their heating and vitiating effects on the atmosphere, 411, 412.

rental per mile of main, 427.

site for a gas-works, 426.

time in which the yearly consumption of gas is doubled at different rates of increase, 428.

Usual dimensions of bricks, 436.

Utilization of tar, 372.

Valon on the use of oxygen in purification, 112.

Value of different coals and cannels, relative, 29.

of coal per ton in pounds of sperm, 28.

of gas per cubic foot in grains of sperm, 27.

Value, structural and commercial, 427.

Valves and bye-pass mains, 101.

Valves, useless as governors of pressure, 192.

Valves, centre and other change, 122.

Vapours, gases, liquids, and solids, specific heat of, 415, 416.

Variations in the illuminating power of gas, 335.

of gas pressure according to level, 196.

Varnish and lacquer, 289 to 291.

golden, 290.

for india-rubber tubing, 286.

for ironwork, 291.

Various gases: their specific gravity, weight, and solubility in water,

Velocity and force of the wind, 453.

Ventilating globe and sun lights, 283.

Ventilation of purifying house, 115.

of stored coal, 19.

Vertical atmospherical condensers, 77.

Vitiating effects on the atmosphere, of various illuminating agents, 411, 412.

Voelcker's, analysis of gas lime, 388.

on the use of gas lime in agriculture, 388.

Volatile hydrocarbons, 62,

Volatile matter in coal, 12 to 14.

Volume of aqueous vapour in gas in contact with water, 339.

various gases which 100 volumes of water will absorb, 100.

Vulcanized india-rubber joints for main pipes, 204.

Walker's purifying machine, 100.

sulphur recovery plant, 382.

Waller's exhauster, 86.

Walls, thickness of gasholder tank, 145.

Warner and Cowan's meter, 260.

Warner's annular condenser, 78.

Washer and scrubber, Anderson's combined. 100.

Washers, 90 to 92.

advantages of using, 90.

Anderson's, 91.

Anderson's combined washer and scrubber, 100.

bye-pass mains and valves for, 101.

Cathels', 91.

Cockey's, 100.

Ford's, 100.

Kirkham, Hulett, and Chandler's washer-scrubber, 97, 98.

Laycock and Clapham's washer-scrubber, 97, 99.

Livesey's, 92.

Walker's purifying machine, 100.

Water, dilatation of gas in contact with, 279.

leakages of, from iron gasholder tanks, 144.

memoranda relating to, 415.

proportion required for scrubbing purposes, 96.

and air as cooling agents compared, 80.

and atmospherical condenser combined, 80.

channel condenser, 80.

distributing apparatus in scrubbers, 94.

in governor tanks, freezing of, 196.

in lutes of telescopic holders, freezing of, 170. its power of absorbing ammonia, 92, 100.

Webber on regenerative and generator furnaces, 45.

Weck valve, the, for purifiers, 123.

Weight and specific gravity of ammoniacal liquor, 378, 380.

brass tube, per foot, 286.

coal and cannel per cubic yard, 27.

composition and lead pipes, 286.

Weight-continued.

gasholders, 172.

hemp ropes, rule to find the, 452.

specific gravity and solubility in water of various gases, 100, 409. various earths and rocks, 139.

various gases, 343.

various sections of iron and other metals, 446 to 452.

various substances, 454, 455.

wire and hemp ropes to find the breaking, 452.

wrought-iron tubes and fittings, 245.

Weights and measures, 475 to 487.

French decimal system, 481 to 486.

Well, dry, for gasholder tank, 144.

tar and liquor, 101 to 103. Welsbach, the, system of incandescent gas-lamps, 9, 255,

Welsh coals, 11, 13.

Wenham's regenerative lamp, 283.

West's stoking machinery, 5, 71.

Wet meter, description of the, 259.

Wet or damp coal, result of using, 18.

Wheel or measuring drum of a meter, 130, 131, 259, to 261.

Whessoe-Munich method of enriching coal gas, 345.

White and red lead, 205, 209.

White Indian fire, 351.

Whitworth's screws, 246.

taps and dies for gas tubing, 246.

Wigan cannel and coal, production per ton of, 26.

Williams (Greville) on proportions of products from coal tar, 373.

Wills' method of testing ammoniacal liquor, 379.

Wilson on the results obtained by applying certain manures to land, 389.

Wind, velocity and force of the, 453.

Winsor, a pioneer of gas lighting, 3.

Wire ropes, weight and strength of, 452.

Wood casing for service pipes, 242.

Wright's "Acme" regulating burner, 285.

Wright's method of determining the specific gravity of gas, 341.

pressure register, 134. Wright and Kirkham's annular condenser, 78.

Wrought-iron gasholder tanks, 139, 148, 162.

main pipes, 207.

multiplier for, 446.

tubes and fittings, weight of, 245.

"Yeadon" system of continuous carbonization, 6.

Yellow coloured fire, 349.

Yield of gas and coke of various coals and cannels, 16, 17. Yield of sulphate of ammonia per ton of coal, 378.

tar per ton of coal, 372. Yorkshire coals, 11.


Young and Aitken's analyzer, 82.



# THOMAS GLOVER & CO.'S' Patent New Improved

# Prepayment Meter

For Pennies, Shillings, or any Coin.



SIMPLE IN MECHANISM.

POSITIVE IN RESULTS.

PRICE CHANGER in 8itu.

## GUARANTEED FOR FIVE YEARS.

Telegraphic Address: "GOTHIC LONDON."
Telephone No. 725 Holborn.

# THOMAS GLOVER & Co., Ltd.,

DRY GAS-METER MANUFACTURERS,

214 to 222, St. JOHN STREET, CLERKENWELL GREEN, LONDON, E.C.

#### MANCHESTER:

87, BLACKFRIARS STREET. Telegraphic Address: "GOTHIC." TELEPHONE No. 8898.

#### BIRMINGHAM:

1, OOZELLS STREET.
Telegraphic Address: "GOTHIC."

#### BRISTOL:

28, BATH STREET.

Telegraphic Address: "GOTHIC."

TELEPHONE No. 1005.

#### GLASGOW:

ARGYLE WORKS, KINNING PARK.

Telegraphic Address: "GASMAIN."

TELEPHONE No. 1525 SOUTH SIDE.

## THE GAS APPARATUS CO., PETERBOROUGH, GAS ENGINEERS,

Manufacturers of Gas Burners, Governors, Lamps, Gauges, &c.

Hawkins & Barton's Patent Self-Regulating Lamp Governors and Burners.



FULL SIZE. No. 9. 24/- per dos.

FULL SIZE. No. 10.

80/- per dos.

An enormous quantity of these Burners are in use in this country and abroad; and they have never failed to give satisfaction. Wherever they are adopted, complaints against Bad Gas and Excessive Gas Bills naturally cease. Owing to their extreme simplicity, they cost very little more than the commonest Burners made, and will last years without attention. They are used by most of the Railway Companies in the Kingdom. They are the only Governor Burners made fitted with the Union Jet Tip. Gas Companies and Gas-Fitters would do well to recommend these Burners to their Customers as being the best possible means of preventing waste of Gas, and ensuring the highest Illuminating Power from the Gas consumed.

#### REPORTS.

We give the following Extracts from Reports received, vis. : From PROFESSOR LAMBERT, of the Royal Naval

College, Greenwich. Jan. 19, 1893. "I have given one of your Burners a very long and con-tinuous test. It has been used daily, and is still in use. I am pleased to say that it has never required attention for a moment during the long period amounting to over 9100 hours' actual working. It is the cheapest and neatest Gas Regulator which has ever been brought to my notice, and I have not found any more efficient."

"I find your Governor Burner is more reliable than any other to give the required quantity."

By J. MACKAY, Esq., Engineer.

Gas-Works, Peterhead, July 18, 1889
"The enclosed Burner has

been in use here all last winter, and does not seem much the worse. We had seven different kinds of Governors on trial, and yours seemed to come out the best. Please send us five gross more of the same kind.

The following appeared in The Gas and Water Review and Journal of Electric Lighting, Bept. 28, 1889: "Hawkins and Barton's Self-Regulating Lamp Governors and Burners —We have had an opportunity of testing these very excel-lent Governors and Burners, quite endorse makers' statements that they thoroughly control pressure, give an even-shaped flame, and are in every way suited for burning Gas either in the public lumps or private houses. They have the advantage of being cheep and very durable."



No. 1094. 7/- per doz.

Gas Company, Banbridge, Sept. 28, 1889.

Gentlemen,—I have tested your Hawkins and Barton's Burners, and I have no hesitation in saying the street the best Pressure-regulating Gas-Burners I have yet come across, and I shall have great pleasure in recommending them to our consumers and my friends.

The Gas Apparatus Company, Peterborough.

6/- per doz.

Liberal discount to the Trade. Trial Order Solicited.

Works and Offices-PETERBOROUGH, ENGLAND.

Telegrams: \*\* HARRIS-PEARSON, STOURBRIDGE.\*\*

M. Telephone: Me. 7. BRIERLEY HILL EXCHAUGE.

GAS RETORTS

OF ALL KINDS,

HORIZONTAL.

INCLINED, AND

SEGMENTAL.

LARGE STOCK AT

WORKS.

**EVERY** 

DESCRIPTION

OF BEST QUALITY

FIRE-BRICKS,

LUMPS, AND TILES.

GLAZED BRICKS, WHITE AND IN COLOURS, PORCELAIN BATHS, FIRE-CLAY GOODS OF ALL KINDS, HARD BLUE PAVING BRICK FOR RETORT-HOUSES, BEST RETORT BOLTS, CAST-IRON RETORT MOUTHPIECES, FITTINGS, AND LIDS, CAST-IRON GAS AND WATER PIPES, AND CONNECTIONS OF ALL SHAPES AND SIZES.

# CLAPHAM BROTHERS, LD.,

KEIGHLEY, YORKS.

ESTABLISHED 1837.

CONTRACTORS TO HER MAJESTY'S GOVERNMENT.


LAYCOCK & CLAPHAM'S PATENT

"ECLIPSE"

WASHER-SCRUBBER.

Machines supplied will deal with a total of 92,670,000 cubic feet of Gas per day.





GASHOLDER TANKS, COLUMNS, GIRDERS, LAMP-POSTS, GUTTERS.

London Representative:
THOMAS B. YOUNGER, C.E.,
Chesterfield House, 96, Great Tower Street.

RETORT-FITTINGS,
PATENT CONDENSER,
PURIFIERS WITH PLANED JOINTS.

Manchester Representative:
MAURICE SCHWAB,
96, Deansgate.

WATER VALUES & MAINS,
AND ALL KINDS OF GAS-WAKING APPARATUS AND GENERAL IRONWORK.

# GASHOLDERS.

GADD & MASON'S Patent COLUMNLESS SPIRAL-GUIDED GASHOLDERS.

# PLANED PURIFIERS OF ANY SIZE.

PURIFYING-MACHINES FOR REMOVING AMMONIA.

CARBONIC ACID AND TAR EXTRACTING WASHERS.
SCRUBBERS.

SULPHATE OF AMMONIA PLANT.

SELF-DISCHARGING SATURATORS.

CLAUS' PATENT SULPHUR-RECOVERY PLANT.

SELF-SEALING RETORT-MOUTHPIECES. LIFTING
APPARATUS. CENTRE AND FOUR-WAY VALVES.

WECK'S PATENT CENTRE-VALVE.

TAR-DISTILLING PLANT. CONDENSERS, SLIDE-VALVES. WOOD SIEVES. TAR-BURNERS. ROOFS. GIRDERS.

CRIPPS' PATENT GRID VALVE AND HYDRAULIC MAIN VALVE.
HOLGATE'S PATENT GAS-PURIFYING PLANT.

TYSOE'S PATENT SELF-SEALING MOUTHPIECES.

# C. & W. WALKER, MIDLAND IRON-WORKS, DONNINGTON,

NEAR NEWPORT, SHROPSHIRE.

10, FINSBURY SQUARE, LONDON.

Telegraphic Addresses: "FORTRESS, DONWINGTON, SALOP;" "FORTRESS, LONDON."

Codes Used: A.B.C. (Fourth Edition) and A1.

# W. C. HOLMES & Co.'s PATENT "NEW" SCRUBBER WASHER

In Horizontal or Vertical Form where floor area is limited.



#### SPECIAL ADVANTAGES.

Removal of every trace of Tar that may escape Condensation in the Condensers.

Complete Extraction of Ammonia from the Gas without affecting the Hydrocarbons.

Minimum quantity of fresh water required.

Maximum strength of liquor obtained.

Removal to a large extent of the

Sulphuretted Hydrogen and
Carbonic Acid Gas.

#### Special Note.

A Machine constructed for 1,500,000 cubic feet of Gas per diem is dealing efficiently with 1,800,000 cubic feet of Gas, equal to 1500 cubic feet per cubic foot gross area per diem, giving only 1 inch back pressure.


# Works: HUDDERSFIELD.

Telegrams: "HOLMES, HUDDERSFIELD."

London Office: 80, CANNON STREET, E.C. "IGHTOR, LONDON."

# W. C. HOLMES & CO.,

# Gas Engineers & Contractors



- MAKERS OF -

GASHOLDERS of Improved Construction and of all Sizes.

GAS AND CHEMICAL PLANT.

IMPROYED CONDENSERS, TAR EXTRACTORS, SLIDE AND CENTRE VALVES.
PURIFIERS WITH PLANED AND CEMENT JOINTS.

ROOFS, BRIDGES, TANKS, GIRDERS.

Engines and Exhausters. Malleable and all kinds of Castings. GOVERNORS and METERS.

#### WORKS: HUDDERSFIELD.


TELEGRAMS: "HOLMES, HUDDERSFIELD."

London Office: 80, CANNON STREET, E.C.

TELEGRAMS: "IGNITOR, LONDON."

# PATENT GUIDE FRAMING FOR GASHOLDERS

Has been adopted for many important Holders.




Cutier's Patent Guide Framing does not require Piers for its support, and the cost of the tank is thus much reduced.

#### CUTLER'S PATENT GAS CONDENSERS, OYER 100 IN USE.

Messrs. S. CUTLER & SONS undertake the Construction and Equipment of Gas-Works in any part of the World.

# CARBURETTED WATER-GAS PLANT

(CUTLER'S PATENTS).



This Plant includes several important improvements, ensuring safe and efficient working, and has been adopted at the following places:—

HORNSEY. HASTINGS. BUENOS AIRES. SOUTHALL

SOUTHEND. HARROW.

PLYMOUTH. BEXHILL.

PLYMOUTH (2nd order). SOUTHEND (and order)

FOLKESTONE.

We are our own Manufacturers, and can guarantee high-class Materials and Workmanship.

#### SPECIALITIES:-

CUTLER'S PATENT INTERLOCKING GEAR.

To prevent Air and Steam Yalves being coincidently open.

CUTLER'S PATENT SEPARATOR.

For the Liquids from Washer and Scrubber.

**CUTLER'S PATENT OIL SPRAYER.** 

GUTLER'S PATENT WASHER SCAVENGER.

## OIL STORAGE TANKS.


SAML. CUTLER & SONS, MILLWALL, LONDON.

# PORTER & CO.,

# GOWTS BRIDGE WORKS, LINCOLN,

Gas Engineers,

MANUFACTURERS, IRON FOUNDERS, & CONTRACTORS.



Over 600 Gas-Works erected for Home and Colonial purposes. Extensions in Gasholders, Purifiers, Retorts and Fittings, Scrubbers, Condensers, Yalves, &c., undertaken on the lowest terms.

Specially designed Gas-Works for the supply of Gas from 1/8 to 2/- a thousand to Workhouses, Asylums, Industrial Schools, and Government Buildings. The Firm undertakes the expeditious supply of Castings, Iron Roofs, Tanks, Standards, Lamp Posts, Lamp Heads and Lanterns, Gas and Water Pipes, and Gas Fittings for all purposes.

#### ESTIMATES ON APPLICATION.

Telegraphic Address-"PORTER, LINCOLN."

National Telephone, No. 13.

# CARBURETTED WATER-GAS APPARATUS,

Merrifield-Westcott-Pearson Patents.

# The ECONOMICAL GAS APPARATUS CONSTRUCTION CO., Ltd.

W. H. PEARSON, CHAIRMAN.
W. H. PEARSON, JUNE, DEPUTY-CHAIRMAN.


J. T, WESTCOTT, M.E., MANAGER.
L. L. MERRIFIELD. M.Inst.M.E., Engineer.

London Offices: 19, ABINGDON STREET, WESTMINSTER, S.W.

TELEGRAPHIC ADDRESS: "CARBURETED, LONDON."

American Offices: TORONTO.

# CARBURETTED WATER-GAS ENGINEERS.



Working Floor of Generator House. One Quarter Section of Birmingham Plant, Windsor Street Station.

The Maximum Daily Capacity of the Birmingham Corporation's Plant, which was erected by this Company, is 10 MILLION CUBIC FEET.

The M.-W.-P. PLANT is designed to use the Heaviest as well as the Lightest Grade of Oil.


RESULTS PROVE EFFICIENCY.

# SHMORE, BENSON, PEASE, MANUFACTURERS OF APPARATUS FOR THE RECOVERY OF BYE-PRODUCTS

APPARATUS FOR THE RECOVERY OF BYE-PRODUCTS FROM COKE OVENS AND OTHER PLANTS.

STOCK TON-ON-TEES.

SULPHATE OF AMMONIA PLANT (COLSON'S PATENTS).



Colson's Apparatus surpasses any other for economy in working, and quantities produced.

Colson's SELF-DISCHARGING SATURATORS act with absolute certainty, and at lowest cost for labour.


Full particulars and prices on application to the SOLE MAKERS-ASHMORE, BENSON, PEASE, & Co., Ltd., STOCKTON-ON-TEES.

# ASHMORE, BENSON, PEASE, & Co.

STOCKTON-ON-TEES.

MAKERS OF GASHOLDERS & GAS APPARATUS. PURIFIERS. CONDENSERS. SCRUBBERS. WASHERS.

RETORT-FITTINGS, MAINS FOR GAS AND WATER, WOOD GRIDS.



PERTH, N.B., 2-LIFT HOLDER, 126 feet by 25 feet, CABLE GUIDED. (From a Photograph,)

MAKERS AND PATENTEES OF COLUMNLESS GASHOLDERS GUIDED BY STEEL CABLES.

Over 50 Holders are now at work on this system, and several others are in course of construction.

Telegrams: "GASHOLDER, STOCKTON-ON-TEES."

# GUEST AND CHRIMES,

#### FOUNDRY AND GENERAL BRASS WORKS, ROTHERHAM;

AND

128, SOUTHWARK STREET, LONDON, S.E.,

MANUFACTURERS OF

WET AND DRY GAS METERS, STATION METERS, EXPERIMENTAL AND TEST METERS.

PATENT FOUR-WAY DISC AND OTHER GAS VALVES. PATENT GAS MAIN GOVERNORS.

IMPROVED CONSUMERS' GAS GOVERNORS.

Experimental Apparatus, Photometrical Apparatus, Test Gasholders, &c.

Street Lanterns, Lever Lamp Cocks, Gas Main Cocks Water-Meters,

and Plumbers' Brass Work.

#### .... IMPROVED DRY GAS-METERS .....



#### ALSO MANUFACTURERS OF

Cowan's Patent "Arc" Lanterns for Incandescent Burners, for Inside & Outside Lighting.

COWAN'S PATENT HIGH-POWER GAS-LAMPS.

F. SIEMENS' PATENT REGENERATIVE GAS-BURNERS.

Patent High-Power Ventilating Gas-Lamps.

GAS LIGHTING APPARATUS OF EVERY DESCRIPTION.

# WILLEY & Co.,

GAS ENGINEERS,

248, KINGSLAND ROAD, LONDON; & EXETER.

#### GAS DEPARTMENT.

SPECIAL REFERENCE AND ATTENTION ARE INVITED TO OUR

# WET AND DRY METERS,

Which have acquired a high reputation for the excellence of Materials and Workmanship; their DURABILITY and ACCURACY OF REGISTER guaranteed.

STATION METERS of every capacity fitted with Overflow to ensure accuracy of Water Level. Station Governors. Self-Acting Adjustment to regulate Pressure accurately.

STREET LAMP METERS with special Lamp-posts to receive same, or provided with separate Street Boxes.

BORRADAILE'S PATENT LAMP GOVERNORS adjusted to required Pressure and Consumption.

STREET; LAMP PILLARS in variety of design.

STREET LAMPS, square and hexagon.

CAST-IRON MAINS all sizes, Socket Joints Turned and Bored, Flanged Pipes and Specials for Connections to order. Wrought-Iron Service-Pipes (Gas, Steam, and Water quality), with fitting of same. Syphon Pumps for Stations. Syphon Pumps for Town Mains. Service Cleansers.

Pressure-Gauges for the Exhauster-Room, and various lengths to meet the whole requirements of Gas-Works. Gas Chandeliers, Brackets, Pendants, Coronæ, and Fittings. Mediæval for Churches. Special Elaborate Designs for large Public Buildings and Halls of Commerce. A Choice Variety of Hall Lamps, Gas Globes, Shades, &c., to agree. Carter's Valves, Main Cocks and Levers, Brass Cocks, Union Jointe and Connections, with every description of small Gas-Fittings, Brass, Copper, and Composition Tubes.

#### ENGINEERING DEPARTMENT.

MANUFACTURERS OF EVERY DESCRIPTION OF

#### GAS APPARATUS, GASHOLDERS, TELESCOPE & SINGLE LIFT.

Plans and Specifications furnished for Extensions and Enlargement of existing Works, adapting them to the most Improved and Modern Principle of Gas Manufacture.

PURIFIERS, CONDENSERS, WASHERS, ENGINES and EXHAUSTERS, STATION METERS, and GOVERNORS manufactured and erected.

Makers, by permission of that eminent authority, Mr. GEORGE LIVESEY, of his CELEBRATED PATENT WASHER. Highly approved by all the Engineers of Works where adopted. Largely in demand.

# NEWTON, CHAMBERS, & Co., Ltd.,

Thorneliffe Iron-Works and Collieries, NEAR SHEFFIELD.

MANUFACTURERS OF EVERY DESCRIPTION OF

# — GAS APPARATUS, —

CAST-IRON RETORTS, RETORT-HOUSE FITTINGS.

IMPROVED COAL & COKE ELEVATORS & CONVEYORS.

- AIR AND WATER CONDENSERS, OF WROUGHT OR CAST IRON TOWER SCRUBBERS AND WASHERS.
- PURIFIERS, WITH PLANED JOINTS. HYDRAULIC & HAND-LIFTING GEARS.

  WOOD GRIDS AND SCRUBBER BOARDS.
- Patent Centre-Valves, working all four Purifiers, or three on and one off. BYE-PASS VALVES & SLUICE VALVES for GAS or WATER WORKS.
  - GASHOLDERS.
- Telescope & Single-Lift. Wrought & Cast Iron Tanks of any Size.

  CAST-IRON FLOOR PLATES.
  - Columns, Girders, Ornamental Lamp Columns, Gas, Water, and Hydraulic Pressure Pipes and Specials.
- WROUGHT-IRON COLUMNS, GIRDERS, ROOFS, BRIDGES, AND STRUCTURES OF EVERY DESCRIPTION.

Chemical Works Plant and Apparatus.

DESIGNS, SPECIFICATIONS, & ESTIMATES FREE.

- PLANS and SPECIFICATIONS furnished for Extensions and Enlargements of existing Works, adapting them to the most Improved and Modern principle of Gas Manufacture.
- PIG IRON OF SPECIAL QUALITY FOR STEAM AND HYDRAULIC CYLINDERS
  GAS COAL, FAMOUS FOR ITS UNRIVALLED EXCELLENCE.
  - Sole Makers of Thresh's Patent Current Steam Disinfectors.


    PROPRIETORS OF THE "IZAL" DISINFECTANTS.

# **ALDER & MACKAY,**

ESTABLISHED 1850

#### MANUFACTURERS OF WET AND DRY GAS-METERS.

COMBINING ALL THE LATEST IMPROVEMENTS.



EDINBURGH.

#### DRY METERS.

DHY METERS IN BEST TINNED-PLATE CASES.

DRY METERS IN CAST-IRON CASES.

(We are the original designers and makers of Cast-Iron Dry Meters.)

DRY PREPAYMENT METERS ARRANGED FOR EITHER PENNIES OR SHILLINGS. DRY EXPERIMENTAL AND TEST METERS.

OUR METERS ARE NOTED FOR THEIR RIGID EXACTITUDE OF MEASUREMENT, RELIABILITY UNDER THE EXTREMES OF WORKING, WITH GREAT DURABILITY.

#### WET METERS.

WET CONSUMERS' METERS.

ROUND CASES.

UNDEEGROUND WET METERS FOR STREET LAMPS OR OUTSIDE SERVICES.

(Dispensing with Footway Boxes or Special Lamp Posts.)

WET PREPAYMENT METERS ARRANGED FOR EITHER PENNIES OR SHILLINGS. WET STATION METERS IN SQUARE OR

WET EXPERIMENTAL AND TEST METERS.



BRADFORD.

Samples, Prices, and all Information on application.

New Grange Works: EDINBURGH.

Ventnor Street Works: BRADFORD.

TELEGRAPHIC ADDRESSES:

ALDER, EDINBURGH,
TELEPHONE No. 81 WESTERN.

ALDER, BRADFORD.

## ORIGINAL MAKERS OF THE INTERNAL RACK AND PINION GAS-VALVE IN 1847.



"The Donkin Gas-Valve."

Over 1200 Valves always in stock to ensure quick delivery.




Internal Worm and Rack Gas-Valve.



Rack and Pinion Cocks from 3 inch to 4 inch. Over 4000 in use.

## WE HAVE SUPPLIED OVER 100,000 OF THESE VALVES AND COCKS.



Small Exhauster and Engine combined

(new design), from 1,000 to 15,000 cubic feet per hour.

Manufacturers of EXHAUSTERS on J. Beale's 1877 Patent; also Makers of the BEALE-DONKIN (1892 Patent) EXHAUSTERS. space in Internal Drum utilized, adding 40 per cent. to capacity.

## BRYAN DONKIN & COMPANY, Limited, SOUTHWARK PARK ROAD, BERMONDSEY, LONDON,

Manchester Office:

Mr. HENRY THOMAS, 10, MAWSON'S CHAMBERS, DEANSGATE.

# ...TORBAY...

# ...PAINT...

FOR

# GASHOLDERS & GAS PLANT.

ALSO

SPECIAL QUICK-DRYING GLOSS PAINTS FOR LAMP COLUMNS, METERS, &c.

# THE TORBAY PAINT COMPANY

(Proprietors, STEVENS & CO.)

WITH WHICH IS AMALGAMATED

The Torbay & Dart Paint Company, Limited,

26, 27, & 28, BILLITER STREET, LONDON, E.C.

8, INDIA BUILDINGS, FENWICK STREET, LIVERPOOL.

Works and Mines:

DARTMOUTH AND BRIXHAM, TORBAY.

# GEORGE GLOVER & CO.

HIGHEST AWARDS

POR

DRY GAS-METERS.

**LONDON, 1862** 

PARIS, 1867

AMSTERDAM, 1869

**VIENNA, 1873** 

MANCHESTER, 1875

**SYDNEY, 1879** 

MELBOURNE, 1880

MELBOURNE, 1889

NEW ZEALAND, 1882

**LONDON, 1884** 

**LONDON, 1885** 

LIVERPOOL, 1886

ADELAIDE, 1887

# Prepayment

# Meters,

FOR PENNIES OR SHILLINGS.



SIMPLE.

ACCURATE.


DURABLE.

ROYAL AVENUE, CHELSEA, LONDON, S.W.;

And LANCASTER AVENUE, MANCHESTER.

Telegrams: "DRY METERS, LONDON."

# R. DEMPSTER & SONS, Ltd., ELLAND, YORKS.



DIRECT-FIRED, GENERATOR, AND REGENERATOR SETTINGS, AND RETORT WORK IN ALL ITS BRANCHES.


Contractors for Complete Installations on Horizontal and Inclined

Systems, without sub-contracting.

# BORRADAILE'S

PATENT

# DRY METALLIC GAS-GOVERNORS.



THE MOST SIMPLE AND ACCURATE REGULATORS EVER INVENTED.

PERMANENTLY ADOPTED BY THE LEADING ENGINEERS AND LOCAL AUTHORITIES.

ALL HARD METAL.

NO DESTRUCTIBLE SUBSTANCE.

FULL DETAILS GIVEN FOR CLEANING AND ALTERING CONSUMPTION.



Special size for
Incandescent Lighting,
18s. per doz.


# J. & J. BRADDOCK, GLOBE METER WORKS, OLDHAM.

MANUFACTURERS OF

#### BRADDOCK'S NEW PATENT

# GAS STATION GOVERNORS.

Which are unequalled for compactness, governing power, and general excellence.



THE LIGHTEST AND MOST CONVENIENT GOVERNOR.

May be placed in a passage wide enough to admit a flanged pipe of equal bore to its inlet and outlet.

FULL PARTICULARS ON APPLICATION.

#### BRADDOCK'S PATENT

## PREPAYMENT (WET & DRY) GAS-METERS.

Improved Consumers' Wet and Dry Gas-Meters.

STATION METERS OF ALL SIZES. TESTING APPARATUS.

Lamp and Main Taps, Street Lamps, Gauges, etc.

BEST QUALITY ONLY. TELEGRAMS: "BRADDOCK OLDHAM."

# W. & B. COWAN, Ltd.

ESTABLISHED 1827.

DRY AND WET

# GAS-METER MANUFACTURERS

LONDON, MANCHESTER, EDINBURGH, & SYDNEY.

Warner and Cowan's Patent Meters.

GAS GOVERNORS.

WM. COWAN'S PATENT.

THE COWAN PRESSURE SYSTEM.

IMPROVED SERVICE CLEANSER. FIDDES & STAGG'S PATENT.

PREPAYMENT METERS,

WET AND DRY.

## DRY GAS-METERS.

In Patent Improved Cast-Iron Cases.

FRICTIONLESS PRESSURE REGISTERS, W. R. CHESTER'S PATENT.

CROSSLEY AND OTHER PATTERNS OF PRESSURE AND EXHAUST REGISTERS.

ALEX. C. HUMPHREYS, M.Inst.C.E.

A. G. GLASGOW, M.E.

SINCE 1893

# Messrs. HUMPHREYS & GLASGOW

Have constructed or have in hand

# CARBURETTED WATER-GAS PLANT

FOR THE FOLLOWING UNDERTAKINGS:-

C	Jub. Ft. 1	Cub. Ft.
`	Daily.	Daily.
Copenhagen	700,000	Holyoke, Mass 600,000
Belfast	.700,000	Edinburgh
Belfas (Second Contract)	.500 000	8t. Joseph, Mo
Glasgow	800,000	Lea Bridge
	700,000	Lea Bridge (Second Contract) 850,000
Brussels (Second Contract)	708,000	
	700000	
	3,500,000	Stockton-on-Tees
	,500,000	Syracuse, N.Y
Tottenham	750.000	Brentford 1,900,000
Tottenham (Second Contract)	750,000	Commercial Gas Co 850,000
Santiago	400,000	Commercial Gas Co. (Second Contract) 850,000
Swansea	750,000	Bridlington 125,000
Manchester	8,000,000	Middlesbrough 1,250,000
Brighton	1,750,000	Croydon 1,250,000
Preston	L,500,000	L. & N.W. Railway, Crewe 700,000
New York	1,200,000	Taunton
Southport	750,000	Lewrence, Mass
	L,000,000	Rotterdam
Newburgh, N.Y.	850,000	Dorking
Newburgh, N.Y. (Second Contract)	250,000	McKeesport, Pa
Hoylake	125,000	The Gaelight and Coke Co., Bromley . 8,750,000
Coventry	600,000	The Gaslight and Coke Co., Nine Elms 2,750,000
Coventry (Second Contract)	600,000	Durham
Bordentown, N.J.	125,000	New York (Remodelled)
		Guarbananah 900,000
Winchester	900,000	Scarborough 800,000
Shanghai	225 000	Perth, W.A
Stockport	500,000	Commercial Gas Co. (Third Contract). 1,250,000
Norwich	1,000,000	Bremen

In addition to which the 1891 Installations of The Gaslight and Coke Company, on the Humphreys'
Double-Superheater System, have a capacity of 12,000,000 Cubic Feet per Diem.

#### IN THE UNITED STATES,

Messrs. Humphreys and Glasgow and the United Gas Improvement Company have jointly constructed 254 Sets of Humphreys' Double-Superheater Apparatus; 141 of these since 1893. This Company (of which Mr. Humphreys was farmerly Chief Engineer) were, until lately, the largest Constructors of Carburetted Water-Gas Apparatus in the World.

At the Present Time, Messrs. Humphreys & Glasgow, of London, Hold that Position.

#### o, VICTORIA STREET, LONDON, S.W.

Telegrams: "EPISTOLARY, LONDON."

UNITED STATES OFFICE:

BANK OF COMMERCE BUILDING, NEW YORK.

# WEST'S PATENT AUTOMATIC MACHINERY

FOR

CHARGING & DRAWING GAS-RETORTS.

FOUR DISTINCT TYPES, ADAPTED FOR ALL SIZES OF GAS-WORKS.

SAVING OVER 50 PER CENT. IN LABOUR.

Complete Gas-Works Designed and Erected in the most Modern Form.
Inclined Retort Installations and Machinery a Speciality.



Makers of Retort Mouthpieces, fitted with Self-sealing Lids, and eccentric fastenings for all Sizes and Sections of Retorts.

COMPLETE MACHINERY FOR HANDLING COKE FROM RETORTS TO COKE YARD, SCREENING AND WASHING SAME SUITABLE FOR HOUSEHOLD AND SMITHY PURPOSES.

LARGE INSTALLATIONS SUPPLIED TO MANY GAS-WORKS IN THE UNITED KINGDOM AND ON THE CONTINENT.

Oxide Elevating Machinery, Coke Barrows, Valves, Hydraulic Mains, and all Retort-Bench Fittings.

ILLUSTRATED CATALOGUE SENT UPON APPLICATION.

ESTABLISHED 1803.

# R. D. WOOD & CO.,

Engineers

Iron Founders

PHILADELPHIA. U.S.

(CABLE ADDRESS: TUCKAHOE.)

**Machinery:** 

# CAST IRON PIPE

1 inch to 72 inches Diameter.

3 INCHES AND OVER, 12 FEET LONG.

# **GASHOLDERS** STEEL TANKS HYDRAULIC MACHINERY

OF THE HEAVIEST DESCRIPTION.

CRANES, RIVETERS,

VALVES.

PRESSES.

FIRE HYDRANTS, TURBINES, AND PUMPS. HEAVY CASTING OF ALL KINDS.

TAYLOR'S FUEL GAS PRODUCERS.

CATALOGUES FORWARDED ON APPLICATION.

# KIRKHAM, HULETT, & CHANDLER, LIMITED,

WASHER-SCRUBBER. PATENT "STANDARR, BRIDGE STREET, WESTMINSTER, S.W. Extracts from recent Testimonials. " As to the efficiency of the Washer-"Sorubber erected some three years "ago, I may say it has given us "perfect satisfaction; we obtain 10 gallons of 14 oz. Liquor per ton of "Durham Coal, and the wear and tear

**\*\*\*** 

Acid and Sulphuretted Hydrogen, also Removes the whole of the Ammonia and a large percentage of Carbonic any Tar passing forward from Con-Minimum power required to drive the machine and water used. Maximum strength liquor produced, all the ammonia being extracted. densers.



"tracts the whole of the Ammonia and "with very little Water. It requires "I can say that the machine ex-"very little power to drive it."

**\*\*\***\*\*

Upwards of 550 Machines in use and in course of Construction. Extraot

MARSHALL'S

PATENT

etter from Mr. Coventry: "The Condensers you Winstanley,

PATENT IAR

> have been in use some time, and are working very

CONDENSER

COMBINED BATTERY SORUBBER,

EXTRACTOR

erected for us

R

MABHER. satisfactorily."

In use at Ramsgate, Shanghai, Hord, &c., In use at Ironbridge, and recommended where and in course of construction for Barking, only small ground area is available, and no motive These Condensers are in use at Covenity, In use at Ramsgate, bhangual, allows, well missione, Randers, Asiborg, Velle, &c. Others in and in course of construction for Barking, Pelton, &c., &c., Jersey, &c., &c., cc. server.

ESTIMATES, &c., ON APPLICATION AT ABOVE ADDRESSS.

FOR SMALL BUITABLE **WORK8 MITHOUT** 

STANDARD "

etter from the

MARSHALL'8

ste Mr. Jabez

Extract from

Church: "The Marshall Patent

**SCRUBBER** VERTICAL

OWER FOR MECHANICAL VAILABLE MOTIVE

WASHERS.

EXTRACTOR.

satisfactory re-

has given very Par-Extractor

# THE GAS-METER CO., LTD.,

PATENTEES AND MANUFACTURERS OF

WET AND DRY GAS-METERS, STATION METERS, GOVERNORS, GAS APPARATUS, &c.

Works-LONDON, OLDHAM, DUBLIN.



VALON'S PATENT STOP METER

As used by all the principal Gas Companies and Corporations in the Kingdom.

For Prices and Particulars apply to

R. L. ANDREWS, General Manager, 238, KINGSLAND ROAD, LONDON.

# "MELDRUM"

PATENT

# BREEZE Furnace

For Burning Pan Breeze, Coke and Coal Dust, Ashpit Refuse, &c.

**6000** 

AT WORK.

## The Use of Breeze as Boiler Fuel.

Te the Editor of the "Journal of Gas

LIGHTING." SIR,-My attention has been drawn to a letter appearing in your issue for the 18th ult., asking for the experience of users of breeze as boiler fuel. The special information your inquirer desires is whether the steel plates of boilers are injuriously affected by the steam admitted under the fire-grate. As the first user of the Meldrum furnace, I



may be permitted te say that for ten years I have employed it in connection with steel boilers, and that no deterioration of the flues has occurred. It is highly desirable that all poor fuels should be utilized, and that no misunderstanding as to the efficiency of the furnace should hinder this. Your correspondent need have no hesitation in adopting this economical and convenient apparatus wherever small cheap fuel is available.

T. HOLGATH, Gas Engineer,

Halifax, Feb. 10, 1898.

#### ALSO MAKERS OF STEAM AND WATER JET APPARATUS

ACID ELEVATORS, AGITATORS, LIQUID ELEVATORS, MILK OF LIME INJECTORS,

FOR SULPHATE PLANTS.

Blowers for Gas Furnaces, Compressors, Ejectors, Automatic Gas Exhauster and Governor, Revivifying Blowers (Continuous and Intermittent), Ventilators, &c.

MELDRUM BROS., Atlantic Works, MANCHESTER.

# MELDRUM & CLAYTON'S


PATENT

# **AUTOMATIC BREEZE AND COAL STOKER**


WITH FORCED DRAUGHT. Self-cleaning Bars. High Efficiency. Little Labour. Small Cost of Up-keep.

#### FOR GAS AND WATER WORKS AND ELECTRIC LIGHT.

Will work with cheapest Coke Breeze or Dust Coal. No high Chimney required. No Smoke.



MELDRUM BROS., Atlantic Works, MANCHESTER.



FOR TAR, SULPHATE, CREOSOTE, CHEMICAL, BYE-PRODUCTS AND RESIDUAL PLANTS FOR GAS-WORKS, BLAST FURNACES, AND COKE OYENS, apply to

# R. & J. DEMPSTER, LTD.,


GAS PLANT WORKS.

### Newton Heath, MANCHESTER,


ENGINEERS, IRON FOUNDERS, AND CONTRACTORS FOR EVERY DESCRIPTION OF


### GAS-WORKS PLANT.

R. & J. D.'s Works stand upon 71 acres of land, of which about 4 acres are under cover.











RETORT SENCH.

CONDENSERS.

PURIFIERS.

**RCTURRER** 

# HUTCHINSON BROTHERS,

GAS ENGINEERS, &c.

#### MAKERS OF

WET AND DRY GAS-METERS of all kinds.

STATION METERS AND GOVERNORS.

BRASS MAIN COCKS, LAMP TAPS,

UNIONS, FERRULES, &c.

THE "FALCON" LAMPLIGHTER'S TORCH.

BRASS AND COPPER SYPHON PUMPS.

SERVICE CLEANERS. &c.

LEAD SATURATORS, ACID TANKS, ELEVATORS AND COCKS,

SALT SCOOPS, AND SUNDRIES.

APPARATUS FOR CHEMICAL LEAD BURNING.

PRACTICAL LEAD BURNERS SENT OUT TO REPAIRS.


WROUGHT-IRON AND WOOD PURIFIER GRIDS. SCRUBBER BOARDS.

MACHINERY, TOOLS, AND SUNDRIES FOR GAS-WORKS.

# FALCON WORKS, SACKVILLE ST.,

BARNSLEY.

Telegrams: "HUTCHINSON BROS., BARNSLEY."



**BOILERS:** 

MAKERS of HIGH-CLASS BOILERS, to stand any test or pass any inspection.

MADE BY THE LATEST IMPROVED MACHINERY. THE MOST MODERN AND COMPLETE PLANT IN YORKSHIRE.

MAKERS OF THE FOLLOWING SPECIALITIES:

CLAYTON'S IMPROVED GUIDE FRAMING FOR GASHOLDERS. CLAYTON'S IMPROVED ANTI-FREEZERS.

DEIGHTUN'S IMPROVED PATENT DRILLING AND TAPPING APPARATUS for Gas and Water Mains—handy, cheap, and effective. No Works should be without them.

Retort Ironwork of every description for Inclined or Horizontal Retorts made in the most improved way. Retort Lids made by Special Hydraulic Machinery.

### JAMES M'KELVIE & Co.,

Cannel and Gas Coal Merchants,

HAYMARKET, EDINBURGH,

And at 37 and 38, MARK LANE, LONDON, E.C.

ESTABLISHED 1840.

WINKELMANN'S "VOLCANIC" and "VOLCUM" CEMENT. Fire Resistance up to 4500° Fahr. In use in Gas-Works all over the World.

ANDREW STEPHENSON, 182, PALMERSTON BUILDINGS,

OLD BROAD STREET,

Telegrams: "Volcanism, London." LONDON, E.C.

Telegrams: "FOUNDRY, LEVEN, FIFE."

# HENRY BALFOUR & CO., LD.,

LEVEN, FIFESHIRE.

ESTABLISHED 1814.

London: 47, VICTORIA STREET, S.W. Mr. HENRY PUPLETT, M.S.E.

#### MAKERS OF ALL GLASSES OF

GAS-WORKS PLANT, COAL and COKE SCREENING, CONVEYING and ELEVATING MACHINERY, COKE-CONVEYORS, &c

GASHOLDERS with STEEL and CAST-IRON TANKS, IRON ROOFS, and BUILDINGS.

FOUR-WAY VALVES.

#### THE LANEMARK COAL Co., Ltd.,

NEW CUMNOCK, AYRSHIRE,

CAN OFPER THEIR SUPERIOR AND WELL-KNOWN

#### HOUSE, CANNEL, GAS, AND STEAM COALS,

Delivered in Waggons at any Railway Station in England and Scotland; or f. o. b. at Ayr, Troon, Ardrossan, Irvins, Greenock, Glasgow, and Grangemouth.

PRICES, ETC., ON APPLICATION.

TELEGRAPHIO APDRESS: " LANEMARK, NEW CUMNOOK."

# R. & A. MAIN, LIMITED.



GAS COOKING

AND

HEATING APPARATUS

Of Every Description.



ARGYLE WORKS.

MANCHESTER, BRISTCL,

BIRMINGHAM.

109, FARRINGDON ROAD, LONDON, E.C.

# WIGAN COAL & IRON COMPANY, Ltd.

6, CORPORATION STREET, BIRMINGHAM.

BEST WIGAN ARLEY MINE -

- GAS COALS AND GAS CANNEL.

Agent: A. C. SCRIVENER.

Telegrams: "WIGAN, BIRMINGHAM."

Telephone: Ne. 200.

# CARLESS, CAPEL, & LEONARD,

HOPÉ CHEMICAL WORKS,

Also at PHAROS WORKS, HACKNEY WICK, N.E.

Specially distil Carburine Spirit, specific gravity '680, or of any other grade suitable for enriching Gas; also Gas Oil best adapted for injecting into the Retorts, as in the Herring Process.

Importers of Petroleum for Carburetting Water Gas, or for Manufacturing Oil Gas.

Distillers of Pentane, Petroleum Ether, and Naphtha for clearing the pipes of
Naphthaline, &c.

Manufacturers of Petrol—the best Fuel for Motors, Auto-Cars, &c. SAMPLES AND PRICES MAY BE HAD ON APPLICATION.

# ARROL-FOULIS

PATENT HYDRAULIC MACHINERY

# CHARGING AND DRAWING GAS-RETORTS.

#### THE ARROL-FOULIS MACHINES

ARE EMPLOYED AT THE FOLLOWING WORKS:-

**GLASGOW BAS-WORKS**—

Tradeston.

Dawsholm.

Dalmarnock.

BASLIGHT & COKE

GCMPANY-

Beckton.

SOUTH METROPOLITAN

East Greenwich.

Yanxhall.

Rotherhithe.

COMMERCIAL GAS-WORKS-

Wapping.

Poplar.

BROMLEY GAS-WORKS

(KENT).

EDINBURGH GAS-WORKS.
LIVERPOOL GAS-WORKS.

LEEDS BAS-WORKS.

BIRMINGHAM GAS-WORKS.

BRITISH GAS COMPANY-

Hull.

BOLTON GAS-WORKS, IMPERIAL CONTINENTAL

BAS ASSOCIATION-

Imsterdam.

Ylenna.

HAGUE CORPORATION
GAS-WARKS---

Hague.

METROPOLITAN BAS-WORKS,

Melbourne.

**CLEVELAND GAS-WORKS-**

Cleveland, Ohio,

âc., âc., âc.

**OVER 200 MACHINES** 

ARB AT

WORK OR IN COURSE

OF CONSTRUCTION.

THE TIME TAKEN TO DRAW AND CHARGE EACH RETORT BY THESE MACHINES AVERAGES
ONE MINUTE.

SIR WILLIAM ARROL & Co., Ltd., sole makers, DALMARNOCK IRON-WORKS, BRIDGETON,

London Address: 32, VICTORIA ST., WESTMINSTER, S.W.

PLANS AND ESTIMATES FURNISHED ON APPLICATION.

ESTABLISHED 1850.

# PARKER & LESTER, MANUFACTURERS ...


THE ONLY MAKERS OF -

PATENT ANTIMONY PAINT. - - -

PARKER'S IMPERIAL BLACK VARNISH.

Oxide Paints, Oils, and General Stores for Gas and Water Works.

Works: ORMSIDE STREET, OLD KENT ROAD, LONDON.



#### TROTTER, HAINES, & CORBETT,

BRETTELLS' ESTATE

#### FIRE-CLAY AND BRICK WORKS, STOURBRIDGE.

MANUFACTURERS OF

Gas-Retorts, Glasshouse Furnace and Blast-Furnace Bricks, Lumps, Tiles, and every description of Fire-Brick.

PROPRIETORS OF BEST GLASSHOUSE POT AND CRUCIBLE CLAYS.

SHIPMENTS PROMPTLY AND CAREFULLY EXECUTED.

WHOLESALE GAS-FITTING MANUFACTURERS TO GAS
COMPANIES AND THE TRADE.

WROUGHT AND CAST IRON TUBES AND FITTINGS FOR GAS, STEAM, OR WATER.

CHANDELIERS, BRACKETS, HALL LIGHTS, ETC.,

#### Street Lamps,

ORDINARY OR

OUR SPECIAL HIGH-POWER.

The best Lamps in the Trade.

STREET-LAMP GOVERNORS. GAS-METERS.

**HULETT'S** 

#### **SERVICE-CLEANSER.**

No Gas Company should be without this Apparatus.
THOUSANDS IN USE.

Every Description of Gas-Fittings, Pressure Gauges, &c.

D. HULETT & Co.,

55 & 56, High Holborn LONDON.



# WELDON MUD

FOR

# GAS PURIFICATION,

FOR USE IN

#### THE RECOVERY OF SULPHUR,

ALSO

REMOVAL OF LAST TRACES OF SULPHURETTED HYDROGEN IN CATCH POSITION.

Full particulars on application to-

# THE GAS DESULPHURIZATION CO., Limited,

I, Fenchurch Avenue, London, E.C.

### DANIEL HOWARD

(Successor to the late BENJ. WHITEHOUSE),

GASHOLDER AND BOILER WORKS,

WEST BROMWICH, NEAR BIRMINGHAM (Established 1765),

#### TELESCOPIC & SINGLE GASHOLDERS,

WROUGHT AND CAST IRON TANKS FOR DITTO,

Purifiers, Condensers, Scrubbers, Hydraulic Mains, and all kinds of Gas Apparatus,

WROUGHT-IRON ROOFS, BRIDGES, GIRDERS, ETC.,

STEAM, HOT WATER, AND RANGE BOILERS, TANKS, CISTERNS, BOATS,

And all kinds of Wrought-Iron Work.

DRAWINGS, SPECIFICATIONS, AND ESTIMATES SUPPLIED ON APPLICATION.



SULPHATE OF AMMONIA SATURATORS.

## JOSEPH TAYLOR & CO.,

CHEMICAL PLUMBERS, &c.,

And Makers of every description of SOLID PLATE LEAD and TIMBER CASED SATURATORS, &c.,

CENTRAL PLUMBING WORKS, TOWN HALL SQUARE, BOLTON.

SPECIAL ATTENTION TO REPAIRS.

SPECIAL-MAKERS OF SELF-EMPTYING SATURATORS.

N.B.—All Orders entrusted are under strict personal supervision.

## PORTLAND CEMENT



#### H. F. CURRIE & Co.,

Office: ALBERT BUILDINGS, PREESON'S ROW,

Stores: NOVA SCOTIA, CANNING DOCK,

Telegraphic Address:

"QUALITY, LIVERPOOL."

LIVERPOOL

Telephone No. 1889.

LONDON PORTLAND CEMENT, PLASTER OF PARIS, GYPSUM, LIME, PAYEMENT, BRICKS, CRUSHED GRANITE, FIRE-CLAY GOODS, SLATES, WHITING, CHINA CLAY, &c.

Double Lever Automatic Cement Testing Machines and Arnold's Patent Testing Plant.

SPECIAL FACILITIES FOR EXPORT ORDERS

Over 50,000 Tons supplied to Manchester Water-Works, Liverpool Corporation, Mersey
Tunnel Extension and Mersey Docks and Harbour Board.

#### THE WINSTANLEY

# REGENERATIVE AND GENERATOR SPECIALITY COMPANY.

ERECTORS OF RETORT HOUSES, &c., COMPLETE.

With Special Appliances, the outcome of years of experience. Many complete Installations of Inclined and Horisontal Settings now in use, giving exceptional satisfaction. Alterations to existing Plant undertaken.

#### WINSTANLEY'S PATENT REGENERATIVE SYSTEM IS THE ACME OF SUCCESS.

NO OTHER SYSTEM ITS EQUAL IN RESULTS OBTAINED—FUEL ACCOUNT THE LOWEST RECORDED.

In many instances no Clinkering is required. Can be applied to any kind of Retort Setting, Horizontal or Inclined; also to Brick Kilns, Glass Furnaces, &c. Many complete Benches in use; several Stage and Floor Houses under construction; over 350 Settings in use.

#### WINSTANLEY'S PATENT HYDRAULIC MAIN.

Engineers contemplating alterations or additions should use it; saves money, as weight of Fittings are reduced from 4 cwt. to 5 cwt. per mouthpiece.

#### WINSTANLEY'S PATENT MOUTHPIECE FASTENING AND CATCH

is "UNIQUE," easy to fasten, makes a light and clean face. No screws or eccentrics to wear out, or pins to alter to take up wear. Will last for years.

Apply G. ATHERTON WINSTANLEY, Kenilworth Road, Coventry, or G. WINSTANLEY, Gas-Works, Coventry.

# THOMAS PIGGOTT & Co., Ld., ATLAS WORKS, BIRMINGHAM.

WELDED AND RIVERTED AND RIVERTE

OTES! MAINS BOD WATER-WORKS

STEEL versus CAST IRON.

WELDED AND RIVETED PIPES ABOUT ONE-THIRD WEIGHT OF CAST IRON. MORE DURABLE AND RELIABLE.

OF CAST IRON. MORE DURABLE AND RELIABLE.
AS SUPPLIED TO WATER-WORKS IN ALL PARTS OF THE WORLD.



STEEL AND CAST-IRON TANKS. ROOFS	
FOUL MAINS. PURIFIERS. RETORT LIDS	i
PETROLEUM TANKS A SPECIALTY	
CONSTRUCTIONAL IRONWORK	
GASHOLDERS AND PLANT OF ALL DESCRIP	rions.

MANUFACTURERS SOLELY OF

# HUMPHREYS & GLASGOW'S PATENT \_\_\_\_\_

CARBURETTED WATER-GAS PLANT.

INSTALLATIONS IN ALL PARTS OF THE UNITED KINGDOM AND ABROAD.

TELEGRAMS: "ATLAS, BIRMINGHAM." "INTERSECTION, LONDON."
THE ABC AND AI CODES USED.

# G. & J. HAIGH,

Raven's Lodge Fire-Brick Works, DEWSBURY,

Manufacturers of

# MACHINE-MADE RETORTS

#### Fire-Bricks

of the highest Quality, made from Fire-Clay of a most Superior and Refractory Character, suitable for

Glass-Works, - -

- Gas-Works, and -
  - - Blast-Furnaces.

For Prices and Analysis, apply as above.

### O'Neill's Oxide

(NATURAL BOG ORE)

For Gas Purification.

GAS PURIFICATION AND CHEMICAL CO., LTD., 160, 161, 162, Palmerston Buildings,

OLD BROAD STREET, LONDON, E.C.

### PRICE'S COKE & COAL BARROW

effects a great saving of time, labour, and expense. For Particulars, Price, &c., apply to—

MR. EDWARD PRICE,
Gas-Works, Hampton Wick.

# BALE'S BOG ORE



. AND

OXIDE PAINTS for Gas.

Works. Our Paints keep their Colour well, are a good Preservative, have good Covering properties.

BALE & Co., 120 & 121, Newgate Street, LONDON, E.C.

# FIRE CEMENT

# G. R. HISLÒP'S Patent Regenerative Retort-Setting

These Settings are by users assigned the First Position in Excelle of Design, Workmanship, Durability, and Efficiency; while in Compass Power, Facility of Management and Yield of Gas per mouthpiece in d or life volume, they have no equal. They carbonize 17 to 20 cwt English coal per mouthpiece per 24 hours, or 1000 cubic feet per lin foot of Retort; and of Scotch coal, 20 to 24 cwt., or 1200 cubic f per lineal foot, and with the lowest attainable amount of Fuel. necessary Steam for Producers is raised by the waste gases from settings.

RETORT BENCHES ERECTED COMPLETE,

with all up-to-date improvements, or existing ovens fitted with Patente arrangements.

FULL PARTICULARS FROM PATENTEE'S PRINCIPAL AJENT-

R. F. HISLOP, GONSULTING CRAIGIELEA, PAISLEY.

# . LAIDLAW & SON,

S AND WATER ENGINEERS.

UND OR SQUARE STATION METERS

CONSUMERS' WET AND DRY GAS-METERS.
EPAYMENT & COMPENSATING METERS.

SQUARE WORKS, ALLIANCE FOUNDRY, 6, LITTLE BUSH LANE, DINBURGH. GLASGOW. LONDON.

LDWARKE MAIN GAS COAL.

PROPRIETORS:

JOHN BROWN & CO.,

LAS STEEL AND IRON WORKS, SHEFFIELD.

nd )WARKE MAIN GAS COAL yields 12,600 feet of 19-candle gas per ton. Weight of Illuminating matter in pounds of sperm, 820-80. Very free from impurities.

### DAVID PARSONS & SONS,

ENGINEERS AND IRONFOUNDERS,

MANUFACTURERS OF

#### "AND WATER PIPES AND CONNECTIONS:

RETORT MOUTHPIECES, BENDS, ASCENSION, BRIDGE, and DIP PIPES, FURNACE and DUST DOORS and FRAMES, DEAD PLATES, ASH PANS, WALL PLATES, PILLARS, STAGE-FLOOR PLATES, LAMP COLUMNS and BRACKETS.

orks: LAYS IRON FOUNDRY, BRIERLEY HILL, STAFFS.

Telegrams: "PARSONS, BROCKMOOR." Railway Station: BRIERLEY HILL.

#### COAL UNLOADING AND - -

#### - - CONVEYING MACHINERY.

Also Makers of Liquor Tanks, Rack and Screw Valves, Hydraulic Hoists and Pumps,
AIR-COMPRESSORS.

AIR-COMPRESSORS,


Machinery for Horizontal and Inclined Retorts. Buckstaves, Columns, Stage-Floor Girders, &c.

RETORT MOUTHPIECES.

Regenerative Retort-Settings. Ascension, Arch, and Dip Pipes. Coal and Cannel Breakers. Coke Breakers and Screens.

COKE STORING and Screening Plant, Gas Compressors and Exhausters, Tubular Condensers, Coolers, Capstans, LIVESEY WASHERS, Gas-Engines, Floor-Plates, Roofs.

#### W. J. JENKINS & COMPANY, LTD., RETFORD.



ESTABLISHED 1851.

# HANNA, DONALD and WILSON, Engineers and Iron Founders, Abbey Works, Paisley.

Makers of Gas Plant of every description.

# OIL FOR GAS MAKING PURE DISTILLATE.

HOMOGENEOUS IN CHARACTER.

CAN BE STORED SAFELY ANYWHERE.

Flash Point Guaranteed Over 200° Fahr. (ABEL'S CLOSED TEST.)

ANGLO-CAUCASIAN OIL COMPANY, LTD.

18 & 19, GREAT ST. HELEN'S, LONDON. INDIA BUILDINGS, CROSS ST., MANCHESTER.

# THE LEEDS FIRECLAY CO., LTD.,

ENGINEERING DEPARTMENT.

Manufacturers of RETORTS, TILES, BRICKS, &c.

#### CONTRACTORS FOR

THE ERECTION OF

RETORT HOUSES COMPLETE, INCLINED AND HORIZONTAL

# RETORT SETTINGS & IRONWORK

On the REGENERATOR, GENERATOR, & DIRECT FIRED Systems.

SHALLOW REGENERATORS (a Speciality).

COAL & COKE BREAKING, ELEVATING, & CONVEYING MACHINERY.

## THOMAS BUGDEN,

INDIA-RUBBER MANUFACTURER,
71, GOSWELL ROAD, LONDON, E.C.,

And at 256, PENTONVILLE ROAD, KING'S CROSS, N.

### MANUFACTURER GAS BAGS,

Diving Dresses, Bellows, Sewer Boots, Miners' Jackets, India-Rubber Delivery and Suction Hose, Leather Bands, Oils, and Fasteners, Brass and Gun Metal Work of every description.

#### STOKERS' MITTS AND GAUNTLETS.

..Wringing Machine Rollers covered with India-Rubber.

CYCLE AND CAB TYRES

Gas Bags for Repairing Mains.

KEPT IN STOCK.



Brewers' Hose, Unions,

CONTRACTORS TO H.M. WAR OFFICE,
THE INDIAN GOVERNMENT, LONDON COUNTY COUNCIL,
CORPORATION OF CITY OF LONDON. &c., &c.

SKUDDER'S
SKUDDER'S
SKUDDER'S
SKUDDER'S
SKUDDER'S
SKUDDER'S
SKUDDER'S
SKUDDER'S

Offices

Asbestos and Rubber Goods of every description.

Boiler Scale Dissolving Compounds.

Free Analysis of Feed Water, before executing first order.

Cylinder and Machinery Oils, Dynamo and Gas-Engine Oils, &c.

Boiler and Steam Pipe Covering.

Engineers' Stores, Belting of every description. Belt Laces, Fasteners, Belting Cream.

For Axle Grease, Lubricating Grease, Solid Oil, Asbestos Grease, Heavy Bearing Grease, &c.

Gauge Glasses, Steam Gauges, Valves, Lubricators, Packings of every variety.

High-Class Steam and Water Fittings.

Gold Medal, Highest Award, Sheffield, 1892.

SAMPLES AND QUOTATIONS ON APPLICATION.

# G. SKUDDER & CO.,


Warehouse		<b>TOOLEY</b>	STREET,	LONDON	BRIDGE,	8.E.
Chemical Laboratory	)					
Oil Refinery and Grea	188 Works	• •		80UTH	BERMONO	<b>)8EY.</b>
Boiler Composition and	d Boiler Co	vering W	orks	)	BERMONE	1QEV
Enginee <b>ri</b> ng Works		• •		}	DENMUNI	JOE I.

Telephone No. 899 Hop. Telegraphic Address, "Skudder, London."



# INDEX TO ADVERTISERS.

Page.	Page.
Alder and Mackay 17	Hulett & Co., Ltd 41
Anglo-Caucasian Oil Co., Ltd 48	Humphreys & Glasgow 25
Arrol & Co., Ltd 39	Hutchinson Bros 35
Ashmore, Benson, Pease, & Co., 12, 13	Jenkins & Co., W. J 48
Bale & Co 46	
Balfour & Co., H 37	
Borradaile, T. A 22	Kirkham, Hulett, & Chandler, Ltd. 28
Braddock, J. & J 23	Laidlaw & Son, R 47
Brown & Co., John 47	Lanemark Coal Co., Ltd 37
Bugden, T 49	Leeds Fire-Clay Co., Ltd. (Engineering Department) 49
Carless, Capel, & Leonard 38	
Clapham Bros., Ltd 4	Main, R. & A 38
Clayton, Son, & Co., Ltd 36	Marsh, T. G 32, 33
Cockey & Sons, E 40	Meldrum Bros 30, 31
Cowan, W. & B., 24	M'Kelvie & Co., J 36
Currie & Co., H. F 43	Newton, Chambers, & Co., Ltd 16
Cutler & Sons, S., Millwall 8, 9	Parker & Lester 40
Dempster & Sons, R 21	Parsons & Sons, D 47
Dempster, R. & J 34	Piggott & Co., T
Donkin & Co., B 18	Porter & Co 10
	Price, E 45
Economical Gas Apparatus Con- struction Co., Ltd 11	11.00, 2. 11 11 11 1. 1. 1. 49
·	Richmond & Co., Ltd 51
Gas Apparatus Co., Peterborough 2	Chudden & Co. C
Gas Desulphurization Co., Ltd 41	Skudder & Co., G 50
Gas Meter Co., Ltd 29	Stephenson, Andrew 37
Gas Purification Co., Ltd 45	Taylor & Co., Joseph 42
Glover & Co., George 20	Torbay Paint Co. (Stevens & Co.) 19
Glover & Co., Thomas	Trotter, Haines, & Corbett 40
Guest & Chrimes 14	Walker, C. & W 5
Haigh, G. & J 45	West's Gas Improvement Co., Ltd. 26
Hanna, Donald, & Wilson 48	Wigan Coal and Iron Co. (A. C.
Harris & Pearson 3	Scrivener) 38
Hislop, G. R 46	Willey & Co 15
Holmes & Co., W. C 6, 7	Winstanley Speciality Co 43
Howard, Daniel 42	Wood & Co., R. D 27



89077808004




This book may be kept

#### FOURTEEN DAYS

A fine of TWO CENTS will be charged for each day the book is kept overtime.

		1 3 7	
		7-3-3	
	1-7-1		
	1 - 1		
	1 7		
No 201-B	DEMON HONDON		



89077808004 b89077808004a